

Miami-Dade County, Florida

Building and Neighborhood and Compliance Department
Board and Code Administration Division
Product Control Section
11805 S.W. 26 Street-Room 208
Miami, Florida 33175-2474
T (786) 315-2590 Fax (786) 315-2599

Laboratory Certificate



This certifies that Cleary Inspection Service, Inc. located at 1017 North "H" Street, Lake Worth, FL 33460 is an approved Testing Laboratory in accordance with Miami-Dade County Building Code Compliance and Protocol TAS301-94, and is Certified to perform the following tests:


- TAS105
- TAS106
- TAS126 (Nuclear method only)

Results of the above mentioned test shall be properly submitted to the Miami-Dade County Building Code Compliance Office per TAS301-94, along with all other documentation required for the approval of products. Approved engineer(s) for this laboratory:


R.N. Sailappan, P.E.

This Certification and Registration Approved: March 17, 2011
This Certification and Registration Expires : May 11, 2016

Certification No. : 11-0211.01



Jaime D. Gascon, P.E.
Product Control Section Supervisor
Product Control Division



Americo Segura
Quality Assurance Unit Supervisor
Product Control Division

The Miami-Dade County Building Code Compliance Office reserves the right to remove this certification for non-compliance with rules and regulations as set by Protocol TAS301-94.