Miami-Dade County, Florida

DEPARTMENT OF REGULATORY AND ECONMIC RESOURCES

BOARD AND CODE ADMINISTRATION DIVISON

PRODUCT CONTROL SECTION

Laboratory Certificate



11805 S.W. 26 Street-Room 208 Miami, Florida 33175-2474 T (786) 315-2590 Fax (786) 315-2599

This certifies that Cleary Inspection Service, Inc. located at 1017 North "H' Street, Lake Worth, FL 33460 is an approved Testing Laboratory in accordance with Miami-Dade County Department of Regulatory and Economic Resources and Protocol TAS301-94, and is Certified to perform the following tests:

TAS105 TAS106 TAS126 (Nuclear method only) ASTM D5957

Results of the above mentioned test shall be properly submitted to the Miami-Dade County Department of Regulatory and Economic Resources per TAS301-94, along with all other documentation required for the approval of products. Approved engineer(s) for this laboratory:

R.N. Sailappan, P.E.

This Certification and Registration Approved: April 13, 2023
This Certification and Registration Expires: May 11, 2026

Certification No.: 23-0317.01 Revises: 21-0323.01

Helmy A Makar, P.E., M.S.

Product Control Section Supervisor

Product Control Section

Americo Segura, M.S., CGC Quality Assurance Unit Supervisor

Product Control Section

The Mami-Dade County Department of Regulatory and Economic Resources reserves the right to remove this certification for non-compliance with rules and regulations as set by Protocol TAS301-94.