















## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/20/2023 05:33:04 AM	05/21/2023 08:11:03 PM	38:37:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/21/2023 08:11:03 PM	05/21/2023 09:02:01 PM	0:50:58
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/21/2023 09:02:01 PM	05/22/2023 07:39:02 PM	22:37:1
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/22/2023 07:39:02 PM	05/22/2023 09:11:02 PM	1:32:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Red	05/22/2023 09:11:02 PM	05/23/2023 07:31:02 AM	10:20:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/23/2023 07:31:02 AM	05/23/2023 08:07:03 AM	0:36:1
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/23/2023 08:07:03 AM	05/23/2023 11:15:03 AM	3:8:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Red	05/23/2023 11:15:03 AM	05/23/2023 11:51:02 AM	0:35:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/23/2023 11:51:02 AM	05/23/2023 11:55:01 AM	0:3:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/23/2023 11:55:01 AM	05/23/2023 09:49:02 PM	9:54:1
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/23/2023 09:49:02 PM	05/24/2023 04:01:01 AM	6:11:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/24/2023 04:01:01 AM	05/24/2023 05:30:01 PM	13:29:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/24/2023 05:30:01 PM	05/24/2023 07:02:02 PM	1:32:1
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/24/2023 07:02:02 PM	05/24/2023 10:54:02 PM	3:52:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/24/2023 10:54:02 PM	05/25/2023 04:50:01 AM	5:55:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/25/2023 04:50:01 AM	05/25/2023 07:38:16 PM	14:48:15
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/25/2023 07:38:16 PM	05/25/2023 08:22:02 PM	0:43:46

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/25/2023 08:22:02 PM	05/25/2023 10:06:02 PM	1:44:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/25/2023 10:06:02 PM	05/26/2023 04:50:01 AM	6:43:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Red	05/26/2023 04:50:01 AM	05/26/2023 06:53:03 AM	2:3:2
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/26/2023 06:53:03 AM	05/26/2023 06:14:02 PM	11:20:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/26/2023 06:14:02 PM	05/26/2023 07:38:02 PM	1:24:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Red	05/26/2023 07:38:02 PM	05/26/2023 10:02:02 PM	2:24:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/26/2023 10:02:02 PM	05/28/2023 08:27:01 PM	46:24:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/28/2023 08:27:01 PM	05/28/2023 08:39:01 PM	0:12:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/28/2023 08:39:01 PM	05/31/2023 07:49:02 PM	71:10:1
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	05/31/2023 07:49:02 PM	05/31/2023 08:57:02 PM	1:8:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	05/31/2023 08:57:02 PM	06/01/2023 12:33:02 AM	3:36:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	06/01/2023 12:33:02 AM	06/01/2023 04:49:01 AM	4:15:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	06/01/2023 04:49:01 AM	06/16/2023 05:54:01 PM	373:5:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	06/16/2023 05:54:01 PM	06/16/2023 06:07:02 PM	0:13:1
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	06/16/2023 06:07:02 PM	06/16/2023 08:26:01 PM	2:18:59
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Yellow	06/16/2023 08:26:01 PM	06/17/2023 01:46:01 AM	5:20:0
Gate D10 MRR	North Terminal	Gates D	Hand Towel 2	97722	Paper Towel	Green	06/17/2023 01:46:01 AM	06/23/2023 05:36:02 PM	159:50:1























## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/24/2023 02:30:02 PM	06/24/2023 02:49:01 PM	0:18:59
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/24/2023 02:49:01 PM	06/25/2023 07:49:01 AM	17:0:0
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/25/2023 07:49:01 AM	06/25/2023 09:33:02 AM	1:44:1
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/25/2023 09:33:02 AM	06/25/2023 03:26:02 PM	5:53:0
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/25/2023 03:26:02 PM	06/25/2023 03:30:01 PM	0:3:59
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/25/2023 03:30:01 PM	06/25/2023 09:31:01 PM	6:1:0
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/25/2023 09:31:01 PM	06/25/2023 09:39:02 PM	0:8:1
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/25/2023 09:39:02 PM	06/26/2023 11:25:15 AM	13:46:13
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/26/2023 11:25:15 AM	06/26/2023 11:28:02 AM	0:2:47
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/26/2023 11:28:02 AM	06/26/2023 08:30:42 PM	9:2:40
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/26/2023 08:30:42 PM	06/26/2023 08:48:01 PM	0:17:19
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/26/2023 08:48:01 PM	06/27/2023 10:30:01 AM	13:42:0
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	06/27/2023 10:30:01 AM	06/27/2023 03:02:02 PM	4:32:1
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	06/27/2023 03:02:02 PM	07/10/2023 11:18:02 AM	308:16:0
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Yellow	07/10/2023 11:18:02 AM	07/10/2023 11:49:02 AM	0:31:0
Gate D10 MRR	North Terminal	Gates D	Stall 2 - Bath Tissue	97725	Toilet Paper	Green	07/10/2023 11:49:02 AM	07/10/2023 03:18:45 PM	3:29:43
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	05/08/2023 07:43:01 AM	05/08/2023 09:23:01 AM	1:40:0









## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	05/29/2023 09:05:01 AM	05/29/2023 03:49:01 PM	6:44:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	05/29/2023 03:49:01 PM	05/29/2023 04:57:01 PM	1:8:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	05/29/2023 04:57:01 PM	05/29/2023 06:58:03 PM	2:1:2
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	05/29/2023 06:58:03 PM	05/29/2023 07:07:13 PM	0:9:10
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	05/29/2023 07:07:13 PM	05/30/2023 10:34:01 AM	15:26:48
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	05/30/2023 10:34:01 AM	05/30/2023 11:14:02 AM	0:40:1
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	05/30/2023 11:14:02 AM	05/31/2023 06:43:51 AM	19:29:49
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	05/31/2023 06:43:51 AM	05/31/2023 07:43:01 AM	0:59:10
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	05/31/2023 07:43:01 AM	05/31/2023 02:43:02 PM	7:0:1
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	05/31/2023 02:43:02 PM	05/31/2023 08:03:01 PM	5:19:59
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	05/31/2023 08:03:01 PM	06/16/2023 09:38:01 PM	385:35:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/16/2023 09:38:01 PM	06/17/2023 01:38:01 AM	4:0:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/17/2023 01:38:01 AM	06/17/2023 11:10:01 AM	9:32:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/17/2023 11:10:01 AM	06/17/2023 01:29:15 PM	2:19:14
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/17/2023 01:29:15 PM	06/18/2023 12:54:22 PM	23:25:7
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/18/2023 12:54:22 PM	06/23/2023 08:20:02 AM	115:25:40
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/23/2023 08:20:02 AM	06/23/2023 06:52:02 PM	10:32:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/23/2023 06:52:02 PM	06/23/2023 07:36:03 PM	0:44:1
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/23/2023 07:36:03 PM	06/24/2023 08:44:02 AM	13:7:59
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/24/2023 08:44:02 AM	06/24/2023 09:30:03 AM	0:46:1
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/24/2023 09:30:03 AM	06/25/2023 06:17:02 AM	20:46:59
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/25/2023 06:17:02 AM	06/25/2023 07:41:02 AM	1:24:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/25/2023 07:41:02 AM	06/26/2023 12:33:02 AM	16:52:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/26/2023 12:33:02 AM	06/26/2023 06:29:02 AM	5:56:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/26/2023 06:29:02 AM	06/27/2023 02:34:01 PM	32:4:59
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/27/2023 02:34:01 PM	06/27/2023 02:54:02 PM	0:20:1
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/27/2023 02:54:02 PM	06/28/2023 07:54:02 AM	17:0:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	06/28/2023 07:54:02 AM	06/28/2023 02:26:01 PM	6:31:59
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	06/28/2023 02:26:01 PM	07/10/2023 10:54:01 AM	284:28:0
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Yellow	07/10/2023 10:54:01 AM	07/10/2023 11:49:02 AM	0:55:1
Gate D10 MRR	North Terminal	Gates D	Stall 3 - Bath Tissue	97726	Toilet Paper	Green	07/10/2023 11:49:02 AM	07/10/2023 03:18:45 PM	3:29:43
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Red	05/08/2023 12:18:01 PM	05/08/2023 01:17:03 PM	0:59:2
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Green	05/08/2023 01:17:03 PM	05/23/2023 02:49:01 AM	349:31:58
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Red	05/23/2023 02:49:01 AM	05/23/2023 07:17:02 AM	4:28:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Green	05/23/2023 07:17:02 AM	05/25/2023 10:46:01 PM	63:28:59
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Red	05/25/2023 10:46:01 PM	05/26/2023 11:50:02 AM	13:4:1
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Green	05/26/2023 11:50:02 AM	05/29/2023 08:35:01 PM	80:44:59
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Red	05/29/2023 08:35:01 PM	05/30/2023 06:15:03 AM	9:40:2
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Green	05/30/2023 06:15:03 AM	06/25/2023 11:37:01 PM	641:21:58
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Red	06/25/2023 11:37:01 PM	06/26/2023 06:17:01 AM	6:40:0
Gate D10 WRR	North Terminal	Gates D	Soap 1 WRR	97718	Hand Soap	Green	06/26/2023 06:17:01 AM	07/10/2023 03:18:45 PM	345:1:44
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Red	05/09/2023 09:55:01 AM	05/09/2023 12:59:02 PM	3:4:1
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Green	05/09/2023 12:59:02 PM	05/29/2023 08:20:02 PM	487:21:0
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Red	05/29/2023 08:20:02 PM	05/30/2023 06:15:02 AM	9:55:0
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Green	05/30/2023 06:15:02 AM	06/23/2023 08:19:04 AM	578:4:2
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Red	06/23/2023 08:19:04 AM	06/23/2023 06:48:02 PM	10:28:58
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Green	06/23/2023 06:48:02 PM	06/28/2023 09:22:02 AM	110:34:0
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Red	06/28/2023 09:22:02 AM	06/28/2023 12:54:01 PM	3:31:59
Gate D10 WRR	North Terminal	Gates D	Soap 2 WRR	97719	Hand Soap	Green	06/28/2023 12:54:01 PM	07/10/2023 03:18:45 PM	290:24:44
Gate D10 WRR	North Terminal	Gates D	Soap 3 WRR	97720	Hand Soap	Red	05/10/2023 09:50:02 AM	05/10/2023 02:34:02 PM	4:44:0
Gate D10 WRR	North Terminal	Gates D	Soap 3 WRR	97720	Hand Soap	Green	05/10/2023 02:34:02 PM	05/26/2023 01:18:02 PM	382:44:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Soap 3 WRR	97720	Hand Soap	Red	05/26/2023 01:18:02 PM	05/27/2023 07:38:02 AM	18:20:0
Gate D10 WRR	North Terminal	Gates D	Soap 3 WRR	97720	Hand Soap	Green	05/27/2023 07:38:02 AM	06/25/2023 06:29:01 AM	694:50:59
Gate D10 WRR	North Terminal	Gates D	Soap 3 WRR	97720	Hand Soap	Red	06/25/2023 06:29:01 AM	06/25/2023 09:01:02 AM	2:32:1
Gate D10 WRR	North Terminal	Gates D	Soap 3 WRR	97720	Hand Soap	Green	06/25/2023 09:01:02 AM	07/10/2023 03:18:45 PM	366:17:43
Gate D10 WRR	North Terminal	Gates D	Soap 4 WRR	97736	Hand Soap	Red	05/22/2023 08:04:01 AM	05/22/2023 12:52:01 PM	4:48:0
Gate D10 WRR	North Terminal	Gates D	Soap 4 WRR	97736	Hand Soap	Green	05/22/2023 12:52:01 PM	05/30/2023 03:04:03 PM	194:12:2
Gate D10 WRR	North Terminal	Gates D	Soap 4 WRR	97736	Hand Soap	Red	05/30/2023 03:04:03 PM	05/31/2023 06:20:02 AM	15:15:59
Gate D10 WRR	North Terminal	Gates D	Soap 4 WRR	97736	Hand Soap	Green	05/31/2023 06:20:02 AM	07/10/2023 03:18:45 PM	968:58:43
Gate D10 WRR	North Terminal	Gates D	Soap 5 WRR	97737	Hand Soap	Red	05/21/2023 11:37:03 AM	05/21/2023 03:35:02 PM	3:57:59
Gate D10 WRR	North Terminal	Gates D	Soap 5 WRR	97737	Hand Soap	Green	05/21/2023 03:35:02 PM	05/28/2023 09:15:02 PM	173:40:0
Gate D10 WRR	North Terminal	Gates D	Soap 5 WRR	97737	Hand Soap	Red	05/28/2023 09:15:02 PM	05/29/2023 06:39:01 AM	9:23:59
Gate D10 WRR	North Terminal	Gates D	Soap 5 WRR	97737	Hand Soap	Green	05/29/2023 06:39:01 AM	06/25/2023 09:14:01 AM	650:35:0
Gate D10 WRR	North Terminal	Gates D	Soap 5 WRR	97737	Hand Soap	Red	06/25/2023 09:14:01 AM	06/25/2023 10:51:02 AM	1:37:1
Gate D10 WRR	North Terminal	Gates D	Soap 5 WRR	97737	Hand Soap	Green	06/25/2023 10:51:02 AM	07/10/2023 03:18:45 PM	364:27:43
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/08/2023 04:36:02 PM	05/08/2023 04:43:02 PM	0:7:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/08/2023 04:43:02 PM	05/08/2023 05:27:01 PM	0:43:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/08/2023 05:27:01 PM	05/08/2023 08:20:02 PM	2:53:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/08/2023 08:20:02 PM	05/09/2023 05:20:01 AM	8:59:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/09/2023 05:20:01 AM	05/09/2023 05:23:01 AM	0:3:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/09/2023 05:23:01 AM	05/09/2023 07:47:02 AM	2:24:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/09/2023 07:47:02 AM	05/09/2023 07:55:01 AM	0:7:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/09/2023 07:55:01 AM	05/10/2023 11:35:02 AM	27:40:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/10/2023 11:35:02 AM	05/10/2023 02:52:01 PM	3:16:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/10/2023 02:52:01 PM	05/10/2023 03:21:08 PM	0:29:7
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/10/2023 03:21:08 PM	05/10/2023 06:31:15 PM	3:10:7
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/10/2023 06:31:15 PM	05/10/2023 08:40:01 PM	2:8:46
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/10/2023 08:40:01 PM	05/11/2023 09:18:01 AM	12:38:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/11/2023 09:18:01 AM	05/11/2023 09:19:02 AM	0:1:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/11/2023 09:19:02 AM	05/11/2023 11:35:02 AM	2:16:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/11/2023 11:35:02 AM	05/11/2023 03:19:02 PM	3:44:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/11/2023 03:19:02 PM	05/12/2023 10:23:04 AM	19:4:2
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/12/2023 10:23:04 AM	05/12/2023 07:19:03 PM	8:55:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/12/2023 07:19:03 PM	05/12/2023 08:44:03 PM	1:25:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/12/2023 08:44:03 PM	05/13/2023 07:19:01 AM	10:34:58

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/13/2023 07:19:01 AM	05/13/2023 12:15:03 PM	4:56:2
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/13/2023 12:15:03 PM	05/13/2023 01:52:02 PM	1:36:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/13/2023 01:52:02 PM	05/15/2023 09:04:03 AM	43:12:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/15/2023 09:04:03 AM	05/15/2023 07:16:02 PM	10:11:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/15/2023 07:16:02 PM	05/15/2023 09:12:02 PM	1:56:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/15/2023 09:12:02 PM	05/17/2023 01:25:02 PM	40:13:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/17/2023 01:25:02 PM	05/17/2023 02:44:02 PM	1:19:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/17/2023 02:44:02 PM	05/17/2023 05:45:01 PM	3:0:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/17/2023 05:45:01 PM	05/18/2023 04:29:01 AM	10:44:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/18/2023 04:29:01 AM	05/18/2023 06:00:02 PM	13:31:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/18/2023 06:00:02 PM	05/18/2023 08:04:01 PM	2:3:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/18/2023 08:04:01 PM	05/18/2023 09:12:01 PM	1:8:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/18/2023 09:12:01 PM	05/19/2023 04:44:01 AM	7:32:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/19/2023 04:44:01 AM	05/19/2023 11:56:01 AM	7:12:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/19/2023 11:56:01 AM	05/19/2023 12:24:02 PM	0:28:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/19/2023 12:24:02 PM	05/19/2023 12:52:02 PM	0:28:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/19/2023 12:52:02 PM	05/19/2023 02:50:01 PM	1:57:59

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/19/2023 02:50:01 PM	05/19/2023 03:22:01 PM	0:32:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/19/2023 03:22:01 PM	05/19/2023 03:24:01 PM	0:2:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/19/2023 03:24:01 PM	05/20/2023 12:44:01 PM	21:20:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/20/2023 12:44:01 PM	05/20/2023 01:08:01 PM	0:24:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/20/2023 01:08:01 PM	05/20/2023 05:24:01 PM	4:16:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/20/2023 05:24:01 PM	05/20/2023 06:47:01 PM	1:23:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/20/2023 06:47:01 PM	05/20/2023 08:23:02 PM	1:36:1
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/20/2023 08:23:02 PM	05/20/2023 08:24:01 PM	0:0:59
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/20/2023 08:24:01 PM	05/21/2023 03:35:01 PM	19:11:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/21/2023 03:35:01 PM	05/21/2023 05:17:17 PM	1:42:16
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/21/2023 05:17:17 PM	05/21/2023 06:55:01 PM	1:37:44
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/21/2023 06:55:01 PM	05/21/2023 06:56:01 PM	0:1:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/21/2023 06:56:01 PM	05/21/2023 10:26:03 PM	3:30:2
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/21/2023 10:26:03 PM	05/22/2023 04:08:24 AM	5:42:21
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Green	05/22/2023 04:08:24 AM	05/22/2023 11:20:01 AM	7:11:37
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Yellow	05/22/2023 11:20:01 AM	05/22/2023 12:43:01 PM	1:23:0
Gate D10 WRR	North Terminal	Gates D	Hand Towel WRR 1	97712	Paper Towel	Red	05/22/2023 12:43:01 PM	05/22/2023 12:55:01 PM	0:12:0











## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Green	05/09/2023 05:25:02 AM	05/11/2023 10:24:02 AM	52:59:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Yellow	05/11/2023 10:24:02 AM	05/11/2023 08:55:02 PM	10:31:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Red	05/11/2023 08:55:02 PM	05/12/2023 03:55:02 PM	19:0:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Yellow	05/12/2023 03:55:02 PM	05/12/2023 09:03:02 PM	5:8:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Red	05/12/2023 09:03:02 PM	05/15/2023 09:04:03 AM	60:1:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Yellow	05/15/2023 09:04:03 AM	05/15/2023 09:24:03 AM	0:20:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Red	05/15/2023 09:24:03 AM	05/15/2023 09:44:02 AM	0:19:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Yellow	05/15/2023 09:44:02 AM	05/15/2023 10:20:58 AM	0:36:56
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Red	05/15/2023 10:20:58 AM	05/15/2023 10:48:02 AM	0:27:4
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Yellow	05/15/2023 10:48:02 AM	05/15/2023 11:00:03 AM	0:12:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Red	05/15/2023 11:00:03 AM	05/17/2023 01:25:03 PM	50:25:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall WRR Hand Towel 3	97714	Paper Towel	Green	05/17/2023 01:25:03 PM	07/10/2023 03:18:45 PM	1297:53:42
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/08/2023 04:48:02 AM	05/08/2023 10:26:02 AM	5:38:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/08/2023 10:26:02 AM	05/08/2023 01:21:01 PM	2:54:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/08/2023 01:21:01 PM	05/08/2023 04:53:02 PM	3:32:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/08/2023 04:53:02 PM	05/08/2023 08:53:01 PM	3:59:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/08/2023 08:53:01 PM	05/09/2023 06:17:01 AM	9:24:0





## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/14/2023 03:01:02 PM	05/14/2023 07:32:01 PM	4:30:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/14/2023 07:32:01 PM	05/14/2023 10:28:02 PM	2:56:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/14/2023 10:28:02 PM	05/15/2023 07:04:02 AM	8:36:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/15/2023 07:04:02 AM	05/15/2023 09:28:02 AM	2:24:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/15/2023 09:28:02 AM	05/15/2023 10:52:02 AM	1:24:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/15/2023 10:52:02 AM	05/15/2023 03:48:01 PM	4:55:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/15/2023 03:48:01 PM	05/15/2023 04:58:05 PM	1:10:4
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/15/2023 04:58:05 PM	05/17/2023 07:13:01 PM	50:14:56
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/17/2023 07:13:01 PM	05/18/2023 04:33:01 AM	9:20:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/18/2023 04:33:01 AM	05/18/2023 06:25:01 AM	1:52:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/18/2023 06:25:01 AM	05/18/2023 06:49:02 AM	0:24:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/18/2023 06:49:02 AM	05/18/2023 07:02:06 AM	0:13:4
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/18/2023 07:02:06 AM	05/18/2023 11:19:02 AM	4:16:56
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/18/2023 11:19:02 AM	05/18/2023 04:15:01 PM	4:55:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/18/2023 04:15:01 PM	05/18/2023 05:11:02 PM	0:56:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/18/2023 05:11:02 PM	05/18/2023 07:51:01 PM	2:39:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/18/2023 07:51:01 PM	05/19/2023 07:24:43 AM	11:33:42

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/19/2023 07:24:43 AM	05/19/2023 08:27:44 AM	1:3:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/19/2023 08:27:44 AM	05/19/2023 11:19:02 AM	2:51:18
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/19/2023 11:19:02 AM	05/19/2023 04:39:02 PM	5:20:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/19/2023 04:39:02 PM	05/19/2023 05:19:01 PM	0:39:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/19/2023 05:19:01 PM	05/19/2023 10:35:01 PM	5:16:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/19/2023 10:35:01 PM	05/20/2023 05:39:01 AM	7:4:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/20/2023 05:39:01 AM	05/20/2023 09:51:01 AM	4:12:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/20/2023 09:51:01 AM	05/20/2023 11:11:01 AM	1:20:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/20/2023 11:11:01 AM	05/20/2023 02:48:01 PM	3:37:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/20/2023 02:48:01 PM	05/20/2023 06:56:02 PM	4:8:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/20/2023 06:56:02 PM	05/20/2023 08:56:01 PM	1:59:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/20/2023 08:56:01 PM	05/21/2023 09:40:01 AM	12:44:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/21/2023 09:40:01 AM	05/21/2023 10:00:02 AM	0:20:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/21/2023 10:00:02 AM	05/21/2023 01:40:02 PM	3:40:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/21/2023 01:40:02 PM	05/21/2023 02:48:41 PM	1:8:39
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/21/2023 02:48:41 PM	05/21/2023 06:20:01 PM	3:31:20
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/21/2023 06:20:01 PM	05/21/2023 07:44:01 PM	1:24:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/21/2023 07:44:01 PM	05/22/2023 06:12:01 AM	10:28:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/22/2023 06:12:01 AM	05/22/2023 07:24:01 AM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/22/2023 07:24:01 AM	05/22/2023 09:36:01 AM	2:12:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/22/2023 09:36:01 AM	05/22/2023 11:24:01 AM	1:48:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/22/2023 11:24:01 AM	05/22/2023 03:04:02 PM	3:40:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/22/2023 03:04:02 PM	05/22/2023 03:49:03 PM	0:45:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/22/2023 03:49:03 PM	05/22/2023 07:56:01 PM	4:6:58
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/22/2023 07:56:01 PM	05/22/2023 08:36:57 PM	0:40:56
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/22/2023 08:36:57 PM	05/23/2023 08:26:09 AM	11:49:12
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/23/2023 08:26:09 AM	05/23/2023 08:49:02 AM	0:22:53
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/23/2023 08:49:02 AM	05/23/2023 01:33:05 PM	4:44:3
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/23/2023 01:33:05 PM	05/23/2023 03:01:02 PM	1:27:57
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/23/2023 03:01:02 PM	05/23/2023 08:47:04 PM	5:46:2
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/23/2023 08:47:04 PM	05/23/2023 09:45:40 PM	0:58:36
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/23/2023 09:45:40 PM	05/24/2023 09:09:01 AM	11:23:21
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/24/2023 09:09:01 AM	05/24/2023 10:58:02 AM	1:49:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/24/2023 10:58:02 AM	05/24/2023 11:38:02 AM	0:40:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/24/2023 11:38:02 AM	05/24/2023 11:54:01 AM	0:15:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/24/2023 11:54:01 AM	05/24/2023 05:10:02 PM	5:16:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/24/2023 05:10:02 PM	05/24/2023 05:46:01 PM	0:35:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/24/2023 05:46:01 PM	05/24/2023 10:22:02 PM	4:36:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/24/2023 10:22:02 PM	05/25/2023 12:54:02 AM	2:32:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/25/2023 12:54:02 AM	05/25/2023 09:34:01 AM	8:39:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/25/2023 09:34:01 AM	05/25/2023 12:30:02 PM	2:56:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/25/2023 12:30:02 PM	05/25/2023 02:58:03 PM	2:28:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/25/2023 02:58:03 PM	05/25/2023 07:26:01 PM	4:27:58
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/25/2023 07:26:01 PM	05/25/2023 10:02:01 PM	2:36:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/25/2023 10:02:01 PM	05/26/2023 07:58:01 AM	9:56:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/26/2023 07:58:01 AM	05/26/2023 11:00:02 AM	3:2:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/26/2023 11:00:02 AM	05/26/2023 03:18:01 PM	4:17:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/26/2023 03:18:01 PM	05/26/2023 05:02:03 PM	1:44:2
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/26/2023 05:02:03 PM	05/26/2023 08:50:01 PM	3:47:58
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/26/2023 08:50:01 PM	05/27/2023 08:58:01 AM	12:8:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/27/2023 08:58:01 AM	05/27/2023 10:46:02 AM	1:48:1



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/30/2023 07:16:02 AM	05/30/2023 01:09:02 PM	5:53:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/30/2023 01:09:02 PM	05/30/2023 01:37:02 PM	0:28:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/30/2023 01:37:02 PM	05/30/2023 02:17:01 PM	0:39:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/30/2023 02:17:01 PM	05/30/2023 03:05:02 PM	0:48:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/30/2023 03:05:02 PM	05/30/2023 05:13:02 PM	2:8:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	05/30/2023 05:13:02 PM	05/30/2023 10:13:02 PM	5:0:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	05/30/2023 10:13:02 PM	05/31/2023 04:17:02 AM	6:4:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	05/31/2023 04:17:02 AM	06/16/2023 02:57:01 PM	394:39:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/16/2023 02:57:01 PM	06/16/2023 03:21:02 PM	0:24:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/16/2023 03:21:02 PM	06/16/2023 07:10:01 PM	3:48:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/16/2023 07:10:01 PM	06/16/2023 09:54:01 PM	2:44:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/16/2023 09:54:01 PM	06/17/2023 09:14:01 AM	11:20:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/17/2023 09:14:01 AM	06/17/2023 10:54:01 AM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/17/2023 10:54:01 AM	06/17/2023 12:14:03 PM	1:20:2
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/17/2023 12:14:03 PM	06/17/2023 05:26:02 PM	5:11:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	06/17/2023 05:26:02 PM	06/17/2023 07:10:02 PM	1:44:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/17/2023 07:10:02 PM	06/18/2023 05:38:02 AM	10:28:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/18/2023 05:38:02 AM	06/18/2023 07:50:02 AM	2:12:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	06/18/2023 07:50:02 AM	06/18/2023 08:38:01 AM	0:47:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/18/2023 08:38:01 AM	06/18/2023 12:02:01 PM	3:24:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/18/2023 12:02:01 PM	06/23/2023 09:55:16 AM	117:53:15
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/23/2023 09:55:16 AM	06/23/2023 11:27:03 AM	1:31:47
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/23/2023 11:27:03 AM	06/23/2023 03:16:02 PM	3:48:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/23/2023 03:16:02 PM	06/23/2023 07:05:00 PM	3:48:58
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/23/2023 07:05:00 PM	06/23/2023 08:08:54 PM	1:3:54
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	06/23/2023 08:08:54 PM	06/23/2023 08:48:01 PM	0:39:7
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/23/2023 08:48:01 PM	06/24/2023 07:04:01 AM	10:16:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/24/2023 07:04:01 AM	06/24/2023 09:32:02 AM	2:28:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/24/2023 09:32:02 AM	06/24/2023 01:28:03 PM	3:56:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/24/2023 01:28:03 PM	06/24/2023 03:20:02 PM	1:51:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/24/2023 03:20:02 PM	06/24/2023 06:23:02 PM	3:3:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/24/2023 06:23:02 PM	06/24/2023 06:45:01 PM	0:21:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/24/2023 06:45:01 PM	06/25/2023 06:25:02 AM	11:40:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/25/2023 06:25:02 AM	06/25/2023 07:10:13 AM	0:45:11

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	06/25/2023 07:10:13 AM	06/25/2023 07:49:02 AM	0:38:49
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/25/2023 07:49:02 AM	06/25/2023 08:45:01 AM	0:55:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/25/2023 08:45:01 AM	06/25/2023 12:03:02 PM	3:18:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/25/2023 12:03:02 PM	06/25/2023 12:57:02 PM	0:54:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/25/2023 12:57:02 PM	06/25/2023 05:06:02 PM	4:9:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/25/2023 05:06:02 PM	06/25/2023 06:50:01 PM	1:43:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/25/2023 06:50:01 PM	06/25/2023 10:07:02 PM	3:17:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/25/2023 10:07:02 PM	06/25/2023 11:59:02 PM	1:52:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/25/2023 11:59:02 PM	06/26/2023 10:49:03 AM	10:50:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/26/2023 10:49:03 AM	06/26/2023 11:00:01 AM	0:10:58
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/26/2023 11:00:01 AM	06/26/2023 11:56:01 AM	0:56:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/26/2023 11:56:01 AM	06/26/2023 12:48:01 PM	0:52:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/26/2023 12:48:01 PM	06/26/2023 08:32:02 PM	7:44:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/26/2023 08:32:02 PM	06/26/2023 09:08:02 PM	0:36:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/26/2023 09:08:02 PM	06/27/2023 07:49:02 AM	10:41:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/27/2023 07:49:02 AM	06/27/2023 08:33:02 AM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	06/27/2023 08:33:02 AM	06/27/2023 08:57:02 AM	0:24:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/27/2023 08:57:02 AM	06/27/2023 09:05:01 AM	0:7:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Red	06/27/2023 09:05:01 AM	06/27/2023 09:26:04 AM	0:21:3
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/27/2023 09:26:04 AM	06/27/2023 03:09:01 PM	5:42:57
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/27/2023 03:09:01 PM	06/27/2023 04:49:01 PM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/27/2023 04:49:01 PM	06/27/2023 09:15:02 PM	4:26:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/27/2023 09:15:02 PM	06/27/2023 09:42:02 PM	0:27:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/27/2023 09:42:02 PM	06/28/2023 07:58:01 AM	10:15:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/28/2023 07:58:01 AM	06/28/2023 10:46:02 AM	2:48:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/28/2023 10:46:02 AM	06/28/2023 01:58:02 PM	3:12:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/28/2023 01:58:02 PM	06/28/2023 02:50:01 PM	0:51:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/28/2023 02:50:01 PM	06/28/2023 05:18:01 PM	2:28:0
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/28/2023 05:18:01 PM	06/28/2023 07:23:02 PM	2:5:1
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Green	06/28/2023 07:23:02 PM	06/28/2023 10:19:01 PM	2:55:59
Gate D10 WRR	North Terminal	Gates D	Handicap Stall 1 Bath Tissue WRR	97715	Toilet Paper	Yellow	06/28/2023 10:19:01 PM	07/10/2023 03:18:45 PM	280:59:44
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/08/2023 12:59:01 PM	05/09/2023 06:20:03 AM	17:21:2
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/09/2023 06:20:03 AM	05/09/2023 09:24:01 AM	3:3:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/09/2023 09:24:01 AM	05/09/2023 01:08:05 PM	3:44:4

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/09/2023 01:08:05 PM	05/10/2023 09:03:02 AM	19:54:57
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/10/2023 09:03:02 AM	05/10/2023 09:23:03 AM	0:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/10/2023 09:23:03 AM	05/10/2023 09:39:03 AM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/10/2023 09:39:03 AM	05/10/2023 06:55:02 PM	9:15:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Red	05/10/2023 06:55:02 PM	05/10/2023 07:19:32 PM	0:24:30
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/10/2023 07:19:32 PM	05/11/2023 12:55:02 AM	5:35:30
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/11/2023 12:55:02 AM	05/11/2023 06:16:04 AM	5:21:2
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/11/2023 06:16:04 AM	05/11/2023 09:31:02 AM	3:14:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/11/2023 09:31:02 AM	05/11/2023 05:23:01 PM	7:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/11/2023 05:23:01 PM	05/12/2023 06:31:02 AM	13:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/12/2023 06:31:02 AM	05/12/2023 04:43:01 PM	10:11:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/12/2023 04:43:01 PM	05/12/2023 09:12:02 PM	4:29:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/12/2023 09:12:02 PM	05/13/2023 09:40:03 AM	12:28:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/13/2023 09:40:03 AM	05/13/2023 12:48:02 PM	3:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/13/2023 12:48:02 PM	05/13/2023 08:54:02 PM	8:6:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/13/2023 08:54:02 PM	05/14/2023 12:44:02 PM	15:50:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/14/2023 12:44:02 PM	05/14/2023 05:08:02 PM	4:24:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/14/2023 05:08:02 PM	05/14/2023 08:48:50 PM	3:40:48
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/14/2023 08:48:50 PM	05/14/2023 08:56:01 PM	0:7:11
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/14/2023 08:56:01 PM	05/15/2023 08:20:03 AM	11:24:2
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Red	05/15/2023 08:20:03 AM	05/15/2023 09:36:02 AM	1:15:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/15/2023 09:36:02 AM	05/15/2023 07:13:03 PM	9:37:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/15/2023 07:13:03 PM	05/17/2023 01:25:03 PM	42:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/17/2023 01:25:03 PM	05/17/2023 08:18:01 PM	6:52:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/17/2023 08:18:01 PM	05/18/2023 04:34:01 AM	8:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/18/2023 04:34:01 AM	05/18/2023 01:19:01 PM	8:45:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/18/2023 01:19:01 PM	05/18/2023 03:35:01 PM	2:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/18/2023 03:35:01 PM	05/19/2023 09:27:02 AM	17:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/19/2023 09:27:02 AM	05/19/2023 01:07:02 PM	3:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/19/2023 01:07:02 PM	05/19/2023 07:31:01 PM	6:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/19/2023 07:31:01 PM	05/19/2023 09:47:01 PM	2:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Red	05/19/2023 09:47:01 PM	05/20/2023 07:31:03 AM	9:44:2
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/20/2023 07:31:03 AM	05/20/2023 05:59:01 PM	10:27:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/20/2023 05:59:01 PM	05/21/2023 04:47:01 AM	10:48:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/21/2023 04:47:01 AM	05/21/2023 10:44:01 AM	5:57:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/21/2023 10:44:01 AM	05/21/2023 11:52:02 AM	1:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/21/2023 11:52:02 AM	05/21/2023 10:16:01 PM	10:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/21/2023 10:16:01 PM	05/22/2023 07:40:02 AM	9:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/22/2023 07:40:02 AM	05/22/2023 03:12:06 PM	7:32:4
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/22/2023 03:12:06 PM	05/22/2023 04:59:02 PM	1:46:56
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/22/2023 04:59:02 PM	05/23/2023 07:03:02 AM	14:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/23/2023 07:03:02 AM	05/23/2023 08:43:30 AM	1:40:28
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/23/2023 08:43:30 AM	05/23/2023 08:25:01 PM	11:41:31
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/23/2023 08:25:01 PM	05/24/2023 01:09:03 AM	4:44:2
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/24/2023 01:09:03 AM	05/24/2023 09:47:01 PM	20:37:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/24/2023 09:47:01 PM	05/25/2023 06:51:02 AM	9:4:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/25/2023 06:51:02 AM	05/25/2023 11:43:01 AM	4:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/25/2023 11:43:01 AM	05/25/2023 12:31:01 PM	0:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/25/2023 12:31:01 PM	05/25/2023 06:55:02 PM	6:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/25/2023 06:55:02 PM	05/26/2023 03:38:01 AM	8:42:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/26/2023 03:38:01 AM	05/26/2023 07:51:02 AM	4:13:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/26/2023 07:51:02 AM	05/26/2023 11:22:03 AM	3:31:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/26/2023 11:22:03 AM	05/26/2023 02:58:02 PM	3:35:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/26/2023 02:58:02 PM	05/26/2023 10:02:03 PM	7:4:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/26/2023 10:02:03 PM	05/27/2023 12:30:01 PM	14:27:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/27/2023 12:30:01 PM	05/27/2023 12:46:01 PM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/27/2023 12:46:01 PM	05/28/2023 09:06:02 AM	20:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/28/2023 09:06:02 AM	05/28/2023 09:30:03 AM	0:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/28/2023 09:30:03 AM	05/28/2023 10:00:02 AM	0:29:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/28/2023 10:00:02 AM	05/28/2023 10:02:02 AM	0:2:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/28/2023 10:02:02 AM	05/28/2023 10:50:02 AM	0:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/28/2023 10:50:02 AM	05/28/2023 11:06:02 AM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/28/2023 11:06:02 AM	05/28/2023 11:10:01 AM	0:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/28/2023 11:10:01 AM	05/28/2023 01:26:02 PM	2:16:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/28/2023 01:26:02 PM	05/28/2023 03:50:01 PM	2:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/28/2023 03:50:01 PM	05/28/2023 04:30:06 PM	0:40:5
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	05/28/2023 04:30:06 PM	05/29/2023 07:42:02 AM	15:11:56
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	05/29/2023 07:42:02 AM	05/29/2023 10:50:02 AM	3:8:0





## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	06/27/2023 12:39:03 AM	06/27/2023 11:25:01 AM	10:45:58
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	06/27/2023 11:25:01 AM	06/27/2023 01:50:01 PM	2:25:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	06/27/2023 01:50:01 PM	06/28/2023 07:46:05 AM	17:56:4
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	06/28/2023 07:46:05 AM	06/28/2023 08:50:01 AM	1:3:56
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	06/28/2023 08:50:01 AM	06/28/2023 03:06:02 PM	6:16:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	06/28/2023 03:06:02 PM	07/10/2023 07:46:02 AM	280:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	07/10/2023 07:46:02 AM	07/10/2023 11:54:02 AM	4:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	07/10/2023 11:54:02 AM	07/10/2023 12:16:03 PM	0:22:1
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	07/10/2023 12:16:03 PM	07/10/2023 12:58:10 PM	0:42:7
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Yellow	07/10/2023 12:58:10 PM	07/10/2023 03:08:02 PM	2:9:52
Gate D10 WRR	North Terminal	Gates D	Stall 2 Bath Tissue	97716	Toilet Paper	Green	07/10/2023 03:08:02 PM	07/10/2023 03:18:45 PM	0:10:43
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/08/2023 02:25:01 PM	05/09/2023 05:25:01 AM	15:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/09/2023 05:25:01 AM	05/09/2023 07:57:01 PM	14:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/09/2023 07:57:01 PM	05/09/2023 08:45:01 PM	0:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/09/2023 08:45:01 PM	05/11/2023 08:19:05 AM	35:34:4
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/11/2023 08:19:05 AM	05/11/2023 09:32:02 AM	1:12:57
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/11/2023 09:32:02 AM	05/11/2023 08:32:02 PM	11:0:0



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/22/2023 09:47:02 AM	05/22/2023 11:03:02 AM	1:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/22/2023 11:03:02 AM	05/22/2023 01:27:01 PM	2:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/22/2023 01:27:01 PM	05/23/2023 07:32:01 PM	30:5:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/23/2023 07:32:01 PM	05/23/2023 08:39:02 PM	1:7:1
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/23/2023 08:39:02 PM	05/24/2023 08:33:02 AM	11:54:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/24/2023 08:33:02 AM	05/24/2023 09:05:02 AM	0:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/24/2023 09:05:02 AM	05/25/2023 08:34:02 AM	23:29:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/25/2023 08:34:02 AM	05/25/2023 12:58:02 PM	4:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/25/2023 12:58:02 PM	05/26/2023 11:58:02 AM	23:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/26/2023 11:58:02 AM	05/26/2023 03:34:02 PM	3:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/26/2023 03:34:02 PM	05/27/2023 10:42:01 AM	19:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/27/2023 10:42:01 AM	05/27/2023 11:46:01 AM	1:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/27/2023 11:46:01 AM	05/28/2023 08:38:02 AM	20:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/28/2023 08:38:02 AM	05/28/2023 11:04:02 AM	2:26:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/28/2023 11:04:02 AM	05/28/2023 03:50:01 PM	4:45:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/28/2023 03:50:01 PM	05/28/2023 04:30:06 PM	0:40:5
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/28/2023 04:30:06 PM	05/29/2023 08:42:02 AM	16:11:56

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/29/2023 08:42:02 AM	05/29/2023 10:50:02 AM	2:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/29/2023 10:50:02 AM	05/29/2023 07:22:02 PM	8:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/29/2023 07:22:02 PM	05/29/2023 07:38:02 PM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/29/2023 07:38:02 PM	05/29/2023 07:46:01 PM	0:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/29/2023 07:46:01 PM	05/30/2023 08:40:02 AM	12:54:1
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/30/2023 08:40:02 AM	05/30/2023 06:03:02 PM	9:23:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/30/2023 06:03:02 PM	05/30/2023 07:03:01 PM	0:59:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/30/2023 07:03:01 PM	05/31/2023 02:27:01 PM	19:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	05/31/2023 02:27:01 PM	05/31/2023 05:43:02 PM	3:16:1
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	05/31/2023 05:43:02 PM	06/16/2023 04:46:01 PM	383:2:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	06/16/2023 04:46:01 PM	06/17/2023 04:46:01 AM	12:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	06/17/2023 04:46:01 AM	06/17/2023 12:54:01 PM	8:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	06/17/2023 12:54:01 PM	06/17/2023 01:58:02 PM	1:4:1
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	06/17/2023 01:58:02 PM	06/18/2023 08:26:01 AM	18:27:59
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	06/18/2023 08:26:01 AM	06/18/2023 09:06:01 AM	0:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Green	06/18/2023 09:06:01 AM	06/23/2023 12:55:01 PM	123:49:0
Gate D10 WRR	North Terminal	Gates D	Stall 3 Bath Tissue	97717	Toilet Paper	Yellow	06/23/2023 12:55:01 PM	06/23/2023 03:16:01 PM	2:21:0





## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/10/2023 08:02:05 AM	05/10/2023 09:03:02 AM	1:0:57
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/10/2023 09:03:02 AM	05/10/2023 04:07:01 PM	7:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/10/2023 04:07:01 PM	05/11/2023 12:56:39 AM	8:49:38
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/11/2023 12:56:39 AM	05/11/2023 06:53:23 AM	5:56:44
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/11/2023 06:53:23 AM	05/11/2023 09:31:01 AM	2:37:38
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/11/2023 09:31:01 AM	05/11/2023 11:11:02 AM	1:40:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/11/2023 11:11:02 AM	05/11/2023 01:31:01 PM	2:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/11/2023 01:31:01 PM	05/11/2023 08:02:02 PM	6:31:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/11/2023 08:02:02 PM	05/12/2023 06:31:01 AM	10:28:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/12/2023 06:31:01 AM	05/12/2023 09:27:03 AM	2:56:2
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/12/2023 09:27:03 AM	05/12/2023 10:39:02 AM	1:11:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/12/2023 10:39:02 AM	05/12/2023 07:18:02 PM	8:39:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/12/2023 07:18:02 PM	05/13/2023 12:38:01 AM	5:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/13/2023 12:38:01 AM	05/13/2023 07:32:01 AM	6:54:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/13/2023 07:32:01 AM	05/13/2023 11:37:02 AM	4:5:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/13/2023 11:37:02 AM	05/13/2023 12:46:02 PM	1:9:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/13/2023 12:46:02 PM	05/13/2023 04:52:02 PM	4:6:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/13/2023 04:52:02 PM	05/13/2023 05:36:02 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/13/2023 05:36:02 PM	05/14/2023 06:33:01 AM	12:56:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/14/2023 06:33:01 AM	05/14/2023 09:56:01 AM	3:23:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/14/2023 09:56:01 AM	05/14/2023 11:20:02 AM	1:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/14/2023 11:20:02 AM	05/14/2023 11:28:01 AM	0:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/14/2023 11:28:01 AM	05/14/2023 12:36:02 PM	1:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/14/2023 12:36:02 PM	05/14/2023 12:48:02 PM	0:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/14/2023 12:48:02 PM	05/14/2023 03:01:02 PM	2:13:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/14/2023 03:01:02 PM	05/14/2023 05:28:01 PM	2:26:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/14/2023 05:28:01 PM	05/14/2023 08:52:02 PM	3:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/14/2023 08:52:02 PM	05/15/2023 08:04:01 AM	11:11:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/15/2023 08:04:01 AM	05/15/2023 08:56:02 AM	0:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/15/2023 08:56:02 AM	05/15/2023 10:56:02 AM	2:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/15/2023 10:56:02 AM	05/15/2023 12:44:01 PM	1:47:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/15/2023 12:44:01 PM	05/15/2023 01:28:01 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/15/2023 01:28:01 PM	05/15/2023 07:48:02 PM	6:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/15/2023 07:48:02 PM	05/17/2023 01:25:02 PM	41:37:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/17/2023 01:25:02 PM	05/17/2023 01:57:03 PM	0:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/17/2023 01:57:03 PM	05/17/2023 07:33:01 PM	5:35:58
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/17/2023 07:33:01 PM	05/17/2023 08:41:01 PM	1:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/17/2023 08:41:01 PM	05/18/2023 08:13:02 AM	11:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/18/2023 08:13:02 AM	05/18/2023 10:53:02 AM	2:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/18/2023 10:53:02 AM	05/18/2023 12:00:01 PM	1:6:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/18/2023 12:00:01 PM	05/18/2023 03:36:01 PM	3:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/18/2023 03:36:01 PM	05/18/2023 07:12:02 PM	3:36:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/18/2023 07:12:02 PM	05/18/2023 08:56:01 PM	1:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/18/2023 08:56:01 PM	05/19/2023 04:48:01 AM	7:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/19/2023 04:48:01 AM	05/19/2023 09:04:03 AM	4:16:2
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/19/2023 09:04:03 AM	05/19/2023 01:20:01 PM	4:15:58
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/19/2023 01:20:01 PM	05/19/2023 03:20:01 PM	2:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/19/2023 03:20:01 PM	05/19/2023 10:12:02 PM	6:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/19/2023 10:12:02 PM	05/20/2023 05:40:02 AM	7:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/20/2023 05:40:02 AM	05/20/2023 10:00:02 AM	4:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/20/2023 10:00:02 AM	05/20/2023 11:12:02 AM	1:12:0



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/23/2023 04:28:02 AM	05/23/2023 06:08:02 AM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/23/2023 06:08:02 AM	05/23/2023 07:08:02 AM	1:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/23/2023 07:08:02 AM	05/23/2023 10:17:02 AM	3:9:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/23/2023 10:17:02 AM	05/23/2023 11:44:02 AM	1:27:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/23/2023 11:44:02 AM	05/23/2023 05:32:02 PM	5:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/23/2023 05:32:02 PM	05/23/2023 06:56:02 PM	1:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/23/2023 06:56:02 PM	05/23/2023 10:17:02 PM	3:21:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/23/2023 10:17:02 PM	05/24/2023 01:09:04 AM	2:52:2
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/24/2023 01:09:04 AM	05/24/2023 11:38:02 AM	10:28:58
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/24/2023 11:38:02 AM	05/24/2023 11:50:02 AM	0:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/24/2023 11:50:02 AM	05/24/2023 05:18:01 PM	5:27:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/24/2023 05:18:01 PM	05/24/2023 06:42:01 PM	1:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/24/2023 06:42:01 PM	05/24/2023 08:50:01 PM	2:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/24/2023 08:50:01 PM	05/25/2023 06:54:02 AM	10:4:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/25/2023 06:54:02 AM	05/25/2023 08:34:02 AM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/25/2023 08:34:02 AM	05/25/2023 01:06:01 PM	4:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/25/2023 01:06:01 PM	05/25/2023 03:56:03 PM	2:50:2

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/25/2023 03:56:03 PM	05/25/2023 07:36:02 PM	3:39:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/25/2023 07:36:02 PM	05/26/2023 03:41:02 AM	8:5:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/26/2023 03:41:02 AM	05/26/2023 07:33:01 AM	3:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/26/2023 07:33:01 AM	05/26/2023 08:45:01 AM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/26/2023 08:45:01 AM	05/26/2023 11:33:01 AM	2:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/26/2023 11:33:01 AM	05/26/2023 03:13:01 PM	3:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/26/2023 03:13:01 PM	05/26/2023 07:17:04 PM	4:4:3
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/26/2023 07:17:04 PM	05/26/2023 07:37:01 PM	0:19:57
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/26/2023 07:37:01 PM	05/27/2023 07:42:02 AM	12:5:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/27/2023 07:42:02 AM	05/27/2023 09:06:01 AM	1:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/27/2023 09:06:01 AM	05/27/2023 12:10:01 PM	3:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/27/2023 12:10:01 PM	05/27/2023 01:22:01 PM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/27/2023 01:22:01 PM	05/27/2023 01:26:01 PM	0:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/27/2023 01:26:01 PM	05/27/2023 01:34:02 PM	0:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/27/2023 01:34:02 PM	05/27/2023 06:46:02 PM	5:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/27/2023 06:46:02 PM	05/27/2023 08:42:02 PM	1:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/27/2023 08:42:02 PM	05/28/2023 08:58:01 AM	12:15:59

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/28/2023 08:58:01 AM	05/28/2023 11:06:02 AM	2:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/28/2023 11:06:02 AM	05/28/2023 11:26:01 AM	0:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/28/2023 11:26:01 AM	05/28/2023 02:26:01 PM	3:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/28/2023 02:26:01 PM	05/28/2023 02:58:01 PM	0:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/28/2023 02:58:01 PM	05/28/2023 04:38:02 PM	1:40:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/28/2023 04:38:02 PM	05/28/2023 06:50:03 PM	2:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/28/2023 06:50:03 PM	05/29/2023 05:26:01 AM	10:35:58
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/29/2023 05:26:01 AM	05/29/2023 10:10:01 AM	4:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/29/2023 10:10:01 AM	05/29/2023 10:50:01 AM	0:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/29/2023 10:50:01 AM	05/29/2023 11:10:11 AM	0:20:10
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/29/2023 11:10:11 AM	05/29/2023 06:47:02 PM	7:36:51
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/29/2023 06:47:02 PM	05/29/2023 08:23:02 PM	1:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/29/2023 08:23:02 PM	05/29/2023 08:39:02 PM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/29/2023 08:39:02 PM	05/30/2023 07:11:02 AM	10:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/30/2023 07:11:02 AM	05/30/2023 09:00:01 AM	1:48:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/30/2023 09:00:01 AM	05/30/2023 11:24:01 AM	2:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/30/2023 11:24:01 AM	05/30/2023 06:24:01 PM	7:0:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/30/2023 06:24:01 PM	05/30/2023 07:04:01 PM	0:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/30/2023 07:04:01 PM	05/31/2023 12:01:02 AM	4:57:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/31/2023 12:01:02 AM	05/31/2023 04:17:02 AM	4:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/31/2023 04:17:02 AM	05/31/2023 08:09:01 AM	3:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/31/2023 08:09:01 AM	05/31/2023 11:13:01 AM	3:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/31/2023 11:13:01 AM	05/31/2023 01:01:02 PM	1:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/31/2023 01:01:02 PM	05/31/2023 03:05:01 PM	2:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	05/31/2023 03:05:01 PM	05/31/2023 09:13:01 PM	6:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	05/31/2023 09:13:01 PM	05/31/2023 09:29:01 PM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	05/31/2023 09:29:01 PM	06/01/2023 05:17:01 AM	7:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/01/2023 05:17:01 AM	06/16/2023 01:53:02 PM	368:36:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	06/16/2023 01:53:02 PM	06/16/2023 03:09:01 PM	1:15:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/16/2023 03:09:01 PM	06/16/2023 08:21:02 PM	5:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/16/2023 08:21:02 PM	06/17/2023 04:46:01 AM	8:24:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/17/2023 04:46:01 AM	06/17/2023 09:10:01 AM	4:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/17/2023 09:10:01 AM	06/17/2023 01:06:34 PM	3:56:33
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	06/17/2023 01:06:34 PM	06/17/2023 01:34:01 PM	0:27:27

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/17/2023 01:34:01 PM	06/17/2023 05:42:01 PM	4:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/17/2023 05:42:01 PM	06/17/2023 07:14:01 PM	1:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/17/2023 07:14:01 PM	06/18/2023 06:30:01 AM	11:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/18/2023 06:30:01 AM	06/18/2023 09:06:01 AM	2:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/18/2023 09:06:01 AM	06/18/2023 12:42:01 PM	3:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/18/2023 12:42:01 PM	06/18/2023 12:58:01 PM	0:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/18/2023 12:58:01 PM	06/23/2023 08:19:03 AM	115:21:2
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/23/2023 08:19:03 AM	06/23/2023 08:31:01 AM	0:11:58
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/23/2023 08:31:01 AM	06/23/2023 11:19:02 AM	2:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/23/2023 11:19:02 AM	06/23/2023 03:00:02 PM	3:41:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/23/2023 03:00:02 PM	06/23/2023 07:36:04 PM	4:36:2
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/23/2023 07:36:04 PM	06/23/2023 09:28:02 PM	1:51:58
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	06/23/2023 09:28:02 PM	06/24/2023 12:32:02 AM	3:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/24/2023 12:32:02 AM	06/24/2023 09:44:02 AM	9:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/24/2023 09:44:02 AM	06/24/2023 11:04:02 AM	1:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/24/2023 11:04:02 AM	06/24/2023 03:20:02 PM	4:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/24/2023 03:20:02 PM	06/24/2023 03:36:03 PM	0:16:1



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/26/2023 05:54:02 PM	06/26/2023 09:42:02 PM	3:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/26/2023 09:42:02 PM	06/27/2023 12:39:02 AM	2:57:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/27/2023 12:39:02 AM	06/27/2023 10:18:02 AM	9:39:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/27/2023 10:18:02 AM	06/27/2023 11:18:03 AM	1:0:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/27/2023 11:18:03 AM	06/27/2023 04:58:02 PM	5:39:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/27/2023 04:58:02 PM	06/27/2023 05:50:02 PM	0:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/27/2023 05:50:02 PM	06/27/2023 09:42:02 PM	3:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/27/2023 09:42:02 PM	06/28/2023 04:54:02 AM	7:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/28/2023 04:54:02 AM	06/28/2023 10:02:01 AM	5:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/28/2023 10:02:01 AM	06/28/2023 10:46:02 AM	0:44:1
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/28/2023 10:46:02 AM	06/28/2023 11:42:02 AM	0:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/28/2023 11:42:02 AM	06/28/2023 02:02:01 PM	2:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/28/2023 02:02:01 PM	06/28/2023 05:02:01 PM	3:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	06/28/2023 05:02:01 PM	06/28/2023 08:31:01 PM	3:29:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Red	06/28/2023 08:31:01 PM	06/28/2023 09:03:01 PM	0:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	06/28/2023 09:03:01 PM	07/10/2023 08:36:01 AM	275:33:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	07/10/2023 08:36:01 AM	07/10/2023 10:52:02 AM	2:16:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	07/10/2023 10:52:02 AM	07/10/2023 11:49:02 AM	0:57:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Yellow	07/10/2023 11:49:02 AM	07/10/2023 12:36:02 PM	0:47:0
Gate D10 WRR	North Terminal	Gates D	Stall 4 Bath Tissue	97730	Toilet Paper	Green	07/10/2023 12:36:02 PM	07/10/2023 03:18:45 PM	2:42:43
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/08/2023 04:49:02 AM	05/08/2023 08:45:01 AM	3:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/08/2023 08:45:01 AM	05/08/2023 10:53:02 AM	2:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/08/2023 10:53:02 AM	05/08/2023 04:34:03 PM	5:41:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/08/2023 04:34:03 PM	05/08/2023 04:37:02 PM	0:2:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/08/2023 04:37:02 PM	05/08/2023 04:41:01 PM	0:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/08/2023 04:41:01 PM	05/08/2023 11:16:02 PM	6:35:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/08/2023 11:16:02 PM	05/09/2023 05:25:01 AM	6:8:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/09/2023 05:25:01 AM	05/09/2023 06:21:01 AM	0:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/09/2023 06:21:01 AM	05/09/2023 11:36:19 AM	5:15:18
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/09/2023 11:36:19 AM	05/09/2023 01:02:01 PM	1:25:42
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/09/2023 01:02:01 PM	05/09/2023 07:22:02 PM	6:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/09/2023 07:22:02 PM	05/09/2023 08:46:01 PM	1:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/09/2023 08:46:01 PM	05/10/2023 07:50:03 AM	11:4:2
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/10/2023 07:50:03 AM	05/10/2023 02:14:01 PM	6:23:58

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/10/2023 02:14:01 PM	05/10/2023 02:38:02 PM	0:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/10/2023 02:38:02 PM	05/10/2023 07:18:01 PM	4:39:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/10/2023 07:18:01 PM	05/11/2023 12:58:01 AM	5:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/11/2023 12:58:01 AM	05/11/2023 06:30:02 AM	5:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/11/2023 06:30:02 AM	05/11/2023 09:30:02 AM	3:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/11/2023 09:30:02 AM	05/11/2023 11:42:02 AM	2:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/11/2023 11:42:02 AM	05/11/2023 01:30:01 PM	1:47:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/11/2023 01:30:01 PM	05/11/2023 05:54:02 PM	4:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/11/2023 05:54:02 PM	05/12/2023 09:14:01 AM	15:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/12/2023 09:14:01 AM	05/12/2023 10:18:01 AM	1:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/12/2023 10:18:01 AM	05/12/2023 10:42:10 AM	0:24:9
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/12/2023 10:42:10 AM	05/13/2023 07:22:53 AM	20:40:43
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/13/2023 07:22:53 AM	05/13/2023 07:55:02 AM	0:32:9
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/13/2023 07:55:02 AM	05/13/2023 09:22:02 AM	1:27:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/13/2023 09:22:02 AM	05/13/2023 12:26:01 PM	3:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/13/2023 12:26:01 PM	05/13/2023 06:06:01 PM	5:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/13/2023 06:06:01 PM	05/13/2023 07:06:01 PM	1:0:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/13/2023 07:06:01 PM	05/14/2023 08:10:01 AM	13:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/14/2023 08:10:01 AM	05/14/2023 08:34:01 AM	0:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/14/2023 08:34:01 AM	05/14/2023 08:38:01 AM	0:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/14/2023 08:38:01 AM	05/14/2023 03:30:01 PM	6:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/14/2023 03:30:01 PM	05/14/2023 05:10:24 PM	1:40:23
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/14/2023 05:10:24 PM	05/14/2023 07:06:01 PM	1:55:37
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/14/2023 07:06:01 PM	05/14/2023 07:46:01 PM	0:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/14/2023 07:46:01 PM	05/14/2023 08:46:01 PM	1:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/14/2023 08:46:01 PM	05/14/2023 10:26:01 PM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/14/2023 10:26:01 PM	05/15/2023 08:40:03 AM	10:14:2
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/15/2023 08:40:03 AM	05/15/2023 08:46:03 AM	0:6:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/15/2023 08:46:03 AM	05/15/2023 08:48:04 AM	0:2:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/15/2023 08:48:04 AM	05/15/2023 09:20:03 AM	0:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/15/2023 09:20:03 AM	05/15/2023 02:12:01 PM	4:51:58
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/15/2023 02:12:01 PM	05/15/2023 04:40:16 PM	2:28:15
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/15/2023 04:40:16 PM	05/15/2023 09:56:02 PM	5:15:46
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/15/2023 09:56:02 PM	05/17/2023 02:41:02 PM	40:45:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/17/2023 02:41:02 PM	05/17/2023 05:24:02 PM	2:43:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/17/2023 05:24:02 PM	05/17/2023 10:52:01 PM	5:27:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/17/2023 10:52:01 PM	05/18/2023 06:40:02 AM	7:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/18/2023 06:40:02 AM	05/18/2023 10:15:03 AM	3:35:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/18/2023 10:15:03 AM	05/18/2023 11:44:01 AM	1:28:58
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/18/2023 11:44:01 AM	05/18/2023 01:20:04 PM	1:36:3
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/18/2023 01:20:04 PM	05/18/2023 03:28:02 PM	2:7:58
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/18/2023 03:28:02 PM	05/18/2023 10:48:02 PM	7:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/18/2023 10:48:02 PM	05/19/2023 07:36:01 AM	8:47:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/19/2023 07:36:01 AM	05/19/2023 09:04:03 AM	1:28:2
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/19/2023 09:04:03 AM	05/19/2023 12:57:02 PM	3:52:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/19/2023 12:57:02 PM	05/19/2023 03:17:02 PM	2:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/19/2023 03:17:02 PM	05/19/2023 06:49:00 PM	3:31:58
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/19/2023 06:49:00 PM	05/19/2023 09:20:02 PM	2:31:2
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/19/2023 09:20:02 PM	05/20/2023 05:40:01 AM	8:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/20/2023 05:40:01 AM	05/20/2023 10:48:01 AM	5:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/20/2023 10:48:01 AM	05/20/2023 11:34:03 AM	0:46:2



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/23/2023 01:17:01 PM	05/23/2023 02:57:01 PM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/23/2023 02:57:01 PM	05/23/2023 09:49:02 PM	6:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/23/2023 09:49:02 PM	05/24/2023 01:13:01 AM	3:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/24/2023 01:13:01 AM	05/24/2023 09:29:02 AM	8:16:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/24/2023 09:29:02 AM	05/24/2023 11:10:01 AM	1:40:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/24/2023 11:10:01 AM	05/24/2023 04:42:02 PM	5:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/24/2023 04:42:02 PM	05/24/2023 08:30:02 PM	3:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/24/2023 08:30:02 PM	05/24/2023 09:26:02 PM	0:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/24/2023 09:26:02 PM	05/25/2023 05:06:01 AM	7:39:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/25/2023 05:06:01 AM	05/25/2023 09:30:05 AM	4:24:4
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/25/2023 09:30:05 AM	05/25/2023 03:15:02 PM	5:44:57
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/25/2023 03:15:02 PM	05/25/2023 03:23:02 PM	0:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/25/2023 03:23:02 PM	05/25/2023 03:56:02 PM	0:33:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/25/2023 03:56:02 PM	05/25/2023 08:22:02 PM	4:26:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/25/2023 08:22:02 PM	05/25/2023 08:34:02 PM	0:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/25/2023 08:34:02 PM	05/25/2023 09:26:01 PM	0:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/25/2023 09:26:01 PM	05/26/2023 09:26:02 AM	12:0:1



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/29/2023 09:46:01 AM	05/29/2023 10:58:02 AM	1:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/29/2023 10:58:02 AM	05/29/2023 01:54:02 PM	2:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/29/2023 01:54:02 PM	05/29/2023 03:14:02 PM	1:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/29/2023 03:14:02 PM	05/29/2023 07:58:02 PM	4:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/29/2023 07:58:02 PM	05/29/2023 08:42:01 PM	0:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/29/2023 08:42:01 PM	05/30/2023 12:48:56 PM	16:6:55
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/30/2023 12:48:56 PM	05/30/2023 02:52:01 PM	2:3:5
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	05/30/2023 02:52:01 PM	05/30/2023 03:04:04 PM	0:12:3
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/30/2023 03:04:04 PM	05/30/2023 06:56:01 PM	3:51:57
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/30/2023 06:56:01 PM	05/30/2023 08:52:02 PM	1:56:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/30/2023 08:52:02 PM	05/31/2023 09:48:01 AM	12:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/31/2023 09:48:01 AM	05/31/2023 11:08:02 AM	1:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/31/2023 11:08:02 AM	05/31/2023 11:52:01 AM	0:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/31/2023 11:52:01 AM	05/31/2023 01:04:01 PM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	05/31/2023 01:04:01 PM	05/31/2023 05:41:02 PM	4:37:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	05/31/2023 05:41:02 PM	06/01/2023 05:16:01 AM	11:34:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/01/2023 05:16:01 AM	06/16/2023 01:52:02 PM	368:36:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/16/2023 01:52:02 PM	06/16/2023 02:29:01 PM	0:36:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	06/16/2023 02:29:01 PM	06/16/2023 03:12:01 PM	0:43:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/16/2023 03:12:01 PM	06/16/2023 08:32:01 PM	5:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/16/2023 08:32:01 PM	06/16/2023 09:52:02 PM	1:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/16/2023 09:52:02 PM	06/17/2023 09:32:01 AM	11:39:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/17/2023 09:32:01 AM	06/17/2023 01:40:02 PM	4:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/17/2023 01:40:02 PM	06/17/2023 01:58:03 PM	0:18:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/17/2023 01:58:03 PM	06/17/2023 03:12:43 PM	1:14:40
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/17/2023 03:12:43 PM	06/17/2023 06:56:01 PM	3:43:18
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/17/2023 06:56:01 PM	06/17/2023 09:20:01 PM	2:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/17/2023 09:20:01 PM	06/18/2023 09:16:01 AM	11:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/18/2023 09:16:01 AM	06/18/2023 10:36:01 AM	1:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	06/18/2023 10:36:01 AM	06/18/2023 11:28:01 AM	0:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/18/2023 11:28:01 AM	06/23/2023 09:01:01 AM	117:33:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/23/2023 09:01:01 AM	06/23/2023 01:09:02 PM	4:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	06/23/2023 01:09:02 PM	06/23/2023 03:44:02 PM	2:35:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/23/2023 03:44:02 PM	06/23/2023 07:36:04 PM	3:52:2

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	06/23/2023 07:36:04 PM	06/23/2023 07:56:03 PM	0:19:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/23/2023 07:56:03 PM	06/24/2023 08:13:01 AM	12:16:58
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/24/2023 08:13:01 AM	06/24/2023 09:30:03 AM	1:17:2
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/24/2023 09:30:03 AM	06/24/2023 12:17:02 PM	2:46:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/24/2023 12:17:02 PM	06/24/2023 12:53:02 PM	0:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/24/2023 12:53:02 PM	06/24/2023 05:05:02 PM	4:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/24/2023 05:05:02 PM	06/24/2023 10:34:02 PM	5:29:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Red	06/24/2023 10:34:02 PM	06/25/2023 04:49:02 AM	6:15:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/25/2023 04:49:02 AM	06/25/2023 10:19:02 AM	5:30:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/25/2023 10:19:02 AM	06/25/2023 01:06:01 PM	2:46:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/25/2023 01:06:01 PM	06/25/2023 03:26:02 PM	2:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/25/2023 03:26:02 PM	06/25/2023 06:50:02 PM	3:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/25/2023 06:50:02 PM	06/25/2023 07:34:02 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/25/2023 07:34:02 PM	06/25/2023 11:35:02 PM	4:1:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/25/2023 11:35:02 PM	06/26/2023 04:07:01 AM	4:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/26/2023 04:07:01 AM	06/26/2023 06:31:01 AM	2:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/26/2023 06:31:01 AM	06/26/2023 11:51:02 AM	5:20:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/26/2023 11:51:02 AM	06/26/2023 01:07:02 PM	1:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/26/2023 01:07:02 PM	06/26/2023 04:44:01 PM	3:36:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/26/2023 04:44:01 PM	06/26/2023 05:28:01 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/26/2023 05:28:01 PM	06/26/2023 08:42:01 PM	3:14:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/26/2023 08:42:01 PM	06/27/2023 12:47:02 AM	4:5:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/27/2023 12:47:02 AM	06/27/2023 09:26:02 AM	8:39:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/27/2023 09:26:02 AM	06/27/2023 09:46:02 AM	0:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/27/2023 09:46:02 AM	06/27/2023 03:14:02 PM	5:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/27/2023 03:14:02 PM	06/27/2023 04:42:02 PM	1:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/27/2023 04:42:02 PM	06/27/2023 09:18:02 PM	4:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/27/2023 09:18:02 PM	06/28/2023 04:54:02 AM	7:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/28/2023 04:54:02 AM	06/28/2023 09:02:03 AM	4:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/28/2023 09:02:03 AM	06/28/2023 10:58:02 AM	1:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/28/2023 10:58:02 AM	06/28/2023 01:58:02 PM	3:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/28/2023 01:58:02 PM	06/28/2023 02:50:02 PM	0:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Green	06/28/2023 02:50:02 PM	06/28/2023 10:10:02 PM	7:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 5 Bath Tissue	97731	Toilet Paper	Yellow	06/28/2023 10:10:02 PM	07/10/2023 07:46:02 AM	273:36:0



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/15/2023 09:00:02 AM	05/15/2023 11:16:02 AM	2:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/15/2023 11:16:02 AM	05/15/2023 01:28:02 PM	2:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/15/2023 01:28:02 PM	05/17/2023 05:20:01 PM	51:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/17/2023 05:20:01 PM	05/18/2023 04:36:02 AM	11:16:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/18/2023 04:36:02 AM	05/19/2023 09:41:07 AM	29:5:5
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/19/2023 09:41:07 AM	05/19/2023 01:33:02 PM	3:51:55
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/19/2023 01:33:02 PM	05/20/2023 10:33:02 AM	21:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/20/2023 10:33:02 AM	05/20/2023 11:37:02 AM	1:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/20/2023 11:37:02 AM	05/20/2023 12:17:02 PM	0:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/20/2023 12:17:02 PM	05/20/2023 01:29:02 PM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/20/2023 01:29:02 PM	05/20/2023 02:33:01 PM	1:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/20/2023 02:33:01 PM	05/20/2023 03:53:01 PM	1:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/20/2023 03:53:01 PM	05/21/2023 02:41:54 PM	22:48:53
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/21/2023 02:41:54 PM	05/21/2023 05:02:01 PM	2:20:7
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/21/2023 05:02:01 PM	05/22/2023 07:39:02 PM	26:37:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/22/2023 07:39:02 PM	05/22/2023 08:47:01 PM	1:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/22/2023 08:47:01 PM	05/23/2023 07:03:02 AM	10:16:1



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/29/2023 09:31:04 AM	05/29/2023 11:03:09 AM	1:32:5
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/29/2023 11:03:09 AM	05/30/2023 09:44:02 AM	22:40:53
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/30/2023 09:44:02 AM	05/30/2023 11:24:02 AM	1:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/30/2023 11:24:02 AM	05/30/2023 09:52:01 PM	10:27:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/30/2023 09:52:01 PM	05/31/2023 07:40:02 AM	9:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/31/2023 07:40:02 AM	05/31/2023 06:36:02 PM	10:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	05/31/2023 06:36:02 PM	05/31/2023 07:52:02 PM	1:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	05/31/2023 07:52:02 PM	06/16/2023 08:24:01 PM	384:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/16/2023 08:24:01 PM	06/16/2023 09:08:02 PM	0:44:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/16/2023 09:08:02 PM	06/16/2023 09:52:02 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/16/2023 09:52:02 PM	06/17/2023 04:48:01 AM	6:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/17/2023 04:48:01 AM	06/23/2023 02:07:01 PM	153:19:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/23/2023 02:07:01 PM	06/23/2023 03:08:02 PM	1:1:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/23/2023 03:08:02 PM	06/24/2023 12:21:01 AM	9:12:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/24/2023 12:21:01 AM	06/24/2023 12:33:02 AM	0:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/24/2023 12:33:02 AM	06/24/2023 04:37:02 PM	16:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/24/2023 04:37:02 PM	06/24/2023 07:33:03 PM	2:56:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/24/2023 07:33:03 PM	06/25/2023 05:05:02 PM	21:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/25/2023 05:05:02 PM	06/25/2023 06:49:01 PM	1:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/25/2023 06:49:01 PM	06/26/2023 03:03:01 PM	20:14:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/26/2023 03:03:01 PM	06/26/2023 04:15:02 PM	1:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/26/2023 04:15:02 PM	06/26/2023 05:23:02 PM	1:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/26/2023 05:23:02 PM	06/27/2023 12:44:03 AM	7:21:1
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/27/2023 12:44:03 AM	06/28/2023 07:51:15 AM	31:7:12
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	06/28/2023 07:51:15 AM	06/28/2023 10:47:01 AM	2:55:46
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	06/28/2023 10:47:01 AM	07/10/2023 12:32:03 PM	289:45:2
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Yellow	07/10/2023 12:32:03 PM	07/10/2023 01:12:02 PM	0:39:59
Gate D10 WRR	North Terminal	Gates D	Stall 6 Bath Tissue	97732	Toilet Paper	Green	07/10/2023 01:12:02 PM	07/10/2023 03:18:45 PM	2:6:43
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/08/2023 04:47:02 AM	05/08/2023 08:43:01 AM	3:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/08/2023 08:43:01 AM	05/08/2023 10:00:08 AM	1:17:7
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/08/2023 10:00:08 AM	05/08/2023 02:39:02 PM	4:38:54
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/08/2023 02:39:02 PM	05/08/2023 08:43:01 PM	6:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Red	05/08/2023 08:43:01 PM	05/09/2023 05:28:05 AM	8:45:4
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/09/2023 05:28:05 AM	05/09/2023 11:15:02 AM	5:46:57







## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/21/2023 05:58:10 PM	05/21/2023 06:42:02 PM	0:43:52
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Red	05/21/2023 06:42:02 PM	05/21/2023 08:42:01 PM	1:59:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/21/2023 08:42:01 PM	05/22/2023 10:22:02 AM	13:40:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/22/2023 10:22:02 AM	05/22/2023 11:10:02 AM	0:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/22/2023 11:10:02 AM	05/22/2023 02:39:02 PM	3:29:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/22/2023 02:39:02 PM	05/22/2023 03:51:02 PM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/22/2023 03:51:02 PM	05/23/2023 07:31:03 AM	15:40:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/23/2023 07:31:03 AM	05/23/2023 08:39:02 AM	1:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/23/2023 08:39:02 AM	05/23/2023 09:19:02 AM	0:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/23/2023 09:19:02 AM	05/23/2023 09:47:03 AM	0:28:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/23/2023 09:47:03 AM	05/24/2023 09:11:02 AM	23:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/24/2023 09:11:02 AM	05/24/2023 10:54:02 AM	1:43:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/24/2023 10:54:02 AM	05/25/2023 02:42:01 AM	15:47:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/25/2023 02:42:01 AM	05/25/2023 09:14:02 AM	6:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Red	05/25/2023 09:14:02 AM	05/25/2023 09:26:02 AM	0:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/25/2023 09:26:02 AM	05/25/2023 12:54:02 PM	3:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/25/2023 12:54:02 PM	05/25/2023 02:19:01 PM	1:24:59

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/25/2023 02:19:01 PM	05/25/2023 08:42:02 PM	6:23:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Red	05/25/2023 08:42:02 PM	05/25/2023 09:34:01 PM	0:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/25/2023 09:34:01 PM	05/26/2023 03:38:01 AM	6:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/26/2023 03:38:01 AM	05/26/2023 09:54:02 AM	6:16:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/26/2023 09:54:02 AM	05/26/2023 11:32:02 AM	1:38:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/26/2023 11:32:02 AM	05/26/2023 08:18:02 PM	8:46:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/26/2023 08:18:02 PM	05/27/2023 04:22:02 AM	8:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/27/2023 04:22:02 AM	05/27/2023 05:10:01 AM	0:47:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/27/2023 05:10:01 AM	05/27/2023 07:34:01 AM	2:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/27/2023 07:34:01 AM	05/27/2023 11:34:01 AM	4:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/27/2023 11:34:01 AM	05/27/2023 11:54:01 AM	0:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/27/2023 11:54:01 AM	05/27/2023 06:50:02 PM	6:56:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/27/2023 06:50:02 PM	05/27/2023 08:46:01 PM	1:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/27/2023 08:46:01 PM	05/28/2023 10:18:01 AM	13:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/28/2023 10:18:01 AM	05/28/2023 11:04:02 AM	0:46:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/28/2023 11:04:02 AM	05/28/2023 05:18:02 PM	6:14:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/28/2023 05:18:02 PM	05/28/2023 06:50:03 PM	1:32:1



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/31/2023 10:01:02 AM	05/31/2023 03:33:01 PM	5:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	05/31/2023 03:33:01 PM	05/31/2023 05:45:02 PM	2:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	05/31/2023 05:45:02 PM	06/01/2023 04:57:05 AM	11:12:3
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/01/2023 04:57:05 AM	06/01/2023 08:09:03 AM	3:11:58
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	06/01/2023 08:09:03 AM	06/16/2023 01:53:02 PM	365:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/16/2023 01:53:02 PM	06/16/2023 03:31:02 PM	1:38:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Red	06/16/2023 03:31:02 PM	06/16/2023 05:05:01 PM	1:33:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	06/16/2023 05:05:01 PM	06/16/2023 10:45:02 PM	5:40:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/16/2023 10:45:02 PM	06/17/2023 04:45:01 AM	5:59:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	06/17/2023 04:45:01 AM	06/17/2023 12:13:02 PM	7:28:1
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/17/2023 12:13:02 PM	06/17/2023 01:41:02 PM	1:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	06/17/2023 01:41:02 PM	06/17/2023 06:46:01 PM	5:4:59
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/17/2023 06:46:01 PM	06/17/2023 07:17:01 PM	0:31:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	06/17/2023 07:17:01 PM	06/18/2023 07:02:01 AM	11:45:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/18/2023 07:02:01 AM	06/18/2023 08:53:01 AM	1:51:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Green	06/18/2023 08:53:01 AM	06/27/2023 02:33:01 PM	221:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 7 Bath Tissue	97733	Toilet Paper	Yellow	06/27/2023 02:33:01 PM	06/27/2023 04:49:01 PM	2:16:0



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/10/2023 06:46:03 PM	05/11/2023 12:54:02 AM	6:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/11/2023 12:54:02 AM	05/11/2023 08:14:02 AM	7:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/11/2023 08:14:02 AM	05/11/2023 09:30:02 AM	1:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/11/2023 09:30:02 AM	05/11/2023 04:11:01 PM	6:40:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/11/2023 04:11:01 PM	05/12/2023 06:12:02 AM	14:1:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	05/12/2023 06:12:02 AM	05/12/2023 10:44:02 AM	4:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/12/2023 10:44:02 AM	05/12/2023 09:32:02 PM	10:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/12/2023 09:32:02 PM	05/13/2023 12:36:01 AM	3:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/13/2023 12:36:01 AM	05/13/2023 11:57:02 AM	11:21:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/13/2023 11:57:02 AM	05/13/2023 12:48:02 PM	0:51:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/13/2023 12:48:02 PM	05/13/2023 08:36:02 PM	7:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/13/2023 08:36:02 PM	05/13/2023 09:44:30 PM	1:8:28
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/13/2023 09:44:30 PM	05/14/2023 04:21:02 PM	18:36:32
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/14/2023 04:21:02 PM	05/14/2023 08:17:02 PM	3:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	05/14/2023 08:17:02 PM	05/14/2023 08:45:01 PM	0:27:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/14/2023 08:45:01 PM	05/14/2023 10:45:01 PM	2:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/14/2023 10:45:01 PM	05/15/2023 07:05:02 AM	8:20:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/15/2023 07:05:02 AM	05/15/2023 07:57:01 AM	0:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	05/15/2023 07:57:01 AM	05/15/2023 08:48:04 AM	0:51:3
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/15/2023 08:48:04 AM	05/15/2023 09:32:50 AM	0:44:46
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/15/2023 09:32:50 AM	05/15/2023 04:58:05 PM	7:25:15
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/15/2023 04:58:05 PM	05/15/2023 05:00:03 PM	0:1:58
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/15/2023 05:00:03 PM	05/15/2023 05:16:02 PM	0:15:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/15/2023 05:16:02 PM	05/17/2023 02:29:02 PM	45:13:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/17/2023 02:29:02 PM	05/17/2023 04:29:01 PM	1:59:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/17/2023 04:29:01 PM	05/17/2023 10:02:01 PM	5:33:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	05/17/2023 10:02:01 PM	05/18/2023 04:34:02 AM	6:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/18/2023 04:34:02 AM	05/18/2023 01:19:01 PM	8:44:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/18/2023 01:19:01 PM	05/18/2023 03:39:02 PM	2:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/18/2023 03:39:02 PM	05/18/2023 07:55:01 PM	4:15:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/18/2023 07:55:01 PM	05/19/2023 10:15:02 AM	14:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	05/19/2023 10:15:02 AM	05/19/2023 11:39:01 AM	1:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/19/2023 11:39:01 AM	05/20/2023 05:31:01 AM	17:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/20/2023 05:31:01 AM	05/20/2023 07:35:01 AM	2:4:0



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/23/2023 06:56:03 PM	05/24/2023 09:33:01 AM	14:36:58
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/24/2023 09:33:01 AM	05/24/2023 10:55:01 AM	1:22:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/24/2023 10:55:01 AM	05/24/2023 02:03:02 PM	3:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/24/2023 02:03:02 PM	05/24/2023 05:11:01 PM	3:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/24/2023 05:11:01 PM	05/24/2023 10:39:01 PM	5:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/24/2023 10:39:01 PM	05/25/2023 05:03:01 AM	6:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/25/2023 05:03:01 AM	05/25/2023 09:27:01 AM	4:24:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/25/2023 09:27:01 AM	05/25/2023 12:55:01 PM	3:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/25/2023 12:55:01 PM	05/25/2023 03:56:02 PM	3:1:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/25/2023 03:56:02 PM	05/25/2023 09:30:02 PM	5:34:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/25/2023 09:30:02 PM	05/26/2023 09:38:03 AM	12:8:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/26/2023 09:38:03 AM	05/26/2023 11:34:04 AM	1:56:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/26/2023 11:34:04 AM	05/26/2023 06:02:02 PM	6:27:58
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/26/2023 06:02:02 PM	05/26/2023 06:38:03 PM	0:36:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	05/26/2023 06:38:03 PM	05/26/2023 08:38:02 PM	1:59:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	05/26/2023 08:38:02 PM	05/27/2023 04:26:01 AM	7:47:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	05/27/2023 04:26:01 AM	05/27/2023 09:30:02 AM	5:4:1





## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/18/2023 10:13:02 AM	06/18/2023 11:09:01 AM	0:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	06/18/2023 11:09:01 AM	06/23/2023 10:43:02 AM	119:34:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/23/2023 10:43:02 AM	06/23/2023 12:08:02 PM	1:25:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	06/23/2023 12:08:02 PM	06/23/2023 01:00:10 PM	0:52:8
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	06/23/2023 01:00:10 PM	06/23/2023 09:29:02 PM	8:28:52
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/23/2023 09:29:02 PM	06/24/2023 12:21:01 AM	2:51:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	06/24/2023 12:21:01 AM	06/24/2023 12:33:02 AM	0:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	06/24/2023 12:33:02 AM	06/24/2023 12:29:01 PM	11:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/24/2023 12:29:01 PM	06/24/2023 03:21:01 PM	2:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	06/24/2023 03:21:01 PM	06/24/2023 05:41:02 PM	2:20:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/24/2023 05:41:02 PM	06/25/2023 12:41:02 AM	7:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	06/25/2023 12:41:02 AM	06/25/2023 04:49:01 AM	4:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/25/2023 04:49:01 AM	06/25/2023 10:33:01 AM	5:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Red	06/25/2023 10:33:01 AM	06/25/2023 01:01:01 PM	2:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/25/2023 01:01:01 PM	06/25/2023 01:13:01 PM	0:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	06/25/2023 01:13:01 PM	06/25/2023 05:05:02 PM	3:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/25/2023 05:05:02 PM	06/25/2023 06:45:01 PM	1:39:59



## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	06/28/2023 12:38:02 PM	06/28/2023 06:02:36 PM	5:24:34
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	06/28/2023 06:02:36 PM	07/10/2023 07:47:02 AM	277:44:26
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	07/10/2023 07:47:02 AM	07/10/2023 08:51:02 AM	1:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	07/10/2023 08:51:02 AM	07/10/2023 10:55:11 AM	2:4:9
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	07/10/2023 10:55:11 AM	07/10/2023 11:49:02 AM	0:53:51
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Yellow	07/10/2023 11:49:02 AM	07/10/2023 03:08:02 PM	3:19:0
Gate D10 WRR	North Terminal	Gates D	Stall 8 Bath Tissue	97734	Toilet Paper	Green	07/10/2023 03:08:02 PM	07/10/2023 03:18:45 PM	0:10:43
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/08/2023 09:21:05 AM	05/09/2023 07:44:03 AM	22:22:58
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/09/2023 07:44:03 AM	05/09/2023 10:38:02 AM	2:53:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/09/2023 10:38:02 AM	05/09/2023 04:02:01 PM	5:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/09/2023 04:02:01 PM	05/09/2023 05:34:02 PM	1:32:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/09/2023 05:34:02 PM	05/09/2023 07:22:02 PM	1:48:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/09/2023 07:22:02 PM	05/10/2023 10:36:02 AM	15:14:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/10/2023 10:36:02 AM	05/10/2023 12:59:02 PM	2:23:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/10/2023 12:59:02 PM	05/10/2023 05:15:50 PM	4:16:48
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/10/2023 05:15:50 PM	05/11/2023 12:55:02 AM	7:39:12
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/11/2023 12:55:02 AM	05/11/2023 08:11:02 AM	7:16:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/11/2023 08:11:02 AM	05/11/2023 09:31:02 AM	1:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/11/2023 09:31:02 AM	05/11/2023 06:39:24 PM	9:8:22
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/11/2023 06:39:24 PM	05/12/2023 09:59:07 AM	15:19:43
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/12/2023 09:59:07 AM	05/12/2023 10:19:01 AM	0:19:54
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/12/2023 10:19:01 AM	05/13/2023 12:35:01 AM	14:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/13/2023 12:35:01 AM	05/13/2023 08:55:01 AM	8:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/13/2023 08:55:01 AM	05/13/2023 12:46:02 PM	3:51:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/13/2023 12:46:02 PM	05/13/2023 02:47:01 PM	2:0:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/13/2023 02:47:01 PM	05/13/2023 05:43:01 PM	2:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/13/2023 05:43:01 PM	05/13/2023 11:03:01 PM	5:20:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/13/2023 11:03:01 PM	05/14/2023 09:03:02 AM	10:0:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/14/2023 09:03:02 AM	05/14/2023 09:39:08 AM	0:36:6
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/14/2023 09:39:08 AM	05/14/2023 02:08:01 PM	4:28:53
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/14/2023 02:08:01 PM	05/14/2023 02:11:01 PM	0:3:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/14/2023 02:11:01 PM	05/14/2023 02:24:03 PM	0:13:2
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/14/2023 02:24:03 PM	05/14/2023 03:03:02 PM	0:38:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/14/2023 03:03:02 PM	05/14/2023 06:51:01 PM	3:47:59

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/14/2023 06:51:01 PM	05/15/2023 09:24:02 AM	14:33:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/15/2023 09:24:02 AM	05/15/2023 04:30:15 PM	7:6:13
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/15/2023 04:30:15 PM	05/15/2023 09:00:02 PM	4:29:47
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/15/2023 09:00:02 PM	05/17/2023 01:25:03 PM	40:25:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/17/2023 01:25:03 PM	05/17/2023 05:21:02 PM	3:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/17/2023 05:21:02 PM	05/18/2023 04:33:02 AM	11:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/18/2023 04:33:02 AM	05/18/2023 10:17:04 AM	5:44:2
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/18/2023 10:17:04 AM	05/18/2023 10:57:01 AM	0:39:57
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/18/2023 10:57:01 AM	05/18/2023 08:25:03 PM	9:28:2
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/18/2023 08:25:03 PM	05/19/2023 04:49:02 AM	8:23:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/19/2023 04:49:02 AM	05/19/2023 08:33:01 AM	3:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/19/2023 08:33:01 AM	05/19/2023 12:57:02 PM	4:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/19/2023 12:57:02 PM	05/19/2023 04:13:40 PM	3:16:38
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/19/2023 04:13:40 PM	05/20/2023 10:17:01 AM	18:3:21
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/20/2023 10:17:01 AM	05/20/2023 11:05:02 AM	0:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/20/2023 11:05:02 AM	05/20/2023 06:11:03 PM	7:6:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/20/2023 06:11:03 PM	05/20/2023 07:01:01 PM	0:49:58

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/20/2023 07:01:01 PM	05/20/2023 09:57:01 PM	2:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/20/2023 09:57:01 PM	05/21/2023 04:49:01 AM	6:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/21/2023 04:49:01 AM	05/21/2023 11:37:02 AM	6:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/21/2023 11:37:02 AM	05/21/2023 01:21:01 PM	1:43:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/21/2023 01:21:01 PM	05/21/2023 07:10:02 PM	5:49:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/21/2023 07:10:02 PM	05/21/2023 08:42:01 PM	1:31:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/21/2023 08:42:01 PM	05/22/2023 05:02:58 PM	20:20:57
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/22/2023 05:02:58 PM	05/22/2023 07:46:01 PM	2:43:3
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/22/2023 07:46:01 PM	05/23/2023 04:38:02 AM	8:52:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/23/2023 04:38:02 AM	05/23/2023 10:50:03 AM	6:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/23/2023 10:50:03 AM	05/23/2023 09:53:01 PM	11:2:58
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/23/2023 09:53:01 PM	05/24/2023 01:09:03 AM	3:16:2
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/24/2023 01:09:03 AM	05/24/2023 12:23:01 PM	11:13:58
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/24/2023 12:23:01 PM	05/24/2023 12:55:01 PM	0:32:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/24/2023 12:55:01 PM	05/24/2023 08:11:01 PM	7:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/24/2023 08:11:01 PM	05/24/2023 09:47:01 PM	1:36:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/24/2023 09:47:01 PM	05/25/2023 12:36:02 PM	14:49:1

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/25/2023 12:36:02 PM	05/25/2023 12:48:01 PM	0:11:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/25/2023 12:48:01 PM	05/25/2023 06:35:02 PM	5:47:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/25/2023 06:35:02 PM	05/26/2023 03:38:01 AM	9:2:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/26/2023 03:38:01 AM	05/26/2023 12:26:02 PM	8:48:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/26/2023 12:26:02 PM	05/27/2023 04:22:01 AM	15:55:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/27/2023 04:22:01 AM	05/27/2023 04:38:01 PM	12:16:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/27/2023 04:38:01 PM	05/27/2023 08:38:01 PM	4:0:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/27/2023 08:38:01 PM	05/28/2023 03:42:01 PM	19:4:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/28/2023 03:42:01 PM	05/28/2023 05:54:02 PM	2:12:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/28/2023 05:54:02 PM	05/29/2023 04:43:02 AM	10:49:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/29/2023 04:43:02 AM	05/29/2023 10:47:01 AM	6:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/29/2023 10:47:01 AM	05/29/2023 01:11:02 PM	2:24:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/29/2023 01:11:02 PM	05/29/2023 07:39:02 PM	6:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/29/2023 07:39:02 PM	05/30/2023 08:25:07 AM	12:46:5
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/30/2023 08:25:07 AM	05/30/2023 08:45:02 AM	0:19:55
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/30/2023 08:45:02 AM	05/30/2023 08:49:01 AM	0:3:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/30/2023 08:49:01 AM	05/30/2023 01:37:01 PM	4:48:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/30/2023 01:37:01 PM	05/31/2023 09:34:02 AM	19:57:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/31/2023 09:34:02 AM	05/31/2023 11:45:02 AM	2:11:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/31/2023 11:45:02 AM	05/31/2023 05:53:02 PM	6:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/31/2023 05:53:02 PM	05/31/2023 06:37:02 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	05/31/2023 06:37:02 PM	05/31/2023 08:05:02 PM	1:28:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/31/2023 08:05:02 PM	05/31/2023 08:49:02 PM	0:44:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	05/31/2023 08:49:02 PM	05/31/2023 10:57:02 PM	2:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	05/31/2023 10:57:02 PM	06/16/2023 03:05:01 PM	376:7:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/16/2023 03:05:01 PM	06/17/2023 06:54:02 PM	27:49:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/17/2023 06:54:02 PM	06/18/2023 01:50:02 AM	6:56:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/18/2023 01:50:02 AM	06/23/2023 08:39:03 AM	126:49:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/23/2023 08:39:03 AM	06/23/2023 10:53:02 AM	2:13:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Red	06/23/2023 10:53:02 AM	06/23/2023 12:55:02 PM	2:2:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/23/2023 12:55:02 PM	06/24/2023 05:25:01 PM	28:29:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/24/2023 05:25:01 PM	06/24/2023 07:33:01 PM	2:8:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/24/2023 07:33:01 PM	06/25/2023 01:25:01 AM	5:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/25/2023 01:25:01 AM	06/25/2023 04:49:01 AM	3:24:0

## Dispenser Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**Status:** All  
**Dispenser Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Dispenser Name	Dispenser Identifier	Dispenser Type	Status	Scanned Date	Status Change Time	Total Time (HH:MM:SS)
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/25/2023 04:49:01 AM	06/25/2023 05:34:02 PM	12:45:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/25/2023 05:34:02 PM	06/25/2023 06:46:02 PM	1:12:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/25/2023 06:46:02 PM	06/26/2023 05:08:30 AM	10:22:28
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/26/2023 05:08:30 AM	06/26/2023 11:56:02 AM	6:47:32
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/26/2023 11:56:02 AM	06/26/2023 07:48:02 PM	7:52:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/26/2023 07:48:02 PM	06/26/2023 08:57:03 PM	1:9:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/26/2023 08:57:03 PM	06/27/2023 08:38:02 PM	23:40:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/27/2023 08:38:02 PM	06/28/2023 06:18:02 AM	9:40:0
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/28/2023 06:18:02 AM	06/28/2023 12:18:03 PM	6:0:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/28/2023 12:18:03 PM	06/28/2023 01:09:02 PM	0:50:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/28/2023 01:09:02 PM	06/28/2023 06:06:03 PM	4:57:1
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Yellow	06/28/2023 06:06:03 PM	06/28/2023 07:27:02 PM	1:20:59
Gate D10 WRR	North Terminal	Gates D	Stall 9 Bath Tissue	97735	Toilet Paper	Green	06/28/2023 07:27:02 PM	07/10/2023 03:18:45 PM	283:51:43

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/08/2023	Monday	00:00	2
							01:00	3
							02:00	5
							03:00	6
							04:00	11
							05:00	14
							06:00	35
							07:00	98
							08:00	153
							09:00	262
							10:00	122
							11:00	77
							12:00	61
							13:00	54
							14:00	94
							15:00	102
							16:00	152
							17:00	127
							18:00	90
							19:00	123
							20:00	136
							21:00	75
							22:00	43
							23:00	24
							<b>Total</b>	<b>1869</b>
					05/09/2023	Tuesday	00:00	4
							01:00	33
							02:00	11
							03:00	8
							04:00	19
							05:00	50
							06:00	33
							07:00	88
							08:00	114
							09:00	188
							10:00	96
							11:00	133
							12:00	146

## Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count							
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/09/2023	Tuesday	13:00	63							
							14:00	43							
							15:00	51							
							16:00	120							
							17:00	139							
							18:00	103							
							19:00	146							
							20:00	115							
							21:00	79							
							22:00	48							
							23:00	15							
							<b>Total</b>							<b>1845</b>	
										05/10/2023	Wednesday	00:00	18		
												01:00	4		
												02:00	4		
												03:00	8		
												04:00	55		
												05:00	21		
												06:00	34		
												07:00	78		
												08:00	115		
												09:00	184		
												10:00	106		
												11:00	122		
							12:00	89							
							13:00	91							
							14:00	118							
							15:00	95							
							16:00	106							
							17:00	66							
							18:00	96							
							19:00	106							
							20:00	147							
							21:00	91							
							22:00	53							
							23:00	17							
<b>Total</b>							<b>1824</b>								
					05/11/2023	Thursday	00:00	16							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/11/2023	Thursday	01:00	1
							02:00	1
							03:00	2
							04:00	13
							05:00	27
							06:00	126
							07:00	102
							08:00	125
							09:00	186
							10:00	141
							11:00	192
							12:00	34
							13:00	55
							14:00	93
							15:00	132
							16:00	74
							17:00	109
							18:00	111
							19:00	132
							20:00	164
					21:00	90		
					22:00	45		
					23:00	28		
					05/12/2023	Friday	00:00	15
							01:00	4
							02:00	2
							03:00	9
							04:00	4
							05:00	22
							06:00	104
							07:00	109
							08:00	127
							09:00	213
							10:00	92
							11:00	131
							12:00	104
							13:00	57

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/12/2023	Friday	14:00	44
							15:00	97
							16:00	112
							17:00	113
							18:00	109
							19:00	178
							20:00	171
							21:00	109
							22:00	55
							23:00	20
							<b>Total</b>	<b>2001</b>
					05/13/2023	Saturday	00:00	10
							01:00	3
							02:00	5
							03:00	4
							04:00	8
							05:00	21
							06:00	52
							07:00	123
							08:00	130
							09:00	166
							10:00	130
							11:00	138
							12:00	139
							13:00	102
							14:00	86
							15:00	127
							16:00	119
							17:00	115
							18:00	97
							19:00	124
							20:00	135
							21:00	91
22:00	43							
23:00	12							
<b>Total</b>	<b>1980</b>							
05/14/2023	Sunday	00:00	20					
		01:00	3					

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count							
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/14/2023	Sunday	02:00	12							
							03:00	6							
							04:00	12							
							05:00	36							
							06:00	37							
							07:00	147							
							08:00	118							
							09:00	193							
							10:00	73							
							11:00	93							
							12:00	71							
							13:00	41							
							14:00	79							
							15:00	83							
							16:00	71							
							17:00	131							
							18:00	151							
							19:00	122							
							20:00	168							
							21:00	98							
							22:00	108							
							23:00	25							
							<b>Total</b>							<b>1898</b>	
												05/15/2023	Monday	00:00	15
														01:00	20
02:00	8														
03:00	14														
04:00	44														
05:00	24														
06:00	72														
07:00	122														
08:00	113														
09:00	257														
10:00	72														
11:00	151														
12:00	107														
13:00	75														
14:00	58														

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/15/2023	Monday	15:00	115
							16:00	162
							17:00	100
							18:00	122
							19:00	123
							20:00	107
							21:00	74
							22:00	17
							23:00	12
							<b>Total</b>	<b>1984</b>
					05/16/2023	Tuesday	00:00	2
							01:00	7
							02:00	4
							03:00	4
							10:00	298
							<b>Total</b>	<b>315</b>
					05/17/2023	Wednesday	13:00	1878
							14:00	126
							15:00	108
							16:00	109
							17:00	128
							18:00	104
							19:00	114
							20:00	146
							21:00	114
							22:00	60
							23:00	13
							<b>Total</b>	<b>2900</b>
					05/18/2023	Thursday	00:00	15
							01:00	8
							02:00	12
							03:00	7
							04:00	11
							05:00	43
							06:00	54
							07:00	82
							08:00	146
					09:00	198		

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count					
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/18/2023	Thursday	10:00	133					
							11:00	128					
							12:00	130					
							13:00	84					
							14:00	142					
							15:00	72					
							16:00	188					
							17:00	126					
							18:00	120					
							19:00	129					
							20:00	133					
							21:00	70					
					22:00	84							
					23:00	22							
					<b>Total</b>							<b>2137</b>	
										05/19/2023	Friday	00:00	4
												01:00	4
												02:00	4
												03:00	4
												04:00	17
												05:00	40
												06:00	41
												07:00	135
												08:00	155
					09:00	277							
					10:00	172							
					11:00	121							
					12:00	103							
					13:00	122							
					14:00	103							
					15:00	115							
					16:00	115							
					17:00	113							
					18:00	141							
					19:00	85							
					20:00	140							
					21:00	81							
					22:00	73							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/19/2023	Friday	23:00	14
							<b>Total</b>	<b>2179</b>
					05/20/2023	Saturday	00:00	2
							01:00	1
							02:00	3
							03:00	5
							04:00	19
							05:00	52
							06:00	70
							07:00	132
							08:00	98
							09:00	239
							10:00	84
							11:00	94
							12:00	148
							13:00	103
							14:00	166
							15:00	65
							16:00	107
							17:00	128
							18:00	172
							19:00	105
					20:00	99		
					21:00	69		
					22:00	38		
					23:00	33		
						<b>Total</b>	<b>2032</b>	
					05/21/2023	Sunday	00:00	10
							01:00	4
							02:00	5
							03:00	5
							04:00	14
							05:00	13
06:00	36							
07:00	63							
08:00	99							
09:00	216							
10:00	113							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count					
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/21/2023	Sunday	11:00	140					
							12:00	116					
							13:00	64					
							14:00	90					
							15:00	113					
							16:00	176					
							17:00	182					
							18:00	164					
							19:00	152					
							20:00	185					
							21:00	135					
							22:00	86					
							23:00	23					
					<b>Total</b>							<b>2204</b>	
										05/22/2023	Monday	00:00	8
												01:00	12
												02:00	8
												03:00	11
												04:00	18
												05:00	55
												06:00	56
												07:00	110
												08:00	160
					09:00	222							
					10:00	102							
					11:00	138							
					12:00	87							
					13:00	34							
					14:00	47							
					15:00	126							
					16:00	128							
					17:00	158							
					18:00	124							
					19:00	232							
					20:00	189							
					21:00	137							
					22:00	37							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/22/2023	Monday	23:00	25
							<b>Total</b>	<b>2224</b>
					05/23/2023	Tuesday	00:00	35
							01:00	14
							02:00	6
							03:00	11
							04:00	14
							05:00	17
							06:00	50
							07:00	104
							08:00	105
							09:00	244
							10:00	55
							11:00	73
							12:00	110
							13:00	69
							14:00	88
							15:00	65
							16:00	133
							17:00	109
							18:00	189
							19:00	126
					20:00	137		
					21:00	105		
					22:00	55		
					23:00	22		
					<b>Total</b>	<b>1936</b>		
					05/24/2023	Wednesday	00:00	10
							01:00	9
							02:00	1
							03:00	9
							04:00	12
							05:00	23
06:00	33							
07:00	115							
08:00	129							
09:00	181							
10:00	154							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/24/2023	Wednesday	11:00	131
							12:00	85
							13:00	72
							14:00	98
							15:00	128
							16:00	119
							17:00	188
							18:00	179
							19:00	129
							20:00	119
							21:00	115
							22:00	116
							23:00	64
						<b>Total</b>	<b>2219</b>	
					05/25/2023	Thursday	00:00	18
							01:00	18
							02:00	4
							03:00	16
							04:00	27
							05:00	50
							06:00	79
							07:00	124
							08:00	67
							09:00	265
10:00	161							
11:00	175							
12:00	151							
13:00	73							
14:00	158							
15:00	152							
16:00	114							
17:00	208							
18:00	144							
19:00	130							
20:00	161							
21:00	100							
22:00	99							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/25/2023	Thursday	23:00	76
							<b>Total</b>	<b>2570</b>
					05/26/2023	Friday	00:00	24
							01:00	13
							02:00	8
							03:00	14
							04:00	23
							05:00	24
							06:00	70
							07:00	141
							08:00	99
							09:00	281
							10:00	77
							11:00	121
							12:00	146
							13:00	182
							14:00	128
							15:00	148
							16:00	34
							17:00	215
							18:00	150
							19:00	208
					20:00	138		
					21:00	58		
					22:00	79		
					23:00	8		
						<b>Total</b>	<b>2389</b>	
					05/27/2023	Saturday	00:00	24
							02:00	10
							03:00	4
							04:00	17
							05:00	24
							06:00	23
07:00	116							
08:00	160							
09:00	200							
10:00	148							
	11:00	150						

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/27/2023	Saturday	12:00	94
							13:00	81
							14:00	124
							15:00	95
							16:00	112
							17:00	95
							18:00	113
							19:00	110
							20:00	131
							21:00	61
							22:00	44
							23:00	19
								<b>Total</b>
					05/28/2023	Sunday	00:00	12
							01:00	1
							02:00	1
							03:00	5
							04:00	13
							05:00	28
							06:00	48
							07:00	95
							08:00	103
							09:00	203
							10:00	119
							11:00	178
12:00	83							
13:00	61							
14:00	121							
15:00	94							
16:00	144							
17:00	126							
18:00	142							
19:00	163							
20:00	89							
21:00	96							
22:00	31							
23:00	18							
	<b>Total</b>	<b>1974</b>						

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/29/2023	Monday	00:00	21
							01:00	8
							02:00	14
							03:00	7
							04:00	19
							05:00	32
							06:00	41
							07:00	97
							08:00	198
							09:00	149
							10:00	64
							11:00	80
							12:00	89
							13:00	91
							14:00	64
							15:00	69
							16:00	139
							17:00	124
							18:00	74
							19:00	152
							20:00	136
							21:00	121
							22:00	45
							23:00	17
							<b>Total</b>	<b>1851</b>
					05/30/2023	Tuesday	00:00	3
							01:00	4
							02:00	5
							03:00	3
							04:00	15
							05:00	44
							06:00	59
							07:00	62
							08:00	119
							09:00	187
							10:00	109
							11:00	140
							12:00	100

### Throughput Count Per Hour Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count							
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/30/2023	Tuesday	13:00	80							
							14:00	100							
							15:00	99							
							16:00	121							
							17:00	112							
							18:00	163							
							19:00	147							
							20:00	207							
							21:00	127							
							22:00	63							
							23:00	87							
					<b>Total</b>							<b>2156</b>			
										05/31/2023	Wednesday	00:00	54		
												01:00	25		
												02:00	17		
												03:00	8		
												04:00	18		
												05:00	34		
												06:00	36		
												07:00	33		
												08:00	96		
												09:00	244		
												10:00	93		
							11:00	150							
							12:00	86							
							13:00	82							
							14:00	114							
							15:00	69							
							16:00	102							
							17:00	97							
							18:00	131							
							19:00	174							
							20:00	126							
							21:00	129							
							22:00	45							
							23:00	21							
							<b>Total</b>	<b>1984</b>							
					06/01/2023	Thursday	00:00	11							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	06/01/2023	Thursday	01:00	1
							02:00	3
							04:00	10
							05:00	29
							06:00	44
							07:00	83
							08:00	159
							09:00	213
							10:00	80
							11:00	23
							<b>Total</b>	<b>656</b>
					06/16/2023	Friday	14:00	110
							15:00	117
							16:00	124
							17:00	141
							18:00	100
							19:00	103
							20:00	114
							21:00	166
							22:00	42
							23:00	14
							<b>Total</b>	<b>1031</b>
					06/17/2023	Saturday	00:00	17
							01:00	15
							02:00	7
							03:00	2
							04:00	17
							05:00	28
							06:00	56
							07:00	89
							08:00	129
							09:00	212
							10:00	85
11:00	118							
12:00	87							
13:00	110							
14:00	110							
15:00	140							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	06/17/2023	Saturday	16:00	120
							17:00	189
							18:00	121
							19:00	127
							20:00	124
							21:00	82
							22:00	49
							23:00	26
							<b>Total</b>	<b>2060</b>
					06/18/2023	Sunday	00:00	28
							01:00	42
							02:00	21
							03:00	18
							04:00	13
							05:00	40
							06:00	57
							07:00	98
							08:00	94
							09:00	50
							10:00	78
							11:00	126
							12:00	70
							13:00	18
							<b>Total</b>	<b>753</b>
					06/23/2023	Friday	08:00	58
							09:00	199
							10:00	143
							11:00	206
							12:00	123
							13:00	117
							14:00	133
							15:00	131
							16:00	83
							17:00	153
							18:00	140
							19:00	121
20:00	126							
21:00	66							

### Throughput Count Per Hour Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	06/23/2023	Friday	22:00	100
							23:00	51
							<b>Total</b>	<b>1950</b>
					06/24/2023	Saturday	00:00	36
							01:00	19
							02:00	4
							03:00	12
							04:00	12
							05:00	13
							06:00	40
							07:00	86
							08:00	143
							09:00	206
							10:00	82
							11:00	165
							12:00	127
							13:00	90
							14:00	96
							15:00	142
							16:00	124
							17:00	122
							18:00	121
							19:00	114
							20:00	143
					21:00	88		
					22:00	129		
					23:00	25		
					<b>Total</b>	<b>2139</b>		
					06/25/2023	Sunday	00:00	38
							01:00	33
							02:00	21
							03:00	21
							04:00	18
05:00	35							
06:00	68							
07:00	117							
08:00	122							
09:00	222							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count					
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	06/25/2023	Sunday	10:00	78					
							11:00	96					
							12:00	90					
							13:00	93					
							14:00	136					
							15:00	144					
							16:00	107					
							17:00	129					
							18:00	130					
							19:00	145					
							20:00	192					
							21:00	119					
							22:00	62					
					23:00	46							
					<b>Total</b>							<b>2262</b>	
										06/26/2023	Monday	00:00	54
												01:00	39
												02:00	16
												03:00	18
												04:00	27
												05:00	42
												06:00	55
												07:00	89
												08:00	89
												09:00	160
					10:00	71							
					11:00	105							
					12:00	109							
					13:00	59							
					14:00	98							
					15:00	89							
					16:00	122							
					17:00	131							
					18:00	108							
					19:00	160							
					20:00	181							
					21:00	72							
					22:00	55							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	06/26/2023	Monday	23:00	16
							<b>Total</b>	<b>1965</b>
					06/27/2023	Tuesday	00:00	24
							01:00	4
							02:00	1
							03:00	4
							04:00	9
							05:00	32
							06:00	63
							07:00	85
							08:00	113
							09:00	189
							10:00	66
							11:00	208
							12:00	70
							13:00	29
							14:00	36
							15:00	67
							16:00	101
							17:00	99
							18:00	126
							19:00	117
					20:00	159		
					21:00	111		
					22:00	43		
					23:00	17		
						<b>Total</b>	<b>1773</b>	
					06/28/2023	Wednesday	00:00	8
							01:00	1
							02:00	4
							03:00	8
							04:00	9
							05:00	13
06:00	102							
07:00	122							
08:00	152							
09:00	187							
10:00	103							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count							
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	06/28/2023	Wednesday	11:00	111							
							12:00	107							
							13:00	114							
							14:00	95							
							15:00	90							
							16:00	104							
							17:00	39							
							18:00	241							
							19:00	140							
							20:00	157							
							21:00	65							
							22:00	41							
					<b>Total</b>							<b>2013</b>			
										07/10/2023	Monday	07:00	31		
												08:00	112		
												09:00	205		
												10:00	86		
												11:00	208		
												12:00	133		
												13:00	88		
					<b>Total</b>							<b>863</b>			
					Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/08/2023	Monday	00:00	2		
01:00	2														
02:00	1														
03:00	1														
04:00	23														
05:00	9														
06:00	39														
07:00	70														
08:00	128														
09:00	171														
10:00	96														
11:00	104														
12:00	49														
13:00	35														
14:00	72														
15:00	63														
16:00	140														

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/08/2023	Monday	17:00	84
							18:00	89
							19:00	93
							20:00	99
							21:00	54
							22:00	30
							23:00	19
							<b>Total</b>	<b>1473</b>
					05/09/2023	Tuesday	00:00	5
							01:00	13
							02:00	2
							03:00	2
							04:00	10
							05:00	41
							06:00	25
							07:00	80
							08:00	97
							09:00	135
							10:00	73
							11:00	134
							12:00	112
							13:00	62
							14:00	26
							15:00	46
							16:00	97
							17:00	108
							18:00	73
							19:00	112
					20:00	97		
					21:00	68		
					22:00	40		
					23:00	19		
					<b>Total</b>	<b>1477</b>		
05/10/2023	Wednesday	00:00	15					
		01:00	18					
		02:00	1					
		03:00	4					
		04:00	32					

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count					
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/10/2023	Wednesday	05:00	20					
							06:00	30					
							07:00	91					
							08:00	92					
							09:00	134					
							10:00	97					
							11:00	105					
							12:00	70					
							13:00	72					
							14:00	76					
							15:00	83					
							16:00	74					
							17:00	60					
							18:00	98					
							19:00	82					
							20:00	139					
							21:00	80					
							22:00	48					
							23:00	3					
						<b>Total</b>	<b>1524</b>						
										05/11/2023	Thursday	00:00	9
												01:00	3
												02:00	1
												04:00	7
												05:00	13
												06:00	115
							07:00	77					
							08:00	118					
							09:00	105					
							10:00	131					
							11:00	139					
							12:00	27					
							13:00	50					
							14:00	92					
							15:00	96					
							16:00	66					
							17:00	100					
							18:00	98					

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/11/2023	Thursday	19:00	101
							20:00	113
							21:00	70
							22:00	32
							23:00	27
							<b>Total</b>	<b>1590</b>
					05/12/2023	Friday	00:00	2
							01:00	4
							02:00	2
							03:00	3
							04:00	4
							05:00	19
							06:00	74
							07:00	96
							08:00	121
							09:00	160
							10:00	52
							11:00	13
							12:00	17
							13:00	10
							14:00	14
							15:00	85
							16:00	100
							17:00	106
							18:00	107
							19:00	159
					20:00	131		
					21:00	73		
					22:00	42		
					23:00	4		
					<b>Total</b>	<b>1398</b>		
					05/13/2023	Saturday	00:00	13
							01:00	1
02:00	1							
03:00	2							
04:00	6							
05:00	22							
06:00	25							



### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/14/2023	Sunday	20:00	122
							21:00	79
							22:00	78
							23:00	15
							<b>Total</b>	<b>1503</b>
					05/15/2023	Monday	00:00	8
							01:00	7
							02:00	3
							03:00	6
							04:00	22
							05:00	14
							06:00	47
							07:00	86
							08:00	103
							09:00	158
							10:00	66
							11:00	128
							12:00	105
							13:00	51
							14:00	41
							15:00	87
							16:00	132
							17:00	80
							18:00	86
							19:00	105
							20:00	87
							21:00	60
							22:00	14
					23:00	2		
					<b>Total</b>	<b>1498</b>		
					05/16/2023	Tuesday	00:00	6
							01:00	4
							02:00	1
							10:00	453
					<b>Total</b>	<b>464</b>		
					05/17/2023	Wednesday	13:00	1635
							14:00	81
							15:00	56

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/17/2023	Wednesday	16:00	92
							17:00	88
							18:00	95
							19:00	83
							20:00	150
							21:00	93
							22:00	51
							23:00	13
							<b>Total</b>	<b>2437</b>
					05/18/2023	Thursday	00:00	6
							01:00	10
							02:00	5
							03:00	7
							04:00	22
							05:00	31
							06:00	47
							07:00	69
							08:00	131
							09:00	139
							10:00	124
							11:00	116
							12:00	79
							13:00	85
							14:00	119
							15:00	47
							16:00	152
							17:00	118
							18:00	89
							19:00	97
							20:00	105
					21:00	55		
					22:00	56		
					23:00	10		
					<b>Total</b>	<b>1719</b>		
					05/19/2023	Friday	00:00	4
							01:00	7
02:00	4							
03:00	3							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count				
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/19/2023	Friday	04:00	18				
							05:00	28				
							06:00	31				
							07:00	112				
							08:00	115				
							09:00	186				
							10:00	159				
							11:00	98				
							12:00	50				
							13:00	103				
							14:00	69				
							15:00	84				
							16:00	68				
							17:00	71				
					18:00	99						
					19:00	67						
					20:00	108						
					21:00	55						
					22:00	49						
					23:00	9						
											<b>Total</b>	<b>1597</b>
									05/20/2023	Saturday	00:00	5
											01:00	2
											02:00	3
				03:00	6							
				04:00	13							
				05:00	45							
				06:00	66							
				07:00	130							
				08:00	84							
				09:00	172							
				10:00	73							
				11:00	121							
				12:00	142							
				13:00	96							
				14:00	119							
				15:00	49							
				16:00	97							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/20/2023	Saturday	17:00	105
							18:00	148
							19:00	105
							20:00	75
							21:00	36
							22:00	38
							23:00	15
							<b>Total</b>	<b>1745</b>
					05/21/2023	Sunday	00:00	6
							01:00	4
							02:00	2
							03:00	3
							04:00	10
							05:00	13
							06:00	22
							07:00	75
							08:00	114
							09:00	160
							10:00	111
							11:00	130
							12:00	96
							13:00	39
							14:00	49
							15:00	79
							16:00	127
							17:00	115
							18:00	121
							19:00	125
							20:00	136
							21:00	109
							22:00	69
					23:00	18		
					<b>Total</b>	<b>1733</b>		
05/22/2023	Monday	00:00	12					
		01:00	5					
		02:00	6					
		03:00	4					
		04:00	11					



### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/23/2023	Tuesday	18:00	150
							19:00	97
							20:00	134
							21:00	97
							22:00	44
							23:00	9
							<b>Total</b>	<b>1465</b>
					05/24/2023	Wednesday	00:00	6
							01:00	7
							02:00	4
							03:00	8
							04:00	3
							05:00	20
							06:00	26
							07:00	84
							08:00	83
							09:00	144
							10:00	76
							11:00	139
							12:00	87
							13:00	74
							14:00	84
							15:00	103
							16:00	89
							17:00	130
							18:00	155
							19:00	128
							20:00	85
					21:00	83		
					22:00	106		
					23:00	46		
					<b>Total</b>	<b>1770</b>		
					05/25/2023	Thursday	00:00	6
01:00	11							
02:00	5							
03:00	6							
04:00	30							
		05:00	33					



### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/26/2023	Friday	19:00	177
							20:00	133
							21:00	64
							22:00	67
							23:00	4
							<b>Total</b>	<b>1903</b>
					05/27/2023	Saturday	00:00	10
							02:00	2
							03:00	2
							04:00	9
							05:00	23
							06:00	22
							07:00	98
							08:00	163
							09:00	158
							10:00	134
							11:00	167
							12:00	91
							13:00	61
							14:00	128
							15:00	65
							16:00	159
							17:00	74
							18:00	98
							19:00	86
							20:00	115
							21:00	42
							22:00	33
							23:00	12
							<b>Total</b>	<b>1752</b>
					05/28/2023	Sunday	00:00	7
							01:00	2
							02:00	2
03:00	4							
04:00	8							
05:00	22							
06:00	37							
07:00	106							



### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/29/2023	Monday	21:00	104
							22:00	26
							23:00	5
							<b>Total</b>	<b>1724</b>
					05/30/2023	Tuesday	00:00	2
							01:00	8
							02:00	2
							03:00	2
							04:00	8
							05:00	53
							06:00	42
							07:00	62
							08:00	117
							09:00	164
							10:00	110
							11:00	117
							12:00	82
							13:00	52
							14:00	98
							15:00	88
							16:00	97
							17:00	92
							18:00	141
							19:00	111
					20:00	142		
					21:00	106		
					22:00	47		
					23:00	47		
					<b>Total</b>	<b>1790</b>		
					05/31/2023	Wednesday	00:00	20
							01:00	15
							02:00	9
							03:00	3
04:00	17							
05:00	19							
06:00	29							
07:00	35							
08:00	105							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/31/2023	Wednesday	09:00	150
							10:00	74
							11:00	133
							12:00	94
							13:00	53
							14:00	79
							15:00	67
							16:00	85
							17:00	85
							18:00	112
							19:00	134
							20:00	109
							21:00	83
					22:00	12		
					23:00	8		
							<b>Total</b>	<b>1530</b>
							06/01/2023	Thursday
							00:00	15
							01:00	3
							02:00	1
							03:00	1
							04:00	17
							05:00	21
		06:00	21					
		07:00	62					
		08:00	113					
		09:00	165					
		10:00	64					
		11:00	13					
		<b>Total</b>	<b>496</b>					
		06/16/2023	Friday					
		14:00	116					
		15:00	89					
		16:00	83					
		17:00	95					
		18:00	85					
		19:00	69					
		20:00	78					
		21:00	104					
		22:00	14					

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	06/16/2023	Friday	23:00	12
							<b>Total</b>	<b>745</b>
					06/17/2023	Saturday	00:00	6
							01:00	4
							02:00	3
							03:00	3
							04:00	7
							05:00	19
							06:00	32
							07:00	73
							08:00	104
							09:00	150
							10:00	82
							11:00	125
							12:00	102
							13:00	59
							14:00	74
							15:00	94
							16:00	118
							17:00	146
							18:00	83
							19:00	93
					20:00	89		
					21:00	54		
					22:00	32		
					23:00	18		
						<b>Total</b>	<b>1570</b>	
					06/18/2023	Sunday	00:00	24
							01:00	41
							02:00	13
							03:00	10
							04:00	20
							05:00	45
06:00	67							
07:00	92							
08:00	132							
09:00	26							
10:00	199							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	06/18/2023	Sunday	11:00	142
							12:00	71
							13:00	11
							<b>Total</b>	<b>893</b>
					06/23/2023	Friday	08:00	72
							09:00	154
							10:00	120
							11:00	162
							12:00	73
							13:00	69
							14:00	102
							15:00	92
							16:00	70
							17:00	110
							18:00	86
							19:00	117
							20:00	103
							21:00	47
							22:00	89
					23:00	41		
					<b>Total</b>	<b>1507</b>		
					06/24/2023	Saturday	00:00	20
							01:00	11
							02:00	8
							03:00	7
							04:00	8
							05:00	3
							06:00	24
							07:00	57
							08:00	108
							09:00	148
							10:00	55
							11:00	136
12:00	110							
13:00	59							
14:00	70							
15:00	101							
16:00	107							

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	06/24/2023	Saturday	17:00	79
							18:00	103
							19:00	95
							20:00	130
							21:00	69
							22:00	90
							23:00	17
							<b>Total</b>	<b>1615</b>
					06/25/2023	Sunday	00:00	30
							01:00	20
							02:00	18
							03:00	8
							04:00	27
							05:00	25
							06:00	46
							07:00	107
							08:00	93
							09:00	176
							10:00	79
							11:00	108
							12:00	74
							13:00	75
							14:00	92
							15:00	131
							16:00	102
							17:00	119
							18:00	93
							19:00	99
							20:00	154
							21:00	103
					22:00	61		
					23:00	34		
					<b>Total</b>	<b>1874</b>		
06/26/2023	Monday	00:00	29					
		01:00	14					
		02:00	10					
		03:00	16					
		04:00	20					

### Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count					
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	06/26/2023	Monday	05:00	19					
							06:00	42					
							07:00	61					
							08:00	80					
							09:00	135					
							10:00	64					
							11:00	99					
							12:00	87					
							13:00	45					
							14:00	60					
							15:00	63					
							16:00	120					
							17:00	106					
							18:00	77					
							19:00	135					
							20:00	149					
							21:00	64					
							22:00	64					
							23:00	14					
						<b>Total</b>	<b>1573</b>						
										06/27/2023	Tuesday	00:00	11
												01:00	4
												02:00	8
												03:00	10
												04:00	4
												05:00	26
							06:00	49					
							07:00	82					
							08:00	108					
							09:00	131					
							10:00	62					
							11:00	165					
							12:00	51					
							13:00	26					
							14:00	38					
							15:00	50					
							16:00	84					
							17:00	68					

### Throughput Count Per Hour Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Day Hour (HH:MM)	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	06/27/2023	Tuesday	18:00	102
							19:00	81
							20:00	140
							21:00	109
							22:00	29
							23:00	6
							<b>Total</b>	<b>1444</b>
					06/28/2023	Wednesday	00:00	1
							01:00	2
							03:00	3
							04:00	4
							05:00	9
							06:00	91
							07:00	107
							08:00	117
							09:00	160
							10:00	83
							11:00	111
							12:00	121
							13:00	96
							14:00	77
							15:00	64
							16:00	88
							17:00	29
							18:00	168
							19:00	116
							20:00	148
							21:00	42
							22:00	20
					<b>Total</b>	<b>1657</b>		
					07/10/2023	Monday	07:00	29
							08:00	81
							09:00	157
10:00	73							
11:00	183							
12:00	90							
13:00	58							
<b>Total</b>	<b>671</b>							

# Throughput Count Per Hour Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

<b>Total</b>									<b>119292</b>
--------------	--	--	--	--	--	--	--	--	---------------

## Throughput Count Per Day Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	05/08/2023	Monday	1869
					05/09/2023	Tuesday	1845
					05/10/2023	Wednesday	1824
					05/11/2023	Thursday	1999
					05/12/2023	Friday	2001
					05/13/2023	Saturday	1980
					05/14/2023	Sunday	1898
					05/15/2023	Monday	1984
					05/16/2023	Tuesday	315
					05/17/2023	Wednesday	2900
					05/18/2023	Thursday	2137
					05/19/2023	Friday	2179
					05/20/2023	Saturday	2032
					05/21/2023	Sunday	2204
					05/22/2023	Monday	2224
					05/23/2023	Tuesday	1936
					05/24/2023	Wednesday	2219
					05/25/2023	Thursday	2570
					05/26/2023	Friday	2389
					05/27/2023	Saturday	1955
					05/28/2023	Sunday	1974
					05/29/2023	Monday	1851
					05/30/2023	Tuesday	2156
					05/31/2023	Wednesday	1984
					06/01/2023	Thursday	656
					06/16/2023	Friday	1031
					06/17/2023	Saturday	2060
					06/18/2023	Sunday	753
					06/23/2023	Friday	1950
					06/24/2023	Saturday	2139
					06/25/2023	Sunday	2262
					06/26/2023	Monday	1965
06/27/2023	Tuesday	1773					
06/28/2023	Wednesday	2013					
07/10/2023	Monday	642					
<b>Total</b>							<b>65669</b>
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/08/2023	Monday	1473
					05/09/2023	Tuesday	1477
					05/10/2023	Wednesday	1524
					05/11/2023	Thursday	1590
					05/12/2023	Friday	1398
					05/13/2023	Saturday	1761
					05/14/2023	Sunday	1503
					05/15/2023	Monday	1498
					05/16/2023	Tuesday	464
					05/17/2023	Wednesday	2437
					05/18/2023	Thursday	1719
					05/19/2023	Friday	1597
					05/20/2023	Saturday	1745
					05/21/2023	Sunday	1733
					05/22/2023	Monday	1808
					05/23/2023	Tuesday	1465
					05/24/2023	Wednesday	1770
					05/25/2023	Thursday	1952
					05/26/2023	Friday	1903
					05/27/2023	Saturday	1752
05/28/2023	Sunday	1744					
05/29/2023	Monday	1724					
05/30/2023	Tuesday	1790					

### Throughput Count Per Day Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Date	Day	Visitor Count
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	05/31/2023	Wednesday	1530
					06/01/2023	Thursday	496
					06/16/2023	Friday	745
					06/17/2023	Saturday	1570
					06/18/2023	Sunday	893
					06/23/2023	Friday	1507
					06/24/2023	Saturday	1615
					06/25/2023	Sunday	1874
					06/26/2023	Monday	1573
					06/27/2023	Tuesday	1444
					06/28/2023	Wednesday	1657
					07/10/2023	Monday	523
					<b>Total</b>		
<b>Total</b>							<b>118923</b>

# Throughput Count Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Location	Building	Zone	Sensor Name	Sensor Identifier	Total Visitor Count
Gate D10 MRR	North Terminal	Gates D	D10 Men PC-CM	23615	65528
Gate D10 WRR	North Terminal	Gates D	D10 Women PC CM	23614	53120

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:00:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:53:00 PM	Positive		:) 10
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:55:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 02:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:09:00 PM	Positive		El baño esta excelente todo muy limpio
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:34:00 PM	Positive		Very good
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:35:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 03:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:43:00 PM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 04:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:26:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:26:00 PM	Positive		Was perfect
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:28:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:38:00 PM	Positive		Super clean
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 05:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:08:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Litter on the floor	Clean
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:11:00 PM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:18:00 PM	Positive		Excelent services
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:41:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 06:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:28:00 PM	Positive		Ok
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:36:00 PM	Positive		Perfect
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 07:48:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/10/2023 07:58:00 PM	Positive		The lady that clean the bathroom do and amazing job
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:00:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:01:00 PM	Positive		Great
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:08:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:09:00 PM	Positive		Finish
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:28:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:28:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:31:00 PM	Neutral	No Paper Towels, Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:37:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 08:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 08:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:07:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:33:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 09:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:53:00 PM	Positive		Fix it
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 10:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 10:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 10:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 10:11:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/10/2023 10:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 10:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 10:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/10/2023 10:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 10:31:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/10/2023 10:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 10:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 11:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/10/2023 11:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 12:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 03:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:20:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 04:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 05:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 05:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 05:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 06:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 06:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 06:14:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	D
North Terminal	Gates D	Gate D10 MRR	05/11/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 06:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 06:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 06:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 06:51:00 AM	Positive		Buenicimo
North Terminal	Gates D	Gate D10 WRR	05/11/2023 06:53:00 AM	Positive		Very good
North Terminal	Gates D	Gate D10 WRR	05/11/2023 06:53:00 AM	Positive		Goog
North Terminal	Gates D	Gate D10 WRR	05/11/2023 06:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 07:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 08:07:00 AM	Negative	Smell	No
North Terminal	Gates D	Gate D10 WRR	05/11/2023 08:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 08:48:00 AM	Positive		Nice and clean
North Terminal	Gates D	Gate D10 WRR	05/11/2023 09:02:00 AM	Positive		

## Feedback Summary Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/11/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 09:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 09:14:00 AM	Positive		Very good
North Terminal	Gates D	Gate D10 WRR	05/11/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 10:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 11:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 11:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:35:00 AM	Positive		Muy biem
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:39:00 AM	Positive		Muy muedo
North Terminal	Gates D	Gate D10 WRR	05/11/2023 11:40:00 AM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:42:00 AM	Positive		Lindo
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:48:00 AM	Positive		Acojedor
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:49:00 AM	Positive		Bueno
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:51:00 AM	Positive		Super
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:52:00 AM	Positive		Huele bien
North Terminal	Gates D	Gate D10 MRR	05/11/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 12:13:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 12:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:08:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:16:00 PM	Negative	Other	Toilet had fecus on it
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:17:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:35:00 PM	Positive		Muy limpio
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:55:00 PM	Neutral	Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 01:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:42:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 02:48:00 PM	Negative	Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 03:14:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 03:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 03:23:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 03:24:00 PM	Negative	Smell	Smell really bad
North Terminal	Gates D	Gate D10 WRR	05/11/2023 03:38:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:02:00 PM	Positive		Very good
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:08:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:09:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:40:00 PM	Positive		Amazing service from the cleaning team
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:45:00 PM	Negative	Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 04:53:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/11/2023 05:20:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/11/2023 09:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/11/2023 09:54:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	05/11/2023 10:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/15/2023 08:56:00 AM	Positive		Johnathan test
North Terminal	Gates D	Gate D10 MRR	05/15/2023 08:58:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/15/2023 09:10:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/16/2023 11:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:12:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:50:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:53:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 01:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 02:13:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/17/2023 02:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 02:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 02:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 02:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 03:54:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:11:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:47:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/17/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:02:00 PM	Positive		Gg
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 06:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:23:00 PM	Positive		Excelente banos super limpios
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 07:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:31:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 08:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 09:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 09:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 09:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 09:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 09:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/17/2023 10:37:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:02:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/17/2023 11:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:10:00 AM	Positive		Muy bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:29:00 AM	Positive		Limpio
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:33:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:52:00 AM	Positive		Thank
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:19:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:44:00 AM	Negative	Other	More toilets
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:53:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:00:00 AM	Neutral	Dirty Walls	No
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:23:00 AM	Positive		Super
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:40:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:42:00 AM	Positive		Super bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:49:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:50:00 AM	Positive		Muy good el bano
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:56:00 AM	Positive		Super todo
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:58:00 AM	Positive		Olor bueno
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:00:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:04:00 AM	Positive		Todo recojido
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:09:00 AM	Positive		Limpio todo
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:15:00 AM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:20:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:44:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:10:00 AM	Positive		Horrible
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:18:00 AM	Negative	Wet/Dirty Counters, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:10:00 AM	Positive		Todo limpio

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:35:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:39:00 PM	Negative	Smell	Stinks
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 12:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:05:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:46:00 PM	Positive		Limpio
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:47:00 PM	Positive		Super el bano
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:49:00 PM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:51:00 PM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 01:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 02:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 02:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 02:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 02:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 02:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 02:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:48:00 PM	Positive		Good condition this r r

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 03:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:18:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 04:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 05:47:00 PM	Positive		Great
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:21:00 PM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 06:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:25:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 07:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:10:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 08:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 09:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:36:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/18/2023 10:46:00 PM	Positive		Brasil
North Terminal	Gates D	Gate D10 MRR	05/18/2023 11:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 03:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 05:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 05:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 05:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:09:00 AM	Positive		Super

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:17:00 AM	Positive		Muy bien
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:54:00 AM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:16:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:21:00 AM	Positive		Super limpio
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:50:00 AM	Positive		Ok
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:11:00 AM	Negative	Dirty Mirrors	Stink
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:12:00 AM	Positive		Excelent
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:50:00 AM	Positive		Very clean
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:57:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:10:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:28:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:24:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:30:00 AM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:33:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:42:00 AM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:02:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:03:00 AM	Positive		Super
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:31:00 AM	Neutral	Other	No
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:31:00 AM	Neutral	Other	No
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:45:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:03:00 PM	Negative	Smell, Litter on the floor	No
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:12:00 PM	Negative	Other	No
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:31:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:36:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:43:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 12:56:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:44:00 PM	Negative	Litter on the floor	And smell
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:44:00 PM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:45:00 PM	Positive		Muy super bueno
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 01:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:42:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:48:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 02:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 04:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 05:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 05:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 05:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 06:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:54:00 PM	Positive		Yes
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:54:00 PM	Positive		yes
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:55:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:55:00 PM	Positive		Yes
North Terminal	Gates D	Gate D10 MRR	05/19/2023 07:56:00 PM	Positive		Very good
North Terminal	Gates D	Gate D10 MRR	05/19/2023 08:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:34:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 09:54:00 PM	Neutral	Other	No soap
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:03:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/19/2023 10:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 04:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 04:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 06:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 06:18:00 AM	Negative	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 MRR	05/20/2023 07:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 07:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 08:38:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/20/2023 08:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 09:29:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/20/2023 10:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 10:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 10:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 10:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 11:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 11:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 12:14:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/20/2023 12:18:00 PM	Positive		Excelen clean
North Terminal	Gates D	Gate D10 MRR	05/20/2023 12:32:00 PM	Negative		Sucio
North Terminal	Gates D	Gate D10 MRR	05/20/2023 12:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 01:42:00 PM	Positive		All,good
North Terminal	Gates D	Gate D10 MRR	05/20/2023 02:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 02:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 02:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 02:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 03:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 03:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 04:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 07:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 08:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 08:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 09:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 10:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/20/2023 11:48:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 02:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 02:52:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/21/2023 03:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 04:25:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/21/2023 04:50:00 AM	Positive		It's clean and smell good
North Terminal	Gates D	Gate D10 MRR	05/21/2023 05:31:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/21/2023 06:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 08:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 08:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 08:46:00 AM	Negative		Sucio
North Terminal	Gates D	Gate D10 MRR	05/21/2023 08:54:00 AM	Negative		Asqueroso
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:12:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:45:00 AM	Negative	Dirty Walls	Sucio
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:06:00 PM	Positive		More ventalation
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:21:00 PM	Negative		Muy sucio
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 12:38:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/21/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 03:41:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	05/21/2023 03:48:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/21/2023 04:18:00 PM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	05/21/2023 04:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 04:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 04:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 05:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 06:16:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	05/21/2023 06:22:00 PM	Negative	Smell	Stink
North Terminal	Gates D	Gate D10 MRR	05/21/2023 06:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 07:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 07:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 07:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 08:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:12:00 PM	Positive		It was very clean
North Terminal	Gates D	Gate D10 MRR	05/21/2023 09:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 10:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 10:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/21/2023 11:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 01:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 04:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 06:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 07:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 07:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 10:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 10:44:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/22/2023 10:46:00 AM	Neutral	Other	No
North Terminal	Gates D	Gate D10 MRR	05/22/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 11:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 11:21:00 AM	Positive		Good job, congratulations
North Terminal	Gates D	Gate D10 MRR	05/22/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 01:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 01:35:00 PM	Positive		God
North Terminal	Gates D	Gate D10 MRR	05/22/2023 01:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 01:40:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/22/2023 02:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 02:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 02:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 03:29:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/22/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 04:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 05:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 06:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 06:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 07:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 08:03:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	05/22/2023 08:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 08:49:00 PM	Positive		Guy working cleaned good.
North Terminal	Gates D	Gate D10 MRR	05/22/2023 08:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 09:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/22/2023 10:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 12:25:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/23/2023 12:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 02:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 03:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 04:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 05:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 06:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 06:35:00 AM	Positive		Muy clean
North Terminal	Gates D	Gate D10 MRR	05/23/2023 07:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 07:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 08:12:00 AM	Positive		Dey clean
North Terminal	Gates D	Gate D10 MRR	05/23/2023 08:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 08:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 08:19:00 AM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/23/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 11:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 11:49:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/23/2023 12:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 12:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 01:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 02:11:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/23/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 02:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 02:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 03:10:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/23/2023 03:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 03:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 04:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 04:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 04:35:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/23/2023 04:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 04:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 05:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 06:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 06:28:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/23/2023 06:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 07:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 07:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 08:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 08:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/23/2023 09:20:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/23/2023 09:47:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/23/2023 09:54:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	05/23/2023 11:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 04:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 06:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 06:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 08:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:19:00 AM	Positive		Test
North Terminal	Gates D	Gate D10 MRR	05/24/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:34:00 AM	Positive		It cool

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:05:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:14:00 AM	Neutral	Other	Hot
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:27:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 11:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 11:28:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:54:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:55:00 AM	Neutral	Other	Not AC
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 12:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 12:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 12:34:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 12:35:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Hb
North Terminal	Gates D	Gate D10 WRR	05/24/2023 12:46:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 01:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 01:38:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 01:43:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	05/24/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 02:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:26:00 PM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:27:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 02:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 02:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 03:33:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:43:00 PM	Positive		Excelente, todo muy limpio
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:44:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 03:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 03:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 04:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 04:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 04:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 04:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 04:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 05:14:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 05:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 05:48:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 05:50:00 PM	Neutral	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 05:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 05:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 06:08:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:21:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:29:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:32:00 PM	Neutral	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:33:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor, Other	Dirty diaper on counter
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:43:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 06:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 06:54:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 06:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:00:00 PM	Positive		Beautiful restroom
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:00:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:13:00 PM	Neutral	No Paper Towels, Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:15:00 PM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:18:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:22:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:35:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:35:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:43:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:48:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:51:00 PM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	05/24/2023 07:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 07:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 08:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 08:52:00 PM	Positive		Mjgh
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:23:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:27:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:35:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 09:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:39:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:54:00 PM	Positive		Ok everything
North Terminal	Gates D	Gate D10 WRR	05/24/2023 09:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:21:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor, Other	O
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:22:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:24:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:25:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:25:00 PM	Negative	Wet/Dirty Counters, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:28:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 10:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:34:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:44:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:49:00 PM	Positive		All clean
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:57:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 10:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:12:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:24:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	Bathroom completely unattended...no one here to clean
North Terminal	Gates D	Gate D10 WRR	05/24/2023 11:41:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/24/2023 11:50:00 PM	Neutral	Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:36:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:42:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:43:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 06:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:31:00 AM	Positive		Muy bien limpio
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:55:00 AM	Positive		Mucho bueno
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:59:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 WRR	05/25/2023 07:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 07:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:06:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/25/2023 07:15:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	05/25/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 08:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 08:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 08:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 08:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 08:40:00 AM	Positive		Es bueno muy limpio
North Terminal	Gates D	Gate D10 WRR	05/25/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 08:42:00 AM	Positive		Por favor si no tienen enque gastar el dinero delen un bono ca 6 meses a estas empleadas que trabajan tanto porque estas tablet los muchachos las cojen para jugar y las rompen por favor asi se estimul
North Terminal	Gates D	Gate D10 WRR	05/25/2023 08:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 09:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 09:20:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 09:51:00 AM	Negative	Smell	No
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:18:00 AM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 10:42:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 10:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:00:00 AM	Negative	Smell	Yes this bathroom needs disinfectant and fabulisa. It smells terrible. The paper towels terrible. help the ladies thank you
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:16:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:21:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:24:00 AM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:37:00 AM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 11:55:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:00:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:01:00 PM	Negative	Smell, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:02:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:05:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:07:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:13:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:16:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:30:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:33:00 PM	Positive		Good job
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 12:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:46:00 PM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/25/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:03:00 PM	Positive		Ok
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:10:00 PM	Positive		Small' busy restroom but well managed by employee
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:27:00 PM	Positive		Great
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 01:42:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:43:00 PM	Positive		Super especial
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:43:00 PM	Positive		Limpio
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 01:47:00 PM	Positive		Ok

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:03:00 PM	Positive		Good survice
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:20:00 PM	Neutral	Smell	Yes i think you should fix the lock in stall number 3.
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:23:00 PM	Neutral	Other	Broken door locks
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:36:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:43:00 PM	Neutral	Other	Broken door lock
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:50:00 PM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 02:56:00 PM	Negative	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 02:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 02:59:00 PM	Negative	No Paper Towels, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:09:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:09:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 03:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:20:00 PM	Positive		It was great
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 03:53:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 03:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:01:00 PM	Neutral	Litter on the floor	

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:05:00 PM	Neutral	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 04:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 05:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 05:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 05:36:00 PM	Positive		Clean thank you
North Terminal	Gates D	Gate D10 WRR	05/25/2023 05:40:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 05:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 06:09:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/25/2023 06:09:00 PM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 06:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/25/2023 06:37:00 PM	Positive		Good' excelent
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:18:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:30:00 PM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 07:58:00 PM	Positive		W BATHROOM
North Terminal	Gates D	Gate D10 MRR	05/25/2023 08:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:10:00 PM	Negative	No Supplies e.g. Soaps/Paper	No soap....
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:16:00 PM	Neutral	Smell, Dirty Walls	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:20:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 10:21:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/25/2023 11:16:00 PM	Neutral		Dirty floor
North Terminal	Gates D	Gate D10 MRR	05/26/2023 04:00:00 AM	Positive		Why is always wet
North Terminal	Gates D	Gate D10 MRR	05/26/2023 05:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:13:00 AM	Positive		Mhhh
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:19:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:16:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:24:00 AM	Positive		Thanks
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:30:00 AM	Positive		Good job
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:30:00 AM	Positive		Na
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:34:00 AM	Positive		Super todo
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 07:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:57:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:05:00 AM	Positive		Recuerden no gasten dinero en tab denle bono
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:09:00 AM	Neutral	Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:40:00 AM	Negative	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:44:00 AM	Positive		None
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:06:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:53:00 AM	Negative	Smell	I dont know
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 10:15:00 AM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:23:00 AM	Negative	Smell, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 10:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:40:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 10:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 10:58:00 AM	Positive		clean
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:04:00 AM	Negative		Rude attendant
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:23:00 AM	Positive		Ok
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:25:00 AM	Positive		Bueno esto
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:59:00 AM	Positive		It didnt have any soap on some sinks
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:06:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:25:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/26/2023 12:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 12:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 12:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:20:00 PM	Negative	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:22:00 PM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:23:00 PM	Positive		Ecelente todo
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:32:00 PM	Positive		Muy bien esto
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 01:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:53:00 PM	Positive		Ok
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 01:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 01:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 01:57:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	05/26/2023 02:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:29:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 03:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 03:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 03:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 03:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 03:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 04:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 04:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 04:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 04:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 04:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 05:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 05:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 05:12:00 PM	Positive		All good
North Terminal	Gates D	Gate D10 MRR	05/26/2023 05:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 05:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 05:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 05:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 05:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 05:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 06:00:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 06:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 06:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 06:50:00 PM	Neutral	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 06:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 06:55:00 PM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 07:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:03:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	Disgusting
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:07:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Fuch u
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:41:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/26/2023 08:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 08:59:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:04:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:23:00 PM	Positive		Smells bad
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:45:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:49:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:49:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	05/26/2023 09:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 09:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/26/2023 11:18:00 PM	Neutral	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:03:00 AM	Negative	Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 04:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 04:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 04:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 06:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:03:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:33:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/27/2023 08:45:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:35:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/27/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:41:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:55:00 AM	Neutral	Smell, Other	Air freshner
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:03:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 10:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 10:19:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:22:00 AM	Positive		Na
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:29:00 AM	Neutral	No Paper Towels, Other	Wel o th e r t a hhhhhsb ns a nnnnnn
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:31:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 10:37:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 11:01:00 AM	Neutral	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 11:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 11:44:00 AM	Negative	No Paper Towels, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:04:00 PM	Negative		Sucioooo
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:08:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:25:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	05/27/2023 12:33:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:43:00 PM	Positive		I am so happy to go to jordan and see my cosins and i am i little sad my dad is not coming
North Terminal	Gates D	Gate D10 MRR	05/27/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 01:21:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	05/27/2023 01:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 01:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 02:14:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 02:18:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/27/2023 02:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 02:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 02:32:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 02:42:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 02:55:00 PM	Positive		Rsc
North Terminal	Gates D	Gate D10 MRR	05/27/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 03:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 03:05:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:08:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:15:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/27/2023 03:16:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 03:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 04:16:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 04:22:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 04:38:00 PM	Positive		Love
North Terminal	Gates D	Gate D10 WRR	05/27/2023 04:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:04:00 PM	Positive		Cleaner
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:17:00 PM	Positive		Thanks!
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:35:00 PM	Neutral	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 05:59:00 PM	Positive		Love
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:34:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:50:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:51:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 06:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:00:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	This is a gross bathroom
North Terminal	Gates D	Gate D10 MRR	05/27/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/27/2023 07:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:11:00 PM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/27/2023 07:13:00 PM	Positive		Very good
North Terminal	Gates D	Gate D10 MRR	05/27/2023 07:23:00 PM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:36:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/27/2023 07:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 07:50:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:04:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:15:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:16:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:18:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/27/2023 08:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:37:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:42:00 PM	Positive		Shes great
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 08:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 09:29:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:26:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:46:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/27/2023 10:52:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/27/2023 11:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:50:00 AM	Positive		Very good
North Terminal	Gates D	Gate D10 WRR	05/28/2023 06:37:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/28/2023 06:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:58:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Bad
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:02:00 AM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:24:00 AM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:50:00 AM	Neutral	Smell	Tganjs
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:53:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	Ew
North Terminal	Gates D	Gate D10 MRR	05/28/2023 08:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 09:30:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Very bad
North Terminal	Gates D	Gate D10 WRR	05/28/2023 09:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:09:00 AM	Neutral	Wet Floor, Smell, Litter on the floor, Other	Very bad smell
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:12:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/28/2023 10:22:00 AM	Negative		Muy suvio
North Terminal	Gates D	Gate D10 MRR	05/28/2023 10:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 10:58:00 AM	Positive		Good

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:17:00 AM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:25:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:25:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:37:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:45:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:57:00 AM	Negative	Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 12:10:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Litter on the floor	Disgusting
North Terminal	Gates D	Gate D10 WRR	05/28/2023 12:11:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 12:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 12:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 01:07:00 PM	Negative		Puerquisimo
North Terminal	Gates D	Gate D10 MRR	05/28/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 01:27:00 PM	Positive		Right
North Terminal	Gates D	Gate D10 MRR	05/28/2023 01:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 01:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 01:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 02:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 02:09:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Litter on the floor	All is unacceptable
North Terminal	Gates D	Gate D10 MRR	05/28/2023 02:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 02:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 02:57:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 03:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 03:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 04:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 04:40:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 05:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 05:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 05:37:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 05:48:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	05/28/2023 05:51:00 PM	Positive		.j
North Terminal	Gates D	Gate D10 WRR	05/28/2023 05:56:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	05/28/2023 06:30:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 06:50:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/28/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 06:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 06:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:03:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:03:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:07:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:19:00 PM	Negative	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 07:41:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 07:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 07:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 07:52:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:07:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:14:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors	clean better
North Terminal	Gates D	Gate D10 MRR	05/28/2023 08:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:45:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:48:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 08:56:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 09:00:00 PM	Positive		It would be better if it had good smell
North Terminal	Gates D	Gate D10 WRR	05/28/2023 09:04:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 09:07:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/28/2023 09:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/28/2023 09:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/28/2023 09:49:00 PM	Negative	Smell, Dirty Stalls or Urinals	Bad odor
North Terminal	Gates D	Gate D10 MRR	05/28/2023 09:52:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:05:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/28/2023 11:07:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 12:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 12:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 01:59:00 AM	Positive		It is find
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 04:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 06:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:32:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 07:16:00 AM	Positive		Limpo e perfumado.....nota dez !!!!!
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 07:30:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:01:00 AM	Positive		Thank you
North Terminal	Gates D	Gate D10 MRR	05/29/2023 08:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 08:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:17:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:21:00 AM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:31:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:39:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 08:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:51:00 AM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 09:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 09:29:00 AM	Negative	Wet Floor	Fix toilets
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 10:16:00 AM	Positive		It was neat.
North Terminal	Gates D	Gate D10 WRR	05/29/2023 10:26:00 AM	Negative	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 10:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 10:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:10:00 AM	Negative	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 11:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:27:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 11:52:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	Do better
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 12:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 12:08:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/29/2023 12:27:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 12:31:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 12:42:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell	No
North Terminal	Gates D	Gate D10 WRR	05/29/2023 12:54:00 PM	Negative	Dirty Stalls or Urinals, Litter on the floor	Smells terrible
North Terminal	Gates D	Gate D10 MRR	05/29/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 01:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 02:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 02:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 02:44:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:32:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 03:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:47:00 PM	Positive		The best
North Terminal	Gates D	Gate D10 MRR	05/29/2023 03:58:00 PM	Positive		Smelt nice
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:58:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 03:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:00:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 04:01:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:03:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	This bathroom needs a upgrade or clean
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:03:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Clean it
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:08:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:14:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:17:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 04:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:50:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 04:53:00 PM	Positive		Good job
North Terminal	Gates D	Gate D10 WRR	05/29/2023 04:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 05:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 05:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:21:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:22:00 PM	Negative	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:22:00 PM	Positive		Bad
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:29:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 05:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:02:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:10:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:14:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 06:15:00 PM	Positive		Stolls need service
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:16:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:31:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Nasty
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 07:45:00 PM	Neutral	Smell	Smell like marihuana
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:39:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/29/2023 08:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 08:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:05:00 PM	Neutral	Smell	Smells urine
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:10:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 09:31:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	05/29/2023 10:13:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 10:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 10:33:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	05/29/2023 11:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:47:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/29/2023 11:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 12:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 04:03:00 AM	Positive		Limpio
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:35:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:36:00 AM	Positive		Thx
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 05:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 06:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:28:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:24:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/30/2023 07:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:31:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:39:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:17:00 AM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	05/30/2023 08:36:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	05/30/2023 08:37:00 AM	Neutral	Dirty Mirrors, Dirty Stalls or Urinals	Hiooooo
North Terminal	Gates D	Gate D10 MRR	05/30/2023 08:38:00 AM	Positive		Hhsbfggggndfnbbddd dd ssssbfnfgfg fggfff f ffg f fhfh gghgh t ht ffmntmtmyyyhhh,hhh? hhjh??h? hj,hju,uiuuuiyg ?? jghhghggmgggmg? hgm?ggg? g,hhh,yyy,yyy,uuuuuu uumggghhhhhhhhhn ggghhh ggg ggg ggg g
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 09:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 09:54:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 10:02:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 10:55:00 AM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:14:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:23:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:32:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:33:00 AM	Neutral	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 11:55:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 12:07:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 12:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 12:31:00 PM	Neutral	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 12:56:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 12:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 01:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:50:00 PM	Negative	Smell	Clean it please
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:52:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 01:53:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	Ugly *** bathroom
North Terminal	Gates D	Gate D10 MRR	05/30/2023 01:55:00 PM	Positive		Good job
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:21:00 PM	Negative	No Paper Towels, Dirty Walls, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:38:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/30/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 02:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:42:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 02:44:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:09:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:10:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:49:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 03:53:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:03:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:19:00 PM	Positive		Very clean. thank you
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 04:27:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:39:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 04:45:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:23:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:31:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:33:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 05:50:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:01:00 PM	Neutral	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:07:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/30/2023 06:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:17:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:24:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:27:00 PM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:30:00 PM	Negative	Wet Floor, Smell, Other	Bug
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:31:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/30/2023 06:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 06:52:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:01:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:43:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Gurk yo booty stamnk
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:46:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 07:58:00 PM	Negative	Wet/Dirty Counters, Smell	

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:11:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:15:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:23:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	Bug
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:27:00 PM	Negative	Other	Roaches, broken locks, no purse hook.
North Terminal	Gates D	Gate D10 MRR	05/30/2023 08:40:00 PM	Positive		Smell bad
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:47:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 08:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:35:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 09:39:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 10:04:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:21:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:27:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:34:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/30/2023 11:54:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/31/2023 12:03:00 AM	Negative	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:15:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:43:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:09:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:10:00 AM	Negative	No Paper Towels, Smell, Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:19:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:32:00 AM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:34:00 AM	Negative	Smell, Dirty Mirrors, Litter on the floor	Do better
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:36:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	05/31/2023 05:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 05:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 06:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 06:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 06:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 06:52:00 AM	Positive		Good ****
North Terminal	Gates D	Gate D10 MRR	05/31/2023 07:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:39:00 AM	Neutral	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:49:00 AM	Positive		Good job
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:59:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:01:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/31/2023 08:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 08:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:20:00 AM	Neutral	Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 08:28:00 AM	Positive		Good cleaning
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:38:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:44:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:51:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 09:07:00 AM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:45:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:46:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:22:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	05/31/2023 10:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 11:01:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Dirty Walls, Litter on the floor	Hhgh

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	05/31/2023 11:10:00 AM	Positive		One of the sinks do not stop gushing water
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 11:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:00:00 PM	Neutral	Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:20:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:24:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:53:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 01:54:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:08:00 PM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:21:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 02:51:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 03:06:00 PM	Negative	Smell	.

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/31/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 03:13:00 PM	Positive		Restroom in good conditions
North Terminal	Gates D	Gate D10 WRR	05/31/2023 03:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 03:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 03:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 04:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 04:09:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/31/2023 04:20:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 04:22:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Mirrors, Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 WRR	05/31/2023 04:23:00 PM	Negative	Other	Hot
North Terminal	Gates D	Gate D10 WRR	05/31/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 04:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:03:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:19:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:21:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:44:00 PM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 05:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 06:35:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 06:35:00 PM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 06:38:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 06:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 07:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 07:11:00 PM	Neutral		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:35:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:43:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:46:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 07:57:00 PM	Neutral	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:17:00 PM	Neutral	Wet/Dirty Counters, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:31:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:37:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	05/31/2023 08:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 08:47:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:15:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	05/31/2023 09:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:19:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 MRR	05/31/2023 09:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 09:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	05/31/2023 09:50:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:02:00 PM	Negative	No Supplies e.g. Soaps/Paper	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	05/31/2023 10:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	05/31/2023 11:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 12:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 12:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 12:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 03:52:00 AM	Negative	Dirty Stalls or Urinals, Litter on the floor	Keep the bathroom clead
North Terminal	Gates D	Gate D10 WRR	06/01/2023 04:04:00 AM	Negative	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 04:15:00 AM	Negative	No Supplies e.g. Soaps/Paper, Other	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 04:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 06:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 06:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 06:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 06:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 07:01:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 07:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:15:00 AM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:41:00 AM	Positive		Mai
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:46:00 AM	Positive		Super

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:15:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:25:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 10:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 10:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 10:31:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 10:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 10:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 11:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:15:00 AM	Neutral	Wet/Dirty Counters, Wet Floor	Could be cleaner
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:28:00 AM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:38:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 11:56:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/01/2023 12:23:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 12:25:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 12:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 12:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 12:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 12:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:16:00 PM	Positive		Q buen servicio
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:16:00 PM	Positive		Esta muy limpio
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:33:00 PM	Positive		Limpio todo
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:41:00 PM	Positive		Todo muy bien
North Terminal	Gates D	Gate D10 MRR	06/01/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 02:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:32:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 02:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 02:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:51:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 02:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 03:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 03:10:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 03:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 03:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 03:52:00 PM	Positive		Excelente
North Terminal	Gates D	Gate D10 MRR	06/01/2023 03:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 04:08:00 PM	Positive		Very well
North Terminal	Gates D	Gate D10 WRR	06/01/2023 04:15:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:37:00 PM	Positive		Pee
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:40:00 PM	Negative	Wet/Dirty Counters	****
North Terminal	Gates D	Gate D10 WRR	06/01/2023 04:48:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 05:08:00 PM	Positive		Super
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:13:00 PM	Negative	No Paper Towels, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:19:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:46:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/01/2023 05:53:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 06:19:00 PM	Neutral	Wet/Dirty Counters, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 06:23:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 06:33:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 06:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 06:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 06:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 06:53:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 06:59:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 07:04:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 07:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 07:18:00 PM	Positive		Very good experience
North Terminal	Gates D	Gate D10 WRR	06/01/2023 07:26:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/01/2023 07:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 07:34:00 PM	Positive		lets go nuggets
North Terminal	Gates D	Gate D10 MRR	06/01/2023 07:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:09:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:12:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:12:00 PM	Neutral	Wet/Dirty Counters	No
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 08:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 08:51:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:04:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:06:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:11:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	Asco
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:23:00 PM	Positive		Goo
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 09:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 09:58:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/01/2023 10:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 10:20:00 PM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/01/2023 10:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:20:00 PM	Positive		Jl
North Terminal	Gates D	Gate D10 WRR	06/01/2023 11:25:00 PM	Positive		Excelent
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:01:00 AM	Neutral	Smell, Dirty Stalls or Urinals, Other	There needs to be a box for sanitary napkins in the stall!
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:11:00 AM	Positive		Bueno
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:10:00 AM	Positive		Smells bad but i kobr tge
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:13:00 AM	Neutral	Smell	It smekks
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 03:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 06:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 06:16:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/02/2023 06:22:00 AM	Positive		Super todo muy bien
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:11:00 AM	Positive		Bien
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:54:00 AM	Negative	Smell, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:57:00 AM	Positive		Muy limpio
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:32:00 AM	Positive		Riquete bien
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:57:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:57:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:25:00 AM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:26:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:34:00 AM	Negative	No Supplies e.g. Soaps/Paper, Litter on the floor	No attendant
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:44:00 AM	Positive		Bjen
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 10:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 10:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 10:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 10:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 11:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 11:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 11:51:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 11:58:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:04:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:07:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:16:00 PM	Neutral	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:24:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 12:59:00 PM	Positive		Thank yyou
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:04:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 01:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 01:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 01:59:00 PM	Negative	Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 02:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 02:42:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 03:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 03:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:14:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:18:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:27:00 PM	Negative	Smell	Stupid
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:38:00 PM	Negative	Smell	No
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:40:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 03:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 04:11:00 PM	Positive		Excelente
North Terminal	Gates D	Gate D10 MRR	06/02/2023 04:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 04:20:00 PM	Negative	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 04:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 04:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 04:34:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 04:52:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 04:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 04:57:00 PM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 04:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 05:32:00 PM	Negative	Wet/Dirty Counters	No
North Terminal	Gates D	Gate D10 MRR	06/02/2023 05:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:44:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 05:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 06:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:13:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 06:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:35:00 PM	Negative	Other	Paper all over the floor
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:02:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:03:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:20:00 PM	Negative	Other	Please put a garbage in the stalls
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 07:41:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:46:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:53:00 PM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	06/02/2023 07:54:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:07:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:19:00 PM	Negative	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:22:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:27:00 PM	Positive		Ho
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:39:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet Floor, Smell, Litter on the floor	Nasty
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:45:00 PM	Neutral	Smell, Dirty Walls, Dirty Mirrors	It was mid couldnt **** in here tho
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:45:00 PM	Neutral	Wet/Dirty Counters	No
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 08:56:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 08:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/02/2023 09:28:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/02/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 10:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/02/2023 11:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:00:00 AM	Neutral	Wet/Dirty Counters, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:53:00 AM	Neutral	No Paper Towels, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:22:00 AM	Negative	No Supplies e.g. Soaps/Paper, Other	Door locks broken, hangers for bags missing
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 03:59:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/03/2023 04:09:00 AM	Positive		Good service
North Terminal	Gates D	Gate D10 MRR	06/03/2023 04:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:23:00 AM	Neutral	Smell, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 04:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:55:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 05:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 05:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 05:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:58:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 06:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 06:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 06:40:00 AM	Negative	Smell	**** smell
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 07:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:40:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:02:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:12:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 08:22:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:52:00 AM	Neutral	Litter on the floor	Hot
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:04:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 10:18:00 AM	Negative		Sucuoio
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:20:00 AM	Negative	No Paper Towels, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Gross
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 10:38:00 AM	Negative	Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:00:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:06:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 11:26:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 11:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 11:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:46:00 AM	Neutral	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:02:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:06:00 PM	Positive		Nice and clean
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:06:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:09:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:17:00 PM	Negative		Muy sucio
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:18:00 PM	Negative	Wet Floor, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor, Other	Should be a clean example of who we are bad expression
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:27:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 12:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 12:56:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 01:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 01:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 01:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 01:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 01:49:00 PM	Positive		Xzabbvbbvvgb bbb'hhhhhhvfgvvvvv v'hhhhddddd bkkkkk kkkkknjjjjjjjjkkkkkr kc. V
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:17:00 PM	Positive		Happy
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:18:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:23:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:25:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:27:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:35:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 02:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 03:02:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 03:06:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 03:10:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 03:43:00 PM	Negative	Smell	****
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:44:00 PM	Negative	Wet/Dirty Counters, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 03:52:00 PM	Positive		Todo limpio gracias
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:28:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 04:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:33:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Other	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:34:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:42:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 05:45:00 PM	Negative	No Paper Towels, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 MRR	06/03/2023 06:08:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:09:00 PM	Neutral	Smell, Dirty Stalls or Urinals	No

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:12:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:13:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:21:00 PM	Negative	Smell, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:32:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:34:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 06:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:31:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 07:45:00 PM	Negative	Smell, Other	It looks very poorly maintained and the smell is very strong
North Terminal	Gates D	Gate D10 MRR	06/03/2023 07:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:04:00 PM	Neutral	No Supplies e.g. Soaps/Paper	No soap
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:05:00 PM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/03/2023 08:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 08:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 08:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/03/2023 09:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:52:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:57:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/03/2023 09:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:17:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:22:00 PM	Negative	Smell, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:26:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:40:00 PM	Negative	Wet Floor, Smell, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:42:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:46:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:53:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 10:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:03:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:28:00 PM	Positive		Excellent
North Terminal	Gates D	Gate D10 WRR	06/03/2023 11:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:33:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:08:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:15:00 AM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 06:14:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:33:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:40:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/04/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 06:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:26:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:07:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:17:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 08:19:00 AM	Negative		Sucio y prstoso
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:14:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:27:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 09:50:00 AM	Neutral	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 10:10:00 AM	Negative		Puerco
North Terminal	Gates D	Gate D10 MRR	06/04/2023 10:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:27:00 AM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:28:00 AM	Negative	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 10:29:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:49:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:02:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 11:22:00 AM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/04/2023 11:22:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 11:23:00 AM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell	UhUUUU
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:25:00 AM	Neutral	Other	Dated
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:07:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:08:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 12:09:00 PM	Positive		Bnhhhh
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:10:00 PM	Positive		Got yhw p
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:17:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:20:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:36:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 12:38:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 12:52:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:26:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 01:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:30:00 PM	Negative	Other	Smell so bad
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:31:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:49:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 01:59:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:00:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:01:00 PM	Negative	Smell, Litter on the floor	Sucio todo
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:05:00 PM	Neutral	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:06:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:17:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:31:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:32:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	lck
North Terminal	Gates D	Gate D10 MRR	06/04/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:44:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:46:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:50:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 02:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 03:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:07:00 PM	Negative	Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:39:00 PM	Positive		Muy limpio el bano
North Terminal	Gates D	Gate D10 WRR	06/04/2023 03:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:02:00 PM	Neutral	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:05:00 PM	Negative	No Paper Towels, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 04:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:16:00 PM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 04:21:00 PM	Negative	Wet Floor, Smell	Stinky
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:22:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 04:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 04:59:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:07:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	Dirty
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:15:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:20:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	Gross
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:21:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:23:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:26:00 PM	Positive		Fantastic
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:30:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 05:41:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 05:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:19:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 06:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:53:00 PM	Neutral	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 07:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:29:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 07:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 07:55:00 PM	Positive		,jhhgvnj
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:23:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:33:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals	

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:35:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	This bathroom stinks really bad
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 08:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:55:00 PM	Positive		Ok
North Terminal	Gates D	Gate D10 WRR	06/04/2023 08:56:00 PM	Negative	Smell	Horrible
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:14:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:20:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 09:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 09:34:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 09:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 09:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 09:59:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:08:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:08:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	06/04/2023 10:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 10:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/04/2023 10:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:32:00 PM	Negative	Smell, Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 WRR	06/04/2023 10:59:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:22:00 PM	Positive		Bueno
North Terminal	Gates D	Gate D10 WRR	06/04/2023 11:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 12:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 02:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 02:11:00 AM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	06/05/2023 02:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 02:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:00:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 05:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 05:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 05:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 05:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 06:17:00 AM	Positive		:)
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:32:00 AM	Positive		It was soo good
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:33:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:21:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:32:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:32:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:37:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:46:00 AM	Negative		Sucio
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:57:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 08:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:15:00 AM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:29:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 10:03:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/05/2023 10:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 10:23:00 AM	Positive		



### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/05/2023 12:07:00 PM	Neutral	No Paper Towels, Wet/Dirty Counters, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	Wvg was at the badroom
North Terminal	Gates D	Gate D10 WRR	06/05/2023 12:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 12:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 12:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 12:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:20:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	Disgusting
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 01:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 02:11:00 PM	Neutral	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 02:12:00 PM	Negative	No Paper Towels, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/05/2023 02:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 02:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:39:00 PM	Positive		Muy limpio gracias
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 03:46:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/05/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:02:00 PM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:03:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:18:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/05/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 04:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:30:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:38:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:42:00 PM	Negative	Dirty Walls	Redo it
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:50:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:51:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:55:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:55:00 PM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 04:56:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 05:16:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 05:24:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 05:54:00 PM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:05:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:13:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/05/2023 06:15:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:18:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	L
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:19:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:20:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:22:00 PM	Neutral	Dirty Stalls or Urinals	Nope
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:29:00 PM	Neutral	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 06:44:00 PM	Positive		Good cleaning is good
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:50:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:55:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 06:58:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:02:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:03:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:10:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:20:00 PM	Negative	Smell	No huele bien
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:22:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:23:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:23:00 PM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:26:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:44:00 PM	Neutral	Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/05/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 07:48:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 08:12:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:25:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:26:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:27:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:35:00 PM	Positive		It was nice and clean
North Terminal	Gates D	Gate D10 WRR	06/05/2023 08:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/05/2023 09:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:38:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:46:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 09:49:00 PM	Negative	Smell, Dirty Stalls or Urinals	I hate it
North Terminal	Gates D	Gate D10 WRR	06/05/2023 10:09:00 PM	Neutral	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	This airport sucks. 2,5 hrs immigration for us citizens???????
North Terminal	Gates D	Gate D10 WRR	06/05/2023 10:19:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	06/05/2023 10:50:00 PM	Neutral	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/05/2023 11:38:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/05/2023 11:44:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:39:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 05:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:36:00 AM	Negative	Other	Very rude cleaning lady
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:53:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:07:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 07:58:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:04:00 AM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:52:00 AM	Negative	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:04:00 AM	Positive		Todo bien gracias
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:34:00 AM	Neutral	Other	No
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:28:00 AM	Negative	Other	Broken
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 11:51:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 12:14:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:14:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/06/2023 12:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 12:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 01:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:48:00 PM	Negative	Other	Outdated and raggedy
North Terminal	Gates D	Gate D10 WRR	06/06/2023 01:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:29:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:44:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:19:00 PM	Positive		It was good

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:21:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:34:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:48:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 03:58:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:01:00 PM	Neutral	Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:06:00 PM	Negative	Smell	Stinks!!!!
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:14:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:14:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:16:00 PM	Negative	Smell, Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 WRR	06/06/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 05:10:00 PM	Positive		It was very clean
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:18:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 05:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 07:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:48:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:51:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 07:55:00 PM	Neutral	Wet Floor, Smell	Please i cant breath it stinks so bad in here.
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:12:00 PM	Neutral	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:38:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:39:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 08:42:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/06/2023 08:48:00 PM	Negative	Smell	It stink
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:01:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/06/2023 09:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:19:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:44:00 PM	Negative	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 09:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:03:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:05:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:12:00 PM	Negative	Wet/Dirty Counters, Litter on the floor	Muito sujo e sem sabonete
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:22:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:27:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:29:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:32:00 PM	Negative	Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/06/2023 10:49:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/06/2023 11:56:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 06:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 06:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:00:00 AM	Positive		Esta muy ordenado y amable la atencion
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:02:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/07/2023 07:13:00 AM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:36:00 AM	Positive		No everything is goog
North Terminal	Gates D	Gate D10 MRR	06/07/2023 07:49:00 AM	Negative	No Paper Towels, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:55:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:07:00 AM	Negative	Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Dirty
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:15:00 AM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Pee all over and dirty
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:05:00 AM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:32:00 AM	Neutral	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:35:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	:/
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:03:00 AM	Neutral	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:11:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 MRR	06/07/2023 10:22:00 AM	Positive		Clean sinks
North Terminal	Gates D	Gate D10 MRR	06/07/2023 10:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 10:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:01:00 AM	Positive		Clean and nice
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 11:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:23:00 AM	Positive		Great job
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:38:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:46:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 11:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 12:16:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 01:59:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 02:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 02:22:00 PM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 02:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 02:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:01:00 PM	Positive		N
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:25:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:30:00 PM	Negative	Smell	Very dirty
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 03:54:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 04:17:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 04:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 04:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 04:45:00 PM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 04:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 04:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:26:00 PM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 05:29:00 PM	Positive		Awesome service they even helped me wipe
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:31:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 05:43:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 05:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 06:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 06:40:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 06:53:00 PM	Positive		Wemdys
North Terminal	Gates D	Gate D10 WRR	06/07/2023 06:54:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 06:55:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/07/2023 06:57:00 PM	Positive		Miami heattttttt
North Terminal	Gates D	Gate D10 MRR	06/07/2023 06:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:00:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:01:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:04:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:08:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:18:00 PM	Negative		Bad
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:23:00 PM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:34:00 PM	Positive		Muy buena atencion
North Terminal	Gates D	Gate D10 MRR	06/07/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 07:54:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Mirrors	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:19:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:22:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:31:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:33:00 PM	Negative	Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 08:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/07/2023 08:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:41:00 PM	Negative	Wet Floor, Dirty Mirrors, Dirty Stalls or Urinals	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/07/2023 08:51:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/07/2023 08:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/07/2023 09:46:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:30:00 AM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 12:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 12:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 03:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 05:08:00 AM	Positive		Keep up the excellent work
North Terminal	Gates D	Gate D10 WRR	06/08/2023 05:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 05:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:26:00 AM	Neutral	Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:23:00 AM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:43:00 AM	Positive		Na

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:44:00 AM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:59:00 AM	Negative	Wet Floor	*****
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:14:00 AM	Positive		Esta limpio es mejor les den bonos a lo que limpian bien para estimularlos
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:27:00 AM	Negative	Smell, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:31:00 AM	Neutral		The door open both ways
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:44:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:46:00 AM	Positive		Cgood
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:56:00 AM	Positive		Super bien
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:56:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:27:00 AM	Negative	No Paper Towels, Wet Floor, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:32:00 AM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:37:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:57:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:01:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:09:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals	Hhm
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:13:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:18:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:19:00 AM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:25:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:36:00 AM	Negative	Smell	So sad
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 11:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:52:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 12:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:40:00 PM	Neutral	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 12:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 01:08:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Wet, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 01:10:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:12:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 01:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 01:38:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:46:00 PM	Positive		Super limpio este lugar
North Terminal	Gates D	Gate D10 MRR	06/08/2023 01:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 02:27:00 PM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/08/2023 02:28:00 PM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 02:33:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 02:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 02:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 03:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 03:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 03:31:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 03:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 04:03:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 04:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 04:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 05:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 05:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 05:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 05:53:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:02:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:08:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:08:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 06:20:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:23:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:39:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:42:00 PM	Neutral	Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:02:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:17:00 PM	Positive		Gracias
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:31:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:33:00 PM	Neutral	Wet/Dirty Counters, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 07:40:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 07:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:05:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet Floor, Smell, Dirty Stalls or Urinals	Awful
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 08:18:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:28:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:33:00 PM	Positive		Angel
North Terminal	Gates D	Gate D10 WRR	06/08/2023 08:33:00 PM	Neutral	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:06:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:20:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Other	The bathroom is discusting can be beter
North Terminal	Gates D	Gate D10 WRR	06/08/2023 09:20:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/08/2023 09:55:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:07:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:16:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:20:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:21:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/08/2023 10:27:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	Poor
North Terminal	Gates D	Gate D10 MRR	06/08/2023 10:33:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:30:00 AM	Neutral	Dirty Mirrors, Other	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:30:00 AM	Positive		E
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:32:00 AM	Neutral	Smell	Smell :(

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:41:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 01:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 02:18:00 AM	Neutral	Dirty Stalls or Urinals	Nnnnnnnnj
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:43:00 AM	Positive		P
North Terminal	Gates D	Gate D10 MRR	06/09/2023 03:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 04:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:44:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:06:00 AM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:53:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:13:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:17:00 AM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:25:00 AM	Positive		Nice
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:51:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/09/2023 09:56:00 AM	Neutral	Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 10:04:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 10:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 10:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 10:25:00 AM	Negative	Smell	Mop with clean sanitized water, change it out before finishing whole bathroom
North Terminal	Gates D	Gate D10 MRR	06/09/2023 10:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 10:58:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	Horrible
North Terminal	Gates D	Gate D10 MRR	06/09/2023 11:02:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Vvvvfhhhhcgggggvvvvfaaacsssse
North Terminal	Gates D	Gate D10 MRR	06/09/2023 11:03:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Stupid bathroom
North Terminal	Gates D	Gate D10 MRR	06/09/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 11:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 11:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 11:29:00 AM	Negative	Smell	P
North Terminal	Gates D	Gate D10 WRR	06/09/2023 11:39:00 AM	Negative	Other	Sucio
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:02:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:10:00 PM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:40:00 PM	Positive		Friendly staff
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 12:50:00 PM	Positive		Todo limpio bien
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:56:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 01:13:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:25:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:28:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 01:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 01:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:57:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/09/2023 01:57:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 01:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:08:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 02:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 02:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 02:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 02:52:00 PM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 MRR	06/09/2023 02:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 02:54:00 PM	Neutral	Litter on the floor	The soap dispenser broke.
North Terminal	Gates D	Gate D10 MRR	06/09/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:07:00 PM	Neutral	Wet Floor, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 03:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 03:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 03:48:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:52:00 PM	Positive		Thanks
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 03:58:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/09/2023 04:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 04:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 04:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 04:19:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 04:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 04:38:00 PM	Positive		****
North Terminal	Gates D	Gate D10 WRR	06/09/2023 04:39:00 PM	Negative	Dirty Mirrors	****
North Terminal	Gates D	Gate D10 WRR	06/09/2023 04:47:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/09/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 04:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:14:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	***
North Terminal	Gates D	Gate D10 MRR	06/09/2023 05:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:25:00 PM	Positive		Nice
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:26:00 PM	Positive		N/a
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 05:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:06:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:10:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:13:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Bad
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:23:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:26:00 PM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:36:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/09/2023 06:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 06:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:19:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:20:00 PM	Positive		So clean
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:48:00 PM	Positive		Super
North Terminal	Gates D	Gate D10 WRR	06/09/2023 07:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:08:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:09:00 PM	Positive		Missing toilet paper.
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:39:00 PM	Positive		10/10
North Terminal	Gates D	Gate D10 MRR	06/09/2023 08:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:47:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/09/2023 08:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:05:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:10:00 PM	Positive		Super
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/09/2023 09:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/09/2023 10:15:00 PM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 10:44:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/09/2023 11:00:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 12:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 04:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:28:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/10/2023 05:44:00 AM	Neutral	Litter on the floor, Other	No
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:00:00 AM	Neutral	Other	An airdryer for hands
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:03:00 AM	Neutral	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:40:00 AM	Neutral	Dirty Stalls or Urinals	Jaylanie
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:51:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:25:00 AM	Negative	Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/10/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:03:00 AM	Neutral	Dirty Mirrors	I dont really like it
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 08:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:03:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/10/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:37:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:38:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 MRR	06/10/2023 09:42:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:13:00 AM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:16:00 AM	Negative	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	06/10/2023 10:24:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:25:00 AM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:42:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/10/2023 10:44:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	**** on wa
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 10:53:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:14:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:17:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 11:37:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	A man jerkinb off and ***** on the wall
North Terminal	Gates D	Gate D10 MRR	06/10/2023 11:47:00 AM	Negative	Smell	Stinky
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:58:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/10/2023 11:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 12:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 12:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 12:39:00 PM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	06/10/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 12:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:19:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 01:56:00 PM	Positive		Thank u
North Terminal	Gates D	Gate D10 WRR	06/10/2023 02:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 02:21:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/10/2023 02:29:00 PM	Positive		Potato
North Terminal	Gates D	Gate D10 WRR	06/10/2023 02:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 02:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 02:39:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 02:50:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:00:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 03:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:26:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:33:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:39:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:49:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:50:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 03:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 04:02:00 PM	Negative	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 04:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 04:27:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/10/2023 04:40:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:06:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Litter on the floor	?
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:10:00 PM	Negative	Smell	Smell ****
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:14:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:19:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:47:00 PM	Positive		J
North Terminal	Gates D	Gate D10 WRR	06/10/2023 05:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:08:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	Ew
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 06:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 06:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 07:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 07:48:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 08:14:00 PM	Positive		Good job
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:17:00 PM	Negative	Wet Floor, Smell, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:20:00 PM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:26:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 08:58:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/10/2023 09:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:30:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:38:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/10/2023 09:59:00 PM	Negative	No Paper Towels, Other	
North Terminal	Gates D	Gate D10 MRR	06/10/2023 10:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:34:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:47:00 AM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 05:28:00 AM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	06/11/2023 05:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/11/2023 05:50:00 AM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:04:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:17:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:49:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/11/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:25:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:28:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:32:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:02:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:11:00 AM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:13:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:19:00 AM	Neutral	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:25:00 AM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals	Hott
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:25:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:27:00 AM	Negative	Wet Floor, Dirty Walls, Litter on the floor	Sucio
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:31:00 AM	Neutral	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:31:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:32:00 AM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:32:00 AM	Positive		"
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:35:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:51:00 AM	Positive		Georgina was exelent,,,restroom so clean.thanks to her .thanks georgina for been so good
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:56:00 AM	Positive		You dont have to tuch the toilt
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:57:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:13:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:14:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:27:00 PM	Neutral	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 12:54:00 PM	Positive		Hard working employee.
North Terminal	Gates D	Gate D10 WRR	06/11/2023 01:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:09:00 PM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:22:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 02:44:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:31:00 PM	Positive		L

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:36:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	**** you
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:37:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	****
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:42:00 PM	Negative	Smell, Other	P
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:49:00 PM	Neutral	Wet Floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 03:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:11:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:42:00 PM	Neutral	Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:50:00 PM	Positive		E
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:51:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/11/2023 04:54:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 05:56:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:05:00 PM	Negative	Dirty Stalls or Urinals, Other	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:09:00 PM	Positive		Clean up
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:35:00 PM	Negative	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:54:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 06:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:04:00 PM	Neutral	Smell, Dirty Walls	No
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:12:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:21:00 PM	Neutral	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:26:00 PM	Neutral	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:35:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:40:00 PM	Neutral	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 07:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:03:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:26:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:50:00 PM	Negative	No Paper Towels, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 08:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:02:00 PM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:02:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:22:00 PM	Neutral	Other	Hot
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:30:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 09:42:00 PM	Negative	Dirty Stalls or Urinals	Really nasty

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:04:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:18:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	Gross
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:18:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:33:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:34:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:39:00 PM	Neutral	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	P
North Terminal	Gates D	Gate D10 WRR	06/11/2023 10:42:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:04:00 PM	Positive		Dfr
North Terminal	Gates D	Gate D10 WRR	06/11/2023 11:50:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:34:00 AM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 06:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 06:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:50:00 AM	Neutral	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:56:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:57:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:58:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:15:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:40:00 AM	Positive		Like clean bathrooms. Thank you
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 07:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 07:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:52:00 AM	Neutral	Smell	It was hot
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:20:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:34:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:51:00 AM	Neutral	Smell	It was hot
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 10:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:24:00 AM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:32:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet Floor, Smell	Terrible conditions, hot as balls.
North Terminal	Gates D	Gate D10 MRR	06/12/2023 10:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 10:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:58:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:08:00 AM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:19:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:21:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:36:00 AM	Neutral	Other	Nk garbage in mf
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:47:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 11:52:00 AM	Positive		Good job
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:55:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:00:00 PM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:13:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:23:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:44:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 12:58:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 01:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 01:52:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 02:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 02:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 02:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 02:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 02:55:00 PM	Negative	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:06:00 PM	Positive		

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:18:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:20:00 PM	Negative	Smell	No
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:35:00 PM	Positive		no
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:37:00 PM	Neutral	Other	It stinks
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:40:00 PM	Negative	Smell	Stinks
North Terminal	Gates D	Gate D10 WRR	06/12/2023 03:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:13:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/12/2023 04:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 04:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:35:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:37:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:38:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:39:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 04:58:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:32:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:44:00 PM	Negative	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:48:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:56:00 PM	Negative	Smell	Ac and air quality
North Terminal	Gates D	Gate D10 WRR	06/12/2023 05:59:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/12/2023 06:09:00 PM	Positive		No

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:10:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:16:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/12/2023 06:32:00 PM	Negative	Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:32:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:32:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:38:00 PM	Negative	Smell	no mm
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:41:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:42:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:43:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:43:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 06:45:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/12/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 07:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:18:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:26:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/12/2023 07:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:37:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 07:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:27:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:30:00 PM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:34:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/12/2023 08:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 08:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:20:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:24:00 PM	Positive		Mfggnfhgg
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/12/2023 09:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 09:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:10:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:14:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 10:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:00:00 PM	Neutral	Other	Dirty toilets!!!!
North Terminal	Gates D	Gate D10 WRR	06/12/2023 11:02:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 12:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 12:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:22:00 AM	Neutral	Other	Lack of counter space inside stall (for wallet or hats)
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 04:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 04:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:59:00 AM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 05:02:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/13/2023 05:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 05:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 05:38:00 AM	Negative	Smell	Durty
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:02:00 AM	Neutral	Wet/Dirty Counters, Other	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 07:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:02:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 08:08:00 AM	Positive		Naw
North Terminal	Gates D	Gate D10 MRR	06/13/2023 08:08:00 AM	Neutral	Smell	Hot
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:08:00 AM	Neutral	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:53:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/13/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:00:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 09:22:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 09:29:00 AM	Negative	Wet Floor, Smell, Other	Long line
North Terminal	Gates D	Gate D10 MRR	06/13/2023 09:33:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:41:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:59:00 AM	Neutral	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 10:03:00 AM	Positive		Very clean
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:05:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 10:22:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:26:00 AM	Negative	Other	Dirty!
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:28:00 AM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:39:00 AM	Negative	No Supplies e.g. Soaps/Paper, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:51:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:03:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 11:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:12:00 AM	Neutral	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 11:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:22:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:33:00 AM	Neutral	Smell	P
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 11:58:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 12:09:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 12:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 12:38:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 12:44:00 PM	Positive		Muy limpio
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:02:00 PM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:52:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet Floor, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 01:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:14:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:18:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:23:00 PM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 02:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:34:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:37:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:38:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:42:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:45:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 02:50:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:17:00 PM	Positive		Super clean
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 03:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 03:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:32:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 03:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 04:09:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 04:43:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 04:47:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 05:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 05:21:00 PM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/13/2023 05:38:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 05:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 05:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 06:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:01:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:01:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 07:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:07:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:17:00 PM	Negative	Litter on the floor	Clean thisplace,
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:33:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 07:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:35:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:39:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:41:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:42:00 PM	Neutral	No Paper Towels, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:43:00 PM	Negative	Wet/Dirty Counters, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/13/2023 07:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 07:47:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:00:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:11:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:26:00 PM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:30:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:42:00 PM	Neutral	Smell, Dirty Stalls or Urinals	No
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:43:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/13/2023 08:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 08:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/13/2023 09:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:23:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/13/2023 09:36:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/13/2023 10:00:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 02:40:00 AM	Positive		Gg
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 05:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 06:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:12:00 AM	Positive		

## Feedback Summary Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:17:00 AM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:25:00 AM	Positive		Quiten este sistema y den bonos
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:30:00 AM	Negative	Smell, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:30:00 AM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:41:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:58:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals	These restrooms are in dire need of an upgrade
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:07:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 09:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:30:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 09:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 09:43:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:49:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:55:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:24:00 AM	Negative	Wet Floor, Smell, Litter on the floor	Sucio
North Terminal	Gates D	Gate D10 MRR	06/14/2023 10:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:40:00 AM	Neutral	Smell, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:10:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 11:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:17:00 AM	Positive		Okk
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:44:00 AM	Positive		Well done job
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 11:57:00 AM	Positive		Bueno

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:08:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:09:00 PM	Negative	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 12:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 12:39:00 PM	Positive		Very nice
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 12:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 12:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 01:47:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:06:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 02:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 02:10:00 PM	Positive		I love pooping
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:35:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:40:00 PM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:43:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 02:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 02:58:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 03:09:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/14/2023 03:20:00 PM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	06/14/2023 03:21:00 PM	Positive		Hi
North Terminal	Gates D	Gate D10 WRR	06/14/2023 03:34:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 04:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 04:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 04:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 04:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 04:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 04:36:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor, Other	nothingbto say just clean and make smell go away
North Terminal	Gates D	Gate D10 WRR	06/14/2023 04:37:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor, Other	Please do better at your cleaning job
North Terminal	Gates D	Gate D10 WRR	06/14/2023 04:38:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 05:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:11:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:19:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 05:28:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:47:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:48:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 05:51:00 PM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:05:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:16:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 06:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:25:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:25:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:26:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:37:00 PM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:40:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:42:00 PM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:42:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:43:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:46:00 PM	Negative	Smell, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 07:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 07:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:08:00 PM	Neutral		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:15:00 PM	Negative	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:18:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 08:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:48:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 08:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:09:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/14/2023 09:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 09:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 09:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/14/2023 10:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/14/2023 10:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:11:00 AM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:41:00 AM	Positive		All wonderful,
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:11:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:43:00 AM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:55:00 AM	Negative	Smell	Necesita un extractor
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:56:00 AM	Positive		:)
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 07:20:00 AM	Positive		It was awesome!
North Terminal	Gates D	Gate D10 MRR	06/15/2023 07:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 07:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:10:00 AM	Neutral	Smell	Nnnn
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:45:00 AM	Negative	Other	Your mo
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:45:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:47:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:53:00 AM	Neutral	Smell, Litter on the floor	no
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:54:00 AM	Negative	Smell, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:57:00 AM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:59:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 09:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:18:00 AM	Positive		Good service
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:18:00 AM	Positive		Friendly staff
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:20:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 09:23:00 AM	Positive		Good job
North Terminal	Gates D	Gate D10 MRR	06/15/2023 09:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 09:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 09:56:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:09:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:33:00 AM	Negative	Wet Floor	finish
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:46:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:48:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:52:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:06:00 AM	Positive		P
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:08:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:12:00 AM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:30:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:40:00 AM	Positive		No she is really clear
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:41:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:44:00 AM	Positive		Great
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:48:00 AM	Positive		Skylar
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:51:00 AM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:55:00 AM	Positive		love it
North Terminal	Gates D	Gate D10 WRR	06/15/2023 11:55:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:21:00 PM	Negative	Smell	Smelly :(
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 12:41:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/15/2023 12:53:00 PM	Neutral	Wet Floor	Hhhhhddhhhhvjijiv
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:15:00 PM	Positive		Bien
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:34:00 PM	Positive		Limpio
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 01:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 01:59:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters	No
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 02:16:00 PM	Negative	No Paper Towels, Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 02:19:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:47:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/15/2023 02:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:56:00 PM	Positive		Happy
North Terminal	Gates D	Gate D10 WRR	06/15/2023 02:58:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 03:11:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 03:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 03:44:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:28:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:31:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 04:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:22:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 05:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 05:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:35:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 05:44:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 05:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 05:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:06:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:06:00 PM	Neutral	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:11:00 PM	Negative	No Paper Towels	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:12:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Gross
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:16:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:27:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:29:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:33:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:35:00 PM	Positive		Nice batgrii? pp
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:41:00 PM	Neutral	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	Appreciate a bano
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:50:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 06:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 06:56:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:37:00 PM	Positive		Its very nice
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 07:53:00 PM	Negative	Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals, Other	No ac
North Terminal	Gates D	Gate D10 MRR	06/15/2023 07:57:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:01:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:05:00 PM	Negative		No soap

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:24:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:25:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:30:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:36:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:37:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 08:46:00 PM	Positive		Nice and clean
North Terminal	Gates D	Gate D10 MRR	06/15/2023 08:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:00:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 09:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:00:00 PM	Neutral	Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/15/2023 10:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 10:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:18:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:36:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	06/15/2023 11:45:00 PM	Negative	No Supplies e.g. Soaps/Paper	Trash
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:03:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	Yuck
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:32:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:56:00 AM	Negative	No Supplies e.g. Soaps/Paper	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/16/2023 04:00:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:00:00 AM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	06/16/2023 04:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 04:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 06:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 06:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 06:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 06:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:22:00 AM	Positive		2171
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:00:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:37:00 AM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:53:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 09:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:55:00 AM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 10:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:17:00 AM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:20:00 AM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:22:00 AM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	06/16/2023 10:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:38:00 AM	Positive		Mejor le dan bonos
North Terminal	Gates D	Gate D10 MRR	06/16/2023 10:53:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/16/2023 11:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:20:00 AM	Positive		Nice lady
North Terminal	Gates D	Gate D10 MRR	06/16/2023 11:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 11:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:03:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:15:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:26:00 PM	Neutral	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:31:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:49:00 PM	Neutral	No Supplies e.g. Soaps/Paper, Other	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 12:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 12:57:00 PM	Positive		Great assistance!

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:02:00 PM	Positive		Very clean
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:03:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:36:00 PM	Negative	Dirty Stalls or Urinals	Gaps in doorwtf
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 01:49:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 01:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:12:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:21:00 PM	Neutral	No Paper Towels, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:23:00 PM	Neutral	Smell	Caca
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:29:00 PM	Neutral	No Paper Towels, Smell, Litter on the floor	Fix the bathroo
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:30:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet Floor, Smell, Litter on the floor	Fix the bathroom!::
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:43:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:53:00 PM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 02:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 03:01:00 PM	Neutral		Urine mostly
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 03:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:56:00 PM	Positive		G ood
North Terminal	Gates D	Gate D10 WRR	06/16/2023 03:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:21:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/16/2023 04:25:00 PM	Negative	Smell, Dirty Walls, Litter on the floor, Other	I love nuts' i didnt see any naked men
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:25:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 04:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 04:55:00 PM	Negative	Smell	Yuck
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:36:00 PM	Neutral	Other	Ran down
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:37:00 PM	Positive		Hgj
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:48:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 05:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 06:08:00 PM	Negative		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/16/2023 06:21:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 06:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 06:50:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:00:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:11:00 PM	Positive		Not
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:16:00 PM	Neutral	Smell, Other	Hot, doors don't work
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:47:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	06/16/2023 07:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:53:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 07:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:10:00 PM	Positive		Clean more
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/16/2023 08:19:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:19:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:27:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 08:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:19:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Amazing
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:27:00 PM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 09:53:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:09:00 PM	Negative	Wet Floor, Smell, Litter on the floor, Other	P
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:41:00 PM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/16/2023 10:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/16/2023 11:33:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 02:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:52:00 AM	Positive		;)
North Terminal	Gates D	Gate D10 MRR	06/17/2023 04:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:35:00 AM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:40:00 AM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:18:00 AM	Positive		Excellent
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:44:00 AM	Positive		Very clean

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:06:00 AM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:15:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:22:00 AM	Negative	Smell	Need air freshner!!!
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:43:00 AM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:46:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:01:00 AM	Negative	Wet Floor, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor, Other	Cleaning should be done more often

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:24:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:35:00 AM	Neutral	No Paper Towels, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:07:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:35:00 AM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:36:00 AM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals, Other	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:38:00 AM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 12:36:00 PM	Negative		Sucio
North Terminal	Gates D	Gate D10 MRR	06/17/2023 12:37:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/17/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:53:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:55:00 PM	Negative	Smell	Ee
North Terminal	Gates D	Gate D10 WRR	06/17/2023 12:56:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	Ee?
North Terminal	Gates D	Gate D10 MRR	06/17/2023 12:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 01:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 01:06:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 01:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 01:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 01:47:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 01:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 01:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:14:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 02:15:00 PM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 02:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:19:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:20:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:33:00 PM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:33:00 PM	Neutral	No Paper Towels, Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 02:40:00 PM	Negative	Smell	Smelly. Pee yew
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:50:00 PM	Neutral	Smell, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/17/2023 02:50:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:04:00 PM	Negative	Smell, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:09:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:13:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:30:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:30:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:39:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 03:42:00 PM	Neutral	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 03:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:02:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:04:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:04:00 PM	Negative	Wet/Dirty Counters, Dirty Walls	No room
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:05:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:06:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:07:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:08:00 PM	Neutral	Wet Floor	Hiiii

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:08:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	I WILL never come here agin
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 04:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:29:00 PM	Negative	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:31:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 04:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 04:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:49:00 PM	Neutral	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:50:00 PM	Neutral	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:52:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 04:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 04:59:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:02:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 05:35:00 PM	Positive		Flawless experience. Great job guys.
North Terminal	Gates D	Gate D10 MRR	06/17/2023 05:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 05:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:39:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 05:56:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:00:00 PM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/17/2023 06:03:00 PM	Negative	Smell	Nah
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:16:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 06:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:26:00 PM	Negative	Smell	Facundo ochoa honor
North Terminal	Gates D	Gate D10 MRR	06/17/2023 06:29:00 PM	Neutral	Other	One bathroom locked
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:33:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:44:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:44:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:45:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:48:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 06:56:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:08:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:09:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:29:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:56:00 PM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:57:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 07:58:00 PM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:12:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:19:00 PM	Negative	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:33:00 PM	Neutral	Smell	REEEEKS of urine
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:40:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:42:00 PM	Negative		Kojkjk
North Terminal	Gates D	Gate D10 MRR	06/17/2023 08:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 08:59:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:34:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:42:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	Smells like pee
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:49:00 PM	Negative	Smell	Filth
North Terminal	Gates D	Gate D10 WRR	06/17/2023 09:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 09:53:00 PM	Positive		Good time

### Feedback Summary Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/17/2023 10:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/17/2023 10:15:00 PM	Positive		No **** on the ground!
North Terminal	Gates D	Gate D10 MRR	06/17/2023 10:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:29:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:30:00 PM	Negative	Dirty Walls, Litter on the floor	****
North Terminal	Gates D	Gate D10 MRR	06/17/2023 10:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:42:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 10:45:00 PM	Negative	Smell, Dirty Walls, Litter on the floor	****
North Terminal	Gates D	Gate D10 MRR	06/17/2023 11:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:13:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/17/2023 11:17:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/17/2023 11:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:38:00 AM	Neutral	Smell	Smells like sh
North Terminal	Gates D	Gate D10 MRR	06/18/2023 12:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 01:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:01:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:48:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:48:00 AM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:02:00 AM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:29:00 AM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:44:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:02:00 AM	Negative	No Paper Towels, Smell, Dirty Walls, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:59:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:11:00 AM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:21:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:52:00 AM	Neutral	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:13:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:24:00 AM	Neutral		Smell bad
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:26:00 AM	Neutral	Smell	Ri
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:31:00 AM	Positive		Its a little dirty
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:32:00 AM	Negative		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:00:00 AM	Neutral	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:13:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:20:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:29:00 AM	Positive		Very clen
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:54:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:03:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:15:00 AM	Negative	Litter on the floor	Todo asqueroso
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:20:00 AM	Negative		Asqueroso directo? a ota hola va
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:20:00 AM	Negative		Parece no trabsha nadue asco da
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:37:00 AM	Negative	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:06:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:08:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:15:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:22:00 AM	Positive		Smells
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:49:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:09:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	No
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:09:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 12:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 12:28:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:32:00 PM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:39:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 12:43:00 PM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 12:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 01:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 01:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 01:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 01:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 01:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 01:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 01:51:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 01:54:00 PM	Neutral	Smell	Smells like urine
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:06:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 02:07:00 PM	Neutral	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Dirty Walls	No
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 02:18:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:24:00 PM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:50:00 PM	Positive		Great
North Terminal	Gates D	Gate D10 WRR	06/18/2023 02:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 02:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:16:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:25:00 PM	Negative	Smell	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:39:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:44:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 03:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 03:59:00 PM	Positive		no
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:00:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:29:00 PM	Negative	Smell	De santis fix your airports before you fix books
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:42:00 PM	Positive		Pp
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:46:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 04:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:32:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:33:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:55:00 PM	Neutral	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:55:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 05:56:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 05:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:16:00 PM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Steamy *****
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:22:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:37:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:38:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:57:00 PM	Positive		Dope
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:58:00 PM	Positive		Super dope
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:58:00 PM	Positive		No

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/18/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:18:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:31:00 PM	Negative	Smell, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:36:00 PM	Positive		'y"u"n'eed"need' 'h"n' 't'h'e' 's"a"s'
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:40:00 PM	Neutral	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:41:00 PM	Neutral	Wet Floor	No
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 07:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 07:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:06:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:09:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:10:00 PM	Negative	Smell	I
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:22:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 08:27:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:48:00 PM	Negative	Other	Cp
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:51:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/18/2023 08:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:37:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:43:00 PM	Neutral	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:47:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 09:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 09:55:00 PM	Neutral	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 10:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:09:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	gross and unkept, not a good reflection of usa
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:14:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:21:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 10:55:00 PM	Negative	Other	Smells
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:19:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/18/2023 11:26:00 PM	Negative	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/18/2023 11:44:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:49:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 MRR	06/19/2023 04:54:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:35:00 AM	Neutral	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:00:00 AM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 07:10:00 AM	Negative	Smell	Clean
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 07:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:24:00 AM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:26:00 AM	Negative	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:27:00 AM	Neutral		L
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:36:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 08:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 08:14:00 AM	Negative	Other	Too hot
North Terminal	Gates D	Gate D10 MRR	06/19/2023 08:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:20:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:23:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 08:49:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:49:00 AM	Positive		Na
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:06:00 AM	Positive		Very clean and well supplied even with so many ladies coming in, thank you!
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:13:00 AM	Positive		G
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:20:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:59:00 AM	Negative	Smell, Dirty Walls, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 10:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 10:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 10:31:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 11:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 11:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:13:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/19/2023 11:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:24:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:55:00 AM	Positive		Yes
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:56:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:01:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:13:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:36:00 PM	Neutral	Smell	**** rockin
North Terminal	Gates D	Gate D10 MRR	06/19/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:00:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 01:04:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 01:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:42:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 01:43:00 PM	Neutral	Wet/Dirty Counters	Se
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:49:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 01:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:53:00 PM	Negative	Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:54:00 PM	Negative	Smell, Other	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:54:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:56:00 PM	Negative	Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 01:58:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 02:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:10:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:11:00 PM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 02:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:17:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 02:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:26:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:27:00 PM	Negative	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:28:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:29:00 PM	Neutral	Smell	Smelly
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:30:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:34:00 PM	Negative	Smell	Smell like **** **
North Terminal	Gates D	Gate D10 WRR	06/19/2023 02:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:08:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:21:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:29:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:34:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 03:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 03:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 04:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 04:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:27:00 PM	Negative	Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	Disgusting
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:28:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 04:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:32:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:33:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:34:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 04:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 04:56:00 PM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 04:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:05:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:12:00 PM	Negative	No Supplies e.g. Soaps/Paper, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:42:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 05:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 05:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:04:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:05:00 PM	Positive		Stinky
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:13:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:19:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	Bad condition
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:20:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:46:00 PM	Neutral	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:46:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:48:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:57:00 PM	Positive		Ctddsvbm,.kmdwshj uft
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:57:00 PM	Positive		GfddssXcv mx
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 06:58:00 PM	Neutral	Wet/Dirty Counters, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 06:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:07:00 PM	Neutral	Wet Floor, Smell	Bvggggfggcfcv xv
North Terminal	Gates D	Gate D10 MRR	06/19/2023 07:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 07:31:00 PM	Positive		Ryker



### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 08:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 08:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 08:58:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:04:00 PM	Positive		Nice
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:22:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:25:00 PM	Positive		I was happy to be here
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:26:00 PM	Negative	Smell	It smells
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:35:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 09:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 09:56:00 PM	Negative	Wet Floor	Ab
North Terminal	Gates D	Gate D10 MRR	06/19/2023 10:00:00 PM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:13:00 PM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:16:00 PM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:27:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:34:00 PM	Negative	Smell	

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:35:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	I hate american airlines
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:45:00 PM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/19/2023 10:47:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 10:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:00:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/19/2023 11:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/19/2023 11:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:01:00 AM	Neutral	Wet/Dirty Counters, Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/20/2023 12:19:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/20/2023 12:22:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/20/2023 12:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 12:28:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/20/2023 12:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:54:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	06/20/2023 01:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 01:17:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/20/2023 02:19:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	06/20/2023 03:38:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 03:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 04:33:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/20/2023 05:04:00 AM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 05:32:00 AM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 06:03:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/20/2023 06:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 06:12:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 06:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 06:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 06:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 06:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 07:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 07:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 07:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 07:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 08:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/20/2023 08:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 08:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:06:00 AM	Positive		Mnhuiok
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:53:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/20/2023 10:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 10:55:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Smell, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 11:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 11:13:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 11:22:00 AM	Neutral	Wet/Dirty Counters, Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 12:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 01:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 02:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 02:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 02:38:00 PM	Negative	No Supplies e.g. Soaps/Paper	Finish
North Terminal	Gates D	Gate D10 MRR	06/20/2023 02:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 03:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 03:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 03:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 04:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 04:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:07:00 PM	Positive		****
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 05:54:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 06:05:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/20/2023 06:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 06:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 06:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 06:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 07:00:00 PM	Positive		Keep up the good job
North Terminal	Gates D	Gate D10 MRR	06/20/2023 07:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 07:10:00 PM	Positive		Make equipment newer
North Terminal	Gates D	Gate D10 MRR	06/20/2023 07:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 08:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 08:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 08:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:18:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:30:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:40:00 PM	Positive		It was very clean and good to use
North Terminal	Gates D	Gate D10 MRR	06/20/2023 09:40:00 PM	Positive		The toilet was clean
North Terminal	Gates D	Gate D10 MRR	06/20/2023 10:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 11:13:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/20/2023 11:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/20/2023 11:26:00 PM	Negative	Other	***** streaks
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:04:00 AM	Negative	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:58:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/21/2023 01:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 02:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 06:13:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/21/2023 06:23:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:50:00 AM	Positive		Excelente
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 08:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 08:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 09:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 09:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 10:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 10:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 10:26:00 AM	Neutral	Smell	Its amazingly not good
North Terminal	Gates D	Gate D10 MRR	06/21/2023 10:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 11:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:42:00 PM	Negative	Wet Floor, Smell	ldk what tht smell is..
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 01:02:00 PM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Smell	H
North Terminal	Gates D	Gate D10 MRR	06/21/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 01:30:00 PM	Positive		I liked it today more than i did yesterday when i got stuck in the toilet
North Terminal	Gates D	Gate D10 MRR	06/21/2023 01:32:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/21/2023 01:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 02:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 02:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 02:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 02:51:00 PM	Neutral	Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/21/2023 02:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 03:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 03:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 03:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 03:40:00 PM	Positive		The bathroom was so clean
North Terminal	Gates D	Gate D10 MRR	06/21/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 04:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 04:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 05:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 05:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 07:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 08:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 08:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 08:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 09:20:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/21/2023 09:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/21/2023 11:19:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 12:05:00 AM	Neutral	Other	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/22/2023 03:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 04:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 06:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 06:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 06:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 07:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 08:11:00 AM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 08:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 08:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:04:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:49:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:06:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:12:00 AM	Negative	Smell	FfydtezeaEe stgbbuccwzwyvbn nninnj,oko,Il.l.p
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:52:00 AM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 10:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 11:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 11:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 11:24:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/22/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 11:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 12:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 12:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 12:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 12:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 12:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:06:00 PM	Positive		Super
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:06:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:07:00 PM	Positive		Limpio
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:29:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:30:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 01:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 02:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 02:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 02:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 02:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 02:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/22/2023 02:47:00 PM	Positive		****
North Terminal	Gates D	Gate D10 WRR	06/22/2023 03:02:00 PM	Neutral	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/22/2023 03:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/22/2023 03:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 03:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/22/2023 03:49:00 PM	Positive		Clean bathroom

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/22/2023 04:05:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 04:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 04:57:00 PM	Negative	Dirty Mirrors	R
North Terminal	Gates D	Gate D10 MRR	06/22/2023 04:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/22/2023 05:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 05:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 05:35:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 WRR	06/22/2023 06:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 07:41:00 PM	Negative	Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/22/2023 09:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 03:51:00 AM	Positive		Goob job
North Terminal	Gates D	Gate D10 WRR	06/23/2023 05:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 06:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/23/2023 06:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 06:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 06:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 06:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 07:32:00 AM	Neutral	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 07:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 07:39:00 AM	Positive		Ecelente todo
North Terminal	Gates D	Gate D10 MRR	06/23/2023 07:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:11:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/23/2023 08:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 09:25:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/23/2023 09:25:00 AM	Negative	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 09:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 09:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 10:06:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 10:18:00 AM	Negative	Wet/Dirty Counters, Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 10:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 10:37:00 AM	Positive		Tood
North Terminal	Gates D	Gate D10 MRR	06/23/2023 10:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 11:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 11:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 12:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 12:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 12:51:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:33:00 PM	Positive		Its alright
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/23/2023 01:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 01:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 03:04:00 PM	Neutral	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 03:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 03:42:00 PM	Negative	No Paper Towels	1

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/23/2023 03:42:00 PM	Positive		???
North Terminal	Gates D	Gate D10 WRR	06/23/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/23/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 04:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 05:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:20:00 PM	Negative	Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/23/2023 10:18:00 PM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/23/2023 11:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/24/2023 02:14:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/24/2023 02:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/24/2023 04:21:00 AM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/24/2023 05:50:00 AM	Neutral	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/24/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 09:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 10:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 10:28:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 10:29:00 AM	Negative		Sucioooo
North Terminal	Gates D	Gate D10 MRR	06/24/2023 10:30:00 AM	Negative		Parece hace un mes no se limpia aqui
North Terminal	Gates D	Gate D10 MRR	06/24/2023 10:34:00 AM	Neutral	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 11:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 11:17:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 11:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 11:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 11:44:00 AM	Neutral	Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 12:02:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/24/2023 12:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 12:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 12:15:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 12:56:00 PM	Neutral		Funky joe is cool
North Terminal	Gates D	Gate D10 MRR	06/24/2023 01:58:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 02:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 02:22:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 02:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/24/2023 02:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/24/2023 02:48:00 PM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 02:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 03:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 03:11:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 03:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 05:11:00 PM	Negative	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 05:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 06:00:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 06:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 06:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 06:28:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 06:36:00 PM	Negative	Wet Floor, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:02:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 WRR	06/24/2023 07:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:09:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:18:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:30:00 PM	Positive		Needbmore stalls
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 07:52:00 PM	Neutral	Smell	No
North Terminal	Gates D	Gate D10 WRR	06/24/2023 08:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/24/2023 08:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 08:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 08:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 08:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 08:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 08:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 08:48:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/24/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 09:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/24/2023 10:12:00 PM	Negative	No Paper Towels, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/24/2023 10:15:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/24/2023 11:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:04:00 AM	Negative	Smell	Smell terrible
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:28:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 WRR	06/25/2023 02:54:00 AM	Neutral		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 02:58:00 AM	Negative	Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 04:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 05:14:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 05:17:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/25/2023 05:51:00 AM	Neutral	Smell, Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/25/2023 05:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 06:58:00 AM	Negative	Dirty Walls, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 09:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 09:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 10:15:00 AM	Positive		Tom
North Terminal	Gates D	Gate D10 MRR	06/25/2023 10:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 10:43:00 AM	Negative		No trajan aquinsuciooo
North Terminal	Gates D	Gate D10 MRR	06/25/2023 10:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 11:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 11:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 11:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 11:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 11:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:14:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	Dirty
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:29:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:29:00 PM	Negative	Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 12:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 01:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 01:02:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:07:00 PM	Positive		G
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:15:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:34:00 PM	Negative	Litter on the floor	Dfghjk, b cv bvawrtg?? m v,,lmmmmmlhhhc ssssss md cn xxrgggggddddddccc cccc dddvcbrt ttv ffnff nndddcff xvmmmmmmmmmmmm mmjnnnnnnnnnnnnnn nh hhhh hhhhhhhh,,,,,,,,
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:35:00 PM	Negative	Litter on the floor	Jjj xshhhjdcmddddd,d dddnhhhb cccccc kkk,nnnhjjjjgaaas
North Terminal	Gates D	Gate D10 MRR	06/25/2023 01:36:00 PM	Neutral	Wet Floor, Dirty Mirrors	
North Terminal	Gates D	Gate D10 WRR	06/25/2023 01:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 02:03:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 02:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 02:25:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	06/25/2023 02:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 03:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 03:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 03:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 03:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 03:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 04:22:00 PM	Neutral	Wet Floor, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 04:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 04:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 04:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 04:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 05:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 05:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 06:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 06:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:18:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 07:30:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:51:00 PM	Negative	Other	No condoms
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 07:54:00 PM	Negative	Litter on the floor	No
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:01:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 08:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/25/2023 09:31:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/25/2023 09:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 11:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 11:33:00 PM	Neutral	Other	
North Terminal	Gates D	Gate D10 WRR	06/25/2023 11:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/25/2023 11:57:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:02:00 AM	Negative	Smell	No
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:14:00 AM	Negative	Smell	Bad smell
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:44:00 AM	Positive		Zzzffgddddd
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:52:00 AM	Negative	Smell	Ewww stinky
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:03:00 AM	Neutral	Smell	To hot
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 02:25:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 02:31:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/26/2023 03:03:00 AM	Negative	Smell	Smells bad
North Terminal	Gates D	Gate D10 MRR	06/26/2023 03:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 03:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 04:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 04:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 04:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 05:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 05:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 05:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 05:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 06:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 06:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 08:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 10:00:00 AM	Negative	Wet/Dirty Counters, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/26/2023 10:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 11:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 11:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 11:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 12:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 01:13:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 01:55:00 PM	Neutral		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 01:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 01:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 02:43:00 PM	Positive		Right
North Terminal	Gates D	Gate D10 MRR	06/26/2023 02:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 02:56:00 PM	Neutral		Add a smeller so it can smell good
North Terminal	Gates D	Gate D10 MRR	06/26/2023 03:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 03:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 03:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 04:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 05:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 05:17:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 06:55:00 PM	Positive		Rigth
North Terminal	Gates D	Gate D10 MRR	06/26/2023 07:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 08:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/26/2023 08:58:00 PM	Neutral	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/26/2023 09:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/26/2023 10:03:00 PM	Neutral	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 02:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 04:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 05:27:00 AM	Neutral	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 05:46:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:35:00 AM	Positive		Great cleaning
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:53:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:09:00 AM	Negative	Other	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:14:00 AM	Negative	Dirty Stalls or Urinals	Your bathrom is ****

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:16:00 AM	Neutral	Smell	Joosh
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:20:00 AM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:16:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 10:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 10:56:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 10:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 11:03:00 AM	Neutral	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 11:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 11:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 11:27:00 AM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 11:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 12:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 12:07:00 PM	Positive		No
North Terminal	Gates D	Gate D10 WRR	06/27/2023 01:44:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 01:44:00 PM	Negative	No Paper Towels	
North Terminal	Gates D	Gate D10 WRR	06/27/2023 01:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 02:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 02:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 03:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 03:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 03:21:00 PM	Negative	Other	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/27/2023 03:29:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	06/27/2023 04:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 04:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 04:26:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 WRR	06/27/2023 05:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 05:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 05:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 05:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 06:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 06:20:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 06:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 07:45:00 PM	Positive		Very good
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:02:00 PM	Neutral	Litter on the floor, Other	c
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 08:41:00 PM	Negative	Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 08:43:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 WRR	06/27/2023 08:44:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/27/2023 08:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:49:00 PM	Positive		Dfffffffffffffgggggxgmk cdd

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/27/2023 09:55:00 PM	Negative	Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/27/2023 10:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 10:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/27/2023 10:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/27/2023 11:32:00 PM	Negative	Smell, Other	Saw a bug,
North Terminal	Gates D	Gate D10 WRR	06/28/2023 12:17:00 AM	Positive		Fix some of the door of the bathroom doors!!
North Terminal	Gates D	Gate D10 WRR	06/28/2023 12:20:00 AM	Positive		Fix the doors
North Terminal	Gates D	Gate D10 MRR	06/28/2023 12:22:00 AM	Neutral	Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	06/28/2023 12:24:00 AM	Neutral	Smell, Dirty Mirrors	Clean yo bathroom please bc it smells badddd!!!!!!
North Terminal	Gates D	Gate D10 WRR	06/28/2023 05:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:10:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:43:00 AM	Positive		Noooooooooooo
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:44:00 AM	Negative	Smell, Dirty Walls, Dirty Mirrors, Litter on the floor, Other	Make it beterc
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:45:00 AM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	No
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:45:00 AM	Negative	No Supplies e.g. Soaps/Paper, Wet Floor, Dirty Stalls or Urinals, Litter on the floor, Other	Uuuuuuu,
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:46:00 AM	Positive		??????
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:54:00 AM	Positive		Noice
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:55:00 AM	Positive		Noice
North Terminal	Gates D	Gate D10 WRR	06/28/2023 09:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 10:16:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 WRR	06/28/2023 10:24:00 AM	Negative	Wet/Dirty Counters, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/28/2023 10:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 10:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 10:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 11:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/28/2023 11:52:00 AM	Negative	Wet/Dirty Counters, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/28/2023 12:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 12:49:00 PM	Neutral	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/28/2023 01:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/28/2023 01:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 02:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 03:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 03:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/28/2023 03:16:00 PM	Neutral	Smell, Dirty Walls, Dirty Stalls or Urinals, Litter on the floor, Other	No
North Terminal	Gates D	Gate D10 MRR	06/28/2023 03:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 03:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/28/2023 05:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 05:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/28/2023 06:20:00 PM	Negative	Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	06/28/2023 06:24:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/28/2023 06:42:00 PM	Positive		Happy
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:21:00 PM	Negative	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:22:00 PM	Positive		Floor was mad wet ngl gang
North Terminal	Gates D	Gate D10 WRR	06/28/2023 07:30:00 PM	Negative	Smell, Litter on the floor	No

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/28/2023 07:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 08:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 08:16:00 PM	Negative		
North Terminal	Gates D	Gate D10 MRR	06/28/2023 09:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/29/2023 12:45:00 AM	Positive		Great
North Terminal	Gates D	Gate D10 MRR	06/29/2023 02:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 02:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 06:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/29/2023 06:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 07:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/29/2023 07:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/29/2023 09:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 09:36:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/29/2023 09:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 09:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 10:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 10:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 11:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 11:22:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 11:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 11:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/29/2023 11:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 11:58:00 AM	Neutral	Wet/Dirty Counters, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:34:00 PM	Negative	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 12:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:10:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 01:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 02:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 02:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 02:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/29/2023 02:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 02:44:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 03:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 03:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 04:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 04:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 05:13:00 PM	Negative	Smell, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 05:19:00 PM	Neutral	Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 05:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 05:48:00 PM	Negative	Other	Need more toilets
North Terminal	Gates D	Gate D10 MRR	06/29/2023 05:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 06:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 06:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/29/2023 08:44:00 PM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/29/2023 08:53:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/30/2023 12:19:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 06:37:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/30/2023 06:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:32:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:44:00 AM	Neutral	Other	Not enough stalls
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:45:00 AM	Positive		Super todo
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:46:00 AM	Positive		Limpio
North Terminal	Gates D	Gate D10 WRR	06/30/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 08:48:00 AM	Negative	Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	06/30/2023 09:16:00 AM	Negative	No Supplies e.g. Soaps/Paper, Other	Middle sink doesnt work, right sink doesnt drain
North Terminal	Gates D	Gate D10 MRR	06/30/2023 09:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 09:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/30/2023 10:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 10:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 11:33:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 11:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 11:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 11:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 12:00:00 PM	Neutral	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	06/30/2023 12:13:00 PM	Negative		Sucioooooompesimo
North Terminal	Gates D	Gate D10 MRR	06/30/2023 12:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 12:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 12:46:00 PM	Positive		Luv
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:33:00 PM	Positive		.biem
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:40:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/30/2023 01:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/30/2023 01:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/30/2023 02:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 02:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 02:38:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/30/2023 02:39:00 PM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Just do a little bit more cleaning
North Terminal	Gates D	Gate D10 MRR	06/30/2023 02:40:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Clean it !!!!!!!
North Terminal	Gates D	Gate D10 MRR	06/30/2023 03:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 03:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 03:49:00 PM	Negative	Wet/Dirty Counters	
North Terminal	Gates D	Gate D10 WRR	06/30/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/30/2023 04:44:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	06/30/2023 05:01:00 PM	Negative	Wet/Dirty Counters	Nop
North Terminal	Gates D	Gate D10 MRR	06/30/2023 05:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 05:29:00 PM	Positive		Dood
North Terminal	Gates D	Gate D10 MRR	06/30/2023 05:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 05:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 06:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 06:40:00 PM	Negative	Smell, Dirty Stalls or Urinals	This bath are discuting
North Terminal	Gates D	Gate D10 MRR	06/30/2023 07:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	06/30/2023 07:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 08:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 08:02:00 PM	Neutral	Litter on the floor	

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	06/30/2023 08:29:00 PM	Negative	Wet Floor, Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	06/30/2023 08:36:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Ffrf
North Terminal	Gates D	Gate D10 WRR	06/30/2023 08:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 09:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	06/30/2023 09:27:00 PM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	06/30/2023 10:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 04:28:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 05:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 05:38:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/01/2023 06:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/01/2023 07:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/01/2023 07:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/01/2023 07:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 09:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 09:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/01/2023 10:29:00 AM	Negative	Wet Floor, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:39:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:43:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 06:59:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:11:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:13:00 PM	Positive		Mui bon
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:14:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 07:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:16:00 PM	Negative	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:19:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:20:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 08:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 09:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 09:56:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	Ggfff
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:09:00 PM	Negative	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	07/01/2023 10:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:34:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/01/2023 10:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/01/2023 11:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 12:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 12:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 12:46:00 AM	Positive		Melvik  eerqaszcxdertgffffffft hsutsygs
North Terminal	Gates D	Gate D10 WRR	07/02/2023 01:38:00 AM	Positive		Mer
North Terminal	Gates D	Gate D10 MRR	07/02/2023 02:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:16:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:04:00 AM	Negative	No Paper Towels, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:12:00 AM	Negative	No Paper Towels	No
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 06:06:00 AM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	
North Terminal	Gates D	Gate D10 WRR	07/02/2023 06:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 07:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 07:12:00 AM	Negative		
North Terminal	Gates D	Gate D10 WRR	07/02/2023 07:13:00 AM	Negative		Estaba sucio
North Terminal	Gates D	Gate D10 MRR	07/02/2023 07:27:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:31:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:51:00 AM	Positive		G
North Terminal	Gates D	Gate D10 MRR	07/02/2023 09:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 09:56:00 AM	Neutral	Wet Floor, Other	
North Terminal	Gates D	Gate D10 MRR	07/02/2023 10:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 11:04:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 11:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 11:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 11:19:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 11:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/02/2023 12:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 01:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 01:26:00 PM	Negative		Pestoso y sucio parece no?trabaja nadie aqui
North Terminal	Gates D	Gate D10 MRR	07/02/2023 01:59:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/02/2023 02:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/02/2023 02:32:00 PM	Negative	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/02/2023 02:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 03:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:10:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 04:54:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:30:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 05:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 06:18:00 PM	Negative	Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/02/2023 06:42:00 PM	Neutral	Wet/Dirty Counters, Smell, Dirty Walls, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/02/2023 06:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 07:06:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/02/2023 07:34:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/02/2023 08:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 08:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 09:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 09:12:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/02/2023 09:39:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/02/2023 09:41:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/02/2023 09:59:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 12:07:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 12:09:00 AM	Negative	No Paper Towels, Smell, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 WRR	07/03/2023 02:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 03:02:00 AM	Negative	No Supplies e.g. Soaps/Paper, Smell	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 04:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 05:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 05:38:00 AM	Positive		Muy limpios
North Terminal	Gates D	Gate D10 MRR	07/03/2023 06:36:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 07:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:01:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:02:00 AM	Neutral	No Paper Towels, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:31:00 AM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:44:00 AM	Negative		Clean it!!!!
North Terminal	Gates D	Gate D10 WRR	07/03/2023 08:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 09:09:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 10:13:00 AM	Neutral	Smell, Dirty Walls, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 10:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 10:28:00 AM	Negative		Sucio
North Terminal	Gates D	Gate D10 MRR	07/03/2023 10:42:00 AM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 10:44:00 AM	Negative	Smell, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 11:15:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 11:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 11:25:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/03/2023 11:37:00 AM	Neutral	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 11:43:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 12:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 12:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 01:04:00 PM	Negative	Other	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 01:48:00 PM	Negative	Smell, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 02:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 03:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 03:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 03:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 03:47:00 PM	Positive		Ngodvd2
North Terminal	Gates D	Gate D10 MRR	07/03/2023 03:48:00 PM	Negative		Good
North Terminal	Gates D	Gate D10 MRR	07/03/2023 03:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 04:42:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:35:00 PM	Neutral	Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals	Bgb
North Terminal	Gates D	Gate D10 WRR	07/03/2023 07:50:00 PM	Neutral	Wet/Dirty Counters, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 WRR	07/03/2023 07:51:00 PM	Negative	Smell	Bad
North Terminal	Gates D	Gate D10 MRR	07/03/2023 07:55:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/03/2023 08:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/03/2023 09:09:00 PM	Negative		F
North Terminal	Gates D	Gate D10 WRR	07/03/2023 10:52:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	07/03/2023 11:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 01:06:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 03:17:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/04/2023 05:40:00 AM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/04/2023 05:44:00 AM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Dirty Mirrors	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 07:08:00 AM	Negative	Wet/Dirty Counters, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 07:25:00 AM	Negative	Wet Floor, Smell	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 10:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 10:42:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/04/2023 10:50:00 AM	Neutral	No Paper Towels	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 11:28:00 AM	Positive		Love
North Terminal	Gates D	Gate D10 MRR	07/04/2023 11:51:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 11:52:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 01:58:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 03:27:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:07:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:16:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	Mj
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:18:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:34:00 PM	Positive		More stalls
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:35:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:36:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 04:36:00 PM	Negative	Other	Very nice he helped me
North Terminal	Gates D	Gate D10 MRR	07/04/2023 05:36:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 05:48:00 PM	Neutral	Wet Floor, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 06:16:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/04/2023 06:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/04/2023 07:45:00 PM	Neutral	Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	07/04/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/04/2023 08:27:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/04/2023 11:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/05/2023 03:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/05/2023 04:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/05/2023 05:00:00 AM	Positive		Clean
North Terminal	Gates D	Gate D10 MRR	07/05/2023 05:09:00 AM	Positive		Ok
North Terminal	Gates D	Gate D10 MRR	07/05/2023 05:20:00 AM	Positive		100
North Terminal	Gates D	Gate D10 MRR	07/05/2023 05:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 06:41:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 07:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 07:46:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 07:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 08:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 09:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 WRR	07/05/2023 09:45:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 09:48:00 AM	Positive		Bhg h
North Terminal	Gates D	Gate D10 MRR	07/05/2023 10:14:00 AM	Positive		Suck my ****
North Terminal	Gates D	Gate D10 MRR	07/05/2023 10:22:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 10:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 11:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 04:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 04:52:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 05:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 06:25:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	07/05/2023 06:29:00 PM	Neutral	Other	Update
North Terminal	Gates D	Gate D10 MRR	07/05/2023 06:31:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/05/2023 07:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 08:00:00 PM	Negative	Wet Floor, Smell, Dirty Mirrors, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/05/2023 08:39:00 PM	Positive		It is very good i approve
North Terminal	Gates D	Gate D10 MRR	07/05/2023 08:45:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	07/05/2023 09:08:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 09:22:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/05/2023 11:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/05/2023 11:29:00 PM	Negative	Wet Floor	
North Terminal	Gates D	Gate D10 MRR	07/06/2023 01:09:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/06/2023 01:23:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:46:00 AM	Positive		Good love the vibe
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:47:00 AM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	07/06/2023 06:05:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 06:24:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 07:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 07:34:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 08:01:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/06/2023 08:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 08:44:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 09:11:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 09:18:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 09:21:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 09:25:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/06/2023 09:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 10:00:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 10:02:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 10:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 10:55:00 AM	Neutral	Smell, Other	Only two stalls and it smells
North Terminal	Gates D	Gate D10 MRR	07/06/2023 12:26:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 12:27:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/06/2023 12:29:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 12:50:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 01:04:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 01:30:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/06/2023 01:42:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/06/2023 03:40:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 04:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:49:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/06/2023 05:52:00 PM	Positive		Restrom good
North Terminal	Gates D	Gate D10 MRR	07/06/2023 08:20:00 PM	Positive		Keep up the good work
North Terminal	Gates D	Gate D10 MRR	07/06/2023 08:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 06:13:00 AM	Negative	Wet Floor	***
North Terminal	Gates D	Gate D10 MRR	07/07/2023 06:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:01:00 AM	Positive		Gunner
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:35:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 08:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 08:57:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 09:04:00 AM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/07/2023 09:30:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 09:53:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 09:59:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 10:17:00 AM	Neutral	Smell	*****
North Terminal	Gates D	Gate D10 MRR	07/07/2023 11:27:00 AM	Positive		Best
North Terminal	Gates D	Gate D10 MRR	07/07/2023 11:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 12:27:00 PM	Positive		Very clean :)
North Terminal	Gates D	Gate D10 MRR	07/07/2023 01:03:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 01:04:00 PM	Neutral	Smell	Smelly eww
North Terminal	Gates D	Gate D10 MRR	07/07/2023 01:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 03:04:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 03:51:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 05:15:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 05:22:00 PM	Negative	Smell	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 06:21:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 06:25:00 PM	Negative	Smell	Puto

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/07/2023 06:47:00 PM	Positive		Great job team
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:10:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Wet Floor, Smell	Bad work
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:15:00 PM	Positive		No
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:38:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:48:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 07:58:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 08:25:00 PM	Negative	No Paper Towels, Wet/Dirty Counters, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 08:52:00 PM	Negative	No Paper Towels, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 09:08:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/07/2023 09:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/07/2023 10:19:00 PM	Positive		Hi
North Terminal	Gates D	Gate D10 MRR	07/08/2023 01:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 06:29:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 08:54:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 09:02:00 AM	Negative	Other	h
North Terminal	Gates D	Gate D10 MRR	07/08/2023 09:24:00 AM	Neutral	Other	Not enough stalls
North Terminal	Gates D	Gate D10 MRR	07/08/2023 10:13:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/08/2023 10:14:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 11:20:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 11:25:00 AM	Positive		It was great
North Terminal	Gates D	Gate D10 MRR	07/08/2023 12:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 01:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 01:28:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 02:21:00 PM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/08/2023 02:37:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 02:47:00 PM	Neutral	Smell	Smell

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/08/2023 03:09:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 03:22:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 03:23:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 03:25:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 03:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 04:00:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 04:16:00 PM	Positive		E
North Terminal	Gates D	Gate D10 MRR	07/08/2023 04:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 04:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 04:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 05:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 06:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 08:01:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 08:12:00 PM	Negative	Smell	People bottom was leaking
North Terminal	Gates D	Gate D10 MRR	07/08/2023 08:31:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/08/2023 08:33:00 PM	Negative	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor, Other	*** on floor
North Terminal	Gates D	Gate D10 MRR	07/08/2023 09:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 06:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 07:13:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 07:50:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 08:26:00 AM	Neutral	Smell, Dirty Walls	
North Terminal	Gates D	Gate D10 MRR	07/09/2023 10:08:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 12:47:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 12:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 01:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 02:43:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 02:49:00 PM	Negative	No Supplies e.g. Soaps/Paper	
North Terminal	Gates D	Gate D10 MRR	07/09/2023 03:17:00 PM	Positive		

### Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/09/2023 04:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 04:14:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 05:13:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 05:27:00 PM	Positive		Good
North Terminal	Gates D	Gate D10 MRR	07/09/2023 05:56:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 05:57:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 06:21:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 06:32:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 06:39:00 PM	Positive		No coments
North Terminal	Gates D	Gate D10 MRR	07/09/2023 06:46:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 07:30:00 PM	Positive		Very Clean. Thank you.
North Terminal	Gates D	Gate D10 MRR	07/09/2023 07:33:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 08:02:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 08:05:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 08:45:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 11:41:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/09/2023 11:42:00 PM	Positive		Israel
North Terminal	Gates D	Gate D10 MRR	07/10/2023 12:16:00 AM	Positive		Cleaned
North Terminal	Gates D	Gate D10 MRR	07/10/2023 12:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 01:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 04:12:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 05:03:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 05:20:00 AM	Positive		Fernando
North Terminal	Gates D	Gate D10 MRR	07/10/2023 05:50:00 AM	Neutral		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 06:05:00 AM	Neutral	No Paper Towels, Smell	
North Terminal	Gates D	Gate D10 MRR	07/10/2023 06:55:00 AM	Neutral	No Paper Towels, Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/10/2023 07:48:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 08:37:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 09:26:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 09:42:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 09:47:00 AM	Positive		Ni

## Feedback Summary Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**Weekdays:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Survey Time	Survey Response	Survey Details	Survey Comment
North Terminal	Gates D	Gate D10 MRR	07/10/2023 09:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 10:48:00 AM	Neutral	Smell	
North Terminal	Gates D	Gate D10 MRR	07/10/2023 10:58:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 11:23:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 11:24:00 AM	Neutral	Dirty Stalls or Urinals	
North Terminal	Gates D	Gate D10 MRR	07/10/2023 11:40:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 11:47:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 11:55:00 AM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 01:18:00 PM	Positive		We want a bouncy house in this john
North Terminal	Gates D	Gate D10 MRR	07/10/2023 02:09:00 PM	Positive		The water was anice temperture and the pee felt great
North Terminal	Gates D	Gate D10 MRR	07/10/2023 02:24:00 PM	Positive		
North Terminal	Gates D	Gate D10 MRR	07/10/2023 02:38:00 PM	Neutral	No Paper Towels, No Supplies e.g. Soaps/Paper, Wet/Dirty Counters, Wet Floor, Smell, Dirty Walls, Dirty Mirrors, Dirty Stalls or Urinals, Litter on the floor	
North Terminal	Gates D	Gate D10 MRR	07/10/2023 02:56:00 PM	Positive		

### Feedback Positive Negative Count Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**Weekdays:** All

**Feedback Types:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Building	Zone	Location	Positive Count	Negative Count	Neutral Count
North Terminal	Gates D	Gate D10 MRR	2652	295	183
North Terminal	Gates D	Gate D10 WRR	2587	762	439

## Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
efd25925-5aee-4fa6-82c8-1fa2ae9f5847	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	05/10/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2293173-271a-4bb6-87bc-fbd5c6f6434d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34b9b83c-0f34-482b-b426-e2be86c9721a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0174a11-d67a-420d-8c38-de3918a7be09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
57cbec90-6250-4de9-b1e1-711d1cadf640	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b3cf70d1-e3ea-45ae-af05-d34071e7a4f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

## Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8570b1c6-56d9-4709-bb8f-98da08a855cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fcaa485d-4343-4a5a-90bd-3e2626385dda	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
879cc1e5-f543-4dbf-ae96-728329b9817e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2726a82-7cc3-4fb2-a865-b9a8c470b807	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56e5e9f1-74be-4c55-85eb-4f2b56559bb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d85fd100-3637-431f-87ce-eabd69c33709	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ec4baf82-51b5-48b5-b26e-b2540bc20add	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8367f580-df87-422f-98ed-5b9fb7e87a56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	05/10/2023		:) 10
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6dfc7ce4-3e2c-4102-8bb8-17550ddf012	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	05/10/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d2af52c4-7814-47db-8e0e-5a39bed7803a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d514cbd4-bad7-48ae-87bb-7558175d7e1c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6077dc47-bf8f-4718-a8e9-6212cab92945	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6be308e2-c72d-47b2-9bee-a2a3241bca87	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34a1fb2a-f60c-4964-ac15-d4dd65e2ebc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ed5466eb-9dca-4bdd-8849-f82b78df985b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ebfe9afe-2406-4a63-af34-dac52541c8d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
032cfb8e-d605-4b7e-86a8-72a2f07c8b88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ae274e04-02a0-46e7-a8c3-783960ed1c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/10/2023		El bano esta excelente todo muy limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e17133b4-b765-4935-b103-1a9007e7797f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
65f56e0c-f2fa-4ae1-ad24-772bdf0ed462	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f2800183-f39d-46e9-99ca-024eb81500ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6d6ec0a4-332b-4e10-a7d0-275ae61f3044	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f01619ba-ff12-40ef-a590-4a2b53c9e26e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca420cae-1377-4cb0-a734-a2fb86f7d82c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1f32bc6-8490-4ca9-9f99-df2cc97b457a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	05/10/2023		Very good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d77002d-9e65-44ae-a7f4-b31a279e52d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cbdd491b-7bad-4489-99f7-d024b3039e56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a28a8a60-49a4-4704-af39-6a2eb3def505	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
33ad796d-3c46-4c08-9cc4-4674066d3878	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
18691c39-496f-42eb-83b8-023a81140e51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4f895457-5431-4622-a30f-c7951ee0318b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c21d3b73-1b23-441f-9b87-4d1950e8656a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aa6ffb6-a391-47fb-9496-35ab00fd9598	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2993677f-ad4d-47c3-b5d6-5497daf6b281	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
91e84980-b9bc-4201-b43a-364fb714fe48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b9fc08d-c77f-4c17-b843-63d084e2004e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:29:00	TRUE	FALSE			en-gb	16:29:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
409c659e-3f6e-4aef-abe9-12b709880a3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
751b32a2-5ef7-4921-9bf8-b81b664d5830	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
463871a5-fc7c-4287-8327-dce1afb426f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a1606623-32a1-41fc-9755-07dd63b14c45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dd36d264-3db3-4584-aa17-d37a3cbef0c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c738230f-1a4d-4181-a0dc-3e8f6c901240	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fade60a-e14e-4c54-b615-0beabfaafaea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5be2bf43-801b-4f59-a720-caf7ad0d553b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d6ae08ea-69f7-41f4-b674-b1be2a23cbdd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86ef659a-cb00-44bb-895c-926ac48b610e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:00:00	TRUE	FALSE			en-gb	17:00:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
86cad584-36a9-4eeb-be5b-52266e3cde3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9c00eee-2cbd-46d9-95ec-b1041f7cb432	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
709a0575-5d7e-4e40-895a-4d4f3f932905	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c88b25b-9827-421a-a277-23cb645c72e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28092748-2dbd-4d41-bd92-6a1558c51327	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6d8c1028-70cf-4da2-8e0e-04ba00eb246e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f4e90665-1af5-42c4-bc94-9b9aeacadb25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5853cce-028d-44de-b731-8248d6fc3547	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26801272-9323-430f-a9fc-865dfb4cf448	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/10/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
30fcd2c1-02e2-4d3d-99de-2db2a6754e20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/10/2023		Was perfect
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc48c6cd-e92a-4645-9f9e-fe01a0d4a265	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2df90564-524a-4304-b93a-50a0a2529057	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f9025f5-a023-44f7-90bf-ee10a9f7d317	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b08ecafb-e762-495c-8170-89a40bd585f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb83bb31-9052-4c37-b752-c487804a0684	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f3a56805-77d7-44d4-bc6b-f1bb0e0f0975	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a76e6130-371f-46b0-9c3b-241e1022bd12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
875a28e8-b8ee-498a-bfea-500970b0664b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	05/10/2023		Super clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
01bb53e8-7145-48db-87f9-cbd756c3bc7e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2c658e51-d8dc-448c-a81b-e9357637918b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4722edd9-f01b-421e-a450-727cd421c2c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4307e7d2-0c15-4e66-9785-b52b3241ed48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
950d7fc1-995c-4182-9d07-dc02c2124b45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6b41e722-e945-4831-87e8-f16161bf3310	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
57db48ab-b6c5-41d1-8d78-dec6aa1063b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
322f9857-3597-4177-87df-a2eaa381c8f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aab318d2-fc2e-489b-9038-f18f36a2503a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:03:00	TRUE	FALSE			en-gb	18:03:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bfbcadcb-9cf0-49c9-8553-d51d27e84bc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:04:00	TRUE	FALSE			en-gb	18:04:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
923d1bca-822b-4651-9df2-fbe0c7bbe4b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a27bb480-8a59-40d8-872a-26c755ab5855	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	05/10/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a27bb480-8a59-40d8-872a-26c755ab5855	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
			Yes	Yes				Yes	Yes	Yes				
673412e4-a4a3-4bf8-9384-5ec4d831a05a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	05/10/2023		
	How would you rate this restroom today?													
aed20a6d-a1ca-4437-a056-92ae0c955e1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/10/2023		
	How would you rate this restroom today?													
			Yes											
ed48895b-89ae-42bb-8d03-34109546159d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	05/10/2023		Excelent services
	How would you rate this restroom today?													
			Yes											
7816be58-bd61-4364-846b-8c8165b5f4b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	05/10/2023		
	How would you rate this restroom today?													
			Yes											

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4efdc57a-ac74-4b94-b812-6dc9b284c612	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c838bf3e-2feb-4f16-8893-698dd3f9ac62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d443527-21ad-46e0-9532-9baa6db14289	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c44b9725-26c9-4ebf-92cd-f9d5eb92f3c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
921bc59a-d34d-4d8b-b735-7806d6e6d9fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5fdd1dc8-7924-4e9a-8737-2087835ef8db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ddc34886-0988-4955-acfe-8751b4770818	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eefae641-606f-49d9-bf6d-3d2c33da8d5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85558972-4109-44e0-a160-75ba88cdb856	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c6df421f-2130-4b91-9e40-7cca48d1ed5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96f44468-1a01-46c1-8860-1ab5c3a37ac6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
309710d9-7ae4-41b2-93a1-066ded300a7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ecc8ae98-6c88-4577-a8bf-a05dc731e805	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0ce09d1c-78b2-4db8-a82c-ec85c3049274	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9baba749-e545-4303-91b7-62dc6e6ce6ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f0ed33c6-f6a9-45a5-9aed-534d2609e656	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a9ef719-5a3d-45be-9322-ebfe26e35fbf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a602b4ef-1b95-4a98-b2d3-be335a42b8f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54a711d0-609f-45be-8c20-43944676b6ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28b200a6-b3f2-48d2-85cd-1faa46d3007f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
256ea9c2-4b27-44b0-859d-18fd0ee37b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d45e0a74-27d1-4d6e-a794-b890d9bf4cb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae04fb6f-ddc3-4458-a7cb-ace2941efb73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0f585b3e-ce23-4289-9802-fb629a9f570b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3075a9ed-8ecc-432f-b672-9af81a1b97df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:24:00	TRUE	FALSE			en-gb	19:24:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3467d437-42e1-47c2-9d97-9a833263dd7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8cbd445f-0931-4957-b1c0-c2180cb7cd40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b53dc58-e52d-424b-846f-8750377b5fd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	05/10/2023		Ok
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
005b37a5-c8b8-4228-84f3-284762d59467	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e787da8-0bb3-4eae-b3d1-ae80a528917c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8ac51bbd-5050-4539-af82-d67aa87e1617	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
79468479-bf5a-4e7d-8fd9-6d77607e78b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0256c4a5-f93f-4ad9-a3e6-e7cdb0bcd303	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68477a8c-8801-44f7-91d1-aa5c27b38430	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c27c84c-6e52-4daf-b8e5-53fdf67d2223	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/10/2023		Perfect
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2628fcf-31d9-44b8-822f-4c0eee21d33e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e8ed0e7e-b83b-4fc5-bc08-ef41e7873c62	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
130657d1-96b2-4683-b34b-833cab8f126a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
766abf6c-7e72-4cac-adad-8b2e8b4fecf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d6d5b62a-1744-4401-8664-f73d138311f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/10/2023		The lady that clean the bathroom do and amazing job	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8c45a660-bde9-4cd8-90f6-5d7f3526d0cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
21bbe4a5-073e-4fde-bbe9-b6fc6583fd65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	05/10/2023		Great	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98369113-5e28-4f61-9e42-24f144c84767	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
69a77a0e-0a76-443e-91bb-847a2b399216	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	05/10/2023		Finish	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
16324b3b-fbdd-4b80-9769-7e9639664820	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3738270-fe90-4d79-8c24-7afa0851f461	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
335ef08a-76ba-4721-8261-1a5f07e2d162	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
bf19a5c2-e73c-4538-a90a-f8e3dbadbdec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
e972f2dc-c845-4a2f-b5d6-4c63a8cfeec3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
33ea81e2-271d-404d-9551-4e80b9ca650e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
59a8e97c-dd12-4058-ad5f-9e97998039b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1c6fe01c-4731-443c-a727-3718330f2522	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
810d6ccf-8c26-487b-853a-8b69a072d514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b2230938-6a4a-46f0-8629-353f628d1eff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	05/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d83aa208-f145-4cb1-a581-be085b491c02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	05/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cbbe5775-dfae-491e-b0e0-11a989b4850f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	05/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
591053b2-9dda-42ac-9afa-24e2ff41ea31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
c3bccff8-a734-4758-a089-e52e355a7e93	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
1dff2302-9d21-4ade-9a7f-9ddeb44b7720	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
d0d7b867-3d64-4b86-a008-9ce1888f2d28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
d23ef464-39f4-4ce9-9a77-dcc19c4d1dc5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3e071d2e-d003-4d99-bd69-d7cc11064e06	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c46abf09-a4b0-428d-96b7-9ac73047d77e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d509aeae-a84b-43b4-b2ac-a71fcad5ce8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
97aab931-dd19-493b-9913-a769f31c826e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54806d0a-b0eb-41f5-a17b-c7ce6accf570	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:03:00	TRUE	FALSE			en-gb	21:03:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a0a91ed5-40cd-4af9-b1dd-a15864e93237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
70d88d98-797f-42b1-9553-d9df871a4dc4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29d17d85-d4fa-4dbf-bfeb-0d4e0a1d2fb7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c33b42a0-28b5-43d8-b751-bb31e4a0ddb5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4412163-a468-4996-9ae2-3e0d91b98c46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6d24be91-1736-4e2b-9fed-6600a1586800	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:13:00	TRUE	FALSE			en-gb	21:13:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
26d347a5-02d1-4de1-b2a4-2b1d7536681a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:14:00	TRUE	FALSE			en-gb	21:14:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ad2dd213-9da4-4c06-a518-9c7256399353	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1222d56e-9136-4183-a6cd-f23e8ac334f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b0a244c-c821-49fa-9390-717908acb15d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7837318-3557-43cf-a962-de8fc9d76b90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3877b508-c6a9-47ac-abd1-f74fbb5dd797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	05/10/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1dbd6e1b-5afb-4681-af1f-8118498bb59e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
39c8b772-3a56-49db-9f0a-70bb086bee12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:43:00	TRUE	FALSE			en-gb	21:43:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ac1cf4ab-25ff-4f7f-a388-3eeb20910fde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c1ff63e-4c5f-47ca-94db-d049572e89dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d26bb0e4-b64a-486a-a031-d8f06c4ba749	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	05/10/2023		Fix it
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c534ff83-decb-472b-9cc7-d101e6117f8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
14b5f2df-b1ca-4a3c-a4fc-dbc871ad30b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:57:00	TRUE	FALSE			en-gb	21:57:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dabfb491-44ae-4058-80b7-6cffafad47a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c999a238-0747-4978-a8ce-bccf7fb78937	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24ec72ac-9ed5-4b51-8e76-cba60d783eb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11f62446-666f-4741-ad40-f1358250fb9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4138e1b5-fdbb-4607-9bd6-8e3c4d5886e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:11:00	TRUE	FALSE			en-gb	22:11:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d5ab1b9d-4a56-478c-98bb-918dac4afbde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d110aaa1-b425-428c-9143-2e54007b0504	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7208ef11-012b-4649-8168-43f9bd183e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9354bca1-0fd0-45f4-9c38-c81927651399	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6287add4-e35a-42b9-a329-3aa5dc33a244	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:31:00	TRUE	FALSE			en-gb	22:31:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0646549c-648d-49ca-8eca-43cce5ecce9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:32:00	TRUE	FALSE			en-gb	22:32:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
83113b7a-ba76-45d7-8a7a-ee35154ef8d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:45:00	TRUE	FALSE			en-gb	22:45:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
92cde1d5-ccb8-44e1-b9ed-b776ab829632	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 23:16:00	TRUE	FALSE			en-gb	23:16:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
154fa2b9-c9ab-4ade-88a7-111534d59397	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 23:28:00	TRUE	FALSE			en-gb	23:28:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3342b2bd-a7db-4c90-a453-fb52c5b4bb26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 00:44:00	TRUE	FALSE			en-gb	00:44:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
737acc18-d16b-4235-b88b-51e4bff2427f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 03:31:00	TRUE	FALSE			en-gb	03:31:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2c82d737-c0f4-4532-81c3-7640bedc69e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:20:00	TRUE	FALSE			en-gb	04:20:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f9ff91ab-f4c7-43e6-8ac6-16bce26b8fbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:42:00	TRUE	FALSE			en-gb	04:42:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
01a8d840-4fbd-4574-897d-553473922e39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:50:00	TRUE	FALSE			en-gb	04:50:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81ac8f28-242c-4062-b5e2-94bb178e9a06	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f4eb9a83-33eb-49a4-b5a6-b6abf7cccb3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:13:00	TRUE	FALSE			en-gb	05:13:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1d61c311-8f2f-4019-a22f-21e1b48bbd7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
34abd5d6-0608-4937-9dd4-521cd7d643d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20dc679b-6190-435b-8724-9f9e963d60ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
661ef151-72a3-4128-a5b8-9861a23aa690	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd4f7a94-df2a-4335-bd4c-ee215d353d4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:45:00	TRUE	FALSE			en-gb	05:45:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0fb18ca9-2242-4962-954f-c5324cc2a9d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:54:00	TRUE	FALSE			en-gb	05:54:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c54c2a0d-f621-410d-8f0a-3a3e26f709d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6c235a0f-2561-4184-bd17-7b80e276d0f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:06:00	TRUE	FALSE			en-gb	06:06:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ab6d6ba-a3e0-4650-8911-944e1adb5ab5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:07:00	TRUE	FALSE			en-gb	06:07:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c8310a0a-72ec-49a4-8b08-d10ddb96d65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	05/11/2023		D	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
312dad29-96de-45cc-8a1a-e4f02eb22d1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ccd41f3-80d7-458e-90ca-f60d7d11b595	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b455dd63-dfcd-479d-a9ac-fba651a33ef3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ab9aba9-54cc-4fd1-be77-6a2a5b2bb04b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:44:00	TRUE	FALSE			en-gb	06:44:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dfe7ee60-bf0c-4c3f-84fe-9b3ad850f7fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	05/11/2023		Buenicimo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
32d2b503-906a-42a3-bef5-7d2589f055d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	05/11/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a1cc527a-589c-4b16-9d89-cf2f1c8f2918	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	05/11/2023		Goog
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
630eeecb-dba6-4199-9ed0-010d55b68c24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b83d9c95-875e-44e2-a121-4ae142e5c170	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
26fc09a5-90d7-4ab4-b506-01fa235af537	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d8a71aad-69cb-4934-9607-e1c0fc318599	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	05/11/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
130e9b14-df96-4514-88cc-65b522c19cca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8313c402-4688-4d60-95d8-e5926929ec33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e261532-c09a-47ec-bc02-57a7d60a2c06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	05/11/2023		Nice and clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88bc2985-fe1e-469f-aca1-0a92b66cb281	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d773ef8-4ac2-4a48-b07a-cb2e597db28a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a286523-db3c-4aba-862c-d0ba43d5157b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da923adb-286c-4680-a3e2-385c44b57033	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	05/11/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06603182-5cf0-42c4-b5d0-f0aad1ee6731	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d0b4f264-7450-47dd-aa0b-de3e1cbbcbce1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
afbae95a-2183-482e-8217-366d5c8f2950	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ccf57bba-fb9c-4b1a-9d3a-f6f2bd0e7aa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
15509314-4856-4392-b9c2-41a5b66980b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b798fdc7-237d-4ba7-b563-0c0dd0a569ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
312c63df-4504-4eb9-9045-2162437087fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b5e46007-159c-4d5b-932f-3af113c9b60b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a417f2db-c2e0-476a-a133-18c8a38fd65c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1768316b-0a8c-4d7a-92f0-b701f8903616	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
147f4406-4941-45d5-b1b9-6a22605b0de3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bc03c7c8-69c7-40c3-bafb-3c4487290cde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fad02220-9519-4f37-8be7-9c4e3cf57374	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b29ac06b-ea88-4698-ab3c-02d42fb30325	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/11/2023		Muy biem	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
505bab0d-2368-4142-abac-7d56ae66b0ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4203a04b-8e20-4c55-a24e-ed1bafd4c1af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	05/11/2023		Muy muedo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f1641a7b-9816-4c8c-849f-94495c741186	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes							
7348fdb-31d2-46ca-9ac3-cb0e1f873e1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	05/11/2023		Lindo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5cc4c063-22bd-4aac-a2f3-023bcf0f04c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52092d57-2eba-41d1-afbb-b940fca1dbf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/11/2023		Acojedor
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76c527e0-47b1-40db-8d0a-ce61c1ffb288	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	05/11/2023		Bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6976b606-ad77-4ea9-bbe2-9384d449a369	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	05/11/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39e03169-c9e8-4c08-9871-37d7ef5ddb97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/11/2023		Huele bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fdc4f563-75d2-4061-9c5d-a67db5724c6a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
2ce23e60-36cb-4e32-b832-cf8a6e687854	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/11/2023																	
															How would you rate this restroom today?														
															<b>Average</b>	<b>Good</b>	<b>Poor</b>												
															Yes														
1a9beaf2-fcae-4a79-9baa-7a66b88a0721	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	05/11/2023																	
															How would you rate this restroom today?														
															<b>Average</b>	<b>Good</b>	<b>Poor</b>												
															Yes														
346e03f2-588d-4759-bfef-fc24146f8fd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/11/2023																	
															How would you rate this restroom today?														
															<b>Average</b>	<b>Good</b>	<b>Poor</b>												
															Yes														
004e924b-e631-4b77-a461-9c44b6579df2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	05/11/2023																	
															How would you rate this restroom today?														
															<b>Average</b>	<b>Good</b>	<b>Poor</b>												
															Yes														
9ab1f3fd-64e8-45bb-a869-b7cc8369a838	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	05/11/2023																	
															How would you rate this restroom today?														
															<b>Average</b>	<b>Good</b>	<b>Poor</b>												
															Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e65ed042-8c5b-4f16-9105-0093e1b2c764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d7503a5a-32b8-4fa9-963d-9db076cbb4c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/11/2023		Toilet had focus on it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
0a749f45-4fff-482b-ad2c-e9161b276509	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
d21845da-fbe6-4a1b-9508-25f2218c90d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d9ff512d-06e0-47a7-bcd8-e0f5284ac5f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/11/2023		Muy limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96c05df8-4c7b-4ccc-af07-31792d7b0fd0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2fc12147-6e62-4ff9-a5cc-dff218f1bb6a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95d580a8-3c20-49b9-8e61-130332309217	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes												
f9cae9aa-ba7b-416c-b85e-da77bf4a3daa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
40c3d03c-455d-426c-94eb-fed627f917dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7e28fdb4-4fcf-4394-a8cd-3f89c601bf52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a7fd76dc-5d68-4da3-83c0-ccf7a30cef01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0ae33df1-6602-4874-8f43-fef525055b19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cd4a78fa-9fe4-4854-82f7-980fd09e4748	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b7b0eb9e-9c34-4a6f-9ebb-6e2588bcd3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
185619a9-d0d4-4a75-a6ad-5de6ce26bacc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes					Yes							
4db6ce9c-dcf3-4177-8918-9f27f6dbb43f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c6a88ba8-29d5-41d9-a41c-38d34870dff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a8632080-78b7-45ef-8681-1ef198af80c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d98c9f3-2606-405f-902e-13b78a0708c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
45597473-2e60-48d1-8183-4d5a16773619	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:24:00	TRUE	FALSE			en-gb	15:24:00	05/11/2023		Smell really bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
3ac7a83d-5f91-43f3-a16b-913dc4281961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/11/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e15e3347-85f7-41f3-97a8-f50c50049e78	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	05/11/2023		Very good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a4fad2-f548-43d1-b99c-0cc4d4643732	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
0c7096e6-18f6-4b67-9679-be1195fae6a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes	Yes	Yes					
b0625440-4d58-4d1d-b250-299997eecbf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
270b99be-2db9-4702-b961-8e384d2410fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	05/11/2023		Amazing service from the cleaning team	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1fa8835c-10b7-43ed-b28a-8a33980a11d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes			Yes									
4048f6f9-1297-4aa0-95a6-3dcc9afecac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ee1e8e96-0dbf-4b39-bfec-6c7b1d328a45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7f8e91cc-8488-4f49-8bf8-e4ba77142b14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
17cfab31-474a-4a19-bc5c-9e02b99a1cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
848232da-2c92-468f-9a5d-01a47d5df08b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6253be28-94f1-4bdc-9210-a98619969781	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ebfd6bad-3e68-497c-a68e-a9357f0f8f2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 22:04:00	TRUE	FALSE			en-gb	22:04:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b277b72-b171-48d2-ab11-37fb27f293db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/15/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	05/15/2023		Johnathan test
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f707ff8c-eb90-46a5-a522-90c7d6c9eaa5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/15/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
419127a6-5d14-4b2d-9dd4-7713f7c188d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/15/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
fdf6ae21-3d27-49a1-bc9a-646899ee5f71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/16/2023 23:24:00	TRUE	FALSE			en-gb	23:24:00	05/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
20e89c2f-b9da-4f52-8e8f-c9ac31763c32	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
db563dfb-252b-4ab7-b59e-56d194408501	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ffb2b338-c6c7-43a2-93c9-88d6fa35af1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1853134-3d02-4d56-8721-a73918e1b66c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fe5e0461-ee64-4df0-b462-44d4c097ad81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6a9930f7-8c52-4861-b260-d18d006d9da7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
89b5d158-ee3d-4126-9f69-aa9cb600214e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	05/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
a9dcc734-3fc1-4516-a394-6eb0ea329b8c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	05/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
0c02c2a6-2f03-4911-a7b1-041e0d02550a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	05/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
8214349a-2347-4a8e-9276-e4f3ed484c07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
37e672c7-6fec-4efb-85ed-a280146b8488	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	05/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
45d4275e-abff-4ec7-869e-9c8a7b37fe4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
850cda70-fcd4-4a8b-9c7c-81409c26bb4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca684dc4-d938-4921-9317-8db6c06b44b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6b5dabca-50f4-4584-a18f-4c1bc3f3ebac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b17b6ddd-7741-4035-a7ef-529827e431fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2d58e5bf-7770-481c-9b4e-673b93e24052	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9590f53-6158-46d3-9421-c9c2650f43b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea025637-990d-4a05-9fb2-cfe0dcecc24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
773208f3-1dc4-47c6-8cd8-e0eb60223f91	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06635ff1-4027-47a6-bfe7-8af57189e354	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f95930b-80b3-43db-86a2-cf8aac572f80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:13:00	TRUE	FALSE			en-gb	14:13:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
31c2396d-763a-4a24-aa60-cd74fae498c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7aa27e44-6f55-44c6-bb94-89fe4000cf5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
57fd0e69-8fc7-4268-8e11-8e8fd0a99082	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
af5f7621-579f-4251-ae40-5705c82c1326	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c8deb6b6-7c52-48d7-a5aa-154e96afa6b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f901e755-0c9a-4a3c-8d97-65a07603b5e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d44aece2-75ce-4cce-a8c3-ae6f6cf679a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
62a0ca4f-f066-469e-a200-59fce23c72ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6e504c1b-8258-4ff9-b8b9-9a4bb2316b61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bb3fcaf5-d713-4ed5-a89a-006bc93e354b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
37a35794-002f-4729-8885-7aa18fd4a732	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
bead45e8-9637-4c97-9a74-352edc0ea1ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
71c9e3b0-98a3-49fc-99b2-6e7945d151e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	05/17/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
4e1038b4-e187-40be-a887-d320ec37b940	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	05/17/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
0fd5fc18-dfaf-4b21-80a9-7d8260933fe8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	05/17/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
1c77231a-9d06-4500-a804-cc2066b2109d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/17/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
5c8e23ae-daaef-47cf-a4ae-39986ec79b48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/17/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e3315595-7e6d-4f3b-96af-2f0a2effad17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41bacf13-220f-4f24-8c3e-49092b0aedab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1bd6dac2-4791-483c-9eb9-8e7650858435	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98f511ba-e406-41a0-82c4-269314621dc3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a669f6d-88a5-49d5-bf8c-83feac9e3a98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0218c32b-5957-468e-8d59-a5f780c73f79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a9082f1f-80b9-4b7e-9f65-5bd4031a6c3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
49fea50d-a532-46b9-bf61-f32cb851b81e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4247cc6-1756-4fee-af94-a1a0ceb9d154	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:00:00	TRUE	FALSE			en-gb	17:00:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7ec1201d-f9db-48c2-b549-4f87ec8f739d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
920c6178-f09d-4f70-9fb5-f46068585a66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e0ef905-7179-4e49-a302-03c3f9fe7afc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9903734f-ea92-4285-8ebb-7d8e744590a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44b66ba5-09b3-4a37-8c73-e76ed6099be6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a6edbd8-8657-44ab-b2f3-e2596a011c3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bbf213e4-6b25-4102-8ebe-5efc9c7ff868	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc01aa0a-8cbe-4ea8-807a-45825ec5fb7f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:02:00	TRUE	FALSE			en-gb	18:02:00	05/17/2023		Gg
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3525dfe4-be15-45bf-8626-bfbc08943694	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e22bee43-ae50-4bd5-bef7-470b188e3d56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b98bf60-af54-4f1b-80f2-2ef759573ded	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ce7362f-3907-4cd6-a8cf-de329a37ed76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
53f07171-5cf9-4566-8667-6eb80644c691	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ae0366f-6d45-40ec-8402-a78f3b1fa035	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:31:00	TRUE	FALSE			en-gb	18:31:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
08b5e8ac-2a01-45f9-98ca-0c7da3d0422c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ed313425-7827-478a-a846-b032395f4654	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
670c8e7f-512c-4396-98c4-9e28d810ab76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0926cf9-5c49-4154-8972-d20f52044412	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee38c696-7a7e-4514-9d10-7a25c10ad218	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da422c16-eb4f-4cf1-96c7-0b7e51a9b4e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c1a9813-2295-4873-8319-e00058c2551e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d6600296-6a4a-4704-ab1a-686a1c2431df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f72263ef-4e53-4870-90d3-7e9c2facb28f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
738bb173-21ab-4d3b-b7a6-38ad6a335cb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c55e4889-5497-4932-badb-5471d9e0d4f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/17/2023		Excelente banos super limpios
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cb265669-9f03-43c1-8fa8-af83847f7164	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0686b8e0-a235-407e-88df-e240fcc83e2b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ee970fdf-f644-4b1a-8077-95234c9cd8b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
194782b9-b547-4b72-b5d3-19c370501fa4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:38:00	TRUE	FALSE			en-gb	19:38:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
807e81f3-45b4-41cb-b97a-5c0899451ccb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6d7a79eb-504f-4071-8e05-86cf777fe4bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8f8ab70c-6fa7-444a-8fed-30a3aae6d021	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4aefe787-3ed6-4f00-be3e-73cc64e7d093	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18e274ca-22b1-468d-851e-0c1a29d16244	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5cf5948-4d71-4f05-9c75-a551dac897d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ede6c8b5-2964-43f6-8041-acbee171ec1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b91063a-ace0-44c4-908b-c5d03812ae54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e38d945-c207-4248-a637-9b03740f760c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a54c8bf1-8112-447a-8b98-914a9727d9ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
346c765b-31f5-4cb9-a0f1-4511a88f6abd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e7491c73-acbb-4157-8104-230e27dc6f74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2dbbfaec-efeb-4db6-9107-4fad38df08de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
73020bf6-23e6-4792-84e5-e8e3d8f3a64c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50614ecb-ea41-4dc1-9e73-ec72b9a157ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cbaf8d-8e78-4adb-aea5-3d155df9b630	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:15:00	TRUE	FALSE			en-gb	21:15:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6f131497-f7af-4892-b173-b069d6c255a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52b55964-4adc-40f9-9792-7a9b64f3d6b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:51:00	TRUE	FALSE			en-gb	21:51:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2b55ae1-b284-4ef2-b6f3-d161c22be798	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7413dd27-4aba-4b88-81a6-ea4bff55dd72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd802840-b860-407e-88de-3ff6996d381a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:06:00	TRUE	FALSE			en-gb	22:06:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d6de866-dd6c-465b-887d-c4627df55033	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fecc8ce2-e516-4591-886f-0d25a66e7762	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:19:00	TRUE	FALSE			en-gb	22:19:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0d096562-0758-497e-9c8a-c002fdbe79d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c7d64611-ecb0-4db9-980e-abead7f2913a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
a0550bd8-d021-47d8-91b0-73677e6ce8a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 23:02:00	TRUE	FALSE			en-gb	23:02:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
499198e1-2c05-449f-b215-487a015ec9bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 23:34:00	TRUE	FALSE			en-gb	23:34:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc8b5dde-ab44-49d6-8049-bb26a53786b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 00:41:00	TRUE	FALSE			en-gb	00:41:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f7cce4b8-54ad-44dc-b53b-9ded3642b6aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 01:32:00	TRUE	FALSE			en-gb	01:32:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9901106a-7468-426a-97a9-d0615a7a2203	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 03:01:00	TRUE	FALSE			en-gb	03:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad72f5e7-868d-4f9f-a0ed-21584d86f899	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 05:10:00	TRUE	FALSE			en-gb	05:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54c7cb4c-f7bc-41a5-b2ff-2a0ce08443ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 05:32:00	TRUE	FALSE			en-gb	05:32:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d4112578-ab5c-45eb-8ec0-c3d53be8377c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 05:39:00	TRUE	FALSE			en-gb	05:39:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76b6524d-5681-4551-87f9-1a57dc9c1ee8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:10:00	TRUE	FALSE			en-gb	06:10:00	05/18/2023		Muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44378640-f777-479a-9c14-b4d6e5fce287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	05/18/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0d86291-7b67-4467-9619-68239882569c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
00fef06c-0b4b-450d-8988-db0406780316	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3e60dc6-49b6-4733-bc63-cc3dc7bda1b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1f8a8150-7d74-4373-a789-63f95c3f198c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	05/18/2023		Thank
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
94b7af2c-80df-4c95-8240-d45fe0ab366f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a20b96d7-711a-4e15-bc4c-d2e56d37a7cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a61d714c-7a05-4a70-a589-32d53be931c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
567e6197-4f61-43aa-bae8-5a8ecd6d9415	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24237359-cd59-40e9-8fb9-c89b2fe43b72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	05/18/2023		More toilets
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
24237359-cd59-40e9-8fb9-c89b2fe43b72	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
17ef3cc5-83e5-4a57-b89c-821f709231d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b15ceb63-75f1-48f3-ae0c-9035825423dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f349172c-d581-4082-a45f-f826fdf2b905	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	05/18/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eebf67fe-e705-4868-9930-3c0ff245aa43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	05/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
041d8aa2-51b1-469d-bdbc-748cea79458f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
83a5c122-3249-42b0-b3db-050ca070f016	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d39b3572-36bb-49db-ba59-f87467be1471	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
932e7fc6-847d-4134-a3f0-1358b7066a8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	05/18/2023		Super
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e5f0ddb8-8af8-4b21-9eb6-ac5739def04b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/18/2023		Bien
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1fb8d2da-2304-46e8-9ecf-1ba5c39348ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
faa87d1a-a65e-4d0f-a451-830d7d40520c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	05/18/2023		Super bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bbb2bcfb-fd6e-414b-9ba0-ecd42e5b95d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c34b2a5-a885-444d-839f-ae1758b23cbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a02b53db-d6ca-4376-bbb6-4be34b182629	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	05/18/2023		Muy good el bano
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec9b529d-6beb-4d28-a95c-615d6b8aacd7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb2d179b-8fd8-4078-9db5-5763fa307593	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1637f25a-85e6-43b3-b9ce-357ff5183afe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	05/18/2023		Super todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b49e8fe4-6332-4b34-a749-ba935d4fb84c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/18/2023		Olor bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30cefbfb-c1ec-4fc1-9361-22fa60d8b758	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca52a5c9-b32e-442b-8936-07945552f9dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9df58722-5aae-4df3-91d6-1fcd2fc0aa02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
264a7d69-b655-45e2-a5d1-7aa6d0716ec4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	05/18/2023		Todo recojido
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
8179a4cb-1988-4477-a3b9-1aecaac34857	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	05/18/2023		Limpio todo		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
cb00c618-6dee-4c25-bad9-a9cc985758a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
1c9ea67a-e709-4e73-86f0-b938188ea300	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
44c5228e-0ccf-4968-9970-81e24895086e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
4d0a06e4-f53a-4762-9998-3793ec66017e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38c24e3c-a597-4bdb-a8c9-ee7807d60d9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
258cba1f-19fc-407c-8678-f190a740ad61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
859b13e6-2f35-4632-b1ae-59e5f5a4710b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
299fd87f-ef61-4d0a-83a7-fbf62e8c61cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
671cdbc0-5fbc-41c1-a538-3efbe031c252	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb6753ba-7760-4acb-a4ee-453d4242f0c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fc141af3-9061-4385-9b35-67a92b456923	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a7575ef-2ace-4151-b178-4e5b06fa81f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1808ebf1-07fd-4589-bd4d-d9b34125bbdd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6286be29-db39-4dd0-9ac3-6d42fb8948f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
8f4f1615-1ff2-4f4c-828c-fd7964dd9ab6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f0a9b4e-edcc-4c94-94c1-1347d44b0b12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1db473d1-939e-488b-8a18-9f73e940fa69	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
36d5d8f4-7269-467a-9043-d944a6074b71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91f29943-3998-45dc-a564-42bf190bb5d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a54a5e10-545c-48b1-b5ee-8bf79f3aa91d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7c64584e-4fb1-4540-aded-20ef8ddcff40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	05/18/2023		Horrible
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cf20c07-b998-4af9-8f08-a92ca7d67fbf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:17:00	TRUE	FALSE			en-gb	10:17:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
db613301-a298-496b-a7b8-5c866c268653	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
ebd4d0d0-ae83-4617-862b-c327539687ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
6c3605e1-17c8-4b71-b5e6-b88c4ce3a8b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
32a1180c-6fb5-4f2c-8016-36899e53d250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
8fefe4b7-8d08-49f8-ba65-2e96ee408a52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f307fa54-7c8c-431b-81e9-2aec369a493c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30b4ae27-bf71-4b5c-a380-01e811d29c33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a86799bd-a4e9-4346-9328-4f5328de7038	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
94809180-b932-4b55-a7f8-5256cd4cc50e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a93d2d8-631e-4ecc-9cb5-ada2043822f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b690aa6-74bd-4f7f-8c60-2d4c64795f00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2dde0b6a-514c-400c-a799-4c7a8cb168e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68e5d365-d0a0-4690-bfae-b4c2422f0bae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c6cd28d3-dee0-4dcb-bdbd-b393df538f0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76de2959-06cf-43b6-9741-958aa0be8750	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/18/2023		Todo limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b74c25c6-1e14-4fd0-9bea-6df0f7055709	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aeb70c23-07f4-4ed6-b91a-51d900e9e2f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
43e49c3e-926d-4bdb-8ac3-be286b5c8b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c0fbacc9-a764-4f4c-a6ac-f90aca8603cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6f35d977-0bb1-4bbc-be33-bbb89f546a78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8a2aa69d-6c71-4156-acf7-2692b22325f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
88ef8bcf-c844-4a5e-9e4c-e2a3afd03924	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c5c65430-28fb-4412-af15-8515b53c4ae4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
47334faa-ef20-40a0-acb9-f029b864a00c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9139a1fa-04d0-497a-ba13-257515720f28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6424d9a2-156e-4635-8d0b-f0cc5293ef8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a62f7fec-2511-4e68-82aa-afe2a112a78d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1a981d9-6ad7-4fb1-92e4-fda5bf990ce9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3786e6e-b6d8-4afd-b85e-c15d3f588620	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3ccc6408-8e6c-45de-afdb-1014a3f74da0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7ca95e70-af87-401d-9007-9efa99726b88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53d87102-89a8-4824-8d99-a67e14365ae2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
14093281-e86a-4b01-82d5-204b566b561d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
11a5c89e-a56b-4d42-af47-83af2640c159	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54e773fc-e9c9-4b0f-a2ff-875b8199b8ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ce27cb16-83f5-4f45-a51d-41bff2e9bdca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c541e29-c899-4f3e-8cd3-eb8fd4dc2a96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9eb2b858-c53b-4f66-9f21-4e33fd20cf95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3cb1239-84cb-40ef-8a14-ee62f50668b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76605658-5fd6-4c20-8c59-cb65cfa22390	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/18/2023		Stinks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
36dae9d8-e608-4511-847c-5273c2925242	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
97f7fc63-56d1-44df-85ed-895de486f40b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c1876ee5-23ea-4e36-8116-33f00408cfa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f3dc2c6f-426d-41dc-87d7-43fd877a6151	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8f78c87-4116-4936-a93a-45a14f491ac5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb5ac65b-9e61-46ad-916a-7d3ec87ca9c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1c678a02-ff9c-455d-851c-e9ea70c6bc1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
64d990ee-2f69-408c-ae6f-ed80f59735ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cce3cb03-a2f0-497a-9947-bd3998277f80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a1484ef5-1a67-48d3-b5cb-1eff78730366	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ac40db1-9be9-4c2e-9169-98503b401084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c841d84-aa11-40dd-bd1c-13065146c47e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
04152d81-95cb-48fd-88d8-02b9f038cacd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
80a7db44-c72b-4d9a-ac18-e17d2567bfd5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5438dbc6-b66d-4e42-a857-68157a702945	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a8b9239-a36b-4578-bca8-2e255e4c3549	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70263ffa-e1c2-45c4-99fe-0d8e2885398a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
37e99620-49b6-4e98-a461-f963d8ef0df0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ff5d428e-dd22-4b2d-8afb-2623f9ebf941	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/18/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e5fa168-0e1e-4a43-a8c6-5fd85b2d2ffd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	05/18/2023		Super el bano
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1529bc88-400e-41d5-b394-f8378d974ee0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
67ae30f2-4764-44b5-a2da-b1e6c290ba50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e47e6e18-a33b-42cb-a23c-12946418363e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a9427bdb-7930-4064-9558-d0e1d8ce3f36	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
440557e9-b370-4718-b7a0-003679735a20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
76ab85b3-c098-40ac-b449-a34a6c71c85a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
154f2b9c-2569-4805-9b9f-bd5ba9626c5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a3ba5aee-2102-4a4e-9c2d-092dc2d2e27b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e92cc06-d598-45c3-992b-7e2f4f7222b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9b885ff5-df39-4fc0-be44-e3516126f07f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3b570019-73ba-4ec5-90ad-7e809282655c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
184f87a4-d6ce-4c08-9aed-948ecc012811	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
584aa60d-1c8b-4fa1-9cfc-ccac58fda581	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1956b124-7ed4-4aa0-bf14-75c7ecd01a5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7af35cc9-9528-40c8-9a7d-6dceff5fc531	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
554ebf41-f783-4f92-8f6d-ea96f1340f6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ec2eeffe-c06c-49b3-9a8c-bdc4ce2becf7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
972f5add-ca46-40be-bc2e-f5d0b096fbc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e2d474e-bbcd-4c9c-b5e6-623f55a6686e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f24d5686-b82d-4726-ac01-be3043dd1447	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
371f71ae-aab7-4a38-b01d-e80df84e4bef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	05/18/2023		Good condition this r r
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81ecf3c1-d03f-48bb-af6e-01213f4ca048	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8857c426-7460-4e6a-b19a-bd380f7ca181	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9782e55-b062-4960-8121-a117eb7998af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cc375b99-a375-412a-9c9f-8af207b1c6a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
359dd46a-6574-43ef-99ad-787d3df202c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes		Yes				Yes	Yes	Yes						
d9da50ab-27ac-4832-9a09-5443de96f19a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2f753893-1dce-40fe-8fe9-9af1d0d5c987	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95ad1d08-e326-46f6-8d77-b1db665fbdee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1b26c078-8166-4861-8955-bd49c0df4ffa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c45ab71-48ed-4349-97ce-1bc2f2e333c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
224059fb-60eb-4798-897a-99823c81b959	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70a7f662-49f3-4571-8f7a-f5fa33fa95ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b6350e74-4d1b-4fd0-ad13-353155bf643a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce60b013-1647-4b6e-b52c-0fed4e0cf802	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
079d9935-5072-42a6-bf48-ab38a1a17ad1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8576388c-0f10-4e13-b6d4-849d6737012c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4c9b219-51c3-40a7-bef3-ec125d400476	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8eaa1338-c3e4-4ba9-8a73-248be607b66f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
806b32cc-20d2-4d14-9190-85348dd70409	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/18/2023		Great	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c79101df-5aea-4ced-86de-b00c993b4342	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92ee101b-4135-462c-9a0e-a3d713b0c134	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	05/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
21226bac-b949-4615-a259-b173417a0caa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dca8ceb4-05b7-4e47-8c53-b8e37c8eb5b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cae58947-6235-475d-9e16-10a2ed1c14d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8860699f-fbec-458f-9805-dc57aec0131f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c57e3a5-829b-4f5a-aeed-7e2170b2dd1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75035b02-1144-4c69-9184-892ccca2e9c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07ecff0d-e345-417b-948b-66832e78850e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
187628f7-6d95-4292-86d3-ee492b691f52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f2ef2cc5-e348-4cf9-893b-c94be294f2b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b260a79-0650-4053-8dc1-bd1a33855aa2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75ea97f3-0edf-4483-8e13-265d375dcef2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e63399f-8ca6-40ef-8dd3-901340cd9cbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
261fdf97-9453-4dab-812e-8c2e83b35b51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7851ddfc-84aa-4762-8eb0-c81a7579dbf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c641dd03-26c1-46ea-9e6c-d23bd1d7e835	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	05/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a9ad1d76-db20-4141-acb5-5327cf2359f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fbf3e453-e849-4773-9772-a14c1eebd2e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
abd6705d-da25-4f7f-bbed-88f38c06bad9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41563c76-41d6-49f7-b8cf-211a2d4b8270	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e260b945-b4f3-4b62-8ca2-8bee6bb3f113	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bbcfa9b-d2ef-4a26-9769-186dee1169ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a7a2c95-ce0c-489a-b7e3-27a8b801b0e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a476169b-2b45-4dad-940c-2346d3bde7e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
46ad1720-7f62-40d4-99dd-97c0a86bfd82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
374701d6-dc52-47ca-8f97-370f1731a251	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f975f9af-0993-4a5b-8beb-41c24867a087	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
64ee2c51-16fb-41a0-af1b-98ecda8149d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
02e3d9d8-9cb4-487f-bd67-945980d31b45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:17:00	TRUE	FALSE			en-gb	22:17:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
005792d6-1f98-41ab-a579-b9ca331c35a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:36:00	TRUE	FALSE			en-gb	22:36:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
38efc94c-c8d1-454d-942d-4079a4a40904	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	05/18/2023		Brasil	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e625e862-158b-4e9b-a94f-f2a38de98886	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 23:56:00	TRUE	FALSE			en-gb	23:56:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d2edb19c-8679-4f97-9d3b-bc8e1a6daacf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 03:39:00	TRUE	FALSE			en-gb	03:39:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfd59b26-0d13-4266-ab67-cccc9b3cce33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:16:00	TRUE	FALSE			en-gb	04:16:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0bf7094f-4827-4323-befc-8c7bb10f1363	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:22:00	TRUE	FALSE			en-gb	04:22:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9c0256f9-2083-496b-9bbb-d9397ff254cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:24:00	TRUE	FALSE			en-gb	04:24:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8fc2ab6e-9cb6-44de-8a10-a415706f993c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:34:00	TRUE	FALSE			en-gb	04:34:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4c452cc8-ea9a-4699-8d77-ed3790beb6b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f8f824eb-75c8-49a3-9a10-bc4ca50291d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:58:00	TRUE	FALSE			en-gb	04:58:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
17a1f77b-d0f1-4eef-8b77-57b893d613bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 05:06:00	TRUE	FALSE			en-gb	05:06:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bbe812dc-7c52-4a43-86a6-4a4fe7163ecd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
274e89b5-e9f7-4322-9028-1666415a44f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 05:56:00	TRUE	FALSE			en-gb	05:56:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c023c7d-4464-42a1-b62b-6a6ee7431b90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	05/19/2023		Super
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f5531820-679c-4f91-a03b-7408fd5b68f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:10:00	TRUE	FALSE			en-gb	06:10:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6be33d21-219c-4b2c-8f17-9567c21fd1a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:16:00	TRUE	FALSE			en-gb	06:16:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4eb5633d-aba8-43bd-84e1-ca723daf3fe7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	05/19/2023		Muy bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
441f0367-18e5-42b7-a2f4-fba5ad44649d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
354a3b79-1453-4b86-b3ea-e5d662866f74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
1d11987a-d032-4276-b548-5921f9089510	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6d7eca39-3ba5-4105-8e5a-d4f6433237ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a591dd7a-62e9-44cd-8f51-0fde7de4f645	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:18:00	TRUE	FALSE			en-gb	07:18:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
412c39c1-4d0f-4fa2-86d1-755eee52ced9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ff6e8dd6-24ec-48d2-8731-0d4d7c813bac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/19/2023		Super limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
01541486-c75a-4ded-9524-4a955a177209	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
667f61a3-e0cb-4c67-af9d-f237b62b244c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
206c4b90-1aeb-4b3d-95ff-16694bb043eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3423f11b-a05a-4b79-b0b6-af456fc0dcb0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	05/19/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5e1326d8-fcaa-476e-babd-772528f68606	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6278b754-82ae-4801-bb33-de21e5e5dd4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef2adb14-a273-4e74-a856-d5604063c3a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
771b9697-dc98-4b55-a6a5-a10c34f10b1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a8999a28-2490-42a8-b574-3227544c196d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	05/19/2023		Stink	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3b47707a-3378-472a-9f16-5e85b4cb4f45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	05/19/2023		Excelent	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e3065172-845a-4286-a670-1ced2053ec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7e4ca117-7b88-470f-88f2-2ab3cd5b8b80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
201a7fbc-7499-4c87-87af-e6989ee825c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44128d84-ddbf-427f-bac9-d7788cf0fad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9a339d08-ffa-4469-8aef-af024bbfe76d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b792499c-b0ea-4acb-8574-52787bda3ca9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
741302b0-bd6d-40d5-aa7b-db0dc66d261f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ba8087cf-f886-4194-8ab5-70dea74faaf7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
31234d4a-0936-48c7-881b-687ba970c064	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	05/19/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b442dabd-0993-455a-bea7-3223116a4a50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae0329d5-dc33-49e8-863b-518ba865eeb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ebdec011-7e43-4ed7-b443-a192351df5a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
343b9a21-9a84-47e5-9d40-0c45042480db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d314f63a-9247-47bb-89c2-fa12a9491f12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
12b14664-5324-4513-9b31-a02fe8d461c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a98f64ef-8cb7-4cf2-aa79-ac06c9bdf29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56091e91-9282-4e35-b6ea-eb3304a27476	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1dbd0889-1d74-4016-981e-024b12a4e7ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2d795046-9eee-4ba3-b7fb-68f5dc9f3585	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1b5e7797-9cbc-4622-b106-4de8e927ab2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc4c33ce-e54a-4c5d-9aab-4ba5541dd1dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cd121d05-b226-418d-bfcc-622ad40b6675	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/19/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
dfe48e8a-fb76-4a39-ab90-443a8ca153de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	05/19/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
3e52df2b-24f6-4b4e-9d49-0da342b7e56f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	05/19/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b849cb86-b0c8-4fe4-8e55-154e2e6cf01d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	05/19/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f593c1d2-9578-46dc-983f-0654cec4f171	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	05/19/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
9218a51c-2b95-495b-8f08-1d7ec47c4297	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/19/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
553a35c9-3626-41a0-b1c7-3935a18fe467	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b98ccf7a-5492-4b04-a44d-1b5aaac03edc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5101f19f-6d05-4ee8-aa80-0616dc0cecb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0d12b22-03ca-42b7-b6fb-bdb3f38ebb46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17af5078-d9ea-434b-b4ee-1e5763d3f2e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2949e129-0564-4749-92cd-b07c236104c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eb9f2f4e-8ecd-4254-aa67-d35470a07180	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32861e91-4d71-4347-91bf-921b45f52769	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc5a2cbe-4dc5-4202-b038-890fa0f2629	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1e323253-2f5e-45cf-acd2-c6e55329ced4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d69849c-4406-4d4e-a287-85fff9c9ff5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d580026-68c3-4dd9-8d19-ccf4f9ca80b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f67c130b-6289-431f-bc40-a5c0e4484421	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
90eefbb1-9f31-4ac8-9b9a-91c690a49f8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76b193f6-e765-49f2-88cb-31a7c5b9093f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	05/19/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ae249a8-22b8-43fa-9b26-249ebf406780	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes	Yes						
7300f7c2-a8d0-45e5-a2c5-b85af2f71d82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cc88b8cd-4d38-4086-bba9-42be25b244cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8b8c36ee-83aa-4511-9d10-39c0964b467a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes								Yes					
c1bdb396-ca8e-44b6-b83b-dfa0d1c3ce38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7885619-6980-493f-9f35-cc2a07cc199c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
132a8406-99b2-4235-a5b9-03e6a8eb733a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6244f4ca-106e-44a7-af5a-2a401bf5f0c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
821c8312-89e1-446e-ad8f-be29989e7cc0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1af1cd2f-8861-44ed-b1da-593ba5f11276	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d417effa-90c3-4ea0-9c95-963b5779216b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a1cc419f-e6bb-40f4-822d-566f3a92036b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eb12bcc0-5928-47a2-9e3f-fb0945913822	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/19/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
271bfe6a-ca7b-40c3-861f-86a6a482da96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be41b736-72fd-4087-acb8-3e35ed88f478	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11e2e4ca-7a54-477c-90f0-95025bb5a35f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Ofac6472-c2c4-4555-8e9b-19282ac13919	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5aa96e25-f250-4135-ba9f-9071ced54ab9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/19/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5aa96e25-f250-4135-ba9f-9071ced54ab9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
f5691c68-4797-4c8e-9b94-021ed3c5d8d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/19/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
8d7607a5-8a11-4e87-912d-1af0b366fd0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e95b5768-1e8c-4239-8e4b-c19f1aeb8cd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d850028c-06b7-4242-98ec-7cadfbd14720	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
426108ee-4020-42dd-bfc6-1724da343dd4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/19/2023		Bien	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
250985e8-885c-4d59-b43b-0de04691c184	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
49e9bc38-7d8e-42da-9a4d-8b0d96195bb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
33254594-a72f-4642-80ab-dba1ec847b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
93224224-1471-4d4c-8f2e-0d7ada0c9840	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	05/19/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f069ba58-7a08-475a-9f38-bc3ae0870216	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a4825cb2-ca8e-456e-8a1a-bce87d518899	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:12:00	TRUE	FALSE			en-gb	12:12:00	05/19/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
ae2a6018-2a0b-4b0e-bbf2-1e999aa5812f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
03c72e94-6e96-4fbc-a482-de7f37f12f4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/19/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af1315c8-d1fe-4565-9c49-0e80dd5b78cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0072d12a-83e1-469f-b563-c58d267f4c10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7eee5535-de66-4b85-b6fe-b61e3078e944	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82bcce41-8c13-461c-8890-e04a4452bec3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
398435e4-435b-4b51-aa82-aa660a900f81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e71147fb-8ed4-4d0a-b038-bf0588f64227	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d6ea182d-2ad3-4a75-8e9f-38a35b5d9e62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
badd87ff-7676-414b-b61a-0aacd87d0fc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25af4abf-1199-4359-96dc-3bb6db50760b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3e2e497-7414-4a63-baa4-93743d8c14e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
854c222e-944c-44d5-9595-a6fc61859680	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae8be0cd-ac2a-435d-9f05-e058eea6898c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bb81b987-d85d-4089-b627-e3272f3ed37e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b4867d62-5124-4631-98e9-c91310a7aed1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e599dbb5-f62d-4f3d-89aa-843e01074037	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b376c703-76f9-444d-a614-f3924c683239	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78a5ccd8-33f4-46a2-a2f6-38df9782d54f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:29:00	TRUE	FALSE			en-gb	13:29:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8bb846bd-6b36-4604-95b6-e9d9eb223c25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ce5af8cd-5926-4edb-945a-de512a3a72ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
265d371d-78ab-4ba8-9b13-9ae9a267d70d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
b441cfd3-9775-4d0f-8cc8-e6a20d53f2a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
83c219d2-cf96-4432-b99f-ff5cdc9c66f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:39:00	TRUE	FALSE			en-gb	13:39:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
da29b2ba-cd2a-44ca-a9ac-9a8ca8f2447d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
0e843920-9665-44a8-befa-a073902a68db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f8286295-14fb-4c8d-be78-d3a7d2669c5c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
abe92f4d-45d3-4617-9aa9-c397ca07624c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/19/2023		And smell	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
dd603aa9-7e5c-4ac3-a717-eb25d0c3c2ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e15b1b5d-0ebe-4deb-a82f-13e6daf930f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d874f9d6-2631-4224-b9d0-41dacf1662ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	05/19/2023		Muy super bueno	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
4c9195b7-c1a1-419d-919b-1dc0c22190e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
b7dfacbd-1127-4670-8a92-18020eb28e4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
1421b9ec-b6a1-4738-9378-b0a1170afea9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
9f10adf8-f56b-4b30-8aa2-ba276c535c54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c01cfe8d-057c-41ff-97c6-d46f4b489eca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
fdcbd4b7-fffc-4f82-9ebe-1f325d775034	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fcdcb4b7-fffc-4f82-9ebe-1f325d775034	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
ce799755-741e-4ef9-92dc-4e549903dc5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
def481d8-8d7f-4005-8521-0370ec64906f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb823736-ec56-4475-b7ea-37c54ddf7e32	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d0bd5cf-3c70-416c-8229-ad7337bf94cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aa6b57e3-8bf2-4401-93fd-920ce80ed388	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f3443a1f-7722-40b0-b6db-903a720ba748	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bbe64818-a3c9-449a-9482-fa601892edcf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
49c7debc-de1c-46c3-8985-035c80de95bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d40b745b-032b-4667-b993-91de6ba8ee4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3549ecf-656c-418c-9bbe-4a0a4a5935f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
943f87bc-38fa-42b4-abd2-75efee074a53	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
94227dcd-8d9a-4dc4-9efc-f9247a802503	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5da92456-07a3-474e-bab7-3929e9c855a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07a40422-cec6-4fc5-ac5e-7c62158259ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0837e645-5ec9-425e-90b5-caee7d5b5ad2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0dfb1c0a-41c8-4216-bd2a-0484d8493f9d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	05/19/2023		Yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
36ba8d0c-e98c-4ba5-b6ec-bceabacc34f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	05/19/2023		yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2e00c08c-142c-4d01-80bb-fb8cfc2755e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/19/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb4f7509-d835-4874-a033-5c8c8d000f28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/19/2023		Yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc79041e-cbdb-47dd-88a6-b849382d85ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:56:00	TRUE	FALSE			en-gb	19:56:00	05/19/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ff23f47d-64b8-424d-b833-d29d552c38df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bd4fb10-26ef-4b32-ab64-5e93da4e533c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0fa98709-681e-4632-bc61-1b4bd7d96c79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/19/2023		No soap	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2779374a-fa4e-444b-8238-0cc824dcffe0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6aa57b6b-6878-4d5e-b5fe-dcf73ce6a667	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
98e97279-ade9-4ffa-aede-26611efdbf4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 04:02:00	TRUE	FALSE			en-gb	04:02:00	05/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
228483de-346d-44b4-af1e-5ffc0668cab3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 04:08:00	TRUE	FALSE			en-gb	04:08:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81ebad3b-6130-4377-9720-2eff81192a0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5273fa5b-d3ca-411d-93e5-d5e711f378a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes							
b5a702f9-3e6b-4d47-87ee-e78241439e27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
67595c62-219e-4b76-8789-6f965073d6a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
602ae92d-3051-4384-a2d2-6037512795a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c510112a-573d-44df-b6c0-7a9bc2fce495	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	05/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c7d85d61-cc70-4baa-95d3-bacdb14f9bae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	05/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
bc201f90-1c17-45b9-9d33-e5576493cc73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
ae326de2-bd80-4a51-a431-e870fe1f444f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
84092f22-6079-4953-9c6f-af2bb453f2a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	05/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
84092f22-6079-4953-9c6f-af2bb453f2a1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
357ce37f-8e1a-4f75-8a43-71cae02f93bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8e9d15ca-9067-4d82-bc56-4bf482dc77dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0d277cef-d71e-40cd-a151-f404082bc68c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c341d3f1-31bd-4f6b-9a66-ba46efbc13e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a3ee21e-ec35-48d4-9655-e7e235b0b938	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cbf6b781-7c75-482e-9c4c-e8b562f32ef4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fe5de3a2-728f-464d-944d-d1d0111ed7f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d091eacd-84d8-4b23-a8b8-5b38c4481fd7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fad4d471-ae7c-4ab2-bc6b-11024afe89d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e89dff4-6f72-4480-8dcf-78d1e7da0ab2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	05/20/2023		Excelen clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment											
63d8c11d-c157-4cf2-abdf-71e2d11fdeb9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	05/20/2023		Sucio											
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
		Yes																							
1e80b87d-f594-48b4-a5d3-4d78eda1576f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	05/20/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
66f1d1e9-af68-45a2-adb5-1532aaedc1b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	05/20/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
089eb163-6ab9-4831-81de-b4dae5041830	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/20/2023		All,good											
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
11d88dc5-31ac-450c-9ca0-de4e954db83d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	05/20/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
6f1f9eab-beac-4c1b-9a72-6d1601ca4fd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	05/20/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8579ee27-cc30-4629-a297-7e5415065eee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c4c3314d-5fe4-4ae1-b0cb-b95eb416d248	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc8ef629-4658-4a33-a68b-a0253024dfaf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c1157d4b-04df-40ff-bc48-e5e22297e7c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07f101f3-a782-40ec-af0a-c0fa9400db35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
71ce2b70-c000-4eb8-8540-80272dccaec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
41802f43-2580-4b2b-a7e1-dff02fa3dc31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e5c95d8d-c5f7-4498-a8fc-398da7039544	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 19:24:00	TRUE	FALSE			en-gb	19:24:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c508d6e-1ee1-42c0-98d6-f1c47c40f155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a953daf-bb04-4ca5-bd17-63c6347f9273	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8de90010-7cf8-409d-85e5-b870d8d52e81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30d4428e-beee-42e5-b661-1104efd8000d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0716aed2-6945-48e0-96e5-726374c17c82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 23:48:00	TRUE	FALSE			en-gb	23:48:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6dc11390-388d-4647-8b3a-fe80fd82ab10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 00:12:00	TRUE	FALSE			en-gb	00:12:00	05/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1d861baa-ad2a-4bf7-b859-9b512b2a8a22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 02:02:00	TRUE	FALSE			en-gb	02:02:00	05/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
855b1728-2c33-4c8f-8cb2-8b987e5e80e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 02:52:00	TRUE	FALSE			en-gb	02:52:00	05/21/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b84bf4d3-3af3-4669-a28e-0a0fc0aadb44	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 03:17:00	TRUE	FALSE			en-gb	03:17:00	05/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c1e1b6e-1de9-4698-8003-fc977283350e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 04:25:00	TRUE	FALSE			en-gb	04:25:00	05/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6c1e1b6e-1de9-4698-8003-fc977283350e		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cef35e9e-84b7-41b2-95ce-915a7e691058	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 04:50:00	TRUE	FALSE			en-gb	04:50:00	05/21/2023		It's clean and smell good
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
48bd5aea-0d4e-416b-8f50-bad7f92f64b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 05:31:00	TRUE	FALSE			en-gb	05:31:00	05/21/2023		No
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
78525696-1aed-46f1-87df-30fcd5063229	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
a2dd7266-03cf-4d14-b3b8-14bc01036475	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
355e2faf-1ade-4dbb-852d-9d2b47a3a97d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e43d4415-1e31-4238-af21-f09dadcb5c90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	05/21/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c35de1a5-7015-481d-af01-ebf123659aef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	05/21/2023		Asqueroso	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f8a10d7b-2425-4f50-81cc-9355dc4c65e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5010deaa-84b4-4059-8daf-b5402ce3594a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
3f089c6e-54e8-42f2-af3f-cec05e4002d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4b0aa11b-f7ba-4b71-b6a5-dce05b0e3b6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
374ae84f-9c77-4fa1-947e-d7cf4f762558	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	05/21/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												
c0178e16-d016-4d58-a879-f11f37278cac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8914c6ef-a8eb-402b-9610-78bdce5dd302	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bc6d73ec-b52d-4048-921a-aa7788c05f6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2f0257aa-12e1-43c3-821a-c96e1263d8bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:01:00	TRUE	FALSE			en-gb	12:01:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eb96198e-12cf-42ae-8e33-54f42e5a7ed3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	05/21/2023		More ventalation
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40e2be73-a597-49f2-ae59-bd0a0dd1c297	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65690b8c-f121-49dc-beec-555adf3ebcf6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
716b293f-1b0d-40c4-a55e-d6044090f873	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	05/21/2023		Muy sucio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
cecb93da-0276-42bd-a094-bd058b632f3a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1b1bb137-4a8d-40c2-9d0e-7b45bbd5c622	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f7474107-c726-4264-8565-7f97f6b0038a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
544392d2-f35d-47fb-b112-090ea41cb9e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
915d1646-2e48-4ebc-a081-649fde707ce8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ff9004a0-75bb-497e-be46-e0f23d76c14f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff9004a0-75bb-497e-be46-e0f23d76c14f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
de815748-700d-4fa2-8407-1bae75bbe536	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a47bdda-88e3-47d9-88e5-52105ecb0a0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
244c1706-ff5c-4772-93df-5e92785f977b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e77f770d-e543-406f-914b-0be186ab1146	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ec707168-a300-46f7-8373-c93b27fd95d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
02dba735-4c9d-438a-899a-7b66b4e1158b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
39b97d43-e5c4-4c7e-90c2-b17dacce4b95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
d5b5f9cf-6436-419f-ba07-927af7f6343c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	05/21/2023		Stink	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
540cd166-fbdd-42ce-bcdf-dc72d5134614	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3fc3b6c-9123-40c2-8137-15aa62e8f0fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4add895-dfc3-495f-b786-3fc1a1d1c797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a72ff6b-b25d-44f8-a0df-9a9e8cd188bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d80e68ec-4015-4ac5-8ac5-c21ef614faef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7278983-0387-449f-8300-fa120eb63111	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
94eb997d-c11f-4c86-ac09-a174511ab65b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c922daf-6d5d-48cd-b708-11e88fd60a56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b2068b3-871c-4c5d-93ec-ee567a857084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96e06d05-7047-4d2d-ada5-ca5e528d575b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	05/21/2023		It was very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
820256d3-4263-4095-9d6e-bd8847843dc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:24:00	TRUE	FALSE			en-gb	21:24:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9ee296e9-5aa9-4b51-a155-cdfffa08002a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ce35506-27f7-4371-bbb1-da8507735883	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c2824a9-8b72-48ca-b668-9ba13bd55c9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 23:08:00	TRUE	FALSE			en-gb	23:08:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c544490-e9f8-415d-ba2d-6a2e8ed610a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 01:18:00	TRUE	FALSE			en-gb	01:18:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bef13090-c83c-4ff2-a3e2-5c8e81983a9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 04:56:00	TRUE	FALSE			en-gb	04:56:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c529e3eb-e089-432a-8790-59ec88288da9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
179ff816-a9f3-42c6-b145-d3217f173c9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44513590-f3b4-4d7d-93d1-e351a865ac6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e32f5de7-75ed-4322-8a51-1ef248b2042c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
cba6d971-0c20-4d42-b55b-08066b8ce23d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
a3bcff07-f465-4466-be5d-97791d58fea6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
dd8cd2ba-57c4-4fd3-913f-3664d3e0ca2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
76844432-0777-4a2d-b353-fcd8bf4ddce7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8f1f2b80-1078-4c7d-9797-14787254af36	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bf29c464-55e1-4aac-9185-c46877fce6d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ed8fbc2-2e65-423d-a66e-684ca4f22d43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	05/22/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes							
60f73cdf-aaa3-4960-b9b2-ed858bb84404	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d0bb094-08d9-4058-aa60-75febad44d7e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b581a979-e711-4768-baed-205d87b1dacd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/22/2023		Good job, congratulations
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
691c86b8-5663-4d29-ac52-5bc467075b68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
8ab81aac-9fbd-42b2-9f3a-1cdb03208f10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
6b606dca-d090-4150-9d29-7a8ad6b77247	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
28547c2f-41a7-4d1e-9fad-77dbe48631ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
78f8d948-320e-46ea-9da1-026bd7f5d223	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/22/2023		God	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
493ba44f-b1fe-47da-a441-a66604e86166	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c8415739-48e5-43a5-a81e-98d9d79ea115	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
7ac034a8-4343-4295-9468-62acf187caed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4806b3b9-6559-46c0-bd11-2cc169910b9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cca8e6de-29f0-4cfb-ae0b-b81a9c967617	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
58a4507b-79c1-4fb5-8643-b74d3ef71717	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2ca1461-cee6-4a37-bac9-2ea8f1a43ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	05/22/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
21e09c41-b953-4651-a490-4d9d7471e921	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fe834087-0db6-4d08-b925-381c8c0589b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
555296a8-1bac-453f-b23b-fc654d8c6422	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7bd30620-b2df-4554-a07f-ac7ce2f387fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6ee02cb7-a224-496b-bba7-e48891a54de2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 18:17:00	TRUE	FALSE			en-gb	18:17:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
776a78e5-d251-492f-9aeb-85a5aa4d681e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91f7abc0-7477-4018-8549-32e4c18c97cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54b9f872-4ac5-435a-b954-f82a9505675a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1459ed1c-873e-4e4c-a214-98493fe7d8e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1459ed1c-873e-4e4c-a214-98493fe7d8e4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes						Yes					
544b745c-409e-4ff7-b813-5b049d062cf8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d4ea9ef0-8645-4771-9860-5abda02d8fa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	05/22/2023		Guy working cleaned good.						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
4d79c7ae-f243-4e99-bf03-5c1d9b51f830	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
a0a3f5ed-16ac-48f2-98bd-2f3e732c1f41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
3ffdd30d-0f0d-491a-8454-72fdbfb043b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 22:43:00	TRUE	FALSE			en-gb	22:43:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c52850b2-5739-4073-9ccc-e95eb55deace	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
686aa40d-1955-4884-b7eb-21adc5263dc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 00:32:00	TRUE	FALSE			en-gb	00:32:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50d0342c-288c-45b9-9b6b-7e7305003f66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 02:49:00	TRUE	FALSE			en-gb	02:49:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d3ee05b-13cc-4c20-9a88-6eaa366d656	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 03:20:00	TRUE	FALSE			en-gb	03:20:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cce882f9-68bc-4fed-ac99-ea08b4f90e17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 04:52:00	TRUE	FALSE			en-gb	04:52:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96f20a2e-98b9-4603-84a7-9ff3a15eb1fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 05:25:00	TRUE	FALSE			en-gb	05:25:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
95776ae0-5812-43d2-b79a-6108d4ef2e22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51640b99-d871-4177-b3fa-2cbe2c5248be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	05/23/2023		Muy clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee6e89c8-49d7-450a-995a-6418e1cefb42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5ef8df04-2b58-458b-949f-a3f130eb7ef8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3aff1b5f-bc3b-4bfb-ac4e-8a1ccb7ecb47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	05/23/2023		Dey clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62e0dbcb-b396-4a78-8f17-39c96607dd43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2b472a4c-6018-4036-97cd-4181f672a084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f87a8902-ceca-4cea-8676-d13e1e1a036d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
817fb9ed-3b0d-40f9-9fd6-74fd75de556e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3cc4cce8-bb15-4f7c-9c25-1561aa5d670c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d0f6be54-ded8-4949-a9b2-5236b47074f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c633b3e1-5064-4673-bb2a-3cd0e6d12cbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aece2add-6bb4-4c6f-a8c2-8fa38f2e2e0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	05/23/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
abdfc91-d6de-4285-ab22-f784b5ae31bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bae636bd-fd33-4e17-8abe-af55f2a4bf48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da6306ad-c357-4dd5-a2bf-a46ad010437c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c9dd427-7d69-49d8-9206-d7129f2f9d6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ae99a05f-91e8-4a3a-8155-e92fb467be6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
dcab3356-e4c1-48c1-9761-29f2a3035097	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
6053cd0c-9625-4cf1-beee-ec661aba5ca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
607ea08c-add1-4c65-8b01-3ef47e20025d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
cc7bc819-6c27-4578-b06f-73906521b892	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cc7bc819-6c27-4578-b06f-73906521b892	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
a8d1bf6a-8c01-41b0-827d-cf562f642abc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 15:24:00	TRUE	FALSE			en-gb	15:24:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4dd73447-0219-4a7d-879c-c48187ce46dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
21cd2f44-1ba6-41ed-b26b-11a54e00203c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c17751e0-f7ea-468a-bed5-b6ba5f0a99af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
93751e22-b63e-4b18-8319-be741c349774	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7fefe167-5973-424d-97b3-8b3ad171c53c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a462acba-e008-4cca-a88c-94bd1b566a74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
452b1e37-7ae6-4402-bb45-f097ea7811e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
642b02c0-1949-4df9-bb79-6956ddaa8bd4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c682d3f3-a5d7-42e9-9026-5cb7b24ff02f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 18:28:00	TRUE	FALSE			en-gb	18:28:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0565c0ee-aac2-479d-9ec0-12e1e8a5c19f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2314a5ed-ac8c-4bf5-bf23-08e07b5e3601	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55965782-d15c-4eb3-9fb1-0f67bd6b85ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ecb33c36-7a7d-4555-be9c-3211ccc3b738	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2706fa95-f251-4c21-91a0-cf9506bf3d40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4bee973-a709-4fd0-bed7-60a5d253618d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a4bee973-a709-4fd0-bed7-60a5d253618d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
6b3ad696-3e23-4f4d-b8d5-0cc8097a78c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	05/23/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
739f2056-c91f-4be9-95ef-890f80aec5e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes					
60d57595-bba9-4dee-a228-6b39db746ddd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 23:38:00	TRUE	FALSE			en-gb	23:38:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9f6f8000-3c1c-4357-a199-e9388f00a888	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 04:33:00	TRUE	FALSE			en-gb	04:33:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cb593f9f-2585-4c75-8f61-e42e2c801a09	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd4107f-1ffa-4339-af3e-ce7714bb5fdc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 05:49:00	TRUE	FALSE			en-gb	05:49:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4d97120-3ba7-4563-8745-5d69f3f940c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4615851b-4502-4086-8e35-56b2e3a0f200	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 06:19:00	TRUE	FALSE			en-gb	06:19:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
48cba56d-5b33-4179-ae0-a7a34b876345	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40a17daa-cc47-4fbd-b312-12f2bec8ffae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ee0b94c6-693b-4270-aedb-2b69c9a83da1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9533152a-2037-4961-84f2-48b7e499caf6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7706acf0-1d95-4d9d-bddc-51ef5550eb5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69993d26-f092-4eed-921c-6949d87dbe27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c07f8a27-7560-42e7-a061-7a82910ce7b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	05/24/2023		Test
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98608b07-9db4-4a2f-8735-1659ff88abc8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9fe86c8a-b4ec-415d-be62-c55fd420bd8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edb25b70-66ae-41ce-b7aa-bce47013b2c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3156980b-a96f-4313-8e65-97fe25678859	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
adc7c07e-47cd-4d10-b904-fd124f66c744	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd06630a-5c7f-4836-bc41-e69a174b5deb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	05/24/2023		It cool
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c6e58f0-c4c1-4e4d-8463-a74cf294f13a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be3ba5df-d10a-44ac-9955-22046a33936d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f23a90d2-9731-4aac-9568-96f3d60b090b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
61ccdf8f-2a94-4cb9-be26-a66a8d1a89c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
712482d1-bb62-499a-baa7-d7c71197a85d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
51b42ff9-94e9-4c73-a8a9-1ad578a61f37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c5cd9f61-e077-4a6e-81d3-dca470e09bfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d52eeff-08fb-4e5a-a70a-9686397fabfe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
89c9e145-2d70-4f89-be61-8d4459129272	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	05/24/2023		Hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc11f2eb-bb1c-4865-a4f5-666e6f05f52d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c314c365-2273-4cd3-8487-f0ee04fe2332	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c314c365-2273-4cd3-8487-f0ee04fe2332	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes			
1920cd5c-a1d8-4b5e-a14b-8a6ecc7d8b1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
fcf1e692-b746-494b-bf20-989edbad0547	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
3fc5cd98-335a-4c56-851a-1d21b1397a43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
f6a9aa6a-6dfa-4d5e-99a6-78b0267b2541	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
97d5b37c-cf7f-4ed6-aa7a-9d40f8cdf956	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b1a720a-188c-40b4-9943-ebecf5bf9304	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bf2eedfd-96b9-434f-9166-e2a9f887fbe2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e8a43ff7-cc51-4c6a-8bde-3654cb5304ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
6bc37f7f-669a-426f-84ed-ea9e6b1c60a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5dcbe5ec-411d-4c84-8306-1815660c10aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2dedf633-bcef-47f2-a372-c7b4df83af79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53fd9c84-69f5-4e63-9514-91ad759dffda	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a10a90e8-b768-4b25-8a57-7f8c5d5a006f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9b4d0892-1c38-4822-a5b7-4b1f7f358a30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3fc420e2-877a-466a-beaa-4a90daa7852a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e172f3e-7be0-452a-9425-49ec1fc828a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/24/2023		Not AC
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e172f3e-7be0-452a-9425-49ec1fc828a6	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
f45f60dd-192c-4828-8045-293606253d1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
429d4ca2-7555-48e4-ba05-5c4790eee806	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d96d9589-b021-44f4-9580-53a36212054d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
029136e3-f973-4816-b609-738b1030e865	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b7b61d5d-700c-43b6-befe-10ef57664f73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7b61d5d-700c-43b6-befe-10ef57664f73	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
f95ea8c4-932a-4352-a87c-0c9d5a960d7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	05/24/2023		Hb	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
0903988b-5a25-4a53-ba6c-17293fdf95b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a9571ee2-1b7a-4561-b6e4-38cdc1319ac8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a6444cb5-1b68-4365-978d-0cd99c7b380d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a0e2372c-d597-41ff-87fb-7703a6068f11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d4689205-6e29-4aef-a107-16b3dff7a7d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/24/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
83354220-a267-4e29-a99b-bbd158cf46e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d17b215-a4d9-45da-92d5-44edf9732114	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
10e6c1fa-185d-421c-89e6-b183010e2c05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d412beb-769a-4e55-9a0e-3b7691bb23c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	05/24/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5fd4735b-d23f-4090-9371-77605a30f1c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
61e390e8-277c-4f8b-ab49-a1117c6aeb19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6ec3781a-f1a0-4a45-9e23-95f9a56bbe18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9ca5ddd-70cc-4fb0-9104-452c173417cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1406a209-f51c-4470-adf4-f9c2a10174f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e94d635-511a-44f0-b557-a7364cfa2d62	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4ec8124-c302-4e26-b802-5cb862f164e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
519e60dc-f80c-4f20-a56a-ba341026eae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
901acb0f-5e16-493e-98c2-65718f652e79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
741a17ae-4e75-4cb9-9aa0-48cb9c606d97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e5dbecd6-8d56-4384-a531-bbc9c96ee74a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4096061b-6d20-4c3b-9747-2739404e3f7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ee0e865c-b54f-4694-8070-0d00dfb7debb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
75031ed6-4305-4870-85f9-1119ab5dfb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a3d10484-7d81-4ac5-8e68-cc900c538583	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	05/24/2023		Excelente, todo muy limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
134c666b-02f9-43bb-bec1-cb9d502e2793	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	05/24/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
abaf2320-59cf-4dda-9dd6-6fc5bff39884	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
065b59c3-32a1-4242-b6cd-96a810c8a3cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4aa79284-49ee-4d09-9bc8-ea94c0c80ea8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5af79337-c9c3-49d8-b097-eac8ace2841b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b60a7385-7aca-4824-a900-3e1b6447de14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:56:00	TRUE	FALSE			en-gb	15:56:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9dd3db7a-2ce9-435b-af6f-fa807144951b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
35eced8a-2646-4600-aa35-d673447bc0c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d7c99222-4eee-4f39-b185-b8420b6799cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:15:00	TRUE	FALSE			en-gb	16:15:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da1c5eb6-637f-4bcc-a7d7-0ac266b270b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da95f827-9ba4-4164-be16-9e664035782a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0998fff8-5a35-4517-88a2-fb6d0daf2b24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b119135e-90fe-40b6-b6fd-cf380ba61940	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d634820e-c9c7-417e-b775-a4342af08408	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eae789f4-5189-4a83-b989-6da5beadea81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4e82e950-efd8-4aef-9114-29b2675abca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:01:00	TRUE	FALSE			en-gb	17:01:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1ed2ca28-92a2-4759-9022-37dfe0ac37eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
82e23c8f-ad6d-4d44-90bc-ecfc0030eab8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
82e23c8f-ad6d-4d44-90bc-ecfc0030eab8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes					Yes						
9efcd99c-4749-49e7-bbd8-f6f128096d9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6a154608-27bc-480c-8a8d-0fcf62d6bcab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77de72f8-9fc2-45cd-9a85-8980382eaa6e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
c23d7b30-06a3-4615-94a7-d8ce6bad8e18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
facceb1e-1f3e-4d83-b554-3059fa652243	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c3ae973b-6e2d-44d2-ad19-2b13b15c0075	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4435898c-a382-46f4-a5bb-b83a1047cf21	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
94a5ebd4-ea9f-4605-a37c-fcbd9e3fff00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a199a057-c020-4f75-a53e-9e55bd34489b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
88c1f796-fad7-4d57-afe1-31195ba1a9e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b0bb301a-25bd-460e-9a57-cb3cc2ca12a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
738e0bde-b934-4d97-93aa-2ab276646440	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
97e95e61-dd51-497f-8a6c-45460177bbd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f9b4313e-1496-436b-a5db-c2d2f517554d	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:32:00	TRUE	FALSE		en-gb	18:32:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fdfdbac5-1086-4072-8ce2-5cbd6886435a	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:33:00	TRUE	FALSE		en-gb	18:33:00	05/24/2023		Dirty diaper on counter	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
05aad90d-9772-4a87-8af2-6950067d2222	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:36:00	TRUE	FALSE		en-gb	18:36:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d6476689-568e-41f9-b429-aab5152f2c2d	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:43:00	TRUE	FALSE		en-gb	18:43:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b85180e9-84f1-42e4-846d-e4c4bb0b4c5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c630c4e5-d0d9-4251-b1a2-0b0fb052cd22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f58ab8ec-6508-4a2b-8789-ca9dbd0f9a8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88931b16-76ba-471c-ba49-9195fae57709	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dae2b34d-db1c-460f-a2fe-5b9ed9373aa7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
4db8fc84-198c-4729-965b-e4476f41fab6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
680e8533-a842-4e2e-ba6f-5338b313b7c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	05/24/2023		Beautiful restroom
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c20daa5d-6e33-4870-8806-c424b50b67b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	05/24/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5149f64a-a33d-4d3a-a635-06db2ba20d8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c65463ad-aa48-4d56-add0-44f6a6e90742	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ff183614-ed0d-4809-999a-2ab6c83c6e5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22884ace-f8b2-48ce-98e4-a01fbcea8d0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
357be701-d48d-48c0-b631-ee316827380e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
07fe391e-c27f-478d-be85-96713aa32648	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	05/24/2023		No
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
a68e9aca-bda6-42b3-8dd1-d30b3e4798bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
dc5f1cfb-b2e8-42ec-b5bf-16b4e87e7b48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc5f1cfb-b2e8-42ec-b5bf-16b4e87e7b48	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
5292b57e-f802-42d2-81b5-59935b4b14a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d93d4308-5f5b-479f-8d4c-e0a58ef85451	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
8733cfaf-00de-4fba-9ea3-9c3595d62142	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2010dabb-c1a3-438b-bcb7-e79e16ec9561	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e918a87b-22e2-43b9-a549-cf8cfde9715f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e918a87b-22e2-43b9-a549-cf8cfde9715f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
00273879-c1f5-47ac-90a6-f18b309d1dd3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a06e42b2-3a76-46c3-adc1-5aaa31bd2917	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
77faf0af-bb20-42ae-aa34-f06d69f5a9b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
b9b209a7-4b4a-4979-820e-aa95d1a3f685	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b9b209a7-4b4a-4979-820e-aa95d1a3f685	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
635493d0-e2a2-4328-abf6-74f9d54948da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	05/24/2023		Clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9139e81e-8beb-49b5-b4f9-5890b4100b3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc519cdb-2fc5-4646-a6a5-ea3c9ace330c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9a6faa28-e962-4bec-8291-e5dfe4f13491	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
92d51b81-b41e-416e-aa90-cceed0f0086f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
817a3183-5589-4cd4-8321-9e98a9e09016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
c6f61c09-e024-4f07-9bf6-0604889eb068	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
869f0122-f1cf-4079-83a2-f5df32b27b88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
79153aa8-0222-40da-8fa9-92d6e3f805bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
c8506200-007d-4687-a59c-2e6235b4e764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
f8369a21-f824-4bd2-8116-64ff6250156e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9fdf016-cbe9-41c9-a574-08d8e4b8d796	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39876729-2968-4e0e-abec-7bbe0088f45a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
106835d4-1651-48fb-8ae3-e4bda77b4c52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7249b10-ae49-4954-8e7d-17da4d22ad4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc0d3ec8-7d8a-4ab5-b88e-7f5fa0004046	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/24/2023		Mjgh
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1bfc0c32-6799-4ef1-bd09-a51313c9a0a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6755e62b-f675-4ef6-ac00-669a42c3fb16	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:03:00	TRUE	FALSE			en-gb	21:03:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1d281904-6512-4df5-9006-4b901367534a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1066a9b8-7604-4763-b271-c564395f3301	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
e0b9bacd-3dc1-4e77-abf9-5758ea9f5da1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
648ad32b-735f-4545-b05d-57cb01b58354	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26556c15-819d-4556-8f03-5b059441c570	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
34b845cd-684b-4da2-b65a-a0ea7961cd1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
35435b63-23fe-481f-a3b2-06a0812431a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
91276190-7b6b-4663-99c8-2d3f248f2326	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2a7f1b71-7de8-4a1c-ae34-b9355968dfe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4f892f9b-a3c6-4df1-a670-67952fbb7e30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
441fd014-c189-44b8-a205-e51610c7cf98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/24/2023		Ok everything	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
29032522-cd8d-49e0-b6bd-1dbeb9ee88ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3fb03f2a-b22e-47f6-9584-d1d61072882b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	05/24/2023		O	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes		Yes	Yes	Yes	Yes	Yes					
1c60e96b-e8e9-4362-adde-536aff7010a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d264dada-687f-4003-9ce5-71caf8857c73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:25:00	TRUE	FALSE			en-gb	22:25:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
22e1a1a1-1fcf-4ae4-adad-47ae44ed2cde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:28:00	TRUE	FALSE			en-gb	22:28:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
21c2505e-9450-41a5-a94a-d8cb0012d88c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes						Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
91d2df66-62bc-48f2-9cb1-c7b79231ee56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
626beb8b-7b45-45bc-b8f5-43ed73d9846f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d62e714-e932-44b3-b4de-05bbe91bf1e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b1ef3a9-6173-40d3-86ea-1f7b1f00bbc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:44:00	TRUE	FALSE			en-gb	22:44:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							
6adcf7ab-e53d-4692-98e4-ff944c9fc9db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:49:00	TRUE	FALSE			en-gb	22:49:00	05/24/2023		All clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
84f58b43-163f-4996-afac-090b3784ffce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:57:00	TRUE	FALSE			en-gb	22:57:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a7a75c52-1203-497c-8975-2a62b299f995	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:58:00	TRUE	FALSE			en-gb	22:58:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
331abd28-392d-49ff-9ec4-4bb6b0e6ae41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:12:00	TRUE	FALSE			en-gb	23:12:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
301fde45-f2e4-4890-a945-14bd188c9430	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:24:00	TRUE	FALSE			en-gb	23:24:00	05/24/2023		Bathroom completely unattended...no one here to clean	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
301fde45-f2e4-4890-a945-14bd188c9430	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
f2a5e7a0-07cd-4319-b910-6b7fae467343	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:41:00	TRUE	FALSE			en-gb	23:41:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
01105f01-ec1c-412f-b549-5bb0f07b80c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:50:00	TRUE	FALSE			en-gb	23:50:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes											
63b02a61-bc62-4f18-a980-79cd4897d44a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 01:36:00	TRUE	FALSE			en-gb	01:36:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
63b02a61-bc62-4f18-a980-79cd4897d44a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes						Yes					
f6720230-ae4e-43a3-ac9a-1532eb923b71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 01:55:00	TRUE	FALSE			en-gb	01:55:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
bf901135-21a5-491b-9e33-e9640b2d5762	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 02:38:00	TRUE	FALSE			en-gb	02:38:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
2ec6a5ca-c72d-4d4b-bb93-445862c7c099	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:18:00	TRUE	FALSE			en-gb	04:18:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
efac760c-1b67-4f43-87e7-75dba290e4f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:21:00	TRUE	FALSE			en-gb	04:21:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
3d095c1c-2f04-4dc6-9d36-d59dab8b4737	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:25:00	TRUE	FALSE			en-gb	04:25:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5223c77d-4e9e-4f55-8b5b-9aa6ccfd1c52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:42:00	TRUE	FALSE			en-gb	04:42:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1c76483b-473c-4a82-af19-580de972184a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:43:00	TRUE	FALSE			en-gb	04:43:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
977e6055-4a45-46ba-abb6-c8662862a87f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:09:00	TRUE	FALSE			en-gb	05:09:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
59be9ac0-923e-499f-90cc-2963374a0195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
294372d0-93e6-454c-82ec-4dec13bcb334	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:15:00	TRUE	FALSE			en-gb	05:15:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cac4acc1-d1b4-415e-94ad-d4d68a0a3cca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51eab57c-2ce2-4c11-9a99-fd13c4cac821	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82e8c05c-0217-43f9-82c7-c3423560cb44	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9073e711-07bc-46ef-a9a5-daec937dd190	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aefea173-855f-499b-ade2-27f58540de81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00059316-e076-42cf-9bdf-8e395c8ce6b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65555907-6f8d-4cda-b98a-de76859c2734	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	05/25/2023		Muy bien limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
74b1a23e-26fe-43d7-b015-3f259ae7c644	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
97b1a5e4-d2b8-4023-8cc0-29473920cb76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41304bda-4321-4289-a9c0-88c59626e58c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
425e6d10-eb6d-46c7-bebd-376e9f3b4202	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:47:00	TRUE	FALSE			en-gb	06:47:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e043cee5-f7b0-441d-bcf1-dcd4949fd921	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b39ebd0-0c92-47ad-bf5d-130d7e39478e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:55:00	TRUE	FALSE			en-gb	06:55:00	05/25/2023		Mucho bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
31d4f347-2b7d-4811-a81d-057441121883	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85724d48-e9ae-483e-9d50-bfeb4dd30d24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2db4d29-a354-4a44-b342-5d73bf922ce3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a88cd70a-99c9-4c11-9540-cf3a3b2bdd2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	05/25/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
196db1f3-d385-4e9a-944d-7b3e672ba970	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4aad17a0-0af6-40d1-8580-c3fa13dad210	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:03:00	TRUE	FALSE			en-gb	07:03:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cbb6330f-96c2-406d-9bfa-6cbc5981400f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:05:00	TRUE	FALSE			en-gb	07:05:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dac5b2f0-aea7-4821-ac4c-ac4bb0140109	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3ffb579-bfae-4a89-a1a8-c3869b4a5ce7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:15:00	TRUE	FALSE			en-gb	07:15:00	05/25/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
12c03429-ef5f-4d52-999f-c7bd5c2040cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44a6e273-71e9-4edb-9c0e-d9c7de537e55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f480ce93-a30c-4a42-979f-ce2dac3918a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1bc77185-bbb3-4505-9d81-6cb2dfacce9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9118e7be-0570-4a7e-9e28-3779e5917cc0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
61ecfbcc-b21e-4832-97ce-5e14139564c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea41107f-e0eb-495c-810c-2e981592dfaa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4bc219f2-af88-4e66-93b7-f54aeed885d4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cb1906d5-2959-4fd1-886e-0c26f500ed41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
319ec21a-4eae-4fca-a118-6a3ab9d304ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/25/2023		Es bueno muy limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54170223-0b04-4c5c-a4c1-0be0e17b475a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment										
bd341780-e76b-4bf0-8784-2d1982e4c0f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	05/25/2023		Por favor si no tienen en que gastar el dinero delen un bono ca 6 meses a estas empleadas que trabajan tanto porque estas tablet los muchachos las cojen para jugar y las rompen por favor asi se estimul										
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							
3799b197-309d-4b5e-8ca5-0d38c6644bc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	05/25/2023												
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							
1a5d25db-8990-4d23-852e-be1dc8f7b399	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/25/2023												
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							
95427d03-2828-4c35-8832-b7a8689c3a37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/25/2023												
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
229f9d29-2cf7-49af-9ae6-6817eecee4f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5594b072-157c-4698-80ad-5fecc7071935	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1e2ab6cf-d536-47f6-aab9-38cf2becc87a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0b31fc7-a0d3-479c-a545-89a49e65f897	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0556e3d-8aca-4665-922e-913ce1db4f8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b73e61a6-e083-4e3f-9948-97458644ae8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f0592b4d-138c-4876-a258-175b40dfe5a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
646ed157-ec13-468b-bf83-b9ca2ffccc89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4fb07d63-e0f0-4286-9577-b65a90fdf0e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0fd62053-147a-4b3e-87d1-511f3b3a8227	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c9d6c80-5a3e-4786-95be-338606e90b72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b7ed568-2fa0-4620-bc79-2dcc8638492d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
313c4f20-30f0-41a0-8b1c-d91ad02b1dc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f2edcfd-8eca-4437-b223-76ab60ea5f3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e76b37d-66ed-4b53-bcce-4e38794da689	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
be89bf62-2fcf-4048-9d1a-1cba452ac9c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3fb3ee21-7574-4166-8679-b421beb4083c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8269c4e9-a597-4ac0-87a2-5206f85852d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	05/25/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8269c4e9-a597-4ac0-87a2-5206f85852d3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
c5611f05-9d92-4abd-8621-82c04cc71edd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51f2551e-24da-4a76-a5dc-068a74f63f89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										
52018221-f0f4-413d-8d4b-fd1c606714a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dfb0a601-1c9f-49a5-97e9-471017011541	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c7337c14-6775-4e27-8c34-1b3eaadb3b89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6d6f620-37cf-4d97-8fb1-d62146888ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5ad77b68-85db-4b76-8bb6-3806f23fed28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e8478769-5608-4b13-92a7-e3a5b2f53979	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0f842013-cba3-4abf-a339-d3168f43a02f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c90af3af-c36d-41b5-969e-dc942f747c36	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fe2aa723-825c-4f4c-9f4b-166c79f3066a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ed09551a-afd4-4c43-8086-11fe5b9206de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d29013dd-825f-41ca-ae63-6849e10df158	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca4a2291-00c0-47a9-8441-ce93c7c9b0c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d8366744-bd2b-492d-bbfd-1f6d7bb62665	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	05/25/2023		Yes this bathroom needs disinfectant and fabulisa. It smelks terrible. The paper towels terrible. help the ladies thank you
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d8366744-bd2b-492d-bbfd-1f6d7bb62665	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
914c5f57-7e8c-4638-9f98-03c432be278c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fee5ae4f-ccec-4977-b254-e91d2596d271	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3505d22-4fd9-4f38-8804-15ba3dfb4a74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
edf0a253-465b-4fa2-a3d1-a36f67dd56b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
ef3c1e64-f16e-49b7-a09d-480c8a774e92	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
48ac9f52-ce41-4a13-a626-55480aad66b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
9ce561c1-7ec6-4d3a-b459-aaf03928e86e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
b9f31158-1633-4c09-930a-ef6bf354c4bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes							Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5b2d8b3f-a6eb-4450-841a-f7cc52b298c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3683f08-168e-40ca-b95e-a582be5c247b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes	Yes						
a49addf7-5c2c-44ab-9eda-5b11bac70a04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
04fcde1f-de91-4fca-92f3-dd546af26a8c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e1a2f4f0-d50e-4876-a8ce-b2fb4ff8b9e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cae49e21-aa18-42c1-a19b-1f9071c28cc5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49793f9e-856a-4326-aced-76d01dc42bd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f96e704-a366-45ec-85fd-1ac620084813	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
003fd85c-c7b6-49f9-b67f-80128f4591af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d416faca-230b-4c18-b5ba-5b3d517cc921	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9fc65da6-6b37-4607-9966-dfa5ad82b313	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
ec7d994a-ec8e-47b1-b77a-3809c0ee123f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
7b93644a-4b1a-4979-9d93-38ecdc9bf213	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
7ab89664-6e29-486d-ad9a-dfac99be772e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
38fd677c-85f6-4234-bd37-cbe389eeeb42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
577faae5-2738-464d-acd2-fddde537dd86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:01:00	TRUE	FALSE			en-gb	12:01:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
		Yes	Yes				Yes									
327a8e0e-9ccd-4c7d-a65d-3a698b5fac60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes						Yes		Yes							
bfac468b-e3a7-4fb4-b8a2-f05bccd32076	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e4ce232e-9a74-4786-bcee-b8fd6b310673	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
db7c1989-3f12-4ba8-bac7-9a6b9720ac3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6e981834-581e-4a31-bb88-a8b678351185	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cfe1a67e-0fb4-4829-8eca-9eabe0357945	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
cfe1a67e-0fb4-4829-8eca-9eabe0357945	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes		Yes					
2414be88-3804-4594-8c5b-7fe07177b4ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
ef95454a-a4ba-4e81-b193-aaf782ff21f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
c3216a16-4829-4373-92c7-1277393f0eb9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
7181d650-24f1-49da-8ccc-9c33e50a17ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:30:00	TRUE	FALSE			en-gb	12:30:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
1e86f899-c2b6-4ed3-aa29-7417f9217a0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f86d6baa-7658-4fa6-97c8-1c77cd7c105a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/25/2023		Good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cf54c4e0-59e5-415f-96b8-d61beb7d7fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3a059ff-ecef-46a5-a1b5-de2a15a96898	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
90814782-7b37-4a00-9274-db13a9862259	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c668b68-5515-4db3-95d3-c57db7999b0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50b9654e-3bd6-4edc-9f2a-2bc4d168293b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b81cf255-dd4a-4cf7-9ff0-5192201cdfcb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	05/25/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62c8f922-695d-465e-aa14-b6b831995cf3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1080b9ae-05d8-4a6a-8bca-dc4332b99ca7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	05/25/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
323add75-0a8d-4a5c-9f12-2f15c64a6e4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1628fd23-5c35-480c-bf11-fb0e7a229f2b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	05/25/2023		Small' busy restroom but well managed by employee
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eda3e4b7-2c1b-4732-a27f-1f505bb623cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3bd8d1cd-83da-4b5b-a1ad-82c5c5772c96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3591c0f8-738d-4bf7-97dc-b024a5478e64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89b12569-1577-4f2c-b060-deff93f88410	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ee0b2d7-e21c-4588-9afe-1f6c47245909	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
12f19c28-9661-4121-9da8-7cefb5920362	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
42d04d07-31e6-49b6-ae30-8d821d1553da	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f006ad5b-4604-4cc4-ac77-d666eba5f4d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	05/25/2023		Great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5e69de00-7086-442e-92b7-249bc4a7ba35	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28728b0b-9118-4ccd-8e8b-1299153bc738	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eb7ac40d-5e3f-4488-99f6-d73e4d7e22d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d2882e8-a190-490a-9044-9c2ac3fb09c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e4a901d4-5a6f-42ce-94d3-e2039dc2a2a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
23166ea0-2a64-4d8d-ae71-4a8ef9feeadf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
64c8209e-92ec-44ea-80c7-e0422e1b1250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/25/2023		Super especial
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d952d615-5d8b-40e4-bd55-fa59972840aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/25/2023		Limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7e85f31f-8a84-4422-9dd8-5e47923ddbcb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e3822a7c-3189-4a6c-aa06-e071eeb6b0cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
05008a9a-ea08-4924-8fbb-60bae3172770	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
181c884d-12af-4a02-980b-a7c341e058b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	05/25/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d5989fe2-9f15-419d-9482-853e2b6225f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b735b3e-2169-4eed-bad9-b5f1e33a18c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aa45b1cb-b41e-4e70-bfb5-30214b051ed2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	05/25/2023		Good survice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2aaffb3c-9070-471e-8f78-d87e76d9777b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
eaf479ae-e82e-4e8b-a33d-b254baf114ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
05ebed84-e7d8-4a55-9c9c-b2400ffe9a9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:20:00	TRUE	FALSE			en-gb	14:20:00	05/25/2023		Yes i think you should fix the lock in stall number 3.	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
daf0f083-f2ba-41a5-9d56-51aa5eb3b63e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	05/25/2023		Broken door locks	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
4dc19b36-d637-45ac-bd87-0506354896ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:36:00	TRUE	FALSE			en-gb	14:36:00	05/25/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
794454a8-c61d-43ba-a05b-a5e0aeba4949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	05/25/2023		Broken door lock														
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
acc558d6-6d14-43e3-8f62-43d47c6815c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	05/25/2023		Clean														
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
00307d63-1f39-4fa5-90ba-d44f6e2a0eaf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	05/25/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30ae1146-a2fc-40ba-ada8-8574d3dac2dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
59612134-eb72-40df-ab95-2056f67aae72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:57:00	TRUE	FALSE			en-gb	14:57:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e4ba5239-1688-40df-820e-bc0e079a467e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
75668a9a-060e-411d-8974-73fd0b1ad5be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
aae28551-f68b-405e-9969-0cb100a32a2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
afed0b82-5321-45f0-9835-e78eb4391e36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
18c79df9-47b7-4f20-9192-a5ff52f6fd96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
d4dd73de-2162-424e-9e2a-1102bc9fb338	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3c914645-020d-4c5f-b15f-6e2dad4a56e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	05/25/2023		It was great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1ed673ad-93ee-4679-8d1f-f48012f05378	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
048dd5cd-b444-40e6-9aeb-a75a099dfe51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b8673b7-5ac9-4169-9c1b-5e3347a4d545	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0949fb4-4f04-4434-927b-005c0e77c8ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6c496496-7d67-4166-8df8-85ce2d8b8bc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6c496496-7d67-4166-8df8-85ce2d8b8bc1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				
5e73068f-6bb1-4e77-9c38-3c6b062062b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:55:00	TRUE	FALSE			en-gb	15:55:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
273508cb-3e19-4470-97f2-fbe16ad512d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c95db959-fe8f-49ee-9ded-da8c38d882f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
de15e599-1cbb-4f23-a7bf-796c3a3d8328	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7b9b49a3-e64d-4e86-acac-046da2d5b08f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b4d3ae4-6725-45cc-8565-ed523f728b11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0c78c3e2-00fd-48e2-8de3-bd60e69b17c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5a318556-2255-4e76-ab39-d758df2c91d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6a9cf97f-9387-49e5-a7a9-0234f2eed373	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
68eff11b-9d08-47d5-96e6-121ec961509a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3fcab5cf-6b05-4ff3-b06c-4d6f7f94d514	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
930d53ad-f113-4ed4-b773-e84be366ab3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16210e2d-a078-4897-bbc5-8b510939014a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d32a121-3a9a-48ed-9d09-9b3d404d2dcf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
331cb9cf-265c-4d19-b1a8-c41a63ba1164	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2a722619-4775-4d6d-a3dc-b283cb043add	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	05/25/2023		Clean thank you	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8f266b8d-7b9e-4ddd-a304-ce7c956fc553	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes							
7b467e55-3971-4d59-8813-62cb0c937aa1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c1246f0-7cc2-4924-9180-8cd6d9de22f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9e069137-7ea4-455c-8ad3-9ab88a45745f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
9e069137-7ea4-455c-8ad3-9ab88a45745f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
d00cb742-8f02-4dbc-be02-7eccbf7a4f48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
c1729522-617e-4393-abdf-3037b1abc543	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
9891cde0-d22f-479e-b78f-67eb0399fb6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
0105663a-a6eb-439d-989d-c229de735758	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	05/25/2023		Good' excelent						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8122016a-3bdb-4152-a688-65bf96724b84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7cfbe5c-4903-44c3-a0fd-89a175c6d04d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/25/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72153a04-fb7e-4fef-a189-c9e533a99247	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e2d5de2-ea44-432b-9540-88b240a56798	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
4fbc614a-e778-4ab4-bdb2-bcf89a1e7aff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f1778899-825f-4fe9-aaae-baba1035052a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:49:00	TRUE	FALSE			en-gb	19:49:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4aef2da-05f4-4b7d-b5f4-72e393170da1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/25/2023		W BATHROOM
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
82c4265f-945f-4c76-aad5-64411e0c253e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b5181e4-1b5e-42bc-98a1-3cf8b7923f3a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50e344a8-acb1-4f6b-8d90-7c3b3f94fc10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c5307f7a-8984-491b-a03b-a8d618741a2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:10:00	TRUE	FALSE			en-gb	22:10:00	05/25/2023		No soap....
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c5307f7a-8984-491b-a03b-a8d618741a2a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
							Yes							
b12897e0-9ae8-4a15-af9d-08bec3001816	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b7080333-dd33-471d-9736-f190228faeca	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes					Yes					
b7080333-dd33-471d-9736-f190228faeca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7f8778e2-b64a-40cd-a2c2-cc640dce229b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes							Yes				
7f8778e2-b64a-40cd-a2c2-cc640dce229b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
7f8778e2-b64a-40cd-a2c2-cc640dce229b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes										Yes		Yes	
e8d2c075-8e50-4676-974d-29ef69a6dcf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 23:16:00	TRUE	FALSE			en-gb	23:16:00	05/25/2023		Dirty floor						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				
1f30f666-0d55-4e74-bafa-f9888b0b7580	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	05/26/2023		Why is always wet						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
605cc8f7-093e-44e3-9f87-0f78124a5f16	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 05:54:00	TRUE	FALSE			en-gb	05:54:00	05/26/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ed126170-52f5-4d68-923b-69f47847c12c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:06:00	TRUE	FALSE			en-gb	06:06:00	05/26/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
2686fefe-fef2-4013-bfab-3226a01f61d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	05/26/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
233ee0a0-d7c5-4f1a-9aaf-1b87f24e8896	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	05/26/2023		Mhhh
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
809465f1-1ee3-4882-acc8-fb0ef123869a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:19:00	TRUE	FALSE			en-gb	06:19:00	05/26/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
addb8ecd-f207-4af9-ab69-e924d3637593	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e63591a-09a5-4201-8e8d-f59f1eefe87d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6239acc1-4805-453e-9668-4735353bd220	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f45f7e34-b93e-4976-a8d3-418b39f3598e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c42b6c34-04cd-4f18-b1a3-a05ceaaeb835	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e6ff238-edc5-4e31-8bd2-7bb7e11cf686	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29a10dcd-0602-48d8-a322-39abea966a47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9211c892-018c-4401-a8fc-23ad615ab5e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f445045-acdf-44df-be5a-6eda8d995102	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/26/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
728f0ad8-1fba-449a-92e4-bf15e2b3007b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d4cd2cfe-3850-4cd3-87cc-6071c744ace3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4feaca14-6865-48ab-9b69-b728029e57af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	05/26/2023		Thanks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1ee66ac8-ea1b-49b0-95d8-b846e6179409	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/26/2023		Na
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68593661-39f2-4a88-b585-c619987a1acd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/26/2023		Good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9a2f96a-5c44-4dda-a4e3-5ac86be9e8cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0476eecb-5a0e-41a8-9502-48df4180b099	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	05/26/2023		Super todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2994d88c-38b4-4358-88e8-676647867d0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a6dbfcd-0519-4ff7-b979-9a6f43deaa67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da0915df-bff1-4afa-9466-351c49dec487	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2dc74917-904f-4dd1-8f9f-9ffa4320f666	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e8831490-7af2-40ea-8a13-34622dbfbd58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
126ff2a4-af0c-4f73-970f-3f1ba833419a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:05:00	TRUE	FALSE			en-gb	08:05:00	05/26/2023		Recuerden no gasten dinero en tab denle bono
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9278992f-97b2-4778-909c-e2e7ee56bfe1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:09:00	TRUE	FALSE			en-gb	08:09:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d65bf34f-a115-45ac-bcf2-34d121440a07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a12012a5-8efe-49ee-8098-d52d77596c39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f2b8fed6-6f0f-4254-86b0-10e25dc37737	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e12369c-fe8b-4c54-8a1b-d0dceb85c61c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
328548a4-cd2d-4613-9e13-a782f60985ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	05/26/2023		None	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4e1f125b-a817-423b-965d-12ee648c180c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c017782a-3774-45d5-a8ee-72534325f102	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c28b0311-172e-45bd-a425-c30c63ac372f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b5d8d6fa-a315-4112-97ee-380d83dc4682	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a0705d3-19ff-4b2f-9eaa-53ada8628a0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ece84ab9-7b2c-4f90-b1fd-7c1a1a7d5256	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/26/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b37d0333-05bd-4c9e-bc2f-7121abd9a764	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
559a8757-3c97-4f09-9945-4987c97827ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
45147ea5-76c0-4fcd-865c-15eef08914bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4e91d45c-ceeb-4cd6-a8dc-f89895d9a889	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2d94b65-c966-46f2-950e-2d158fff4e58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c446ffb0-6c8c-48f0-97a8-5c393d6046c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2a02797-f167-4ec3-a8f4-cb3e9c533222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15b518e5-1089-4cc9-9824-1150dac47c7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d61a0a26-6a39-4290-964e-543b2dc15ba4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
28f3c440-633f-4c72-8218-5fe64d147987	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	05/26/2023		I dont know	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f5989821-1358-4055-9025-7b9051607031	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0914fbca-12ae-4f1f-8d67-de2ff44da12e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
af2ed3f2-522b-413e-8255-40ce46d9d4a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cd67328c-939c-453e-90c1-78862a55156e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
71a46b9a-835d-4daa-a753-a0be1eb73c4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
86a915bb-a5c9-461c-80dc-515b7dd6109c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
acf9418a-e029-4fa9-8c82-dfee2c3f71fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f666dc9b-e99e-464d-83e9-3df55414572d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d7e0996e-7d28-490d-9592-4785b80db589	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a8541abe-3b07-4eef-97f8-468c8748f5a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d656d22-d1e4-4bbe-a732-317bd92b274a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2276907a-d254-44bf-8c96-88db51c55be6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a17ecaf6-3eeb-44ca-b722-8020a453707e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/26/2023		clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f4c4c265-851f-49c9-9774-37663dac974e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	05/26/2023		Rude attendant
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b46201e-d9f0-4eb6-ac6f-a15a0964b340	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fc45dffe-06d3-4603-a741-54e01ff428a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f6970191-81f9-4c8d-a6fc-0bc50c738426	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
68748ce3-3ab1-4f33-b1fd-a3a9c60b887f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb208090-7a71-4c25-bf6b-99cc6b0a130d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfbbf693-0545-4e87-9515-7839f3bdbc7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
699e1f59-b9d2-407e-9a03-f291d66568a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb32747e-cd18-4999-9c22-b317b7c6fdfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/26/2023		Ok
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7bc3fac6-5e78-4b7a-ae2d-b17221ef13e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/26/2023		Bueno esto
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb86af3a-df3d-4a82-a7a1-42cc3cf3b33a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb7dda6d-018f-4b70-a296-46c8821672af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9e5d6444-368d-4c71-80f1-2560506fb54a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f86eb955-f6f0-4a48-a4a3-7cdc4924be4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1639ec02-6c29-4fad-b58c-e3761625a2e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
46672a1a-8775-446a-b837-0bd2e0dc7a9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f1acfe9-cd75-4a6f-8ee4-89f02eee9699	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
46fc16fa-f24b-4f4e-9fc9-78781d207d1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c03e601-1ad6-4804-8b20-d37bed87e670	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f7f15c98-1d75-4a47-9aac-3e273ed66e47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f479b283-7af4-496f-a545-3e72e1518724	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
364bcfb3-f3d4-4efa-81a7-432fe5c99f1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:59:00	TRUE	FALSE			en-gb	11:59:00	05/26/2023		It didnt have any soap on some sinks
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f32f66f8-444b-4a5d-9172-f40d8c4a6d25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
389e7105-bc47-4b33-ae28-9ec43d396119	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
efa20b96-1044-4175-bb43-c49270e85ee4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f5e0fc5-79bd-438a-bf1f-615bbababc76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0247c917-04bf-445c-9351-f4ea8fcedbbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a777b56-1609-4be1-8803-c0cbe4fa01a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bfebe00-c5dd-40dd-8268-30ecfcf49240	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f954bf4-a0a6-4f76-a8f9-a2c4a0302268	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7b1fe322-27af-4817-8608-1a9a5b0739a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a9f5226-f084-4a65-89e0-3dae6402f3b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c477ae87-9442-44a9-ad12-811ea95676e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4f820abd-5d9b-497b-9f2b-cf7070f4ad9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b85a765-5237-46a6-9b5f-a56e4ad2772a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c53b326d-fa00-4c34-b8d1-90267a9bf18b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2a6ac758-4e43-4726-9bcf-a11893911c9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78f8b266-9070-4444-9896-1652a5b32f3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:58:00	TRUE	FALSE			en-gb	12:58:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
68da79c8-bafb-4df0-ae9b-431e9bad2f45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76c5e0bc-fb52-4973-948b-fd50500fd3c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
b4f93557-f256-4274-831b-645cf4c4db47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/26/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c00c0770-8c02-457f-b861-41129d7e7d12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2e32a32-718c-4f93-9312-8865c690d50b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	05/26/2023		Ecelente todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6a21190-1511-499c-a1b0-15c826f69755	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
79e67446-65c7-4a3e-a176-44044c96e486	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	05/26/2023		Muy bien esto
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75890ea9-efcb-4775-bec0-bad84696c19c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e37449a0-2f8f-4bb0-8a61-701d7ee9b844	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
51b923c5-1d1b-44b2-b5fb-6f00b0318619	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b945558-9c66-477f-b505-795425efd8c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/26/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7326a5fd-c33e-4223-9ac1-5426c25110af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
866a382c-d621-4728-bd5e-af8dd278fc7c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03f83aab-407b-4921-bd6e-47fec0f08223	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0abdba8e-88c7-4430-9942-46fc1e569514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0abdba8e-88c7-4430-9942-46fc1e569514	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes		Yes						Yes					
9aa996ae-56fa-4d53-8953-aeb4182c310d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
99cd5bc3-eb7c-4639-80b4-c782cbf83147	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
2f82ccc4-d341-4873-aed3-7508050db35f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
a0a14162-20ee-421d-9be7-13fe168c55fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
988fa201-24d7-4f2e-9b1e-b0047d69a625	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e56cd8fa-8b36-4d23-b1c0-09129da4babb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0de99bc3-a888-4ad3-af16-bde0db2a11b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
fde16d0a-e3ef-4ade-b6cc-74b0ae3bc602	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:46:00	TRUE	FALSE			en-gb	14:46:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
5574e791-598a-471b-a865-ddfac5c0ac60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d6d35e32-9613-4b9f-b48b-ba7dc5d4c008	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
9d264c78-d3d4-4e8e-bc45-a878c7e8f912	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3b9c8730-8174-4575-9d94-760a2ce8d674	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bf9209e7-1654-45a4-970d-11aac5f54045	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ecaff6da-0323-4017-b29e-13689a856b04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
427b696b-e207-4906-896c-92a58343155d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d53d6972-fbd3-4a64-ac1f-0e782d618a76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd02b6b8-7743-40ec-a49e-e5e10b51fe6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
761095d7-15aa-4ff6-a5f8-24dcab55e93f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6700907c-8829-4480-a866-eaf56ff51082	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f41a4faa-8b61-40cd-b9b7-850a800872c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0a86151-cdc1-431b-8d09-c26f663d7b0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c3fddb4-f3c1-4ae8-b960-8c619a1970ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1ff28dc3-9037-4074-822b-bcc90ea4c53a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
23632877-5675-4f53-988a-924e51c67ce6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	05/26/2023		All good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6739cb47-4bf5-4a15-a164-071f7e387491	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a6530f28-f572-48a3-b277-5894eff93c66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bbbce28e-6f96-411b-9cab-77d8a46cc492	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
47676907-154d-443d-9b07-d2b2bb2c66bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca3fef5c-8b78-4d08-bf62-6e389b7ac05c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff438c1e-bb9f-4f07-b00d-911c86176b4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2899b2f8-2af0-4f50-a3ec-93be2f41dccc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41d92dcf-fc3c-48f5-b39e-2b5f599de949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:00:00	TRUE	FALSE			en-gb	18:00:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
6e1df814-8018-462f-8daf-84280b12cb0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3c977d1-fe20-4841-ae46-7ba7dfe39762	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
edaad221-9927-4313-9888-55419b9bcec1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
177dcec2-19a7-4260-865e-1b96d228182b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
85a990db-9dd0-4a25-acdd-e4d901fe4dc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bfc82119-9195-4a95-b950-4da802e8a179	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d8fdaada-252b-46b4-b224-fe0c1896e69b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
af74cd56-5a5d-43a2-b42c-8a6321cc344f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a181c00e-0efd-4f2a-91b2-502d47513013	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1a82ebd-5f10-4a83-a9de-23e54033d68a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4da88260-7f77-49f4-8477-ed4dfb683f08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
649c62a0-27db-4c40-adac-aae2614475d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
567c46f7-df4e-4eb1-bc32-50bed4b6dd1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3ac124c-68b0-4ea4-965b-5691795b4b99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	05/26/2023		Disgusting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes		Yes		Yes	Yes	Yes					
19912ab7-f042-4be5-a1d4-dfb9d247f310	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	05/26/2023		Fuch u	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
a6f7dd1d-ada6-4767-9c5f-f94b5ddb7936	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:14:00	TRUE	FALSE			en-gb	20:14:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
09c5bbba-1706-44ac-9b5f-28f6bab4ef1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ef451e64-074e-45b0-b8b8-2b128e488a57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d9061f9-6f2e-4776-88a5-258bd2b4a550	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4225305c-db3a-48b5-bfc5-bf5ff95ae378	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4225305c-db3a-48b5-bfc5-bf5ff95ae378	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes					
17f99f76-edfa-4c98-8f94-45b668783c13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f4e3ce4-6497-4490-87ea-4ebc83cde8c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4183767b-6ca2-4e70-890f-7a755b78995c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8db9427-f004-4bc6-b28e-54ac58258d38	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/26/2023		Smells bad
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c5d8dfc-2335-4e56-9cc5-a4343afa53ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0cf4a8ef-7b7b-4b1e-8463-ef3e2c52ed9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:32:00	TRUE	FALSE			en-gb	21:32:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9812855a-dd52-4ad3-9eb1-486df370b329	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
109dd20c-0e9c-46a5-a64a-b72d60f394d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f3f6d3d-ed76-410c-850d-8fc2b9dfac9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
21a4fe59-2f60-4b3e-878f-306f7d82e9ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ddcc554-665a-47e1-9f01-3dd3dc6877ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e138d825-c2f2-42c0-b923-1d514c3cfd50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
05db27b2-e7e0-43ea-8a42-a1e06c629779	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
60c047a0-1c38-462f-ab1a-67f0d9b02195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8e87f078-a0d8-4443-87f0-fcaa19f85bd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
bb18de89-907d-4a60-8671-e975325a6415	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:50:00	TRUE	FALSE			en-gb	21:50:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f54ce0bf-bbbe-4a26-9826-9530bd9bd53e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f8ecf1c9-ba77-4a78-8922-18d5f8fe24d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 23:18:00	TRUE	FALSE			en-gb	23:18:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d670f917-38ba-426a-801b-e772ba27f678	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:03:00	TRUE	FALSE			en-gb	00:03:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6205b197-e124-40e7-ab9f-a0ec2300cc0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:21:00	TRUE	FALSE			en-gb	00:21:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
53d076c6-3758-4db4-b45e-0ac30162d5a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:22:00	TRUE	FALSE			en-gb	00:22:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
325f0872-d075-4668-99b1-075d50851295	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:23:00	TRUE	FALSE			en-gb	00:23:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7dbd4b6a-94b3-4898-95e1-8b7ab6fb634d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f92266cb-7677-4d6d-8d21-1d7dc146fc62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 04:35:00	TRUE	FALSE			en-gb	04:35:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5694f787-615f-4a01-b788-9ddc1f8b4da9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 04:41:00	TRUE	FALSE			en-gb	04:41:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f65a308b-3a14-47f5-ab9b-382bcbae6fa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 04:47:00	TRUE	FALSE			en-gb	04:47:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00ac99fb-f20a-4db2-b730-a93b50111e1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba6a0873-23b7-44d7-a6b8-cd527d983b94	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34099ad5-743a-40b3-931c-bc76c2c8b47d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
df09095c-ad7a-48c1-b5d3-f6e51a021e4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b5f374d0-c078-49c4-96ff-06c916aed4a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
00f42513-8142-4564-b80c-251ae1850887	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6021c277-5ab2-4de1-8c81-51d5c13238c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3c3a72d1-561a-4be5-8aa8-0d22c6c75b97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2893abb-8a35-478a-9a04-5267fc5f8494	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
928d287b-67bb-4378-90f2-d082a84212f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c67c959b-c2f1-4877-88e4-5937cb87b93e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	05/27/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd556c09-ca4e-468b-a103-d1069a8951c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:04:00	TRUE	FALSE			en-gb	08:04:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4dadafe5-5d52-46c6-be38-10fa56c8d4a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
146467ff-607f-40ba-b44f-7762a1f9941a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1e64e613-6384-4263-a93c-64a5fa22100d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
664e306d-aa6c-4901-b0ac-03594327915e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c681f439-c9e8-4304-b1ff-4f167de9a08b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
a94c2440-e6fb-4e1b-95ba-26e7609bf0a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
192c3139-b0fb-4a93-a65b-4698cb7a6f36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76f0e3c5-e904-4451-8b45-04a66844e4c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f0457d4-f311-418f-9160-fa4fcc717dde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8237a7f5-808c-413d-bb98-ee8bf3d9be7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d878443-9f61-4882-ba89-5c56bb634b30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
80bf833d-5702-4f6f-999a-97f54b68ac6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0eb3381e-fdc7-48be-bd22-8324a07d33b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dd583ebc-ecef-4172-818b-bde6b1e367bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
f256b0e4-6685-4135-bd44-e644298fd9f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1db4d752-3e0c-4566-b14e-4b57a39f8e25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	05/27/2023		Air freshner	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1db4d752-3e0c-4566-b14e-4b57a39f8e25	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes						
b72f5253-4c41-431c-9a60-a7e8b3fcaec3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
5ba97bc3-588c-4ee2-9ddf-eb690271ed6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ea1d0256-2800-4cdc-a596-b6a67360faa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
086751e8-a6b2-4319-9403-b6751c87d298	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
086751e8-a6b2-4319-9403-b6751c87d298	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
36236418-fcb8-47c6-b75b-0e6ef887e015	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/27/2023		Na	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e33a533e-ce69-408e-81fa-266a95694bc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	05/27/2023		Wel o t h e r t a hhhhhsb ns a nnnnnn	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes		Yes								
f725df31-a0ff-423f-8ff0-4e7710d06dac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d00183c-8e91-4fae-b812-758e60357c61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dfc06de0-44eb-4f20-97ea-9d7d88466c43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7fc66da0-a1f8-4a89-a878-37c7e32d8033	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a5310a1d-b2d8-44b2-8a7e-f005265cf51f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7115d924-09e7-450e-8d52-cb977671003d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7115d924-09e7-450e-8d52-cb977671003d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes					
74be4b62-b85f-4d55-bcd8-b0d7d0af9674	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66a446c0-ea42-4312-9296-40c641797e54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c72fb14b-83fe-4c1b-b705-77fc73444e1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes			Yes										
4eea5e8e-da05-42c7-98a5-7f40cc470b98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38e6266b-2d6f-4ace-b30e-11ef6748a044	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:04:00	TRUE	FALSE			en-gb	12:04:00	05/27/2023		Sucioooo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
7cefb36a-ffa2-4451-8145-0024a3826879	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68fdab9d-d30f-485a-9c41-3a844a2434e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a526d24e-3a00-4a49-b0ac-624390b51caa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5489f311-4d8b-4af8-a4d9-2573c79a3b19	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
811bfd20-aea3-447b-8afd-5a88370b337a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c22b6c54-f2f7-4038-8b9a-e61b01e9bb18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	05/27/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f1a72fb9-9829-436a-8fb5-ad9d59263b0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
39b90d6d-5662-47be-ae4d-129df3757b5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6a251fe7-bad1-4728-ba8d-8fa4a08e7a4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39ebc7f7-b182-4c08-9593-32c38004504a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	05/27/2023		I am so happy to go to jordan and see my cosins and i am i little sad my dad is not coming	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b1142421-9f03-408b-811f-4b84968c0f33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
816a60f8-594a-4d69-8164-ac7ce1527aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f1ac541-f72f-4e98-8585-76424a42b773	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	05/27/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
099d541a-5801-4103-a3d1-da3f0fab4961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0839f28d-fa68-4872-8b5b-edb662f3c4cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f564c113-5924-476a-85b6-389acf86ab04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
1e0bf92d-bb94-4b5e-8a87-f95f97ed8c48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	05/27/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aa346324-0893-48d9-ae93-15750cb85abc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ae52ad4a-dfd7-4900-a7a0-6c61dc2fa944	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c3dd080b-0878-4ca6-821f-d11a4e9fb16a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0a6ca51c-0bac-4657-b024-eced1c7a191b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ec22d0d-c628-4d0b-96d9-e55b27128bac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	05/27/2023		Rsc	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e96ae59-8f85-4f5c-b9ae-4dc23ad7a553	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
73b6c0a2-1c74-4edf-8779-8906d37266cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c7482b8-be82-4665-a349-ef38e445a32a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
b3471f5c-bda0-4264-9552-ec076efcc61a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5134b297-2753-4ac0-b469-3947dbb194fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b464976c-eebb-4a00-b6c2-53f73cb4bed6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
7cfddf08-b9e8-4acd-b9cf-79d312f18f40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/27/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
a7a1981b-515f-467e-89a9-0a6d0e13ec75	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/27/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																												
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
							Yes																					
31b70556-213b-4a6f-af92-1bbe45f777e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	05/27/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
ba148f75-cb8c-4a6c-bad2-7dca302d3a6d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	05/27/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
64dc252d-c87f-4f75-82b7-2760b86cedb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	05/27/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0b359ef6-71ad-4224-8f13-edacd18e9e92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
662555aa-425d-4439-90b8-ff6c2c915a46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:55:00	TRUE	FALSE			en-gb	15:55:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
85a62bee-f832-4094-b008-cf093b2bb9d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
01415a8b-1337-4a01-8d71-5e591ea93f88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c4de4075-d1c9-4bd9-985d-3cb78f413ae8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	05/27/2023		Love	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
043eeb52-a332-4013-aa20-abdcabe992f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02937e21-8c0e-441a-8e46-7b436f76842f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55f18a0b-0b33-4a9f-b859-49bf9feafeb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96b63485-a251-4ea2-99ba-2b93774fb3ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	05/27/2023		Cleaner
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44adce91-e1b8-4b38-93e1-6151be4dc05a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	05/27/2023		Thanks!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0a33a2b-6859-43eb-84f9-79e3f36dc536	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
28a629bc-2f2f-43dc-8140-526207fa7ce8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a618016-71ad-41c2-9ab2-acbcfb6b02ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes					Yes								
5f31d899-3159-40cf-a2a5-71c1feb63a22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b6e01055-4b4f-4e8e-9b0f-96328a8460e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7214c439-016b-4ce4-a611-9b22a79cac9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:59:00	TRUE	FALSE			en-gb	17:59:00	05/27/2023		Love	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
5ebfcd3d-4712-4c2f-8d17-799858443b5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	05/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
bf95235e-1251-4a85-b861-c9953afcbd20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	05/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
1195a795-748b-42e1-835e-2785cf0d0c45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
4e2509b5-b60f-450a-9d53-e31faa466cfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	05/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4e2509b5-b60f-450a-9d53-e31faa466cfd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
9b6cd013-7d3c-4777-a69b-ba3975febd0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dcf9ed4c-a823-4930-aa4e-40ff00a097b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b1f9c479-fb1b-4cbe-a57b-5ca3a2a69cf8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	05/27/2023		This is a gross bathroom	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes			Yes		Yes							
a21b12d8-edd5-4cfb-85cc-7ea310d4dd4d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6e8d474f-0ce3-4554-87b1-d1a8752abcc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e3418f6c-b7e0-4782-8731-3c3f1f552dbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a6345123-03bd-4e9c-a276-20c8ed4c60f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5f889bae-2925-4786-914a-f4803be0c523	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
8ad02120-f5f1-4842-8041-c51a10f28cfc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/27/2023		Very good	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2942d706-760a-4a77-b215-9476edf1bbe5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2023d060-d7e5-4ef9-b6b7-308148578dd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6864266b-6d06-439a-ad1e-de1d779bc75d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1c46670e-a316-4df2-bd46-9647e731e2e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed82dfc2-6b42-46f3-ab42-09b67415d5fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bca6d6ab-f36f-43fb-b132-830b0b3c1556	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
171901d9-a07b-4596-a463-6dceda9b8cb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
65fafe4a-6093-4101-a816-b4085200fceb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
65f4e4a-6093-4101-a816-b4085200fceb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes										Yes		Yes					
9b19b347-5108-420c-beb6-7c8cf5d45f83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	05/27/2023		Shes great						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
9b75337f-4888-490e-b844-644b74614383	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	05/27/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
fcf7ac78-cfd6-4553-a34a-30fc7d14d5d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/27/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
366037c7-dd66-4818-b17e-d90c9aba3fa2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	05/27/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
1f0a51b7-6b1e-402b-b2e8-767cfeef149d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	05/27/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
600a2378-0b1c-4b1a-8f5e-b4f435e8a34b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a27f4696-eaca-4907-b9f9-603a8440d6ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:11:00	TRUE	FALSE			en-gb	22:11:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c03eca9d-2c42-4443-9a71-669e03c2b78b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:26:00	TRUE	FALSE			en-gb	22:26:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
0478a8d8-b535-42aa-b5bf-c342f8e1564f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
14417942-1cf9-4887-a78e-acdab0d2d021	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
14417942-1cf9-4887-a78e-acdab0d2d021	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes				Yes						
19f97fd0-d93a-44ef-a758-52e62a861d1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:52:00	TRUE	FALSE			en-gb	22:52:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
cb13b29e-3136-4740-a068-be48443eb082	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 23:18:00	TRUE	FALSE			en-gb	23:18:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
b792f94f-f614-447a-ac24-e5fbf3a9243e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 04:49:00	TRUE	FALSE			en-gb	04:49:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
77eb3df0-a08e-46be-b27a-ae4e961e4027	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 04:50:00	TRUE	FALSE			en-gb	04:50:00	05/28/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
680626fb-5897-4c62-ae71-6b7a9564744e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
455e18f3-74ac-4feb-889d-f5e09e2f9a90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29c95a5a-7d13-441d-8108-ed64a4c872e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f020c378-b67d-4d38-b227-09f4392a331a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34721cdf-f853-4df7-ab88-74f6e7acb63f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1772a212-36c9-4e8c-b060-ff03f1665065	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	05/28/2023		Bad
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1772a212-36c9-4e8c-b060-ff03f1665065	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
dc03ff4b-01ba-4d81-922a-b60660f9b16e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
dc03ff4b-01ba-4d81-922a-b60660f9b16e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes										
65bfdd2f-9a01-4830-a734-61ecb687111a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
65bfdd2f-9a01-4830-a734-61ecb687111a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes	Yes				
2cd20740-a43e-4349-b665-69459d8a4155	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	05/28/2023		Tganjs
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2cd20740-a43e-4349-b665-69459d8a4155	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e19cafa1-3550-47c2-8619-5410e33c3d02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/28/2023		Ew	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes		Yes					
7350e86e-5cbd-4ca9-8320-c2961df474fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
f0866e36-9b68-4269-989b-378ac1baab68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
7537cecc-6a10-48cf-9566-a8179e211664	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	05/28/2023		Very bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7537cecc-6a10-48cf-9566-a8179e211664		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes			
30c6a0b3-ef0c-44ec-b3a5-7680824832d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/28/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7049f84b-eaaf-485d-9912-d7ea35849087	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	05/28/2023		Very bad smell
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes			Yes	Yes	Yes				
3319ccdb-d256-44e2-898f-48ce2e60224f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	05/28/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
1feea5a5-c793-4459-bcda-116ef3e48974	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	05/28/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1feea5a5-c793-4459-bcda-116ef3e48974	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes		Yes										Yes					
99745773-f9bd-4e1e-b148-303638f33893	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/28/2023		Muy suvio						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
5838b881-fb97-4080-9c2e-dc9d99ecb478	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
631f4c37-540f-4547-b9ab-181a7f82ab94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ee3cc78c-2e7f-4248-a349-74f6ff85a961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ecf1923a-a92a-4d75-90b2-08c6cfefd584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
a73ca112-1f69-47cb-b8c5-178129fad8ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/28/2023		Good		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
4314cafd-190d-49ac-af49-e5f61318820e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	05/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
4af8cc19-54c9-4693-bc32-52e5b7e4d384	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
						Yes	Yes									
8cb6b504-f36a-4c9d-a0ea-4884bbbabd6e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes	Yes	Yes				Yes		Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
90536079-34dd-4a09-84ac-a7727c4480f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
15b599ac-ed7e-47c9-a63d-b6df45b26a23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4cb11841-f92a-40ff-8fa6-87425533ead5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
55885f1a-6ecf-4b89-b8e4-5eb08f80ad1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	05/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
c257f399-c82f-429a-972d-da7b96ce7ada	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	05/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
0c0ea8cd-eebe-438c-b029-d35587e1fa38	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	05/28/2023		Disgusting		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
01c567e1-fac7-406f-a87f-5edc34cd321d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:11:00	TRUE	FALSE			en-gb	12:11:00	05/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
01c567e1-fac7-406f-a87f-5edc34cd321d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
6f52245d-ba64-4826-8eb2-5bd9881fb750	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b8fe0f6-78ba-4d45-aa1d-729377a3a8d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c972be7b-0074-4763-bafa-8d0ef6663c32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aac4204f-dff8-469f-af3e-fb1bb03286e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd67e914-481c-4e91-a173-af5ad9880dc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
065e44b3-da90-40d0-b7e7-507afd882479	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	05/28/2023		Puerquisimo
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87ee3b00-dacd-4432-8dba-ca21ab163dd6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a34e77b-fba3-4396-a001-3497a098361a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3acb4724-e776-4675-a837-d006bb955f11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	05/28/2023		Right
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5f1221de-71da-478c-be7a-980a24fc6015	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1599902b-3846-4f93-9e76-cf29d1d2e6c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
43e63cda-5afc-4131-b8e4-b9a2bfbd88f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd424ec7-efab-44ee-8c78-2463abe640c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2611e8a2-c307-4c1f-893b-4a39876548ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e9525ef9-2540-4a65-9fed-9ad6ffe14912	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	05/28/2023		All is unacceptable	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes	Yes			Yes		Yes					
d058db49-8279-4f7f-bda7-5f68dc934e86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:36:00	TRUE	FALSE			en-gb	14:36:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
047c93b5-b076-4af6-bc0e-683aa518da53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
63252001-042a-4d60-a7df-ea836ee45778	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:57:00	TRUE	FALSE			en-gb	14:57:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85cbc734-5919-4f99-8b71-588d26f9eee4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30fab814-1d8c-4019-87cd-817843d70f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52909617-5f60-4cc4-a4b6-690c3fb5bb5a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c827042-6917-43d8-88ff-b7ccf773a8ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
af090895-f9dd-4300-ad70-4aa20c45a225	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
356355d7-b6d2-4dd1-a4ab-9ae1de86d4c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eb0fa930-4f19-4805-8ab5-8ccf6b46795d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
79e054f3-71ca-421d-914e-3c15cfa91b54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a72aa92-5019-492e-9982-42e53cc8b9ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b528b27b-235a-47e9-a2de-89a4932b16fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7bbc7375-cd9e-4642-912f-6be02be073bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fa7d3151-93f2-4a8b-9989-0d0914562691	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d4ef9c1-3d2e-4f6b-8adc-0385dfa06484	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cbfe0ca8-5abb-416e-8ab5-dd49db5ce2fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e18fb8a6-6a6b-4b56-8c12-fde62e0916f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3cc7ac5c-56e9-47e3-8a14-deccc5e5ecfa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72e7f3d9-1649-4f38-bf38-e763cc7438c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb7991b5-43f7-4ff7-b7ac-36c5000baa4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
07d2ef81-d249-4dcb-bd65-02676afad137	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
6530a518-63ae-4e28-b512-027e46f55cd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ba9ce68-4aed-4246-b7e6-ff0964819d01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
36266eaa-0e61-4223-aceb-ab34ff16a490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	05/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
0b80bf3e-0134-4dfe-8cef-139cb8cd8a6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	05/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
										Yes									
6bda62df-cb3b-4180-b7f2-763e2a99345f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
a22ea779-483e-4076-b42d-edd280a0cde0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	05/28/2023		j					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fa1239a8-642e-48fa-9da8-0fdcc19caae2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b26ee7cf-ff70-4784-95a2-3d3fc403c374	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
62436def-597f-4e14-8b6a-269b49996554	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4fc43bb9-848f-4800-bf76-8690059758a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54095ce1-a42a-4119-85db-fe94465e4b2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bb255f99-a9e1-444d-abf2-a4fbc97bb4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e23d6c8-a275-4391-a00d-c4d9b220b268	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes	Yes				
e19af826-de23-4cde-8e52-3c4942590eec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
685f68fa-bff2-4ac4-bc16-662cb6cbeb4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
948aff14-b87b-4a1f-9ee5-abf3b285b33e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
ca68e7c6-cce7-4f3c-a796-fd01de936aee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
2df20c59-3747-48cf-bb7f-cae151570b58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
920fe36d-180f-4ef7-8a8e-3e06bfa349c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
231f24f7-6f8c-4462-827d-bea4c5e06c66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
daaedcc9-2b6d-4899-aea3-a4e0d7b74de7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
4472567c-4c20-4bb8-b8bd-d781ac4af1a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a5c9ea56-dc29-4863-9cf2-69c46f235cf1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6db4255-06f0-453e-8076-8f0ddb58a391	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7ab0a0c-f099-4606-b95e-c0d0dda060b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1aba9371-2b53-47f2-ac87-384ed9295977	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6f426330-20b5-4ecc-a3c0-004ced9f3f98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2eee1453-022e-44f1-93e2-d139c928723e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:14:00	TRUE	FALSE			en-gb	20:14:00	05/28/2023		clean better	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6f54c378-f663-4793-873c-cac17388e6b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7a24bb38-02ef-47b0-a5f7-26eaf993745d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e7ea959b-d6d6-4fda-872f-a011e6760685	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e7ea959b-d6d6-4fda-872f-a011e6760685	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
95a6cbc7-0cbb-4642-88af-46d98eb9afb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ed9b3d5-e744-4c29-8e61-e29cd431fa16	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes				
4ed9b3d5-e744-4c29-8e61-e29cd431fa16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	05/28/2023		It would be better if it had good smell
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
959518a2-f971-4c72-90a8-1f3a167683ab	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e9fef383-b63a-4c74-9aac-1065bcc29af7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9966f0ca-df5c-428b-858b-ef36b012d640	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1005b725-5c60-4507-a3b0-e7e22f71b2eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d74632fc-446a-418d-8cbf-85c3bfbfd6794	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/28/2023		Bad odor	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9da02eea-c37d-4832-bfe0-c6a7f5937875	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72aebd17-e2d5-476f-9cd6-26f6308c4f7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 23:05:00	TRUE	FALSE			en-gb	23:05:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
2a501931-2945-4054-8a61-e2102b509cdc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 23:07:00	TRUE	FALSE			en-gb	23:07:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes		Yes					
88691a0a-41a4-40ce-aa31-287fb2409a85	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 00:20:00	TRUE	FALSE			en-gb	00:20:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2eb92909-9c22-4ace-bf87-563d53a9b762	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 00:52:00	TRUE	FALSE			en-gb	00:52:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6d3949f1-6e88-4996-b9da-e5831f70e8ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 01:59:00	TRUE	FALSE			en-gb	01:59:00	05/29/2023		It is find
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca7851ef-273f-4b83-83f0-1d6f4551e546	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 04:48:00	TRUE	FALSE			en-gb	04:48:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e70fa8c5-668f-4cf3-9908-b653e5b468b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 04:52:00	TRUE	FALSE			en-gb	04:52:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a90ed4d3-7975-475d-8525-f4dfea1dbe24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 04:59:00	TRUE	FALSE			en-gb	04:59:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7f5a8897-dc89-445a-a489-98e68d9601dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4a86fec2-4b6e-4089-9aef-941b51788f83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
09020569-36dd-4020-91d0-da024b857fe6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:01:00	TRUE	FALSE			en-gb	06:01:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f3e8c768-8624-489f-a1a0-146a528ce77c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
501bbfc0-a756-4284-9c02-7255c744c17d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfc95d2e-5b7c-4ac6-947f-6275a8e1fb72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	05/29/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
60491467-de4c-4ef0-8a17-52d7d1dada8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
78779482-ba74-4396-baba-04be796b2afb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a7cec49b-0a78-4bda-ba5c-15bccd42ee31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/29/2023		Limpo e perfumado.....not a dez !!!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
20bd678f-5243-4420-bfc7-d45f3f254de6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
837a5037-cb56-4993-a3fd-ef3d949f67ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes								
c616ce2a-7d06-47ef-88ba-d9137be1e256	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b873b3ba-8275-4995-98b0-47c6dfe0398f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ba6af28-e7c0-423f-8f9d-30a2b85e562f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
83de6d86-cda2-46b4-82b1-716bd92a967e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/29/2023		Thank you
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69004b8e-f8dc-4df9-a227-2f7346aa4f3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1408bc4c-1591-4537-a1c8-39ac51074fea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39b95cea-d058-4159-943d-6c7608e34acd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:17:00	TRUE	FALSE			en-gb	08:17:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39b95cea-d058-4159-943d-6c7608e34acd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
a69156df-5b0f-4091-a161-32d554fd26ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
4ca149b9-f2f0-4efb-a7ec-7842643d3dde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
d4c741b9-0e30-4a7d-aacf-89c8b8166795	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
9508f7f3-088c-437b-83da-d888a2eb2f4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d37af0e3-f94d-4e80-8e20-8b1d1e28cd3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f2674b0-f7d8-459f-bd18-a7e9978514fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
48639970-8590-40e9-a6d7-2ff743e816f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
220eb57b-46f6-4f65-932e-1286ce831b1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a40264a6-8123-442f-a9e6-f2cdb696a913	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
99c1a4a5-26bf-4505-b2eb-b7e04b84130e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7d4a7dff-1838-4255-97ea-074aaab40528	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ab3d8fea-de5e-44d8-84cc-60f2e8e0b5a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4fe70a27-39eb-4d9e-a3a4-b04771e35bc0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a8e4ae1f-a91f-4049-be46-8903199ef418	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	05/29/2023		Fix toilets
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a8e4ae1f-a91f-4049-be46-8903199ef418	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
7393292f-c138-4eb1-b4b7-fe44540a3e24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
965d5aed-dfb6-4341-b3ea-78626758593f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
c47b1c10-b71d-44cb-9a4c-76d9d16d37c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
e7d6f098-2ccf-4b18-b1ce-eed3caa6dfae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
99fcff12-bcf5-4765-b578-5db1093d6d4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	05/29/2023		It was neat.						
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7c9e6e49-e0b9-4f90-8e5b-f120ae870d4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c07bf96c-8bb8-43b1-9b4e-24598e2472ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1fd6ca72-6099-45f6-86f4-bcaa9fb6328f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e973a745-b1e1-4bf0-b11c-4d739167b530	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
898b5134-2637-4141-a181-df5cc449befe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7ee860d1-a535-4929-9243-66b942394a9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7462222f-a918-4bb5-b8c1-f0b302361520	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2f9d78a6-db1a-4c83-b91d-675d91ee5d8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8ae67109-5632-44f4-806b-d75f54d35e07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	05/29/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8acc4b76-8d54-4c9f-ad2f-f0bfbea63f37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
26192328-0074-4e9d-87e1-213b422e1ba1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6f37d543-6176-44bc-b4a5-c5529362932e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/29/2023		Do better	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
084a9a1b-27d4-4893-9d4d-8d4a1ac53b2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5cfe5f9e-cb32-4eca-a12a-f7d309ecfe39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
011ca1bc-a436-4c9e-9b22-08951fa155d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
011ca1bc-a436-4c9e-9b22-08951fa155d2	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes						Yes		Yes			
6d374946-d965-4e59-8d55-9d77d84d7086	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6d374946-d965-4e59-8d55-9d77d84d7086	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes					Yes	Yes					
ae2bf35c-8649-4c0c-af2d-e77bcc4066ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ae2bf35c-8649-4c0c-af2d-e77bcc4066ce	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes											
9365407c-c147-43c5-bb88-6a2ee5e8b54b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	05/29/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
9365407c-c147-43c5-bb88-6a2ee5e8b54b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
									Yes		Yes				Yes		Yes			
7373f16b-7073-4879-9c0e-d634bc1102d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	05/29/2023		Smells terrible						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
4644b78a-5537-4f68-b0cc-2cea0f016c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/29/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
e4b445e5-e80e-4e17-87a1-258ed6eed2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/29/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
1ccbad7a-0c1d-4a79-8cd4-1807426c5cd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/29/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
52d1ea30-b8cb-4710-9c21-97f162235227	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c5d528af-0617-4563-aa67-4bdb0dff928f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b2246e7f-7b2d-4b84-a20d-113117ca3f0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
3957f4b5-dfc3-4077-9b3f-9c316c1d54e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
2e069726-b8ca-49c6-bd25-7734c236aca6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
76401625-a62a-450d-bde0-42cd647feba4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
76401625-a62a-450d-bde0-42cd647feba4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes					Yes						
717246d1-282b-477a-829d-2448f46ce998	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d1c7fd08-238b-4830-b01b-d8653a2f9d49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc55d2c9-e408-423d-a405-a8a52faaaa12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
8aa93e0e-a217-4793-af67-b8e8c34dee72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
4fdec7f9-1549-46dd-9e1e-ad9236fa01d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
f3ea4b94-8d13-416f-852a-43b050e81890	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
4217e1f8-3b87-460e-98ef-75ad52d9a3a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	05/29/2023		The best		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
39520270-da6f-4e14-9d53-19e465981e23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes															
daa27d08-e098-4b8f-950b-a8258e9f60b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	05/29/2023		Smelt nice		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c55acdb-2b16-46d0-9e52-85c3eafda1fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1fc35981-9d42-4009-a94b-89c7cb46e693	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
33f3838b-7140-4ad2-a83f-3ffd74e3fca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
49965a9c-befd-4e05-9302-8e3536511509	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/29/2023		This bathroom needs a upgrade or clean	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a2a4d395-3afb-46ea-a75a-b57645fc0bf4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/29/2023		Clean it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
aa8db29e-2bc5-48a6-95f7-ee176d221808	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
4b880ae9-8067-4848-a99e-02c0cbea05d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0688bcc7-147b-45cb-87ca-dc8c21cd40cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
68e35615-d15c-4eaf-b9c9-a8c7215a5114	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e9266e9f-9666-4936-95d5-fb37e8a7ccaf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f857040-d73e-405f-8c42-9a993851fea0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9dcfddc1-f095-46ad-b070-880059c460e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bff951d3-3594-4fed-b3e7-e2f7951466ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
32890924-0e6a-42a0-9554-2513fb024d9a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	05/29/2023		Good job	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b76eef9-825b-42e4-a368-f5cbe19c39d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6d0b93ef-4f2c-4e19-b6f5-a679b1f5fa8a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:00:00	TRUE	FALSE			en-gb	17:00:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
016c5451-8e32-44bb-a443-ceef93f5ea42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
01668fd0-dc16-456a-a2aa-c0da8940c51e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
61d10c84-c8cb-4d5d-af05-e39224ec42c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77278090-ade0-4213-863d-46c16ce6d68e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
4039572a-7a4b-4cde-8be0-d3f2feda09da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes			Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
63541775-6345-4f0d-9ace-4026bcfa97f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/29/2023		Bad
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e0e7221c-a1ad-45af-9fc1-9e51c1a6cb25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6d5b518-ccd7-4eac-acd1-18a09d140a63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
23c2760d-33f7-4cc5-ac49-b798d3d8098f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6cbb684-aac1-46f6-9514-65cf914b4f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
760a0f8e-42c0-4243-b2a5-391adf1c124e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
20061fbc-2930-4112-9255-4892259f20bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:02:00	TRUE	FALSE			en-gb	18:02:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f711e735-f559-41bf-a771-ca00f74330b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53b2ffd7-48a6-4119-9705-ee8b93a07431	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:14:00	TRUE	FALSE			en-gb	18:14:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
afc308d6-4e49-48a2-af1d-249d9a5c8d6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/29/2023		Stalls need service
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81c82144-0d01-43ee-85c9-a9b92eba516f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
9e772608-69af-47df-8b31-f8809fdd235d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:17:00	TRUE	FALSE			en-gb	18:17:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc099ffe-5b55-4746-9c12-de157ba0469e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1dd9e8b-50d9-4803-976c-8cfcd966af65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1bfc4679-ad12-405b-a48a-5efdbe3aeb53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07482ab2-6255-4132-8bfc-92f4e3282bd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
276b71ab-97f8-43f4-a205-d82715610abf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e08cd7e6-ba8f-4990-a59f-6519e2e02b98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae643db6-a5cc-46f3-a8ec-e09bbf8c232c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
84fc8b28-6a5e-468f-a937-c32969efcf27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1e6f97d6-7859-4913-8e35-6fba07063eef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b9194959-88a3-4627-9ff8-299902f30e3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
42fcb87a-35db-42e4-81d7-d956b964a472	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98bbbeb5-ff07-423e-b85d-95c8dfbb08f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	05/29/2023		Nasty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes						
60adb616-ed04-489a-8574-f4615f76bfd4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
46726825-cb2f-46d8-9113-da55740212b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
27c60516-7753-4306-a760-71af44d3e343	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	05/29/2023		Smell like marihuana	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
fdc1beae-66c6-4f08-bdc2-63938749e035	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
96b6466f-b644-43b7-bf75-6d4a03bc9c4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a60474d-5687-4404-9a0c-84d7c190e2aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
70ceaf38-7ad1-4519-880b-19fb94986c86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e69d17e8-b3b0-4a44-906f-7a4824d441f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d8f4d60-bf2d-4962-b63c-289fba9d4cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
51fa5a85-ea35-426a-8727-dda4f7d91b41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8dfdf9f1-205f-468d-b0c6-3a93ff91aa02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7f97c3f2-e333-43dd-9576-4c03dfc6be33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:57:00	TRUE	FALSE			en-gb	20:57:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
0f6e712f-c3b4-4298-8d45-47a332dc8a00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	05/29/2023		Smels urine														
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
f18ab090-d6fc-42af-b4a9-237c3feea41c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/29/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
66b64505-85b4-462f-895a-20c15f1cff69	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	05/29/2023		Good														
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
02950f0e-150b-4b2c-a576-5670b04db69f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	05/29/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
02950f0e-150b-4b2c-a576-5670b04db69f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
7acedda5-1d67-4270-a3b6-b18302fa900e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14682e9a-7ac8-4f1f-8584-28ac8d4e48dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 22:33:00	TRUE	FALSE			en-gb	22:33:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
12d46d03-d3a0-4c2a-8266-8baf5c272825	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 23:42:00	TRUE	FALSE			en-gb	23:42:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
faaff2a1-f456-42a2-9f09-ce975d558fb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 23:47:00	TRUE	FALSE			en-gb	23:47:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
faaff2a1-f456-42a2-9f09-ce975d558fb4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes					Yes	Yes	Yes			
08e7f683-7b21-4211-9be0-9d910ea04483	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 23:59:00	TRUE	FALSE			en-gb	23:59:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2c25a6c0-9f5f-48b8-9f19-57f553875ce7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 00:55:00	TRUE	FALSE			en-gb	00:55:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7d1d96b-0bf2-4737-aa1d-8ef6700409e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 01:39:00	TRUE	FALSE			en-gb	01:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0dc3ea09-fa03-4809-9abb-2633fc9c7e68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 04:03:00	TRUE	FALSE			en-gb	04:03:00	05/30/2023		Limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc6627dc-4a3f-47ab-b7f0-c7f6e0d8cc0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 04:35:00	TRUE	FALSE			en-gb	04:35:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc6627dc-4a3f-47ab-b7f0-c7f6e0d8cc0c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cc98278c-f2b7-4744-9e0d-00a83c5b13ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9cb4ab4b-71dc-4ce9-b2f0-247e1efe6c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:36:00	TRUE	FALSE			en-gb	05:36:00	05/30/2023		Thx
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a399a87d-052f-4fe6-a7e2-e9ce30b9cf65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:43:00	TRUE	FALSE			en-gb	05:43:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4408bba-2b3c-4c46-9990-4be6e2337d94	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:53:00	TRUE	FALSE			en-gb	05:53:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07c31b13-216b-4a49-9e6b-a6a7fb1c6af1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:10:00	TRUE	FALSE			en-gb	06:10:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ab4aa921-5b3c-4a60-b9d4-f9345c9afa74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:27:00	TRUE	FALSE			en-gb	06:27:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3163ffa5-c46a-43be-9309-4c24cf8742dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	05/30/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c092a06-ea7e-45d5-89f0-bf088bd6277d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dfc35c6d-c3e0-4113-af98-9efb31f390d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d14d69cf-6072-44f6-9ccf-1b4d9c498276	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8c6192f-0573-4909-a7fb-3a80283bb892	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9cfc9343-dd93-44f3-b321-4c9e9caab7c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd368772-cd5a-4964-8e60-e990ff2e1900	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	05/30/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d8ce1a0a-84b8-4371-be5d-8fbfdc765279	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d4124159-834c-486e-b0df-996c4a2e345d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7c4a946-bda7-4e3a-86c2-fe675b8595e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d4eba6f-ae4b-4e3f-8347-eb9ce7a2f0f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cb484d73-53d8-43c5-b274-5d3c38da56bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
45491f8f-c6d6-4eee-b860-75c0983f2e68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
678ac430-6f74-417c-812c-bb59679ee64f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3abb00fc-7938-487c-8a44-807d749d60ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:17:00	TRUE	FALSE			en-gb	08:17:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
91931cf3-e943-4b23-9c28-219ff051e597	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	05/30/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fbaa6498-b5fc-4d52-89e1-69432169025a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	05/30/2023		Hiooooo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes													
0391187d-34f0-4cc3-8442-df2302f303ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	05/30/2023		Hhsbfggggndnfb bddd ssssbfnfgfg fgfff f ffg f fhfh gghgh t ht ffmtmtmyyyhhh,h hh?hhhjh??h? hj,hju,uiiuuiyig ?? jghhghgggmgggm g?hgm?ggg? g,hhh,yyy,yyy,uuu uuuuuulgghhhm hhnnhhnggghhh h ggg ggg ggg g	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
86ba862b-7ead-455d-bcc1-237c3d4164e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
80a43435-19f4-4539-984d-86f51cf4c362	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2588f2f-b214-4db9-bddd-31ac717dc660	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f80c07b-e857-4176-9611-59bf4f466b5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7e87c43-6283-4f14-b74f-059a93be8340	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17282fe8-0764-4a98-bbbf-3b21d7201c08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0778eba0-7917-48fb-a9d4-9387f1f2f1e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a43d36a7-8fdb-4322-bcc6-38d193fd09f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0590953b-7a37-480f-a005-1501fc1b29e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6826e88-f455-404c-aeb5-5242c8f4ea63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cb11af85-bc5c-4051-ad15-541714f0603c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a506f9a7-e133-4e9e-9835-d9ca399ed197	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
975979fd-83b6-4add-9d62-3d55811bf07f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bda8db97-8ae8-4053-9c2e-a4726905d90c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
3a642150-d289-4c45-aeac-e727e4c3c15a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5314e4bc-dda5-4b51-b8f8-1f68581a343d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
748f7193-49d4-4e32-a2ac-ecee18a70f80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
748f7193-49d4-4e32-a2ac-ecee18a70f80		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
3fed9633-df59-465d-b3f7-c3e15069948c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
a3f69b33-9e45-4772-8c6d-d6cde4ab603a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
5792312b-5e0d-4f5b-b50a-b557d83d3e65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
4e0a3b1f-5a2d-4a05-bf11-ad1f12019d24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4e0a3b1f-5a2d-4a05-bf11-ad1f12019d24	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
9668423f-923d-4c0e-a5c6-e728f6ce5584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	05/30/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e88e5d3c-27b8-46c5-bd78-b797b52eff53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes						Yes					
2eb563e4-8399-41bc-9c26-4e41a0f56ab5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3eaf19c-e1a8-4485-b351-e3f12dac198a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5534ed37-ad6f-41fa-8b47-5c60aa8a7377	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9473d3ac-770a-4cbf-8077-da6c8392c3cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7c6f9def-a5c6-4f44-994a-d24f16d6a0fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9605c7f8-355e-4e0e-bd2e-618cbd694025	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5589bb34-0ec3-4a5c-979e-b756e65473f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9224e3ff-c533-4087-a039-a4506d49e4fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fab24ff0-41f4-494b-8215-a61b93cde5d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a6745afa-85eb-4b9c-b06e-b339e8ca5491	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
143c70bb-dc59-4f4d-aa35-af8649c402aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d9c3c5a-feb3-43f9-ab5a-125c68eea2bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b974adba-2bd7-4e1d-a7da-974cf0639df0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1246fd71-9c87-4919-9505-cf5f0fdd4b0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b1b7c7e4-5545-4ddf-a1c0-15e6cdefa27a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a6edc22-01de-4cbc-8746-216af296dd27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b125e5e2-b0d2-4660-b0b1-1d94286d69cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	05/30/2023		Clean it please	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9fb2e80e-34ab-46b6-ba7a-c13f460308bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
20ef672a-7fe2-44c9-9c65-129fcdf739b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b3c7a361-634b-4b96-9532-11c1a6087bb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/30/2023		Ugly *** bathroom	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b3c7a361-634b-4b96-9532-11c1a6087bb4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes						Yes						
67e189f8-e2e1-4156-8193-5890e2eedaba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	05/30/2023		Good job	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a070227b-8b77-4d42-aa3e-3b055a15eb97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes		Yes										
7e26e691-b855-4ff5-ad45-9de21761bcc8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
608c4a1a-3b4c-4b2e-89e3-3eeb90eb8804	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2ce45b4-3534-4ff6-87e1-835e7aeb3e04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4ca2cb7-fd98-4f28-9949-d32f6d7ff37b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
7772d72e-2b42-4ec4-8155-c45d9ce6d370	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
06057976-04a9-4561-84cf-d46c09652908	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b72117d4-a122-4bec-a732-a11a9031af51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
31ae50cf-bfa3-46e3-ae91-2150291440c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes					
a95e23bf-5bdb-4fa6-b495-d4f65b2308db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
740c9f35-6944-4aee-a975-f54ceb348c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
40f0182a-418f-4536-a4bd-35e6ef0e2514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
40f0182a-418f-4536-a4bd-35e6ef0e2514	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
a2ad84fb-39ba-4948-834b-49b56dbec2d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
4967a779-4973-4496-b3d2-773b52fa9ef2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4ca8232-606a-4c1b-82e0-9e79b397a390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e7e1156f-c987-401a-b820-01d42028f3ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
eeaea811-30b4-457c-b500-81c5eb14020c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
84f8f809-a965-4bb4-8c17-fdde00ddac55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
9affceba-f843-4ca4-9ef2-1bf4185939b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
387d44a7-94db-4a68-b671-dff4f637f0e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
8bf18b75-dec7-4f02-b159-9983950f6139	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
a4c0f56e-e60f-46cd-b9b8-a47907f999ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a4c0f56e-e60f-46cd-b9b8-a47907f999ea	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes	Yes				
97182a52-ed91-4a85-b50d-d6b58838df9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/30/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
360d12d6-47e3-48e1-9599-cdc8eda6556e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
efba337a-878f-41a3-9d52-bf2e730eda6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	05/30/2023		Very clean. thank you
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
75467d2b-63f2-47bb-936e-bbd3ac696a58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
518eae96-ff64-4f99-9717-eb1ae176d055	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	05/30/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1a9bd25b-efbf-47b3-af95-3cd16fc0347f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ef9d5736-0e85-4687-be9e-80bcb2a9f514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/30/2023		Good	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1bb62d03-24f9-4b08-8472-0f31aa954434	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4dcccfaa-25d4-4268-9845-1a086ba0e8c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
612caf29-6272-42d8-bdf2-342e6be9a6e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:31:00	TRUE	FALSE			en-gb	17:31:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
612caf29-6272-42d8-bdf2-342e6be9a6e9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes		Yes		Yes	
600adbf2-780e-4e85-86d4-307df7f4dd80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	05/30/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
64c69cf0-c6ea-4928-9f7a-ad2a8df59951	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/30/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
0aadba63-9cb8-437c-b6b5-b44ea9438cbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/30/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes		Yes										Yes				Yes	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
43de0fe6-5ac1-4874-825d-67315fdc7332	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/30/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
970fbc86-6557-4fba-9d6e-e924a96a1825	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/30/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
ce305d01-11a4-400c-a4f8-e330b486bcd3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:07:00	TRUE	FALSE			en-gb	18:07:00	05/30/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
31023f25-54ef-49d7-9123-2ab1242f627a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	05/30/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e751a5ea-96fd-4a16-bcb8-c6b0a48af7ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25302978-970f-4751-a5f5-5029e2900b5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:17:00	TRUE	FALSE			en-gb	18:17:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
53528708-01cb-4c1a-9792-ed18a8da7c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32c886c2-3554-49e4-8cbb-5bffbdd6187b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2e6a70af-051e-4150-a354-5e68e9a28c0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
								Yes	Yes						
ef6c7a9b-d8b4-431e-916f-268df4979e94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/30/2023		Bug	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes	Yes	Yes							
aca2718b-8865-4e0d-8289-f75c5666eef7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:31:00	TRUE	FALSE			en-gb	18:31:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes					Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3ecd5ff-3277-4e0c-833b-14e5098f7c81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
586739bd-b060-4048-b215-757ad4bb8001	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
badb9d92-7a9b-42ee-8a7c-0982dfffbd64	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3de9e5a5-b39a-4cf5-af0e-00c165a1c59f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78875e4b-9804-4f3c-bc3a-104bd581d3a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4ef0ed4f-30f7-43a4-87f3-6e430de95f21	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/30/2023	Gurk yo booty stamnk	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes			Yes	Yes	Yes					
6b7bf4d8-da31-459c-84e4-ed7a3bebbe2a	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/30/2023		
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d43aaacd-e9da-47d0-9495-943235b05aaa	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	05/30/2023		
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c2d163a0-25cd-43d2-881f-828035a9f5bd	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/30/2023		
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c2d163a0-25cd-43d2-881f-828035a9f5bd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes				Yes	
431eda7e-a3b7-4a21-a672-2a71a96a1ca4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:11:00	TRUE	FALSE			en-gb	20:11:00	05/30/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
ce86f6f7-197c-4f78-9ea5-2418c759235f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	05/30/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
9998086c-e605-42a3-b2f8-eee9357d0bb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	05/30/2023		Bug						
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
9998086c-e605-42a3-b2f8-eee9357d0bb1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes		Yes		Yes			
8130019d-0265-46b6-ba10-20ae84aa17e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	05/30/2023		Roaches, broken locks, no purse hook.						
	How would you rate this restroom today?																			
	Average		Good		Poor															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
												Yes								
a8d31255-eabf-4d51-91b7-318820a28458	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	05/30/2023		Smell bad						
	How would you rate this restroom today?																			
	Average		Good		Poor															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
a7996763-1253-44cc-8cc9-c462d4f88541	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	05/30/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
		Yes		Yes										Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3876883f-11d4-423f-a2d7-c2d6c0dedc67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad84a6bb-b9b1-4ff1-8441-e9686c861053	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
47d0f006-3153-4a68-9703-8f5a5a506f08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0ed32240-a7ef-40d8-ad87-f106532a0991	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ccb53d82-24e6-4a25-a4af-08990ef6246f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
065055cc-8d2d-4cf5-9cb8-947422d8a69a	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	05/30/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes					Yes	Yes		Yes							
2bd8c44e-e426-4b13-a587-1de5b332a966	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 22:04:00	TRUE	FALSE			en-gb	22:04:00	05/30/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
7cf098f9-02a2-420d-ab52-a80a3601522f	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:21:00	TRUE	FALSE			en-gb	23:21:00	05/30/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72cf93e1-e0be-4e67-ab5c-9d5b8cf0d7b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:27:00	TRUE	FALSE			en-gb	23:27:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
54f4be15-dca4-4d1f-bf89-9561925666a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:34:00	TRUE	FALSE			en-gb	23:34:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
d57827ef-414e-4a8a-8f20-0407ee40e772	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:44:00	TRUE	FALSE			en-gb	23:44:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4a3bae69-ee58-4278-ac42-2fe9ce4849d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:54:00	TRUE	FALSE			en-gb	23:54:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4a3bae69-ee58-4278-ac42-2fe9ce4849d3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes	Yes	Yes			
ba31433b-9537-475a-8782-3062dc4199f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:03:00	TRUE	FALSE			en-gb	00:03:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
86717465-ecfb-4307-b7c7-a4b342555b59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:11:00	TRUE	FALSE			en-gb	00:11:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
04b864c1-48a9-4e4a-aeb6-cae15995933a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:15:00	TRUE	FALSE			en-gb	00:15:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c509f8c-b9e6-4d09-a862-ee9c0a126544	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:43:00	TRUE	FALSE			en-gb	00:43:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0c509f8c-b9e6-4d09-a862-ee9c0a126544	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes											
52575ec2-1645-4e2b-8c0a-a32450a76898	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:09:00	TRUE	FALSE			en-gb	01:09:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
48c68902-8c9f-4a2f-a295-10ba21290a53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:10:00	TRUE	FALSE			en-gb	01:10:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
c0578d1d-f509-4673-8d19-90a7da118bc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:19:00	TRUE	FALSE			en-gb	01:19:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c0578d1d-f509-4673-8d19-90a7da118bc0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes		Yes			Yes		Yes				
4d253408-5076-403d-b530-3cb806e4f422	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:32:00	TRUE	FALSE			en-gb	01:32:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
feb3d1c6-5267-4be8-82c0-95c8ef565e23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:34:00	TRUE	FALSE			en-gb	01:34:00	05/31/2023		Do better	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes			Yes				Yes							
660cf3d0-e985-4cdd-8315-d09107711c39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:36:00	TRUE	FALSE			en-gb	01:36:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
660cf3d0-e985-4cdd-8315-d09107711c39	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes				Yes		Yes		Yes				Yes		Yes		Yes			
66001ba4-ebfb-4402-bb46-e9aa7b9fac95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f450da43-30f2-4ae4-ba99-0b13a83911e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
a40adf37-2977-4b45-974a-70be4d90ec75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
12f22068-0602-44f8-8fc6-5e338b280b33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
d515b5e8-8675-49f4-9a98-aa3415b0f376	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3adc4fcc-77c4-43b2-a9a5-bf66d2799e0e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
90e86f57-c6b3-4d22-a26b-34907c6f4dbb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5eb47f4f-17ae-4208-9c6d-d31e7714fe81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b0e14847-d889-48fd-ae41-e586e1c4b9bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	05/31/2023		Good ****
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd080b0a-4452-4aa6-944f-22f01babfe5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d92b25b-9f07-406d-8775-5df680a97313	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c5a55b94-7c96-4447-b6a6-3c9f71146d84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5b2d5640-d64f-4643-b914-bbcf1c64a7e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5397c43f-86a6-4f87-b8e3-0add14ce30f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3aec4868-4424-48ab-81e3-0dcbc59d0453	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/31/2023		Good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cf600d52-8b5b-44d9-92dd-8eead130f055	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f5fdbb56-592a-45fc-8a10-2877694424af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87abcdfd-9181-4439-875a-423920874c58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												
ab6fdce2-b130-4351-a99b-bf53be021006	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
53bbc391-07d2-42bb-82b7-8d89820f9d1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
db17b355-e798-4d92-9997-0f71f804a40e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8af50a1-c4a9-4fc4-a99f-80bfefc00e37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d45434b7-58de-4c23-bdb8-6cbaab9ba16b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:20:00	TRUE	FALSE			en-gb	08:20:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
1de6f2e3-fe87-4de5-9a53-2c36e74b4599	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
041dee67-4b36-4e20-aa3a-81e9b6327ba2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	05/31/2023		Good cleaning	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5943d8b1-d463-4fca-83e5-09fb2f8df972	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
93f0b6da-cb51-4b26-afaf-fb3a2b280922	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc9643ab-bd2c-4f5d-8834-d4e561ded1bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
7820429f-36e3-4d7c-b78a-8a8acde1aafb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
64d4bb66-cbb0-4cb2-9123-8a2cd3b15430	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1e074f50-5c76-47b8-8644-93fd970036cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c7ba85c9-77b2-4a2e-9c20-b3aea99c12a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
35b897b4-847f-4396-8ec8-b5f0ad076603	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7f44e61d-76f0-4058-95b5-1f5f91a91c46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d258ba5a-a88f-4343-8383-53c415569e13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0a7ad2fc-ff2a-4d0a-8c0b-adce83bf271	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a4b868f-9048-44a5-a6b1-e16a0c2e9db1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d7f685c-57ec-47f7-a042-1624db92a50a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19b67263-0d13-4013-a576-4badc16cc3c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dff9587-dbea-4dc0-98a1-517255c3ad84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d608af07-4ef2-4fea-be66-350c3187b0fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a793a7f-4b63-4136-ad56-3083c2169f3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a5df2028-10f2-45af-946e-270b2ced2684	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	05/31/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes	Yes			Yes	Yes	Yes					
eefc8f62-86ce-4cdc-9a53-1c0a6a4a7d13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4f975958-69c3-418d-ab9b-4b4bb1cdc807	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e975c9b-9f4b-4c76-80b9-d23bab0b8bc7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
6726edf9-2611-44b6-b2da-8ff748e8d693	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8499adec-1b0c-414e-acd0-57a2cb9d8ae8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
705e676f-7302-4cbd-b4f1-e642a15de5a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9fcec8f9-a32c-4134-9b59-52d9dfe370c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4bcae84c-d0ec-4816-b1cf-e8033efbd979	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a666e79-53c9-4a95-83ec-d4f0eed92a08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	05/31/2023		Hhbgh
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes					Yes					
596b8868-2133-40cd-8c70-41727dbe7143	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/31/2023		One of the sinks do not stop gushing water
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c91f1144-d103-4e0c-91ad-9c527453c525	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
197499b4-756a-442f-a810-54ebfe5b6ccc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	05/31/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3a002be5-d041-4751-a673-b4fd846fbf6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/31/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
be6601c3-a042-4c75-b19c-541ba284db54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/31/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8d1ca099-ca03-41eb-abe5-bb9f4d3011e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	05/31/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
edff64ed-6de6-4a38-807f-a2ef3f88845c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/31/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a626492d-aae9-499e-93aa-4c556badcee2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	05/31/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
83d9dd88-be17-4464-b24d-afae81b66e9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6fcdfac-a36d2-4be8-af19-2fc2baec2c41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9951db61-8ac0-4cfb-a4ed-e8b004f6cbd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										
								Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
de205e59-a2c0-4120-870d-c066b8640b28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d53e3cd4-7814-49c5-b699-e2630e52b40f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6916de92-ee26-41e8-b9bb-3d3d6b9a3e37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee1717ca-30e5-40d5-8da1-3721952a49fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd84181-0835-424c-893b-df8350658f95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a5b078bb-e176-4493-a38a-439b77ee8e0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e520a173-1b15-4f78-a20b-a4a94f67e893	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
498f9d1e-0636-49c7-ade2-7ad1aba13dfe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1a41159f-0085-4b90-8637-fdd9dd669cfc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4c43ecb4-d3bb-40e7-9179-7a0bffee5094	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
c25baa20-88e1-4ada-b4f9-1fea668f6aea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c25baa20-88e1-4ada-b4f9-1fea668f6aea	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					
8466a329-2039-49ae-bb29-3e2513aa0ce2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51b472d9-ec1b-4e67-80b3-55a41d112412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e5a53e07-524b-4b01-925c-c4457d2827c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e581206d-e195-4915-80fd-36ee46d6b096	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
93300a32-f6de-48da-b1e2-27dcbffe548e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10e88e75-96c6-497d-bd7e-269be4db4d3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
987ed373-d20d-44de-b321-61abe65e9238	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2efc45b-47bd-490f-af74-ed1d7896bf5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
15c0e21c-f174-412d-b65a-d0e22858573e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	05/31/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
92509622-bcfc-4de3-ae7c-68b35dbf0dd0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/31/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
751faf66-3ef2-4e86-bf7e-40278c555d23	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	05/31/2023		Restroom in good conditions														
														How would you rate this restroom today?														
														Average	Good	Poor												
															Yes													
969376e0-3605-4a44-9f1f-31669acfaa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	05/31/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
9628d65b-cb6a-42f6-a17a-af4a9b3d75ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/31/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6b5745bc-35d1-47a5-8212-2ac3731ef770	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
33e35a86-6337-449b-a3db-f9fca32100a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
753c9167-84f1-4604-9e38-a160766d49a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c682759-36a2-456a-a43c-900f5c68f452	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce14bea6-31b6-4452-9247-d462e1ccab2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:20:00	TRUE	FALSE			en-gb	16:20:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
77617abf-5a84-4ace-b6b0-2c002e6e0949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	05/31/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fc3cfe4a-7496-4604-9177-d6fc850065a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/31/2023		Hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c78f2fa6-c09f-41ca-ae89-dad48527d487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6bc53f57-d6d3-44d9-88e1-fddaf3e54bb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d1618f33-16da-4a3a-9f18-0e8351c339b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
907ec053-d439-4eb5-ad06-2e64f0b7861d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e76874af-def6-4548-a496-932b838b9592	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes		Yes					
1c3a127d-12d6-46e2-93c2-75bd75dc9980	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1c3a127d-12d6-46e2-93c2-75bd75dc9980	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
						Yes									
ee12b319-c16c-4b0a-9d82-5278ccb2ab2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	05/31/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a6b97e8-1a59-48ac-b915-81fc2df25462	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41ae3c77-0ec2-4915-bd95-12b6891dfc7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4632766d-bc0b-436c-99be-0e7e2cf4d3f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a93afa14-05cd-428d-b036-b4ba4ef83813	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
38281816-63c8-463e-95b6-e344bd3aef7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
33123a63-626e-4f1e-9242-421c353fee0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
27cd4f77-71e1-4a27-8b35-4f3c97f4994a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
49a82249-f605-4f3c-8a8f-b4c0e64d6397	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd5893de-df87-461f-b37c-e89ad645a498	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1847d41c-ee02-4e21-9c7e-f685881383fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00558aec-ece5-436f-9337-22ede42f843e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
658a52eb-a2d4-445f-89bb-0ed7be4616b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c38f50f9-0e95-4a5d-883d-628a4f0c33a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c38f50f9-0e95-4a5d-883d-628a4f0c33a2	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes		Yes				
82c983ee-b770-434f-8df9-78f207c7d37a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a2d6240-4c12-4256-9979-0a97adb23713	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes							
3d486d78-1156-430c-8bca-b9de8c7db61e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a75f8b0e-8079-45b7-8910-264cff475e6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ee02f59f-4b2e-4f35-8709-9ecf5ec99d11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d2487b77-50c2-4e1d-bbaf-23fbf8fe6ec8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
085ac075-fe61-4da2-83e2-5c313c0f448c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes	Yes						
38328027-8dd0-4ea9-9682-5f5a798d2158	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
38328027-8dd0-4ea9-9682-5f5a798d2158	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes						Yes				
40dc2bad-eb1d-4243-82e6-e6ef92c069fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8b3fbe9f-dbe2-4f21-a045-62237dd3ea5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
c4c1e595-dabb-412f-bc5f-d85dc8d9ec4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7b396c44-1840-4a97-9ca6-f6e9a6c04326	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
272b92e6-fe4a-4661-8623-5186f0b3a62c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d1c74120-d1ca-4f5b-9c0b-ee77ae13a5b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
0eca4db3-64fa-4d35-916c-c0ebc526646c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
165f4862-b6f0-4e6b-881c-ceb8c6fc8d2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
96c0ae41-069f-46e3-829b-74db7386d10f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:15:00	TRUE	FALSE			en-gb	21:15:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea76b00b-437c-4caa-b926-56cb0eb46724	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0063c0c2-6b9d-4530-8baa-1797f6b051db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	05/31/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8c7ecbe1-bd97-4672-9668-4ebc9f115474	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1887e6c8-ce32-49f2-98dc-9e5086583ee8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c57d078-452c-4bfb-825f-6a4ee1d074a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
942a7bfd-7695-41a1-8bde-146bf1225329	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:50:00	TRUE	FALSE			en-gb	21:50:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c5d1cd48-7b18-44ff-b3b2-720ce4709590	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 22:02:00	TRUE	FALSE			en-gb	22:02:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes									
a83546d6-9547-429c-98d8-2de6e2f6bdc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 22:17:00	TRUE	FALSE			en-gb	22:17:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6ae3a2d9-9e5a-44b7-9d7c-a76756b831dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 23:43:00	TRUE	FALSE			en-gb	23:43:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d6510df-8648-4236-ab3f-25f528d7b89a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 00:16:00	TRUE	FALSE			en-gb	00:16:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9bdb8cac-4ff7-4af8-a542-b5585f48de4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 00:17:00	TRUE	FALSE			en-gb	00:17:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a816ba6-b4b7-468f-b81d-9400a1255c45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 00:31:00	TRUE	FALSE			en-gb	00:31:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f0b05b7-a187-423c-9464-c63a594bce05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 03:52:00	TRUE	FALSE			en-gb	03:52:00	06/01/2023		Keep the bathroom clead
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
25fd4f44-cedf-43ef-9708-bc99861af848	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:04:00	TRUE	FALSE			en-gb	04:04:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
6835711c-8f1f-431e-8560-b47316cbf72a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:15:00	TRUE	FALSE			en-gb	04:15:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
0c137d31-dcfe-4ac2-ba9a-cb2d4f67a403	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:22:00	TRUE	FALSE			en-gb	04:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
b3141e66-e9cc-465c-9028-ae9fb9eecf1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:48:00	TRUE	FALSE			en-gb	04:48:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
322b6e13-d5ef-4800-b7d5-8d2ea6dbdf5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5f2e8e74-2943-467c-9b37-44ad5e19ce7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
43daa35b-6d22-4407-9e2e-721194ca95e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 05:43:00	TRUE	FALSE			en-gb	05:43:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0f7d643f-58d5-489c-bfd6-34cee93fe138	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f7adc070-4abb-4439-a4f0-6130b221474c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d119eeef-1774-457c-ba70-41a18c820cc3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c1403dfe-9efb-46ad-8939-a6a68da2e72d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:41:00	TRUE	FALSE			en-gb	06:41:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
109f3a30-b3e0-4a64-810c-477506741181	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
fee24ca0-3eb6-46f1-ae14-2a1f278cf078	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
14ce400f-6c9c-469d-bced-205259275d45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
252cc91d-7bd5-41b8-906e-b87279dc77fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8dc96cec-a26f-4f62-af3e-9bbb8340506c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
08b68034-ecf5-40dc-8282-3b0885b003ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
71b663f7-4590-49e8-829c-eba5491f76b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0661cf05-a6a9-4014-88e2-cc62acf57763	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d14b5647-92a2-4c89-bea4-6d36ee5925f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1591df13-0f58-4a21-9ef6-d9e3937af401	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
04203e60-1514-4e43-888a-cb64571f06f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/01/2023		Mai
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a2af7f3-b678-47b8-91d8-741ae8d18c05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/01/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad6bb425-f6f9-4fb0-aefe-b09f3c785edf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes					Yes	Yes	Yes					
7feb6408-e271-4818-b4ac-25ae5633524d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
25cb80e6-19a4-4ca4-99cf-44e9e5cf204c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
df1f3867-387e-4ed3-83ba-604323a8322f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6b85cf6e-e9a9-408c-a4a5-9ad5a1717851	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
87e191e4-e9c3-40d3-a94a-1c89e34c6fd5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b74f510-8ac1-4547-8193-2690fdec6e5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec61129f-6e2c-4323-851b-ae0874167200	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6a42940b-6ffc-475d-9657-588c7d395b33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b27953b4-9b9b-49b6-93ee-c711af256f8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes		Yes		Yes		Yes	Yes	Yes						
f12d4f5d-ac29-4f74-9941-e6813f390166	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f13d029-6cf6-4379-b1fd-d3467e017753	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55a7ece4-f91e-4bc4-8182-3f8c9b9ad29f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
407c3771-e7e0-4e7e-b007-67f1c54a7731	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2d1d692-df84-4609-91f4-a1b612edd8e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6aaa91bf-b1da-4f49-ba3f-0ff7848af429	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e44735c-c5d3-4cb7-b014-b242721bea35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b1af683-a53e-4be1-a5c1-c434807ec8b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/01/2023		Could be cleaner
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30bf1810-98cd-4245-afe5-1b3f54d1c0db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99a8852c-2ea0-4f92-b478-54d044da24a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
50d99fbf-beef-4dbe-b247-cbdcd3e77057	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
409da39a-15c4-494c-998e-e2c2dd5286ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0f78551f-9530-4de9-b1c7-580a017cd044	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
Of78551f-9530-4de9-b1c7-580a017cd044	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
							Yes							
efb0095d-a7e4-42ac-95d7-c22257359ac4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e08c9155-e98e-4f27-8b0c-78849ecc4c36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
01dba875-0f3c-428c-838b-8bcf00aa1a45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
a57dc0d1-3a67-444a-8fef-47c1c91ab403	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
2ccb9994-1b07-4e91-bd68-9c26fe823f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2ccb9994-1b07-4e91-bd68-9c26fe823f3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				
333bc37b-fd07-4fe7-8da1-6fe8580fc490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
f1fd59ea-c8ee-411c-9c3c-e1968a620b7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
80ecb5ed-0418-44e1-b9e9-8025e0df6bad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
0d1eb45e-0532-4076-a81d-4d8a79357526	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
63391830-41ba-4941-a05d-997090520738	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0033474-a15e-417e-811b-6c291f2095b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cfb831e9-7af9-40e5-badf-05e10fb97041	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
14480be2-face-4e7f-8990-f463eac6e27b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2b25d15-50bf-4b59-a778-f0862c0e643f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec9764b9-a778-4034-8be7-2a69e7b8679c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c1a1213d-2c7a-4bc5-9c3c-19ef9917fa7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d7920e1d-2f37-4db2-94b0-b37c7117b3cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d993aa75-bc5a-4f08-8c26-c6c179f0bc54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
632cdbad-9f27-4102-8b62-d557510abb70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:11:00	TRUE	FALSE			en-gb	13:11:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a852f2f-e10a-47d2-8389-77f07aedd5fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0cc6f957-a6c2-4f46-9d93-41d71ede2972	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18b2323a-2211-43dc-8e5d-765925628eed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/01/2023		Q buen servicio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
650c7cb2-549e-4bbc-97e0-0aa60f2c0e57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/01/2023		Esta muy limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03529bb5-c5c4-48e6-a1a9-d5d0bb26c44e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c23fd0d7-029e-4778-b1f5-9f21d3480d6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2423741-a700-408d-abbd-1665188ae4e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/01/2023		Limpio todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d079c06-115e-4191-b3ff-1e16d863ba3c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	06/01/2023		Todo muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
86723902-f10e-4e35-8445-93aa5a751d84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ecf41818-9991-48a6-9a31-763c62dd702e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7112a925-1585-4ebb-9862-dd8c98d2e500	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
885bb18e-f068-4e92-b87f-5eec184c5301	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
553d64e5-fbc9-44a3-a6fa-a379b879d6c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1b6c0b8-4169-4c24-8239-a9d365327993	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ce2ffb5a-6980-494e-97df-711130f32fc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d96c85e6-747b-4ee4-a8d5-6c21f659bbb9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cdfda8d5-b2c7-4dfc-af2a-a698af644c5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7b9b9d08-279b-4b12-9139-fbb76c68d9c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a44f3a69-b8bb-4117-bf01-99f36052609a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
49a6f152-1ab7-4d01-a156-f9554f4c7fcb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1424042e-670d-4712-b524-0eb9103d2cb0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
a16bba72-b4e5-4b8b-99cc-8c70818794ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
deeb12fd-ff3a-44e6-8180-a86b530c25a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20de7572-4df3-447f-9c92-536b5686ab1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5009c129-9895-4360-9e98-174ac0adfd47	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/01/2023		Excelente
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
803f3b95-0f88-4ee0-94c2-054c377024ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:57:00	TRUE	FALSE			en-gb	15:57:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a661160-b190-4f01-9e24-36dc11aa0409	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/01/2023		Very well
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28723d51-ea88-4436-b6f3-c37b5b1bb6ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:15:00	TRUE	FALSE			en-gb	16:15:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes	Yes					
34ae74c7-62fd-47e0-bc25-d5380dca8be9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
178911f3-4c9b-4d53-b446-bb787ae50655	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51589b38-c633-483f-9b99-5817a9eb45f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5a3b381e-139a-4e2e-b38e-796376ed3999	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/01/2023		Pee	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ca71ceb-f551-4a0d-84b9-b97a647b5bf0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
43382cf4-aff1-4f33-99c3-23dba7b1b7e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	06/01/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
585f9292-2702-4c3f-bbce-4e8581340141	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cc6f5f7b-e43b-4742-aa8b-1cd4ba75e33f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
11b0ac9a-6905-4f6c-acf3-dfcc6070628f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
675e5ba7-b72a-436b-bff4-81c795283fc4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9dc671ae-6f58-41f9-978c-ed2323e27f60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/01/2023		Super	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
ead06c4c-1feb-43d2-94ce-332c63e981b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	06/01/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
9a8ccba1-9007-4879-9c72-d974d6ab24bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/01/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
2a66292d-e61b-4561-892c-5cde0d241d1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/01/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
8c80aa91-fb2b-48e7-a09a-fb2b667a8448	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	06/01/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
d24e814c-e509-4ea4-a611-bb3241b6c77c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	06/01/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
200fb892-04bd-4682-b0c1-6e65dfb37e2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/01/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes										Yes			
167e283c-270c-4f6d-8307-64a9655ae62f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/01/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes																Yes	
e75007ec-a6e7-4651-9abc-2dee8e62e7d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/01/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e75007ec-a6e7-4651-9abc-2dee8e62e7d8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7b488adc-83a2-4014-964a-6ae0f5edeb67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ad31468a-7511-4c44-a225-aa6669fe9127	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9475e41c-70bb-479b-a840-ef1328505835	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
178e1885-38dc-4607-a20d-a92c1705c3a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cf7b79e9-f89e-4902-9081-32cf694dc6ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6fd6badf-21bb-4da3-b744-1e3deadfc515	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes		Yes					
068e2a9e-2920-4e5d-b81f-4f03d7ec2a65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					
86a76698-1575-454d-9dda-24797336b45e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
da4e3729-30f4-4744-89ba-a8b6b88f5bf3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/01/2023		Very good experience	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
215b70cb-d731-4bf8-9a94-9da8a2496345	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes	Yes						
08f33081-3a65-41a7-aff-ec4c0d4076e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
414fb1e5-1781-4980-9abf-3ca1854e155f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/01/2023		lets go nuggets	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cf3b6e68-4ed8-4d6f-b1ce-2ada5677d058	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
cfbcac40-619a-49ab-8294-6867f9aa6bc7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	06/01/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
					Yes											
8e29f7ab-9235-4363-bc52-1d23a6047866	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/01/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
					Yes											
dc52c0b2-68a8-4333-9d78-193dbe314c36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/01/2023		No		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
									Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d68b153-6600-4d4b-9a40-ac6f94ce8805	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
303ea57d-3ec2-4f6e-9b72-9537b29716f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
67562484-f4cb-4f55-bdcd-661b44cf4047	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01ce7dee-a5c3-4efd-a85b-8dfa34f0a70	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
23d23625-2f05-4c0a-a9f7-978f999dc213	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
23d23625-2f05-4c0a-a9f7-978f999dc213	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes													
21a7d0a0-2c5d-492e-b8ea-d67e974da346	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aba2f5c8-618f-43ff-a7e5-1f42459914f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51508e8a-94a1-4c06-8bf9-12269dc1fb8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:11:00	TRUE	FALSE			en-gb	21:11:00	06/01/2023		Asco	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes		Yes					
944018aa-c1db-4c43-8032-fba6ce9ebcea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2a1e1b1-e1da-4244-8f39-4699a9b1d9b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a436755a-66d7-47b8-8575-377fa8ab58b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29fbaa38-f129-4969-8ed7-d2cc0a38d2a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	06/01/2023		Goo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22952f6a-ebe0-4976-83ef-93be61926b3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:24:00	TRUE	FALSE			en-gb	21:24:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d3781dd-cd88-4c5e-8f43-7ec35bbebe00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b23f6d1d-e562-4dcf-80b6-faac604449b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9b5f713a-8228-4dd0-8021-4296a3901290	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a368f3cf-868d-4d46-bfaf-9a697851af77	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8fd70606-cfaf-4881-951f-f5a1b9580410	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
699d4917-0fc3-4348-b791-3e9d792ba95a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:58:00	TRUE	FALSE			en-gb	21:58:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes			Yes				Yes	Yes	Yes					
ab1a116e-254c-422f-8c1d-220a12c1d9f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8ec2932b-24ca-4281-9773-aa55cfe2fa2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2f17134-4c4b-44dc-af80-0a009a12e020	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
872924f4-f5bf-4c31-8837-bc37f6ebe53c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 23:20:00	TRUE	FALSE			en-gb	23:20:00	06/01/2023		JI
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc85238f-9d04-41f8-a71d-976f230b4eaa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 23:25:00	TRUE	FALSE			en-gb	23:25:00	06/01/2023		Excelent
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
084115b6-586b-4322-9c2d-2560029c80a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 00:01:00	TRUE	FALSE			en-gb	00:01:00	06/02/2023		There needs to be a box for sanitary napkins in the stall!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes					Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9bac1f36-4dae-4b96-b2f5-d8aa00ea626d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 00:11:00	TRUE	FALSE			en-gb	00:11:00	06/02/2023		Bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
92541602-1d3c-4279-ad54-0734dcb2cbcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 01:10:00	TRUE	FALSE			en-gb	01:10:00	06/02/2023		Smells bad but i kobr tge
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1148b854-24cc-4ff1-a8e8-d0dcadda72b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/02/2023		It smekks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
9df91975-4ab9-4a1e-a891-0e2c390a82d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 01:56:00	TRUE	FALSE			en-gb	01:56:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce6198d4-3528-4388-94a0-bad453ab31bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 03:59:00	TRUE	FALSE			en-gb	03:59:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4955919b-88cf-49ca-87ea-146d0714769d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 05:20:00	TRUE	FALSE			en-gb	05:20:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f080896-1063-4521-b6a9-6062547e58ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f90bd3f-9119-49e6-bd6e-b13a46bf686b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f56b1e8-c232-42d5-a871-fb6e078081dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ad318a3-8331-48b2-b496-27d93d3d48fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56aaf172-767d-443f-8a0d-f08401d5d292	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:16:00	TRUE	FALSE			en-gb	06:16:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
aed6e105-c2ff-4f8c-bf6c-5f7240c37b47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	06/02/2023		Super todo muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98953c4d-6e9e-4023-8209-24fd353d97e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1b0c5863-d171-4375-b084-da01fe61001e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:02:00	TRUE	FALSE			en-gb	07:02:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b435d32e-57ef-42a9-85d4-a9f7c2b33c4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4756908b-d776-4ddf-bd05-9a9b81321a2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/02/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f160a81-91ac-4893-aec5-88ea014a7482	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fd111c8e-f007-441c-b0eb-6ea4b7b0a87d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20f7fc1-a7c3-44a4-8713-dccf0b18ae21	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cfbe0b2e-9864-4879-911c-5d359ee5a5f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1946a26c-a6d7-40ef-b2d2-dfe2515bc7ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
136118a1-7faf-4150-afe0-2e7c881079bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4ac9b63c-3ff8-4e0c-a571-555fc2cb1f87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d0b3d1a4-bf49-47e3-9af6-bdae8ac2b989	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
30a5b9f4-888e-4d9b-b390-b0a8bdd40cc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
39a67ddc-587f-4f0b-871f-5d7802dcd18b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes	Yes							
5871ccf2-11bd-4005-81b9-50e76d3ebbb29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/02/2023		Muy limpio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d97feef2-c0c4-497d-b03a-6457be2b9fc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
429a8839-a952-459e-8625-19e5538e0539	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b26c3793-1176-482a-a6ae-b26f420cd443	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
597a6838-da21-4857-b6b0-81c967bdac15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3731a7a2-c199-47d0-ac10-0f6bcd2f8ce7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8ba4cdd5-6a16-475f-abab-cf1cd2f1aa0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae402098-64e1-4d8f-a76e-91759be6a4d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/02/2023		Riquete bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dee5bd72-d319-48ec-82c8-c25aed5f42d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9de9a5c2-c997-457c-b9fb-9811155d4615	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8b0439ec-69de-466b-a1fa-adfe34fb248d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd6829c6-e87b-4fc1-a6e9-c8853e0cc81c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
172dd8c9-2523-4ef8-8b40-7ab87d784223	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
897903d6-1c1d-4140-b6ed-177ca4d4ab1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
dbfa43f0-c3cb-496a-860a-662dd2f50cd3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
23e420c2-c2e6-48b4-9cff-d72d3276cfb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
6831b44c-3a9c-4cc0-aafa-670f5ab44772	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
a2814fd3-6f7d-462c-9ebe-61d43bfce9b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
							Yes																					
37528d40-098b-475e-994e-27d0179bd361	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
951bc4d9-4639-4390-99e2-ac8f027865c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28a6bc19-c3a0-44cf-ab47-6e2e37935d03	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dbda39a8-6408-46ff-9702-cbc3285ff9c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75fd893d-8cfa-4eb0-a01b-d212559e42f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
92b8e909-c2c7-4571-bf0e-26c302135205	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
6b0667c4-9687-4472-8d7e-4ed745b3b1cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6b0667c4-9687-4472-8d7e-4ed745b3b1cc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes	Yes					Yes	Yes	Yes			
b3e60904-6e90-46b0-8f21-0ea0f463d175	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/02/2023		No attendant
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
18aec471-df5e-4483-854f-66124f30ec8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7ed0900c-1d6d-4fc6-bf28-cac08d3776c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53e66f55-8a29-4497-8281-edbc8affeed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:40:00	TRUE	FALSE			en-gb	09:40:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6da28e92-2bed-490b-8629-2a29006139ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6b20013-7ecd-4c19-931a-e1a7bbd4fe4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03637efd-2bd1-4388-8614-f1caafe66013	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/02/2023		Bjen
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aa19265c-a8b5-4b24-bf1b-a4a95840dbae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5270259c-f635-4f80-a461-7874600b49c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03273b09-b3b0-44f3-b06b-55781b6abb0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5463c124-fcbd-4d11-a849-3515d3836fed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:21:00	TRUE	FALSE			en-gb	10:21:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
04cb1883-4ae8-4b92-b832-358665ed4ce5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b6b5ff3c-ec26-4d1e-b4eb-2e7cff4f52a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4515a14-a70e-4ffd-ade1-bb33a80232a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cffaf645-c8ca-4b88-bb4a-52aac0e7aba1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e34287f6-351b-4ffb-ad50-db29a7ba866a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
26b72419-c53a-4150-bf08-139a992fe239	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
641a18b4-5fef-4759-8cde-0301fe935ec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dcbc5088-50a8-46a4-856c-69691d5de439	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
63fb7fa1-84e8-4350-a7c8-ef74128bf89d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f441bfb-9177-40ff-a455-5099b44298d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
76de63ef-5049-430a-ba9e-c6e315323598	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
76de63ef-5049-430a-ba9e-c6e315323598	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
d820c8e0-a01f-4b71-9bb6-8ed9f8dfc1ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c49b7ea5-b2f7-493e-ad81-9ae0c130eff1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:04:00	TRUE	FALSE			en-gb	12:04:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ebc09c76-7e7f-4d15-94ce-b56034a3db57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
b534edfd-2176-432b-8927-124d01c6d84f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b534edfd-2176-432b-8927-124d01c6d84f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes				Yes	Yes	Yes	Yes	Yes	Yes				
afc88368-42bc-4315-85d4-4d348fad2b77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
675ad54e-84de-4662-972f-47183d0b0db2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9377a08f-24e2-443c-983b-02fe6faa1e5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes			Yes	Yes	Yes							
a89e4164-1366-42a7-b36d-b43f26a7c296	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1db5dddf-8634-40f9-a67b-c64daa1f56e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19b3ee48-49b2-4a74-a9d0-6d37fbb84335	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fe135e06-2392-4a6e-b199-8f70a19d04e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:30:00	TRUE	FALSE			en-gb	12:30:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da5a3c6e-86e0-421d-9254-3fce15d18b86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
10ed062f-b11e-46fa-b2fb-456a4ede46ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00a4ccc9-04af-441e-ba88-0d8435b3366c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f4210f83-48bc-4424-8b8b-928aa2875d72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9879f4f-246f-4e2b-928b-af1e07a3de5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cadde74e-e85b-4d43-868e-a01bafabfd65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	06/02/2023		Thank yyou
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ab7c8f1f-a53c-4bb7-aa61-3e7482468f98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
32358336-510d-40e2-a4f1-96fddb52a4d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
51ed1b6f-8c4e-4db9-b300-14f083a7915a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
15349913-66bd-446f-bb8d-c8618a8a5e46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cc6c54c5-b125-4fd2-9df7-07b3d7fd73f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c0bc9810-6e7f-4fe7-974e-8a291055e81c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0583b83e-81f5-4c89-b731-909afb96ad33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d2258e4a-f2fd-464c-af36-ddb98da009cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb9fdbb6-f607-4e21-a09a-e0573c1c9213	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
12e30fa2-c24e-4a15-b07e-f906efae589c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f0d3b3b-9b00-49d4-a34d-7e4f6de8ed2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab9be58e-62c7-49f8-b31b-c3e5e8a0c9bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b911b5a-fe6a-4933-a32c-0c6c0013f690	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2fb420e0-3cf0-4f0b-8599-68717b0524ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4ed92e11-8804-468b-9d2e-ee2ce2f13215	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3b401472-3198-4177-81e0-893982724a16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
478c41d6-9e55-41fb-b7d4-63d01bf8b9be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	06/02/2023		Stupid	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment			
478c41d6-9e55-41fb-b7d4-63d01bf8b9be	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>
															Yes		
da8e42c1-9717-4e80-b490-aa6e6f9052c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
9c713195-c8c3-4971-9dcb-51867eeeb9c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
f0cf701a-1939-4fa8-a59a-37d046d8bb3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
e5e32d92-be9b-4f96-81ef-56007fb84395	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/02/2023		No			
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
					Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>
															Yes		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cac0c011-6f7b-418b-93b7-77a406d87299	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8af2ef40-3c1e-4b17-8534-d6f49d54ec94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fba1ee0c-dee2-42d1-ba37-d991d634b268	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98e5df67-61f9-4101-82e1-38c6b157ccce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/02/2023		Excelente	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7606b971-2398-4fa0-8d25-b66001a46a35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f0ec6df9-94fb-4ffb-a015-8262234ed0de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:20:00	TRUE	FALSE			en-gb	16:20:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2c8bc076-f470-404f-9ca4-3cb54a3e5501	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
963ae383-579d-44f7-bddf-7e2fe370db68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1560b08e-de74-4b9d-bc70-cf8062bb20ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
57db1249-f07f-4ac6-a17c-a4f02012e887	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/02/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
f4d56070-a344-4374-8b54-2bb2fa5a4c12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/02/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes												Yes					
5eaceb77-839a-499e-8362-d7b27e442453	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/02/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
44626def-7247-48a0-b15a-233f378aa1c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/02/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0470d298-6bcf-40df-87db-f2f5bda27412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
581cc534-f164-47e7-ae2b-69144af4dbeb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ec17838d-4909-42ae-9506-0f253487bdac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
91871b51-8f94-47e0-a0e2-4cf803328c68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:06:00	TRUE	FALSE			en-gb	17:06:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a86ecfb-7ba8-444f-9485-caab05341098	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1fe34de5-ad11-4c71-bb5b-ca4a678e1ab4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff4d8f12-7d65-436a-8d81-4c8fe7fe9291	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
709e50a0-2fb7-4801-9073-6223a51c733c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/02/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
									Yes						
05715aa8-917b-434f-a25d-e02c5d0a6200	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53878b5a-3626-4377-ae30-5f9c20b6a6e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a0a38f80-fbeb-47c9-a6cf-11e3872767ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
537d99b5-3adf-42e9-8c8d-906f061a92a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cd978b50-a544-4bee-9cf4-8d90746a1a91	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
95d439e6-7a90-4e59-b709-c7a6e4bcd646	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:03:00	TRUE	FALSE			en-gb	18:03:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7d39d3f9-3e19-40a4-93cf-0d216c6cf393	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c55d8003-66aa-4e79-a76d-72ba3da5c44e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
15eec924-d397-40e1-abe1-fec5556de222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
15eec924-d397-40e1-abe1-fec5556de222	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes	Yes					
8fdf7905-6aac-4b13-b996-1c48fa5b2775	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3b6f3a1d-ccb9-4b3a-a1c7-a4b7b33fd66e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/02/2023		Paper all over the floor	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
363dc4b8-ca93-4a7d-aab6-abe07b034dcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
596b0735-31d9-47cd-b32e-cdb47d7d2ac5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0fe0c53b-b7c6-4b9d-9e47-62f567e68da3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7af4968b-7a67-4e05-a543-0739d7f03558	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b06da723-ec29-40cb-80bb-01928daa91b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8fb2f421-efa9-4fd4-81cc-3664f811bd27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
515199cb-4bf5-4b1d-8798-50b548f948fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70c52b28-f68f-4865-8a5f-dba5b129bb8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment			
70c52b28-f68f-4865-8a5f-dba5b129bb8f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>
															Yes		
987e8020-5acc-4897-8948-c95de7200eac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
e2071f37-ce04-4def-bced-29abe181bcd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
3fb2e7c9-f977-491f-88bc-28cf0e05e568	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
f899b728-0e7f-433d-bc84-5987c7778f48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/02/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e1667371-7a78-4902-8e5a-b249311554b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/02/2023		Please put a garbage in the stalls	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
f82061b3-6284-48e0-881d-36c186784253	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
25ebaf09-5a77-45c3-9269-1cc598265678	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
95c81bbc-9c48-4b70-bd3c-f4bb75073021	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
a4ccfc55-9448-4c72-a219-839b71a05dac	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:46:00	TRUE	FALSE		en-gb	19:46:00	06/02/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
															Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
			Yes						Yes																		
32f19b42-2c66-4602-94ac-bb6a4b26c2f2	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:53:00	TRUE	FALSE		en-gb	19:53:00	06/02/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
															Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
											Yes																
bc4ffc46-dcc8-4db6-937f-8aab4a303dfe	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:54:00	TRUE	FALSE		en-gb	19:54:00	06/02/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
															Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
									Yes	Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4680f958-a563-4337-b86c-14313359f419	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc316bea-5097-48eb-88b8-ffd6d6d250b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes			Yes		Yes							
d30201cc-48c0-4c52-bd01-a90861d120a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
29186bd4-445a-442e-a701-00e4993493d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6e063dc8-e259-488c-9afb-b30353fe35b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1f3fd46f-ebbb-464e-b05e-0a8789bea70b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
658071ab-9197-434f-9099-5ba34e9743fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/02/2023		Ho	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d38261c7-b084-4c2d-9a5a-98fd9d261655	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e98b47e-8fe2-4f8a-a11f-f40d62653a20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/02/2023		Nasty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6e98b47e-8fe2-4f8a-a11f-f40d62653a20	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes				Yes				Yes					
997f78a2-3373-4bce-87a4-7a0be8e8cc0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/02/2023		It was mid couldnt **** in here tho						
	How would you rate this restroom today?																			
	Average		Good		Poor															
	Yes																			
9b1a5c8d-abe1-4a3c-8dce-61cbccfe29a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/02/2023		No						
	How would you rate this restroom today?																			
	Average		Good		Poor															
	Yes																			
4ff56fc0-6ad4-4037-b596-a5e01fb86fc6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	06/02/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
			Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e58eb706-6a5c-48fb-9939-c975a8bec210	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca6fc6cf-da11-4e1f-8fcd-7c5bf91739ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
380cd457-1d53-4b6a-a779-758a31497b2e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
51492f89-a43a-4989-a343-3437d86c6bd8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes	Yes	Yes		Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dd2fe86d-a8b0-402d-8fc0-94079c45047f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
aaba120b-04c0-4f9b-bfc4-f1d655fa8163	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f9eb18db-8970-4f8b-ad5d-3b8e5ddb284e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 23:29:00	TRUE	FALSE			en-gb	23:29:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9529970b-1c09-4761-82a7-2d4d07a719c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 00:00:00	TRUE	FALSE			en-gb	00:00:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes						Yes						
72b60011-95b5-4b46-a098-c8bdb1843676	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 00:53:00	TRUE	FALSE			en-gb	00:53:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72b60011-95b5-4b46-a098-c8bdb1843676	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes			Yes							
86e8baa0-1ac4-4ef5-b71b-24f64f46602a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 01:46:00	TRUE	FALSE			en-gb	01:46:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6d60f7ef-7e9b-4994-9d5b-0ec91ab48e23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 02:22:00	TRUE	FALSE			en-gb	02:22:00	06/03/2023		Door locks broken, hangers for bags missing	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes								
49842df6-f47b-4af5-ab35-8eb6f51ca0ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 03:30:00	TRUE	FALSE			en-gb	03:30:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2b57edd7-f5a7-4491-8388-c2fbe8d3b0d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 03:45:00	TRUE	FALSE			en-gb	03:45:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
67a0c0f3-8907-4351-87a5-0a2ad3ced410	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 03:59:00	TRUE	FALSE			en-gb	03:59:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c4f8201-d24d-44df-ac81-f3d9a87ced71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:09:00	TRUE	FALSE			en-gb	04:09:00	06/03/2023		Good service
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f45517e3-54b0-428b-b421-9d9d5f1c9d7d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:21:00	TRUE	FALSE			en-gb	04:21:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b8d62861-4c85-4c81-acda-447644be183a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:23:00	TRUE	FALSE			en-gb	04:23:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes			Yes	Yes							
3bbab1ce-c289-4779-a098-b58d0e878cf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:44:00	TRUE	FALSE			en-gb	04:44:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5e850c62-31cd-4293-b875-0afca596129e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:55:00	TRUE	FALSE			en-gb	04:55:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b09c4bc-af3d-4fbe-82c5-1e24c0e711e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:10:00	TRUE	FALSE			en-gb	05:10:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53811312-3127-43a6-9e66-186acdd13f15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:18:00	TRUE	FALSE			en-gb	05:18:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
86361ce8-8bdd-4cbd-884b-ba61706f05e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4c83a2de-1269-4815-928c-7653e8ccb0e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3f15539f-ed1e-49ac-94a3-628088da19db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:43:00	TRUE	FALSE			en-gb	05:43:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b36ad51-2b81-4cb8-908b-72219f1b2406	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da428b9a-41a8-4471-9a6d-0cbf4e930b6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06a5cde7-e270-4414-b0a5-7da7538c9358	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86b9ee5c-ba0f-4711-8580-1db08bcc3405	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fde438a3-bf1f-42cc-b454-dd99a6bf12c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4fa0ce3d-6bab-42d8-b900-18a8d165e807	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	06/03/2023		**** smell	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2b0b98c4-139c-49bd-8759-2429af4b7d02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:13:00	TRUE	FALSE			en-gb	07:13:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
76167a42-9085-4d64-9059-a56b17c7c429	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f2b70f2a-b2f2-41fc-a3ef-0d096c6cff4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
136a099c-5003-47b7-ab03-7a6e7e01d7f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d04663b2-1ef4-4e4f-a07f-0d63db63c9b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
4b4c0de9-4fac-4ab0-8100-7a7d4b99a604	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
6e83cf06-077d-4b70-af72-1b64564094b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
f81e4284-de6e-4dbb-8abe-d691e40c418d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
7d6a5386-5500-4671-838f-82efa8731965	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3ef202e6-6b9c-4db3-bbc3-d6e556529dba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
2233748f-3407-4d12-99bc-0eb083530afb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:05:00	TRUE	FALSE			en-gb	08:05:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
ad566dcf-50b8-48d3-ad38-1ed96e695854	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:05:00	TRUE	FALSE			en-gb	08:05:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
03c6677c-f29d-4278-9a5e-37cbe78acdc8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
212ea93d-57d9-4572-ac8e-2c6afd1ae6e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
212ea93d-57d9-4572-ac8e-2c6afd1ae6e1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes		Yes		Yes			
50711f83-6132-4559-8ec8-69da8802a2fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	06/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
a003f9a6-f199-4f09-960a-b0ddf527329c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
4ca1eb8e-77a2-4b7c-9ace-5103e053155b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:25:00	TRUE	FALSE			en-gb	08:25:00	06/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
76c83c27-62d5-4d85-ac9f-dc52f5ff2471	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
298a2cea-06b8-4ce7-813c-06a3e11a0930	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6973238-595f-4b5e-a601-3991f215114a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b72e60f2-c40a-49b5-99dd-68307ec7ed78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e1dd92ac-bd13-4639-a573-79b060fb485a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8c9350a-69e4-48bb-95e3-46e163d66379	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/03/2023		Hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
a61e797f-b7bf-44fb-8fdf-f67426965859	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
262536b1-6686-4cdb-9363-0fb54e77b134	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
10c334ce-c93a-4884-abe2-029eba2ab774	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9fe38e96-c63c-467f-8741-8751ceb75a02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f955da85-02f2-4cc9-beee-96fef982bd2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Obd9116b-52a5-417a-986d-647f01c43985	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
193ec128-0a42-432c-95f5-813c64b45fa0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9f052686-de30-424a-a302-4d7bd8d3efc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7f53fece-d72d-40d5-9673-a7ea2fccd60a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
433e284a-0154-4e67-af54-e0305648db2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f655d9d9-e369-4d52-a7a2-059bab91c944	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
199931f1-e49f-4e81-84c3-aa72c04ea487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
39619e81-d044-4d60-8ed8-fc6bff99a967	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39619e81-d044-4d60-8ed8-fc6bff99a967	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
85108ff2-a245-4361-a4d3-db72e673e5b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/03/2023		Sucuo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7e15ea02-f4c0-46d9-ba31-ab6bdbde4662	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/03/2023		Gross	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes			Yes							
3be4f20e-0b05-4f85-81b6-17c0a40fa2f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3a0067ef-413f-4bdd-a97b-9661edb0d9ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
58900496-2887-47e6-8776-686f6d69d0f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/03/2023		No
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
b6b4611d-f50f-42d8-8feb-c1eff6047d3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
479b5f82-ba39-489f-b442-6677095126ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
a925be2b-0bce-481e-8d71-811af4a6dc5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
7f5c856e-0816-4602-aefc-9813deb4b9d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cb49ecf0-cd8d-4a83-81d6-4ac33d3978d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fbd93d6b-9d01-4ee1-842d-6897c2c770c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a6c9d3ab-531e-474c-8f6d-4e74d8baa727	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
676fb301-52f8-4e2a-b75e-362112fa8004	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b6f3c0a-2e48-430e-b357-c2e8bfc78a2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2f0e6aa1-e859-4597-b668-2664affd33e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
afdb34d2-85c9-4a14-8075-ad5a061bc54a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f907b058-3148-4447-9c36-81bfeae785cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
200722f6-3aee-45a1-a4f5-9d3209888454	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ec6152d6-11d9-4033-9e5a-5705195f1705	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99e3475c-d91d-46e2-81d7-a59ec4a0a000	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d2c36116-b235-4743-9ffb-f547e8b5d95c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
de1b0d04-f22b-492f-a367-920089f49282	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5e017e1f-f905-4e63-a92e-6415894acd20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/03/2023		Nice and clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c60a3127-efc2-42b2-9136-957f2f13061d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/03/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5a162369-3b14-4a7f-ac9b-6f201575a8b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes		Yes					
cd25c5da-75cf-4860-95a0-9d2d8ce94b28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9ef6edb-774f-4ef0-bbef-c03fad75ca9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:17:00	TRUE	FALSE			en-gb	12:17:00	06/03/2023		Muy sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f2478e7c-3588-41ee-9d40-2a7cb57cbfb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	06/03/2023		Should be a clean example of who we are bad expression	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
f2478e7c-3588-41ee-9d40-2a7cb57cbfb1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes		Yes		Yes				Yes				Yes					
5a5fa993-a654-43e7-81ef-1118d46ba794	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
31b3907a-d4e4-4c3f-9687-e4abd92eaf51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
00c3d050-ae71-45be-af30-5796b83c53cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
6cf8d8b5-f971-425f-8438-116dd6cb89e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
														Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2f30dbc-1501-4067-a483-7c9698bbd892	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6a383c38-e78c-4041-a766-c6a8db098711	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5ca2aeaf-fabd-4194-82cd-926685078a9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
703f7955-84cf-4a54-be38-e0b3073d46a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae29350f-ba56-4841-bee2-63d161e5e582	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
33a4b809-5cea-4fa9-ade6-e8fc3350820a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8e81d4bc-137f-4351-b06e-a27de584a73c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bb804493-03ac-435e-90d0-32eaea60664d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4787b4a0-bc66-453c-befe-7322cfe28ae6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b983881b-57cf-40a0-96ff-28d6bc0ef60c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49bec92a-ddd9-4f33-b9a1-19e829c88644	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae29d4ea-8646-449b-ac26-3de395947bc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba9372f3-57b0-4568-86b0-e8c54e9be802	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
853c9539-42e0-4f90-9c36-603a67f96ac6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d55fa641-16bb-4b07-afe9-ee624015dfae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f3197d46-42ad-47c7-870d-c90f1d938d13	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
263e8638-7e85-4cbe-b069-cf0471706eff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b44b70fc-c9df-403c-ad93-84c9fbfd9319	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0f8a3144-60bf-4ee3-b13b-c3c4d3cb0189	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d07d1d-f826-4caa-ba76-408bfb84bbcb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
595f5013-aeaf-406b-a209-9cd3166112ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b9832e8-3876-40a8-84e4-106831071797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:28:00	TRUE	FALSE			en-gb	13:28:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81ea26ad-0a13-47f3-ace4-1025e34ffeb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
881786a7-5456-4997-aac7-34db49fd25f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/03/2023		Xzabbvbbvvgb bbb'hhhhhhvfgvv vvvv'hhhhddddd dbkkkkkkkkknjjjj jjjjkkkkkkkrkc. V
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4de2b75-b0ef-40ee-9d59-294d5737f19e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:04:00	TRUE	FALSE			en-gb	14:04:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25bb0600-4154-4337-b036-e370cd033cc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
26619bb5-575f-4163-abe8-130092ec4dbf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/03/2023		Happy
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1cb5261a-6084-4b49-bf44-f99add28a3fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1cb5261a-6084-4b49-bf44-f99add28a3fb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes												Yes					
5fdb469-7ef9-4a5d-a82d-568f506f8e08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
97dab606-fb73-4b7f-bc19-2c069d354fec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
bc2384e7-3b0a-4050-9683-2f775cfcbea7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
														Yes						
f1e3be9e-5401-4fc4-8c87-13487604a370	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	06/03/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f1e3be9e-5401-4fc4-8c87-13487604a370	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
077430e7-6e47-4d64-b1b1-d3d659da137a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
32ae4a80-5039-4aef-ae4f-244faaa2d0a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
3639c5af-377e-47a9-9825-5a229d7a13fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:46:00	TRUE	FALSE			en-gb	14:46:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
51e58914-6e4e-45f1-b8cb-4dff8a8c292c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
51e58914-6e4e-45f1-b8cb-4dff8a8c292c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											
0aaf9aaa-d9ec-40a2-8467-2edda41614ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
70bc351a-81a5-4bf8-91d0-d3bdfade47d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
efd59a40-deed-4596-a532-776ab2ad9eb6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b3cb91f7-adf4-416b-b18f-fc682af1ef92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7a1bc8f7-cab3-4ee8-b4f2-1fbd5a5b69f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e7d02e35-9e29-44fd-85b4-5b6b6b6931e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3369b4e4-61e3-408b-abf3-38d8b19c6874	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
454ac1c8-47fe-4019-bd5a-9e00f596cccd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/03/2023		****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
72151088-c349-4fc0-b670-55a7a0b2978c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
72151088-c349-4fc0-b670-55a7a0b2978c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes								Yes			
06b9339a-47ba-481d-a63a-76702cfcfa32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
122d0ba5-4c48-47ed-b5ea-a563033af00f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/03/2023		Todo limpio gracias
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1857a60b-3816-4418-8e00-90b99f1478ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74e9d91d-c5d6-4102-8d94-0ba5dad4504	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d21c89fc-d5a3-45ec-869f-71c1aa0ed50b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/03/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44afa9b3-cb8e-40e9-8b15-cfddfa8c706c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef125002-f42d-4935-861c-fbfc63987a9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d05f631-b5f5-495a-92fc-6ddd95a81d67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6fa9004f-2d5e-49a6-bf95-1ce2188ec20e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17eb85ae-f3a3-4a33-8b5e-a9f98b2c40fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:24:00	TRUE	FALSE			en-gb	17:24:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f74de0ae-baa5-404c-bc28-0d92561ede3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
183da570-0807-412e-883a-60d7404fc30a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b4b833f2-6bde-4651-9a7a-6b6c9644f79e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:34:00	TRUE	FALSE			en-gb	17:34:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6f3c8a35-d49d-45ad-938e-a95c1314f76d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:42:00	TRUE	FALSE			en-gb	17:42:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
384fd5b0-ec78-4d00-b5e8-ac4b711489b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/03/2023		No					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes		Yes		Yes		Yes						Yes					
7d386f76-82c8-4ae9-a57d-f860d1c2f93a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/03/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes		Yes		Yes								Yes		Yes			
9b35f0da-ba9c-4238-ae5f-58612f73db57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/03/2023		No					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes												Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
07c9c252-9f0d-46f0-bd67-3291d5401283	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
65190e55-0563-4e0f-8278-fc75da7e5349	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8aaac5ec-88af-4db2-9e4c-61e3ca71b9f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
					Yes			Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fad612d6-570c-4f09-89f8-d02cc81ae0c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e330b1ed-3473-4e92-a121-bc6620682697	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
590749e9-4a75-48e4-a75b-8ad23db10934	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
0b91ad93-edfe-4bb0-803b-0972bf0818b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
de54137b-f8b7-4dcf-bde7-a62ba1258486	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c7baa012-4216-4848-8495-51afbcb06914	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
72506c50-127f-436b-bdd9-6f47e9e6419e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
482b412f-7992-4582-b1de-e3cc5d56f7da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d3005a5e-8adf-45ce-9e53-1660277d8de7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4fd51d2-4421-491b-8ebc-9fa26db796ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e21e6a46-f83c-471d-8bf4-84d9b2ca1837	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f917fe3-4ee8-4c95-ae4e-5518d659be8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f24ae39d-dc76-44e2-b1c7-e1ca7d0a0e79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e8a68179-cfbc-4465-8a25-fe92690fd27c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/03/2023		It looks very poorly maintained and the smell is very strong	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
dad28fc-c394-4dbb-a78d-40db69bbee9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/03/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
452dbf59-6849-4651-84d6-0918d4af58d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:04:00	TRUE	FALSE			en-gb	20:04:00	06/03/2023		No soap					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
										Yes									
3028db14-a5c3-429e-add3-5af697231764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/03/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
												Yes		Yes					
ad70b0fb-def5-435a-9717-a662298b03c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/03/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
06405789-4895-41f5-b931-5e236c0d626d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:24:00	TRUE	FALSE			en-gb	20:24:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e0d1032-6aca-412a-a542-cef7f5822097	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d0640bbb-bc5c-4d59-871e-1335e9f32b0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd69bc0d-a7c1-4974-92ee-32b4cb54f10c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50ee0a50-f103-447a-be57-a0c713dd1c72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5b1a0709-a36f-4ded-acad-56458a6d4053	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dbf9cc3b-f05c-4474-b361-34cb541ae05b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c210db9e-437d-489d-af88-c6bd38e879a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:57:00	TRUE	FALSE			en-gb	21:57:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
017ee91d-04be-483d-a981-85a1eb4e3d36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:58:00	TRUE	FALSE			en-gb	21:58:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
49c559be-8660-497d-bc0f-4d23f22fc023	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:07:00	TRUE	FALSE			en-gb	22:07:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cfb28af2-ac6a-4b55-af11-aca305b55a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3b55a805-abcc-4488-9073-74491645d322	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:17:00	TRUE	FALSE			en-gb	22:17:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes				Yes	Yes	Yes				
7f78c9de-1e89-4f86-ab75-eadaeb791faf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes			Yes				Yes						
9c9ce679-918d-4adc-b149-df58ff7afc8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:23:00	TRUE	FALSE			en-gb	22:23:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
6297eac7-f3a0-4e78-b185-c97136a1ce0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:26:00	TRUE	FALSE			en-gb	22:26:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
			Yes				Yes									
6fe9a4dd-a53b-4875-bbd0-f356e24e0f4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:40:00	TRUE	FALSE			en-gb	22:40:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes			Yes				Yes	Yes								
6a5d56b6-82e3-4612-9274-b55c9cd87455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
65444b44-b43c-46e4-9d06-1734e6c8beba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b6812b08-eb35-4111-b2f4-31dc1d43e3e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:48:00	TRUE	FALSE			en-gb	22:48:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a072820e-be27-44b5-b93d-b0ab169e90a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:52:00	TRUE	FALSE			en-gb	22:52:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b4fcad2e-60ee-44fd-9fd2-13d4fb91e51b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:53:00	TRUE	FALSE			en-gb	22:53:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3668e079-df87-4442-9448-70224b6d0256	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:59:00	TRUE	FALSE			en-gb	22:59:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
98d0417e-6acb-4216-bf45-7a2f64b2231b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 23:03:00	TRUE	FALSE			en-gb	23:03:00	06/03/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
d3cd21c5-c652-4302-b6af-b4c39fc20eba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 23:28:00	TRUE	FALSE			en-gb	23:28:00	06/03/2023		Excellent															
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
7f763259-311f-42e0-9520-753d6e9633f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 23:31:00	TRUE	FALSE			en-gb	23:31:00	06/03/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
f32fc82d-b286-43bd-aa9f-42c0b553b335	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 00:05:00	TRUE	FALSE			en-gb	00:05:00	06/04/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
1f671866-f66a-4c00-a8d7-36b3e586ed58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 00:33:00	TRUE	FALSE			en-gb	00:33:00	06/04/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment			
1f671866-f66a-4c00-a8d7-36b3e586ed58	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>
															Yes		
6476ca1c-bf6f-4c59-81ca-6def11df69c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 03:08:00	TRUE	FALSE			en-gb	03:08:00	06/04/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
f4e97eeb-9707-4689-814f-dc5086278883	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 04:47:00	TRUE	FALSE			en-gb	04:47:00	06/04/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
f549d627-77dd-4932-8e0c-981dbecf38ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 05:15:00	TRUE	FALSE			en-gb	05:15:00	06/04/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>
							Yes								Yes		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed9d9931-31fb-43ba-baf6-3d2e4baaecf4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 05:36:00	TRUE	FALSE			en-gb	05:36:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
44cbec5d-d169-49b9-bdb9-e2dfc189df53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
626681f7-ffd1-4ecb-a338-b6f2ae21b97f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
58879af8-1e36-4d45-93b7-33daad156fc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4145d1eb-60c6-4725-81c2-f676ea22ac5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
590970c0-93de-4b18-8478-a9833eb315	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72d5a4b8-7124-4893-b9c4-b5546755d581	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	06/04/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
effade18-663f-40c0-aea7-8faffdc7e31b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8bce5386-97c1-436c-86d3-710fba551f3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b08b604e-3d86-4f37-b5ae-4e8e5de4272c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
384f6d42-529e-48ed-be71-d74305eedae9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
b967b7e7-e67f-41cc-8ca5-0fa2cb39fdf7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
b7e4708b-1734-4c1f-8b2b-8145c4f29145	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
48148c98-140c-42d1-9fa1-fc0a49f257bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
e0066f70-f984-43bf-86c1-b64147f2219a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
6ee12d8c-38df-496b-bd25-cdfd2bf878f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
5be30c7d-a706-4f6e-a983-582db738a54a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/04/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
cd99ff00-538d-4cfd-aaff-9e2cbc82114e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/04/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
6f7477e3-4c00-4f0b-b9cf-54a756a76082	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:17:00	TRUE	FALSE			en-gb	08:17:00	06/04/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes		Yes		Yes								Yes		Yes		Yes	
788fa968-0da3-46ac-8681-edb9b3bc4c33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	06/04/2023		Sucio y prstoso					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d2cdae52-feb8-4fdc-acad-3ae678423271	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d39c0ad-ec22-47a2-b181-777d248ed740	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea6a9338-0cc0-4f31-aa4a-53199971cf87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
13343c89-d3cf-4b41-9a4d-01391f6119ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b0c4fd7a-20ac-4642-89c1-7e8c2315ba6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
743d1fee-f7c2-4951-8525-4e00cccaa1f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
16791b35-5c5c-4631-a450-f79a0a4d0f22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0bf24ba-47af-4ee5-833a-6de930a86354	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f8b581fc-6af1-4e44-9f15-87faf7eccf1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2f89bc61-7e0e-4a79-b47c-55c88a0c273c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4aa66cac-1eeb-4414-92e6-9df8b46d19b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b9eaf455-58fb-42df-ad3e-8e47faf6799a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1e3e3344-d493-4ea6-8766-21110af858aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
913d79e6-a23f-4762-9a34-f01392cb7f27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0427a4b9-4570-46e2-8b90-8083c1805944	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7df01ce6-6f25-41ba-b683-be0b526eacdb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0a75a0f9-aa38-4cbc-aafe-b0a9f251a5b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b3c27427-614a-4d1b-aba1-a8cf4f8dd89e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
046d8381-48d4-4674-9d07-081dfa901b2e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9014b703-27f7-4465-b786-ee3a8ecfceb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9da30e2e-f5d3-4ab1-9e2a-89f9e7c1b0b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d7c043e-1a60-4238-b0f3-20e6488b5797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e8be859d-76e2-47e1-8214-188ae6077b84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e27cf62-e72f-466a-882f-163033d116b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dca15930-57c4-480b-9746-3cec02e490c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
06261679-ae3a-40f8-b734-d4ded3b72da5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9137415c-f1ab-426a-b40f-39488c6b2f25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fc141c3e-2840-4f8f-b76d-85988f66b5d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ca1c48ce-4277-4e7e-aae9-aa331ae578fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	06/04/2023		Puerco	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
528be483-b54f-4be8-844b-6898dada46a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78011e74-f243-4eff-b945-11b85f7325b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
823ca315-0112-4d50-93ac-1a84d8ad4689	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
4e74a85a-1528-4e8b-bac4-1733b51d2882	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4e74a85a-1528-4e8b-bac4-1733b51d2882	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes						
db8204c3-c844-4b8a-9a57-26a40bf65ce4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
03355717-70f5-452d-84de-fea4e2030762	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
cadec6ca-01cf-42a6-a5e0-3497742d8f46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3b396023-8ba7-45c8-823e-116ade878e1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3b396023-8ba7-45c8-823e-116ade878e1e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
46c86d24-2c0a-49cd-afa3-1ab6ab074afc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77c35e05-6727-4bf0-a802-f27e9e7de741	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1844bd25-bd52-49de-9697-769e545c9158	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
95bc082d-d16c-4af3-ba27-3052363e25cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
124c06dd-a04f-4cf8-a7d8-dfa170f47a93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/04/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
2a425ad7-4028-4ca9-8a9f-eb276d8e472a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/04/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
e3c723c9-5d88-4e61-bbf3-f443b3e220ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/04/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes	
5bdb13f8-ca37-4e09-b8d4-968615b27011	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	06/04/2023		Uhuuuu					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5bdb13f8-ca37-4e09-b8d4-968615b27011	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes	Yes		Yes	Yes	Yes				
49335c2c-0964-4f75-a147-296f1e6ac4da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/04/2023		Dated
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62932986-db2e-4a8f-8604-fa66fc628826	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cafb2f19-aea5-41a4-9449-ef76772ef82e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
521c470e-f9bd-4d59-bea1-7da0d81aae98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f91dca55-c80f-4db6-9d33-bbe632a144f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30074872-ef67-4ba6-8de7-ecb921755c11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9ff1315c-0177-4d3a-9210-df6b559227c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3a65c464-c423-4549-8741-5e1ca94d5278	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
cc38c210-72a6-4410-ac35-de78be3b77d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cc38c210-72a6-4410-ac35-de78be3b77d4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				
1032efd7-bba5-49ae-80cb-64236c17fe6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/04/2023		Bnhhhh	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b944d93-24c3-4410-91ad-c5e88cb91324	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6a905aba-fa0b-421a-8e77-badc13927c55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/04/2023		Got yhw p	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc6f6242-657c-4b4b-b12f-d1486926a1ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:17:00	TRUE	FALSE			en-gb	12:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
245121c3-e085-41ba-9ffe-3fc2cb77bdba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc6c1d57-9a22-4e19-af5d-ce3b5bfbaed6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c2aad285-fe9b-4570-9f5b-728c8c627b95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f5fec93-916e-4e9f-a9dd-9bd6b8bc9c63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f5fec93-916e-4e9f-a9dd-9bd6b8bc9c63	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
42416d66-c969-40bb-8862-f1bc3e425802	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
738b924e-6c1e-4496-b91f-249d83699465	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25ed8f4a-5bbf-4e67-8c5f-885050dbc46b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e258313-fc9f-4948-a17f-b2a7fadfa7f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3638377f-a3de-46ec-823b-1d49df340633	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1da5b2c9-ca4b-41a6-88d1-b702dc9052b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1c7491db-a030-4ef6-849a-30ba9a348a1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8183b5d6-7d27-4fde-9e58-16d776d23bcc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2d7ed8ce-0d96-4acf-9569-784a135ddccd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7fce5bf8-585e-48b5-b7af-68012084b543	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
335a6199-2b6a-4552-8e4b-0b09d4a93037	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
78ed22c0-11b1-406d-821b-91bbb71b4cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:29:00	TRUE	FALSE			en-gb	13:29:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
21c9818f-b3ad-4ea1-b0e8-a08f810f5604	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/04/2023		Smell so bad	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes									
9aba1857-5324-4a74-a445-06e5a629e996	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
106965b8-f3cb-4da5-94f9-f263c6c816f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
68636ef5-46ac-49f4-80d1-4e6620027c0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
0f950f5e-2467-4305-afd2-0ff6b8298f3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes		Yes	Yes		Yes	Yes				
3f31c27d-64d8-4bb2-a3b4-5f9fc457eb98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3f31c27d-64d8-4bb2-a3b4-5f9c457eb98	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes					
d121faf7-d0e8-48fa-9540-7d62e782d4b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/04/2023		Sucio todo
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes						
910ce198-34bf-4713-8c97-f859ed64cc3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:05:00	TRUE	FALSE			en-gb	14:05:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes	Yes						
c6c841a5-b2d9-449b-88b8-67c04b9e7c39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c6c841a5-b2d9-449b-88b8-67c04b9e7c39	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
50a6e17c-fc7a-4587-83be-b23915c9d0c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/04/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
49c43b44-49ff-44ed-9cf8-adedc4c0f283c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/04/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
9a0bd211-0bf9-4300-8aa7-f311cad718f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/04/2023		lck						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9a0bd211-0bf9-4300-8aa7-f311cad718f7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes	Yes	Yes				
316eb9df-85e5-4422-8e88-bef627e83de6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1bc335b8-65dc-42fb-a3c3-e95518f79793	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes	Yes				Yes	Yes	Yes					
c0298783-b0bf-40bc-a67c-a2423b3820ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:46:00	TRUE	FALSE			en-gb	14:46:00	06/04/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3cdb6a7b-d200-43a2-8b86-5de2f231acd3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0903403c-48e4-4aee-8f27-97a55cd273cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b47f890-493d-4ca5-bb52-724651d6f4e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
de6bd58b-eb21-45fc-83be-4dfd7ed99cb5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes								
30e3dc21-a6cf-427f-876d-0a126316f438	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5a08c0f1-6ab2-4a22-9df1-b2dbb441df37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22b2da86-0692-4961-9220-5edecb5e1190	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ffe0acad-cfbd-4f3c-857f-309dec629b0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01b13565-b11c-40c0-95e1-2a10d298e270	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/04/2023		Muy limpio el bano
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9d343c1-6758-46e6-a5b8-c5477cc5dc08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9946ca91-6612-4eeb-b272-e3dbd22f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9946ca91-6612-4eeb-b272-e3dbdde22f3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes	Yes					
141822bd-3d71-4ebf-bb4c-0287e9b22789	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
d0081cf3-0ad0-4580-9ae3-f2376f774d14	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2a8f47f-704e-4cd6-87ec-3b117d9ff455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
190600a2-3680-431e-b0ce-7f183a128f08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/04/2023		Stinky	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5be4833a-f602-44a0-aff9-9fab61a737c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e0f6d16c-f124-480f-938c-bb1a4e949ec2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
11413670-cb61-4ee3-a782-131362c2d292	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a313eb0d-a808-4bd1-9925-1c4eac204d97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ac1f76f-8b18-49ac-83cc-6342eefeca46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6a95cce3-bb63-4916-8ea5-7be3b4ef8b5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5091e72d-f634-42f9-8d04-4d8aa8425749	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3decb292-d7fe-4c81-94cc-707f81664c0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8415fcff-7dce-4008-93e8-5035129f74af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:07:00	TRUE	FALSE			en-gb	17:07:00	06/04/2023		Dirty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0d91b915-8cc2-43d0-ace7-e63fb4c26d88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
caafd456-54c4-41b3-b5de-52a7e84d71bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	06/04/2023		Gross	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes	Yes						
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
18258b2d-ed4b-4471-8f74-05beec784b50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
dbd48066-fb10-4c49-b41e-be0aa46c2e65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
19376ada-dd1f-46c9-b380-42fb0eacd289	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/04/2023		Fantastic	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
661c8f73-018e-4b7f-b123-586a14179633	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
661c8f73-018e-4b7f-b123-586a14179633	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e7e8fb87-e069-47fa-ac56-2c6eced8ff8a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8b258a1-f2ac-4a76-a9a6-adeeabf7d2a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ae37ff0-c258-4605-a414-239263381323	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
83466dd3-3c12-4892-9d24-e135d7cd72fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
75996349-11a8-4efb-9bb2-809d63fd840d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7b00fc9d-879f-47ff-ac80-0a3e5cd5abb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
c99cb21a-81e5-4651-afaa-a64e6deeb4ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
531d49bc-9a63-4a1d-8a86-cfda2faa74f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7365fcee-1ae4-4322-a016-421151f4b7fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7365fcee-1ae4-4322-a016-421151f4b7fe	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes					Yes	Yes				
68e2386e-76ea-4196-986b-682dc033ee72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b85115d9-8ca2-4aa6-9fae-9bd1dd330b18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
97223673-dffb-4dfa-b5bd-cfc9ce3047b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a90d482e-b30a-4c5d-8aea-f174b0741d55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d51a2578-96a2-47fc-a1e0-312e07d1087d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5f0ffc96-1fc6-4457-a7ce-06699eff5b0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/04/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f0c81855-fd38-4de9-96c8-6bdfa5c6f9ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
adf20440-49e1-4ac8-9c04-b727ecefba02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:38:00	TRUE	FALSE			en-gb	19:38:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2427315b-885b-4d54-9701-17a517143712	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f560577-9a4b-4d04-a5ef-2e187e9d460f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
63029ec2-8ea7-4b36-905a-ee4c442db007	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:49:00	TRUE	FALSE			en-gb	19:49:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
da316b2f-689b-4435-813e-70f36e89192d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	06/04/2023		,jhggnj	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e844c954-d079-43c3-a3f8-26d32e03548e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2d155158-1252-44ee-9228-8e65257c589d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2617c672-2224-4ac3-9c3a-b4da1cf1fcb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes	Yes	Yes					
c45abc4e-49fc-4792-83bb-5ba7f5394b27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c45abc4e-49fc-4792-83bb-5ba7f5394b27	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes							Yes	Yes			
9ff61ce7-4b22-4197-b719-3a4187d638b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/04/2023		This bathroom stinks really bad
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes	Yes	Yes				
8d9bfb79-d150-4bb7-9b8a-3d8f3d14fcdb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
e45e64b9-ecdd-485c-a8e4-42adfc45b30f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
15f577d6-0b6d-4099-bafc-bb2040a2ba31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/04/2023		Ok
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f42aed3d-756b-45c8-adc5-4b76ebdb8fa4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	06/04/2023		Horrible	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c5776873-b1e6-4163-a167-a33a8fa7fc51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:14:00	TRUE	FALSE			en-gb	21:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
2f066bf5-4e24-4d25-84c3-10f50d004fbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a778cc84-354f-4ad9-a973-277ec568056e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6b59ba2-3504-4301-8e45-9aad8c562d39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4022401-d409-4844-8092-dbabaafcd438	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e8c26626-49f3-46ad-ad10-33b2b300e2aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Of1968ad-6a98-4da9-94c6-4b34793d6fb6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2335e7ef-2833-45da-bfb1-e74a3358aa78	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ee92a85-7e4a-412d-b9e8-64af86aeaa92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cebe891-dcc6-4f53-9266-8c6feb2011a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
09e86aa9-1488-4804-8faf-07d9877c83d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
782e451e-87f9-42d8-81df-f79c5fa1a4e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:57:00	TRUE	FALSE			en-gb	21:57:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ab49a85-cafb-4d5f-bb1e-a032c6044ef4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:58:00	TRUE	FALSE			en-gb	21:58:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
04b6e50a-6309-42b2-bc6c-04e8ee53e9c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
af9bcf51-1eae-43fe-98bc-43ef1ed56349	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e7df6993-aad5-4618-b985-bc08e89161df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
3ce6ab41-8bd6-4140-8a17-cf7f8330c6ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b623a23e-f847-404e-a0fc-c890d0e49696	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9ca11c79-9240-4702-bb1b-64449d854c65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
233ae0fe-d60e-4a15-b28c-615a99e76988	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e71da7ee-722f-4be1-b816-5e5d88d5cf4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
24840675-0c3d-4537-a408-75aba4610a79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:32:00	TRUE	FALSE			en-gb	22:32:00	06/04/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
24840675-0c3d-4537-a408-75aba4610a79	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes												Yes					
e444e95b-d303-4edb-b57f-4165db071c8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:59:00	TRUE	FALSE			en-gb	22:59:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
0d97dccc-e933-4b40-88c7-8a503f1766a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 23:22:00	TRUE	FALSE			en-gb	23:22:00	06/04/2023		Bueno						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
fbcca1d0-ba30-4240-9690-3bbfd6b6b5f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 23:35:00	TRUE	FALSE			en-gb	23:35:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
2f7936af-747e-4c98-9545-585e8b68aff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 00:27:00	TRUE	FALSE			en-gb	00:27:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc0cef64-00c7-49cd-b673-c97666feed94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 01:09:00	TRUE	FALSE			en-gb	01:09:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bd3cb9d-3711-4321-a938-11a838b5317e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:03:00	TRUE	FALSE			en-gb	02:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
294057d1-b0e1-4558-94cb-b2c87799099c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:11:00	TRUE	FALSE			en-gb	02:11:00	06/05/2023		Very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6c8edd2a-1050-4974-ab47-2281d743d42d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:12:00	TRUE	FALSE			en-gb	02:12:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
19ee92a2-f6a2-43ee-aa5b-a06bdd3ca892	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:18:00	TRUE	FALSE			en-gb	02:18:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be468fa9-7f53-4204-a0ae-f8bc7fc7c00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
be468fa9-7f53-4204-a0ae-f8bc7fc7c00	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
											Yes									
19071ad7-b0b8-4584-918b-09755f9e89ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:33:00	TRUE	FALSE			en-gb	05:33:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
48450c4f-ce13-4e89-86ae-1c71f34d011e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:34:00	TRUE	FALSE			en-gb	05:34:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d01a64cb-ba2b-4a99-b5a3-059370d50030	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:34:00	TRUE	FALSE			en-gb	05:34:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
438f473e-626b-4375-89e1-fa51aaa57c3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:41:00	TRUE	FALSE			en-gb	05:41:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
236829a9-3b2c-4b71-bd19-eae68be81575	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:01:00	TRUE	FALSE			en-gb	06:01:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ef5b705-9f3b-439e-9743-717f0b128540	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cddbdc49-c972-4cf4-ae5a-ee5e1aa49149	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/05/2023		:)
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ac486296-3acd-401f-9c81-0568e10e6b84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:20:00	TRUE	FALSE			en-gb	06:20:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7f23740-1e99-4f1c-91c8-b1a660b83aa6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d9bca8f-21e3-47b0-9418-72d5694a4fea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	06/05/2023		It was soo good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0f354925-747f-4d9f-9510-2745a8ce4870	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/05/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ca28f622-25c1-4c17-97f2-b6dd1462ba44	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
840f309c-5faf-4ef1-ac04-38c5c69044fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
64a87ec4-f685-465f-a01e-143fe0f9edea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db79fada-4b27-40d6-8c66-1deaa44b4aa9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6ad26428-d6d1-4932-a21e-188e0863ec60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
183b66bd-1e67-4509-b5af-31f311a22de7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
183b66bd-1e67-4509-b5af-31f311a22de7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
717124c0-f4c5-4d5a-8f92-6a1c0724bd85	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a2952900-52d9-4013-b2b6-edf35d373752	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
43bca287-4ef1-4e09-b0cb-2577da1e4782	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8f84b02e-2666-4d7c-931f-0ad45b32e5ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
96613d46-cd5e-406f-b352-69a86be46a01	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1c61aae-2e0d-47ca-9d3b-8fd2c699608b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e97610b7-3a8a-4edf-b4e0-3b5a39e99dc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea94a2ad-6ad9-4213-9c42-fcec60615621	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b3db931-61d3-4700-a790-c16602f3d0b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c58a3f6a-f3de-4fca-bb6c-ed8fb15a7b89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/05/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6c410dbe-d601-47b8-8aca-a9d74e37cf46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
885f1003-111d-470b-a694-b12cd1bae222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0a521180-f40a-4d39-9b7d-caa8e8946b5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/05/2023		Sucio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
8fe8f058-bddc-4316-9e01-6d8e2bf0dbc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
033a0139-1465-4d0b-af58-8437a857863a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b1fb7b4-8c02-49f3-a86f-716c02ef40bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1bffbec0-4c21-4026-933f-d5e3f2041c3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/05/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9625897a-39d2-4d72-9c12-4a9dc1d391a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f18e1ec4-cce5-471f-b365-3c095f44ba6c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes									
f9397ae4-2c33-4aab-abef-eec8d98fcbbf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e1105f8-42ce-48aa-96af-040b422618dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:20:00	TRUE	FALSE			en-gb	08:20:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3bd45eee-e945-4284-8f31-e4e5c44564c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c1dfa33-6987-4869-a25b-0bdf6359fb07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c030fe2-8127-4a68-93d0-c203dd62ade8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes			Yes		Yes		Yes						
7bf2d19f-ab80-4a03-883e-ee293fb29791	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d378bdac-abc9-4dc9-adca-d6b7a1b72e51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be92c385-1267-4b82-bbac-308341656acf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1cacfd6f-2ef7-448b-9b69-26804503aabe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
67942b30-ba34-4e27-949b-dcd43f43febe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e90b642a-c7a8-4da4-8052-2e5234225933	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
9311aaf4-88c5-411f-b347-846ffbcf5502	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c918876f-b242-421c-af29-7bbaea4d6032	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c918876f-b242-421c-af29-7bbaea4d6032	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes				Yes		Yes				
5412cb06-3892-49ff-bf57-d83584f1eec7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
300fe02d-9890-49dc-bc26-a5d145f8dd95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2cd31d6e-e54c-42ac-91a7-6d43ee48c44a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/05/2023		"	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes	Yes										
b84e78c3-ff8e-41ac-90db-40ca516df3b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
b84e78c3-ff8e-41ac-90db-40ca516df3b3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes				Yes						Yes				Yes			
68391390-4e1d-43a0-b389-017bbe214388	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
6307790a-733b-4353-8e65-eb46b8c88546	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
91fdb98d-ab73-4977-a1ba-8a710798a101	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
767d44ec-3eb5-4f68-8c64-59b69d5ba0ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
5309cb86-c402-493c-b4b3-d9f279f2f4d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
037e6617-e5dd-4f36-b08a-0fff6942e959	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f23c5d65-faf6-4ffe-bb46-59e9208e8c60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9bcded65-efb2-4426-9da9-ca510ca9179a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a95f0d75-52f8-4393-94be-af18c4b6c23e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2edc3e5b-04b5-448a-a68e-5779e713481f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
185eced6-ff47-4dd9-a9d5-9f73429cf866	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													





### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4b27c42c-76cb-4104-9536-5b680fa4bf6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
513d0faf-591f-4ffd-95c3-1d36a45f3a9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28c6d240-7cf7-44b2-bf07-29656744da83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44b36605-c214-4918-bac0-a671559d6eef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5b6447bd-4589-4e3a-9e82-f2c32a865c41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3cdfc989-6166-4ea7-83de-087e1c56b10a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f08bb365-0dc6-438b-be45-81a8e5d1b194	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40aceb40-9552-4a53-b47e-492e1caed358	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c1b4fc1d-e171-4639-9802-4bd6bbe4cc11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	06/05/2023		Disgusting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							
2222385-afeb-4bb9-a361-57218f883439	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3d92122b-fdf8-4082-aa3e-1e9b89a97ff7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
49e08f36-4007-498c-a10c-1e92c5fdb96d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6d82bf66-8b59-45cb-8148-3e0c8a82abee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e542a4ba-f71d-42d5-80ef-a54a72ae4688	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8092ae68-2704-4cd7-819b-ae81e360678b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8092ae68-2704-4cd7-819b-ae81e360678b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes			Yes							
						Yes		Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bedf2b74-0953-410c-ba48-931b5142418d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81d69716-f133-4af1-98de-16e48ae0dee5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c07003cf-8744-483c-baf2-3c68bc008d23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:03:00	TRUE	FALSE			en-gb	15:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1408385-f952-43f5-84a8-378f5d9061ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
634538e4-2b8d-4a29-92f2-aa67ba37393f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a64d410-15c4-4cff-8d80-8cbbd95aa269	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8a7849ab-f49d-4533-a544-c0f82e02eb7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8ea3cfa6-2d46-4a56-8da9-2727b630d0e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51ab99fa-b49f-4f73-9434-54b5a175238c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/05/2023		Muy limpio gracias	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
21e1d317-ddd5-44bf-8ea8-05c07a240d5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b89a71c-8ba1-4313-9081-9247e4f6cd97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
81dcadb3-c69b-4c2b-ae78-28451fb51cf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
72b1a84d-cbd4-4c85-8c7c-aec485d6d20c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
4ceb83eb-cc04-4307-8821-67cf3c4b91dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes					
5d9c6d3b-d62b-4ed7-aa7a-a69bbc74981a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e040a4a3-ad8e-4a3e-9045-90e0ecad8583	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7f7d6da9-65b4-44f5-9294-4cbde4e92a95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ec645c80-de94-4dba-9484-08f3290b030d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5f9859a7-f74b-4168-8390-ae26a621c437	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1f60bc8b-46e3-40ac-8bb7-789d66633e6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b70311fd-a337-4a13-8caf-cf3cbdf11f78	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
40d213ce-f1ca-4f05-949f-e8d20dfb448d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6cd110b4-8fb1-43ba-adbe-694470d7ab30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
16ec66b1-f7e9-43cb-a362-fa991f31d496	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/05/2023		Redo it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
16ec66b1-f7e9-43cb-a362-fa991f31d496	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
					Yes															
98e95551-e3d0-4f0a-92f1-33d0dc7916dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
98e95551-e3d0-4f0a-92f1-33d0dc7916dc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
d290b42a-c8ec-4bd4-a6c5-66cdc9dd8909	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
d290b42a-c8ec-4bd4-a6c5-66cdc9dd8909	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
			Yes												Yes					
2c837df6-7d3f-4795-ac35-4286c9daba94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
2c837df6-7d3f-4795-ac35-4286c9daba94	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
					Yes		Yes								Yes		Yes		Yes	
d34d84cf-07ed-4437-beff-050c77749396	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				
699d1dfa-fb53-482b-ba16-4719a4aea5a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
9de65f07-7631-4022-86ba-9d739fc81450	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
244cfcba-5478-406d-ae7d-068c5abb78e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 17:24:00	TRUE	FALSE			en-gb	17:24:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1fd39fb7-862b-4262-930b-93242d2309e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	06/05/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
36ee56d2-c660-48bc-ac64-3c6a89ee8683	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
			Yes	Yes					Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
984cf917-3c1e-46c3-8564-f89b92c85aa9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/05/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
532e06fe-b476-40c3-88d4-70b7505cf46a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0473811-2ca7-4806-a685-bc19f0d1173d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	06/05/2023		L	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes						
456214b8-05d9-45d0-bfa1-739a3d42f150	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/05/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes	Yes				Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
d7ffd0af-5b1c-4375-8817-6c20cb4aed57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/05/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes	Yes	Yes				Yes	Yes	Yes							
b6b28f57-d9ad-4bde-ba27-fd2f5c53fada	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	06/05/2023		Nope		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes															
fdb09372-93dd-4f49-a64c-a5b9054929ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/05/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
			Yes				Yes		Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7c8124f6-4a68-46b9-a4eb-38b7aa0e9442	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c20f0de1-8945-4e5a-96a4-79c728d0ff3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
de72dd01-e424-449f-9beb-cde8821e1ff9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/05/2023		Good cleaning is good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
fd87380d-e8e5-461f-b122-e15cecc36ec6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
66c98eb2-4adf-4d0c-bdfe-db0fe094d86d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
ebd89eea-01ce-42ee-b78b-b68f9830b043	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ebd89eea-01ce-42ee-b78b-b68f9830b043	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
befc6607-3e7e-4ba5-acd5-ef07cf64fdc2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
47367ad3-cbec-466e-b442-aa8c1cc12707	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes						
3ee7149e-2325-4675-9899-9dfd94766c5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3ee7149e-2325-4675-9899-9dfd94766c5b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
2e72ed82-f97b-434f-8c65-1edf9b56d5a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
dff3e26d-bc19-4d95-8f89-6e5f06cfb8e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ed09c83-830a-4247-8248-5007c3c9c96c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a277add4-2f0d-4159-83c9-5ca22de42e8b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/05/2023		No huele bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e89bcd38-df30-40cc-b098-6f77b43a3df2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9987e6f0-4d72-4c00-99db-8c8cbc2fb97e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
baeec266-38ca-4cf1-9205-ffd8d04594c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/05/2023		Hi	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3e594dac-6984-464a-a91f-6277534eef51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
3e594dac-6984-464a-a91f-6277534eef51	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																		
								Yes																				
34d98aff-2779-4a1b-adf2-796caa0b2630	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	06/05/2023																
	How would you rate this restroom today?																											
	<b>Average</b>	<b>Good</b>	<b>Poor</b>																									
	Yes																											
0538b7cc-f70d-419c-a139-c4a30d5ca98c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/05/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
4ed12125-ac1f-46b9-a20a-e2c222df51aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/05/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
															<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes																					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
37268503-fdec-4687-b5c2-cfaf930fd26b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
63a7521f-8c77-4b5b-9834-ace88e1290ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
af8df832-6b8d-41cc-86c9-421f152dced4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:25:00	TRUE	FALSE			en-gb	20:25:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6bc3f839-a2bc-4ec9-a6e1-0b2854277192	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6bc3f839-a2bc-4ec9-a6e1-0b2854277192	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes								Yes		Yes		Yes	
0601e67f-97d0-4429-b84b-90b1554e5745	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
2b3c4434-214e-4bf0-9496-dd611f12d2fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
3fadeb0d-2e79-44bb-b106-8d6e05001fa0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/05/2023		It was nice and clean						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
e3a6ed47-c8c1-4dc0-a5db-9f2f3a0e0e17	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4eb734d1-75ec-454f-ab4c-0d762542be50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6200edbb-384d-43d3-9e8f-b900874ea447	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e700e002-e207-4a46-aa36-3c8478372a9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ec9241a-d5bb-4f69-bd0a-7dda4c6c0405	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ae82a54-9944-4460-bdc8-165409d62886	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25f9c0e9-15a5-40f7-8339-d9f7aa451979	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
25f9c0e9-15a5-40f7-8339-d9f7aa451979	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
82037ddc-d58e-4077-acac-d81ae4725059	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
346e0c39-0f82-42e8-abbb-c1545e9232af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/05/2023		I hate it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
ef0c72e9-2242-4ab4-bc29-83be1d57d468	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/05/2023		This airport sucks. 2,5 hrs immigration for us citizens???????	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef0c72e9-2242-4ab4-bc29-83be1d57d468	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes	Yes	Yes				Yes						
c0ee1b1c-874e-4e30-8a15-26f41fce6d5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 22:19:00	TRUE	FALSE			en-gb	22:19:00	06/05/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b1c8a3a-0735-4ab0-9d49-c89b513f593f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 22:50:00	TRUE	FALSE			en-gb	22:50:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes	Yes							
88a885c2-55c9-463b-89af-2e87a54e358a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 23:38:00	TRUE	FALSE			en-gb	23:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
3b60e94f-cf80-42f4-81fd-b19da11b77e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 23:44:00	TRUE	FALSE			en-gb	23:44:00	06/05/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
88b49bab-2885-4294-bcf9-5ed5f7d2d76e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 00:35:00	TRUE	FALSE			en-gb	00:35:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
efd08f8c-aa3d-4f84-822c-c625ed8379b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 00:43:00	TRUE	FALSE			en-gb	00:43:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
9b353bc0-5cf6-44de-95c4-4fb94d7eaf7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 01:04:00	TRUE	FALSE			en-gb	01:04:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
50c5a3f2-95c0-41cf-9a05-390944167e3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 03:39:00	TRUE	FALSE			en-gb	03:39:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
50c5a3f2-95c0-41cf-9a05-390944167e3c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
4b123e0d-9fa0-4002-90ae-ca5d6f2cc2ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 03:42:00	TRUE	FALSE			en-gb	03:42:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6a566573-971c-4382-9f6c-74c2e121f510	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 04:02:00	TRUE	FALSE			en-gb	04:02:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9daf6c78-0994-4198-935e-4611d026d928	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:05:00	TRUE	FALSE			en-gb	05:05:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2cfd52b8-3c47-4468-bc2b-06ad44829a4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
56ccdeaa-bb0b-415d-a4cf-ca7b22d66ad1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fd14e754-bfd9-4337-b650-fbc7fe9cbb22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51f472fb-0cd1-401a-83f0-42009e8b91d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0a6cb8f2-788a-4c59-8b0a-f80f73369610	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:52:00	TRUE	FALSE			en-gb	05:52:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
19b86273-b94e-44e5-90c3-b940ab0cdd7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aac18fd2-263d-4fbf-a472-abf83aac3fe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	06/06/2023		Very rude cleaning lady
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a1159568-c93c-47e3-94c5-84c1bae8e8c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
10a620aa-32e6-4720-8cd3-313da948f679	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
93a9afa5-e850-4d25-b336-867606976a28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
24e2c77f-a43a-4508-a4f5-746e2cdcc410	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b6c9b81-b2f5-4c6d-b4cc-46591898586b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:03:00	TRUE	FALSE			en-gb	07:03:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
edd1f826-2db7-44ec-89aa-065dcea6935d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6190f14a-1612-437e-8bf9-b64d4f0de633	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2612326d-6fca-4907-87b1-3e332d66d86c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9361274e-7713-4df0-927b-d1abb80d6e3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
72796c61-5653-4f18-bfcc-96e743b15ce9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0ec13c98-d5d9-496c-a980-7fbfb2bfdc46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d44eae5a-282e-4c06-b5b6-6995c9741554	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
39be3453-3f1f-4712-b3ce-edaf4fd8e323	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:04:00	TRUE	FALSE			en-gb	08:04:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e3f17d7a-9ba7-455f-86a8-cb9f8fff05b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2af89568-a282-49ad-937e-d2dc5c81cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f66678e5-4b66-4d52-8705-6d8df2a1fbb5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea5eaecb-62b5-4303-bc10-596b2dd3ba31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
680df655-bd94-475f-9110-d9ca9485e5c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4bf102e-4c5e-47f9-b324-153901feec1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
99f274d0-3d7f-4233-a6fd-d812ad37d473	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8641be26-02e2-49e7-a410-b5bdb630a39a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8b7bc2bf-1aef-449f-a82b-a38bb6c20d45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
adb05852-d4c1-4dcd-a601-d3fa33014fff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
009b2796-9641-4ae6-a787-816a9ffbcd54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
33ec86c7-4125-4904-91bf-b04b3d7dc72d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
59ccfaf8-eb84-400e-9f95-f37345e0ada3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
64a7e4d4-5258-48c0-a81a-6c7e7fa692bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1b3a2960-b9eb-4dcd-ac8c-fa8eb723e311	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	06/06/2023		Todo bien gracias	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fe7125ff-93a1-4b2b-9333-e105750ceb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	06/06/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
62736bfb-90af-4827-b330-830efc902c31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c016bd4-ba7d-4180-8faf-8797fdc28400	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6358daab-c5cf-4a51-8704-ee4490dfe5db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ee651841-66b8-4465-b69a-b13867925513	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a912312-eee1-492f-a826-9b5846369fbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
caf5b804-1ba9-4a62-b50d-6ca60ab3aca2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/06/2023		Broken	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1ab3db80-4dba-4258-94b0-a22e41e300e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4b4ae05-f445-44c5-a402-eadf19598ba4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c588bf17-a9a7-464f-8022-0682e7a7c5d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ab7458b9-cc71-4e01-a3a2-bb4e0cb46016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
055b5cd0-f799-41ab-83cf-def234905191	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
365063a3-fdd9-4c8d-987d-c402a58d8714	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5523ae6f-5011-4ac3-afb8-2fcc2b01b302	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2fad3a1-e688-41f0-af5d-e76420bdc5a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/06/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b158864a-2f9f-4516-bf3a-761b9d1a50c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
339bfa31-fa6f-4c26-9bc8-037ca93fdf1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d66ef438-09cf-4e61-b013-772437d17191	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ce2685fd-c248-4b7b-a44b-9420fb82f463	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3c56242f-349b-4d0c-97b0-1f776621907c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f60c56e2-1420-42c0-8b3c-34d326f6de01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a42a9f9-aa5e-46cf-b6d4-ea5eb0d45532	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d90e620e-3971-46f3-8316-79970a75b303	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
44bc0133-613c-46ba-9f3b-b13380ebee6c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ac199994-7e13-42fb-8250-1e891e4f0876	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd82b60d-8bc3-47e5-9854-cf629fd4bb48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db60eea1-4969-4978-b6bd-5272c77382ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a187ff8-2d16-4b3f-a935-3404ad2a4128	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9265f0b3-7fcf-4d43-8abf-1a87cf9a4511	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b59b04b3-d846-47c7-912b-b376c32e4224	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7d588e6c-4bce-46c7-8dec-bbe918a18af6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eabb864e-412c-43af-bec6-10b11e3b34dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b1464dcb-28ff-447b-9043-dea96223028b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a7acd86-9349-4519-8d41-17f6cefd218f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/06/2023		Outdated and raggedy	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
684681cc-8d3f-4970-86e2-b48c0de6b6cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
55fd3ed6-9e03-48de-b2ac-5b881c4ef1a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7158f9aa-ac31-4110-a7a7-98f9dbb80e27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4ad1c4a-4b49-48f6-816a-15fd029949e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54daddf8-b5f8-436e-98b1-bb529cd77e8c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
08109e86-6b55-43eb-9404-ab16fa36495c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1d9f88ce-3991-4e5c-a5c1-3426e218812a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d10d3de0-f2e0-48ed-bc7b-a1bcc3d96284	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d7a1189-8fe7-427c-adc7-087223b178f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
4a531d9e-9b41-47d1-befe-00b17ef1631e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
80d23647-6ebe-46c5-9319-e653dc3b8474	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ce70e85-85a2-43f3-aabc-7800a0b474e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	06/06/2023		It was good	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d126daa9-5746-4057-a608-63e349f2b3c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes						
1a14f0cb-c77e-4934-9196-79988b602a1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0f02c433-9e51-4058-b575-b6f8453da1da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
946fab0-6660-4ee6-889b-6411ffd09913	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/06/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
aa64facf-6f34-4d24-af89-56f4e0bb44cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7ba9c8de-f3fb-443e-811b-0e59a94d377b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ecd4b967-1bb0-43a5-881b-79579716ad57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
bc283ce5-249b-408b-a3f4-558aae6dbe58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bc283ce5-249b-408b-a3f4-558aae6dbe58	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes			Yes							
c63c310b-7d9f-4618-a496-c491c2d487aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/06/2023		Stinks!!!!
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
095cee81-d7c5-4322-96a1-08a670b2e0b6	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
095cee81-d7c5-4322-96a1-08a670b2e0b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6626a98e-7d5b-49f4-abc1-8ba2a634b979	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
6626a98e-7d5b-49f4-abc1-8ba2a634b979	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment			
6626a98e-7d5b-49f4-abc1-8ba2a634b979	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell	Wet Floor	Wet/Dirty Counters
															Yes		
324b97df-98c8-4796-983d-596f20eb04f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	06/06/2023		No			
	How would you rate this restroom today?																
	Average		Good		Poor												
		Yes															
0286822a-c435-429d-86d2-bc5113c19e54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/06/2023					
	How would you rate this restroom today?																
	Average		Good		Poor												
		Yes															
2f1a893e-8ef1-4f9f-97b4-2ad499cdc77e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:10:00	TRUE	FALSE			en-gb	17:10:00	06/06/2023		It was very clean			
	How would you rate this restroom today?																
	Average		Good		Poor												
		Yes															
c8059012-1f9b-47d2-b0c7-bee3c8a8b23d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/06/2023					
	How would you rate this restroom today?																
	Average		Good		Poor												
		Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3f852e23-209f-4ef8-92ed-b5db42a3d928	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:18:00	TRUE	FALSE			en-gb	17:18:00	06/06/2023		No
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
37313076-0cb6-472c-8757-28786ffae358	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
567a12d9-a642-4cd9-b9be-4640af798dd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
4e22ab30-cc0a-406d-bace-e501209155f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
5b118daa-116d-4a66-8285-40eaf94d8bce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
254148b9-723c-4bcd-ace6-f5193cd675ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a653878-c748-4df4-b913-48446a98e25e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6a448bf-136e-4252-a47a-7f9250994b0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c3c36e78-a4a8-4b26-8d3d-a743ea2ff166	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5676af7a-5723-418d-9800-bd1118333a46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1983744b-46d7-4bca-a55e-db381650902a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c0b273ce-6f09-4ab8-8316-3e79af1dc269	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6018d547-dd4b-4967-9ae0-853cc18ed746	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes					
d0fae78f-67f2-427e-be2a-f7ca167394c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	06/06/2023		Please i cant breath it stinks so bad in here.
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes					
5b5bb968-40df-4636-bd65-fb0abba9b965	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
763eedc6-5815-43f8-be0e-6275106c6cb0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
e4c5590c-e966-4762-a4dc-72f77dcf9c6d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
bfde0aa3-72df-4b0f-b86b-4f012e02ca9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
492264e4-5d5f-4e42-98df-ffc7fb210be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:38:00	TRUE	FALSE			en-gb	20:38:00	06/06/2023		Good														
														How would you rate this restroom today?														
														<b>Average</b>	<b>Good</b>	<b>Poor</b>												
															Yes													
a5dda7d1-ca0c-4c5f-8106-498ba0812309	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a5dda7d1-ca0c-4c5f-8106-498ba0812309	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes											
90a42d26-3ec2-4e0a-8940-aa0a176aa8be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
f23ac9f1-b2b7-4a80-b789-4db23003097e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/06/2023		It stink
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
879e4a7c-d827-4209-ab9a-cccdef21c865	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
879e4a7c-d827-4209-ab9a-cccdef21c865	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes										Yes							
d2c1b252-90cd-4ee0-ac30-3c92b3e6fcbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
52bee864-42f1-4fa2-817f-4708be61b9b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
c3ca02bc-0934-4077-ba9c-bc09e3d23fed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:14:00	TRUE	FALSE			en-gb	21:14:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
dd85a485-39c7-44de-88ab-d24b99ab381b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f77f4d1b-25ba-4400-87fa-047518444611	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f77f4d1b-25ba-4400-87fa-047518444611	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
411def09-3491-4923-856f-3d5b6fc9757	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
21e376c8-fbbf-47ae-801b-c7fa009abe4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:41:00	TRUE	FALSE			en-gb	21:41:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
25e0113f-067c-462f-8dba-79dca83536f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:44:00	TRUE	FALSE			en-gb	21:44:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
26cbf5bd-d6ad-4f5f-b198-cda975e7352d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b09812c5-f072-4b54-8709-b6b15b1a665b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
217468a0-5360-4277-9793-da20938ac902	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6f34ac2e-1200-4998-a33a-51dabbd0459a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:06:00	TRUE	FALSE			en-gb	22:06:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
03d9d778-26bf-47c9-b9a7-9401329aee11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:12:00	TRUE	FALSE			en-gb	22:12:00	06/06/2023		Muito sujo e sem sabonete	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
03d9d778-26bf-47c9-b9a7-9401329aee11	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes						Yes				
ce83a771-9c5c-4832-b4e6-2b2f6bf84c5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3dc9943a-435d-4974-910a-d9530abb5a5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
2d9d3e67-f859-4cde-825c-0b84f6f57786	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:27:00	TRUE	FALSE			en-gb	22:27:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
f2e2de67-940c-42fa-8b71-eb3fd04f19a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	06/06/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes				Yes	
f4578abb-8f6d-48a6-aad9-4512bf4cb5c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:32:00	TRUE	FALSE			en-gb	22:32:00	06/06/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes																	
27eb5c8b-f05d-4aa9-9f4c-eee57ae48ba0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:49:00	TRUE	FALSE			en-gb	22:49:00	06/06/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
ee9f64b4-e867-4d09-8aa3-d1769b8c35f7	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 23:56:00	TRUE	FALSE		en-gb	23:56:00	06/06/2023																
		How would you rate this restroom today?																										
		Average	Good												Poor													
			Yes																									
06652ed6-4f08-4bcc-b3d1-f28f7dca712	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	06/07/2023															
		How would you rate this restroom today?																										
		Average	Good													Poor												
			Yes																									
fcd5a53f-709c-4899-86d3-17bdb5e028b0	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	06/07/2023															
		How would you rate this restroom today?																										
		Average	Good													Poor												
			Yes																									
cc9c5343-fb70-431a-9a2c-8c44f144235b	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/07/2023															
		How would you rate this restroom today?																										
		Average	Good													Poor												
			Yes																									
1869c008-64dd-4475-8b0c-12b363287730	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	06/07/2023															
		How would you rate this restroom today?																										
		Average	Good													Poor												
			Yes																									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7b4e5def-7c6c-4739-9299-e470b73beb66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:00:00	TRUE	FALSE			en-gb	07:00:00	06/07/2023		Esta muy ordenado y amable la atencion	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e49ce7e2-8850-40fc-8574-70476a64657d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:02:00	TRUE	FALSE			en-gb	07:02:00	06/07/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c4542a05-9bab-4529-a1c2-82c4132381d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:13:00	TRUE	FALSE			en-gb	07:13:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
330d132a-1232-49dc-9611-2ad91571f217	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ceafbc-4a4c-4159-875a-b9dee4a1e3e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ba246a1c-ac07-4444-ab42-2bd89312bb83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/07/2023		No everything is goog	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ce7319a-265f-4398-a996-a33948539f0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes		Yes											
cc812217-1634-4e6d-8008-752b51723204	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f7cf3121-d270-4af6-afa0-ec7055e4cc3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/07/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1bfa9458-6b66-41cf-bcec-69641b1f93c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/07/2023		Dirty	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1bfa9458-6b66-41cf-bcec-69641b1f93c8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes										
f7403725-ef1a-464f-b0d0-6536f7d253a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/07/2023		Pee all over and dirty
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
eeba9378-4cf6-420e-8363-ee17f9eadcfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
06eea39f-79c7-4c76-bb0b-780680e2e037	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
efaf294c-a234-4ad2-ac01-13038719d1bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e757ea82-bee6-4e5d-8295-bfba9d7e40dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
316f69f0-5796-4379-8729-bd35ce011dc7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7047e3a6-67ac-41f1-a5e7-92edb4fcc285	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes							
578078c4-6d58-4b85-bb62-f06f8ee65eee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
345552c8-978d-4ae8-bb7d-2e1a27fd287e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
19f24c45-5d5b-4eba-8cd4-b1314610efcf	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/07/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
7de57143-6c40-4386-888b-594db4c01af3	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	06/07/2023		/	
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
7de57143-6c40-4386-888b-594db4c01af3	Gate D10 WRR	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes						Yes		Yes					
eb3c3eab-3bab-443c-aaf4-08d119d0041a	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/07/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
5d27dcf1-ca9c-4ae1-807d-f8e6af6816ef	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/07/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d8b89ee1-0f41-4fe2-b5f2-5fded1e9a078	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99766e1c-aa99-4328-90a8-e179cc1d875e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40419fc5-ed40-49bb-94cd-9c37f129ba65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1678209f-ce16-4734-b20c-5dbc8ea53fbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
9648109e-d2f5-4ce7-9cae-dec459362745	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
941784bd-dfa9-48de-b362-9b220f3a6e8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/07/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
78da4d72-d50b-44cf-81c8-1303764d240f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/07/2023		Clean sinks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4a8604e-614c-41cf-9cbb-36623132092e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89004ffd-de63-49cf-9b96-c01f253572ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
73ec3f27-5099-4999-a34e-a5bf5d094252	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5e302b07-14c7-43e5-9eb8-3fb863ed1fec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
efb167d3-8d59-4d98-9370-61178d44be46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fc78cfe2-7765-40bf-b0e2-3537250b2181	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ce63ff93-1b6e-44ae-8b8f-5a1a5598480d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2795556e-c651-4607-89c1-fc0d0597e5e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
180edaf0-fa6c-41c9-8c67-504ef7b1a867	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8c89ba49-d2fa-4ae5-b712-9486ce1a488b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/07/2023		Clean and nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5cf54ba2-4e23-4cb2-80aa-c67cfbe04bbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0e46946a-1ab6-420b-840e-cc54e281b136	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a92e933b-9c2a-4c3d-84c7-808be25d8f31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:18:00	TRUE	FALSE			en-gb	11:18:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3c55cbe-8157-49a3-8d30-1c351e1f3c82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f9e0b11-ede9-4887-9894-93ee3c859590	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	06/07/2023		Great job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bec17b0-8955-4710-9c77-ff68b8de391d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
09f9b9d3-8544-4090-8b29-39224b3908a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
86cfdb7c-6bfa-48dc-a559-d6e91c436d4e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
280a85d3-9174-4cc9-b5d6-d48fbeb7abda	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d261c142-ff45-41b0-acbe-4ee0e1c50445	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8952c1cb-ec01-4baf-9000-a9f6906b0f57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0cd72a08-e5d0-45e8-97ed-1e41d6b43aa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0b4b68e0-789b-4163-bb6b-2c5bd4aad2cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f4030081-4a2f-4226-9252-4745ed211e34	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fc550d90-7774-4ca4-8a83-3c938581b27f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4c687db1-6639-46c0-8cd7-f6716524430d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6a853c5c-5ca5-422d-9c63-983e6e82d737	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0d952bab-0c74-4978-aedc-595565a088ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
111518f4-c7dd-402d-b8c9-85e02b0b26d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9a9158e9-11b1-4153-8cab-b0cb98a000c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ec29e0e-7a0a-4855-8580-faf9a8bec6db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4f161d9-d198-44ab-b043-4abdf9503da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c7725ca-8877-4ac4-9b36-2fa53bc069f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c0aaa62f-a5dd-4dc1-91cf-ecf0a88776aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cbe5ec93-38e3-4bca-bdff-82ec16f39c21	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5bc4058a-29bd-4331-8a14-ec12cf73de9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f47bac88-99c0-4c27-ae87-f306f6d0a141	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7f6a44d9-27cf-4a5e-aae3-9d6b22f41340	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0ba8697a-0f25-4da6-8bde-a05cf7aab5fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d887ae-5444-4683-a239-65a983353769	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad32d9d4-2ae5-47f1-91a1-eacc5907174f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6ee4dafd-9d77-4841-ac76-d37bc856d242	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
076689a0-120b-4f26-a712-cb65de25dd0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d8ffb1-1162-4f0c-a83c-9919805ff8bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6a58591f-63ce-4552-a6e1-90676239f558	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4345841d-ff1a-4534-837d-2aa2ab51373c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
574a6b70-e607-4acf-9eff-63a16dbe860c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2f2a22a1-575b-4d6b-b8a3-fa241eab9c94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:45:00	TRUE	FALSE			en-gb	14:45:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4816ae05-9f04-4406-9684-f890dcd0dc72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7c888915-f08e-46c1-8177-5044b069d394	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3feed544-907a-4ac3-9d70-1c5b617f27e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/07/2023		N	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ba141522-be4e-41e3-97a0-3309dce027bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5d4801f1-aa5b-4180-8002-0465e8300c0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b67c8d61-9253-46b4-829f-9762783a375f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:28:00	TRUE	FALSE			en-gb	15:28:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4d94b370-323b-4fd7-a160-7e645ab88031	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/07/2023		Very dirty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e08353cd-fae8-4712-bfea-8df297cfdbfe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
57362c3a-85e0-429b-832a-3b7ad07c24a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
71ecf69c-4cd2-4333-9d13-b8a6b196dd61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
14fe5641-c280-4377-8db5-73c482328c03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
1d9d39c8-6326-4a36-885e-f5ff60c9fbee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
dbbb0736-ad48-49f0-8f68-e05b40cba63b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
720d73ba-5b5b-4097-b6a2-b6ef0e9632ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
934079fc-44c7-426e-af99-31dc760080ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40f0b1b4-cb2b-4970-8d7c-57e96c371d9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4940963e-c21f-4ea0-ac69-c64130e35985	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
0b520f56-047d-41c0-b4bf-86da1b860ff1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9cbd78e8-7f09-4698-846b-92984f33dff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e3d3659e-a6d7-461b-9596-16e44f734123	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a7d09c0a-c332-43aa-95ea-8c40168af0bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bf5c638e-94b9-458c-bf8b-b83bc5e7f6cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b84dbd84-d600-4ecc-9e08-c964ce34aa4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:25:00	TRUE	FALSE			en-gb	17:25:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
53b9c63a-cb27-456c-b2dc-90e2e257c25c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
24fb922a-8add-416e-b2b8-17f9ea98ecd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
984c6167-53f7-4aec-a6c4-ea7e0d53fd57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b373b33-a6be-42cf-9b3f-d15aceae168d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a15f6ff-a00a-4dce-a59b-d67f3ba15759	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/07/2023		Awesome service they evem helped me wipe
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b42c4bd6-e180-425f-9602-140eddad45f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:31:00	TRUE	FALSE			en-gb	17:31:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
9fe21983-3cb8-4721-bac5-9713aa5bdc64	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:43:00	TRUE	FALSE		en-gb	17:43:00	06/07/2023															
		How would you rate this restroom today?																									
		<b>Average</b>													<b>Good</b>		<b>Poor</b>										
															Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>									
						Yes								Yes		Yes		Yes									
de1ee499-8923-4cac-b623-03469840f25c	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:57:00	TRUE	FALSE		en-gb	17:57:00	06/07/2023															
		How would you rate this restroom today?																									
		<b>Average</b>													<b>Good</b>		<b>Poor</b>										
															Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>									
						Yes																					
e803a626-02ab-48e3-add2-c8fec62f439b	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:11:00	TRUE	FALSE		en-gb	18:11:00	06/07/2023															
		How would you rate this restroom today?																									
		<b>Average</b>													<b>Good</b>		<b>Poor</b>										
															Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>									
						Yes																					
7f048325-13bd-4734-b530-6f897519b3db	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:40:00	TRUE	FALSE		en-gb	18:40:00	06/07/2023															
		How would you rate this restroom today?																									
		<b>Average</b>													<b>Good</b>		<b>Poor</b>										
															Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>									
						Yes																					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1c47bac8-6dde-4c28-aa43-da898890a5a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/07/2023		Wemdys	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b9594f6f-4bea-4d3c-beba-e6a44e19ec52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						
22700b61-38c8-4560-8ede-f959ec5e3a8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5241674e-9292-48ea-9d2d-143573d8c418	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/07/2023		Miami heattttttt	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a93a3587-b354-4e46-b556-9b6c85fd1502	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
46fed5c6-aaa4-4931-9357-76c512e8aea3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																												
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																	
			Yes						Yes																			
244abf18-f681-46d2-b5e1-7e5d0c2121ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																												
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																	
									Yes																			
aabdfa0e-32a8-4897-a97d-fd5d5a5ace52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																												
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																	
1a33ed01-78e4-484e-a4ce-342877166b9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e0f868e-b09a-4c56-a958-d03ce5db40eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66bb1491-6c67-4a1d-8910-e2ed171f2570	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0374e6f0-fdc6-4f1e-a04c-d597375f7fcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9aa6ba1f-e844-4951-94ce-1770d7f3b1a9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
9aa6ba1f-e844-4951-94ce-1770d7f3b1a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
df4b059f-b2f7-48aa-9f86-bcd80d902ce4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
9f8beb64-ebf8-491d-87d5-9deda72b3899	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/07/2023		Bad														
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										
7d8a7a33-1369-49fc-911b-8f85f7cbf552	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/07/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																												
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																		
							Yes																					
8b0e2e89-2abb-4180-b469-9fee429f976b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/07/2023		Muy buena atencion														
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										
f0e2e697-12f1-4245-9ce7-6653e2dd4491	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/07/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										
02dc3aee-3a8d-49b6-aae0-6e525effb49b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/07/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
936788c4-9a3a-42a1-af57-67e9a7c6673e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9b5bb3eb-b264-4f89-9307-9701a4583680	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes								Yes	Yes					
b76c991e-d5bc-416a-9330-3947255ea781	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
459418f7-dec0-43e9-a5be-38fad66765b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
633cde84-e840-4487-9c90-b26841fa11d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
633cde84-e840-4487-9c90-b26841fa11d0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes	Yes				
d1e97ed8-df96-4345-884f-aa8312c2d22a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9701e1cd-5e7c-4bee-a3b8-5ba93d28c93f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/07/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a62f70b-aea4-42d6-addc-dc957ce82c19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
f7836e91-68f7-4934-a14f-f1900d289d20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f7836e91-68f7-4934-a14f-f1900d289d20	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
				Yes			Yes								
9f2496ac-5e21-4f05-b2eb-a2a6359164f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	06/07/2023			
	How would you rate this restroom today?														
0df60b98-02d5-4f8f-9169-1265bfa1cd28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/07/2023			
	How would you rate this restroom today?														
779683f7-9979-48f7-b319-e507ac160897	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/07/2023			
	How would you rate this restroom today?														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
939feec9-bcca-4b4c-aadc-7c008cc3b8f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/07/2023			
	How would you rate this restroom today?														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
939feec9-bcca-4b4c-aadc-7c008cc3b8f9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes			
85f20161-de8d-471b-afce-479529c9ab48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
43733cc9-fbaa-40f5-9997-4d9e71959278	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
691bff63-8984-4122-84a6-6ac388dd36d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
56e832ac-290a-4fe1-90a7-ca49b573c5bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
dcb81ac2-5291-45fd-9cb2-f5705103405e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dcb81ac2-5291-45fd-9cb2-f5705103405e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
ff12c238-6631-4b79-bf33-9010d918ffd6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
8610ebd0-15a4-4a6d-ab6f-b4bc2d563f4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 00:34:00	TRUE	FALSE			en-gb	00:34:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
dc4f4a86-25a9-444a-ba8e-7fe7bc3dcf31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 00:41:00	TRUE	FALSE			en-gb	00:41:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
2c05c232-df7f-4bdf-9cca-001e66f4c721	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 03:00:00	TRUE	FALSE			en-gb	03:00:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4dc64c74-4eac-422e-b1bb-2dc35f9b07ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 05:08:00	TRUE	FALSE			en-gb	05:08:00	06/08/2023		Keep up the excellent work	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7ef7b0a5-4088-46b8-ab34-43f245c08180	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 05:14:00	TRUE	FALSE			en-gb	05:14:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
dcef6ab8-f53f-4bdd-a90d-093b8c6498af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6889acd4-38e1-4d16-9f48-3d270aca0bb0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d31a9c55-5bc4-47aa-a52d-ad651aa8120e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b0c3f94-6874-4079-9a17-541e10059fe0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
709db156-14b1-4148-92a9-cce108a0cc12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:30:00	TRUE	FALSE			en-gb	06:30:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95b9c3bc-31ed-4e17-b5e2-323ecc9e5eb7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
661224dd-a95b-497c-9c54-eddf152e72d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b853293-ed1f-4383-8636-0a6c94d23f68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bf8290eb-8d53-492b-bd15-09d7040812bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d1559deb-13aa-4943-9b1d-cb89907da942	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1ad2bfb-be50-41cc-8a09-b9408bd304f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
927b112a-c85c-4db0-9968-75d0eeec2df7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/08/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6e73fc7d-1a6b-44b6-b1da-f405b865a639	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c67539e-881a-4fc1-a424-1a3b05e08fb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7c28b5ee-4615-4af5-b4a9-834e6951a64b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/08/2023		Na	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3cc0c3c7-a904-408c-888e-c0b7cd7e4b72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/08/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8ce09b6c-a3df-4349-baa7-2de4a25cea0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
88d4738c-1cb7-46fb-99c5-03a9fce2f790	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f6878ee5-6cda-4e3f-9dc5-36e6aee66f8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	06/08/2023		*****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
890b40a5-ec6f-42e3-9a93-0d59cf66e342	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	06/08/2023		Esta limpio es mejor les den bonos a lo que limpian bien para estimularlos	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea667ef8-cfb0-46d1-84eb-c8276edd53ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes								Yes							
3f192e15-1655-4f1a-9862-3fe368acee96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e6def92e-304e-4c71-9597-7cf7fc1aa714	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/08/2023		The door open both ways	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
98046a66-9aec-43d4-8db6-8ac42b63f7f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5eb3e4e8-7841-4419-83bf-ac5a92e8ae59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c08874ef-92cd-41e2-8e89-c8eeddae4ffd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2dac0aeb-d29b-4b77-b51f-cdc74c4b181f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a795588e-5d10-46ec-a93b-f50efb69b134	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d616e98-2ab2-4337-8497-37e1f0636754	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	06/08/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4af40bbb-3947-4c23-a432-810d928e75db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/08/2023		Cgood
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c43c2254-6858-4bac-9232-712f94ef270a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a96a229e-4889-42d6-9eb5-0c458eaa860a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
14086021-6335-456b-83f4-3dcb38ac82c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
15dc9b02-9749-45ee-ac09-d367f7591eb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/08/2023		Super bien
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2c7df231-77e8-47cf-9d5a-452fa948affe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e7a04d8-c624-4065-85eb-ca2058ad07fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4eac6f6-c19f-4b4c-97c0-8bcf64a63df7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9a46837e-0d9e-4027-b4cf-839bd8d8108f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38706996-c6b7-446b-96e4-f04172542561	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5ac42bf-bfc3-4aea-842f-e5839445e041	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
545dc6c1-2671-4a47-ae8b-cbd24d5a45d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bf004116-f6e2-41c5-a9ba-c3be6728b7e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
89f562bb-aa84-41e2-8922-eb024238e9bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1dd9714b-54a4-48a3-8d6d-df5ddd1a6d49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e6bd73b0-43cb-49ba-b3fb-22f36929989a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes	Yes				Yes							
e5aa3287-4f64-41b9-b46d-cb9064c5e440	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e5aa3287-4f64-41b9-b46d-cb9064c5e440	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
d9687efa-1ec1-48f3-97d1-b20a8e225927	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/08/2023			
	How would you rate this restroom today?														
e8d2986b-813d-43c1-bd24-9595db46657a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/08/2023			
	How would you rate this restroom today?														
c5532b57-4d53-4bad-8190-3099eee835f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/08/2023			
	How would you rate this restroom today?														
3670c219-8951-4343-b27e-9a0831a80ff2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/08/2023			
	How would you rate this restroom today?														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
88130c8a-7fc9-4fd6-a571-3749dd069a96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
82932f0f-376c-4a15-839f-235e0f6aa470	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e0ae7ee5-219f-4d69-a46e-03a80e92bfab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:57:00	TRUE	FALSE			en-gb	09:57:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
ebe32dc9-5ecf-474f-ae4b-2cbbd0675889	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
553187bd-a5f0-4af6-9c2c-b2d8b829a76b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/08/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
4ddc56df-9912-4b5c-875c-a8b07e6e8c51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	06/08/2023		Hhm					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes		Yes										Yes					
5b51bfa4-da15-485a-b491-ef88813aefb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	06/08/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
b06da947-3de2-4241-9eaa-08210aacf8bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/08/2023		Good					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef9a61ce-3f3b-4712-b275-1154f6f42839	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0f62ba8-427a-44b7-bde4-4c7e7170df40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:21:00	TRUE	FALSE			en-gb	10:21:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b31ccff-0eba-42dc-aaa0-3fe7d552f764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e876fdc1-7735-4107-b682-0ee1786372b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed9aff54-481c-421c-afed-aefbf0f11960	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f7678b2c-d7bb-45d5-ad2d-2cc6ef0550d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/08/2023		So sad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
db4aa09b-6a0e-412c-916b-a0d3285f6aac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
828a8997-2b45-4191-9424-e8e77dba383a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a33a27c3-bfce-499b-8e73-f3b24169091c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2356f72a-9ad9-4eef-ae5f-7d0fb6cbc6ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c04ff0a8-cb1c-4077-b67b-8e2992f30286	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
251f932c-d0b7-451f-acc6-ada082c13f18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2235e557-3deb-473d-9f78-fd6a1033e9aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25ce3f61-5295-421c-88ae-c3e0775c954c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b837a3f8-75eb-41cc-b910-6348ad18b499	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2a026c88-74e3-4563-9764-fb0495afa77f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
391c059d-14fd-426b-919c-3d8fad50e376	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ac71fd9f-fc52-4afb-90b7-571c68b4ccf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
32df9823-7960-40c8-952f-74a590a5c75b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b86336a2-5d9a-439a-9970-cf06153e1c04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef945a15-fcb1-4223-a220-dfc471268c18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ea6e55ad-303d-4a71-8d20-e3bfe3c3b103	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b62f7e8f-85aa-46d8-8a96-327bb9d22b5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes												
7bbfb2c2-7a08-4dbb-8066-1478fbeba7a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb0294a5-6ef6-4df2-83ac-763070152205	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
729ca2ce-c71d-4693-b0fb-76732c61bf19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
89f69ea3-aa3a-4825-97cf-b0379cefa970	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3490d573-d6b1-4d41-ba82-b4a7e48aa71f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7b35eeb-3be3-4578-8494-a6a7f077bf48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81d473e1-e544-4aa3-bd10-99de72c054f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
22016ed4-e75d-463d-8d10-cce1cf25be66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
22016ed4-e75d-463d-8d10-cce1cf25be66	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes			Yes	Yes	Yes					
05da456e-f31b-4933-ab2e-8f111f87d4a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
99905fc1-5140-45ec-84f4-0ad7d082afd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
65258b99-01f9-47ad-b9e7-4aa60a965c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
133e22ca-970c-4aeb-9c96-eb10d8c80805	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
252b1168-1203-47db-8dc8-a0ffd4a2334a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cca6556a-169c-4e86-925a-a0e4982a9bca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:39:00	TRUE	FALSE			en-gb	13:39:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e47f6145-f22e-4e32-bfc6-1b41b8f7bec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
18c792f1-60d1-4e6c-8737-411a2aa6453c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	06/08/2023		Super limpio este lugar	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9acd4852-746b-419a-894b-efb41e0323aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
6356b1a9-f127-4c47-a9da-20a381e482ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
7c8383fa-dcf2-4aed-8cf5-bf38df55565f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:28:00	TRUE	FALSE			en-gb	14:28:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
1ca3bf52-e8a3-44dc-861f-84d5343feb8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8bdd8fc9-97b0-447f-8633-4959001fac7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6aea7ed5-ccdc-4374-b410-699970fe5b29	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c8eda0dc-38d2-4f23-b875-d0439860f332	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c25723e5-8c39-4cfb-b769-e3eaf4bf5b2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a800559b-7efa-40c5-b3cc-d1c55cf24028	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da07812e-78e1-4a91-833a-b18ab342b4ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
702a18a1-1fb6-4b09-ab83-4330d63fe525	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
62e2e574-a62f-4c29-8fe4-afcadf07e133	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
02345b6d-0451-4c2e-914c-bdf5ba662ad9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c2044048-a015-4510-b7d4-bfdc6a41eda6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4d565622-bbfa-4ef1-bf1a-2cebe7429adb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4d565622-bbfa-4ef1-bf1a-2cebe7429adb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cb754c86-703e-4409-963a-6b951e4e29a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5045ad5f-6264-4417-81fe-cc0ed117e95e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
60480a9c-03c7-41f5-8098-79171d700af4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c483702-ce43-423d-b1a9-c3602a79f4ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
961ce1ee-0a25-4125-aa4f-5c2ca95c5996	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
061d7756-7792-4336-9d48-b0508c305293	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
71719510-b55c-435f-8649-c72b8524afca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a04e695-c483-4855-a956-66598621be12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4156fee3-4cf8-4637-b1c6-48b8120114d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c8c9ef3-c284-462e-b575-b38fd6534dbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bc65e22f-6bc6-43c8-a119-3082535502ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d8522af-23b1-43ba-af26-b1e623291743	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b213087-d0a8-4a03-806d-5f0832c5a8e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					
c393d1a9-a8a1-435e-9210-5691ec396232	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:02:00	TRUE	FALSE			en-gb	18:02:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
830a7106-a71f-460b-bbf7-8ff366579f44	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d60b1be4-12d2-4515-972f-30e8db47a674	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ea035965-dc1e-460d-b2cc-a4a0e7b00ea5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
459b1243-9468-457b-ab9f-9455c9826412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
222f674d-73d9-4c53-993c-9b4001df7b56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
349f5eb6-c82b-469b-8ebf-26427a74e9fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
349f5eb6-c82b-469b-8ebf-26427a74e9fe	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
6b3b378c-673f-460a-b262-886bfe0ddece	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e416e339-0068-4d48-9bcd-366a010818f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes					
039002c6-51a4-4bdd-b1e0-39162761568b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes			Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d79df06c-4c6d-4abb-919f-f1a78be0f61b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b591b85-1b02-47c0-8746-bec6a9425bd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72ef71ed-1e2f-4b61-b8c3-1d530af2191b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes				Yes		Yes							
7c94b19c-e797-4b78-beca-592d479430c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/08/2023		Gracias	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ae6f0fd6-ac67-4bbd-a852-d240c1392e0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4c6b0dc6-7784-4b1c-b749-e9ab9c9bd25b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
2da9e869-d6d0-4994-955f-84a626a2719f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
c300e162-0dde-465c-9f1e-21aab05ec90d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
be20e166-a7ec-427e-a4e1-a7d30cc145f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be20e166-a7ec-427e-a4e1-a7d30cc145f9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
fbc6dd3-6833-4655-b272-d1882589d908	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
09dfd057-b7d7-4a8b-8be8-36ea9f872cf0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b566a626-07f2-4f42-8f3b-3910ce9487f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
16d05409-0dd9-4216-a2d2-a2077a22b5ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
84e367d0-ffa7-40e2-8812-a1dac101ceb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/08/2023		Awful
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
84e367d0-ffa7-40e2-8812-a1dac101ceb1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes			Yes	Yes		Yes	Yes					
e9a0de3f-e71f-4286-a8c0-b095b4f867fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a3884bd-5297-46b8-a3da-533ddc753954	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes				
0e160739-40a8-4d7d-b171-8896734437c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes						Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
59ef1e68-b667-494d-b827-0d99333874da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/08/2023		Angel	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d6e4f8d-803f-43c7-b52b-a25d4f05ad4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes			Yes							
2d38861e-e0fc-4f66-a608-b53d9fd873bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
0b5dcacf-88b7-4f53-982c-1c5ec216a559	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0b5dcacf-88b7-4f53-982c-1c5ec216a559	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes					Yes		Yes		Yes				
a37e4f2a-21c4-4fd6-8a3c-9cf5f36eba7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/08/2023		The bathroom is discusting can be beter
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes		Yes	Yes	Yes	Yes	Yes	Yes					
15e8da05-c5be-4efa-bbbf-1b0a2c5e410a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
aa77cdb4-a228-4f22-9033-9956c1f75d91	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
31465b35-8414-481f-a3fc-2f02721a1c8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
31465b35-8414-481f-a3fc-2f02721a1c8b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes		Yes				
c5217ed5-d00c-445f-a75a-7246b9dbe7c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:07:00	TRUE	FALSE			en-gb	22:07:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
646b6f3d-6589-4fdb-b9ab-c3d878707833	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes		Yes					
de64dd82-53d4-4679-b7ca-f98ca1d660e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
de64dd82-53d4-4679-b7ca-f98ca1d660e9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes											
f6eb8016-80bf-4658-ab2e-afa970880861	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/08/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
		Yes				Yes		Yes						Yes				Yes		
34e5920f-10da-4eed-a3a4-c486026a0da0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:27:00	TRUE	FALSE			en-gb	22:27:00	06/08/2023		Poor						
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
		Yes												Yes				Yes		
a9a8e7e0-59f5-4534-af32-7818fd43555d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:33:00	TRUE	FALSE			en-gb	22:33:00	06/08/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a9a8e7e0-59f5-4534-af32-7818fd43555d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
6b3cbc81-8777-4c87-95fc-142e36cffc63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
6b3cbc81-8777-4c87-95fc-142e36cffc63	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes												Yes							
e3687b5b-cc43-4cce-b100-78047b885e39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/09/2023		E						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
efd5ca8e-f691-48ca-bf50-135ed209e021	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:32:00	TRUE	FALSE			en-gb	00:32:00	06/09/2023		Smell :(						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
efd5ca8e-f691-48ca-bf50-135ed209e021	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
															Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
0fd8104d-0ca8-4f6f-abe7-7d0e0eb848c3	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:41:00	TRUE	FALSE		en-gb	00:41:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
ae32a24f-a0f2-41a4-842d-5a6f8af30077	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:01:00	TRUE	FALSE		en-gb	01:01:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
45e54b74-ba9f-41e1-99cb-0fc89c653137	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:06:00	TRUE	FALSE		en-gb	01:06:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
bccdb0c0-2b18-41d6-ad8d-6cf0ed8ad5b4	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:46:00	TRUE	FALSE		en-gb	01:46:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
d99915d9-20d9-4e37-b609-d5095c682d4d	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:48:00	TRUE	FALSE		en-gb	01:48:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eae417b7-f487-4ba0-8feb-f02bd9ca1aaa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 02:18:00	TRUE	FALSE			en-gb	02:18:00	06/09/2023		Nnnnnnnnj	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
788e9947-4786-4590-8f74-ba6b2f8cc4d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 02:43:00	TRUE	FALSE			en-gb	02:43:00	06/09/2023		P	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd50e2e0-ac7f-4a08-b30c-d2ddc7af1709	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 03:42:00	TRUE	FALSE			en-gb	03:42:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
494f7d63-2b60-4945-b18d-ccbe2f330956	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 04:33:00	TRUE	FALSE			en-gb	04:33:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0a894ee8-2651-4b5c-8188-343b771d7f4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
285a6dfa-2163-40dc-aa2c-16b4749f3b2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
206698db-43cc-44b6-b377-689cde43d1e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0252c0d-6cf9-44d0-a323-8e6086c37739	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2d68074-d7f5-4e93-91e2-d4f89825ae7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:19:00	TRUE	FALSE			en-gb	06:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88ff8845-f419-4c98-a5e5-6eb7a8370413	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85dc480e-7bee-4ecf-8062-adba65c057fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cb8d744a-20ed-406c-b742-475b9aa3ae3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
568a3159-1c9c-4bce-aceb-db7afd4ca00c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:44:00	TRUE	FALSE			en-gb	06:44:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0dd89a35-e3bd-4849-86b6-73d8d43bbe9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4dbace13-1d69-4faa-81be-d0a90522db45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:05:00	TRUE	FALSE			en-gb	07:05:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db2df8b7-2108-4a42-8ae9-f5ec0caf904b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba91b99f-e527-4247-9926-90ccb9703b4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c1361234-de47-4554-bab7-ca4041c13b39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75abe700-cb52-4135-b9c7-8029d7a66c64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd24c4c9-3758-4907-9b9a-a2181373bfe5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3b4b9ff-637b-4f32-9717-c83ae2c5b94c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d066d0-f9e7-47bd-a42b-639f75b75621	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fe4693c4-f977-4d0e-9305-5bfae48efa05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9a912fcc-a83c-44d5-a3e9-24760bcf44b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb707ade-8b48-4c6b-a71f-bb35ee431048	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70b128cc-a0a3-4990-8729-c34271b89999	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
551ab6d7-bcc2-4cfb-9cbb-76b5d968f237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
264164f1-59c9-4986-8b1e-f5f01ef53fba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
264164f1-59c9-4986-8b1e-f5f01ef53fba	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes						Yes					
75b964dd-c34a-44fa-9995-866da31978e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
38a70e03-04bf-4157-833f-012db2ce995b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	06/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
2e41825d-09b1-4563-bd40-7182815d6176	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
e91890db-6a9b-43f4-bcf1-91bf333bfc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
584525ef-f962-4629-9767-2ad69194ce60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a4a6a29f-f5b6-4cbf-927f-fb73b4066d63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6ae425b-fe29-4135-899e-cfa277d45ea9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
64bbde84-7d3f-4a09-aa67-6b874026f4a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
839639b9-f643-48a0-8a49-0a0eb588b40f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c082bfef-2069-471f-8c70-2c5019a84ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f914a3a-9b02-4bf6-82b0-cce877bcfc88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9d7311b7-843d-4613-8bc9-6020aa6941f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
99b5476f-61e5-484a-bddd-499e3995c5f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50e3c421-20d2-472a-9271-b8546cf3efe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
67a977cb-a8d4-4c6a-bfd2-8cfa9821d01c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85fc4bcd-3e7c-48d5-8394-b11b84efc293	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
678f4a92-7f69-4e0a-9e2e-53322e5f2d54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
678f4a92-7f69-4e0a-9e2e-53322e5f2d54	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes		Yes		Yes							
16dcbfdf-d4b6-4c80-8bad-1fb2f2bea6396	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/09/2023		Nice						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
c9973fe7-15f4-4676-87e5-9b7796b46b94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
4f47dedc-48c9-4d85-8cda-76c134d5aa62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
4a3f038c-b3bb-4377-acdc-04a20642297d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
863cf17a-1f8c-4416-9432-218f7f411b7c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c35f6b8-0ec4-40fb-bd68-5996b57c785f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1f8ef7c5-bf9a-46cc-9ed0-dbd9d34a9fd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b2ccf62b-a65a-47f7-8ad5-c2744aaec37f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f42c2300-685d-41fa-8183-7319df9305af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0cc11e74-a3a7-46d6-8f13-284cc9091692	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
88171d08-8dcc-44e9-9b6f-de881e968b60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6010b9f2-b376-4538-a125-31ba6bdeda2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1e6a216d-86d9-41e1-b79f-58eb3071bf97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:21:00	TRUE	FALSE			en-gb	10:21:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3a511134-fb2b-4e35-a516-a0877a07345a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/09/2023		Mop with clean sanitized water, change it out before finishing whole bathroom	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3a511134-fb2b-4e35-a516-a0877a07345a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
c182ff68-b008-4bef-a851-e5680415a51f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
83be7fae-38dc-420a-af19-1333b6b0fcf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fe4cb564-752e-460a-b5d4-32e000d2a4e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	06/09/2023		Horrible	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
3194a7aa-a478-4d87-8ad2-70e8e18c61c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/09/2023		Vvvvfhhhhcggg ggvvvvvfaaacsss sse	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
3194a7aa-a478-4d87-8ad2-70e8e18c61c1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes			
f9bd9186-43ad-41ad-b69e-65292529d45e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/09/2023		Stupid bathroom						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
Yes		Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes		
d973f119-5536-4139-a04c-aa1d622ba52d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
Yes		Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes		
ae3a8149-136c-4141-b07b-154335c3b244	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
Yes		Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes		
b0101c0d-13f2-4dbd-a627-6e9df1ff3862	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
Yes		Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bffa8f8d-9910-476e-892c-92b881200155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46bed297-30de-4f9c-8a53-8728f3a035ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed77f369-7f60-4655-9336-8fad1459d6c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6dbad864-ab51-4e32-bced-c53221054022	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/09/2023		P	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
63822a7a-ba6b-4b03-ac59-ecc5202acf3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/09/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
63822a7a-ba6b-4b03-ac59-ecc5202acf3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
126fd4fc-3fd8-440a-b31f-3614368c1dbb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
26c909b7-b5b4-44f2-83d8-9840b562781b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes	Yes	Yes					
be1786ca-a127-4f32-9d16-1686ee138ce2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54be4b5b-9089-46f3-ab1d-6f6a615f56a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3b0a7510-f91a-4331-8842-841d37175c41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
79fcf570-dcfa-4084-9256-c71733e1a051	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f888620e-b2ca-48a8-b0eb-f2cd6d5c4f34	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9cd5326-6cd5-4da7-be39-87dc3004c028	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/09/2023		Friendly staff
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5115c63c-54e1-48ea-b39f-e62ef25a1fe1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f4768ebd-e9e2-4f4f-8071-4d7415dfef97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2abbabb5-8fdf-4235-8461-8e180807486c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81df2e56-890e-4642-a503-e6f3e602ab93	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/09/2023		Todo limpio bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
181e03ac-6599-453d-974b-b8d3aac6677f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
815d4624-eea5-466c-b0be-053011daf231	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2ef8638e-e76e-4d80-8496-75deee4f6019	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
825f86b7-39cb-4def-aef0-ce18cbe1af11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes		Yes					Yes								
eb65de87-edbf-4ca5-be8d-a3edec2c9e12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
509e2834-8a6a-4219-8436-268215001032	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8003eb94-faeb-4b12-a188-b3751a8cb2bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
ab8faea8-b15b-4f63-a5ac-e27fd8862a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/09/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
33b6c4ba-2301-4fb8-8d93-cad06ceedcf3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:28:00	TRUE	FALSE			en-gb	13:28:00	06/09/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
af16ed93-6f1f-42de-8e55-bf4474c6a304	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	06/09/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
b1995a86-575e-4fb3-acd3-f9a6d6f28db5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	06/09/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c7c5b27f-ea9b-4f1e-9520-0ab91bed5284	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6f7ae18-9764-417e-8121-1e47b16e473e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98cf75b3-7281-48ca-bbb2-9fa8b5365efb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6048e928-6be1-42b2-a7e6-ba38971ea0c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be9955a5-f8b0-44f7-9ff9-9b582a464e51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes				Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fcd585c4-31e3-4f59-ba0d-79a620c6d5db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
028c2297-1f56-44e3-93d4-0c188af479d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
96a2e7d7-fdbd-4ede-b983-3573cbffa0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:05:00	TRUE	FALSE			en-gb	14:05:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
01aa4338-0507-492a-b279-35ba500538a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
27719ef3-ee5b-456e-8f94-9996cb98e723	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7121f677-d25d-468f-ac70-799344ff612b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8e488308-04da-4d31-b12f-6a6bb4d8db87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
11429aba-cf8d-4369-bfba-6be6c34c4693	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8019c8ee-4bc1-4190-baba-12b30a5f22f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b781fa4e-414b-40b5-a2da-3cf4ff7874db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:36:00	TRUE	FALSE			en-gb	14:36:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
88f1c881-b15b-4af9-8556-80e436b6a2e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d6461607-1f50-4ea4-9ca6-9964a0491b48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
741c6ec8-13a3-4eaf-b80c-ca6fa8ae7755	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
abc6f763-3682-460f-9712-7ca5efa95789	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	06/09/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
0e6a82b7-62c6-4329-af2c-30ef8ce4a984	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
411e2c52-fbcd-4052-97c4-e351774f6ba4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:54:00	TRUE	FALSE			en-gb	14:54:00	06/09/2023		The soap dispenser broke.	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bbdfdd35-c31b-4904-9a70-b5a526adc53f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5813e744-29c2-4841-a11e-5583417a2253	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53bbc8a2-ba66-4be0-890d-4afc46dc2e81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
79a0ba56-48fb-4bd2-b0f1-d8b3418b44db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a7c946d-e7de-421a-b4eb-fac220ddb30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a5d598a3-f287-48e6-8dbc-f09fecc899e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96c0ff29-3b14-47cc-a494-8a79d4448663	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c819f429-880d-4053-b8b6-f98b68189afa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c39a4baa-895a-4348-a3ea-e32f22fd3377	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d137027f-993d-4171-9c45-f4fcad29edd2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
136564ae-d868-46b8-a42d-77ddd8564aa1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2981e78b-bf64-4836-b2b6-e5db6ef781e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b3331026-2289-4054-8508-ec9817d641a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f93858d1-27d9-4a91-87ca-927bbc0baabe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/09/2023		Thanks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bb877a4-4c4b-4ec4-b000-6274b466c456	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:55:00	TRUE	FALSE			en-gb	15:55:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e6da446f-6159-47b6-8da5-49dd913d0df1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6d0eb3c8-3f24-447d-9d8e-086dc4338b7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
31147f86-76e7-4d08-8d01-712617c60157	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:10:00	TRUE	FALSE			en-gb	16:10:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91a88334-4742-489c-9638-43fe5825383b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:15:00	TRUE	FALSE			en-gb	16:15:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62cc2516-d4f3-477e-aae9-685acbdfdc11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f5038ae6-eb2e-4104-b74e-e4c7c4de2efd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ae264de-512a-4add-a94d-29e59c59abc2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/09/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ad65164b-9643-4f56-ac88-b167c89dff11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/09/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes														
a407894c-f79e-4d91-a29c-aaf2eeb3f1e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/09/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
112409f5-aa6c-4d83-97ac-084ea1d6719d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0867296d-9862-4e9c-867a-bbfa69becb3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c9c5e8c-65dc-47ff-9bf2-05b5c59991a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5f126d1d-2a74-42a9-8b01-f96129346610	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9a41a4a0-ca79-4b1f-abf8-553a76276417	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/09/2023		***
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
0bb6c6b5-c380-4f70-983b-e5aabda30d55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
17505a54-1196-4032-a359-a6ecb6d767f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad24e840-e582-460b-ba19-0e56d35c27a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:25:00	TRUE	FALSE			en-gb	17:25:00	06/09/2023		Nice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2e2a066-1caa-47bc-b104-ca83a3449263	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/09/2023		N/a
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b8a1d7d0-4514-46b4-8525-9de067b9860a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
711abb9a-1180-4164-9b05-c854a9c078e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d384926c-949b-4a2d-ac12-282f362c1a5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
328df791-6ba3-4b5e-b41e-079439b7a425	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b4322c7e-7429-4621-8dd2-d7a078b30704	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77e7bdc3-e5bf-4a84-9aa0-47acc9dce54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77e7bdc3-e5bf-4a84-9aa0-47acc9dce54	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
27503b7e-696f-4c73-b6dc-0f02be54bb8b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aa797c6b-08ed-42a2-8d23-784b27f4679f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
030f1bb7-5592-42b5-b9b6-0b8efcbdfadf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/09/2023		Bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f387b6fc-5416-4e9b-95ba-8c3ed5d8dd24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6556a123-2e95-41b5-88f9-214314bfa691	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9ebc57d6-65e8-401d-9a21-ef595570baaa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	06/09/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ebc57d6-65e8-401d-9a21-ef595570baaa	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
587151fe-181d-4256-9af4-ddacf223869e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1551b835-7a45-46d6-9e0d-72adb0fb6a0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:36:00	TRUE	FALSE			en-gb	18:36:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes							
39ea52b3-f66b-4569-89cc-a2d93cc77f55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d8a8cee-c69e-406c-9c2a-4c509f4df3bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38f415a9-0106-4825-be50-20106e836b10	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81f48e2b-5494-44fa-814b-087cee4fe0d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
84166c60-03e4-4b44-888c-922e321692d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3205f75-01f5-4d0f-861e-c51a291fbbb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c5feb50-d9f7-4880-88e1-c8c9e8cac5ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d68f39bf-bd07-4c9b-86cf-e9325a903752	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d68f39bf-bd07-4c9b-86cf-e9325a903752	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
f7021a4f-bcc7-4f0d-a651-2a4f0ad9f5e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/09/2023		So clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c647888e-a1d3-40db-bdcc-8b383cd33b24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
11eabd6e-8e6c-43ea-94ae-f4b56c06cde5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7207b0cb-7204-4ff1-9a7d-18474ecb2d01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/09/2023		Super
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
de44f190-4c1b-4882-9634-7f542362c155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dbcfce1b-5ed6-490b-8f4e-a71beac7a83f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3a29d601-d0c2-428b-b9f6-844e43794115	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e867932-6070-45f9-9ba9-26cf16c5e7b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	06/09/2023		Missing toilet paper.
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e2a9165-0042-4e0f-b7d9-45abbc9aed79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20fc368e-2074-4ad4-b30f-9558d349c1c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b0772dad-caf6-4779-83df-1ff7340315ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/09/2023		10/10	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
214082bd-1268-4eba-8200-a2f29d0289de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53370458-f1b6-4c57-8fc1-1facb71e8ead	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c818642c-13e4-43a1-ae74-edc3bb6d4ab6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f2269683-1537-45ee-a024-33c47b6625c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
33150b74-c4a2-441f-bd84-aa9c09fe8e3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9324d9c0-5f8b-4c9a-a4ba-4a078310b219	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/09/2023		Super	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4d04402e-7667-44be-84a2-92969190ae52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab9564a7-e486-404a-9933-d712a1c6055f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d4d5eed-0a2e-4a71-a293-a524ce7e119b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
b0236669-9244-4f61-890f-6d892cb72ee4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 22:44:00	TRUE	FALSE			en-gb	22:44:00	06/09/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
2c84cfca-e7ee-4e68-927f-42a2ee2984f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/09/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
9b22fc7c-32ab-4e72-9870-d353019006b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 00:57:00	TRUE	FALSE			en-gb	00:57:00	06/10/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
fec9e1e4-5396-4e79-bbbf-1d9519a6dec2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 01:49:00	TRUE	FALSE			en-gb	01:49:00	06/10/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cf5e25e8-96a3-46a1-ab33-d2ee69a97342	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 04:26:00	TRUE	FALSE			en-gb	04:26:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
aef66d85-cf7a-4994-b483-dcf9168a1b86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 05:25:00	TRUE	FALSE			en-gb	05:25:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1ff34da1-222c-4bca-bfee-666d86a73424	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes						
f304eed6-3639-446b-8e61-1f4e3612651a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	06/10/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes			Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c394e4c-465a-449c-9fd0-4af261b7f11a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:00:00	TRUE	FALSE			en-gb	06:00:00	06/10/2023		An airdryer for hands	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c87e7a0-79b9-4899-acef-f4857a6ebc9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
236b4ccd-cc12-46b5-a64f-b095925f8390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
24f267eb-feac-4fc5-9e53-71a4a0575516	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9dcd5373-71c6-4588-a674-566321940119	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c3385d7-a07c-4370-8559-f2300d037a59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70019394-03c3-41ae-a9c5-83a84aa28d43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b27f1d6a-739a-4b68-b9cb-b63fc443633f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a81ec92-a778-45f4-93b8-e5617b11f34d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	06/10/2023		Jaylanie
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e4b85cf7-1fcb-4db9-960f-fc5ad497b70c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
46e070f2-8086-4feb-ba89-bfba323da67e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cbdd028-eb1c-4fce-9de9-d661cc9e29c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3076392f-397a-490d-a953-5aac3f4854f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b378f841-ee26-4c8e-a4ee-31ff92cd66bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c525a6e2-19aa-49fe-85fe-c66ac112e75d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
a0ae14a6-b64d-4097-8479-0809479344e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
21168948-7740-420d-8287-72995ddaefb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
8110a02c-69fe-466a-9dac-67d2f6f2c8eb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
e8078953-a5cf-4cc6-941e-0bc3b8d245b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
7544c916-47b3-4ea4-a6ef-f792a376a1bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a6b7fff8-acb3-4b45-a098-2bf608f5a0bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
23c347a4-bc5e-4914-a64f-055392989aca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9dab87f5-f26e-496f-9ea4-f8274799a868	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c08476be-299a-438b-8d43-32ea2026dd9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5ee8df6b-3ebc-48f0-983c-556e999064c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4f349636-85e6-4bde-91fe-aa075e32957f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	06/10/2023		I dont really like it
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f349636-85e6-4bde-91fe-aa075e32957f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes													
a1af49ab-6a7b-4639-a7e4-83eb789ce430	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae34e21e-a95b-41dd-bcd4-887d8145501c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00a0a6f6-c3ca-4501-bdc2-2ea2bc4fc1b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b225090-e83a-408e-955b-ab3cff55b157	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
280c16cc-38ca-4e89-a73d-b9312746c716	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:25:00	TRUE	FALSE			en-gb	08:25:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c21753bc-3981-418b-aadc-57fa76e390c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5d10aaf-a508-4185-b841-9ee590c34dce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e8a4db8d-fa8e-4a22-b619-d889bb69a697	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
60929be9-373b-4952-832f-86f1770b27aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34c614c8-7fcc-4345-a204-39bc7a170ffb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1773c198-d04a-4bf9-9a2f-d390f506beef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54cea9ae-34b1-4b0f-863b-669330f05761	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
35f9590b-c37a-4111-95c0-f716e63c9d01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e11ffa37-f7ca-4cb0-9a36-b7b91eb7e7a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2475262-4d21-4cc3-aa56-80fdca11bbee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b4e3e86-7e20-4a52-a3ec-35d0bb98c6ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
933d3f42-e204-4d55-b605-2e72de86f85d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e97f8074-c608-469c-9428-5858a561bd4e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bf458a7-50f4-4f73-92f5-0e284e3c0ebd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b8b9801d-a472-496c-917c-a6ffe7f0c87c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28bf9f97-e34b-4e42-a007-8e1b334f8be2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3bf2b40d-93cc-44ff-87b8-429773450477	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6b173f4-057d-419f-9ef9-faa37a1fa3f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fc24e953-6c18-4fb6-b40e-70062a022453	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0e75167f-8d21-4be4-bca5-3ebc3221f4cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3822bf1-7c44-4662-8ed3-3158ebbb79e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0750c1a5-2b65-43a2-bf26-804d46b2cbba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
751ffdc-314a-45c1-a0c6-fb3859f53f73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b12b5478-3ac5-4dda-8744-699468b9ad05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b12b5478-3ac5-4dda-8744-699468b9ad05	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes			Yes	Yes		Yes				
71b62e12-eea4-4572-8131-822fe48ec827	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								
54635ec7-4cf2-489e-93bc-2f8fb107c6a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/10/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
34e23a6c-32ca-4f1e-91ee-396d6be7531a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
23232bb4-c52c-4a4c-a8cd-a3a34e4d845e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5196a9c5-8589-4d2c-b95e-70b22a3dd02f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc113130-7650-4386-b17b-002c58631ebf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ab0da407-cbb9-4e4b-8afc-455ff7a52264	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d938d93f-14c5-463c-bd39-0028d78d5b63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a50fcbb-d70d-4569-babc-835aac55041f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56fafa6a-e3b9-491f-b74f-1465f4a39efa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
56fafa6a-e3b9-491f-b74f-1465f4a39efa	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes		Yes					
c9e7b3d0-7b6b-4340-85f6-50c118fa3838	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
d39ce738-b160-4217-9faa-adea9bf66666	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
1d3e2836-ce6a-46da-82c9-86999a82c245	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1d3e2836-ce6a-46da-82c9-86999a82c245	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes													
cfad9ba5-72c6-4498-bec0-35f686551b39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d82a6b51-5d6b-4e34-8ae6-479aa71d63c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
27a097e9-e6c1-44ab-bab9-c9db06d07af5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
f75b422a-5be8-41a8-af65-6a833ffde882	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
930bdd75-2e8c-45e6-af14-c0e76494929d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
797ccab3-8c1c-45f3-b15f-1ad40ed4db9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/10/2023		**** on wa						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
ae357730-7528-4cd1-946d-c08d1f1c6033	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
4115420f-2b43-431b-96ff-63deb6649f27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
b5167623-8aea-4079-8124-fb10e7a36514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes												Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
83bdf9ad-71f0-43a0-b8cb-54d6e9ad72c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a6b1574-6bc7-445f-b6b5-61294762d137	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/10/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
167cf70a-dfcb-489b-98c1-853865371415	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7fcdcc0a-e73d-4c66-8c09-e46e6cd7d263	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/10/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b0afd93d-9625-4c1e-a58a-b3750703eb76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ec6dc61a-fd60-4d9c-8712-53e173371c6a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
abf3ab7d-1c5f-48b4-bb44-54a021ebb573	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/10/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
bfbb0074-631f-45f2-9694-e75f51f99112	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/10/2023		A man jerkinb off and ***** on the wall					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes			
00a7330e-4ec9-4c60-ab73-ce8a786a7207	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/10/2023		Stinky					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
2ffc5ab-f2cc-400b-83bb-dffc5d7350ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/10/2023		No					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6d69ed34-c0b2-4c76-8352-a216ddcda784	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34c1826e-9665-4a7f-84bc-9fc7008e251d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d73efa94-87cc-4cf2-bd93-ccf518b2a721	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9aef663f-35b3-4a08-95fe-383a62ea8ffb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/10/2023		Clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78a042a8-8155-427b-b0f8-753187689d18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87d3a4d2-12c5-49fa-8552-933dd72847ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
95fcb3a7-4e91-4669-8088-fbd70ed11492	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34ea3ceb-6958-40c0-afb6-1a58de452bdf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e246923b-706e-4254-8bc4-22b3f39b2b9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
73254e92-cb74-42a2-9905-0f79a909060d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ef1ae234-2c86-400b-82dd-14e8e2d92bba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d5271b48-902e-4e69-bec8-df8135e1866b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0ed62507-532c-4a39-942d-b311cca24457	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0127ff41-af97-4a46-b2ed-7bbdc264a69e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
05f66b98-2674-4f53-bcd9-d46e5c505743	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c7e45f4f-57c0-4e6f-ad48-ffc9be4c00f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/10/2023		Thank u
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b5c03be9-1fde-40f4-82a7-a7ccf7dc1ad4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7bd2a1a3-b4dc-4641-97cd-b7ee95755b28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7bd2a1a3-b4dc-4641-97cd-b7ee95755b28	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
b0581253-373e-409c-b361-d67ad62235a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/10/2023		Potato	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d9b7a7a3-ac6a-494a-9eb1-ea94f02e4c9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
04fe2be9-7382-4f03-b5d7-3eb21567d0fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
971f4f14-2d04-419b-9aeb-aa2ef6692467	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
e55b5e3f-9bdb-47c6-955a-051b4024a453	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/10/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes								Yes		Yes		Yes	
dfcb8643-dcce-44fb-a0a0-1266e0ae1948	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	06/10/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
								Yes											
bc2ac12b-dd86-4f91-af48-d3ea1293cf6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/10/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
5133920e-cf4d-4868-9107-2c616838856e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/10/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0e985395-ce77-4e89-8d53-d627210c4746	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c7d97e01-5f3d-40e6-83ec-9354265a8bab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0132895e-beaf-47dc-8c39-4608eae64188	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:24:00	TRUE	FALSE			en-gb	15:24:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77ff428c-8607-4901-acfe-7ef881c42016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7dd21270-f1d9-4adb-855e-8ed3cf544d39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes						Yes							



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
974d29e4-408b-44b9-95ad-72419e389ff9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bff139ac-f1f6-46a2-81ee-13562292b4ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:57:00	TRUE	FALSE			en-gb	15:57:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
034a33fd-c9b3-491d-88d9-2cf275dce027	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes					Yes						
d447da19-f6b4-460e-8212-946e8be66fab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c5642cd-c65e-4a5d-a4a6-2ecd5c1ae1cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
e211dc34-0178-48a2-94e1-c86bb151921c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	06/10/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
7c22f193-a05b-4272-b3bb-d256350cdd9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:06:00	TRUE	FALSE			en-gb	17:06:00	06/10/2023		?														
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
aa346119-52c0-4516-9d96-9a2fa632492b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:10:00	TRUE	FALSE			en-gb	17:10:00	06/10/2023		Smell ****														
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
															Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters				
																Yes	Yes	Yes				Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
98ae4c6b-4233-412b-b263-506e6139a1a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
87dca238-0ed2-4bf3-b8f7-280dd077702a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes				Yes	Yes	Yes						
3baf44ce-348a-4361-a183-b3568677381a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bf941818-b1fc-4e1f-b909-f2b7cb7f89c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/10/2023		J	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
507f2112-9ed3-4006-9250-5e1a5cab0239	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18c8f465-16eb-4794-a78e-0473268f8c1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/10/2023		Ew
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
1082c6cb-713b-48d8-9a36-868285aa147a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
45f16696-5697-4049-9581-2c764a07d869	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
aace68d5-20c8-4bd7-ab23-9b5d416b5091	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
099ea314-bd97-4df1-a8c3-92587ba050ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba87ff10-6866-47a9-b2a6-6debc2edd525	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
882adce5-7f19-4006-a2fe-2cea3895484f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eadbc1db-3e75-44ab-83e9-0991a8a4c4d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
36cdc53d-7544-467d-b97e-cfe8f8ff7325	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56f5dd45-44fb-49f7-a49b-c790972ba897	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c8b42e0d-240b-41bf-a120-71e903ae6a73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
48e54240-5adf-4ddf-8dc3-dbb2a4c0fab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fc160280-985b-4b12-a67b-bc88b1596817	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d0505470-ca62-40e1-81db-c66761556cb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
753cd927-a0b8-44bd-af08-6e4dd416aea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fbb70c85-250a-47b7-9a77-66ce393c5898	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:14:00	TRUE	FALSE			en-gb	20:14:00	06/10/2023		Good job	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
095b86b0-f0d1-4d50-8e4b-801686f8cd6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2a230a1c-91f6-4180-8f47-77c092281158	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9def31ef-7bb0-4f39-970b-9d2a19b0df49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/10/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0af40a16-6293-4260-ae22-37d8ab221195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9f973d11-10fa-4d1d-816f-99fa14d486c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e990a0b7-eb13-40a9-b7f8-2df7329f68f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
36c874e7-7780-4cd5-9761-e49ac8af4a81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c41f049c-3a38-47ce-af77-2b29856ea0ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
87afb74a-658b-450a-a0d0-515856c842fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
87afb74a-658b-450a-a0d0-515856c842fe	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
ddefadf6-9af2-4e99-a8e5-b9c953a1d233	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
05707bf-8279-4f0c-ac22-6270e76ed9c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes		Yes								
4664e03d-7bbd-4caa-afc0-9d7cdb30e1af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cd50cb89-2bc5-4526-a22c-dfbd04a97f37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:02:00	TRUE	FALSE			en-gb	00:02:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e472036b-728b-4277-b9df-b1963cde3e93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:15:00	TRUE	FALSE			en-gb	00:15:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc7b4d62-ac62-45c9-9cd1-a28f105224ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:27:00	TRUE	FALSE			en-gb	00:27:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ee86c4a-f8cd-4e53-a55a-6e7221bba5a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:32:00	TRUE	FALSE			en-gb	00:32:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
722a1b1a-5359-4833-a61b-aae6937a9d7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 02:32:00	TRUE	FALSE			en-gb	02:32:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad89a968-a1a2-4a60-ae37-82c5e53d8777	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 02:34:00	TRUE	FALSE			en-gb	02:34:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ad89a968-a1a2-4a60-ae37-82c5e53d8777	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
4d31f9be-995b-457a-b4f9-7725890452e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 04:47:00	TRUE	FALSE			en-gb	04:47:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							
0b77b366-4150-4b63-8f13-c0d9f42ec40d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
528320fd-164f-42fc-af6f-fe3c839fbf2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
edb4ad22-2f58-4fb4-933c-97effc6a2309	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 05:50:00	TRUE	FALSE			en-gb	05:50:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eba38d66-e442-404e-b443-7fcd813213ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:04:00	TRUE	FALSE			en-gb	06:04:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fcdd38f1-eea0-4edc-8ab2-d62d989b70f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes		Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c34f4893-db9c-4336-85e4-2865db32e44e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:20:00	TRUE	FALSE			en-gb	06:20:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3834b2c-36eb-4e6f-86ff-12b7a2cf1395	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
58b5f4af-96b3-44a2-9119-5c0c9c90449a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d350ab4c-49a0-4f4b-ba18-3cc43f8d35a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f829449c-8f17-4994-8abc-a189361205ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7f95e11-3423-4dc6-a094-8515172ade7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5860296a-1db7-4b87-beda-5b16aba1585e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:50:00	TRUE	FALSE			en-gb	06:50:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b9c3808-b77c-4c32-ae4-8a7059b5a644	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55f54c44-f0f9-4643-9b78-a5cac7e3a5c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a69dafef-75e1-4517-abf7-e838a12bd56c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72b6446f-4861-44ad-991d-a32bfd063d71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c99e9602-b443-431d-a013-73711045edb2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f36e4bec-aa6d-45cc-a67c-dfa4013d984a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88533938-cc85-4780-8da0-893b965a2c2b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65860b50-1121-474b-a9da-4420a5da6736	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8678014a-101c-4f3d-a890-413b0fd9c9b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cbc655aa-3e67-4014-a5b9-5d7118bd8f70	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f88ef87-bfd3-472a-b232-894c39d1aff7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e14ec6c2-bf4c-4734-a661-b1c7b8b42192	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6dbe1841-9d69-4006-9289-9c243fe977db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f869216a-2953-44e4-87d2-fe6ed8388cc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f5a43445-aae4-4ee8-8a73-23c9ecff6552	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d0aed53-6e04-4e19-9c08-9f6602aeb3a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5261e668-6cfd-408c-a9bf-47850ab4d660	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bdf86701-ff95-48a3-a52d-2fd72cf393df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
72d3dde8-d373-4d70-9b4f-1602bbd85f1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c4752391-156b-4ee9-80c9-8323e4539209	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b76e1e52-62ba-473c-a628-004ccd8f0333	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a15df1fd-0209-4b13-bfda-0e6d5bed75a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d424ef5-626d-4474-ba07-f656a317df64	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
14eefb42-ec7a-4d73-a7f5-81b8d35e7a51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03159841-2df9-4431-a324-a9bc6d70d2ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2142778a-9fd9-405a-94b2-3cd266b4aff8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0dd9a43-c516-475a-acfe-a294f680c24e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1554c49f-99a6-48c3-8277-0f82225a7647	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d2802d1-3fff-4747-a065-290167bb6a94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
f37d3e92-c96c-4ebc-abb3-fbd2208abd56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
19b4fd99-ffa0-4d90-b9fd-e52ec69b35b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
1c74c8c3-ae53-4003-8711-09b83caefe04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
e708cb75-8fa4-466e-81ce-473697cb046c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1923927b-a2f7-42e5-a858-4d9dd53f539b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b234639-f39f-4079-85d0-ca2f0d70a366	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7532332-14a2-484e-9878-c35e2a69c51a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7821181-f5f9-4cc3-9382-e800436830d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9754bb9-21d1-497c-af1a-604946b0cd60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
289e31f5-08cb-4d83-a716-4d7f20485e46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
18ec2f5b-5a1a-4023-bc63-a56542483101	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
068164c5-9396-4d45-97e7-f31580d2a3de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
a1c36136-3d0e-4594-a2f0-52f62b756195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes		Yes			
eb46c44d-e5f9-4042-a07e-01c2486a9778	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eb46c44d-e5f9-4042-a07e-01c2486a9778	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
06277600-20aa-4ac6-922e-f3c39cc637df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37ff4416-fbe9-4b25-8b0c-d56096254751	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes	Yes						
9d75ec74-82bd-4ee3-9b7a-6c09d870c4dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/11/2023		Hott	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cbb1cd6e-8f02-4365-a0bd-6908677260c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d1777d62-14a0-452f-8b7a-7f6dd5156e87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	06/11/2023		Sucio	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b3ec7014-b224-43dc-b23a-492671b6fed9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes					Yes					
					Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b708e70a-b370-4186-a137-da0142f23fae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
358dc14e-3dbd-4ade-b4ed-9dfd4304251c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:32:00	TRUE	FALSE			en-gb	10:32:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c7970551-e617-49e2-91e9-db28e3aeb879	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0ae6510f-1446-4651-99cd-820e606e332f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
46f63fd0-0b08-4489-9c27-b63b3236484d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
76eedf53-5357-4e8d-b113-352d00ccbdbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a49e17ec-b57d-48c7-8661-396eb2cb6780	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c8bbb415-91ec-45bb-aabe-77b90685fdbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b148186f-ff13-4c04-a6c9-1dea0374ceca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cf3a7a2a-b116-42a4-a958-ac66e3b94abb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/11/2023		"
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6a7ed52a-527e-4578-bdbf-b222ac089bf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
356c4971-cd6e-4659-8dc6-86e6e3246a84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c6f81518-b998-4216-8174-3158c69438da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a420276-0dc0-4289-a015-0b3860d3aedb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/11/2023		Georgina was exelent,,,restroom so clean.thanks to her .thanks georgina for been so good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
623e0662-45d1-4fef-8542-1af4bf9df767	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/11/2023		You dont have to tuch the toilt
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
302de6a7-8aed-430e-b369-32d2c7b7be87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
22a298f1-927e-4033-9e83-7e6b9c28cfd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d3d5c99a-78c5-4e3e-a133-ad80ed4b9074	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9834bb7c-57bf-4e4d-bdb6-2e100ef5b67e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9834bb7c-57bf-4e4d-bdb6-2e100ef5b67e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
b71115bd-36b2-4d73-bbd7-ada19cee6b08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:17:00	TRUE	FALSE			en-gb	12:17:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a6682b1-6464-4928-a4c9-674d1d229634	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes							
209ec196-2d88-4c05-aa95-3d27039d145f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:30:00	TRUE	FALSE			en-gb	12:30:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a91fe0b4-d30b-42ee-8a4d-4ac239efc55f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6ad41e2f-a1a8-46ad-aafc-09719ff175d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f603d6ee-2894-4b82-bef0-9fe64e333668	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7c0ba232-cade-4bc0-80d5-b5c469b7cfa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e8feb78-34a6-4b48-803f-2271974502a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/11/2023		Hard working employee.
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2b252b82-2621-4979-9765-2c7398181017	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d04e1b2-f24c-4de9-92f2-bf703adf9687	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
cf80a3cb-a821-4acd-bf77-376f781feb9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
06739040-eb7d-4c61-a4f7-e434372c0698	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
d8b3a861-08d9-4223-a738-b3c172ea7870	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
2f0098f8-c013-44a0-b4b0-f630693a2141	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2f0098f8-c013-44a0-b4b0-f630693a2141	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
f2793392-62d5-43e6-ad41-9f67a1d0bb3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9c66ef54-6531-4664-951d-f1245d7c1d8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d0361ef1-551b-47c7-9221-ab99c308e56d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74ec6db4-b148-4449-a117-662c5a75a23b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/11/2023		L
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c7fcaac-58d6-4ffb-a08d-ae8b8efc9be0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	06/11/2023		**** you
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5c7fcaac-58d6-4ffb-a08d-ae8b8efc9be0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes				
68259338-b366-4593-a40d-afbf3a2689f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/11/2023		****
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
025ca0a1-74da-45db-876a-371c68187dea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
372fe44d-423e-482d-9755-ea4feace368a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/11/2023		P
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
95ac27e5-d5de-41ee-9812-ee479a8671cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
94b929bb-51b2-4c9b-8248-5afda6bb6f09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes		Yes						
4671b988-d167-47ff-92a8-c4f0527c45d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:56:00	TRUE	FALSE			en-gb	15:56:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e87b4347-8005-4df9-968d-d9c196348fd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
172fcb81-7276-4ee5-af9d-f0454e31fa87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1be4acfe-46d2-4bdb-95b8-19166d377ed3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cb1d8475-ee60-4ce2-a3bd-4e9450b3ab31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/11/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes	Yes	Yes						
757dbae5-bd5c-4792-832a-a0493f46e241	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b11b3f87-9bfd-4151-89b3-c2fe5492c092	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
166384bd-7c9d-44ab-a708-b726a30a0b1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
23df0e97-59f9-4910-96d7-63571b82e764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e3eac49c-9bb7-4b8a-8693-eb2c394c7c30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7392270f-92eb-4f0e-b9b4-cb1d0981ea81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9650019a-7148-4fe7-8ae7-28502e44fc71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	06/11/2023		E	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
12b4da8a-b07d-4c61-b698-1dd7c294a58b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/11/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
12b4da8a-b07d-4c61-b698-1dd7c294a58b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
cb5006c6-610b-40ae-abbb-61a23c64bcc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
47f00971-3cc3-4848-8200-2bf0a0bf3433	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8007a9e8-6f56-4322-a28d-aa57b185b4c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes			Yes	Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
4f9c7c33-7e2c-4183-960e-c32b79aee02a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/11/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
27fcc438-1d52-4d3e-85d4-0668fee92961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/11/2023		Clean up															
														How would you rate this restroom today?															
														Average	Good	Poor													
															Yes														
3c8fdda7-7759-4b73-87da-0b4b7088c992	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/11/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
1d3f9295-37e1-43be-9532-9ef8df11f4c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/11/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8301b88b-1535-4e48-a2fd-374a63bb1af0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1336f87e-62db-4fc7-a904-9f19cb5a21e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
4e40a31f-bb07-409a-b5d6-a197f8dba67a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af35ffc7-f295-4b3b-a5cf-37ed6e7c6455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/11/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
54fa1e6c-5143-4624-b66b-3f190b983a20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a2872cc9-c676-4402-8665-848cbc17fff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
4772d8ee-9401-4880-808a-58ad82e23c08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
06616a59-095f-4c66-9b7f-0fd9a89fff7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes					Yes								



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cc1b247d-4514-4ccf-bc36-990c13e5138a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d4ec764-6c28-4d90-a4d8-8cbdf6305785	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												
ac1dc87a-42a6-475f-a1b6-5d0d2a82deb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes	Yes	Yes				
86c1f095-1e0a-4c86-b7d7-9b0008405f40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9d45b2bf-ea2c-4759-9e42-807b57666cf8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc5fb91c-73a8-4ecb-bef6-c797419ea88b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes			Yes			Yes						
c316d19e-db37-4da0-a1ba-753375a0b0d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
45290438-c6aa-490e-95b3-bed96c2eb4b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a4d1be11-259d-4022-ab0e-98a446f3db3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9957fd2d-8733-4155-89d0-7116aa916752	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d26ab7aa-c868-4988-bf68-264bfe87f73c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	06/11/2023		Hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2bcd3122-dca1-476b-aece-35b11d7afb3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2bcd3122-dca1-476b-aece-35b11d7afb3a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
3a75b797-964a-4a73-b896-7c8e0a8cfe05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	06/11/2023		Really nasty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
bdce547a-a3c8-43dd-9faf-16d7b8885161	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:04:00	TRUE	FALSE			en-gb	22:04:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes					Yes	Yes					
050f6d82-0e08-4743-9df1-ffa4fe6db4e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	06/11/2023		Gross	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
050f6d82-0e08-4743-9df1-fffa4fe6db4e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes					
ff780245-6dfd-4350-814f-6d7eb60b0c49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7c4d5509-f88a-4a03-9828-26505606a282	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b4aa1f0-1c05-4791-a4e3-75e3d5b53b0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:33:00	TRUE	FALSE			en-gb	22:33:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30916513-be64-4c9b-b7f6-16aa31126e22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes							Yes	Yes					
7397cf38-f3f6-46bd-b4c3-c525b23492e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:39:00	TRUE	FALSE			en-gb	22:39:00	06/11/2023		P	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes		Yes					
7e581a93-be67-4e7d-8cfb-0372b2c6d630	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7e22e0d6-b3a3-4334-8c3d-2afe0397ae5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 23:04:00	TRUE	FALSE			en-gb	23:04:00	06/11/2023		Dfr
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9ba8f24-c20d-464d-b200-dccedafbba89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 23:50:00	TRUE	FALSE			en-gb	23:50:00	06/11/2023		Very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68d2e339-e6ee-4b3e-bfc5-e945ae3e2f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 00:55:00	TRUE	FALSE			en-gb	00:55:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b03ab3a-d5fc-4932-8b46-01fee3bb8214	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 01:21:00	TRUE	FALSE			en-gb	01:21:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3e8a6fb6-5def-4c13-b981-86e8782fcc25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 03:17:00	TRUE	FALSE			en-gb	03:17:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a88b7fe8-5a47-4279-aa38-12541b8838d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 05:34:00	TRUE	FALSE			en-gb	05:34:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a88b7fe8-5a47-4279-aa38-12541b8838d9		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes						Yes					
a69a3b93-9d9e-4743-b260-04b9e4fd67e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
efe9dea1-38e4-4f57-987f-bc24d362b971	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
e13aebc3-824f-4fb0-9738-3cb6c79e5584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:15:00	TRUE	FALSE			en-gb	06:15:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
2cfe910c-9614-41e0-a78d-0c6ea7c176b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
5bbcedda-ba16-4ecc-8fd9-718cd1cad420	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
85c68f98-652b-4ab0-a70e-b71a4c74cbfd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd12dd5f-021a-47d4-8c45-2802458deffa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:44:00	TRUE	FALSE			en-gb	06:44:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a782116d-fdd2-4f40-a621-1f5108baae0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
20032978-d75f-4c0d-88dd-cc538529be52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ed480a15-391f-4e2b-86d0-d7488c3acdf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:50:00	TRUE	FALSE			en-gb	06:50:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
da83b6c3-c86b-4e49-8202-a255949d5412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e0cda24d-e225-4405-833f-32e850425ab9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
781db705-f274-47e0-96d5-df9e57094e93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ca55ee9c-ef9d-45e0-a7ac-9e30bca851f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:02:00	TRUE	FALSE			en-gb	07:02:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ecb9e20d-fd0d-47e2-985e-0d30c451d6b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be25f956-e965-4bc6-b932-402458fb9db6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:15:00	TRUE	FALSE			en-gb	07:15:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01ac85c4-8ec7-470c-9ce9-337a3ee04b9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1f57bc8-4724-4574-a502-2c20c0fc0359	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
193ff26a-3d2e-49e3-be14-e4439397d677	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
adbfb11-5a25-4dba-b9df-b9885683a282	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d330bd6-f9e7-4ab1-afef-c531cd97d483	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/12/2023		Like clean bathrooms. Thank you
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
127df3c7-6739-4569-a2d4-5c178aaade7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
153d9f6e-1943-4e72-b2c7-0ef6583e5a7b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
5c03771c-b865-41e4-8073-00238424a372	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
b514655f-3c36-4a99-9e20-8810ba4cc92f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0a46a657-5ae1-4cb8-961c-a151331a011f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28f8364a-04c9-4f83-ac41-633d77eadf68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a06b5192-9aae-4145-b328-a7025e966b0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ac3f991-f274-4fc6-86ab-4afe29d5b431	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d3698594-ae36-422e-88ce-a8708d59126e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6ffe0434-b623-4ed5-9753-ffe77119193c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
213904d8-4ffb-4924-8bce-7d56c2d6faf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
42928b5a-2fe5-49b6-86c9-cfe404b7a94a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/12/2023		It was hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
4c2e8621-c99e-4d28-8b0f-779973994c2f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
27955576-57c4-4dd6-8d9b-2446fc73c203	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c86c5c8-d644-42d5-93c0-01b4f226e1ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
83cc21d6-e395-40e4-9804-b5e80a30cdd0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea84ec57-d911-4246-b0f6-6d5f1fd16106	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0f0c14a7-da51-4ff2-b05a-66d853e707b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae8a3921-2a69-40fc-982f-cfe9db106a27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0ae7b830-ec16-4d60-a934-73f8dbe6d601	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2975e29d-e2dd-447c-b3fe-36a79c503451	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
80925aae-6bea-4c40-9275-7d8a29bf4e1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
29abb923-5bc3-4d7a-ae1b-8dc61e781fc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
4524cdf-74e9-4117-a7e0-2a05747f457a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
e443f4d1-1678-4770-8b29-3b72a6c3a556	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
c3d0242a-f3f6-41ac-b646-9920bce92330	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
ef024f14-e497-413d-9af0-b04c8af5a23c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef024f14-e497-413d-9af0-b04c8af5a23c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
4d834889-ffbe-4c35-b37a-e3e7ca712c8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dae05513-977f-4145-844b-5cb233eeb3fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c4200e8b-83cf-4ef0-880c-405cb9fd728e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/12/2023		It was hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
0816d5bc-4274-45be-b66c-221a03bfd64d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
41ed61ae-d0e2-4883-a5aa-8aa982657b2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3afdd49f-b26c-4cfe-bb78-2e36eb6ba4d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14287268-54b4-4849-b556-70945e5f39aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3e06c8c8-32eb-4a46-9c45-e606378f29b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fb2a338b-4bb6-418d-8a62-b61832d9d80f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:32:00	TRUE	FALSE			en-gb	10:32:00	06/12/2023		Terrible conditions, hot as balls.	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb2a338b-4bb6-418d-8a62-b61832d9d80f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
						Yes		Yes	Yes					
d1c6e158-e934-4123-9de7-10262ef3e36d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
677981d0-524d-4d9e-abc1-4dc60633af1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
66928f3a-f616-4547-9d84-065d5d274390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a78d2ecd-b983-4b0a-872a-27dce39b4ede	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
44c604f1-5e3e-47b7-a02e-65f19623ec13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
497ea655-86f3-46b0-92f5-0febb5d80fc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a0fa7721-a9bc-401c-8087-40e0524d07e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3e7e6c5a-6636-4ee8-98d8-a670f7484390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
95a31a6d-6898-46c3-bc32-2565ecd0ee0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3949b1e8-c3c5-4f3a-bf93-99e2e8644efd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
80db8d9c-e663-4dfc-9ba5-5b434b8aa7c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d6b134c8-225a-4556-b325-a8c2c5c0e146	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/12/2023		Nk garbage in mf	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
61a08e63-beb7-4aff-8a7f-ea99c37f7dcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
04a82d10-8a25-4e08-9898-f51718edba60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
ed4825ce-6e36-40e4-9225-c1e0557445c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
0760f355-e67c-44e2-bed3-67ef6305c0d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/12/2023		Good job															
														How would you rate this restroom today?															
														Average	Good	Poor													
															Yes														
001b443f-1f23-4b40-bcf4-bef70cce2507	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3a934e55-3b50-4479-b989-25b1d562633f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
60aa678c-185f-444d-9238-8aba0f7d157a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
703c0dc3-bbc3-43c7-ad6b-3ac6963541e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
02bf14ff-6fac-4d4d-9990-eded2d1f3745	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
649bf18c-ca14-4558-aa48-f7f44dca6653	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
52223ccc-1504-4320-924d-5d9b3fed8f7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e167bb80-99d4-4b43-b731-3f56a21ef63d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f4a7989e-b442-420e-aaf4-1a8a72e2808b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2d6eeeb-de37-45a8-b11e-9cd5e8397bcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6cdc9553-bf53-4173-8591-2a2a451b0840	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1a657bab-a429-4f0a-adf1-1e31a91ec631	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
36b000f4-df66-439e-a241-91b4d6efddc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9bbb80ba-9929-4d24-8d14-b63d128cef16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:58:00	TRUE	FALSE			en-gb	12:58:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9bbb80ba-9929-4d24-8d14-b63d128cef16	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
a1cba269-61a6-40df-855b-2c71f12531a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d90b9096-f63e-4bf9-850a-b839ab9a1c06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d22dec83-109d-409b-af46-72a860d7e1d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9adb2376-8c36-4f8d-a429-d04eb16698fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32ffc41-f563-4c58-bc08-dab9be36860c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e6ce1368-46de-49c3-a15c-75e0d9278ae0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5a21eb78-5ffa-4927-b58c-70aec5a5893	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2436e58-11bb-45fc-8c71-5945601d227b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
880dde1-87de-44ad-936a-ab383c08ff91	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b4496cb-fa9b-4652-891d-20d9eb36a8cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d561c6b8-6d93-45a5-8195-2b818814cbbd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44855e7d-6974-40eb-a732-248155577e2b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a8513a56-151e-4b7e-b17b-b50c198dac49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c9fb77a5-9deb-4f7c-8b90-930195236511	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b811fecc-aa36-453e-b2e5-d64b884a0097	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes				Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
56a48983-e1ca-45cf-ac17-2c7e6d5dec9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c57663f5-9ca9-47f0-bb59-7777c623b3fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46f05838-beb8-472b-b80d-816ba7b1e433	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
095364bd-37cf-4674-836d-ab9ec8d7e8de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
c2f3ceee-5d0b-4326-9bb5-087899895465	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	06/12/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c2f3ceee-5d0b-4326-9bb5-087899895465	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
bb025aac-e382-4db0-bbef-59f76c6c6e1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/12/2023		no	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
65b885ea-c869-432d-91c1-9a5d4a6a4492	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/12/2023		It stinks	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
741f655b-e5ab-421d-8e62-f33e73629f24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/12/2023		Stinks	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
99fcb74a-f151-4966-a2b5-4e1c3634e2cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
805ca9b0-4717-4f13-a531-5526ad62afe2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2bb6a88e-bff4-47b9-80ed-4d67f0112657	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
90315563-16fd-4785-a3ff-4b0367158ccc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
889a5653-436d-401d-b571-93654fd63937	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
729e19c2-1d02-40b4-89a0-eb05de1d3ca8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4006eb68-62e4-400f-970d-3bc80c71614f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fdd2e335-c164-4e4d-93bb-f720b4534d90	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes			Yes	Yes	Yes	Yes				
							Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d7cbd478-56f9-41dd-aec0-0159650b0a41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ed4457f-3677-426f-8336-b84685e267dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
09e69043-eb80-4a7d-8293-02d50ff63533	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
033eefc8-bb0e-4d5a-9f64-127b325feff9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b88efe24-c73e-4439-a1f6-0601ea3d9bfa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
128fa270-a16b-4084-bdb0-2b3142d0653a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d738c038-c264-4201-ac92-bc0d63f61a7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
636a6cb7-7658-4b61-97ed-bfb8b4ed41ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
73b9f1a1-b3fc-46e5-98fd-b09e49684ad6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/12/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
16e21ef5-bd47-40c6-b8d1-6580e3c184df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5899d3a2-1f48-4936-9712-29d63ea525e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a0771883-7995-4823-a598-93f4e14b5789	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
61a2c815-0f7f-453d-8cd3-1506cf805cde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9ae0db4c-9872-43a6-a8de-e10a250b3a15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/12/2023		Ac and air quality	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ae0db4c-9872-43a6-a8de-e10a250b3a15	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
478e9425-962e-4ad6-ade5-4412fc6e09c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:59:00	TRUE	FALSE			en-gb	17:59:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
16059592-d757-48ae-80b3-f70c2de7ee37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/12/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
60f9a326-053f-4317-b17a-c99bd5f59529	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
a5d4185f-ca68-4791-9a8e-1adb842e7a4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
8de0ccc7-025c-43cc-a5bd-ad0eb795038b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes		Yes	Yes				Yes	Yes	Yes							
bc5ed00a-7309-43e7-945a-ea8eadd66ba8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes	Yes	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d4de4e9b-b8bc-4183-b7d0-3c0b53bc84a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9eb95bd4-7df5-40b1-a3e4-f0b2b13151b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/12/2023		no mm	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
76f32c93-cd15-4585-b64b-15a94fea293d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes	Yes	Yes			Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5c7157a1-d613-4678-b2c2-e08b96fa721b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b8124b4f-2117-4450-ba22-e6b3a8750af7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
cd8cfeb7-5ffa-42ff-946a-ae033ffc1204	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
400af746-2e4f-46c9-b903-82fda8aa19aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8a502e8d-b91d-4474-ab5b-a087d0051d0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d2e8f159-a482-4d4f-a383-6b79e3328853	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
77990780-4eb8-49dd-aa51-2f39acfd856a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b7281ef1-28ec-4a67-83ac-8deae34329f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7281ef1-28ec-4a67-83ac-8deae34329f7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e4bf24b9-e5c6-45db-9d5d-d84e0c5fa4bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
73f354fd-ef45-4cb0-82af-ae5567121db8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes							
bee6233b-d6df-4e3a-8a6d-a8e02f7dfb41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9d8e246-481d-4b40-b267-8f63a9c2884d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a9d8e246-481d-4b40-b267-8f63a9c2884d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes				
c97d3856-d15d-4ea3-8ebd-10216c1cf1e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2307729-303d-4694-a92e-066835e1e0e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													
4782cedd-949e-48c3-95a9-8cf8d00a0a7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f46c660c-356e-4dfc-b1f3-5b2dd9d879cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
bb2efc40-b59e-47fe-bcb8-aa12a3f79780	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
512dc1c0-fa08-48f3-9ec4-0f3d5ce15d89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
250b7a57-6662-45da-9e6f-ba90b9286297	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0b5bc291-7e45-49b9-b6eb-c58c1f7b6849	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
6a84c7bc-c4e8-489c-9b6e-3d31c66a3cba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
023f5b6d-de50-406d-b510-09136fa78c4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
54246e21-df04-479a-bab1-271db1a47579	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
293b419d-3384-4f86-bebd-cd00733c9c08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
4de63c2d-82c9-4ae2-938f-86bdbe4f8c6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:24:00	TRUE	FALSE			en-gb	21:24:00	06/12/2023		Mfggnfhgg		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5f4aee8c-8588-45a4-ac6e-25484a135839	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1f35d32c-67d0-4282-a26a-cd76cacbf04f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7a573ef8-5744-4082-ba18-75379f0fa5b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
93cbb3cc-7f05-4e3c-af76-10ceada75e13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:07:00	TRUE	FALSE			en-gb	22:07:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1e263787-59cb-4864-94f7-25a343991197	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:10:00	TRUE	FALSE			en-gb	22:10:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
024a4993-c9ff-489c-9f2e-2bd74d9265db	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:14:00	TRUE	FALSE		en-gb	22:14:00	06/12/2023		No												
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
															Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>															
			Yes	Yes					Yes	Yes																
e673666e-c330-4849-b809-d83fe359423b	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:29:00	TRUE	FALSE		en-gb	22:29:00	06/12/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
fd95e393-703a-4ed9-8ace-b6368ef75f32	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:35:00	TRUE	FALSE		en-gb	22:35:00	06/12/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
bf2a2751-e312-4012-b85a-a132f7c66506	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 23:00:00	TRUE	FALSE		en-gb	23:00:00	06/12/2023		Dirty toilets!!!!												
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
		Yes																								
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>															
								Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
0d7ba21a-89e7-40b1-85f2-2b77c9f489a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 23:02:00	TRUE	FALSE			en-gb	23:02:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
03fe88df-ed17-49c8-aa51-8c22c913b901	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 00:24:00	TRUE	FALSE			en-gb	00:24:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
34181f85-a648-4925-95f0-646b9efc6b9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
3e90bb2c-3324-4c21-9d2a-6688c5182a99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 01:22:00	TRUE	FALSE			en-gb	01:22:00	06/13/2023		Lack of counter space inside stall (for wallet or hats)															
														How would you rate this restroom today?															
														Average	Good	Poor													
														Yes															
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
															Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters					
																					Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eafb1d62-55eb-45b6-af1f-683ed63e0baf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 03:44:00	TRUE	FALSE			en-gb	03:44:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a51200f-21ec-43fb-ac0e-48e54abbe755	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:34:00	TRUE	FALSE			en-gb	04:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b5de2b16-e38a-48a4-a3ef-feaa351d2af4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:34:00	TRUE	FALSE			en-gb	04:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
228268c4-b3d2-4f52-ae17-1912b8f4450c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:35:00	TRUE	FALSE			en-gb	04:35:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
74260fc6-78e0-439e-af2d-b344ba90b036	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:59:00	TRUE	FALSE			en-gb	04:59:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9097c511-a4e5-4e32-8e69-23b73d4fcbfc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:02:00	TRUE	FALSE			en-gb	05:02:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3df2e593-1c60-4b67-b0e8-8d197da13e64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:08:00	TRUE	FALSE			en-gb	05:08:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b3baa27d-4002-45ea-b15f-f87da72dffbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
50d67892-9686-44cb-9fe8-d45b60503a1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	06/13/2023		Dirty	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
00639387-903c-42db-bd88-6fc96872037f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:02:00	TRUE	FALSE			en-gb	06:02:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00639387-903c-42db-bd88-6fc96872037f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes			Yes			
c239ba84-09e0-4d8c-8664-9d08c4363850	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:07:00	TRUE	FALSE			en-gb	06:07:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b863da0-dd10-4680-b2c7-b3737360f75d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c5b8531e-0e0a-4f6d-9d43-2ad74c2a1f9c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:42:00	TRUE	FALSE			en-gb	06:42:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1d12dd67-f6d7-444e-a6a3-da162781cb31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
93cb2c89-084f-4178-b67e-abddc1597dce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f6422fba-251f-4fe6-85ff-9b20a58674b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
173ce8b3-1fa1-47fe-9baf-0685ca88ae5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dfbf1ecc-6be6-4854-a70a-a3d6cae5a897	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
83ed098e-f24e-4164-9b94-186608a44f80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e37eb589-b5b1-4528-aa1d-98736b579c0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
444f2b4e-1c8f-4778-847d-c6b500e5e091	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a83bf03e-2103-4db2-8777-a83c0102bac0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b305c07-10c5-4e5c-ae7e-4bb8c45c39cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0a606674-94ce-41ca-b29b-7bbf77486594	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b70c7e1-95e1-4d32-ae60-f848e9d50778	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
751309b5-c8ac-4dc6-b30c-cb2278a2fc9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes	Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1debdab1-3c84-4a01-8539-747afc9c4cc8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
654da83a-72f0-4881-9814-29b3b5079bb1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/13/2023		Naw
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7b41456-7aac-4d2a-9f24-2c7d651c771e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes		Yes							
fe533dfd-eca8-40b1-a6c4-55d27547b903	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/13/2023		Hot
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
31d16641-7a34-4ba1-a6bd-1a8c4927d2ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
83d1a093-0c64-4210-9d94-760b0148b322	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e15da35d-c3c1-44d4-aab4-00e23e599f42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
863023a5-09b2-415f-927d-c8d90303798d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aa1ad653-d11e-4c41-8704-d0a1de2462e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8363eacc-1fd3-4f65-9bce-a6846c2171c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e5a6e056-aaea-4671-b909-4bb613994495	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9ca8b14f-8fff-4df5-847c-1ac293c370b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f19bcdad-8bbd-4c7b-8f31-52be5f5fc218	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
483924dd-f0c0-4a68-82ab-6ce27538da83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
22a4699e-ad90-42b7-8c8f-16b71fcb4a0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a5f6cf59-42e8-47f0-8eab-cb56bab77cca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06b677cc-386f-4ef0-81bd-55b117aa6cfa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
028e312a-e74c-4d32-b00e-fd6126e8ce14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29970a35-47b8-46cc-9728-4bb8a71fcab2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7aa4bf2a-894e-466e-a6da-f08146f94cd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9047d17-a87e-4c5c-9b13-58210ead7705	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
e760f0fa-7c63-4c64-bf56-d336ca37daf1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
ca5ad1ba-c9da-4a62-b34c-9caa6556d303	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
7eec66a4-e8ac-4c21-9197-bda40629d4c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	06/13/2023		Long line		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
						Yes	Yes	Yes								
e4880fe0-c864-4a31-a3e4-9ff55c9f6a56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e4880fe0-c864-4a31-a3e4-9ff55c9f6a56	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
ecc66451-ce24-4a18-80f4-2f470bacbe95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f77b9d0-fba9-4b1f-b3b8-e71febba44c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dfdd71c1-4ff3-4205-a794-eb17f121c201	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
a981e9df-9b05-447d-b330-8120f4abba72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ee5c1197-3fd2-4715-9223-6863e636d75b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1e0636a4-16ec-404a-8da2-7a29c17d793f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6628a198-4570-4311-9510-6f1a2a08cdfb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:58:00	TRUE	FALSE			en-gb	09:58:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5b4ef037-fd49-4ee7-8534-594e329130d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes					Yes								
d8393813-51ff-48c0-b12d-f7831845e5ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/13/2023		Very clean	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
17eedca-d9bf-4b5a-832f-c0fe32366277	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
2b2015c4-eb2a-470a-8eec-71efa9a451fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/13/2023		Good						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
316705ef-2029-468e-94a2-e8628f561a93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
d83dd628-d05f-4ed5-b227-e72fd5a8def4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/13/2023		Dirty!						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bc8a7d83-59a7-4cf6-989f-7d6ce0384d11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f040b40a-d5ff-48f2-a5bf-7523e2ab62f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0d6ad93b-92a1-47ef-9a90-d3294a317329	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
276029c6-85d7-4952-8fcf-e194ce72f98a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c7106e3-fe8e-45ca-8bad-dd86486f662b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
23956c7d-d3a2-4319-bdb9-1b798e0c359b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4378f5ad-b1fa-4c98-8f7b-ef527e5437a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a93c12f2-c05c-4e54-8b6f-fa7fb20345ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes	Yes					Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
039c7cbb-75fb-4d4b-9e16-d22670c8e536	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d7436335-58c6-4c3d-af3b-4b2ccdd4bddc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
19b8caa8-fc4e-48f8-b0d7-aa172a122d15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a7c2bd71-bb58-4fb3-9294-6b069a74b2e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
5ed81215-6a62-4700-8bd9-9855d357ebeb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/13/2023		P	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5ed81215-6a62-4700-8bd9-9855d357ebeb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
b049d257-7b9d-41dd-b3e1-951dbe4ac03f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f0268693-54b1-4044-b223-2ed79203c0cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
34090bbb-eff7-411d-b2e1-aefde4191f72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
00293d19-6d71-4569-abb4-a9c93b0acb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
00293d19-6d71-4569-abb4-a9c93b0acb4c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
c6c68212-c2a9-4b14-aaf7-e0e6c3dd0d94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b12a9b2-01d6-44d1-adf5-4b4217c12ac9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c9f0dffe-e7d5-4266-aaa3-f9cdef01ce05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bedba94f-891a-4d21-a8da-a981e88b1f8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	06/13/2023		Muy limpio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1e8c43fa-b29c-4101-94fb-e0d3b37b22b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/13/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69e42f13-740f-4b5b-b4e6-ebbcac6e11cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d09e0d9c-3c65-48e5-9aae-d99acffe484b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6739c1e5-a5b4-43e6-b4cf-a7b814008889	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db51af8c-fa69-4b1b-b16a-f0ffd111ea6d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3cc81762-bf4c-4ad1-a7ff-b9c4680179af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e01bfa7-bebc-479c-9ecd-e9b9d8c8f584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
92119bd7-6a43-49d2-88da-d86843cd7738	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
efafe19e-f3bc-4c56-9c31-56d2507aa078	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8c56e86c-613a-488c-95fd-5c27e9e5ddb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:04:00	TRUE	FALSE			en-gb	14:04:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
33d0dba3-2dfe-4245-a02e-f74a479fc318	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
33d0dba3-2dfe-4245-a02e-f74a479fc318	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
8d76468a-d7c2-48e9-b1ac-eb4623e8156d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
65a75a49-b89a-4160-983e-f268b4e5b164	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b699dec-f49f-40b0-971a-f1fa2f916881	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55b2d326-965b-4e20-9186-69deb35f40eb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
ca7b7023-c113-40af-ac5f-97c17209bdde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
a1cbd307-5277-4ed9-9aa5-2b4186e82894	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
9df08863-ed36-4a87-ba10-8597fad5b1d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
6703321e-c533-49e9-a7c2-ec378a17bc3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
7c58774a-26eb-4613-941a-ad76e028f524	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:45:00	TRUE	FALSE			en-gb	14:45:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes												Yes					
5ad31c3b-921e-46eb-917c-15f4f34e71a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes		Yes			
13a3398d-3419-47ea-bf7e-d53c882a48c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/13/2023		Super clean					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bb4d374c-3fea-4f98-a69b-1b6d2a70ffcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b9e07b6e-41c4-4d88-b1f0-9b4c4ea4a6b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b2a64d69-ef72-46d8-87c9-6b233238016b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92ee2d0f-2e08-413f-a134-ed097ea53a76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41613341-a815-4cb3-a900-17bc1ea43c0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
59d331b1-48f2-4614-ba6b-8413ebd86a0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f4f3e509-2664-42cd-a4d4-571952b44f3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34273888-ea11-4bd1-8bd8-dc711a8389a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b52b156-1b49-401d-943e-2e141f170b0a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b789c4aa-96c8-41d6-ac48-67e085729b22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d1052873-50ab-49ec-8668-604a1b1234ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d1052873-50ab-49ec-8668-604a1b1234ce	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
59dc77f3-05b3-4f0b-bd40-4baeedde46ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
625d34e1-0137-4da8-a3ba-90e711122e15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
618aa053-46b1-48c7-9e43-c3b8ebd9f23e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
0e8c9710-aa5e-46f9-aac1-86c20c7e4650	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d53164b5-f8c6-4d04-974f-ae30b7612b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f97b01fd-fa8f-4a1f-99be-0c457cac1743	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
1aa26224-9918-46fb-baad-71283834e930	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
76ee4a32-ac1c-45e1-824c-351b32faa58e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1acee37f-f6bb-415d-87e6-4d2d18ce45d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1acee37f-f6bb-415d-87e6-4d2d18ce45d0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
bc9ec08d-5ee4-453a-b558-8653684e7d89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	06/13/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
cb14ab29-be31-4fa9-a59f-be568d0958c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/13/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
c6a2ef48-656b-4da8-ab26-a2a41f58fc17	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/13/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
b24ce356-42bd-455b-89bd-c5c40e117260	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/13/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6cfc4c53-bef5-41fc-ad15-d02d246d630f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
56f41fd4-06d9-4a61-8514-9b8f117a8449	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
27eb5982-c58a-4cd4-9011-9298a0ccd716	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
671b8880-dafe-496c-9d77-5f7b1d07a2b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
708887d5-0585-483d-b9ad-37e2ae587fa1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
dcb08305-cd2a-4e13-a5b5-52bdb3c3d87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
640f5398-e766-4fa1-bac7-0630707e05d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
8950ad53-0ae1-4592-b7ea-461e034b36b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
e2e73d4f-46b2-44e8-a2ae-9d177a0a982a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
384e06ab-8df1-4e9a-aff2-6fbaec2ebcbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/13/2023		Clean thisplace,															
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
51ed9ef5-a764-4abf-a956-6fa4d8e0da65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
6f20aac1-3677-4105-8331-80d521682adc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
07919649-981e-410a-8c45-633755b9071f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
422cc430-033a-4490-ae1c-a1592b9323e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
953457dd-cf1e-4bdc-9d39-8c8f13dd5faa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
806df061-d46e-498d-855e-5a0bbe4d88b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3a4c3811-4b2a-43ff-9ab1-7abc4b249b91	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f66b2fa4-d28a-49ad-9f25-62f54165f7d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0ce36dbf-5fe0-4855-a8a1-877bf2291bee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f37cd227-c65d-4a1b-91ac-f54da36cf35c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
f37cd227-c65d-4a1b-91ac-f54da36cf35c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes		Yes		Yes	
1ee91a0c-ff8d-4303-9283-783ac4f26027	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
40235b91-39f8-4f69-a01d-e08d5e97c606	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:11:00	TRUE	FALSE			en-gb	20:11:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
e9d8e2fe-7f2a-4e78-983f-ebee3b490020	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
															Yes		Yes			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39e6ce3c-70e1-4447-b19b-ea7fddfa4237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3e8993e8-4752-4b07-aa45-d665c1b32def	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4332421a-9495-4e15-aefe-b1a475aec070	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/13/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d09804a-837a-437c-8773-6febcccc40143	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/13/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ec2f54ec-4a09-4f63-b8ed-60824c19128c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4689cebf-51d2-49cb-a4b4-44b40d888120	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
655a2452-6008-4dde-a538-11b75793484f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e957cda-b462-492a-adc9-9ea04d73b9fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2d78203-f112-407d-aa86-4ff4efb0684a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fc422a44-6726-4cb1-82ca-1d980a4f906c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fc422a44-6726-4cb1-82ca-1d980a4f906c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
6a638dc8-c705-426e-a62a-4e496654e487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0413a0c5-7f1e-45b4-b848-db48c88417c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4884ce57-49f3-4063-bc94-d6e0e78c79b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
b857125d-7488-4be1-97e6-9e12389c3966	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 22:00:00	TRUE	FALSE			en-gb	22:00:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b857125d-7488-4be1-97e6-9e12389c3966	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes					Yes				
3013ec4d-7e77-4e31-8fb8-12bf221a88a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 00:40:00	TRUE	FALSE			en-gb	00:40:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d1f211a-442b-47d7-a518-9b4b94d8a949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 00:41:00	TRUE	FALSE			en-gb	00:41:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a48d436-34af-4ff3-9835-dd536834285d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 02:40:00	TRUE	FALSE			en-gb	02:40:00	06/14/2023		Gg
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc7b0fed-e977-4c2e-b670-e08e08862ebc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
10b9b71f-86d1-46ea-a704-3d5a5c244250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f018ca44-a800-491d-9db3-cff291cdb814	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 05:32:00	TRUE	FALSE			en-gb	05:32:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07e2fe27-bce2-41a3-8354-0889590ec5e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7a9abd4-784b-43ed-a3d1-0aaa18877bcb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ba2f05e6-7eb1-4940-9f6e-b461ac224815	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0763aeba-beb2-4de0-bc56-7ac49d308292	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
de9d2dfa-05b4-4eb2-9b00-9fcf3f435322	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2fae4fa3-18c4-43b7-ab33-6012f17d29e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0118a072-8b90-46c2-b76f-cf8b62fb3c48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c48dfe7-153d-4ca2-803f-38d86643a4ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9bd7a501-7142-4ade-9b64-c047912b1cec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1803148-f948-48dc-95c6-401a972237d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
127d21d8-f203-4929-adf9-3f7b5f3d9ecc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c048bc9b-a8ff-4555-9991-15852cbddcf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	06/14/2023		Hi
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2bfe4854-9c76-4bc9-a87e-5ddac7502cdb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f5f4fa1f-fd04-4544-8fba-a38258ea3fea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/14/2023		Quiten este sistema y den bonos
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0127ee84-a3f3-4e1d-9725-a5ad61bded0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e94d670e-03f1-4601-9ec3-6d0a7c599e1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
93da5ca3-21ec-4a23-97ad-1ce3eb871b98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b1a4ee8a-f689-4582-9aa3-a528377e4b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
171513c6-f2b8-44af-ad1c-c8ef9b57be0a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c9995351-9398-4ed2-b821-cd25cfada259	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50e018b6-4705-4b80-9876-43d84f9f56ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9bcc8928-5d16-4ea8-a5e3-33b0f4d59f49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8eac5067-9209-4fd4-90f8-971c1beb8271	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
65464711-e040-435a-b95f-98d1d9d365d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c3a03c4c-f474-48a2-8b06-a3c972da32ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes							Yes								
fb3d213b-83bb-489d-bff2-ad222568c60b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes					Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2cf102a3-e46b-45c7-9627-dbb016a5adc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
59ecae6f-708e-4b0f-89a4-bd2fa7684b23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes		Yes					Yes	Yes					
9d105157-55dd-4590-a99d-a5bef1a22043	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/14/2023		These restrooms are in dire need of an upgrade	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes							Yes	Yes					
ca5b9055-9321-481e-8db1-5231b7a19f6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ca5b9055-9321-481e-8db1-5231b7a19f6b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes						Yes				
48a81db6-ad86-4989-a201-8ddc3570b5c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b95f619a-435f-412f-bb83-9c0824052aa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ba06b9b-d9cb-4d6c-8554-2f8e0254e5a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
727db233-8a09-4f7a-967a-f08b9b8385ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:40:00	TRUE	FALSE			en-gb	09:40:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
7911b7fb-682e-4bd9-88b9-553a4b5d25bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
834966ad-3d65-416c-9814-07f8117d97fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
7e64e312-f506-4f36-8fa6-70eaaf60225d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
6bd9d978-d681-4567-adc7-2a3872108bbf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
846b6318-0ab2-40d1-8cc8-20b30be33da1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/14/2023		No		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
066a6b4e-a722-4a3d-95bf-625c28dfa493	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
595c69c6-c502-4f02-af34-e73532923825	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/14/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
5cc59df7-610d-4c6e-a6a1-f6fb46a2bc4d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:32:00	TRUE	FALSE			en-gb	10:32:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
49bc7d24-b96a-4b74-a472-862228164c47	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e306bccf-b07d-4820-9c99-f92e2445ac9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e306bccf-b07d-4820-9c99-f92e2445ac9a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes						Yes	Yes					
dad6bb2b-85e8-4588-9859-b3b22ecbe3f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a3d801f9-8cc9-4540-99e1-9dd65dd3753d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a58293ce-a84d-4163-ac49-11a50f394d54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cdcd4890-3f33-4be4-8bc5-c687e5e286f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5055cce9-5dac-4077-b44a-e244a4c804fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
8a997063-2cd4-40d3-ae92-db7e2b74f829	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
8b726a36-84a7-4aa9-8c9b-3027973f942f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
24f7065e-2786-45be-98c3-3da5dddb7808	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/14/2023		Okk		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
c227cb30-df03-4c75-b321-3e4293005585	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
ca5a078d-f03c-4c52-8794-7b6583baa437	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
494fd080-77c6-4219-bc28-7697d7a8d83d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
796ccea0-690c-410a-ada3-6c17130e5cfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3407d3a-86a7-4dcb-947a-890a294a1a80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d63dfc6-ba4e-424b-8ef6-806c80479281	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9792c88-0f50-4a6c-9c67-b1acb1c8c2a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
891b820c-fb80-4c6b-be4d-1364da9a15c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ffb939cc-58c8-4d27-b2f8-efc512af2014	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/14/2023		Well done job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0fe2a453-27c9-4da1-8017-e20493b65fe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f68958ad-a59a-47da-b077-fd9021534fe0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bf1a61af-c7f5-4d3a-93db-e1ed7d48d103	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c33b2ad8-a239-4775-bd02-b72db35f35ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	06/14/2023		Bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d47d8917-f295-4c14-b56e-0f89f99a428a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d47d8917-f295-4c14-b56e-0f89f99a428a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes			Yes		Yes	Yes	Yes				
5f13b7dc-ad87-4bae-b696-592975bce7a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
2a0d20f2-7588-4c4d-b387-7c5febacefebe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
2dd2099e-f7f8-4a0a-a275-76d0b5d2a46a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
67a8109b-02b1-48c0-babb-81c762238ed8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
90d11d20-f9c5-4798-a3c4-2b7bfb7e9fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86cdfb16-21cc-4b7f-98b2-11e5efbf01f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0bba206b-7730-45b7-978b-43bf6ffa7fcc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25273a25-6702-47f7-8fc9-83ebdda1476e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/14/2023		Very nice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0ca092f8-fd6c-492c-b4df-16159be95a32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
42acf30b-285c-4571-9a3c-aaaf5c35fb8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b054675f-c5b9-42a8-a821-f53e8167533d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c3387b00-d532-4a75-873d-00ef81c9078f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2cea799-33e8-4f4f-9854-5366db4fb946	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c5884969-c972-4857-bf7c-c36fad4e048c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24013df6-05c7-4922-b4c2-dddb3419e7ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c2363ac9-e2a5-40e9-b6f7-e29548cd7d08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0a5c8671-34f9-4007-bdab-79c76129b66d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2204a76a-63d6-4584-b862-95ad4f2a253d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1df0fc41-c8d5-44bd-b558-fc0f40b6b1ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
49e7e951-d7b2-42b3-9c37-1cb10f28f2c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
7859b9ee-9868-41ca-b3e1-03be1e124ed5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/14/2023		I love pooping														
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
a0a32f6b-5b64-45c6-9c6a-f0abb9d54d40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/14/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
9d5b8207-216c-4a9b-a3f4-59abba0d8078	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	06/14/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c13b7896-9d83-4e93-ae79-79bfbcb52196a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/14/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
							Yes	Yes																				
30863edd-2ed2-40d6-8496-d0e726da12c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/14/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
30863edd-2ed2-40d6-8496-d0e726da12c9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																Yes	
68468a54-2c74-4e3b-90e2-f7b90b89b879	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
64098916-e59c-4b03-8c9d-dd578449f2e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
b982ba37-6f2b-4ba3-81ba-c7fb9e42d7ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9d68fec5-d19d-4542-9013-3d519fbc1cb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1094ca85-0404-4d24-8bed-360b8e8db061	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	06/14/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40b8297c-dfc6-4052-a894-142cd3ac22b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/14/2023		Hi r	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
28ff72a4-278c-4df2-8914-47cde428a3b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
82d663d7-6f36-4cd9-a534-7caed3d16fc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2c7b02d-ad18-4856-9d37-b8f833b8efad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e13d191-ce53-4447-8493-cb612661447a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30069feb-511d-4b9b-aba7-a2ef331abb1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
886a4d0c-79fc-44dc-adeb-8641c2fab56a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40f9dee7-2018-4dec-915f-52d400aa9755	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b926513e-8d3f-48f4-a689-ebca2e5e85e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
449f5d5b-872a-451b-8216-f0717d5e1441	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	06/14/2023		mothingbto say just clean and make smell go away												
															How would you rate this restroom today?											
															Average	Good	Poor									
																	Yes									
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters															
			Yes		Yes			Yes	Yes																	
97c5e490-b637-466d-8e98-f65f5954ed2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/14/2023		Please do better at your cleaning job												
															How would you rate this restroom today?											
															Average	Good	Poor									
																	Yes									
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters															
			Yes		Yes		Yes	Yes	Yes		Yes															
5eece83f-1a1f-4f58-92fe-6b1ec302feb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/14/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																	Yes									
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters															
		Yes	Yes	Yes	Yes				Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f3d1e9af-47ea-4b8a-8553-c040e4bacd55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
415961cd-83e5-45a3-8f48-bbd48583eafc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
85edf7ee-44bd-4282-b3a4-3425142a4a5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
6c07c8de-1f5f-4855-ada8-31f01290b32e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
564c4054-0fe7-4448-9f51-b5ae73f58fb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7856fab-7a7b-4bed-9460-914c6c7a7ae5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	06/14/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76a1fa6e-9e62-4129-beab-2969cf52f281	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e62879c9-ca95-45b9-a9cd-1a9bd5398b9c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ddddec4b-a30e-4130-9633-12fdf76b9606	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52400589-29e0-4e85-bf4f-e8c0389179ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
52d14231-aef4-4d37-ba30-e846a9e3f3bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
9d893a41-4312-4204-8ddf-d5d5a329270b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
3b2e7385-152e-4459-8238-aa3d941ed906	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
9c230a02-d70d-46a4-b53c-34038c9045d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9c230a02-d70d-46a4-b53c-34038c9045d5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes							Yes	Yes			
21978772-9f21-4e65-a25b-39edc9cb4d26	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7840c013-67b7-46c7-bb77-3d1179fe4cc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0bc11463-32fb-4928-a6ae-b945216150ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c4a8b92-c0e4-40d5-8586-5f9a7ee74910	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24f502eb-12c5-469f-a3a1-09017341b160	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2fbe695d-c670-4b0d-a337-96cf37048f02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
60bc4fd2-6fad-42e2-aa91-99aeda0e4fa7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
91a136af-e4b6-4949-94eb-7ae73525a01b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes						
			Yes		Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d9a2d7f-7c12-40b2-8f04-af858d846f7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
67572691-9b71-4749-bfec-6c02cd6f61c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
331c2a02-6668-4379-81b3-890aa3270aff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4a236ac0-7546-4cd8-b39b-4afa9cf52ad8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes	Yes					
4a236ac0-7546-4cd8-b39b-4afa9cf52ad8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4a236ac0-7546-4cd8-b39b-4afa9cf52ad8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
287a90e7-3f8c-4d77-8f34-ecf7fa9ba21e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2b141fbd-f0d7-4172-8790-446cb1a0ff86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f651314f-fcd9-43bc-a732-efeb63dffca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
					Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
e01a30bc-ca86-4605-8c9d-dd67077eef09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
7c7ce5f4-801b-4364-84fb-ac22298812da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
45139ff3-b2c4-45ff-bc0a-537116b9ebb1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:56:00	TRUE	FALSE			en-gb	19:56:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
8cc93a67-e1b8-491e-b4ab-92c4eb13d37a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
df27ebb0-0f56-4182-8bb6-22e755e64d6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e4f6f515-84ee-40f1-90b3-c52fe890ed2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb0a38c8-4c4e-474f-8a95-cf18537541c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
01fe957a-85db-4530-9881-bef3709ce572	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b1deee2-0a2a-4502-8bd3-68a2cef451f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					
5d8e9c33-9471-4d11-a6c9-1ea623ac4bfc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
5d8e9c33-9471-4d11-a6c9-1ea623ac4bfc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes				Yes			
a08e559c-3d5a-44b6-8476-c5d3f289891e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/14/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
e87b5535-edaa-4696-ba04-4ae14b336395	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	06/14/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
cb47b0a5-3be2-4762-9327-6845bfb2af6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	06/14/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
48761e7f-3509-41bc-a92d-a392e57bdbf7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/14/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
f99f4f0a-5ec3-450d-a0fb-377d4c47fd7b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/14/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
96323364-14f3-4311-bb4f-f11e185aef7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8d8ab574-733b-4751-8029-aa685339b9ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
1d6ffc18-bf92-420c-9569-251072ec8f48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f79d019-e8f6-4686-a960-9a0db13782f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e60ef0a-ba42-4a07-bf43-e0ec333a71ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1601a26e-89d0-49cf-b4d7-6323a273e968	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b22b46f2-87b5-4931-ae48-7e156a3f4bad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4992c4c4-2e8e-4b3e-874b-25bb9f561b59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
7d020559-1aff-4f1c-a4df-2c78a9e0feb9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6988be7c-ed41-4562-8448-74a540c6b91b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
19af0248-12b8-4eaa-aea2-8b221d924cb9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ec2b5db-a023-4ea9-ab7b-f357b924e64e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
66fcd894-69d8-41c0-bcde-edd8062a0bf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2fb587a0-c5a4-4246-8d5c-7a74584ff576	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a421ac96-eb56-4c14-9bcf-ff068243cea6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 00:29:00	TRUE	FALSE			en-gb	00:29:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
91d58210-ad22-431d-8f8a-f9b8343d7184	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 01:55:00	TRUE	FALSE			en-gb	01:55:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
77454bbb-ebf9-47d2-a4a0-43e47be690be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 02:43:00	TRUE	FALSE			en-gb	02:43:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
18ebe53c-7663-4fbe-a3b8-233d56d5d47e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 02:54:00	TRUE	FALSE			en-gb	02:54:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea50af98-7b14-4be6-bb76-7c95497d84b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 04:31:00	TRUE	FALSE			en-gb	04:31:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9dcdeb49-82e2-4650-8d25-0f8f3e9401f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes			Yes					
964609f6-a9c2-458a-b47e-12221b706564	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 05:19:00	TRUE	FALSE			en-gb	05:19:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4756ed87-e726-4145-bebf-dc97b573aabb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 05:41:00	TRUE	FALSE			en-gb	05:41:00	06/15/2023		All wonderfull,	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2fab5716-3e70-41f9-a932-4e96ee3f167a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37a77af3-b584-4371-9284-af4cacac46df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0f681352-250f-487a-a7e9-85619fa05d6f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b8bf881b-e690-422b-b003-5c197013a470	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b117080f-ad3b-473d-a141-2cddce51fc2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
814c3e63-5c6e-4b3f-8222-65f24050c06f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d4513698-cc1e-4246-98da-b5e8c38d8d9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:55:00	TRUE	FALSE			en-gb	06:55:00	06/15/2023		Necesita un extractor
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
6e26aab3-e164-49ad-b9e9-230b4bddf6a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/15/2023		:)
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9de63138-4217-4585-8b2d-e80e96045174	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d6f759e-f806-4547-9b77-bf0de8d41181	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c3bc402-b8e9-4a3e-9f03-a148ad8f0a98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e724705a-5ae8-4df0-8fc5-bbce281ae44c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44537c61-3e75-4616-9bf5-aff009c5945e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6a4e977-0121-4daf-b9f4-dbc53bb12a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/15/2023		It was awesome!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d640b590-e82e-4ec2-82d0-0ca81e9eb14e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e1b92e39-d9fc-483d-9745-cd6d3e6c241c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30a6b725-b2c5-466a-b296-1a80f8473de8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a407386-d55a-4bb5-8322-dc149baddead	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d5504ef-b5ad-4479-b098-f516efc0e7f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3a3a2128-925b-479b-b239-6f6c0050c880	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2cea8021-eb62-4103-960e-22761e503d7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d9a144e9-f3f5-4314-b962-f840cc75af26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
db68521c-6310-4b68-ba1a-1d3a3f9e33e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
074867ab-3907-4091-85e8-b8783f2177e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	06/15/2023		Nnnn	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
696d4918-5303-453e-9e31-23b92357dbb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4fbdbb71-a7c5-4763-b730-6d079b763360	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6441832c-54e8-4c9d-a2fb-b6eddb62f909	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd8326e-1d63-438f-a49e-73a2779ab019	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5eb1d69a-32f2-4c64-813a-d7b0906a4b47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3292e280-3617-46b2-a4fb-b5dc1416997a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae3710ae-0d7a-4a4c-ae71-a698e2139eff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/15/2023		Your mo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b6fbed61-bd6b-4c13-b753-48955f0c30b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4d7e0bf6-451a-4dfa-ae9-013ddbc94fc4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
97464f7a-ef07-406a-a451-4e90c6d5161f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/15/2023		no	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
45212703-af4a-4b47-afbd-007580f37991	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
45212703-af4a-4b47-afbd-007580f37991	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes			Yes					Yes						
b0fd35d1-da4e-4573-bacf-393827aa7ba9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						
750e9381-d878-429b-b564-c191632e11a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						
b70489f8-9e4b-46a7-9edd-1cd2cc902d1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						
94c2a9bf-c4a0-42e4-bd2c-5f622ba5b274	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3e0c26f5-84ee-4cd4-bb07-5078c9f9145d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aeb9c38c-59e8-4478-ba4b-9eb505783328	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89d37cbb-aac7-4aaf-916d-c8fa467d8006	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/15/2023		Good service
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c11ff5a-6749-4628-80a2-70c24d1a21ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/15/2023		Friendly staff
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9309b91-7de8-45b0-949d-ac86f4b664fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
acf3fd69-4951-469b-96fb-04d15c1618b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	06/15/2023		Good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1da5d00b-95a5-4f9a-a051-92b0f8009e6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
adb4d2e7-7721-4d40-868b-faa9eb0eda83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
642e447e-1722-462e-9a6e-b63104f96935	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0cd4b88e-e85c-4e34-bc7a-d9ed0b08b497	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d85aaa0f-5912-4521-b60e-b787a5c40db6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f12c6a10-d98e-46fd-b00e-39ffd5c61321	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f4089d9-d47b-46ca-a8a6-012f6446eb28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/15/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
42141bee-f267-4f88-b797-b336bca0c57b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f5eb07fc-6eed-41db-aa68-e7292ed22259	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02d0f74a-140d-4e98-b713-ec0eac401523	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	06/15/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9905a39c-f319-46bf-a09e-decdd99f0479	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4d27db4b-2495-4a30-9a38-0a84255d0822	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5fba0fb-1b3f-443a-85d3-54d80759a015	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	06/15/2023		finish	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
								Yes							
d94b7b82-0b0a-4f88-a5db-294c0e54649c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a25c9608-75ad-4ec9-b1f4-56b910786521	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
064fbc32-8444-4f16-8f95-60107961b574	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9da6ddc2-8297-46a5-8c27-53bf5cd9c5a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
deddbdd6-b8d6-4c8b-8ba5-2071dbbceafe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82662bce-2c82-433f-bd39-a41188a51d62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a587876-d66c-41b0-af15-171d099c15b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b1cd9aa-de14-44b0-af68-7d822ebc275c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2d0e497-d7e9-46a9-9697-76131fa62686	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bb2e32bc-f5fe-4a5e-b853-ebb4f8f33483	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d966974-8ad4-42f9-9a16-a76a2b653fee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/15/2023		P	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4570bc22-f3b5-45d1-bb03-828044386ae6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46e34792-2ffe-418f-af71-856bd9165250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb7df57f-a8d9-42c4-8eef-83ee73aad9cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30104d10-1c2b-460b-b937-b5212084f315	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e16e93f1-0546-467b-a4c1-001e20cea106	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
16f524d7-6244-4bdc-8e40-a3039a3a9e75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
45261708-8823-4953-9f27-95e9cce3b13c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ebc3fab-a218-4e4a-9f1b-73bdde7654f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4ab660e7-f573-436c-9f63-58be334ababe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/15/2023		No she is really clear
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f98d2d0a-286d-442b-bfdd-20ac70150219	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/15/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5a098003-d552-495e-af3d-f5f3a29b6b00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/15/2023		Great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fe437623-d22c-4b4d-a793-4a553123bda1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/15/2023		Skylar
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2f2efb0-9203-4447-aa40-68ec66bf65de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6f43d6d2-b01c-439e-8e2e-47ae15c33442	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0b61485b-64b3-4b9a-8799-d2df83f76606	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
7dd3fff8-e485-4480-8c71-1482f3c4c811	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
82a45b27-b77d-414a-b8b3-e8f31206c718	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
4f24c7fa-6465-440c-a3bd-8c25ad966e20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/15/2023		love it
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
e39b2ded-1351-4491-8ec9-d5321d882619	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/15/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6d2e966-bbd1-4ffe-b915-66b592081e43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af1a0945-ed24-4c75-9ee9-4a4126a68f6e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/15/2023		Smelly :(	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
745506be-968c-4355-b11a-a033f59aead2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7481c9ec-0475-47f2-8bd4-90dfe113e1a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76745c87-715e-4197-9881-9e4efb9f081d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7af84ab-e749-44c7-9d04-d987efa3c516	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8ec67876-7ba9-4a6d-a5d2-5210058a2263	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed6e8f7f-4442-49b2-8f52-cb9078f76dcd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/15/2023		Hhhhhddhhhvjjjiv	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
daf06f0f-b9b1-4a19-aaf7-e0865625b5a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
856625e7-3878-4f60-b7af-5f52054de626	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/15/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9c65b074-7a8d-461a-9bd2-d239e647363d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a166b27c-396a-4902-9362-9a2d88b417cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
029648f1-2e4b-4866-b5b3-c05e4d864341	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
23493561-b155-4c55-aea9-4245c401ac0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8602bd27-634f-48c9-b315-243b8d678c78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
933bcd44-78ac-43de-b13f-647e3b223ccc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a768f188-5d54-48c9-afb2-fbda980eca71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
214de869-7997-48ce-af49-68d5979f88fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/15/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
66455150-c44a-4542-b7b0-866597727e56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6cdf93bf-07ef-4b6e-a950-41743e8af5d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
505b7ffd-d4b3-4448-a4d9-7c2379f01c20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fbd8f9e8-bfe7-42a7-98e8-8ce39c28aacb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
611529d7-b853-46eb-a87d-bd499e1d9e4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
45d255d9-abbc-46fd-983b-1228c8eba0bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c70ea77-999f-41ff-a0e1-8963c7c7f22f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5935fedb-3c9c-4d55-a4a8-69f89ac18aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aee71f14-354d-4c39-99c8-2d5421d576fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/15/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes				Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e42e75d2-3511-45a3-b3a1-0a73ad4f28f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3d232973-225a-4fd3-a697-50c07d183055	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0ac34b24-7e70-46f5-a91b-65031a50ecec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c131c3fc-9a32-4a69-8bb5-8565b9a180b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes				Yes							
71254296-677b-405d-9622-1f325f828e41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
71254296-677b-405d-9622-1f325f828e41	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
5a893f95-1ccf-4751-bc61-d06069c562ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
58c2f087-0838-48c2-aa17-0848b9cd992e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c125cab9-3103-4a1c-b88d-84bc169aaf7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8e73a84-17b3-4f60-b61f-f2fb4dd5cb9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
33fee787-d326-423c-8278-05d090baea81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:45:00	TRUE	FALSE			en-gb	14:45:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff937d3b-fd64-42e4-8b2c-ab737f592a88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6b46b1a8-6ea9-401a-acbe-1a18104ae6b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c2d0cd8-59cb-4999-b7aa-0da61e86a2ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	06/15/2023		Happy	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4cb77c0b-73a9-4c95-b345-4c024b0ae7b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
26431e3e-91e2-4c6c-85c7-69eb651246cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
26431e3e-91e2-4c6c-85c7-69eb651246cd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
73c9f0ec-132b-499e-9232-fadf25b6c801	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b29cf3b0-92f6-4707-8af1-232175048c45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38ea0407-94cf-4762-87db-485d6dca7bac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d68d1b28-aff9-4da1-82e2-05a585f018ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
e4446cf5-c867-4f28-b153-a864322f55f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/15/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
b0384ed3-621d-4d32-98db-4397ec409334	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/15/2023		No															
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
aaec49bb-afc5-4d5c-8886-ad437538a093	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/15/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
ae4b0bd4-3b16-4c5b-b12a-983072380006	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/15/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
a442c894-d092-474c-b598-12a668f346db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/15/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d12148df-1f67-48ab-a279-e0f89eeeb8ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cf1580a1-3bd0-4c31-9d73-2677b4e7c9be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e2ca6c8e-bf04-4dba-a7a9-e4351893f2e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
18eafc29-aff0-4485-b100-c60584b97af3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0f2444f0-b10c-467b-9755-b7cb01775a07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
595a214b-af56-47f2-a273-6f601d396bea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cb8b4555-5ab3-485f-9e96-5a11ac635d9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/15/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
28f5f5c4-4753-46b2-9d4d-d3ab29f725fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4ca129c5-d51a-4f4b-9321-93899c52d8e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
96e66597-2e6e-4208-a0bc-8c1e42fa5556	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
adace830-e886-47ee-9c20-1d9987ea25c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7e26cab0-fac7-456b-a316-4e105ae0450b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
c3fdaaaf-f111-4205-a9f1-5674472e65d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/15/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1fef5ca-6103-427c-994b-4b7dea3fc1ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
27a15c50-f5a5-4a15-b44e-cbd5a6378a38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
fab6a27-a628-4bd7-aba9-bfb624cd7851	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	06/15/2023		Gross
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9b48ba78-835e-4dca-9137-57825ef811f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9b48ba78-835e-4dca-9137-57825ef811f4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes		Yes		Yes			Yes	Yes					
8a85fb86-6c84-4625-85c3-7d14b2fc6c13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
db6afee1-72d0-47a6-96a0-87eb8ca1ffa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b3baf87e-3b43-4134-a3fe-0a8d79db1a1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
51cfafe6-e3c2-4b49-89b9-7c0f5d31ca2f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6005525c-0897-4a18-9b5d-179b555742f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/15/2023		Nice batgrii? pp	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e6749618-5a56-4f2b-aa31-d2ecf9aad2a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	06/15/2023		Appreciate a bano	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
498e8344-e525-49b8-8248-67b71001f7e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
498e8344-e525-49b8-8248-67b71001f7e0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
03dbd79f-9a1e-4367-822f-71a5213c2f03	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
04401afb-5d6d-4268-96f4-190e5e0e4a6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
069e1636-4d00-4f8a-8f79-1ce1f636a5af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a33b174f-1f89-4454-ba89-1eb3831f5bf1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
656e8e86-176d-4e60-bc39-ec9425a9f247	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f095d760-2999-4000-9cbd-b467d810aadf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/15/2023		Its very nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cee1d218-d5ca-48fd-b338-aa695d23c603	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26973e62-9254-46c0-b991-f16bcc6e78fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1ff33a3-b0ad-47c8-b135-c75bc71a8269	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f1716dd2-3ef3-4879-841a-2112e34abe5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/15/2023		No ac
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f1716dd2-3ef3-4879-841a-2112e34abe5d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes					Yes	Yes	Yes						
f4fd0dc5-b550-4ccb-bb06-e3d713 added8e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
1e7fe1dd-2c06-4a68-a516-c6a85d25b75e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
dce7dcab-547b-45a7-8d3a-04be9d2d6e15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1a93bc4a-a227-4b49-8da6-340adf25ab63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d0ff657-ec1a-489e-a848-977775d81aff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/15/2023		No soap	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fb4b3df-3498-417d-a89b-73c8304bfa76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f1d32e8d-ba4d-4322-9cd2-d6d8091e18ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:24:00	TRUE	FALSE			en-gb	20:24:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
e03de3d9-0099-4055-9916-8ed8a0ccd1cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:25:00	TRUE	FALSE			en-gb	20:25:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e03de3d9-0099-4055-9916-8ed8a0ccd1cc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes	Yes								
fd184116-8f7d-474d-bf74-c3e28766c826	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
89ff6400-dcf6-4d4a-816f-fe564ec537ad	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes	Yes				
89ff6400-dcf6-4d4a-816f-fe564ec537ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
00f3c1eb-8006-479f-8af8-d07a85377045	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes						
00f3c1eb-8006-479f-8af8-d07a85377045	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00f3c1eb-8006-479f-8af8-d07a85377045	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes	Yes							Yes					
1f39d91d-f7b0-4f8f-aa27-d5ace0b0681d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6149596d-1f7b-4a34-8a53-94cf6f2020e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53a70e8d-42fa-4c4c-afda-e5cb1a6f25b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7c948337-4112-45e9-a1cf-3b632c7f4160	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a83296c-9ef5-40e8-8614-31975f807c3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	06/15/2023		Nice and clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
35dd4451-6c48-4b19-90a5-804ee423ef07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:57:00	TRUE	FALSE			en-gb	20:57:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fcaf0907-6dda-452a-92a8-d40626be9128	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes									
2fbd52ea-7a9a-4cac-8984-32325b44ade8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
69429ffa-b013-49f1-848b-e5f3cc3d7516	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f2585948-ece6-40b5-9372-20a7479555f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:00:00	TRUE	FALSE			en-gb	22:00:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2585948-ece6-40b5-9372-20a7479555f0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes					Yes							
7ed7246f-f724-40ab-ae39-c3352ba1c3f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd992598-ec80-4dd8-93d7-9c25670dd89a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:39:00	TRUE	FALSE			en-gb	22:39:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
19357a97-1436-438a-a531-4a526115996b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:51:00	TRUE	FALSE			en-gb	22:51:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3be36111-4b8c-4250-82cb-2ddb9ecbec81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 23:18:00	TRUE	FALSE			en-gb	23:18:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes							Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0421ba9c-c2a1-45ac-b6fe-321b0c1a5df9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 23:36:00	TRUE	FALSE			en-gb	23:36:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b5b71435-730c-4ea0-a459-37dc976bad66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 23:45:00	TRUE	FALSE			en-gb	23:45:00	06/15/2023		Trash	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6b70dc78-fa3b-41b9-99cc-8257bc1ff4d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 00:03:00	TRUE	FALSE			en-gb	00:03:00	06/16/2023		Yuck	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e2531759-d448-4250-b168-f8b8033cf463	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 00:54:00	TRUE	FALSE			en-gb	00:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76d33e1c-7259-497e-851b-4d84e7629194	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 02:13:00	TRUE	FALSE			en-gb	02:13:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e08cb44b-f4b9-4c45-8353-9d619637b795	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 02:23:00	TRUE	FALSE			en-gb	02:23:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c729235-d45b-4128-a1bf-af2700efac26	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 03:32:00	TRUE	FALSE			en-gb	03:32:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5d4bd806-ae16-440a-a6af-8fde2f2e0086	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 03:56:00	TRUE	FALSE			en-gb	03:56:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5ef2a309-2aa3-43f0-8838-69801e867aa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
be27f2ed-577a-409a-91ae-300337a7da23	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2808a3f6-d5a8-4c19-9e4e-4c1a25bd881e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:11:00	TRUE	FALSE			en-gb	04:11:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3fbec991-0fdc-41a4-956b-ca284f6f4b41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:17:00	TRUE	FALSE			en-gb	04:17:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c8735c0c-5238-4909-9af2-7e215c1d0d1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:24:00	TRUE	FALSE			en-gb	04:24:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d053ff39-2bdd-4c69-989f-d409e0a85652	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 05:49:00	TRUE	FALSE			en-gb	05:49:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e92c59b4-f669-4c91-b89f-f3f0a3fb1106	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
506b69be-53ef-48df-82dd-5a1a92836416	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41d9a56a-c2b7-4f78-a6b4-228d9110c542	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:42:00	TRUE	FALSE			en-gb	06:42:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5dfa817e-acd2-4463-a669-9ad0fd1473d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
30e3a7f7-9157-4864-95b7-6f46c53f4acc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eee6170e-bb01-4db6-919e-bc8b6829275f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
438ff9c7-60eb-4df2-a89c-a527bf8200b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ed8292ff-a2d7-430d-9c26-2f85a2e8886c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/16/2023		2171
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1e2408cf-e03a-4320-b07d-2bd783dc879b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
784697e6-1d74-4bc0-bf47-64bfb0db5498	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8d27203b-ac6d-4e69-b14f-98115b08734c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
25b0d6cf-d590-4f51-8185-1bdd361a6e63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ff32ac83-2895-43e0-b5e7-1e3a3d1e0b4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f97fea52-8bae-49a6-85e5-5be1b191ba9c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d1cbb55f-d61d-4610-b3ce-dd5173a619ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8501be78-d504-4918-9052-edef0a453fe1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11434ec1-c4a0-477d-bf1d-f6fdb082f9e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56a4faaf-eb03-4d56-994b-3059d3846820	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:25:00	TRUE	FALSE			en-gb	08:25:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
307b1186-a812-4ff1-a74d-7969373ed760	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e217b410-f0b2-401c-9ee9-999619bc6605	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c580a8c-474a-4b89-80bb-5b138f45f59d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
bf6b7090-556c-4501-b2a8-27e1d30e4cea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/16/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
81fa2f2f-b121-4791-a248-bdc4f303f0ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/16/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
b4618d2e-0b3f-4caf-b28a-dfe295d60847	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/16/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
036e0f59-1947-4fd6-bb7d-07796d08c911	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/16/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
228a1074-ba70-43c2-a047-b9d081e93c8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/16/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d8821736-102f-4e3e-b3ed-543107a87f26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40c0c2c6-b007-4ccf-8138-94058d6f2b16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49c0712c-229a-430d-a290-2c0e7c36250d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8110144c-7e38-4387-a92d-890917700766	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f017c23b-ac83-46c1-a414-f6999c30786f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24ac694a-8c49-4a6c-bd59-7e9cb95dd61f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7ce6015e-0119-4939-9b2f-1f63b08bdbbd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
793e2609-9e43-46ea-b5ae-29e793ae9157	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cfec095-d920-4d40-9407-2ba6a79d1310	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2067b483-7f7d-44a5-a6a4-53a63a567b5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
decc63c5-5830-4699-81bf-a9c0085a780a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0df57e10-5c12-4b71-9a9d-f9bf088560d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
80b0680b-3e1f-4394-aeb4-f81b74dfb869	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:40:00	TRUE	FALSE			en-gb	09:40:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da450d38-847a-4f89-b0ab-061bbcfe198d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38d4aa81-dcde-41fe-b8f1-6b59cb3691b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
48cc94c3-2ce8-4ef5-affc-4fd0973a8540	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aaf145be-0868-42e1-9063-2bf2e0397b0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9f8da58-4dfb-436a-a6c0-0df6d3e840d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cfe2b4f7-6f2e-42cd-8c32-da567141f954	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
33d98b19-6db7-4228-8ac1-cd5692618d56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
979ce079-2701-4ddf-9b8f-635b79b3a0c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d80c8634-22b6-4294-9d68-b42adadae863	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e2383f35-d049-4ef6-8718-b501bf33cab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5c0dd423-34ab-4e91-a778-646ca30980bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:17:00	TRUE	FALSE			en-gb	10:17:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						
d3aa396c-0e78-4742-8e88-b363feb2ef92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
								Yes	Yes						
ab4dd315-95fc-4873-ae3a-b45190ab298a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
39c8dbdd-a6f1-4b51-a2f2-4246f25b17cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8652ac17-fadd-40ad-b46b-7ac5337347ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eea939ce-b79f-4cc7-a2df-c151eb1e9485	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/16/2023		Mejor le dan bonos
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e9c057e-29ce-4723-ae70-52feed4825db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f9b2c8a7-98e7-4487-9441-78e590a3fa16	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22d41656-c819-4028-b962-1cf790e6a97d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
06683d1b-3ec6-4ee8-af21-c2e68a7af18a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/16/2023		Nice lady
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9b94c299-a7a8-4b36-8680-76f99245115b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b2783416-18f4-445c-8f99-262a799815a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a051caa-0f54-4ccf-95d4-a174fce17887	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
01120c71-96a9-4dd2-820b-4f71c46082e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
efbb87a0-6238-48dc-ae94-1cbbd7a12d76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2009baaf-4d41-488c-a46b-018af3494228	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0947503-34e5-47cf-8c18-07fa2d0a6e76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes		Yes	Yes	Yes	Yes		Yes	Yes	Yes						
df8dbbf7-f5da-4ae1-8941-f8c28611806b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
56aa8299-b972-4616-a6b7-33278f822a15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:11:00	TRUE	FALSE			en-gb	12:11:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e4195538-5f16-4cd0-9052-5e154077c705	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:11:00	TRUE	FALSE			en-gb	12:11:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
401320da-ffec-4ab3-914f-4c4571cc9796	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bd26fbc9-ab4a-4ef6-ada2-858c71fd13a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8007af12-2e0e-4dba-83c1-49f479df1857	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3317c9a8-4141-411b-949b-184d2097848b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a04a3daa-2ed2-4d41-95f7-46a601348a46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
786b2709-90cd-4f07-870d-85d70cccec5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8ba4d2e-31c2-4357-b080-f696a8e688fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
13f259c7-2c77-42bb-a9d7-05b4aac10f4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0200b63c-a363-43c6-a395-37cd62b9b7b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b8bcd23-d5be-430d-9c24-465d1ac0f0f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
36a06086-0241-4656-8184-1f3485cb7aef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6791d142-bb23-4abb-9a3e-a210bd9b2faa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes								
7948b790-4b9c-40eb-999d-649af350958a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
70859568-22fd-4d14-8498-248c7a77c942	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bd21f390-63d0-44be-ab09-6296053e2312	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	06/16/2023		Great assistance!	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2d213e47-2d40-425f-9d27-ba326ecae0df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/16/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a9e3298-bc91-4d41-9bfd-7b7bf677aa7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
77a26185-0f37-4682-a7f3-a518e3d37c1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aa01e9d6-734c-40d5-a543-8a515afc4fa9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
00eb1c1a-df38-4dfa-bd1c-c08dd19b0707	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cdcb146-2475-4ed9-9350-ae2442819c9a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3a107d50-b4c2-41f3-a14c-7d01a8b9e016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8405187e-e182-4d7e-b92c-816c94313bce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f914da9e-8e72-4d59-a7ad-d3c498c9d13f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
64cb2e17-bf68-4010-b830-8db6e715ac40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
185835e2-9c01-429d-8caf-512d2861668b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4a7d2779-3da6-4dc5-9253-7719b94a7edf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dbf1b5f0-8d76-46bf-8269-af20d24e279b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ce32d4a-cb97-46a9-aba8-7064d3df2654	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
259710f9-9233-4b47-a374-4645d61bdda7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/16/2023		Gaps in doorwtf	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
f0d857e4-3cc3-4685-a8d4-88dbebadf9d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/16/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d7ae5992-2f82-4676-a3c5-0b28cedf9f90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8eb2e46a-11f9-4935-be6c-30f5422d73e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
805bba3c-9748-4b26-8117-55637edefad5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fc8b2224-4132-423d-8581-36dcae7025b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2d65e61-57c1-4185-9b15-d16315c83a56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c7553b18-1853-4df6-b6a2-6dc10fcd1554	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22aeb041-703d-4636-a9e2-abdf15403024	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/16/2023		Caca
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1645d352-75ce-456a-8f9a-2daddb6ee7a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
6837f1cd-f9df-47b8-b582-e7387efe2b71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/16/2023		Fix the bathroo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6837f1cd-f9df-47b8-b582-e7387efe2b71	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes		Yes						Yes					
3e0792f4-6569-4ce4-825d-1e511d0ba7ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/16/2023		Fix the bathroom!::						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
cd64ac49-78e3-403d-a5e9-0f0f4f7128c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
946f568a-88a6-480d-9123-a0d9bf518f5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
0da3c98e-e556-478d-a246-870ecf1f9c88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b73e490-f526-433f-8db5-301173176da7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2e1e0a17-57ca-49a4-9388-a99976eb7470	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:57:00	TRUE	FALSE			en-gb	14:57:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
84385fc6-458c-442a-b627-e2bbf95668c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6295096c-5dbe-47f0-8453-38c711070eb17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/16/2023		Urine mostly	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ce4dcf18-7b07-4f4e-a30d-1003c0909072	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a9f45584-5e34-44dc-b799-461bb1703f80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
288d4ddf-5b98-4fdb-9c18-06dce47ecb5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c33e6862-ee48-49de-b1ec-19e2c2890067	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
57eefc4a-7475-4638-8650-dfb5088bdf5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:56:00	TRUE	FALSE			en-gb	15:56:00	06/16/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5f07c7f8-793e-4b11-b83f-cef72d0db5da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d9b6d95-feb1-4b0b-8ebd-175cbc99362e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fa875364-d332-4cd5-af44-2deccb0337f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f00e47ca-642c-44fe-992b-1f6c894f9c61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f2f4b437-b610-4c8b-bfb1-a3a92e0a7c8a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/16/2023		I love nuts' i didnt see any naked men	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
				Yes	Yes			Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
08afc6f8-5df9-4062-aac8-7846a186c246	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29ecde04-1c5e-4c4f-a55a-f772fa17e750	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d5e05230-2c9c-4d52-b57f-0849ccdd06d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f370ae04-a40b-4e30-8853-f91087e56450	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
042037fb-e4c0-420b-b786-bc0cf1f496cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c81f6211-4b3a-4e53-82d5-c900feacc17e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/16/2023		Yuck
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c81f6211-4b3a-4e53-82d5-c900feacc17e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
1c0aea90-bfac-4456-9cc3-a4ccad8985dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ec98863-45ad-4336-88e5-8efd363ac906	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9af6500c-627f-471d-b358-06fe038f9d49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d245456-598f-4acb-ab21-97edc9820e0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
548ad305-60de-419b-b5a4-c216bf47fcc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/16/2023		Ran down
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
548ad305-60de-419b-b5a4-c216bf47fcc9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
c6d9e503-942a-4f42-92f3-a5fc536a7e50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	06/16/2023		Hgj	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e5460c2-2645-46eb-90e7-227dc90d2693	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f67a036f-1989-4ff0-a875-1f7d2c1473c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d00fd8c2-fcb2-4c0a-8372-6b1ad3a703df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
11c6eb21-c095-4b50-bced-4a63e84911f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2de4f2aa-537b-4875-85f6-cf812dabbfe6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
426283d4-049a-4c6c-8235-3adecd7851c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b19ebacc-2d01-4570-abfa-112309e52188	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14d90869-3e67-4952-938d-f0a6b789aeee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
14d90869-3e67-4952-938d-f0a6b789aeee		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes					
0363f20e-9a9f-4ac2-aa39-43f9719e3151	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/16/2023		Good
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
bed0f349-1cc1-4aa2-8f3b-36f8634ec553	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/16/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
75038ed0-e739-4c1c-8fc6-e07a1a89dfec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	06/16/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
45cde2ca-790c-4053-bc1a-a9e1c70a9089	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/16/2023		Not
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
bb0ebf6a-fc93-424e-8c7a-67067134656c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/16/2023		Hot, doors don't work
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
bb0ebf6a-fc93-424e-8c7a-67067134656c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
											Yes		Yes							
0a276e04-8d19-4cad-8325-293d53f7847e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:24:00	TRUE	FALSE			en-gb	19:24:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
04c0a3ed-2761-4ae7-abd9-aa6d507cec0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
f8f15a86-d1f1-493a-a04c-58e6086b7b8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/16/2023		Good						
	How would you rate this restroom today?																			
	Average		Good		Poor															
a32de37c-146a-4221-8efa-d4652553a988	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
8743b5d4-104d-4787-a713-72b48ebde7e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor										Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8743b5d4-104d-4787-a713-72b48ebde7e6	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
2de575bf-9c80-4391-832c-3b819a66fbd4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8f2289b2-b520-407a-bd47-b51dd6d4e63b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb1afe73-c1be-4c0d-8bb5-eb79897ae4e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca9819ca-93e3-4827-89cf-e23509134a93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/16/2023		Clean more
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3e3273c-8046-45d3-a3d7-e1e90e7ced6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
10769f67-945b-4dfe-92ae-77fb827f3ea6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
94ea97da-9444-4098-bd8a-815bcf580478	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b70ef368-1495-4293-a5d1-54f606e863ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
894a4f82-d7f3-4163-8d62-27c1160997b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
894a4f82-d7f3-4163-8d62-27c1160997b3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes						Yes					
88389f85-b02f-4e1b-8b54-c5ffe102ad5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9976f3fb-7e10-451b-a0d4-74b73efa9e9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:13:00	TRUE	FALSE			en-gb	21:13:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b8ef08b4-2c45-4e31-a238-6275f65921c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:15:00	TRUE	FALSE			en-gb	21:15:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c898d79-f29a-4e79-83bf-f741a987708b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9063ae48-2f21-4220-9887-0a9942b0eec5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/16/2023		Amazing
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9063ae48-2f21-4220-9887-0a9942b0eec5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
fb65ba8c-c5bf-4e12-8a71-76e4b9116842	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
8ccd274c-3ed7-49f0-a117-9d183b722676	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49c4efa9-fd96-4a49-bcfd-29e7fdb7c2c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a17be264-7cec-436a-bf0b-040980b82e1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/16/2023		P	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
47080e52-4e23-4cbd-b244-a36430d43e7b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 22:41:00	TRUE	FALSE			en-gb	22:41:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b5be2d87-dd26-4c3b-9adc-70f0b25cc8f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6cb9935a-2c56-4043-98e2-b6f89705efcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 23:33:00	TRUE	FALSE			en-gb	23:33:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6cb9935a-2c56-4043-98e2-b6f89705efcf	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
9aa215e6-796a-4b85-9c24-545fc2b0a50f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 00:12:00	TRUE	FALSE			en-gb	00:12:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4b60c8a-bef2-435c-9f15-aa0f287d49db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 00:13:00	TRUE	FALSE			en-gb	00:13:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8117e09-a229-47d4-aa38-6d5a6d2c1045	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 02:02:00	TRUE	FALSE			en-gb	02:02:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
51cbf3e2-12d9-4282-be95-b458569bacac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 03:52:00	TRUE	FALSE			en-gb	03:52:00	06/17/2023		;)
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3ace4877-325d-4d1a-9330-ed24288515f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 04:04:00	TRUE	FALSE			en-gb	04:04:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4a504942-afae-4931-a0a3-774529b5e747	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
116c174f-1ee0-4fa8-9541-ed551f7f5106	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 05:40:00	TRUE	FALSE			en-gb	05:40:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
defeb090-7a11-4ab9-8fa9-385c95b88942	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 05:48:00	TRUE	FALSE			en-gb	05:48:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d2937e20-7636-48ff-9a17-d253ba486e4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ab0adea4-02ca-44bd-b9d6-1202b6bf4c8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0e9016d9-3a28-49fd-93bb-d3000babeaea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9263b7bf-79b4-4eaa-b9a6-d420f2653515	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6cc0ac94-29bc-4be5-b748-3cb066bbfc0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f7abe372-e5a4-4dcf-b1ee-37d2680182de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
131bfed7-7cb6-4278-914f-d8de25e35083	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c684e002-1480-4554-8caa-794a4b57d679	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5ec65d46-ee69-4d16-a877-505de2fd6356	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea281ce0-b544-4eaf-9b64-8cca30c4f056	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:15:00	TRUE	FALSE			en-gb	07:15:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9089f1c5-4f6d-4183-bb94-b3e98683f023	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:18:00	TRUE	FALSE			en-gb	07:18:00	06/17/2023		Excellent
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bcc50dc-7c6f-4e54-8fc2-6c0ac7193eaf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8ed183e-c917-45c1-9480-2f0ed643b89a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a7373106-8e04-4f37-9d28-fec18b27a8fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f686d5ea-301e-48dc-ace0-144190dfae5a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5adbc303-b978-46e2-aaa4-e924657eb590	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e14394c4-db11-4f5c-ac41-9e463c73faf4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/17/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f1e71b66-c41d-48c2-b003-751fa9669f9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28732e3a-59fc-417b-8aca-2a6e4ae6b7a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
370c1cc8-e54b-41bb-8b38-5c5dbb600c99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c983eec-191a-44d7-bd01-3d23daf60a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed2bb737-f0c6-4d72-af53-feb9e99ff8c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37848a07-92cc-412f-9dd8-b3dc38cbf0b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
46035f56-2d59-4c87-b668-8462ce004724	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ac64f93a-d52c-4dff-a50d-9b6c3471e2b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b27d67b9-334d-492b-b844-cca31a7643d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cf7d6520-07b9-4223-9f46-d60bdc20f5ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5362d4b6-ef9d-4ef3-9998-999ac092e7c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aa645480-63ee-493b-ba32-5d22f3b7786a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6021e00a-32c1-49c6-80cf-b5ce7e697853	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8900ac6d-acea-4a24-b9df-03228c2b4f99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4d8f4cfb-bc8a-46d0-ae2b-50a62b336315	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
761bf3b-873c-4ebd-93eb-e407ee7d2ce8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28b26e93-3564-4abb-b9b6-194d0fa6f062	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/17/2023		Need air freshner!!!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2e111fce-4e4e-4190-8498-2ccc78ee03e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a7d7faf-bdde-42f5-b320-50d6c3f619d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd2af91b-2710-4a79-a92f-1c461232fe2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
682cdca2-985d-4ac9-ade9-4ca0490f1110	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
522b0248-96f5-45a2-95d7-c1f61f0aaaa0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
76652034-f3fa-4457-99b6-7581f6989265	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
09ce0885-e73c-4533-941c-ddead8dcfb89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
cb7f5d78-d85b-4a4a-929d-3a6f3e092eaf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d079da5-df35-4e3d-b005-05c1e319d1ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4787fcb-a-d673-4596-b6f0-6b69ccb2ef07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
532065d1-c3fd-465e-aaba-8959d7fa06dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
58d4ae62-44f1-40c2-abc0-6d0fb76189e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	06/17/2023		Cleaning should be done more often	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes	Yes			Yes		Yes							
52a9b6a0-bfbb-45f7-bf7c-3b91d08aab95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes	Yes					Yes						
679f0e18-08ab-455d-a5c4-dca3dd280621	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/17/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
679f0e18-08ab-455d-a5c4-dca3dd280621	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes	Yes									
6ca79573-6662-4325-a251-524a7922c15b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54ae6ee2-fdd3-44db-bb49-9d1e75ae5c2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9bd4a381-52e8-4ca5-9a1a-f4c6f4bdbe2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d67fdf7c-3a4c-4d2f-995d-9a8f812a2c7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
67f51b3b-f111-4f2c-b75c-04bece56da25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
05d57f81-1bf9-41be-9585-d07c4f06fb24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
84ad0659-694f-4417-a394-f0cfd2094a8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
af5dbff7-bd71-44c0-90a3-0ceb02b1eaa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b262655-9c89-45de-b230-c62ae03a6423	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
913660f3-4f90-4144-b17a-955893ffe22a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
a4caciaa4-d7a4-467a-989e-0a92ca4c4d73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
feabe875-3587-447b-98f3-7e22498f7349	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes								Yes					
67aadd7b-fded-4d06-b3c8-fe24c15e5a38	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes										Yes		Yes					
d52db78b-b263-452d-9dc2-d6d130b2959d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d52db78b-b263-452d-9dc2-d6d130b2959d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes	Yes								
965d1195-5d38-4efb-aafa-96520123ef07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
028235a6-9c11-4c02-b725-fd8f63c06108	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
500a0e8b-a030-46bb-a0c9-defdd29f961b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca77d080-6a61-4589-b7b3-52ad0a24d0a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a883c40-da5c-4d9d-bde7-f1801f0de9b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
47b04755-e467-4450-9c9c-248cae032114	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d654573f-fb59-4baa-90b9-c637daf56211	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a1571ca4-6814-437a-9ae0-40e6603c37ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d058fd78-4d94-4b3d-b0cf-2e4f01b9b91f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8e1f2a4d-af00-462b-96ac-716415671c18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0b962fb-4daf-4fcc-8506-0a39c6b82e1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/17/2023		Sucio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38355e5c-9000-4477-a783-eb09ca342751	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b274968b-c701-40fb-9adc-793c2dbd6e47	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2868bcf-9390-4779-9c44-c7f7a93e6222	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ff88c5e-c309-495e-b563-0edc32a0bfcd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
498668c6-aca2-43f9-9b32-a4f61dda0890	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88cbc687-f6f1-4ba9-8cca-7851ead8c8c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
88cbc687-f6f1-4ba9-8cca-7851ead8c8c3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes		Yes				
90815988-9cf7-4d52-b5ca-d3b0abce933e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/17/2023		Ee
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
90815988-9cf7-4d52-b5ca-d3b0abce933e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
35b39272-f335-4110-827b-002552b2a28f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/17/2023		Ee?
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
35b39272-f335-4110-827b-002552b2a28f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes	Yes				
1b04ecc1-80d0-4c15-b3af-484f7001ee9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e3e3c683-c297-4d42-83f9-3e3e0890cc05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ab59740-ff3e-486a-83f8-9ba4043fb9ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8347a2f6-ac9d-415a-b25d-b8c00aca8c0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6b0367b5-38bc-4e94-bb77-802706bae145	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d561dd41-9371-44b8-8f79-8bd0cd482961	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:11:00	TRUE	FALSE			en-gb	13:11:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f851b56c-9e33-400a-a7a3-a0cc4246bed0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d2e5161-91ed-456f-b155-a65e6bada196	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
26d3523d-9fd7-4422-bd68-f7ae6bd4b412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41dee8c2-e480-43a4-91c0-c6a8d723f10a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
172db318-5ffd-4553-b121-4a06ed2f7b40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
172db318-5ffd-4553-b121-4a06ed2f7b40	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes						
07c32805-eefd-4399-b9d5-2eb82d56eb41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d96346f1-0974-40f1-ba9e-5c7f46266084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
0b432192-1144-4704-ae5e-de01e2d2a993	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4231302e-dd5c-4ae3-80b3-78ff26353491	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4231302e-dd5c-4ae3-80b3-78ff26353491	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
f4cf1213-bc87-4318-9604-0a708ccc064f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:20:00	TRUE	FALSE			en-gb	14:20:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
374d8aa1-e96d-4b8e-bba2-793c620be2c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes								Yes					
8ea9b318-30bf-47b8-84d1-3cf306219ade	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
8ea9b318-30bf-47b8-84d1-3cf306219ade	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes		Yes								Yes		Yes	
f9944a24-b560-460f-bb75-28f1ab017671	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
c5ade74b-5fdc-48a1-af53-7abfa785b85d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
cc39922f-691a-4785-b51a-3040c21e76f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/17/2023		Smelly. Pee yew						
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
														Yes						
59560b28-dfe1-46c9-a0c5-e43cbbe80acd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
59560b28-dfe1-46c9-a0c5-e43cbb80acd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes								Yes					
ab640f8a-fa66-4352-9828-f84e44d7c9a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
6448114f-cb0c-474b-bb56-c4f899f36182	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
b3b97a4f-fab9-44bc-b08e-0e79e3c6657d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
25285a27-8a2d-4f2f-9ea1-b72c7f606b30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55cce35-a71b-4e1d-900f-b9ed613e1070	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes			Yes	Yes							
be8627d9-c835-433f-a5d9-a666afdbd1aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c59c550a-ba76-4d00-914c-ef498af5d2f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
218b58da-17d5-4521-95cf-4fba40996590	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9458942-ed57-4251-b8c8-426386ac63dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f666a30e-c95b-4538-8fab-75861e2f8608	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f0cc821-0d73-4a8f-90c9-fe47795b8c5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/17/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
867c1974-4626-4844-be6b-7bc68bc8edd9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes		Yes		Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
99a940d8-146a-416b-8aff-780d88d71bbe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
e8b138cc-df0e-4327-8445-e5b928b7aa30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes		Yes		Yes	
1d2bc416-ad49-4ebe-bb72-31c13e9dda66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes		Yes			
c9d66edc-90d2-4a0a-9828-7b1653715325	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e698c40e-4915-4827-a325-59bd7ed9a110	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:50:00	TRUE	FALSE			en-gb	15:50:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
57602b58-7039-43ee-9a57-947ae1954a41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:57:00	TRUE	FALSE			en-gb	15:57:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8e2d749d-b471-49b9-bc35-259277d4b490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
20a74933-2766-400f-b8df-0335d29ff241	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:04:00	TRUE	FALSE			en-gb	16:04:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes					Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d39d5799-bf8b-4c0e-841a-d6e911978065	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:04:00	TRUE	FALSE			en-gb	16:04:00	06/17/2023		No room	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
eae116e7-7c35-4f51-88a7-8b3e7ddf52a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4a780371-d07c-46c6-aaab-be3d1038694d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
970a6eab-e77d-40c6-ab31-200e4d2ac334	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
84d7826a-63f4-46b8-bc01-4621c249f578	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/17/2023		Hiiii
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
884915c1-ef96-4398-91de-faa72044cc5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/17/2023		I WILL never come here agin
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f9a6f20a-0772-411f-b291-9f00e57746f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
34435899-8888-4f8e-bec9-7868ff07b2a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:20:00	TRUE	FALSE			en-gb	16:20:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f1112cb5-25de-414d-8849-7ec747eb1936	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:29:00	TRUE	FALSE			en-gb	16:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
1c130c57-f4ac-479d-be2f-f42367f0291e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7f596be0-6426-456f-8294-ff734c4e0d33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2f2f41f4-7af6-430e-992f-1de21d3a8026	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ec7a993d-c295-49ff-a04b-c30fce38b062	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:46:00	TRUE	FALSE			en-gb	16:46:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8ac45b5a-478c-48fa-94c7-aaba9a0c53cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
ef66ea83-ce02-423f-b088-b0eae98d5da3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
ef66ea83-ce02-423f-b088-b0eae98d5da3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes										Yes			
45aaa8cf-63ab-4d57-82a6-08e66fddd921	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ebd68fe1-e7d2-48dc-8f50-f2c90431c3e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes										Yes		Yes		
cd183242-53d2-4fcf-a747-09164a18e6b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
46f7e8a1-ec1d-4ef5-b4c9-6f258450f686	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
46f7e8a1-ec1d-4ef5-b4c9-6f258450f686	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes						
d88625f4-fbbd-43d8-af99-f966427cdee8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
4997eb40-3252-4536-adcd-6d0f7672d285	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
72bc8c1f-df45-47e2-9391-4a5c70e63104	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:18:00	TRUE	FALSE			en-gb	17:18:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
981b1e04-4908-4a8d-a3ee-5c1cda1014ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7dc72c61-f14b-425b-bf9e-e3746aa8573f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/17/2023		Flawless experience. Great job guys.	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ce6f70f-2b82-41e8-a42f-6e7ccf68fed3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b71ac8fe-a762-4f25-80d8-74838ad849d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes							
d9879914-f14d-4e28-9f81-c3b1f19d3f99	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d747ecdd-4589-45cb-abe7-92ac86f4ecd1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72ec48f3-32c8-42ac-ac90-389872c2f6c5	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:56:00	TRUE	FALSE		en-gb	17:56:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ee98a381-7777-4ea2-afea-e0e415fad195	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:00:00	TRUE	FALSE		en-gb	18:00:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ad81e477-cefb-423b-a187-69c145ea4e9b	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:03:00	TRUE	FALSE		en-gb	18:03:00	06/17/2023		Nah	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3046aba8-4b63-4de4-82c1-1f7e737a52e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1dbdcea0-85c1-4aba-a26a-1c2271aee6ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
dff87ad3-5be7-4daf-83e4-6f9185ce10a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
09f85cad-b07a-4ccc-95c3-513774d27781	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	06/17/2023		Facundo ochoa honor	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d34e674d-564a-4ed4-9237-6bbc464c07e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/17/2023		One bathroom locked	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3c879ec9-9521-47f6-b146-2aa97efe180b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5fef1a89-eacc-4656-99a1-66876a540246	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
									Yes	Yes	Yes				
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b3f80f20-7e62-4453-a0ba-3ee9e22b3903	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
dfa00375-bf41-4e69-a3d7-b93fd7cf2e62	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bc35b678-78cf-4863-b064-405b6cbd3088	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
211eef2f-0fca-44d2-af19-6e98623cb5d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eda46297-c6cb-4dba-8c11-2b8470af860f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b10510f1-e3f9-4b0f-8510-4b64e5813bee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bbb1994e-a3cb-4b34-94a5-b2b047feb673	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d19e1b9-3f6f-4b83-862c-85fe46a435dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8d19e1b9-3f6f-4b83-862c-85fe46a435dc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
031dab4b-19a0-409c-a4ef-f1c6fb2e723c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f8890fd9-21da-4f10-9716-bc39989275c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4c44d872-2c24-46bb-afde-d5df019cebb0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a409f0a6-4ede-4074-9ec6-f0c24b047975	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a409f0a6-4ede-4074-9ec6-f0c24b047975		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes	Yes					Yes	Yes				
fcb5032a-3bb6-4c1f-85a5-3aac8b19354b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:30:00	TRUE	FALSE				en-gb	19:30:00	06/17/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
d8434d3a-497b-44ff-b2f8-36fcad9f9ecc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:32:00	TRUE	FALSE				en-gb	19:32:00	06/17/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
0357d9cf-1586-45a6-bcb6-637b17f4d14d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:33:00	TRUE	FALSE				en-gb	19:33:00	06/17/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6980da34-e429-4b81-ac0f-62486771d108	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:35:00	TRUE	FALSE				en-gb	19:35:00	06/17/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
76edf237-b555-4ec6-b4cb-301007be9a42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:36:00	TRUE	FALSE				en-gb	19:36:00	06/17/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
769fb849-ca63-4a1b-adb9-9eed6d36fc8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
fef05561-041d-42f7-98be-6b26ee4fe23e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:56:00	TRUE	FALSE			en-gb	19:56:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
e84914c4-44c3-44e2-98ee-6b02304b50b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
5eb67615-19ba-45cf-aa03-c21493bab108	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5eb67615-19ba-45cf-aa03-c21493bab108	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
						Yes								
e53dcceb-5741-4e93-9851-162a0572a870	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fa059993-7208-403c-b127-393041f9de04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d30f5c3d-dfb7-40fb-8ec4-9adab629bc8a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54d80281-733b-4b0f-afcf-b79c33546673	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:11:00	TRUE	FALSE			en-gb	20:11:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
140b700a-af2d-4d73-9c66-b53db6d7dd59	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
92056699-21a5-4305-9b52-062a4fe3066d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
531a638e-bb6d-4686-897b-2317a6598411	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bf48f67d-10a4-411e-8f4c-0c3244971dc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a13f38ba-60bd-47e3-8242-400be80e95fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5111950f-ad00-4465-a105-7d6e719ddd83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7c14a10b-4273-484e-8527-c82a8d6d594e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ec4708fe-7498-4d54-aca8-8a1f59462a06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/17/2023		REEEEKS of urine	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c26caf57-9445-4388-8b08-a18ae65f3da6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d909b071-f0c3-4497-9b5c-a5c084762d87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d909b071-f0c3-4497-9b5c-a5c084762d87	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
04b2cf9e-58db-4022-a1b8-e86c82bacf87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/17/2023		Kojkkm	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
42173f84-b93b-4773-a0ee-8732d8a2ca09	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d8b2101f-d671-49fa-9d9a-cae5f6fa83bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
cdb2b41e-5fb0-4190-9591-83fca0b450cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5e4347ad-2ad9-496a-8787-bbfb3d4eb7b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78cc03b6-b132-4c3f-ab5c-433aecbc41f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f730187b-01a0-41b6-9f24-80e4c446bff4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2495e9f9-4d3e-4f95-a713-1b6bce2ac958	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6b35bfc6-6edb-4713-9c94-b2db4c5632e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
75c50eb5-719f-4fcf-8c5e-cddcfcdc2022	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c0b78a99-0268-4546-8e3e-efdc51827d7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	06/17/2023		Smells like pee
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
b0d9d5c9-96e3-4d33-9be7-a0af5a4e6e58	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d2c456f9-d458-4345-936e-801a8aa7e10a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/17/2023		Filth
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ae4d3cc-c56b-4895-8656-d321e5ffe02f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:50:00	TRUE	FALSE			en-gb	21:50:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
48f447b4-dc92-4be5-ac53-a9e0a7f13304	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/17/2023		Good time
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
43310727-ba29-4155-8c38-dd2ffbc11785	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07712f4d-ccfc-4fa1-863b-b80e44d38e29	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:12:00	TRUE	FALSE			en-gb	22:12:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
694734e7-214d-45b4-94a7-91a34f352c23	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/17/2023		No **** on the gound!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
684e763d-e599-44ef-ab42-56ed9ec9b2a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:28:00	TRUE	FALSE			en-gb	22:28:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bebcf8ff-868d-4f60-a8a8-7e5c6c6cd1c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	06/17/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d2277183-03f9-4500-98ac-2d8e3ad03ee6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:30:00	TRUE	FALSE			en-gb	22:30:00	06/17/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0e7a8eff-2c2d-48c5-863f-daec1df9cef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:40:00	TRUE	FALSE			en-gb	22:40:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b3ab0065-7355-47d5-9f90-24400ef76def	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
b3ab0065-7355-47d5-9f90-24400ef76def	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
											Yes									
14ecb4e3-2018-45f3-968c-44d77a583e04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:45:00	TRUE	FALSE			en-gb	22:45:00	06/17/2023		****						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
					Yes		Yes						Yes							
82a25814-dcd6-4736-b107-1afa3c67238f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
3590517d-8a06-4bab-8ce5-097edf880b42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:13:00	TRUE	FALSE			en-gb	23:13:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30b2ff46-1d68-4465-900b-0b48e2438e10	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:17:00	TRUE	FALSE			en-gb	23:17:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
801779a6-7068-4fc5-abbc-21c65f7ec9aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:40:00	TRUE	FALSE			en-gb	23:40:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
98989573-6561-47bf-9600-cb5fccc917e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 00:38:00	TRUE	FALSE			en-gb	00:38:00	06/18/2023		Smells like sh	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3e627225-5b9c-440d-bb78-4a80cd4bca07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 00:39:00	TRUE	FALSE			en-gb	00:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dfce7f34-8d06-433d-8978-6d02d6865f27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 01:17:00	TRUE	FALSE			en-gb	01:17:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0d0670b-e332-4174-875e-21466eada4f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 02:01:00	TRUE	FALSE			en-gb	02:01:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
574932b7-c747-43ca-9066-d004609d759a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 02:48:00	TRUE	FALSE			en-gb	02:48:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
e34138ba-0aaa-4e50-9674-1b0c25774ab3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 02:48:00	TRUE	FALSE			en-gb	02:48:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2b322ec4-fa6c-4bd2-b5ad-58588f44e349	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:01:00	TRUE	FALSE			en-gb	03:01:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a640b75b-c157-46f5-b0e3-07cdb74c2859	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:02:00	TRUE	FALSE			en-gb	03:02:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
2f0eae7-7fdb-4db6-a976-cea5eff85cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:29:00	TRUE	FALSE			en-gb	03:29:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b0a35a35-f544-4f56-99f8-6a920e209d98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:48:00	TRUE	FALSE			en-gb	03:48:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
246a0bd3-0394-4c88-8d53-dd64375dfa1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:12:00	TRUE	FALSE			en-gb	04:12:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
454f358d-08d5-43e1-87ba-b35f9223bceb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:18:00	TRUE	FALSE			en-gb	04:18:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a30df957-1be9-499f-b5be-de21c8acc968	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:37:00	TRUE	FALSE			en-gb	04:37:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
71bc72c3-061c-4735-a1d7-3822c3b03958	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:43:00	TRUE	FALSE			en-gb	04:43:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec620cbf-b138-4470-baf3-ad2d1413afc3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:49:00	TRUE	FALSE			en-gb	04:49:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a05bfa54-084a-4d3e-870d-2a09bbb51b4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a05bfa54-084a-4d3e-870d-2a09bbb51b4a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes													
8cd39922-4bc3-470b-8e8a-fc7699bdef04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:00:00	TRUE	FALSE			en-gb	06:00:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7f058b3f-3e0e-4c0b-a959-cff82dcb16a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:01:00	TRUE	FALSE			en-gb	06:01:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1d2fce94-e6de-41e9-89a0-71dacbed9669	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:02:00	TRUE	FALSE			en-gb	06:02:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes	Yes	Yes			Yes							
f6293474-7c73-41ee-87ba-cb541ea94cb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb58f940-70ee-412a-b102-9bd36f7e2073	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ffcbe8a7-36ce-47ef-be4a-55a9cc1e8f4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
900c4706-fead-4173-bf26-0dde15189929	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b40e0e8e-68e0-4bac-9706-17f9fa6c0f9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c4282a9-f3d1-4400-8f69-d02245b6edf2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8fb5f4af-6fd7-4c64-9b6a-9a60a3c095cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
f6471766-48a2-4928-a3ea-ca309fc5ca73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/18/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
aba37fc9-7c4a-45ec-a6ca-689687a52425	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/18/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
b2e286d2-dc31-44f5-a241-94e03bac057d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/18/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
3d5e0659-56d4-488a-9cad-01b2a444ba80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/18/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
8aed7206-c3be-41ea-b000-2699b55b8b68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/18/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
570d93c8-6ff9-4c0f-b3df-259ff499e5a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40fd394f-01de-4545-8d90-877d8aa79f05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1dfdd556-5439-4574-880b-273a66622185	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2fdd64b-3847-4a12-afbc-ecdfe1e4a8a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f881f421-b30c-4b66-84e6-8ce0e2135a2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15b97159-8e20-47dc-8b68-094eada7f1db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
159c19dc-6444-43ec-b109-459060fd6506	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
7693cfdb-a758-439d-b176-1ee325685703	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
1454a5bd-9a85-4dcd-9f51-a6f28a7a9daa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
871716bd-530c-49e1-9366-2bb83dba9751	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
30686eb5-4cd7-4fb4-9202-b304c235d346	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f8a6db4b-def0-42cd-a6f9-33c9827d00b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
75f4efb3-1c77-4686-8d78-e107ca1a3c74	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
d74808ab-c08a-49ca-8488-fc8f3ede2a76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
9c8b17c9-a358-4f77-a0c1-f6bb18071a80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
5c8a30e0-6702-455e-854a-fc09468568aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/18/2023		Smell bad
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0e31ab1e-0a0d-4404-9161-d0cb182004b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
212ae4bc-dcf8-49e3-b38b-bdf05f5d12d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/18/2023		Ri	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
796bc706-86c7-477e-8b43-aa7c5c95555d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fb4cd10a-db97-4f71-900c-9656bdce473d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4962e8d1-4b3d-4e38-85bd-b12f5d56e72b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
de3490a2-c487-4a55-8797-62c0a89c7756	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
751ee6a2-466c-4c8e-bf57-edf643dd32d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/18/2023		Its a little dirty
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
372928f3-be37-47f5-97b1-6d3ac39aba54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7bc4db28-c345-4539-b3a8-888491935080	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9c3c452f-265c-4452-8ac3-6c0c4badacec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
455cad2c-cc3b-448c-8fb1-6db0c7657015	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
50e1210a-ab8a-4f15-8c67-e4a979ce95fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dff7b5cf-aaec-4acf-8c92-126453257cc6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4fb2cd0-6e89-41b3-95ed-46832373ee52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2f74008f-1dc9-4e2e-90da-385ddf1ce059	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81ed9beb-a74f-4fae-b55b-5bfb816805ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28357233-e72b-45b3-8273-1425b99ea8c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ca3099d3-2266-48d6-97ec-7b0d48925e62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9cb71a39-c7b2-49c9-b176-85025770e15d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1a5bc7d3-0b91-4f3c-8331-6e93d261ba28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a8beaea4-d201-4526-b082-7c920cb7fa12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
010f211c-eb21-41ac-b04f-0ef6dd446560	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
36d07eed-e416-4687-a1d4-6c54c6503d37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
159f87a4-ba43-4b87-9560-ea8917d07f6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b367e181-ee5c-4a68-988b-8531ec97fb99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
11dcc03c-7d0e-45e2-a55a-ce9e8fe985a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3210aa67-737e-40fc-92e8-3c15e8f66c98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32cae31d-c7ee-4755-bb14-dab801889f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
22615fc3-fbc2-4996-99c8-46280790552f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dea6dd76-2e4b-4aca-b5bb-a9e58c455b31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
0a315455-c083-4f9d-9656-a0e6593a7173	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
01fb65b7-5288-4134-86c8-bd2d40acfa5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0bcea0a5-1a29-48b9-b36e-178cd00e228c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	06/18/2023		Very clen	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4b9eb90e-cb0c-4b29-b3eb-0a6542cc7c76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1741a6c8-3446-4360-9bff-731e42a3ae63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8fdb3e2b-dcc9-4dd9-876a-217706fe6aa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
93f3054b-0867-45f1-b3d9-9e9fc6960d7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bdceeff6-e2f4-4c9a-906e-6eed0029771f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes	Yes				Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b5a59298-bc6e-4b49-b3f9-4f66ff662e8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3629cd67-5a0c-4850-b227-036318451c15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
d533fc1f-5653-4898-afac-6850d748603c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4da12574-ba68-48a2-a23a-53a19e32acfb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
30405773-daf2-46c5-8c4b-825bd7eb40fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/18/2023		Todo asqueroso	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
30405773-daf2-46c5-8c4b-825bd7eb40fa		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes									
9a75e524-38e7-4b22-8323-532a8a9d2192	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
45776f0d-3c13-49c0-98f6-dfca476d9c39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/18/2023		Asqueroso directo? a ota hola va
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
6e9e4b9d-8863-431c-aa84-93e8c0aaa292	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/18/2023		Parece no trabsha nadue asco da
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
7cda4152-eb72-44c4-bd83-5f402b9ecde0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
1ceaf9f0-c4a5-4647-97da-565a5ee53298	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1ceaf9f0-c4a5-4647-97da-565a5ee53298	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes						Yes				
e5e2e718-b4ea-485f-bd78-040cd3bf9d10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3db58d8b-27af-426d-abc9-4e0bb70e6e29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
48bb69b8-fd99-4781-8f6f-0607b07a11e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ce3ba4ae-1084-4b1e-830f-f367b70ef947	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2a7ef3fe-77fa-41f7-b787-1b8e55c70ef7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
deffb8ca-29e4-4f31-ae9-6b48d5e7e32d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
450cd2ea-b84b-43f3-bdc0-60cc5a532395	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
47a71d79-c528-45c2-8a72-cd11fb524583	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8c09083b-fd29-49cc-84cd-16418245ae9a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
59da4192-0d93-4690-a67d-07719e7ce93c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
59da4192-0d93-4690-a67d-07719e7ce93c		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes											
b1429fc9-d9a7-4b49-a40a-8c9da7119374	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
8918b5d4-7be2-482f-aad5-e461c43e30f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/18/2023		Smells
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9a349ace-973e-4837-86ba-bb395e7b60e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
d8d16d1d-a71f-4a70-9f2c-a46e92951f7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7578af8a-d51a-4fa0-be0f-352b4295e43e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d52cc1d8-4f19-4b89-af1a-a8efb7106045	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dcd845a6-b950-4706-b145-88beb5d7ef0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8e73a6cf-d9cb-4d19-9d3f-890605dd6ab0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
db19ffe0-d84a-4c25-aa95-ed5f8dc33f2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4445b72-12f1-4ff4-b568-f3b77a5b3a95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78571ada-b58b-43fd-b71e-1968dd7d137e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1815dc89-58d3-4c2d-920b-4d00505741bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
57233159-361d-4829-b54a-da9adc959fad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
82277a0a-1146-4fa4-af7e-ce4ebeb8eb9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
69b7b594-be79-4270-af82-f9a624381576	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bc27672f-843d-4637-9bf3-e3c0921d7200	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cee1786a-2d41-4a0b-9a87-b7d2474b2785	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0dff1356-bd3d-44e3-a59f-41f114fb05c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
84e5e064-689a-4837-816d-47d102d76351	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/18/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
86059b93-56b8-4747-9a8a-559d74fdc875	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d2ffd1d-b271-4934-a060-59a619dacf2e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ecd3517d-f435-4a1c-a455-03a1b9db9304	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fabd04cc-7e62-44e8-b49e-20adf66e21cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ccdf78e5-f6f2-47e0-94c8-7f6e53d98ab1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd8ef55-057e-420d-b871-c19c15e74b75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
097ae4d5-17ef-46a1-bc74-589bab94b341	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
097ae4d5-17ef-46a1-bc74-589bab94b341	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes						
bb629a17-fda2-4b82-978b-1b8b2418f00b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
97017885-256f-4619-9be6-f26030bfa578	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b16876cf-0d27-481a-9c7e-b2171b45fc9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f2302101-72d0-4944-a457-211b313278d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3445478d-1038-43d7-967f-a18ee1485a81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cf2a042b-9e36-4b45-9b94-4e16201091ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4c21e26d-1330-44f4-a792-4d3d3aa6d18c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1011c06-6acb-4362-a303-c8222432b1dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
760bd19b-1af0-48a2-936f-d616f08c9ede	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f71fdd91-87ec-49fd-b12d-681ba9361fcf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d870c9d0-0b62-4d66-8e99-bf30a3eb1b2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
edd7858f-36b1-4e42-a624-fa6d8368d1c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
44767f2f-45bb-46d2-a48b-ff15d2719eed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8563c85b-6876-48d6-8767-f447355017e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/18/2023		Smells like urine	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
69882503-b6f1-42da-85b9-b60e6a707af0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2f3b83b1-6ee7-44e1-b98c-5491b24f8e5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	06/18/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c23c1167-c8b8-4cd1-bf30-11cb7f984882	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
895d9ef9-27d1-4ae0-a309-6775e5ee62ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
895d9ef9-27d1-4ae0-a309-6775e5ee62ca	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
097b0eb7-a648-4a3c-a9ba-f560f90bb0b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes				Yes						Yes								
1a2e54da-da23-48cf-b970-f508eadf8fec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/18/2023		Great						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes																		
31cd198f-c796-4114-b69a-2187bdb69c28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes																		
53f2393e-ca9e-4665-a324-63a18a4377e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e7463bf-2004-4a0c-b726-6ad8f0b2320e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb94c7ab-c8d6-4df9-906b-c81104efdf15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
60f3ae2e-2437-4adc-9ccf-4ff3c8da5f2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37d7a6ba-0804-47ee-b5f0-01bde2feb8a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6fd04ab0-a862-4a1d-99f1-34467e7b13ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0f9dc816-4f64-4057-a28b-0ff82fadd9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1fc489e0-4e01-4fcc-8f69-d4de94e71b51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c90f1fd7-7cfc-4a8f-b07a-6bd9a4a69f47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9cc49247-a08a-4447-af40-ef01fac5b187	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8522582d-6c52-4f86-91f4-951fd24fe8b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e1bb140-51ac-48b9-8d1a-2f20827d4406	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ad7ba096-2acc-4c93-b12e-d58f24ed7425	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1dd0a2dc-7218-46b6-a61b-8113c6083f3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
63d26b56-c5f0-41fc-a091-e9a26fc9248c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fdf9ca7-0750-4e48-97b3-12ab3552e1ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fdf9fca7-0750-4e48-97b3-12ab3552e1ee	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
272249ae-5b97-4494-91cc-6ffab7658e58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6fc9d0f4-b8dd-4058-b8a0-8d0cad1be689	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50fb2e03-2527-48c9-bdbf-2de3e86b2e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c8a820b-dcfa-45cb-9c3c-c98e3651f967	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
677ab5ce-9016-4e8d-8a46-1190e53a0a9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c5d33da1-6b7c-4f17-b362-394730ce1708	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	06/18/2023		no	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f670ce58-1274-41ec-984b-83af489c9e54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
a36681b4-d9f3-4e1b-a201-d652c88492cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb8eaaab-d4ae-4199-8047-d2f9134435f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4024013b-3324-4fd7-a8e4-1a5d765b6bb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
30a7975b-3477-411d-ab78-195659f5e232	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/18/2023														
															How would you rate this restroom today?											
															<b>Average</b>	<b>Good</b>	<b>Poor</b>									
	Yes																									
34e641e7-3e90-42dc-9b24-16eba9e48f14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:29:00	TRUE	FALSE			en-gb	16:29:00	06/18/2023		De santis fix your airports before you fix books												
															How would you rate this restroom today?											
															<b>Average</b>	<b>Good</b>	<b>Poor</b>									
																	Yes									
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																
								Yes																		
145456dd-f3dc-4fed-8352-d97572ce8317	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/18/2023														
															How would you rate this restroom today?											
															<b>Average</b>	<b>Good</b>	<b>Poor</b>									
	Yes																									
c3a6671a-5dac-44ce-b870-2b357a96c82b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/18/2023														
															How would you rate this restroom today?											
															<b>Average</b>	<b>Good</b>	<b>Poor</b>									
	Yes																									
0777b828-4fef-402a-b5ea-3f334aceac65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/18/2023														
															How would you rate this restroom today?											
															<b>Average</b>	<b>Good</b>	<b>Poor</b>									
	Yes																									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ce603416-e73e-488d-851a-151fc427f7e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/18/2023		Pp	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8b1c0f99-33c8-4260-80f0-18591b21566b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bac1814c-608d-467a-bf7f-042ada11fee4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cb90f7a2-023c-49c8-bf40-dc8376220360	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:46:00	TRUE	FALSE			en-gb	16:46:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
d0a21d03-3626-4abe-ba9d-41975759feb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1560467-ff06-4502-a31f-6d36dadcf3c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
901ea072-dfff-48a6-99be-0e66dee01d01	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:01:00	TRUE	FALSE			en-gb	17:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
df2e3a66-5b7a-4926-be1a-7d6b9d99e4d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fe2280fe-576d-411a-842f-06c5d0c3b5fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:07:00	TRUE	FALSE			en-gb	17:07:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8f4770ec-c550-405c-9f28-da3ccb3c4dcc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
95a0c182-1f61-4108-bd88-117151b979ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
97d57e1b-2269-413e-91cd-062b7214b4c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c054386a-adb6-436c-832a-b071bf801da8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ef5c9cce-5725-4094-9abc-632ec9089be0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
41b56309-c4ca-4351-b54d-a7f6f44f53e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9c505de9-1f41-4b80-a7b4-206f793b54c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
71f1f698-823b-48fd-b0c5-3fe5b02dcaae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ff89015d-7103-4f86-a34f-12aba3ab78dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
091699bf-1808-4040-9202-39d91686e911	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes					Yes						
7bf74ab5-0cee-4890-bdb4-9a94ae56b52d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e1158c1c-76b0-4969-8088-2cb935647486	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
10027178-097c-4bf4-a487-a9a4830fa6b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
01c52085-cf00-4e73-8b59-4052f0af1a99	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:59:00	TRUE	FALSE			en-gb	17:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ccd61dac-0794-484a-88ce-887c894c5e61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
00656eac-b799-4eab-9198-e072d9a70d39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/18/2023		Steamy *****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00656eac-b799-4eab-9198-e072d9a70d39	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
2112d311-1047-4a8d-aa70-32165b2a0aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22e70402-ac78-4b51-84a4-5286182a8f65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
e11bf37d-6119-45da-a273-bdd2463eeb37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88bd4290-9ff1-4ad5-9244-29bcaa199ab3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
221b7727-67ff-4d8e-801f-a0f95cc5ce84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2bc66fda-31d8-4bac-bcd4-1196d410cc6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3a6bcf85-4fed-4a70-a7b1-8d2ad9ed9321	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f6637dae-09a1-4d4b-8aac-0288634fd049	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c175cf85-e2d7-4334-b8c4-7291e5b811f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ffda51a-7b2b-4790-955a-ef49a9f4d820	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/18/2023		Dope
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b604233-af07-4b9c-8477-61742ac302cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/18/2023		Super dope
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6bb8df2b-f8d4-46b6-b2b5-be716f535b27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
843ebc53-6b3e-4550-befb-063bab1a511c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72a143c7-b54f-4d80-8aa8-95f91d0cc2e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea9501d3-1064-41fc-94ac-1d20b785fb28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ebde231-baee-4f4d-be5d-d9d29f7f0cf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3d77afb-f112-4b8b-8e62-bae4168390da	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
957129eb-58cc-4dea-9de7-ec72c1ef409c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1bf8d1b3-389c-4cde-b12a-082648f71b68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ad8c9343-345d-4181-83ac-aa74e20da898	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9b3b9c0d-195b-409a-9d2f-58f0062a9e6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
259b7877-d53f-4147-83fc-dced605f199b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/18/2023		'y"u"n'e'e'd"''''''''n' e'e'd' h"''''n' 'the' 's"a"s'	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
45afe203-b75e-4cad-8ce3-41b02d23ed11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
16db5239-a06a-4d3c-a889-6d59fc62f32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
de7af2bc-6df2-4a06-8817-f01ab27c8698	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
376f0bf3-539a-4e97-b419-e415464afed2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a10fb823-f2d6-47c3-82ca-34631432fa06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ebfedd7e-dfcd-4f09-8920-c834e127af04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fc06add3-b038-43e9-bb79-b576f8c47ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a7b88528-5422-4750-a6bf-90bbc048bcdf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ecae5f47-7dd3-4c5f-a34c-968ede1e0766	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5cc72c85-ba86-4a1f-81d1-ceb03093459b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/18/2023		I	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4f6ccf75-4069-4e54-9394-0ba11f363dfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
456a6d13-9095-479f-8921-ebcf6e10a17e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4bb8d3a2-a6b8-42e3-ac6c-c45e022044f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes	Yes					Yes	Yes						
6d3355ce-2f1f-4459-8cb3-621a988c1b67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b6523e4f-133b-4b20-9d4f-17dd1d64b623	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dffaaec6-83a5-4eca-8564-831de75f46c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6caaab56-3162-42ba-a5c5-328edad26a2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/18/2023		Cp	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9fc085fe-362d-4d1a-b529-24e2fa1f0460	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
9fc085fe-362d-4d1a-b529-24e2fa1f0460	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0237fada-6449-4bcc-994e-b3d2b29a4ee9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cef3b76-e636-43df-b409-83b0811a114e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f8abc0db-0482-4e66-a6a0-5ea3b4b35802	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d7704b6-faea-47a2-ac39-1a5bd050c198	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3a1016d-e219-41dd-895d-250c29a55021	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24b8d75a-1f32-4221-9a77-6a081057c7c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c2cafade-b5ab-4596-924d-a498e6b536c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bc45f297-0865-4ddc-9587-3a1d670b4d45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:37:00	TRUE	FALSE			en-gb	21:37:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cd4dbaa6-8273-48cc-aaf5-140b703935d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:37:00	TRUE	FALSE			en-gb	21:37:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f77b350c-6091-4c4a-ae31-4282b9ce30a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:41:00	TRUE	FALSE			en-gb	21:41:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0a6634f6-7224-4d9f-859a-f328543cc474	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:43:00	TRUE	FALSE			en-gb	21:43:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
1b663c27-ac08-4054-a970-0fa4bb6cce28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
1e1b2fe1-6b7c-4945-8016-0ab0c467e9ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
7d9f3e9c-7b26-4532-891b-6bdfa566ac5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
82b29e2b-5520-4f0d-afba-954ece4c6441	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:01:00	TRUE	FALSE			en-gb	22:01:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
e7c8c33a-9100-4e00-ac3c-23ddc3f55ab0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:02:00	TRUE	FALSE			en-gb	22:02:00	06/18/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
f33cfb4a-1a07-4092-96fb-14af1cefabc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/18/2023		gross and unkept, not a good reflection of usa					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes		Yes		Yes								Yes		Yes		Yes	
f4dded2c-66bc-47a8-8462-0ca9059178fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/18/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes														Yes			
066f4128-6deb-497b-9e52-316dc19b0ff4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/18/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
066f4128-6deb-497b-9e52-316dc19b0ff4														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes		Yes			
3ce0f732-fec0-4d6f-8d19-7a67bb0586cb														
Gate D10 WRR														
		Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:55:00	TRUE	FALSE				en-gb	22:55:00	06/18/2023	Smells
How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
00033f9e-399e-4970-9269-3a47ffafc927														
Gate D10 WRR														
		Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:19:00	TRUE	FALSE				en-gb	23:19:00	06/18/2023	
How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes		Yes				Yes					
9ef5746a-50e4-4cbb-aaaf-6bd15eaabcc1														
Gate D10 WRR														
		Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:26:00	TRUE	FALSE				en-gb	23:26:00	06/18/2023	
How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ef5746a-50e4-4cbb-aaaf-6bd15eaabcc1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes										
4ba9955b-7a7b-409c-9b0e-eece105b4e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:43:00	TRUE	FALSE			en-gb	23:43:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74497afc-57fc-4a30-8222-538d08498647	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:44:00	TRUE	FALSE			en-gb	23:44:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25be55de-3af2-4701-a0ea-3ce2521e7db3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b24e9d07-dd4c-4496-83c5-62e2eb445f3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 00:52:00	TRUE	FALSE			en-gb	00:52:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78c8bc84-72c8-4cfc-9fb8-6f0c991cadbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 01:07:00	TRUE	FALSE			en-gb	01:07:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7f88b6c1-b300-466d-a6ad-5b6552dd17e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 03:49:00	TRUE	FALSE			en-gb	03:49:00	06/19/2023		Clean	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
95579f8b-72d5-49bd-932d-11d0f3cfc0fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 04:54:00	TRUE	FALSE			en-gb	04:54:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes	Yes	Yes						
7c3c1437-6ea2-4649-a81d-efee77a62a07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2d463604-16c1-4521-a49a-4ca5b55c0a1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
48d474b5-bb9f-43ab-b8bc-02716c917797	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:48:00	TRUE	FALSE			en-gb	05:48:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
daa81d3d-bdc2-4589-9ddc-eb03db0bb2e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
8a857806-60ca-4132-bda5-913274f5ded5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:00:00	TRUE	FALSE			en-gb	06:00:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
				Yes												
ba16c4b5-dcb5-471c-b8cc-6c7c2d04ff68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:07:00	TRUE	FALSE			en-gb	06:07:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
f6eb6829-53f7-4d61-80f2-e16c192c641d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:15:00	TRUE	FALSE			en-gb	06:15:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
07913d4f-533d-4fd9-b4d4-74e5f1b94922	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:20:00	TRUE	FALSE			en-gb	06:20:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82bdeea0-48fa-4846-8295-b3d6390edfee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e482ec81-2785-4fca-9aba-d9e3627f3d03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c78bcf6-1c20-4fe3-9f27-058a2c00329c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4ef37df-f9df-42ec-ae87-c93044cd1725	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
008229f5-7288-4af3-9b2d-ad763be21ed0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
02c06a64-48b5-445f-a3f7-34e63460a784	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
192a238c-90d4-4ff9-b119-e8c6c87d844e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:05:00	TRUE	FALSE			en-gb	07:05:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
958d1034-7413-481b-8204-0d33e77bcf57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b252cd02-3123-4c44-8782-8e415e0d2f4d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/19/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
c383cf47-73de-4050-bbe3-c66b5b2695ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9a4c6cc3-2361-4919-990b-300cd62003ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0ad76e22-230e-4c23-9cf3-1b071252954e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes												
e33c5219-9453-4d93-b974-4ad2738ea3e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes			Yes								
11562e14-38f1-4292-bf25-b9593dca0806	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	06/19/2023		L	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
bca0e2b2-e6ab-4d8a-adc9-daaa985bedc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
52634b5e-a518-43c8-9265-7a3f572769a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c5280416-5861-4d31-b159-baa290afe046	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
d9adee1d-8c69-4964-bab0-b3f4b280782f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
273ddd9-8f28-4c2a-b1af-de6dcb53c3e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
2dfd281-cbab-4e15-84ee-128ee92183ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
416ad273-3a5a-4aa4-9984-834a437854d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/19/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
b93da836-90e1-4a60-b274-6171929ea364	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	06/19/2023		Too hot					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
												Yes							
43fb679-08be-4950-8940-619170f33996	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	06/19/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
23f274fb-9d28-426d-b0c0-8ef0f2b48d99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:20:00	TRUE	FALSE			en-gb	08:20:00	06/19/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
418551f5-2645-4a78-b83f-3f4414ac590e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17169c6e-3657-40d0-93d4-4e5e34085287	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dea89e5e-259a-452e-b8d3-eebb1e15a5ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9d80699-564b-4f54-8978-b1c2f0e716ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2842f900-014c-47b1-959c-d9bbe565d400	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
244d7acf-c267-4992-ad93-26a683db8dee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7652de1e-b2e6-4a72-b6c7-0561fcd533f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9e32038-31dc-4386-8ce2-14c5b9171741	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	06/19/2023		Na	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ff572b2-b740-4018-a3e7-5894abd72e3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0acef391-7d84-4738-9fc7-5b883b0037be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
15566e32-40c7-4f46-b9f5-977f450541ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
668abdc0-0795-458c-bffd-42ee08c517f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78144c5e-588f-406e-9352-45a08c511490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
58f6f6dd-06b3-41e7-bbb6-934edf6454c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e360424-320c-4415-9d07-4e540bfb74f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
736ea615-9b92-4c7f-90b4-fa98e5e237a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/19/2023		Very clean and well supplied even with so many ladies coming in, thank you!
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
237b4b37-156c-4a7d-9741-eed2687a8724	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a8672b69-c33c-4382-85fd-6ccc42f4a2ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
226380b2-04bc-42b0-bebe-d2240f252231	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/19/2023		G
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
65d77d54-552a-41f0-a016-1c20f39eab5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2601a25b-a23d-432e-9963-9d68649abe77	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ecb7b800-ba3c-4809-90cb-23a5634cf8e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
42d05de8-fb76-4965-a1d1-cd440362581d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
683efb2f-6878-4ece-b674-4aa00436c161	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4f789c1-2974-468b-9f70-d5b62b0dd2f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4af5c2e1-10d3-4568-86ac-7094e4ae3c56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1d32bcc8-d5c8-4128-b318-9ffb02687bc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b32180e8-292c-4d36-97ff-fd21601e4669	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2ce7c78-07b6-4ae9-8347-f1d77c537240	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d118eebd-7c2d-4b10-b336-8f2ad5033e90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22835407-fcc2-4187-8798-9d0bf5e9f487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3004f752-c801-43a3-a1d5-2e2aaf8a73bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8646befe-a107-4a2d-ac90-1d78b15b268f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eb92e220-50c1-4ee9-bcf0-086fd309d7f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1f7d4b62-2960-4263-afa2-4977b1cc6455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
63423a6f-8202-40cc-b0ab-80e6fe4d53ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
90ea1902-c33c-47e1-b39e-2a5fa080d078	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca5fe2d6-6c77-4d67-ac5f-fdc738015eb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:57:00	TRUE	FALSE			en-gb	09:57:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ef2d6ddb-8e59-4fd5-a394-acaa148a44c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
82ef2d6b-1c42-40fb-9b7f-cd9fb32eaa02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d7afcaa-06b1-40ba-82e5-b013a1f1b541	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4594691a-d6d1-4bbb-a06d-20fb0f5e4c1c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:08:00	TRUE	FALSE			en-gb	10:08:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a56625a-5961-4833-b802-9a18c03dbffe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
ee3514f8-d596-4c8c-807a-8955f60d7566	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ae312c1-f38c-4f00-9469-262e59d2039c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c4dc2db4-53b2-441c-9966-865d3eccf23b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b28b56e6-d1cf-4e15-9197-eb0987f39bc3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc1be7f2-8cb9-4f82-aa07-8bac78572cb2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d4266103-07d3-44ff-b9d4-98c290d8a400	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34acad5a-4657-4680-ad2a-2049ed908c7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5020a3fb-a760-4714-8264-9261a2e8a652	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
33ae4a58-0e76-458f-88f3-117028ca0e12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0dfc460d-6960-45d4-b67b-f07d2922d91f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5a8ac3c9-0a56-4e52-82ec-4982ff10b248	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86b7508e-c219-486a-af55-1245e0fdb287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6cacede5-d917-4151-93a0-677c6bd3fe06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d7b3c8a1-b26d-4d45-9acb-5a1d349da123	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
63108160-4031-49c7-8585-cc384e840279	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
fe8e688d-a233-4c1b-bb83-2b52a36184f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b8b95c26-6bc9-4651-b1e3-03c1c9a7e536	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f448f660-80e5-4445-bf94-e319d1449cf5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bc42e5d2-4535-4847-9518-b1d0b35c890e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e77d69bb-5c66-4966-8fea-4f264e609b5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
695f62e0-7e8b-43f1-8352-52b3dd49e4f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96e799b5-a640-49f5-a8f3-8f7c32c23ef0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b95ba7ab-bb99-4972-acd2-0d01f2513dd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/19/2023		Yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bfdea0a8-6e21-4116-b626-4934615ee5ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bfdea0a8-6e21-4116-b626-4934615ee5ee	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e1119d8e-8e2f-4817-92dd-a9976f9e5641	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:01:00	TRUE	FALSE			en-gb	12:01:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
8953596c-6006-4ffb-9821-cce1c8c02dd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes		Yes					
199be5f7-efd6-4af6-aed2-427ff94229cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
89f0ee6c-d6aa-4710-811e-e3a7f16c0748	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4ef1f625-e817-443a-9742-dd5b05350172	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
732965a9-deba-44c5-b473-f4bc70e7d3bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
424f29f1-1b94-4483-9262-c32139b52266	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/19/2023		**** rockin	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
d552e002-ff43-4ed2-b864-5d039ae3a16b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a140f60a-fe86-479b-a71e-ec45d067abce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
053c14c7-70b2-4975-90c1-25a15eb2c952	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:47:00	TRUE	FALSE			en-gb	12:47:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd226d18-cf07-4744-807c-d8d249480cd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6a9acc0b-bc3c-43fa-82da-fde7907fcb02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b565886-7022-4e11-9c58-82b245652519	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8aa583ea-bb87-471f-9902-1d7383984084	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8aa583ea-bb87-471f-9902-1d7383984084	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7816f483-fe85-410f-ac11-a84c02cae939	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d3a91ed-bfc6-4a6d-9b40-2c58755916aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
04d95846-9783-4106-9547-0035a07148cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
adfd9052-d830-4cd7-8abb-ed0f3e8ae432	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d7111e8-983e-41e2-8ae0-4cf2c0e4ce20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
1dc6ad08-95ed-4746-a356-7d6f96caaa12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
75f34b93-0ec2-4d22-969b-8dac16c38568	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
5a7b673d-e4c1-4249-ae0-e87149814300	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
79a0cd02-9487-406b-a20c-fbe6424cf5d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/19/2023		Se		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
									Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
951f3ead-d30b-4593-a4d5-77b5653dba8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
031f9175-07d6-446c-8bea-044b143b1e45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
303044de-c10c-4f8b-98e2-de26b7360104	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5ef60e8d-dc83-49cb-a302-457adc2ae24e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
84bd2367-91be-4ca3-8918-58f2006a49e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes								
e4cc111b-738a-4605-8913-748292803ac5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes						Yes	Yes							
ca8e6aac-28f1-491b-8971-2c9edfde5eba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes				Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
d47ca057-3ac5-4ee2-aa98-6df2474daf14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes						Yes							
2ded3eb1-1d69-4063-990f-78448b1a70c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
a81df281-72eb-4fb9-9da6-f5a5c7953767	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes							
a4d77b22-7401-48a7-b31b-38bb5594d574	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a4d77b22-7401-48a7-b31b-38bb5594d574	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											
378b829f-c775-4406-bacd-45d461b3c565	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b20a413f-5e41-4611-b3f3-89860cc0bceb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
f5ca6c2e-06dc-4f55-9006-b90e391d3ad5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3f5812a3-89fb-43ce-b240-4bba28a41f17	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3f5812a3-89fb-43ce-b240-4bba28a41f17	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
8f60019a-034f-416b-80ff-73df977e06b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
f5cebe24-2e22-4477-a096-edcbf11b2923	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:28:00	TRUE	FALSE			en-gb	14:28:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes		Yes					
04147f68-e731-46bc-9b6c-e9cfbc227861	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/19/2023		Smelly	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
04147f68-e731-46bc-9b6c-e9cfbc227861	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
78117f57-3609-416a-8f8e-9cab593d06f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes						
452ae7a1-09bd-4dc6-bed8-21b6160159fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	06/19/2023		Smell like **** **
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
22acf679-7f02-4137-a6e7-676f175f04ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
9ac945a6-3191-4462-a2b1-700fc91726cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/19/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
9b32d84a-c960-4fcf-9008-7965c420991b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/19/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
dad049ba-6d3a-46e1-9b7f-68fb62c28f5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/19/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
c6107f9e-9f52-4d8f-b9de-dc8a1dd9c58f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/19/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
b0b059cb-2dcf-4ca8-b483-acb4c3a88f05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/19/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b0b059cb-2dcf-4ca8-b483-acb4c3a88f05	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
1f9607b3-be75-410f-923e-7db923a0ddb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
93f29ead-2d55-43fd-9d62-53a9c5015662	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6f3fe45a-9b96-48fc-afa3-35bc0479e18d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
bb7473bf-facb-4980-a7ef-a47d1fc516a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0ffa43ee-6e77-4227-8eb4-5fb569725f67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
49f2dd60-6a48-439b-97da-e48162b5b19d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
794e98cb-6b14-4859-8563-46691d5355aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
92cec3c4-5ed7-41af-8496-2ad6e88471ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25f6e027-a6eb-43be-8bae-d62c4277373b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
95554ced-18cd-4058-9a9d-34f816e0e237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:26:00	TRUE	FALSE			en-gb	16:26:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2c053f4e-389e-4fd3-9200-7efe791876a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/19/2023		Disgusting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes											
bd0b2ff9-cb9b-44cd-b52c-2f0c9613bd2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
91f3681c-462a-47e8-b98c-55927df4c0cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a94fc301-da8a-43eb-a0af-59ed759b7bcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a94fc301-da8a-43eb-a0af-59ed759b7bcf	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											
b4fcb2d-70b9-491e-a006-9cc47c23edd9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
5afba9a0-25bc-4d75-b506-73824fb5bc9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
14e8e7a6-3757-4693-8d8d-ad221aa0a564	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c58c8cff-d4eb-44aa-badf-b1a9ec63ac25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b088b4c7-fee9-422a-af6a-31bc807a9db7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
1ecff14b-a821-4ea7-90ce-32c6300703ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0d9be832-a462-4ab0-9ea3-b3b5cf8eb740	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fac31521-8d45-494a-9e86-0100a35b5756	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ff25c6f8-4dc4-47d2-a8ff-8ad76690686e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes				Yes		Yes							
8f589cd8-007e-419f-a541-df1d89999990	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
17326e40-0ca3-41a4-b293-f33c44791bb8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
69918516-7649-4407-8e66-6df22824753c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:42:00	TRUE	FALSE			en-gb	17:42:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ef851672-b3cf-4e8d-9b0f-0c7ff7c5e935	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:42:00	TRUE	FALSE			en-gb	17:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6c387cb-dfd5-4ee3-a9ed-fec5fed477a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0cc81728-4364-45de-a0f9-c293e5126b90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4d4abc2f-5aef-4bdb-88f9-935261afec20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea809838-4d1c-4af0-8b04-538a6e218aa9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9ee9ef2f-42b7-4550-9865-9c2141579877	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:04:00	TRUE	FALSE			en-gb	18:04:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ee9ef2f-42b7-4550-9865-9c2141579877	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
0753d6c9-1653-4ba4-8f30-4b813e08efc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/19/2023		Stinky	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bc75c2ba-1a34-480a-89e8-178e9e5c4803	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
69f07cd1-b46e-44a9-999e-4c1e6db15bdc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4b495d6f-4fad-4524-8780-529c2a385405	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/19/2023		Bad condition	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4b495d6f-4fad-4524-8780-529c2a385405	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes					Yes	Yes				
f9bb46a8-082e-431b-be00-6d13a668808b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b1a20b07-20e4-4fcd-985f-1a828f23e9b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b469cd26-744b-4c56-a65b-1262491c8aac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b2bb21b7-8eae-42cb-95dd-8ce819d814d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7cbbb17a-8f56-4ddc-8ef3-6bf74f4e967e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d9c84c0-d78a-4e0c-aa22-0bc0ca4d4b53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c29ab08e-2ebd-46ac-850f-598b5a7bbfd4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
32f51b59-a426-45b2-a0c3-bf3aad8c8cfd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
79ed7de6-0192-4a48-bc65-81ee0590fa3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/19/2023		Ctdddsvbm,.kmdd wshjuft
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91494b15-15ed-421e-8194-f74b318713bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/19/2023		GfddssXcv mx
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
750a96fc-7158-4866-89f3-2f13ef1be0e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d38166d-4314-466a-933c-17e8c1d9c27c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes									Yes					
73053658-44e3-4ac2-ab34-c8238d7237e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
23e8f75f-d5c3-458f-9485-12a686baf010	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/19/2023		Bvggggfggcfvcvxd	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
749b0acb-d2be-4e80-b5e5-a51367333efc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1b7fa5da-afac-42dd-8d98-417e1b0687ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/19/2023		Ryker	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
54e8c064-f7db-4121-8ea8-36f39c2f5976	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes				Yes										Yes		Yes	
f2870029-f1a6-4a2c-8a47-013f7e09b5d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/19/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
1145041f-cc7f-4d7e-9bcd-8c12389eb23c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/19/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
																		Yes		
ef72d7d6-457b-4d30-bbe4-d341f94a830b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/19/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
440deb55-14bc-40fb-a413-8171de1386bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/19/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2317a81-145d-4be6-953e-3456ce344eaf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5fa137fd-935b-4dc2-9d0f-20dc3c425d4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
53416b35-0e4b-412a-bae3-2c9770e9c8b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:04:00	TRUE	FALSE			en-gb	20:04:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
598515a6-5e4a-4d5e-b731-57790704068d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
368dae58-20c9-4393-b5cf-9bedf101cfe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ae427aba-d3ce-49b0-84b0-58ce8cddec98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
303122f1-c73f-4add-b13d-c2d80c6bbccd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
298f1cc1-8b65-452f-8ea1-b8c379aecdc5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bea65d92-0057-4d00-85fa-9400003d374c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	06/19/2023		Good clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f0c06fbc-f413-4d7d-b4ba-27f8157ce77c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
b4b305ee-e2d3-4ff8-9449-b74c75b1cec4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e55eb1e-dc7c-4d1c-8427-0ef56f971cb0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
124c2bab-9822-40de-b3a3-a7d949068f2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f7528754-81da-42ea-8bfb-62c13953b550	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:57:00	TRUE	FALSE			en-gb	20:57:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
334e2a6e-ed1a-4174-8009-9e7d749a2c0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
bfcfb513-5992-43c5-91ed-2bfa9ede5f50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
be16beb0-7df0-4c41-822e-c8e26c46df4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	06/19/2023		Nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
838533dd-3197-45c2-8e40-5e3992eb5b05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5f9d0ce3-9547-439b-8c62-3fcea5a8f7ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:13:00	TRUE	FALSE			en-gb	21:13:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c0e4553-740b-4079-8260-f2a284674f9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
511f1b07-86ab-42ca-a2df-a0323068cf1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
357faf8-5c32-4a04-92c5-7c77239bd025	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/19/2023		I was happy to be here
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3aa05b12-643c-4109-9eaa-3e2ec3757b06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/19/2023		It smells
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3aa05b12-643c-4109-9eaa-3e2ec3757b06	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
37110e45-94e9-4b5b-80cc-0f12dd66cd22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc378c9c-fe6f-4ca2-bb10-89d748e26452	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1404401a-8785-4ae1-b4e3-f89722906217	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	06/19/2023		Ab
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4ed9fe88-4585-410a-938c-bc83c216918b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:00:00	TRUE	FALSE			en-gb	22:00:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ea457ef9-7174-44e8-86d1-fb5fb9e8f0ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9865dcad-efd9-4b48-a049-ecb4d9a535d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab857166-a1a1-47aa-b224-48a0de0e257b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:23:00	TRUE	FALSE			en-gb	22:23:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4d0c525c-a33f-4c15-82eb-b7be970958b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:27:00	TRUE	FALSE			en-gb	22:27:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
300a9638-9f3d-4bb2-94d2-7d3b654835cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
16472204-c3c0-49e9-bf46-755976f45532	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:35:00	TRUE	FALSE			en-gb	22:35:00	06/19/2023		I hate american airlines	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6fb38e66-bb31-4f01-a3c7-14dad632558d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
95f73711-d139-4ca3-9ea8-de7aa7e2afe5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:45:00	TRUE	FALSE			en-gb	22:45:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes	Yes				
4279040e-73e2-4731-a2e7-3043d6e7ab85	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:47:00	TRUE	FALSE			en-gb	22:47:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes	Yes				
1f94431a-31c2-4023-b993-0ec8e2474a6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:53:00	TRUE	FALSE			en-gb	22:53:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c2a3496f-047d-432e-8bb8-6f129e36ede9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
188f880d-42d1-4fab-990b-72e09714cf29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:07:00	TRUE	FALSE			en-gb	23:07:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c2a23274-8f00-475a-a41e-adfeadafe3fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:14:00	TRUE	FALSE			en-gb	23:14:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ffc172aa-f2a6-47d7-86e6-9be4d8949274	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:14:00	TRUE	FALSE			en-gb	23:14:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4d99336c-54a3-4a16-8531-74273c966253	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:53:00	TRUE	FALSE			en-gb	23:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9e4e9c88-96c2-4d34-a08d-2c44497a7531	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:53:00	TRUE	FALSE			en-gb	23:53:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6ac54f34-ed19-4ca1-961c-d024dbf36a51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:01:00	TRUE	FALSE			en-gb	00:01:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes					Yes	Yes						
c801c303-4ad7-471a-a35d-85e5d6760602	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:19:00	TRUE	FALSE			en-gb	00:19:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes		Yes						
e58c2465-18f6-48c5-8ddc-d5231e412ec1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:22:00	TRUE	FALSE			en-gb	00:22:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e58c2465-18f6-48c5-8ddc-d5231e412ec1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
8b43b3f8-6edb-4185-b873-cd31fac240c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dac87c9a-dc17-48a2-a080-22f60a4ca04f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:28:00	TRUE	FALSE			en-gb	00:28:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes							
cb648fbf-b159-4c7d-963f-7e1f0cbf0b7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:47:00	TRUE	FALSE			en-gb	00:47:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc2c3ff5-f001-49dd-a3a3-44d5086f5fb8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:54:00	TRUE	FALSE			en-gb	00:54:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc2c3ff5-f001-49dd-a3a3-44d5086f5fb8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes			Yes	Yes	Yes	Yes				
0ad13ef3-ebbe-405d-8584-0594db93a39d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 01:02:00	TRUE	FALSE			en-gb	01:02:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d852ce69-e929-43b7-8f8f-86ceb9c0ff27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 01:17:00	TRUE	FALSE			en-gb	01:17:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes	Yes	Yes					
f166ed60-9d5d-4fa4-9c48-00e3fbd4b957	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 02:19:00	TRUE	FALSE			en-gb	02:19:00	06/20/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29a9a30e-e9da-47bc-a273-a8ccaffbd308	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 03:38:00	TRUE	FALSE			en-gb	03:38:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b8dae8f-7d1f-468e-9dc1-96a48a44b1ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 03:49:00	TRUE	FALSE			en-gb	03:49:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cc0fc9d-d573-4f68-be44-0fad25aaafb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 04:33:00	TRUE	FALSE			en-gb	04:33:00	06/20/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99b82349-1285-4289-b358-5ce6c4cc1e86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:04:00	TRUE	FALSE			en-gb	05:04:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
c0b2a998-2ea9-4e2b-a3aa-37b796ac2a8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92ff2066-0325-4057-be8f-05d7f1e194ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
2500f3ef-58b0-4673-9ff0-81ed29c55198	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:32:00	TRUE	FALSE			en-gb	05:32:00	06/20/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes								Yes					
d6067adc-f72b-45e2-8607-0385dda0e62e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:40:00	TRUE	FALSE			en-gb	05:40:00	06/20/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
5044b780-f842-45f8-a4ec-6c9382381f74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:51:00	TRUE	FALSE			en-gb	05:51:00	06/20/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
5e740169-0d2f-4cd7-9825-6f06ebf82009	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	06/20/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes				Yes		Yes		Yes				Yes		Yes		Yes	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f179641f-5992-4089-8b88-0ff044263216	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:08:00	TRUE	FALSE			en-gb	06:08:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c42376b-674a-42ea-8300-47c831341a09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
0fc8420c-a10a-462f-8cc5-871893e20fd6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e83e1c2f-d85d-4dd5-afa1-f17be59c2d60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
73065625-8c39-40d7-8637-57f2b2123152	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d736ee63-ab82-4c36-af5c-471ebf93793f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6beb71a-7f14-4c67-94a5-f277e3a5dcab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:00:00	TRUE	FALSE			en-gb	07:00:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b41c0d4-a2d5-417a-aeec-5b9fa1a5ab08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:03:00	TRUE	FALSE			en-gb	07:03:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5cac0ef4-96cb-47dd-9a31-90cc67dfcd5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15fd871e-12dc-4c5b-9e21-9497268367cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:18:00	TRUE	FALSE			en-gb	07:18:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
793183bb-bb7d-4146-a0bc-b2fef235a655	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
89a7d761-3ed4-46d4-bb1f-e734a7f0754e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
258f77cf-d485-4bfc-bf29-e5d5d5b9237e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b804a7f-b871-4780-9dc8-1a882241ac69	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
975a1c14-f6b9-4103-83a4-1b40a88aae2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/20/2023		MnhuioK
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a211ea1-702c-415e-9b2b-6365fe90e4ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76ee098f-54cd-4073-ac2c-0b187097f173	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e2d0df6e-6ae2-42bb-b629-26569389b5f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
010573c1-cda2-4e0e-bc0a-0692ac7a1b55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af63a596-df58-40f3-9691-22c45e2d99d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes				Yes	Yes		Yes							
fa89a681-1e96-4405-ac9f-4d4fe218ba6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
71fab164-e222-41bc-b77f-19b42140a35b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
71fab164-e222-41bc-b77f-19b42140a35b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes		Yes					Yes	Yes	Yes				
1e71ae36-c72a-498a-9a78-9ec7f65eac86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					
7225e134-1a79-40d0-910b-0a76d98acc4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
10013462-87dc-4104-a886-9fc3c61ef704	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
e315d6fb-75b5-40d7-9ce2-ee453ced8f19	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
11defeb2-c31e-4544-bf59-5b0771059dde	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9dfc60d-4a19-42df-acbd-3e096c61130f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d1a1592d-f459-4b82-a9fb-f5f1c364a4e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
093ca251-849f-47a6-9d2f-66f29a86ab92	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89169360-28d3-46ab-abf7-37db5adccc7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6fc956b-f4cc-4bfb-82dc-238997db095e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
b6285ecc-a72a-4d30-8216-b897744cc91e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/20/2023		Finish														
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
645f9f5d-9291-491e-85cb-2bc5fbc6b7ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	06/20/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
af923116-3093-4c77-af92-93a601622bc6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/20/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
51a398e9-df65-436f-aef2-c30805e869d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	06/20/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
924ada29-030b-4947-9a9b-4b2f8f9943f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	06/20/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
cadc2c7f-846e-49e1-b96e-96734aad06a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/20/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
63cc43b6-5962-436a-bf88-6f8000e10522	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/20/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
4a160d5e-306e-4bc4-9caa-f6f35b0b3d71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	06/20/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
f689605b-c8b6-4aa6-8dbc-96db4a1aafd5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/20/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
343c81b2-0df2-4aa1-b640-5c7cc824da35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/20/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c685c271-b04a-4583-a1b1-cd6475decacb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:07:00	TRUE	FALSE			en-gb	17:07:00	06/20/2023		****														
														How would you rate this restroom today?														
														<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
336bc4c1-acdc-4daf-9d0b-dcd31a150828	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
455c3f65-73ad-4e3c-b04e-669a2b39d5cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
35be5ba4-a91f-4dc3-a7aa-c5c08ac5020d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes		Yes						
9c7440c6-63ac-4025-9438-c26a0f6e8506	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
df053044-bacf-4924-91c2-ccc81cd65b94	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b91b78d7-a092-47fa-8158-8db28b82fc2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8b9efa1b-ebf6-4d3b-9f75-d174e1cd473d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ee4efa8-bf6a-4ae7-a866-514fcaa8e1c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e0f1897b-058e-44b2-afa3-9b85c38cfcfb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/20/2023		Keep up the good job
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
590731cf-1c6e-443c-9d78-c8c08f7ffdee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b451ab5-e31a-438c-aa50-55a9e0a9641e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	06/20/2023		Make equipment newer
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fbeca1fa-4894-47d3-af7b-318a8be03e86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4b615c1-f0e8-43c2-b6ad-30b6b2317b49	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9e166d26-0df9-4d3e-b945-6b0535e96ae8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9703351-d607-4a43-87fe-74ce58cb41f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c89cb05c-19d8-47c5-9d43-08683546d64b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b1f27e2f-fceb-437f-9747-2017d04324fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cfe307bb-a16d-44b9-aeb8-d3bb2ab858c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55a07ebb-fa3c-49ec-b9d2-6e2d4bc2a35b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/20/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fe3e021c-8d9f-447a-9666-69af7c77bf22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes		Yes	Yes			Yes	Yes					
4c2f2b0f-8922-4e39-a7f0-e5630be32563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/20/2023		It was very clean and good to use	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a3241c46-faad-4b73-bf15-be0cb9458a26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/20/2023		The toilet was clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
0e1883f7-a3dc-4ec7-860d-5454d50f49de	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/20/2023															
		How would you rate this restroom today?																										
		<b>Average</b>													<b>Good</b>		<b>Poor</b>											
															Yes													
ff674276-6b6a-4f0e-b039-00ee6bda9795	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 23:13:00	TRUE	FALSE			en-gb	23:13:00	06/20/2023															
		How would you rate this restroom today?																										
		<b>Average</b>													<b>Good</b>		<b>Poor</b>											
																	Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>										
		Yes		Yes		Yes								Yes														
e670cb44-fe5a-47f9-9857-51758783d16b	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 23:22:00	TRUE	FALSE			en-gb	23:22:00	06/20/2023															
		How would you rate this restroom today?																										
		<b>Average</b>													<b>Good</b>		<b>Poor</b>											
															Yes													
614386b6-90e8-4d60-a45c-9191924c31d8	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 23:26:00	TRUE	FALSE			en-gb	23:26:00	06/20/2023		***** streaks													
		How would you rate this restroom today?																										
		<b>Average</b>														<b>Good</b>		<b>Poor</b>										
																		Yes										
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>										
												Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5e774616-3251-4dfc-bbf9-47721b79c556	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 00:04:00	TRUE	FALSE			en-gb	00:04:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5c294e18-c23d-4f4a-baa1-174dda37dca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 00:58:00	TRUE	FALSE			en-gb	00:58:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1003d98c-0646-4355-8237-3bc41ca34827	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 01:14:00	TRUE	FALSE			en-gb	01:14:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
29833d73-47a7-43db-bf42-90098b49a237	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 02:42:00	TRUE	FALSE			en-gb	02:42:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3f56f452-84b1-45a9-b165-3bddd88bf41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ccd5444-8fd0-46db-b44e-15287438047c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes		Yes			Yes	Yes						
31013a6d-5363-4704-be24-cbdbbacfc624	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c094b04-d2f3-4853-a51b-2bfd1c43b66d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98986f69-2188-4dc6-a129-b807402972e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/21/2023		Excelente	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
92b33312-f2c8-4d50-b4e4-3c0d5dd3c549	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1446fa6f-116f-4217-8c9d-8cea77092c42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
efa936b4-3876-4d2c-b2f1-4251460f9a02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
31a066e3-d992-43f4-a131-20e41db9153b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b906f86-74a9-4cb8-8a3d-c139bcf559d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a95562c5-d4b2-4eb3-9a15-6c51e9168abd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c5477d31-60a9-4cb7-8b57-9fe8a4d6e9bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dbf12942-03d0-498d-94ab-18a3a9ecef7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3271268f-225d-4a50-a167-d63b03af4b1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
263854f1-fd22-4768-a078-67f566aa9502	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ae2069e-4400-4d55-b7ad-3d4dc457cafc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/21/2023		Its amazingly not good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
555794c2-17ee-45f3-b836-25ca04cf9832	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eac28dc7-22cc-4eb8-a8cf-90fcc7d4294f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3031321f-2c1f-4234-b886-8bc23771d598	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f7b9d0e-89bb-4285-9b68-90414fe4a917	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
57310b30-12f3-4bee-9289-2bafa84161d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a42bce47-98f1-4c41-81ee-9b281baa07ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
47d14bc5-0961-4bde-9465-31107aed388c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8a663b4-e32a-459f-a412-e10832306e3c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/21/2023		ldk what tht smell is..	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
45de3a2a-1e65-4c01-a22a-d9988341bde0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2bf424a3-8fd8-4af9-80f8-9fbe8e7910a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d30d85ff-b136-4f7d-8cf7-df96ffe7206f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/21/2023		H	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d30d85ff-b136-4f7d-8cf7-df96ffe7206f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes	Yes		Yes						
ee8cee89-d26a-44a4-ad00-2383534cabe8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
98eede09-059e-4968-ae45-a09b9bf0adf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/21/2023		I liked it today more than i did yesterday when i got stuck in the toilet
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f8bbb065-c90c-4d40-bf9a-9dfa143e83c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f220ff1-8876-416b-bf98-1f80f675a730	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
861418cc-a529-4653-9f3a-5b265f762f4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/21/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
3462b4fa-9031-46c9-a835-3de5527f2c81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/21/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
e20b6cd0-3003-46ae-a22e-fe1e3ec32899	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/21/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
061b6b8b-a57f-4f05-a7da-6ea5600026ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	06/21/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes						Yes	Yes	Yes							
41fa6971-4f8e-4343-b7a1-39f7a3faede1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/21/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f5d9bad-f19d-44b9-9ba5-f955313d9a78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ad1add4-9eab-4575-aba6-7930230c10ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
84433ac6-fca4-4984-bd0a-19f6bb7a20c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40b571a7-020f-4fbb-82e4-bd62f66f78e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d780ab1b-6fb8-4771-99d1-8afd175c2cb1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/21/2023		The bathroom was so clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50bd9893-6f82-44cf-9178-e2bae0e76058	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
46d44fc4-14d0-4ac1-b517-fa3bfe93a70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fa3f6b8a-4ff5-4199-a0c1-027383e1a968	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
06669546-6b7f-4863-a442-630a6300f8f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
65d12a9d-7ff9-4f0b-845c-10056ce10566	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
80e780f5-b5ae-4002-ba6d-3789960af410	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
133e4271-ece7-4022-b04f-8d634eb6aedb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
11c6821a-20cb-4cfe-b105-bc5cfabe297e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b947562f-2aaa-4d40-9aab-30a7adb9e5f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
881fd5eb-1d08-4e1e-87a6-e62bb68723fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c3961fb-3166-4173-9399-2d73847d8ae7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef0084ee-779f-4050-b330-038b9bade3ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81136899-c250-485d-8ec4-f37f25f45985	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
81136899-c250-485d-8ec4-f37f25f45985	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
										Yes					
799b122e-af61-4b68-a75a-2c0072a103b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32142ae9-ec6c-4115-9c97-9cb78d34d8ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 23:19:00	TRUE	FALSE			en-gb	23:19:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
8dd95b69-0378-4a1a-8725-5db7d3353c07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 00:05:00	TRUE	FALSE			en-gb	00:05:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4b415cd4-e52b-4e2e-8dcd-1c49cefc78d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 03:38:00	TRUE	FALSE			en-gb	03:38:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02b01e71-a427-4b42-aeb6-f250951b2bfa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9418577-24bb-4210-bb37-f5ca8a891927	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b148522-54e3-427a-8847-77b66835c2e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1c1e4d8-353b-41b0-a991-0224054a50db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1b0dc11-a93a-4ba6-aa2f-857384df8175	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f27b030b-8585-416e-9763-a2be7f8171ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b3b7ba54-4114-4641-b7b4-5a80ac9f3436	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					
35ab5c5c-1d46-4233-a083-b3ec995244c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9320d3bc-5ca2-4c15-a9d9-fbbf6f6d824c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ee05abb4-fd95-4662-bced-100db59a4c5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0b5cf416-55ad-4e33-96e3-4706b3ecf976	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
54a578c3-0a00-4a7b-aa8f-e0453f159372	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
877aa2de-3ad0-4e04-ae20-cef6e5cc0b1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a0313eec-3c10-4d27-a643-42292f695a3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
384c9b59-f0e8-442b-8aa0-9b810a4244ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cd96b821-ed6-41c3-882d-8919da5df49f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
23395d5f-55b6-42c7-bd18-0f93341ec2c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:57:00	TRUE	FALSE			en-gb	09:57:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c97b340e-fe93-460c-8ca6-5f5919515b2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
68a34283-f225-4400-97b2-2afc7f5f54cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes		Yes						
fed2402e-1cd3-4c13-9065-729c89079e77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
6d55dc09-6644-434f-836d-57db780df119	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	06/22/2023		FffydztezaEe stgbbuccwzwtv bhnnninnj,oko,ll.l.p					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
85a5782f-386d-4c1f-b387-d8aa38f1f5b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	06/22/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
8636397b-e206-4a3b-a19c-409d01be7512	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/22/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
daca5a8d-6e9a-45aa-89ba-b7be0c2d2c84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	06/22/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
be3f51c9-edbd-46aa-b24a-f0ea07d16128	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/22/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
94c90c3b-c3f0-4659-b7d6-b2a0ca75ad5d	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:52:00	TRUE	FALSE		en-gb	10:52:00	06/22/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																
			Yes																								
d23fe557-8cba-48f5-a50a-bfd1b0555824	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:54:00	TRUE	FALSE		en-gb	10:54:00	06/22/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								
ea4be07e-cd8c-4881-b482-9cb2568d95a1	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:06:00	TRUE	FALSE		en-gb	11:06:00	06/22/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								
f0bf8001-24d1-461b-97e2-974f4cb6cc88	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:08:00	TRUE	FALSE		en-gb	11:08:00	06/22/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								
d1d32b5c-921b-4711-a7bd-55c5153a71dc	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:24:00	TRUE	FALSE		en-gb	11:24:00	06/22/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
710e529b-97e6-4501-af19-c7c4bcc02b1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c5820c2-9843-4f79-8623-20d47bc09797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39c0a33e-0c9a-4017-8dbb-6df9680befe8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a6a4e3f-7339-4905-a8b0-96d534cfb9d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2d489e8-2b6f-4a23-af75-fa63093a8d28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d993c15e-cac2-484c-a2e4-7181735ec145	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
578a0027-0c04-46ee-822a-7e4c2a2cbfa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2e8009f6-26bb-454e-ba2b-2c82a713ceba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ded7629c-2ca2-490d-afc0-341a35bcbd73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/22/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ff795b66-62e0-4bec-a947-aebd5b7072a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
367efc0d-c66a-4a26-a3fc-0bc0a736633a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/22/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
541aafac-0dfc-4e7b-b22d-8cf3fb7dbec7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7c6052b-4501-48e6-9be8-a7e1e6e9a874	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:29:00	TRUE	FALSE			en-gb	13:29:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3c2a2115-c29e-4c52-9756-be5fb8c2c236	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/22/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f52cf988-06dc-4547-89b4-3c855c76a658	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
196cfd48-c1b4-4cf0-8336-c937377d8a87	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a80d7776-3f45-41d8-887a-d10db76471fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
212040ff-d78c-464f-8843-284e1f915556	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72a58aca-b900-41dd-a89c-195b71de796a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6191c8eb-78a3-49e7-82fc-ad95acf68715	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b09c3469-7e60-40b7-91bb-d38b3efebae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a35e4b81-1f20-4580-9c3f-f40c56766d64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
78fb8b64-cf22-49c9-a213-8ce460e60756	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dfb1c076-58fc-4afe-86da-1c63f807be13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/22/2023		****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f3595a95-d655-49b6-baa4-6fa7a876a8ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes								
2140f5a0-5e4b-49cb-a2bd-4f06cc40c86b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
af5b205d-18cd-4e83-b8cb-d60fdde59424	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
eeded6e8-ee7f-4ab2-9a46-3eae0f544642	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
296a0058-01e7-4ff7-8bd2-b5c6efbca15e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/22/2023		Clean bathroom	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e71e249d-ade1-4947-966e-7312e85aa5ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
ccef1621-37da-4364-bd64-4a00d8ec3df3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32c2dba6-e6cf-42a3-a8c8-219a100df443	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d7ed7ae0-fc66-4977-9a2e-7e55bf94681a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/22/2023		R	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d7ed7ae0-fc66-4977-9a2e-7e55bf94681a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes													
e6cc1e5c-f1d9-4190-aa84-580a62ad3da2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e541c4cc-daf3-42c2-9033-f67a08dc7a30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1e0b70f4-b524-432f-81fd-1abbcc5de68e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
546af792-0410-40d1-b607-1039bc8bc8eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
420b01f4-0e58-4e23-93f5-f8a512fcfb08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
420b01f4-0e58-4e23-93f5-f8a512cfb08	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
										Yes					
4e366ac5-551c-4e52-8e22-d18be54144a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6336e50b-b711-4115-a956-7253697f5e03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes											
59a702e3-a977-41e0-a9f9-995c1eb21a0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ef54b71-b987-411e-b503-8e94c6581bfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
70fb0960-1df9-4cdf-8977-2c337fa3bf2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 03:51:00	TRUE	FALSE			en-gb	03:51:00	06/23/2023		Goob job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b170b88-b38f-4b98-b374-25d91e985e84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 05:41:00	TRUE	FALSE			en-gb	05:41:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
63bfba8c-ce4f-4172-924c-27332a3a6b3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69df4dca-eddf-471a-9013-396c5b9e3efd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e64cf9a-83fa-47f5-85c9-4748b020d52e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc3f8c04-b36d-4156-9e31-9c6113340667	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eabc95f0-dd67-4aad-a52d-97a367f4b217	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55122b45-0592-4038-b29c-fe6c42db6c5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
2403f1b4-d8f2-418a-8e55-cabdd6c8a9cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2e7783cc-9662-4177-bd05-61eb8a462701	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	06/23/2023		Ecelente todo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
21c19367-8f9c-4869-823d-9b6acc57faa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef52b354-d265-4122-8dcf-5e566a95c0c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
470142bc-53cc-4b0c-a9ac-fcb3824bab2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5ed99417-132c-4a08-9666-de5924b159a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fb9d6bcb-b5d6-4d9e-98a3-698cfe78677	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f7849d8a-ac0d-4db9-8cde-bb0513752af0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4d8643d1-ddcb-4cde-b40c-d9b9692647e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca50d368-3f83-45b5-b855-68a8d781c5e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
9f3d4ed7-e43a-4740-b08a-92e3dbb8f889	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
809b0d31-c8cd-40f5-84ec-3684c66bb703	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
22d9db25-da89-4aea-bbe8-8cc339286c98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed54b76e-530d-4364-8c12-5c74f49dc422	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c3b8179-8771-450a-ab7c-33b3e4623f8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
2c3712b7-b2c5-437a-9812-060e8f8a227d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
7d8c84bf-fc15-4ec0-bce5-8becccd13746	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cf54e09-55e7-4702-8ac0-68c1fff97cca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	06/23/2023		Tood
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a27b5fc3-1d93-4cd3-83af-5ef963f16b86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d30adcf4-dcf4-438d-9f04-513bce30f3fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b4f6963-df3e-4e2a-9c32-af67132f51e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd02e704-fdd7-4910-aa31-91ee205471a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b72c5cc5-6c65-4bac-b948-b21ee4c8723c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
80f41e3c-e964-4a91-a139-f3230e1c826e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f2c0537c-d9e1-45aa-ba5a-d2bd9a6a64d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7eec3b33-fb23-43b1-b016-5d3db5943837	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed3b7d19-26f1-482f-bf70-1b51334c5054	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						
812cd458-9910-4353-bd23-c96cbc38f787	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b71e988a-0784-4e8a-9ccd-5ecd1dda0836	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4281f4a3-e4ac-4c73-b69a-601656e47ddc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
20c9f425-66db-43ab-bb59-233dddab6c66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a2f5fe0-398e-414a-ad13-6701080c6985	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/23/2023		Its alright
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55f82fee-1cc8-4b7e-b6bc-de4ef71248f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
356b728f-af7e-49be-bb70-6027345ce3d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
63631ef4-f035-4d5a-837b-5c65349ca053	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b4d31063-3a4f-4091-bf5d-47a597747579	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
13306158-df11-4fc4-a7cb-d04ad9b9d683	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes				Yes								
0412813a-815e-47d6-8ffb-861a77ac55ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3a77dab2-ea3b-4fbd-8308-f6b7ce9783c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/23/2023		1	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
3a77dab2-ea3b-4fbd-8308-f6b7ce9783c8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes											
e1c690c8-0bd8-4220-9f02-b4e29316cecd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/23/2023		???						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
05e52d97-2415-45bd-8625-9ea3110bbbd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
09bbe6e6-7514-4336-82e4-3638ac90a452	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
ee8d3aa9-64c7-482f-b8f2-18d8094c5d43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
1782b72e-a982-44e6-adfe-d3226d4dabf6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
56361e58-da21-4991-814c-c0f182acbb29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c1162408-9a0c-4d5f-a145-ae66754fc1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aade9e55-164b-480f-9895-3415603e8f1b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes	Yes	Yes				Yes	Yes					
ced356fa-1d5e-432e-8752-f63494ee052d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eab71bd6-0da1-45ca-ad9a-bb555c708e3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eab71bd6-0da1-45ca-ad9a-bb555c708e3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes		Yes				
6b1c6dc3-287b-4612-a6bb-4ea42af0b6a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 23:11:00	TRUE	FALSE			en-gb	23:11:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f5f02590-1b55-44ff-ab38-cc1fc0adf2de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 02:14:00	TRUE	FALSE			en-gb	02:14:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1836172-407e-4144-8a95-f65ef02d9156	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 02:36:00	TRUE	FALSE			en-gb	02:36:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
71dc92f6-95c5-4b12-8c12-3f7903913aa1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 04:21:00	TRUE	FALSE			en-gb	04:21:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
255bc594-8358-498b-85dc-e1e1a02076d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 05:50:00	TRUE	FALSE			en-gb	05:50:00	06/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
74504ccf-9453-4e2e-b05f-db946ac1b87a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
752802d1-c36c-4d69-b4a7-cf163f9e8324	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
ba4eaf7f-a07a-41af-a44d-60446d3cca3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
94fb75bd-67ea-465f-98b1-bdc76722eed1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
571b06d2-4bbb-41f3-8601-5ae152db94e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/24/2023		Sucioooo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
126df87e-b94c-499a-ad95-734d8c8637a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	06/24/2023		Parece hace un mes no se limpia aqui	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a06d7712-2ee5-4d41-87c3-3e95219ca10e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes										
2ab3bcfa-42c1-4f1b-b81d-f9b5920dd9a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7838b9e9-1406-4118-b5ed-935174538563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7838b9e9-1406-4118-b5ed-935174538563	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
d9564c7f-32a1-4750-856d-dacdce4a4c08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6db1cd91-cc57-4232-84af-6108e9cb317e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd5faa01-2206-4e26-afbb-d4c32330d5f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b69f74ab-4fe3-40cf-94f0-d9092acedee5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9e19d2fd-46f7-42f4-9899-b4aa68500763	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
dd05bd3d-8784-45fb-850c-998556797f5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0ee5aaca-dcb2-456e-98bc-69b699fb4eef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
25473d52-d6b6-44d0-9242-540aae7b21fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
0bb9281f-116c-446a-a33e-504c5af6486b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/24/2023		Funky joe is cool	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8f355dde-2b56-4511-9a31-0f396dff46b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
583685c4-17c2-41a5-b725-e167c0d39b6a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
582e38ab-02b6-4805-8823-ed5c4e39861f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f1116084-b97f-439f-98d4-f9dccb3a3955	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cdb62f88-a799-4c4f-a198-b71f58b9685f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b625636-9610-4054-840f-46b783c70914	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
09cc8882-4d11-4f19-8a19-cc86c098b358	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
218bc727-acdf-4ce6-a9c2-1ed1dd55181f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
15c3c46e-cb49-427d-a3ba-3c8165d36ea8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
15c3c46e-cb49-427d-a3ba-3c8165d36ea8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
9d3d0dc6-58e6-4d24-82e5-5311a4a52aa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
83ecf1dd-a2c7-425e-8226-99bbc99b9bbd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c93a1401-576a-4cd6-952e-4e02daed264b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
8461e2ce-c0b9-483d-9c52-d4a7c8b78e97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3bedd3cf-87f6-4fd9-a4c4-c5f865a704dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:00:00	TRUE	FALSE			en-gb	18:00:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ff999e42-0766-41bc-8826-7695c034e0d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
38013116-847a-4352-9149-f223dbd3674e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
cae68719-14f7-4c8c-909a-f57ba3ff2eef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:28:00	TRUE	FALSE			en-gb	18:28:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5bcf711f-87d6-4d87-a0f5-5d280a9691c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:36:00	TRUE	FALSE			en-gb	18:36:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cdfcc3b-e1cc-47c0-bbd9-02e6f8c5ac24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0757f162-c362-4a16-a391-81a9965c8a57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/24/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8fd7428b-5e04-4ecc-9113-290217fa83a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5e28c81f-6746-4f50-a1e8-d1b909bc797f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c8923ca1-69c4-4338-8fb8-d9ae3a4b30a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2321e52f-8743-4234-8c4a-3114b944c795	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
d1a2e29b-1750-4167-a029-2a5b3f53bd67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/24/2023		Needbmore stalls	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cdddeb0b-22cc-40c8-80fc-7aa9bf9dc571	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8aa52968-f2b1-4270-bba5-d1f99ff1b146	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/24/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8aa52968-f2b1-4270-bba5-d1f99ff1b146	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
0789cb63-b04c-4957-9597-c573b8f517c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53e9e051-4a91-498a-bab4-1b951f71929c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8709f758-531f-4abb-8719-328a00b17987	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
944db65b-d7de-4a65-91ad-cb576ad9bb8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22d93f92-b624-4873-b5f6-45064c69ad56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
1f8beea2-db4d-4c1d-baf0-b86bf8bbaaac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	06/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
0adf5dbc-7e3a-4fb3-8c2d-91112721b0d4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
d60fb363-e544-4265-9bb4-93a96f7d430e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
48d3bd37-978f-456c-9a25-17e81140d502	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
a3104acd-a137-46e5-b44f-4e5fcd8e2081	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
06f1f92b-aa45-4106-806b-6200aebf1bb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 22:12:00	TRUE	FALSE			en-gb	22:12:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4feb8131-2c78-47bc-a760-37d6d61fee9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8c80bcd1-876d-498f-95a3-f92da614806a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 23:12:00	TRUE	FALSE			en-gb	23:12:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8b201051-282d-439c-9f3b-71183e4315bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 00:04:00	TRUE	FALSE			en-gb	00:04:00	06/25/2023		Smell terrible	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b201051-282d-439c-9f3b-71183e4315bf	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
23729759-be1d-4741-b582-c7210528b613	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d2b0bef0-87b9-4c6b-ac2b-7812cde67ac7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 01:28:00	TRUE	FALSE			en-gb	01:28:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
768274ed-6308-43fb-8272-267dd5d4256a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 02:54:00	TRUE	FALSE			en-gb	02:54:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fbca4f62-2bc8-4798-bcba-5ce99bbca325	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 02:58:00	TRUE	FALSE			en-gb	02:58:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fbca4f62-2bc8-4798-bcba-5ce99bbca325	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes										
d5250e2e-be31-43ad-8d82-0a1c259c7ba4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 04:22:00	TRUE	FALSE			en-gb	04:22:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66b3b79c-50cb-463a-9e89-a99d403b8f99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:14:00	TRUE	FALSE			en-gb	05:14:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ee395174-c622-4bc2-98b7-a19eabf514de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:17:00	TRUE	FALSE			en-gb	05:17:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes			Yes			Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f9758669-f302-4b71-bc80-ac34002dac3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:51:00	TRUE	FALSE			en-gb	05:51:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9230348b-f377-4caa-a705-fab1fb680f5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:55:00	TRUE	FALSE			en-gb	05:55:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5046019e-7c3c-4361-8398-fb3ebc27ca52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
62c93cdc-d2a2-4983-b8e5-19d85c0b7d9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c1fe5f80-bd27-49fd-8f6f-2daf9106c641	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
475c5ee1-1e4e-4779-8b25-53cd91de1997	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54840011-94a8-431c-8e7f-15f45b9780b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85211060-e60d-4199-9c86-7e94db593ba9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b18514b0-035b-4743-bcb4-a325c12297bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3936fe75-acf6-4df2-9e6b-07a8736156c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0f374f34-0f49-448e-9553-f491aed533a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
706de0d1-5051-4356-8c2e-5f20df8a42b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4bd52eb3-3d75-4abd-b5ee-490963375d95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/25/2023		Tom
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c216d856-56f2-43f7-ba06-fbe2162d1b39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd07e376-0951-4802-8081-5addc22055a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/25/2023		No trajan aquinsuciooo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
4bdb2a6e-0731-4137-b437-8c6f53b71a79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
093e9c66-c270-473a-8455-844fec3d9883	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0739c1eb-ce27-4c62-ac8f-e52ac682cae3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d0cb7bb5-c605-4370-8a2c-c8fe86e5e119	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
485a09f8-559e-4806-83a3-16c732e8ef08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bd08ec22-c022-408f-82ec-2d8e7fe1dcd6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d33e499-7bd1-40ca-ae0d-1e468d51a503	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1e366212-7115-4aed-9e1d-a2c1073eef4f	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:14:00	TRUE	FALSE		en-gb	12:14:00	06/25/2023		Dirty	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes					Yes		Yes				
908d577d-e108-46ac-b52f-6dd47e144e98	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:22:00	TRUE	FALSE		en-gb	12:22:00	06/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes						
28575a21-dc26-47cd-a17f-70d25b0ba823	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:29:00	TRUE	FALSE		en-gb	12:29:00	06/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes						
df6d258f-e40d-45e3-988a-3373759a6467	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:29:00	TRUE	FALSE		en-gb	12:29:00	06/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
df6d258f-e40d-45e3-988a-3373759a6467	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
			Yes												Yes					
cd0879bb-114c-4091-9064-4d37b6a49f7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
2ca786cc-9eb1-469d-94d3-a9fdb13cac8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
74d432b9-a14f-4b0f-9473-f9100846df43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
38173d5f-6c95-4bf6-81b1-eba3b5fdd255	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
5bc5b9d4-ee32-49f3-85ba-4c0080a34467	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment											
30fd1760-bf4e-43d4-af3a-10fc498db05e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/25/2023		G											
															How would you rate this restroom today?										
															Average	Good	Poor								
																Yes									
575ed528-7a95-4611-82e5-11a70a947a17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/25/2023													
															How would you rate this restroom today?										
															Average	Good	Poor								
															Yes										
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
	Yes																								
ac234436-aa89-4a98-9ef9-ea11ef32b092	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/25/2023		Dfghjk, b cv bvawrtg??m v,,,lmmmmmlhhc ssssss md     cn xxxrgggggddddd dccccccc dddvcbrt tttv fnff nnddcff xvmmmmmmm mmmmjnnnnnn nnnnnnnnh hhhh hhhhhhhh,,,,,											
															How would you rate this restroom today?										
															Average	Good	Poor								
																	Yes								
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
			Yes																						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b195daa7-be62-4399-8b0e-8eebd6aa31f1	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:35:00	TRUE	FALSE		en-gb	13:35:00	06/25/2023		Jjj xshhhjdcmmdddd dd,dddddnhhhb ccccc kkk,nnnhjjjjigaas	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
cd5c9012-7ede-49c8-9d91-a6cff9d878fa	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:36:00	TRUE	FALSE		en-gb	13:36:00	06/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes									Yes						
ce308943-b97c-4f64-ac57-a51797af18d1	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:38:00	TRUE	FALSE		en-gb	13:38:00	06/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cadabb23-24ff-4015-bd76-b75dd71f6a68	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:03:00	TRUE	FALSE		en-gb	14:03:00	06/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
cadabb23-24ff-4015-bd76-b75dd71f6a68	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes							
56709a02-0796-49e9-87ca-3c8373a086c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:05:00	TRUE	FALSE			en-gb	14:05:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
672d3cad-6553-43ee-aedf-8183781aa4b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes																		
0171128d-011f-4b46-87e9-cb293fd8c1ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
1e926b34-339c-4965-bb84-4082179d7f9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0fa9b0bb-74c8-4eb8-8e89-99d43e6b6518	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
556bf66f-caea-4871-bf47-c682095a0fa8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
566b9ff3-6292-40f7-bc01-27f565c42303	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
167411fd-e575-44ac-bfa2-36aed6b5f465	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad01398f-ed22-457f-bf6b-d01db213141c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
74926bb9-a096-4766-b696-9b2546e9adbf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
62e5bc96-b885-41e8-8e68-d8b82b6aef6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ac9f2625-8f14-4db8-9dc2-3b4a552a2114	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c364a7b9-ebbb-4c99-9387-8849ef4d5e68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
30152984-f187-456d-818e-3527a57e28c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4411bb68-f963-4325-b951-3fbd634bf6a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
97af9359-3f24-4ba9-a4f7-da7f6f3e5965	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c7a37750-cebf-44a2-a17f-aef143d9a106	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76f8fc03-affd-4240-96ef-feb2b778210c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2c1ca7ad-c231-4068-8285-4c4fe99940b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
35f9b662-9abd-43bd-8610-c953fe46514e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f8fcc6a4-3723-4052-9fcb-906c5c9aca52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
e1cca707-9831-40b9-a4e4-d7bfb0250478	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:30:00	TRUE	FALSE		en-gb	19:30:00	06/25/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
															Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
			Yes		Yes				Yes																		
09145a50-349d-4aed-97b0-07c4417b85ee	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:40:00	TRUE	FALSE		en-gb	19:40:00	06/25/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
			Yes																								
b6b3c521-d698-4769-a9ad-99fc42fa9c8c	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:48:00	TRUE	FALSE		en-gb	19:48:00	06/25/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
			Yes																								
196e7bf9-f683-4202-a11b-2e6a4acf28e1	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:51:00	TRUE	FALSE		en-gb	19:51:00	06/25/2023		No condoms													
		How would you rate this restroom today?																									
		Average	Good											Poor													
														Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
								Yes																			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f4f4923a-d361-42f6-b1bc-8def21196b1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
084b6b61-c198-490d-9ebe-c52999419043	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/25/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
a6f13f82-4897-4c9f-a7e0-5c86d40f2d76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						
11b91b9f-9782-4bd3-b39b-a7eedc12a06c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a0e4d8a0-ffb0-4cdb-b58b-b19df3f243d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fbbd14a3-1161-43c9-8e5a-7c713db5152a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
537882a7-8cce-43cd-a2ac-56a6420a45d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2d38efd6-2d54-4531-8b5e-c183a4a44f00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ded5daf9-2a5e-43a5-92ba-45acf855ee15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c831ea3-c379-450f-aab7-efe662d73c5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8324174-7984-4340-9334-cffa3adcea84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:06:00	TRUE	FALSE			en-gb	23:06:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66dd1982-335b-404f-9c28-f56c6d2eee30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:33:00	TRUE	FALSE			en-gb	23:33:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
729b8837-7cc6-41ca-8ae3-5f11581e9166	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:47:00	TRUE	FALSE			en-gb	23:47:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
105438ed-2dfe-440f-8083-ee7089568301	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:57:00	TRUE	FALSE			en-gb	23:57:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
105438ed-2dfe-440f-8083-ee7089568301	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
555f4561-a2e4-418d-a7fe-69e497803b3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:02:00	TRUE	FALSE			en-gb	00:02:00	06/26/2023		No						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
b7164684-3ab1-4404-b5cc-36f192532eb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:14:00	TRUE	FALSE			en-gb	00:14:00	06/26/2023		Bad smell						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
c69e8113-91c8-4d55-b438-3a10e958f9de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:44:00	TRUE	FALSE			en-gb	00:44:00	06/26/2023		Zzzffgdddddy						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
531a2eab-95c1-4618-a949-ff6593725916	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:52:00	TRUE	FALSE			en-gb	00:52:00	06/26/2023		Ewww stinky	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8d4cf25b-c1c5-4bf3-a25d-91ae49c84e52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 01:03:00	TRUE	FALSE			en-gb	01:03:00	06/26/2023		To hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ed4b2ac-ccfe-4b98-a2c6-cc6b9bac4f4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d4d67e12-656e-4309-9a1a-29d97a59c94d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 01:59:00	TRUE	FALSE			en-gb	01:59:00	06/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6452617b-9624-40ac-95cc-d4cd65830e0e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 02:25:00	TRUE	FALSE			en-gb	02:25:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6882f94e-6eff-41f9-8e46-8c36d668529f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 02:31:00	TRUE	FALSE			en-gb	02:31:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f6b45179-8e62-46bd-9151-63c149bff7bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 03:03:00	TRUE	FALSE			en-gb	03:03:00	06/26/2023		Smells bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
89322c16-cc45-4040-abdb-f45956897256	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 03:04:00	TRUE	FALSE			en-gb	03:04:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1b588a18-5da2-44cf-bcd5-b508c047e18d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 03:26:00	TRUE	FALSE			en-gb	03:26:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ffbda842-c895-47fb-a307-e0ccf6fe7b01	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 04:11:00	TRUE	FALSE			en-gb	04:11:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d9acca3d-446f-482f-84f1-5385a3855083	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 04:36:00	TRUE	FALSE			en-gb	04:36:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c8bff6cd-f09a-4870-8381-85fd2d642026	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 04:53:00	TRUE	FALSE			en-gb	04:53:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b9bc81cf-f34c-4948-80a3-41bdaf2117fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:15:00	TRUE	FALSE			en-gb	05:15:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eedb8f4-b415-42c3-8f15-7c0c39c0c5e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:30:00	TRUE	FALSE			en-gb	05:30:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9dbf4777-4615-4145-aa42-0ba55bc491f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:39:00	TRUE	FALSE			en-gb	05:39:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5dbcc9ea-8777-4559-a275-616788a680de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:45:00	TRUE	FALSE			en-gb	05:45:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10d82e92-933f-4cab-957c-4a8b7efec5ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 06:30:00	TRUE	FALSE			en-gb	06:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad7b95da-dea0-4554-acf8-54e1d2db519e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 06:30:00	TRUE	FALSE			en-gb	06:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6b599326-bb2d-46f6-a7e1-3aaf9fa5e6c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ddb92a3d-fc6e-4ce9-810a-4c0902d47e75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fa1922f1-8724-48b9-9efc-60c5dd45edae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1a098948-9fc1-405f-b39d-209d31554964	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a0e5bd7-6403-4462-9745-17a6497a19aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e0190dae-ff45-434b-8951-210c791dea6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2aa3316a-5727-494a-b1f7-b3d975bf3081	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
78f0989a-009f-4a36-9825-893a2c1dd959	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6fd8ec1-e8dc-4d21-8088-f5b29afff885	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0291c8bc-41de-4342-98fc-58ac8c2ced2f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9184598d-ff28-41d1-9b24-07e86f219249	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9a940c38-89ca-4bfd-a27b-cbbcc0eef040	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
56c9cb40-7b7e-4d1d-8d83-5dbfb57dc5d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6adf1ca9-9388-4b98-b97f-faff1baf105f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a6d94842-b886-48d9-9e17-eb11c0b27182	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3c70449d-6920-4626-ad9d-50257522fe35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
75aea0d4-e95c-4535-b5be-cf3acfa0b3fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c97c14e4-af39-4444-9805-bb869fcb6781	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d82303a6-f880-40ba-a868-2f87a8b6914e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
877ce1bf-71e5-4d7d-9426-5b0327cafd2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
42d36c7f-4a54-45fc-b895-16b873d6f8db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
17d824a2-19ca-425f-bcd4-3ba09e516888	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
20fede87-2d33-41dc-a0de-3a58d0ef47df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
f4d98452-c903-4b89-a27b-5d9886640052	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
bb8783c7-794f-400e-9260-fa429d6bce5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
8c29d708-f60a-4cf7-a120-45ee7cc3cfd0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/26/2023		Right
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7026ac1b-0d03-4319-9965-620a31d167e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 14:54:00	TRUE	FALSE			en-gb	14:54:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2378868-623d-4a5b-8881-65ea4abfe1bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	06/26/2023		Add a smeller so it can smell good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6b1e6e1-1f09-47cc-853e-327e8424bf86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1e9a902-18b9-4717-a595-59267ee4ca73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
787ce17b-3cd2-4af9-8a73-704181b12e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 15:50:00	TRUE	FALSE			en-gb	15:50:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2950a263-f661-4b9d-a16e-5d6f578b6de6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
60a83bec-dab1-4843-b63c-fdb2ff744d8c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b7d0ca5a-91d4-46af-b969-68b4513a7751	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bf757ab1-3df2-4b54-b480-972eed880f0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2875c5ec-b22b-4602-ab1f-0db9b123bd38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/26/2023		Rigth
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b1d92ee2-fdea-4dfe-8a0b-8528bf834eb7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d51f56ad-08dd-4b9d-8a5e-614f401c7542	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 20:38:00	TRUE	FALSE			en-gb	20:38:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30e367e9-a55e-4704-8922-18b862d3a3f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
25472375-7260-4dd0-a86a-6682ca06e8ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
48f1bf0f-545e-4e42-a381-ce931676a659	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
73ebde0c-8941-4239-a8cf-4ed93affc5fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 02:00:00	TRUE	FALSE			en-gb	02:00:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
023b010c-0b6f-4794-a4ac-66b4a3f91251	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 04:14:00	TRUE	FALSE			en-gb	04:14:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ce7898fa-8264-4eb3-8506-0187c5f73521	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
ce512221-7218-4701-8caf-68810f17dbf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ebd96c61-4142-4d4c-9cb1-dfecb356ec43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	06/27/2023		Great cleaning	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6418cf85-bb14-40c3-a0bc-6cf6036c8528	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
17684b15-6903-4351-b342-9a2fef6596c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9f721e84-1cef-4898-904c-c9ddd6501403	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
69aa9754-cb51-4f37-b2e2-97496989efa1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/27/2023		Your bathrom is ****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
69aa9754-cb51-4f37-b2e2-97496989efa1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes											
26b83ca7-18bf-441c-8520-1ca6c3928408	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	06/27/2023		Joosh
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7c90140f-1df0-4d22-b8f2-187d25267657	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7c90140f-1df0-4d22-b8f2-187d25267657	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
eeaa71b6-ea9e-41b7-a63b-4c946dd3749a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes	Yes	Yes	Yes			Yes					
eeaa71b6-ea9e-41b7-a63b-4c946dd3749a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
31f27bc7-8244-4461-9307-a00f49b37e81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
59aa4758-63ba-47af-a2b9-757a429590c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
90a68b47-c6be-4d80-9c6d-5c86b024128a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0da6ceff-0069-4e06-a3fa-257196c43845	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bf30134-2304-4b54-859a-42a89e1d84d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
201a0ce4-5685-43e1-8dfe-f6735f325a6a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4de86eb3-2dbf-419f-84fe-5991fb64f91c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
876879cd-69fa-4a46-9786-0578bb31d252	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
08acfb94-aebc-4676-9c0a-aeaff56ce00a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5be1a029-a237-4ec8-b2f3-82250172b9de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1cd270fd-4207-43d7-bf18-203fe6943477	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d6260027-167a-497a-8906-c7c9d03b56f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d6260027-167a-497a-8906-c7c9d03b56f1		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
							Yes							
c57a7e79-81bd-411a-85f6-d171949d0878	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ebd4ecfd-c467-41c1-b40a-673c094b2497	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
860cc21b-080b-4eda-b92f-43a753a31563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
e84024f8-2fe6-4339-b182-b543a2a65fce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
b43ef8ad-4232-45e1-89c2-019385689c89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d182add-1ff0-4e86-b5ab-4023d75cf14c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ebfe5eb8-0218-4908-9f60-39aaaed455a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0db1fc07-b602-46c0-97c5-c8b2053ae955	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	06/27/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9e70513-6c5b-4dec-b7a9-053ba8d7ef59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c019f48c-3f70-4a0a-a8e3-797508e0f8fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4997c7e9-6f70-4881-9b78-f91a57b7c056	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d4861b4-9105-4acb-a5f0-1b711dd2792c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
760b8aba-b9f4-4723-a291-b803b950d58b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a0c18e34-fabb-468b-811a-c4e1966d7c1c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9e0b107d-5c29-4c41-9e95-8eda8f41e0e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b08ee15-5b5e-40cc-a8c9-c570287d1adb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
4b08ee15-5b5e-40cc-a8c9-c570287d1adb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
											Yes									
8be180f0-065c-4a59-b3cd-1f9a34ad6392	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/27/2023		Good						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
e38de5f6-c349-44c6-a3b1-276ad6fcd9b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/27/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d3f797af-4ed8-4ac1-b946-7158ff00a355	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	06/27/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
ea267d97-f706-470e-bb1a-f1663f9fb509	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 16:26:00	TRUE	FALSE			en-gb	16:26:00	06/27/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
												Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18c04493-cf37-4b21-9736-5a87d97a8964	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:25:00	TRUE	FALSE			en-gb	17:25:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e7330eee-1b19-4490-b7b6-e18dbc93ce87	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c62be447-2d3e-49af-a901-88a2b481b16f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
409e9da9-a8e2-4c5c-8887-868c8c994179	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4630c39f-42ec-4b3f-bde3-b20013ce2a61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
896c8542-8a4d-4505-ab9c-86f28ba68769	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8be9a107-c946-4773-8e74-2e39e2980c1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
90bef88e-d10e-40df-b3ca-5a2600788f91	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c69eb743-fb36-4706-adb4-91e3ed89e90c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f7739688-fe14-4372-bdcd-a32164bf50a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
20f3cf51-2fea-43bf-ad4b-d9a83d87a9d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c083cf2a-3b6a-47ec-9694-4912b86a3779	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
01ac544c-a506-49c1-8630-210781392e77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4061e994-9048-451e-8c01-af97705fe99d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8496cc3c-91c5-4d2c-8559-973ba47ee847	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/27/2023		Very good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
490d6a32-fd1d-4767-9aff-38749abb3529	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/27/2023		c	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
49bec07e-2497-4bd0-924c-63e57dc21155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0346251b-5949-446d-bba7-7ccc023eb4e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ec5e64e4-e03b-460f-a50a-7a75deb68e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
dc81ac01-8fd0-4c0b-9ef2-f48c5d9f7db6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes					Yes								
65c930f4-c11c-4a32-8060-9fb730a67dec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
45e65193-e652-45d4-98e6-15b288b3e400	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9452cf4-cc12-452a-829a-e928f0360ea3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	06/27/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
86a95a3e-5e56-4367-88c5-a85f2a4d28be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
54d2b50a-d95c-4c70-8657-36c9d8c3850c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a55dbee-3cb0-4cfc-b4dd-1305edd67120	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f0ad5f6f-b042-42ce-a711-1788159ae72a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/27/2023		Dfffffffffffffggggxxgmkcdd	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
17cba600-e88d-44be-835b-70055252c62f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes							
ef01a571-dda8-43fb-b838-e0fcd84fddad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 22:06:00	TRUE	FALSE			en-gb	22:06:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2e3de1c8-f8b5-41f9-880e-2cd3aaed0885	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 22:11:00	TRUE	FALSE			en-gb	22:11:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f5412fa-f474-453b-91a6-c65f4a47a73c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c2b798c-88fd-4e02-8b6a-735563ae48e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 23:32:00	TRUE	FALSE			en-gb	23:32:00	06/27/2023		Saw a bug,	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2c8483dd-7e69-4189-9ede-d568c6c39d7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:17:00	TRUE	FALSE			en-gb	00:17:00	06/28/2023		Fix some of the door of the bathroom doors!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0d14ac56-ddba-4bc4-9f9a-df77577101e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:20:00	TRUE	FALSE			en-gb	00:20:00	06/28/2023		Fix the doors	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b344eae8-88e3-4c65-88b3-400f2b709433	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:22:00	TRUE	FALSE			en-gb	00:22:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
09d6ec2c-c792-45fc-a763-064f53348fb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:24:00	TRUE	FALSE			en-gb	00:24:00	06/28/2023		Clean yo bathroom please bc it smells badddd!!!!!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b6d43c54-46e9-4269-9d4b-990c13e6084e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ab48bed6-d31d-4ad7-bb85-810ac493549a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
381cfb5c-54eb-4552-817c-18c5bf47d6d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b92d1f9c-37c3-4898-b905-edc5602c0c60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e804859d-4037-4956-a887-fcbce8fbfbfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
740fe70f-8ed2-4172-b884-ce2c773d4f96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
077aebf2-578e-446e-b766-fd86e59db728	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/28/2023		Nooooooooo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8dfbb413-cefa-4d6c-aba2-d0914d7b82d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/28/2023		Make it beterc	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes	Yes			Yes	Yes							
0aa1c9fc-3d4a-49e1-8e92-40ba4316a05c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/28/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0aa1c9fc-3d4a-49e1-8e92-40ba4316a05c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
53c24bdb-b714-4516-a613-43e928015ce1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/28/2023		Uuuuuuu,
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes		Yes	Yes		Yes						
b6ad0c7f-be3f-4045-8957-d027a02b6623	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/28/2023		?????
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes		Yes	Yes		Yes						
e78b804e-e03f-40ea-81c1-8184ae13e437	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/28/2023		Noice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes		Yes	Yes		Yes						
5bf5223a-f6bf-42c0-87e1-96f3f45d96b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/28/2023		Noice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes		Yes	Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
527b7b4b-fee3-42e2-a122-34efd971aa92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3f862e66-fa00-4704-aa2d-a9e58d654548	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cb229029-413a-4209-90a6-c3d85aef2bf0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes		Yes						
8687c8a9-9fc0-4e07-b61a-410172b0cadc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cf906e0f-67d9-41d8-b4aa-529e73cfff3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
838a97df-2a9a-40be-8871-1ec269ca35b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
36b75b1f-ceb1-469b-b56c-94c2261c4c8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2f6b6484-789a-4970-ab4b-a359e1e259f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6812c7d6-530c-431d-ae6e-32d580b64110	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes						Yes						
108eb072-0c91-4ea1-a16f-46ecdcc9aede	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1b86c092-7d8a-4d5e-91aa-5811c8204979	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6d19cd3a-b8ad-49e1-9569-24d953cf31be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cad76381-a766-4f9c-8c2c-d39eb3e9c1f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3d8dabcb-0ae6-4263-9555-b9e2fb5e76d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7f60f619-8a19-41fa-85f6-eb802a846c55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c697a91-2d92-4ee7-aec8-13bce07aa467	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
32f74859-b0ea-4caf-8c5d-e3d77a768de4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/28/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes			Yes	Yes							
b1bfa3c-4569-4fbb-9c08-91d37231b592	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
da364df9-8240-42e1-b65a-bbec1ea8a6d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6ff15319-a24c-4403-9e3a-0d5ff3e77377	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
b1910e2c-6583-4cf7-a37a-1afb23ddfb4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 17:24:00	TRUE	FALSE			en-gb	17:24:00	06/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
d33f5c70-1bf7-49a1-bccd-627e6961dbb2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes								Yes					
f80d2e3e-9de5-4c2c-b016-7f39dbd11d31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	06/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes													
e64ae82f-8f87-4121-81e0-951a86c3c0f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	06/28/2023		Happy					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8c2f4573-b125-4fd3-af59-51c1014ec8bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d21706b0-8768-4a29-b1d5-d4d1772ce494	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7a5eb58-c426-41c9-9e08-9eefd41a6d95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes		Yes					
adfb78b-d4f1-4f9a-8c4b-a6f0354a6b2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	06/28/2023		Floor was mad wet ngl gang	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
967d9387-2592-4bd7-942d-9a331baf054e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/28/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
967d9387-2592-4bd7-942d-9a331baf054e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes					
1be34f12-0453-4c61-97f4-0b8c4c0760dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d35ddc38-6ca5-4c04-a646-4a5a8aafbef2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
80274978-d033-45f8-b345-4dd91b1cae7e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6553a10c-9154-43f8-b713-ea79c4839b70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b3fcf87-dde0-4676-ab85-4c0d0133f287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 00:37:00	TRUE	FALSE			en-gb	00:37:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5b01e650-b02b-4b70-9259-62c300aeadc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 00:45:00	TRUE	FALSE			en-gb	00:45:00	06/29/2023		Great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f523ca13-c48d-482d-8cf0-7edf382842d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 02:39:00	TRUE	FALSE			en-gb	02:39:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7f83c77-0427-498b-ba2f-7bdf18cddf89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 02:51:00	TRUE	FALSE			en-gb	02:51:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24cf0a39-80c6-479e-a60c-b2a3a4deb56d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
749a8b65-1389-4f11-bc0e-c4b7fbd637be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a8090ec1-bb95-4c6c-a46f-ccfb81e32bce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cce3b48e-b5da-48c6-b942-09c61429748a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c145231-d616-4602-a4fb-3d2c99bf00da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d3ea59bb-8abd-412e-831c-78fda16f831d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/29/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fa624fe9-2916-4ff5-8d9a-ffb03706c993	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24b45558-adb3-45eb-b8e4-7fe2cef47907	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
13e40779-bd4e-442c-ab20-c50f0b074316	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3ee083b6-ae47-4209-8c38-ae7e8c24403b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
24daa651-c082-44d7-a080-f254a183f604	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8b001d7e-710b-46a3-bc42-7a5ce6b711f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7a1e640d-b88d-4edf-ae1d-8b2ceda5e0ab	Gate D10 MRR	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
7a1e640d-b88d-4edf-ae1d-8b2ceda5e0ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bb7a7f18-68fe-42ab-9ac2-6a0caa10a790	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
af71ea25-b227-4b86-906a-2b6ba52adb84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
693b7efb-c493-4091-be70-1c5d4ee64c5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes							Yes						
a583f2d1-919d-45b3-b2e1-52bc628a5022	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
86366ed4-be27-49a9-a2f2-ef34b01e9f73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
19ceb96-d3f0-4183-aef6-53c647ce2fa1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00e83b2a-fae7-4abe-839b-dd63a99d3592	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fce61bf7-9e41-4c11-ae8d-e1a683a789b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f0b183a4-b0a0-4d67-b47b-f3ac5bb8cf50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ad002b32-510c-4b8e-b2ed-29ba18ed09bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3b3282f-4977-405c-896f-41e99e79e8b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eb5f4e64-fbda-437e-9582-6fa4ca510e75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
efdbb80b-914a-49fa-94a1-ae770da2f753	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f85ed86a-6704-43a4-a478-9be8351ad36e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9834248e-adbd-47f2-bcf6-274798adea27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7ab53fac-fcce-47d6-9c53-8198a0fc82a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee4d7456-b0b1-4bb9-bb01-db602c5d4c50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3b0edc15-22f2-4f04-a671-849c50081268	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1879c07-ed57-4b63-90a8-49a93a8ec9fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca6bf63e-afc7-44dc-970f-76c82fdda429	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
59ffd323-c7ec-4cec-a8e3-9ca900fc0a9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d34c87a2-8670-4f53-8fa7-69219048025e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01059f1e-9f6e-4664-8f69-861e56efb4eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
01059f1e-9f6e-4664-8f69-861e56efb4eb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
24fb494e-2512-444c-bb78-6f0a9dcf4eaa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3989e00b-5c65-4b47-8adc-732ae65a8e09	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
93c3dba7-5677-417b-be3e-d82a78767b07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 15:50:00	TRUE	FALSE			en-gb	15:50:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1417764c-b5ac-43d4-bdc9-251731dd7d79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1a2f207-8d13-4fed-9c14-b0c9b413453f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
365190b6-68f8-4030-a67d-f5644b49dd83	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c9cf0822-da6f-40e8-b2e0-ae0ce411e9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
70a6be71-d673-4f39-a1f3-edb2b0e2a19b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5a588b3e-b514-43dd-a951-f962715c042c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d266afbc-ed49-484a-b3c6-abc74861f273	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/29/2023		Need more toilets	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fec92a87-f726-4d63-8e5d-8e15facdc78b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a143ea4a-75ba-4593-93ba-7f97c71e5253	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3edf4133-ad09-439f-82d3-b5a21580ec80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9e951ba2-e924-4e5b-b456-6ee4a918011b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9e951ba2-e924-4e5b-b456-6ee4a918011b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes					Yes					
b2336d66-fac4-4fbb-b40a-88d868dfd048	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a152491b-c00e-4560-b5b6-1b959071e1a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 00:19:00	TRUE	FALSE			en-gb	00:19:00	06/30/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e6515fa5-e406-4b70-b401-dec6dd32e8a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd942cf9-a97b-469b-a90f-fd10e448bfc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d9cf547-f189-4b78-b8f1-f715ddff9bfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
606cb1de-87af-417e-a616-13a507d1c65a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14db2b2f-58ad-4f80-901e-9958f9ce6ffc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
97fa6f3e-4f5b-4af7-96c8-a4302b26dc49	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
867f5a9b-b865-4472-a0b1-308ceca64978	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/30/2023		Not enough stalls	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
e76da3d1-49e7-4dc3-a239-409dbc03662e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/30/2023		Super todo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a6aed582-e7dd-4947-a0b4-5829cbbd384c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/30/2023		Limpio	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6bc6b2ea-1132-41c5-a5df-d10b547e9589	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fd049fed-69d4-4fdb-9ce2-f7da3c70710f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes															
11772f8a-c8fa-474c-a4ed-e8b6f6da21e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/30/2023		Middle sink doesnt work, right sink doesnt drain	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
					Yes	Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dfb07224-4f5c-436a-9a67-078cf7b3726d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c62a805-9039-47fc-aa99-6352625f3a71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dda982f2-f519-41d5-a769-64b454813307	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a28c08b2-cd98-4600-b627-92abb0bda12c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f8f67b2-4927-4597-8b9a-b71e7fe20ca3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
251dd269-334d-477d-bae4-65de4beabe7f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
59e14cba-d80d-4754-814d-1d7d49016119	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
515ce972-8bd7-47d0-ae75-c3f1db2fa4e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
284150b3-45fa-4c03-ad29-e6a7608ff759	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fff5e550-5915-4f5d-a3ce-8ea6d1815fa9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
afa17feb-06b2-45ff-9d7f-95cdb2b16652	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/30/2023		Sucioooooompesimo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bda36e7a-fd87-45de-baf0-167be484f50b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74d2b745-64d8-4559-8112-d6df1bc022aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19bf4a78-d06f-4344-8a84-38d2f07f7493	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	06/30/2023		Luv
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0800b775-20ff-4746-bd01-a213f26f87f7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b78ed129-a422-4218-bb10-6accbef133e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cb2dff68-e4ae-4ea4-a1ee-2df981328c8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
52c0aa53-f055-47d0-92ac-71695e4a03a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2980dfeb-8523-45be-9a91-bc4d2d236b79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ba43741d-2e6c-4c88-bd0d-135d0076f2d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85d4d6d9-49f9-48da-8233-ef9e2687d505	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/30/2023		.biem
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d05be8cc-a8d0-4871-9abb-102df6d7faac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f380a8bf-25a1-4b66-a30e-6f3efdd38379	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6d080ba0-15f2-4ab2-8aa7-e43bd0eaf465	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cb74ae85-1e7e-4857-b2f9-29d0c9964d30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c208ddfc-d427-48e2-a449-4ce8bd10a732	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
06f66cac-647a-4433-9d59-e761dc82857e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes				Yes	Yes	Yes						
b1e000e0-2d72-4650-9dd6-5dffec0ccb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/30/2023		Just do a little bit more cleaning	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b1e000e0-2d72-4650-9dd6-5dffec0ccb5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
501f21f5-c1e8-412e-91c5-789434e9e161	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/30/2023		Clean it !!!!!!!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					
5bae4a66-dc2d-4f17-9496-0244153e7b0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					
62c46cd3-5316-4343-bddf-cf4557e734f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					
54150061-2d7a-4191-a9da-1fb4dd33d6a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54150061-2d7a-4191-a9da-1fb4dd33d6a5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
											Yes			
651a2240-b883-4d81-9058-41d508271511	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
267615a2-d3bd-4318-8e9f-383bb89b103f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/30/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ace9909d-bec6-41d7-ba67-cf301b6ff5bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:01:00	TRUE	FALSE			en-gb	17:01:00	06/30/2023		Nop
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
5d62b0e9-4410-420d-973c-bfab5a0461b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d4c08f33-826c-4473-b5fb-0d03dd5b42eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/30/2023		Dood	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
42ababe4-fc59-4e4b-acc6-aae43274e150	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1b631f0-ec16-49ca-8f30-a7557d5827ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:58:00	TRUE	FALSE			en-gb	17:58:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
446ab724-8ed7-48ca-8c14-7fe52be1353b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 18:04:00	TRUE	FALSE			en-gb	18:04:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
24ae844e-a267-4350-8c06-0c6db5fa65b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	06/30/2023		This bath are discuting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f0dd24c7-b7e7-4511-9faa-54ffa294e83a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca7f1643-27d8-42eb-a1b5-482022170c5a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
35421326-793e-4172-b421-5eab68fb31ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
005c6d3d-3581-469a-9516-2abad9b9fc30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
86c5091c-c317-49e1-8e78-69c2c3c7af13	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
86c5091c-c317-49e1-8e78-69c2c3c7af13	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes					Yes	Yes					
a5002c5a-f78a-47e8-b492-2f04ac9d21d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/30/2023		Ffrf	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
9ba8d048-b99e-4307-bf7f-f203e38ac45c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
97d8bd0e-2c2d-4dbe-a051-dd0c0c9eaccf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
9fd718f3-a6db-4cb7-9c92-fa9f83000983	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9fd718f3-a6db-4cb7-9c92-fa9f83000983	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
28d7479c-05b2-4177-89ae-fafa682469e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 22:40:00	TRUE	FALSE			en-gb	22:40:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ffdc0983-bc52-4f07-a50d-ba5fae3f9275	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 04:28:00	TRUE	FALSE			en-gb	04:28:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19319cb9-ea88-42fe-8e42-19389e47b9b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 05:04:00	TRUE	FALSE			en-gb	05:04:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0f6d01df-44c3-4b28-b729-baca7fb3d267	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d6af817-e005-44fd-bb7c-ce11487fab7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f5723b91-5909-48e3-b11b-e43e8b523bf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
23052e36-c5a2-492f-ad4c-4c37d9105ebc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ccf4fdea-eb48-4188-acf2-fd98fcd19e1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfc75959-b5b1-4917-8b7a-373626a9a75d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d44af0ed-62d8-4c31-823c-e2e775da412e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f12e4ef4-3063-4a42-b846-cfceb400ed79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
57f51121-4b52-4403-a25c-5c1d527009a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b0183776-50dc-43ae-afb6-495445ab7758	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6ba9fbc-8d83-41ea-928a-993c07001255	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
97c323c4-388d-473d-9982-d9339e82fa80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ba9100cd-97ac-4323-baf8-e6dec471fdcd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:08:00	TRUE	FALSE			en-gb	10:08:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0648dca8-5a05-46c8-afbb-c75cc3382813	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f02e9091-b465-40d5-88c4-93b4145cae1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0cce6509-512f-4288-af29-80c49ac27cc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9d1d5efb-202f-4b86-89d7-15e22fff912d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
03187037-d9d9-4db7-88cc-19f511b1116f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
073a4109-4797-41a2-b31d-0a6772c7a205	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
321ebae2-2591-4f31-968b-fe71cc9f2e8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a2e1235f-1412-492d-8607-12b25c8a4dc6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	07/01/2023		Mui bon
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6dad0458-bc55-44e2-bb09-d28e1cd64006	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	07/01/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c9e56b80-a1fd-4e84-886c-1246d5f42f8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f557b777-0685-4675-a7f2-0ef3599de3ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ff91983a-77f7-4b74-ad8c-271bd7560fb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a59c40c6-3c6b-4c74-9f35-95dcb6b29e5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4677af4c-2542-4dd1-8cbf-a215f9c22c67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes			Yes								
e8cb64cd-f65a-4805-8529-ab6746f39000	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ec8cc408-85f8-4e21-8728-0047fb3cf356	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ba72299-0a4d-48fc-b53a-7a7a1a5a83bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f398353a-9692-4486-8627-30a8c6ed9ac5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1c2aba90-b18c-4ac0-a539-37c579c9deff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	07/01/2023		Ggfff	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
2f118415-3383-4a64-b63a-b865965de20c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
b83ec000-9d0f-4e7a-9564-816d6366be51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
f8ca5726-a0b7-41cd-ad2e-ca3447ff5d2b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	07/01/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
9c4a756f-ce52-49be-bb9e-84f62f1b5b69	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	07/01/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
75065b5a-5522-43d9-809a-d5bf122f1d3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 23:51:00	TRUE	FALSE			en-gb	23:51:00	07/01/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
e401cdb3-a919-4e72-a626-535167a26e03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 00:37:00	TRUE	FALSE			en-gb	00:37:00	07/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
6e62f088-fc91-40de-b34e-d46233fc1b42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 00:45:00	TRUE	FALSE			en-gb	00:45:00	07/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18a57ac8-bba0-4e8c-98c5-a57701912d40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 00:46:00	TRUE	FALSE			en-gb	00:46:00	07/02/2023		Melvik  eerqaszxcvdergtgfff ffffff hsutsygs
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7188404e-de05-46c0-85a6-967caf7d39ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 01:38:00	TRUE	FALSE			en-gb	01:38:00	07/02/2023		Mer
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b9568e05-7b22-48a8-8116-99038f616af0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 02:27:00	TRUE	FALSE			en-gb	02:27:00	07/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0e1c49fc-0f73-4cda-b135-25704ad5dc3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 04:15:00	TRUE	FALSE			en-gb	04:15:00	07/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
276bfc20-72fc-4b8a-ac1b-9ca4fd9546d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 04:16:00	TRUE	FALSE			en-gb	04:16:00	07/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
937159c5-16b9-4de9-a969-49fd44d7a804	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 05:04:00	TRUE	FALSE			en-gb	05:04:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
aafc4480-af15-476b-a9d6-d031c68394ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	07/02/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0042e74e-20da-40ed-9fe6-b0600b6d9852	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
74e6818e-0614-4a31-9003-80fcf0393e95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 06:06:00	TRUE	FALSE			en-gb	06:06:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
74e6818e-0614-4a31-9003-80fcf0393e95		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes			
0aee1353-e652-4d0b-ad5a-f98a0392a6b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 06:08:00	TRUE	FALSE				en-gb	06:08:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ed8be166-27f6-4049-8b76-489228e92e8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:11:00	TRUE	FALSE				en-gb	07:11:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9a1a9450-eb64-4d05-ae25-de4b4e7cef19	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:12:00	TRUE	FALSE				en-gb	07:12:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
cb1d523e-06f3-4fbc-af8c-4dcdb656eb27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:13:00	TRUE	FALSE				en-gb	07:13:00	07/02/2023	Estaba sucio
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
90402065-9445-4472-8527-f0ba21e651c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:27:00	TRUE	FALSE				en-gb	07:27:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9455456d-baba-4915-96c1-e1e1d73e7f79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e364a33a-e8ec-47d1-bc5c-c75f7b800f4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a16d2694-aeb2-4a54-934d-dff046137160	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1048a9b7-45c2-4c7a-8d13-74891edc561a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c84dcfdb-0020-4e77-83cf-46a0e115d0b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6da880bf-c31a-4016-9bec-9ee1b505b602	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	07/02/2023		G
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
44054877-1bac-4ef8-b4b2-61d5e18e2003	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ae074d8-15cc-4cda-9a5e-2c94f6cc3aef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes		Yes						
648512f5-d1b5-40c1-82c2-745e7835339e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55ce1aea-a329-4864-8ab6-9fb177562a0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b0b2c0b0-a5f1-4b6c-a165-d02e9dee5d00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a4609246-a7be-4e77-8b81-1d566176d32e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53946a57-17c7-4574-84d8-d828e1052198	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7c012dc7-f5a5-415d-8099-3fcd45d3daf1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
29a50562-7602-42b1-80ac-07593ec595af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
df9e94cf-5ba1-4e2d-aead-e3c9beb04757	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f175a5c9-4ea2-491a-93c3-5c4e1135103e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	07/02/2023		Pestoso y sucio parece no?trabaja nadie aqui	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
34188baf-517d-483c-bf7c-87726c05fab4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ffb1b550-096b-4801-80d9-72d792a67d1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
03670f7b-3668-4c7a-aaeb-9a067c1d67ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
03670f7b-3668-4c7a-aaeb-9a067c1d67ce	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes						Yes					
6d2c51fe-9765-46ef-9188-8c43b4d786c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3002a3b1-3837-417b-a7ff-3992f94a1930	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bfd3be28-6091-4d0f-9ea7-482403d87078	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c1299ab8-53c7-4560-a57d-ce31b8015d72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:10:00	TRUE	FALSE			en-gb	16:10:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
84c48785-2fa0-48ed-b761-adc066c92e54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2d190571-17e3-4576-9cbd-871e6baabb17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc61dc4e-61d8-424c-9cf5-e4c70bc28bec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f827493d-0ed6-4764-9e6d-af9df3147bba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6067fce-ecff-4791-8660-3eca08c7d93f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b9b8ebd3-e927-41ec-9c26-1b7239a25c7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9684ca89-fb54-45f4-9e4a-7cbae249af18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:31:00	TRUE	FALSE			en-gb	17:31:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
654677de-fda9-410c-b1ae-81d34b20e9e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9d065d6-8271-4bd1-9567-f4cda808cba5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b3ff9138-6c68-4392-969a-8c41fa194be3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
01521881-44c6-4469-ac8c-25147d7eca90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
86456821-534f-4d26-af6f-c004416d41f7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6d4d170d-3edd-4cba-8402-27a1631bc996	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fee46ba5-aa89-4329-855e-91079276e9fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2f1ebd0-703a-4a6f-8777-442580bec4ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f013c15-927f-4c69-906e-5c8ffaecf63f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bfd9c8b-ae72-4a51-bff0-e110ecef63d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bfb8b436-2ef3-4d0f-ab4b-77803895eca1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0001cf2b-94f1-4676-a5d0-5e11bd2bea17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e1e8b9da-f3e4-4ab6-9c97-5feb47a67087	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86eeb9f9-c729-4fb5-9e60-d603a4583451	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b43036b-82f4-4920-b3f4-ccc73560fb03	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0c3346d-f257-4ad8-b1ee-ad46d1d487af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:41:00	TRUE	FALSE			en-gb	21:41:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d47939-7b0a-4f42-92e9-2ab6f8c0f2c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
004a654f-c828-4138-9e21-77f14d8535d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 00:07:00	TRUE	FALSE			en-gb	00:07:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7d43b7c1-d161-4303-9325-b972f2b5802a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 00:09:00	TRUE	FALSE			en-gb	00:09:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
053229b5-859a-4a6f-970c-09e3f159a00b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 02:22:00	TRUE	FALSE			en-gb	02:22:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2d9cdae0-08b3-4ea7-8ef0-3a06ebe18059	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 03:02:00	TRUE	FALSE			en-gb	03:02:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e19d84e3-532e-4f11-a26d-f0b926c1e7b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 04:11:00	TRUE	FALSE			en-gb	04:11:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e76f4071-019c-4b4b-bcd6-5ddf1bddf3e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 05:14:00	TRUE	FALSE			en-gb	05:14:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4d0a932-8df8-403c-ab0a-6ab780eab1d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	07/03/2023		Muy limpios
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
be903b44-a121-4d8f-8cf8-bc4e0644e5bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0aadb81-829d-4a55-8e13-4cb85aa6a66e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
530e8290-3a89-4b1a-a9fb-951764d6178b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e565456e-ae81-4d82-95c2-059c24a5e3f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7e1747a0-d457-44ab-b573-88e565d54f8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a615debf-68c0-402b-97e7-06b9ea945e30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
02fd7802-337c-44f3-9824-458d183fce51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c16fd02-0f33-40a0-8d48-4ec132803e9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes	Yes											
5e281e50-e282-4b11-9045-f1157548d5bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
5e281e50-e282-4b11-9045-f1157548d5bc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
9a1dc357-73d0-411e-a59e-146476de0ff8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	07/03/2023		Clean it!!!!						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
163a8669-1a6a-446f-a93d-b3654951cbbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	07/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
f3a41268-7aba-4af6-a61d-b5830c4f68b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	07/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
93c7137b-d367-4bc2-b45e-e48b5778a4fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	07/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
8b9144fc-8bc5-41b7-bd8d-1ac6c4ac8a7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	07/03/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
759ed550-d85a-4ea4-a30f-9f4b5d8564b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
778e121a-1044-47be-bf4c-dfbfe36a4dd7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
646aff4e-22c0-4dc1-acea-3d9d559e8f0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	07/03/2023		Sucio	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7dfcdcd4-cb7e-41a6-a314-bfce5d77a745	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f393c1f9-f3a4-46e8-8d4d-8646e3b0568b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6966def8-ab1d-42f6-8dc6-039f73b4b02e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5c3a5111-2f46-4b40-9bd2-ff098c9d6c0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:18:00	TRUE	FALSE			en-gb	11:18:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
19aecf8d-e15d-466e-baaa-334d9bb497b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d1811875-4b98-4c75-b7d2-1dd1d2edbe2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1811875-4b98-4c75-b7d2-1dd1d2edbe2f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes					
e157411b-c120-41a3-8470-ffa81cf3391b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
951e7993-7074-4fc7-ba6e-05e2d40fa10a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f677cae8-5050-4479-939a-87781a2a3f74	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
2d4099c4-fa6b-4634-b571-f261423cff26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2d4099c4-fa6b-4634-b571-f261423cff26	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
75c95354-1d3d-47bc-896f-b2d4235ecc67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
75c95354-1d3d-47bc-896f-b2d4235ecc67	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes						Yes					
aba9b72f-b3dc-4acd-b79d-6bcdca6b45cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a31a2f5d-136d-4896-9ae4-e13739885bad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3dace061-609b-40d3-a887-d6a66adb8f3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
192eb914-7b59-49eb-9ab1-1287c922ff3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a87f5b61-c321-428b-b5fa-20d25a8fbbee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	07/03/2023		Ngodvd2
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4544496-bf57-42a4-909c-0d040e322d2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	07/03/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9c3d9ca0-5627-4a34-8244-4a0c4f7aee26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
09597cba-27cb-41ac-aad4-582f0dd295e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dcd1b170-1b4b-48b6-a27a-325f9a8be93f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bb0d520e-15e6-4f1a-9c7a-65e0cca1ab89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
62145292-3610-4dfa-9c46-2033d3cf8d73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cb2b261d-fa21-4bd7-9640-c3f2af4b01bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
833d12fd-e130-4e0d-98cd-9db090fe98c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
71af1ecf-c00e-4efd-b525-07bb4696c3eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	07/03/2023		Bgb	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
78d2c040-f624-4be8-bf3e-30d02cb93ea5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6757d218-a204-417e-983b-89b15052db7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	07/03/2023		Bad	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e23d5fc7-0c21-4195-b91d-0d6e616ac6a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
25e0871b-edef-4cad-b07c-c235a1ba76e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2614b7f3-3f3a-4203-817c-527a2c849bcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	07/03/2023		F	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
34c20817-0cc1-4d03-9355-061f43dc703e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 22:52:00	TRUE	FALSE			en-gb	22:52:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b4391d24-8226-4270-8e24-3a3bedf51563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 23:22:00	TRUE	FALSE			en-gb	23:22:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
89a27e21-464f-4d3e-b1a7-730db14e70ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 01:06:00	TRUE	FALSE			en-gb	01:06:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8cb71149-404a-489c-a345-077d8bc1c73a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 03:17:00	TRUE	FALSE			en-gb	03:17:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9fa141ab-b2e2-4838-bee6-de8b17aee89e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 05:40:00	TRUE	FALSE			en-gb	05:40:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72a95f3c-800e-438f-b548-4f50d928e75c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes				Yes			Yes		Yes					
e64849bd-8848-47c8-bf7c-509e9fc52864	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes						Yes					
51b26f4e-624e-4c32-a312-9aa68aafbd3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
51b26f4e-624e-4c32-a312-9aa68aafbd3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes		Yes					
ced9754f-54e6-4763-92b5-aeb7715d02bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
fac4a715-2c12-4a87-b89d-024078d88808	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	07/04/2023		No						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
761db4d0-b639-4bc5-a372-4e29e49cff68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
								Yes												
4adaefe0-c4ca-4128-b814-6d34357ceeca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	07/04/2023		Love						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
173b3004-0c74-463d-980b-4e7c041c015f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	07/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a8699d0-f11e-4c68-99d3-0fd3ffb169c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	07/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
08549766-d660-4946-9aec-495b3cbe5282	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	07/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
79f20e7d-1b4c-46a4-bdc6-843cb5187c15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	07/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
86ae924b-7887-483d-b2bd-5ae67aeae456	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	07/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c4e471cf-6d1d-42f2-8c84-297e571c6d74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	07/04/2023		Mj
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c4e471cf-6d1d-42f2-8c84-297e571c6d74	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes			
5ad266c4-b85c-43c0-8143-f8f4ab42d4f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ae5a0dec-5131-4f83-a84c-48abe489d7a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
b94387a8-86a6-4278-a146-a936958100dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
23e146c7-6b69-44dd-a9c8-f85caf22defc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	07/04/2023		More stalls						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
fcf185de-f277-4aa9-b61f-f87594b8527e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f7e283c4-5cc5-462d-853e-ca5b7c9b4042	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
fda81cad-cec4-45c9-9ef9-374a50831067	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	07/04/2023		Very nice he helped me
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									
f936e60e-085b-4336-bf75-ab911ed89798	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
c9a71e78-039d-4b5e-8fb3-c45179038169	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c9a71e78-039d-4b5e-8fb3-c45179038169	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes							Yes					
ef812058-2cc3-4ccb-a302-4bf7f322a3dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c623a310-209c-49aa-a95e-710d660ea2d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9f98efe-35ad-4e92-9958-535d8c0b9ff7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												
858608d2-384c-410d-aa29-9cdc846796dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2e4de218-f2af-48d9-b15b-f52ad0834336	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0677e277-51ad-4ee1-af63-bdbe85c23df9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 23:26:00	TRUE	FALSE			en-gb	23:26:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40227254-8233-4518-9b3e-5ec3fc8db122	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 03:44:00	TRUE	FALSE			en-gb	03:44:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
58a85934-682f-478d-95f7-213561384faa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 04:29:00	TRUE	FALSE			en-gb	04:29:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
359b72ba-c867-44d7-9e4b-10b4dfc6121c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:00:00	TRUE	FALSE			en-gb	05:00:00	07/05/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea7fbcce-0f30-459b-b77c-6eb70f92be77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:09:00	TRUE	FALSE			en-gb	05:09:00	07/05/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d57a1604-6bb6-424a-a396-d8470352cd61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:20:00	TRUE	FALSE			en-gb	05:20:00	07/05/2023		100
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9088294-e878-49e8-81b7-332bea847013	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c6fbfc9-2f72-488b-b8fd-4a7d6e84a3f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 06:41:00	TRUE	FALSE			en-gb	06:41:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c3b41e7e-4b4e-4066-a3fd-7c2e01da9d40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f4da96a-d8cb-4e7f-be72-5f5792e984c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c753249-81ec-4b01-b140-a7ed7974d83c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1218cc42-2057-42d4-ade2-105dd2c79dfb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b94d3a15-27be-48a2-8454-cc5013079fa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01c4742a-6843-43b0-9cf3-a1d516d8c444	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c55dce9-fca8-4b6a-baff-0ed91ed10242	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	07/05/2023		Bhg h
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9efb382-0b88-468d-9099-e666dab640a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/05/2023		Suck my ****
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd022b9f-aa2f-43b9-b345-fcfd96c9263	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7a0c86c2-ad79-4c22-9bf8-4b8290381cfc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cf84dfab-4193-42d0-a279-971c3328dc88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
345a2682-2fd8-4640-8d6e-f52a32f1e0ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
354d18bc-916c-4467-af43-c7cc1eba2fbd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5250c1f2-8587-493f-9048-26dd25d0d5d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5fa66b7-82cb-4800-aaa3-569f5855c7b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5fa666b7-82cb-4800-aaa3-569f5855c7b7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7bfc4b9b-0082-424d-969b-b6693fb5aa47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	07/05/2023		Update
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
af9c2483-ba3a-4e43-ae61-7c69bfc03b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 18:31:00	TRUE	FALSE			en-gb	18:31:00	07/05/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1f31c1f4-46d4-4737-ad65-bbc83b2ed857	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
3162fbd0-b34f-4f13-8f73-adeb187df221	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e4f3346-720d-4d93-804f-68bdae5ee7d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
62baf6a-e8e4-40fc-a552-025b8121446f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	07/05/2023		It is very good i approve	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bfce586f-c2b9-485d-aac0-cedddd2c0d38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0b87ff02-3be1-412c-b629-03fa24077fa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
039e62d0-6224-4fa8-a237-0982b688c744	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
69a2a68d-9a2f-4e0d-9ff8-eb4323d81f33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 23:13:00	TRUE	FALSE			en-gb	23:13:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6d13368c-638f-4243-b650-b716032ef41c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 23:29:00	TRUE	FALSE			en-gb	23:29:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
c829acfb-da16-40a3-a017-faf83635bab2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 01:09:00	TRUE	FALSE			en-gb	01:09:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb974955-3faf-413c-81df-cc8fdfaea5d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 01:23:00	TRUE	FALSE			en-gb	01:23:00	07/06/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f912de2a-2aaf-4f91-8cb9-8c3c2f4cf2d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aef91cae-c1e6-4d9c-b656-95045b285246	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2926fd38-8b10-452b-bf07-5858cee56276	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	07/06/2023		Good love the vibe
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a992ba66-41b6-4e75-bd9a-d7f4e2d59cc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:47:00	TRUE	FALSE			en-gb	05:47:00	07/06/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0d75098-dc0c-47ee-bf1e-af068c0cf582	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
754d6221-c1ca-43b8-a3e3-1ae977996027	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72d4b22f-47ae-40c0-989e-8986f513f972	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ade5a53b-baff-42c8-91cd-27c52301b335	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9e7e597-5dff-4ae8-9a95-d7b0598a2957	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d9dfc0c7-3a81-4aec-8194-4f2a45103489	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9615fa36-4cb6-4806-a986-7498aba47e6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5c1e2092-a068-4ba3-a3e7-66297bc4a46c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7f0d4f99-c431-46c9-a4e3-78f06cd849a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6489c47f-e1ba-4061-818b-bf7ad0f3031b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6ecde8d7-9965-4ad7-8325-6fd3ebce80d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b2858db3-bf50-46ef-a0c8-500c83612bc8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9ef644b2-b34f-4b1a-9c41-90b423cf3e24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c05f9711-09ad-4033-8313-07798fef3e3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea1c289a-a360-4e7c-8bd7-797ac7785bf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
67395d97-ca85-41eb-8d69-13e6fd3b7f0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	07/06/2023		Only two stalls and it smells
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7ccdbfe7-776f-4a7f-b4cb-303bc8257257	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10b74bd9-71a0-416c-8dd1-e9b2e0b795b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	07/06/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
caa90ab1-4baa-42be-b00c-bfcea47fc8159	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ac96d6c-6414-4e4d-849a-28a91867f26e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c8f384a-9a25-4189-a63b-2f622596c6f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06493f87-5d33-4d9f-ac37-e7667cacb1e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fc0c1ed8-1894-4d11-acc1-20b7d218be43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d041dd4-1dec-4b3a-8a0e-d08f1ffd44dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f7ec5ac-93f2-41c5-b897-c387d1402d45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	07/06/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3cfc3b39-1fd3-44c7-be9f-e66e90718b3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7c79650b-962a-4623-a614-55b53290d003	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3aeffa9d-896a-4ea7-a540-3409c5c65cde	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5735f9e9-7208-4f16-a876-9217ee2aeefd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6386cc81-c34e-4406-a54f-ed444cad9a81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	07/06/2023		Restrom good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
126d2e74-3f1c-44b3-9a17-eb8c99fef5be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	07/06/2023		Keep up the good work
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aeed84a8-7d13-44a0-8f3a-9a679c82bde9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81537566-1886-4291-a123-cb60d69da811	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	07/07/2023		***
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
64bb564b-f329-4cb7-8b5f-9f7ccb2e76b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	07/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
98d5dc8a-5207-4a1a-9546-fc090cead302	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	07/07/2023		Gunner
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd6227b8-69d2-4a58-83e0-08d03b54121c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	07/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8aadb0d1-4fdf-4020-94c4-e318b3988425	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	07/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f790ee6-489e-42f4-b02d-0de19a8a80ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	07/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f9cca8ff-e3cd-47e0-9a4a-d9b0b59df637	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	07/07/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9cd563a6-9f52-46c0-8024-455b1deb559a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
23d22d02-a63b-4174-974e-3a98625177e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
413424a9-cf0d-461a-9ddc-e20b3297c991	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
301eac60-0007-44f2-bafb-5ab9707fa966	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 10:17:00	TRUE	FALSE			en-gb	10:17:00	07/07/2023		*****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
a2f2aab7-6bf0-46f2-97b1-dbb65f5f6985	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	07/07/2023		Best	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
093226ab-596f-4086-9b43-fc8820c6b4e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8940f6d-1bcb-4ad8-a802-eee3f9fc0f3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	07/07/2023		Very clean :)	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32a4b233-587a-4c42-99c8-9927340ea9cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
58e4e888-2238-4401-8de9-a027553ac8de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/07/2023		Smelly eww	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
77ab3cc4-0036-456c-b6b4-15c88209646f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
205c3e5c-33e3-4785-adf4-d985ab3f509c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
4ac710d-e77a-459a-bc21-5d759d69aa89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
b2c3a36e-460c-4e65-9034-5963787a0ecd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
02279a47-33a1-4a46-bb7c-5dfe41c172ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
dda90f52-084d-4ede-aea7-67cb12dd1e14	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
dda90f52-084d-4ede-aea7-67cb12dd1e14	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
82f0b0e3-7844-4406-9eef-521721e0feba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	07/07/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
								Yes						Yes				Yes		
eb1c9227-b996-4e4b-b5f3-bdbb14caa3c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	07/07/2023		Puto						
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
														Yes						
c2e646ff-1f1c-4beb-8a75-9546e6fda993	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	07/07/2023		Great job team						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
98ca8d1b-6360-41a1-a685-675296784694	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	07/07/2023		Bad work												
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
9e1006e9-a5c4-4068-925f-21ea6d29de20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	07/07/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
a9ec5886-052c-4824-b394-bff612964259	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	07/07/2023		No												
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
76bf794d-c052-460d-b5e3-f0330b4f2191	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:38:00	TRUE	FALSE			en-gb	19:38:00	07/07/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
9e039979-f810-4c1a-8d1d-8a7bebcc8b9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	07/07/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f269b03c-f696-4d8f-9777-fa9e21385ad7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a6587478-b5f9-49ff-82d8-13aef282741e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 20:25:00	TRUE	FALSE			en-gb	20:25:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
89e48f1a-e047-4589-9bc4-0bf37274dcaa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes			Yes		Yes					
				Yes	Yes			Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
e02def45-bec1-4eb7-b5ce-5ca27a70b37c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	07/07/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
a16c88af-5c3e-4803-903d-189537428fa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	07/07/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
07413e50-942b-4888-b7e9-0ac600efe33e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 22:19:00	TRUE	FALSE			en-gb	22:19:00	07/07/2023		Hi														
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
b4f51c62-ce99-49cc-a2ff-1138819dbb93	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 01:14:00	TRUE	FALSE			en-gb	01:14:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
d668c7e4-3b24-4a49-aded-eba3e4a837ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d847b730-65ea-4a9a-8043-6f2f462c7198	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6348cbc8-50a0-47fb-bffc-ec984c731ac4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	07/08/2023		h
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								
b6219299-d112-4cc4-8835-dfcbb2a4af1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	07/08/2023		Not enough stalls
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								
b24116b4-93e1-425f-a47b-a0fe614966ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b24116b4-93e1-425f-a47b-a0fe614966ba	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
267a5487-131a-49b3-a510-c6356e7684ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87d76d12-c792-462c-b4eb-7570f39d8438	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f20b45dc-ee2a-4012-adb7-c1dc0c4f14e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	07/08/2023		It was great
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4a823c9-e97d-45a3-aaaa-2b9f19451c88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
182e76cf-355e-4479-bf35-21a26048d087	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9251a0b1-b84f-4f93-8809-a35d7b649da4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 13:28:00	TRUE	FALSE			en-gb	13:28:00	07/08/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7dad7f6b-89b1-4414-9cf9-3cc1f27ee755	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	07/08/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
744bd5bd-e962-4780-a6d2-d504206e56fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	07/08/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
98d9c37c-0e84-4503-bf77-92d6981af971	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	07/08/2023		Smell
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
6abab454-9e82-4480-ad39-5fd072d026dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c34c171d-709a-4409-bc7b-4520f4daef63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
e27eb9e9-94de-471e-a25e-91fe89fa43ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
8f7d4c92-521c-42e6-8968-4af29427fcd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
49a87ca5-c4f6-481f-9588-e5143eae2485	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
07348a1b-7ea0-486b-ad35-4d97d45ce9c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b50fca8-4ea5-4406-b529-8e79a46269aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	07/08/2023		E
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4f60a3d1-292d-41ef-bb6b-ec17178e466a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86612a15-4ad1-4d94-84b1-5f8562efd374	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:46:00	TRUE	FALSE			en-gb	16:46:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dce0372c-0cc9-48ab-a93f-fec11993409f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
929591a1-db6d-4cb7-a23d-dfe52809f002	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7dd88cb5-2d13-4967-bf12-ba83a6e1284b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
de2fac12-7e07-4db9-9549-caed1acb7a8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b9349c40-41f5-4018-b59d-148c4fb3e15f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	07/08/2023		People bottom was leaking	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ad376f75-2cd1-46fa-90c0-ae563133f00a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c010383-f0ab-4b9e-9a9d-d551dab8d8fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	07/08/2023		*** on floor	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb4361cc-c1f3-4fa6-9f32-e0561d1e3e7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7506915-071a-4307-a9e9-149444d0879c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 06:50:00	TRUE	FALSE			en-gb	06:50:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
af8ac89b-5859-4bfd-9946-9a23009f3bc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 07:13:00	TRUE	FALSE			en-gb	07:13:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2059d37-71ae-4e31-8912-55c2db4eae5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f12d8718-1f1d-4993-87df-6bfa1829b884	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6a520838-0174-44fb-b0d0-61f47611790b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 10:08:00	TRUE	FALSE			en-gb	10:08:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3fd2a7a-a498-48b3-8efe-ebb7042d1559	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 12:47:00	TRUE	FALSE			en-gb	12:47:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b8ca5933-2658-4e2a-9c66-858b235d86ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc927849-89b2-41cf-9f42-9a925aa1472b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
21faf8a0-7872-45e4-a75e-bff5ef55debb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
faea3479-1a9c-46f3-a326-716a2de26c03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
faea3479-1a9c-46f3-a326-716a2de26c03	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes											
95bc4b8f-c3ab-497f-8e0a-fa4b8bc55d15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	07/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
3f43b365-fbc3-4c03-af44-973faf7d8b68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	07/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
957d196a-53e5-4839-8a0e-452706c324f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	07/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
e596170e-6bb9-4f36-9f70-6b95d3ed8aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	07/09/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
0f913608-ecb0-45af-a7e7-7b5b01505f9d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	07/09/2023		Good						
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2e18e49-11b2-4f70-bbdf-bd235d6cdcab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e9d858a-9efd-4b35-b452-72d1a9b8d92f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3bf64f31-7eeb-4b28-a01d-45d26cf9e765	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bb9927c0-1bd8-414f-b8bc-2b390ca9f671	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bd2bba2d-f8ea-4d49-a402-6d1545335f0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	07/09/2023		No coments
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4526573d-8539-4246-8b13-2d8a8a152e70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
78a5ec6a-dff5-49d6-925c-8d0755da31d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	07/09/2023		Very Clean. Thank you.
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e200450f-deea-4fad-8f29-21872be3b737	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
21598744-c781-4fd9-8596-ed51644e23d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30f8f48d-bbf5-4d13-803b-adac0d752e2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea17e8a1-5eb9-4b8e-80b1-0858cbda3215	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7743b0dc-0007-4244-a049-43898eee43fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 23:41:00	TRUE	FALSE			en-gb	23:41:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6912b11a-d25e-4c2d-8c38-a6d822548958	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 23:42:00	TRUE	FALSE			en-gb	23:42:00	07/09/2023		Israel
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f703fda2-81ca-4397-9bd3-638b61fa1398	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 00:16:00	TRUE	FALSE			en-gb	00:16:00	07/10/2023		Cleaned
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c45e678-0d06-428d-9fdd-40afb2a8b6f7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 00:23:00	TRUE	FALSE			en-gb	00:23:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c9fd98f3-2779-426b-8043-42972654951b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 01:37:00	TRUE	FALSE			en-gb	01:37:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a2bc442-8783-4e1d-9292-bdf88ea5b19b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 04:12:00	TRUE	FALSE			en-gb	04:12:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c53a9cd2-2c81-4df2-9bb4-a654cc965747	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 05:03:00	TRUE	FALSE			en-gb	05:03:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8c467247-f5a6-4188-85c7-1a608704a521	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 05:20:00	TRUE	FALSE			en-gb	05:20:00	07/10/2023		Fernando	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3404abec-a603-4e06-a8df-0809e536b584	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 05:50:00	TRUE	FALSE			en-gb	05:50:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															
21f565d3-305f-4626-8171-8c04a52a2731	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes			Yes								
6b0da0ef-47d1-4942-90bd-7d84de4f6b25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 06:55:00	TRUE	FALSE			en-gb	06:55:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
460f1784-e477-497c-9e84-3ef5e0710945	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
455b284d-6528-40c5-8e6b-eed23fef878a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7e7c2aae-2417-4daf-b063-8875b7f9c287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c2e88071-d12b-4505-b55a-536261ba6407	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f87552a8-ab0e-4cd6-85e3-81bc5e238bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	07/10/2023		Ni
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0249bee0-8f34-484b-9fd3-52efbb6359fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed31751a-babd-441e-b57c-d6939e7783c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
994716dd-7e92-45f8-9834-1c27dac6d464	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5f6d60c9-8e0c-4608-a17b-f4866ea88dc7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7f070058-d329-43fa-9551-61d1a11f633e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
770fa12e-15dc-4361-be08-e5ad47e10d54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c120a0e2-7b7a-41f9-bcf8-e2a520a0325f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0a83e2ac-69de-412a-af0f-1bc99ee61950	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a1f037a-6c62-4318-a389-35a26d00235f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	07/10/2023		We want a bouncy house in this john
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c04aa2c-5d34-4bd3-b431-47cc1c21a4ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	07/10/2023		The water was anice tempreture and the pee felt great
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
662ef13a-778a-4579-87da-4050bdaea800	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
08461b8f-2fb1-40cb-9ee4-b3c57d6a6ac8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
18a64483-8494-4a68-9c1a-a42aa7498f57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

## Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
efd25925-5aee-4fa6-82c8-1fa2ae9f5847	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	05/10/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2293173-271a-4bb6-87bc-fbd5c6f6434d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34b9b83c-0f34-482b-b426-e2be86c9721a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0174a11-d67a-420d-8c38-de3918a7be09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
57cbec90-6250-4de9-b1e1-711d1cadf640	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b3cf70d1-e3ea-45ae-af05-d34071e7a4f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8570b1c6-56d9-4709-bb8f-98da08a855cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fcaa485d-4343-4a5a-90bd-3e2626385dda	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
879cc1e5-f543-4dbf-ae96-728329b9817e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2726a82-7cc3-4fb2-a865-b9a8c470b807	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56e5e9f1-74be-4c55-85eb-4f2b56559bb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d85fd100-3637-431f-87ce-eabd69c33709	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ec4baf82-51b5-48b5-b26e-b2540bc20add	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8367f580-df87-422f-98ed-5b9fb7e87a56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	05/10/2023		:) 10
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6dfc7ce4-3e2c-4102-8bb8-17550ddf012	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	05/10/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2af52c4-7814-47db-8e0e-5a39bed7803a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d514cbd4-bad7-48ae-87bb-7558175d7e1c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6077dc47-bf8f-4718-a8e9-6212cab92945	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6be308e2-c72d-47b2-9bee-a2a3241bca87	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34a1fb2a-f60c-4964-ac15-d4dd65e2ebc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ed5466eb-9dca-4bdd-8849-f82b78df985b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ebfe9afe-2406-4a63-af34-dac52541c8d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
032cfb8e-d605-4b7e-86a8-72a2f07c8b88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ae274e04-02a0-46e7-a8c3-783960ed1c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/10/2023		El bano esta excelente todo muy limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e17133b4-b765-4935-b103-1a9007e7797f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
65f56e0c-f2fa-4ae1-ad24-772bdf0ed462	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f2800183-f39d-46e9-99ca-024eb81500ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6d6ec0a4-332b-4e10-a7d0-275ae61f3044	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f01619ba-ff12-40ef-a590-4a2b53c9e26e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca420cae-1377-4cb0-a734-a2fb86f7d82c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1f32bc6-8490-4ca9-9f99-df2cc97b457a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	05/10/2023		Very good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d77002d-9e65-44ae-a7f4-b31a279e52d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cbdd491b-7bad-4489-99f7-d024b3039e56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a28a8a60-49a4-4704-af39-6a2eb3def505	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
33ad796d-3c46-4c08-9cc4-4674066d3878	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
18691c39-496f-42eb-83b8-023a81140e51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4f895457-5431-4622-a30f-c7951ee0318b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c21d3b73-1b23-441f-9b87-4d1950e8656a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aa6ffb6-a391-47fb-9496-35ab00fd9598	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2993677f-ad4d-47c3-b5d6-5497daf6b281	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
91e84980-b9bc-4201-b43a-364fb714fe48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2b9fc08d-c77f-4c17-b843-63d084e2004e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:29:00	TRUE	FALSE			en-gb	16:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
409c659e-3f6e-4aef-abe9-12b709880a3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
751b32a2-5ef7-4921-9bf8-b81b664d5830	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
463871a5-fc7c-4287-8327-dce1afb426f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a1606623-32a1-41fc-9755-07dd63b14c45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dd36d264-3db3-4584-aa17-d37a3cbef0c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c738230f-1a4d-4181-a0dc-3e8f6c901240	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fade60a-e14e-4c54-b615-0beabfaafaea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5be2bf43-801b-4f59-a720-caf7ad0d553b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d6ae08ea-69f7-41f4-b674-b1be2a23cbdd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
86ef659a-cb00-44bb-895c-926ac48b610e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:00:00	TRUE	FALSE			en-gb	17:00:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
86cad584-36a9-4eeb-be5b-52266e3cde3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9c00eee-2cbd-46d9-95ec-b1041f7cb432	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
709a0575-5d7e-4e40-895a-4d4f3f932905	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c88bf25b-9827-421a-a277-23cb645c72e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28092748-2dbd-4d41-bd92-6a1558c51327	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6d8c1028-70cf-4da2-8e0e-04ba00eb246e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f4e90665-1af5-42c4-bc94-9b9aeacadb25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5853cce-028d-44de-b731-8248d6fc3547	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26801272-9323-430f-a9fc-865dfb4cf448	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/10/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
30fcd2c1-02e2-4d3d-99de-2db2a6754e20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/10/2023		Was perfect
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc48c6cd-e92a-4645-9f9e-fe01a0d4a265	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2df90564-524a-4304-b93a-50a0a2529057	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f9025f5-a023-44f7-90bf-ee10a9f7d317	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b08ecafb-e762-495c-8170-89a40bd585f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb83bb31-9052-4c37-b752-c487804a0684	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f3a56805-77d7-44d4-bc6b-f1bb0e0f0975	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a76e6130-371f-46b0-9c3b-241e1022bd12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
875a28e8-b8ee-498a-bfea-500970b0664b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	05/10/2023		Super clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
01bb53e8-7145-48db-87f9-cbd756c3bc7e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2c658e51-d8dc-448c-a81b-e9357637918b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4722edd9-f01b-421e-a450-727cd421c2c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4307e7d2-0c15-4e66-9785-b52b3241ed48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
950d7fc1-995c-4182-9d07-dc02c2124b45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6b41e722-e945-4831-87e8-f16161bf3310	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
57db48ab-b6c5-41d1-8d78-dec6aa1063b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
322f9857-3597-4177-87df-a2eaa381c8f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
aab318d2-fc2e-489b-9038-f18f36a2503a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:03:00	TRUE	FALSE			en-gb	18:03:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
bfbcadcb-9cf0-49c9-8553-d51d27e84bc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:04:00	TRUE	FALSE			en-gb	18:04:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
923d1bca-822b-4651-9df2-fbe0c7bbe4b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
a27bb480-8a59-40d8-872a-26c755ab5855	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	05/10/2023		Clean
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a27bb480-8a59-40d8-872a-26c755ab5855	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes				Yes	Yes	Yes				
673412e4-a4a3-4bf8-9384-5ec4d831a05a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
aed20a6d-a1ca-4437-a056-92ae0c955e1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
ed48895b-89ae-42bb-8d03-34109546159d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	05/10/2023		Excelent services	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
7816be58-bd61-4364-846b-8c8165b5f4b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4efdc57a-ac74-4b94-b812-6dc9b284c612	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c838bf3e-2feb-4f16-8893-698dd3f9ac62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d443527-21ad-46e0-9532-9baa6db14289	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c44b9725-26c9-4ebf-92cd-f9d5eb92f3c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
921bc59a-d34d-4d8b-b735-7806d6e6d9fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5fdd1dc8-7924-4e9a-8737-2087835ef8db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ddc34886-0988-4955-acfe-8751b4770818	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eefae641-606f-49d9-bf6d-3d2c33da8d5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
85558972-4109-44e0-a160-75ba88cdb856	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c6df421f-2130-4b91-9e40-7cca48d1ed5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
96f44468-1a01-46c1-8860-1ab5c3a37ac6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
309710d9-7ae4-41b2-93a1-066ded300a7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ecc8ae98-6c88-4577-a8bf-a05dc731e805	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0ce09d1c-78b2-4db8-a82c-ec85c3049274	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9baba749-e545-4303-91b7-62dc6e6ce6ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f0ed33c6-f6a9-45a5-9aed-534d2609e656	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a9ef719-5a3d-45be-9322-ebfe26e35fbf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a602b4ef-1b95-4a98-b2d3-be335a42b8f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54a711d0-609f-45be-8c20-43944676b6ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28b200a6-b3f2-48d2-85cd-1faa46d3007f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
256ea9c2-4b27-44b0-859d-18fbd0ee37b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d45e0a74-27d1-4d6e-a794-b890d9bf4cb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae04fb6f-ddc3-4458-a7cb-ace2941efb73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0f585b3e-ce23-4289-9802-fb629a9f570b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3075a9ed-8ecc-432f-b672-9af81a1b97df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:24:00	TRUE	FALSE			en-gb	19:24:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3467d437-42e1-47c2-9d97-9a833263dd7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8cbd445f-0931-4957-b1c0-c2180cb7cd40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b53dc58-e52d-424b-846f-8750377b5fd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	05/10/2023		Ok
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
005b37a5-c8b8-4228-84f3-284762d59467	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e787da8-0bb3-4eae-b3d1-ae80a528917c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8ac51bbd-5050-4539-af82-d67aa87e1617	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
79468479-bf5a-4e7d-8fd9-6d77607e78b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0256c4a5-f93f-4ad9-a3e6-e7cdb0bcd303	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68477a8c-8801-44f7-91d1-aa5c27b38430	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c27c84c-6e52-4daf-b8e5-53fdf67d2223	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/10/2023		Perfect
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2628fcf-31d9-44b8-822f-4c0eee21d33e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

## Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e8ed0e7e-b83b-4fc5-bc08-ef41e7873c62	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
130657d1-96b2-4683-b34b-833cab8f126a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
766abf6c-7e72-4cac-adad-8b2e8b4fecf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d6d5b62a-1744-4401-8664-f73d138311f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/10/2023		The lady that clean the bathroom do and amazing job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c45a660-bde9-4cd8-90f6-5d7f3526d0cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
21bbe4a5-073e-4fde-bbe9-b6fc6583fd65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	05/10/2023		Great	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98369113-5e28-4f61-9e42-24f144c84767	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
69a77a0e-0a76-443e-91bb-847a2b399216	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	05/10/2023		Finish	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
16324b3b-fbdd-4b80-9769-7e9639664820	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3738270-fe90-4d79-8c24-7afa0851f461	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
335ef08a-76ba-4721-8261-1a5f07e2d162	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
bf19a5c2-e73c-4538-a90a-f8e3dbadbdec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
e972f2dc-c845-4a2f-b5d6-4c63a8cfeec3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
33ea81e2-271d-404d-9551-4e80b9ca650e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
59a8e97c-dd12-4058-ad5f-9e97998039b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	05/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment											
1c6fe01c-4731-443c-a727-3718330f2522	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/10/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
810d6ccf-8c26-487b-853a-8b69a072d514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/10/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
b2230938-6a4a-46f0-8629-353f628d1eff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	05/10/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
d83aa208-f145-4cb1-a581-be085b491c02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	05/10/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
cbbe5775-dfae-491e-b0e0-11a989b4850f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	05/10/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
591053b2-9dda-42ac-9afa-24e2ff41ea31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
c3bccff8-a734-4758-a089-e52e355a7e93	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
1dff2302-9d21-4ade-9a7f-9ddeb44b7720	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
d0d7b867-3d64-4b86-a008-9ce1888f2d28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
d23ef464-39f4-4ce9-9a77-dcc19c4d1dc5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/10/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3e071d2e-d003-4d99-bd69-d7cc11064e06	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c46abf09-a4b0-428d-96b7-9ac73047d77e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d509aeae-a84b-43b4-b2ac-a71fcad5ce8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
97aab931-dd19-493b-9913-a769f31c826e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54806d0a-b0eb-41f5-a17b-c7ce6accf570	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:03:00	TRUE	FALSE			en-gb	21:03:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0a91ed5-40cd-4af9-b1dd-a15864e93237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
70d88d98-797f-42b1-9553-d9df871a4dc4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29d17d85-d4fa-4dbf-bfeb-0d4e0a1d2fb7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c33b42a0-28b5-43d8-b751-bb31e4a0ddb5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4412163-a468-4996-9ae2-3e0d91b98c46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6d24be91-1736-4e2b-9fed-6600a1586800	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:13:00	TRUE	FALSE			en-gb	21:13:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
26d347a5-02d1-4de1-b2a4-2b1d7536681a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:14:00	TRUE	FALSE			en-gb	21:14:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ad2dd213-9da4-4c06-a518-9c7256399353	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1222d56e-9136-4183-a6cd-f23e8ac334f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
2b0a244c-c821-49fa-9390-717908acb15d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d7837318-3557-43cf-a962-de8fc9d76b90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
3877b508-c6a9-47ac-abd1-f74fbb5dd797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	05/10/2023		No
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1dbd6e1b-5afb-4681-af1f-8118498bb59e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
39c8b772-3a56-49db-9f0a-70bb086bee12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:43:00	TRUE	FALSE			en-gb	21:43:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ac1cf4ab-25ff-4f7f-a388-3eeb20910fde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c1ff63e-4c5f-47ca-94db-d049572e89dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d26bb0e4-b64a-486a-a031-d8f06c4ba749	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	05/10/2023		Fix it
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c534ff83-decb-472b-9cc7-d101e6117f8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
14b5f2df-b1ca-4a3c-a4fc-dbc871ad30b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:57:00	TRUE	FALSE			en-gb	21:57:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dabfb491-44ae-4058-80b7-6cffafad47a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c999a238-0747-4978-a8ce-bccf7fb78937	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24ec72ac-9ed5-4b51-8e76-cba60d783eb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11f62446-666f-4741-ad40-f1358250fb9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4138e1b5-fdbb-4607-9bd6-8e3c4d5886e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:11:00	TRUE	FALSE			en-gb	22:11:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d5ab1b9d-4a56-478c-98bb-918dac4afbde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d110aaa1-b425-428c-9143-2e54007b0504	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7208ef11-012b-4649-8168-43f9bd183e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9354bca1-0fd0-45f4-9c38-c81927651399	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6287add4-e35a-42b9-a329-3aa5dc33a244	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:31:00	TRUE	FALSE			en-gb	22:31:00	05/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0646549c-648d-49ca-8eca-43cce5ecce9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:32:00	TRUE	FALSE			en-gb	22:32:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
83113b7a-ba76-45d7-8a7a-ee35154ef8d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 22:45:00	TRUE	FALSE			en-gb	22:45:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
92cde1d5-ccb8-44e1-b9ed-b776ab829632	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 23:16:00	TRUE	FALSE			en-gb	23:16:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
154fa2b9-c9ab-4ade-88a7-111534d59397	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/10/2023 23:28:00	TRUE	FALSE			en-gb	23:28:00	05/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3342b2bd-a7db-4c90-a453-fb52c5b4bb26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 00:44:00	TRUE	FALSE			en-gb	00:44:00	05/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
737acc18-d16b-4235-b88b-51e4bff2427f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 03:31:00	TRUE	FALSE			en-gb	03:31:00	05/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2c82d737-c0f4-4532-81c3-7640bedc69e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:20:00	TRUE	FALSE			en-gb	04:20:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9ff91ab-f4c7-43e6-8ac6-16bce26b8fbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:42:00	TRUE	FALSE			en-gb	04:42:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01a8d840-4fbd-4574-897d-553473922e39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:50:00	TRUE	FALSE			en-gb	04:50:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81ac8f28-242c-4062-b5e2-94bb178e9a06	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f4eb9a83-33eb-49a4-b5a6-b6abf7cccb3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:13:00	TRUE	FALSE			en-gb	05:13:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d61c311-8f2f-4019-a22f-21e1b48bbd7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
34abd5d6-0608-4937-9dd4-521cd7d643d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20dc679b-6190-435b-8724-9f9e963d60ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
661ef151-72a3-4128-a5b8-9861a23aa690	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd4f7a94-df2a-4335-bd4c-ee215d353d4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:45:00	TRUE	FALSE			en-gb	05:45:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0fb18ca9-2242-4962-954f-c5324cc2a9d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:54:00	TRUE	FALSE			en-gb	05:54:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c54c2a0d-f621-410d-8f0a-3a3e26f709d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6c235a0f-2561-4184-bd17-7b80e276d0f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:06:00	TRUE	FALSE			en-gb	06:06:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ab6d6ba-a3e0-4650-8911-944e1adb5ab5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:07:00	TRUE	FALSE			en-gb	06:07:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c8310a0a-72ec-49a4-8b08-d10ddb96d65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	05/11/2023		D	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
312dad29-96de-45cc-8a1a-e4f02eb22d1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ccd41f3-80d7-458e-90ca-f60d7d11b595	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b455dd63-dfcd-479d-a9ac-fba651a33ef3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ab9aba9-54cc-4fd1-be77-6a2a5b2bb04b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:44:00	TRUE	FALSE			en-gb	06:44:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dfe7ee60-bf0c-4c3f-84fe-9b3ad850f7fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	05/11/2023		Buenicimo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
32d2b503-906a-42a3-bef5-7d2589f055d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	05/11/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a1cc527a-589c-4b16-9d89-cf2f1c8f2918	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	05/11/2023		Goog
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
630eeecb-dba6-4199-9ed0-010d55b68c24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b83d9c95-875e-44e2-a121-4ae142e5c170	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
26fc09a5-90d7-4ab4-b506-01fa235af537	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d8a71aad-69cb-4934-9607-e1c0fc318599	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	05/11/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
130e9b14-df96-4514-88cc-65b522c19cca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8313c402-4688-4d60-95d8-e5926929ec33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e261532-c09a-47ec-bc02-57a7d60a2c06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	05/11/2023		Nice and clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88bc2985-fe1e-469f-aca1-0a92b66cb281	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d773ef8-4ac2-4a48-b07a-cb2e597db28a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a286523-db3c-4aba-862c-d0ba43d5157b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da923adb-286c-4680-a3e2-385c44b57033	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	05/11/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06603182-5cf0-42c4-b5d0-f0aad1ee6731	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d0b4f264-7450-47dd-aa0b-de3e1cbbcbce1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
afbae95a-2183-482e-8217-366d5c8f2950	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ccf57bba-fb9c-4b1a-9d3a-f6f2bd0e7aa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15509314-4856-4392-b9c2-41a5b66980b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b798fdc7-237d-4ba7-b563-0c0dd0a569ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
312c63df-4504-4eb9-9045-2162437087fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b5e46007-159c-4d5b-932f-3af113c9b60b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a417f2db-c2e0-476a-a133-18c8a38fd65c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1768316b-0a8c-4d7a-92f0-b701f8903616	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
147f4406-4941-45d5-b1b9-6a22605b0de3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc03c7c8-69c7-40c3-bafb-3c4487290cde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fad02220-9519-4f37-8be7-9c4e3cf57374	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b29ac06b-ea88-4698-ab3c-02d42fb30325	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/11/2023		Muy biem	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
505bab0d-2368-4142-abac-7d56ae66b0ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4203a04b-8e20-4c55-a24e-ed1bafd4c1af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	05/11/2023		Muy muedo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f1641a7b-9816-4c8c-849f-94495c741186	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes							
7348fdb-31d2-46ca-9ac3-cb0e1f873e1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	05/11/2023		Lindo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5cc4c063-22bd-4aac-a2f3-023bcf0f04c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52092d57-2eba-41d1-afbb-b940fca1dbf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/11/2023		Acojedor
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76c527e0-47b1-40db-8d0a-ce61c1ffb288	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	05/11/2023		Bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6976b606-ad77-4ea9-bbe2-9384d449a369	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	05/11/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39e03169-c9e8-4c08-9871-37d7ef5ddb97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/11/2023		Huele bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fdc4f563-75d2-4061-9c5d-a67db5724c6a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
2ce23e60-36cb-4e32-b832-cf8a6e687854	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/11/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
1a9beaf2-fcae-4a79-9baa-7a66b88a0721	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	05/11/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
346e03f2-588d-4759-bfef-fc24146f8fd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/11/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
004e924b-e631-4b77-a461-9c44b6579df2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	05/11/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
9ab1f3fd-64e8-45bb-a869-b7cc8369a838	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	05/11/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e65ed042-8c5b-4f16-9105-0093e1b2c764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d7503a5a-32b8-4fa9-963d-9db076cbb4c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/11/2023		Toilet had fecus on it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
0a749f45-4fff-482b-ad2c-e9161b276509	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
d21845da-fbe6-4a1b-9508-25f2218c90d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d9ff512d-06e0-47a7-bcd8-e0f5284ac5f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/11/2023		Muy limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96c05df8-4c7b-4ccc-af07-31792d7b0fd0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2fc12147-6e62-4ff9-a5cc-dff218f1bb6a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95d580a8-3c20-49b9-8e61-130332309217	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes												
f9cae9aa-ba7b-416c-b85e-da77bf4a3daa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	05/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
40c3d03c-455d-426c-94eb-fed627f917dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	05/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
7e28fdb4-4fcf-4394-a8cd-3f89c601bf52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	05/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
a7fd76dc-5d68-4da3-83c0-ccf7a30cef01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	05/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
0ae33df1-6602-4874-8f43-fef525055b19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	05/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
cd4a78fa-9fe4-4854-82f7-980fd09e4748	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes						Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b7b0eb9e-9c34-4a6f-9ebb-6e2588bcd3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
185619a9-d0d4-4a75-a6ad-5de6ce26bacc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes					Yes							
4db6ce9c-dcf3-4177-8918-9f27f6dbb43f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c6a88ba8-29d5-41d9-a41c-38d34870dff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	05/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a8632080-78b7-45ef-8681-1ef198af80c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d98c9f3-2606-405f-902e-13b78a0708c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
45597473-2e60-48d1-8183-4d5a16773619	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:24:00	TRUE	FALSE			en-gb	15:24:00	05/11/2023		Smell really bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
3ac7a83d-5f91-43f3-a16b-913dc4281961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/11/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e15e3347-85f7-41f3-97a8-f50c50049e78	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	05/11/2023		Very good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a4fadc2-f548-43d1-b99c-0cc4d4643732	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
0c7096e6-18f6-4b67-9679-be1195fae6a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes	Yes	Yes					
b0625440-4d58-4d1d-b250-299997eecbf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment											
270b99be-2db9-4702-b961-8e384d2410fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	05/11/2023		Amazing service from the cleaning team											
														How would you rate this restroom today?											
														<b>Average</b>	<b>Good</b>	<b>Poor</b>									
1fa8835c-10b7-43ed-b28a-8a33980a11d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/11/2023													
														How would you rate this restroom today?											
														<b>Average</b>	<b>Good</b>	<b>Poor</b>									
														Why was the restroom experience poor today? (Please select all that apply, then press next to continue)											
4048f6f9-1297-4aa0-95a6-3dcc9afecac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/11/2023													
														How would you rate this restroom today?											
														<b>Average</b>	<b>Good</b>	<b>Poor</b>									
ee1e8e96-0dbf-4b39-bfec-6c7b1d328a45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	05/11/2023													
														How would you rate this restroom today?											
														<b>Average</b>	<b>Good</b>	<b>Poor</b>									
7f8e91cc-8488-4f49-8bf8-e4ba77142b14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	05/11/2023													
														How would you rate this restroom today?											
														<b>Average</b>	<b>Good</b>	<b>Poor</b>									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
17cfab31-474a-4a19-bc5c-9e02b99a1cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
848232da-2c92-468f-9a5d-01a47d5df08b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6253be28-94f1-4bdc-9210-a98619969781	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ebfdfbad-3e68-497c-a68e-a9357f0f8f2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/11/2023 22:04:00	TRUE	FALSE			en-gb	22:04:00	05/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b277b72-b171-48d2-ab11-37fb27f293db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/15/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	05/15/2023		Johnathan test
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f707ff8c-eb90-46a5-a522-90c7d6c9eaa5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/15/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
419127a6-5d14-4b2d-9dd4-7713f7c188d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/15/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
fdf6ae21-3d27-49a1-bc9a-646899ee5f71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/16/2023 23:24:00	TRUE	FALSE			en-gb	23:24:00	05/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
20e89c2f-b9da-4f52-8e8f-c9ac31763c32	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
db563dfb-252b-4ab7-b59e-56d194408501	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ffb2b338-c6c7-43a2-93c9-88d6fa35af1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1853134-3d02-4d56-8721-a73918e1b66c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fe5e0461-ee64-4df0-b462-44d4c097ad81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6a9930f7-8c52-4861-b260-d18d006d9da7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
89b5d158-ee3d-4126-9f69-aa9cb600214e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a9dcc734-3fc1-4516-a394-6eb0ea329b8c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0c02c2a6-2f03-4911-a7b1-041e0d02550a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8214349a-2347-4a8e-9276-e4f3ed484c07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
37e672c7-6fec-4efb-85ed-a280146b8488	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
45d4275e-abff-4ec7-869e-9c8a7b37fe4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
850cda70-fcd4-4a8b-9c7c-81409c26bb4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca684dc4-d938-4921-9317-8db6c06b44b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6b5dabca-50f4-4584-a18f-4c1bc3f3ebac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b17b6ddd-7741-4035-a7ef-529827e431fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d58e5bf-7770-481c-9b4e-673b93e24052	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9590f53-6158-46d3-9421-c9c2650f43b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea025637-990d-4a05-9fb2-cfe0dcecc24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
773208f3-1dc4-47c6-8cd8-e0eb60223f91	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06635ff1-4027-47a6-bfe7-8af57189e354	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f95930b-80b3-43db-86a2-cf8aac572f80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:13:00	TRUE	FALSE			en-gb	14:13:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
31c2396d-763a-4a24-aa60-cd74fae498c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7aa27e44-6f55-44c6-bb94-89fe4000cf5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
57fd0e69-8fc7-4268-8e11-8e8fd0a99082	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
af5f7621-579f-4251-ae40-5705c82c1326	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c8deb6b6-7c52-48d7-a5aa-154e96afa6b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f901e755-0c9a-4a3c-8d97-65a07603b5e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d44aece2-75ce-4cce-a8c3-ae6f6cf679a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
62a0ca4f-f066-469e-a200-59fce23c72ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e504c1b-8258-4ff9-b8b9-9a4bb2316b61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb3fcaf5-d713-4ed5-a89a-006bc93e354b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37a35794-002f-4729-8885-7aa18fd4a732	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
bead45e8-9637-4c97-9a74-352edc0ea1ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
71c9e3b0-98a3-49fc-99b2-6e7945d151e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4e1038b4-e187-40be-a887-d320ec37b940	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0fd5fc18-dfaf-4b21-80a9-7d8260933fe8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1c77231a-9d06-4500-a804-cc2066b2109d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c8e23ae-daaef-47cf-a4ae-39986ec79b48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e3315595-7e6d-4f3b-96af-2f0a2effad17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41bacf13-220f-4f24-8c3e-49092b0aedab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1bd6dac2-4791-483c-9eb9-8e7650858435	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98f511ba-e406-41a0-82c4-269314621dc3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a669f6d-88a5-49d5-bf8c-83feac9e3a98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0218c32b-5957-468e-8d59-a5f780c73f79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a9082f1f-80b9-4b7e-9f65-5bd4031a6c3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
49fea50d-a532-46b9-bf61-f32cb851b81e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4247cc6-1756-4fee-af94-a1a0ceb9d154	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:00:00	TRUE	FALSE			en-gb	17:00:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7ec1201d-f9db-48c2-b549-4f87ec8f739d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
920c6178-f09d-4f70-9fb5-f46068585a66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e0ef905-7179-4e49-a302-03c3f9fe7afc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9903734f-ea92-4285-8ebb-7d8e744590a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44b66ba5-09b3-4a37-8c73-e76ed6099be6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a6edbd8-8657-44ab-b2f3-e2596a011c3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bbf213e4-6b25-4102-8ebe-5efc9c7ff868	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc01aa0a-8cbe-4ea8-807a-45825ec5fb7f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:02:00	TRUE	FALSE			en-gb	18:02:00	05/17/2023		Gg
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3525dfe4-be15-45bf-8626-bfbc08943694	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e22bee43-ae50-4bd5-bef7-470b188e3d56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9b98bf60-af54-4f1b-80f2-2ef759573ded	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ce7362f-3907-4cd6-a8cf-de329a37ed76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53f07171-5cf9-4566-8667-6eb80644c691	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3ae0366f-6d45-40ec-8402-a78f3b1fa035	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:31:00	TRUE	FALSE			en-gb	18:31:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
08b5e8ac-2a01-45f9-98ca-0c7da3d0422c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ed313425-7827-478a-a846-b032395f4654	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
670c8e7f-512c-4396-98c4-9e28d810ab76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0926cf9-5c49-4154-8972-d20f52044412	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ee38c696-7a7e-4514-9d10-7a25c10ad218	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da422c16-eb4f-4cf1-96c7-0b7e51a9b4e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c1a9813-2295-4873-8319-e00058c2551e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d6600296-6a4a-4704-ab1a-686a1c2431df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f72263ef-4e53-4870-90d3-7e9c2facb28f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
738bb173-21ab-4d3b-b7a6-38ad6a335cb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c55e4889-5497-4932-badb-5471d9e0d4f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/17/2023		Excelente banos super limpios
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cb265669-9f03-43c1-8fa8-af83847f7164	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0686b8e0-a235-407e-88df-e240fcc83e2b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ee970fdf-f644-4b1a-8077-95234c9cd8b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
194782b9-b547-4b72-b5d3-19c370501fa4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:38:00	TRUE	FALSE			en-gb	19:38:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
807e81f3-45b4-41cb-b97a-5c0899451ccb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6d7a79eb-504f-4071-8e05-86cf777fe4bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8f8ab70c-6fa7-444a-8fed-30a3aae6d021	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4aefe787-3ed6-4f00-be3e-73cc64e7d093	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18e274ca-22b1-468d-851e-0c1a29d16244	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5cf5948-4d71-4f05-9c75-a551dac897d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ede6c8b5-2964-43f6-8041-acbee171ec1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b91063a-ace0-44c4-908b-c5d03812ae54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e38d945-c207-4248-a637-9b03740f760c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a54c8bf1-8112-447a-8b98-914a9727d9ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
346c765b-31f5-4cb9-a0f1-4511a88f6abd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e7491c73-acbb-4157-8104-230e27dc6f74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2dbbfaec-efeb-4db6-9107-4fad38df08de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
73020bf6-23e6-4792-84e5-e8e3d8f3a64c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50614ecb-ea41-4dc1-9e73-ec72b9a157ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8cbaf8d-8e78-4adb-aea5-3d155df9b630	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:15:00	TRUE	FALSE			en-gb	21:15:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6f131497-f7af-4892-b173-b069d6c255a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
52b55964-4adc-40f9-9792-7a9b64f3d6b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:51:00	TRUE	FALSE			en-gb	21:51:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e2b55ae1-b284-4ef2-b6f3-d161c22be798	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7413dd27-4aba-4b88-81a6-ea4bff55dd72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cd802840-b860-407e-88de-3ff6996d381a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:06:00	TRUE	FALSE			en-gb	22:06:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0d6de866-dd6c-465b-887d-c4627df55033	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	05/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
fecc8ce2-e516-4591-886f-0d25a66e7762	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:19:00	TRUE	FALSE		en-gb	22:19:00	05/17/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
0d096562-0758-497e-9c8a-c002fdbe79d3	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:24:00	TRUE	FALSE		en-gb	22:24:00	05/17/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
c7d64611-ecb0-4db9-980e-abead7f2913a	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 22:37:00	TRUE	FALSE		en-gb	22:37:00	05/17/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
		Yes																								
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																								
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																	
	Yes		Yes				Yes																			
a0550bd8-d021-47d8-91b0-73677e6ce8a4	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 23:02:00	TRUE	FALSE		en-gb	23:02:00	05/17/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
				Yes																						
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																								
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																	
							Yes																			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
499198e1-2c05-449f-b215-487a015ec9bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/17/2023 23:34:00	TRUE	FALSE			en-gb	23:34:00	05/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc8b5dde-ab44-49d6-8049-bb26a53786b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 00:41:00	TRUE	FALSE			en-gb	00:41:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f7cce4b8-54ad-44dc-b53b-9ded3642b6aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 01:32:00	TRUE	FALSE			en-gb	01:32:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9901106a-7468-426a-97a9-d0615a7a2203	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 03:01:00	TRUE	FALSE			en-gb	03:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad72f5e7-868d-4f9f-a0ed-21584d86f899	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 05:10:00	TRUE	FALSE			en-gb	05:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54c7cb4c-f7bc-41a5-b2ff-2a0ce08443ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 05:32:00	TRUE	FALSE			en-gb	05:32:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d4112578-ab5c-45eb-8ec0-c3d53be8377c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 05:39:00	TRUE	FALSE			en-gb	05:39:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76b6524d-5681-4551-87f9-1a57dc9c1ee8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:10:00	TRUE	FALSE			en-gb	06:10:00	05/18/2023		Muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44378640-f777-479a-9c14-b4d6e5fce287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	05/18/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0d86291-7b67-4467-9619-68239882569c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
00fef06c-0b4b-450d-8988-db0406780316	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3e60dc6-49b6-4733-bc63-cc3dc7bda1b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1f8a8150-7d74-4373-a789-63f95c3f198c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	05/18/2023		Thank
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
94b7af2c-80df-4c95-8240-d45fe0ab366f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a20b96d7-711a-4e15-bc4c-d2e56d37a7cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a61d714c-7a05-4a70-a589-32d53be931c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
567e6197-4f61-43aa-bae8-5a8ecd6d9415	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24237359-cd59-40e9-8fb9-c89b2fe43b72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	05/18/2023		More toilets
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
24237359-cd59-40e9-8fb9-c89b2fe43b72	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
17ef3cc5-83e5-4a57-b89c-821f709231d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b15ceb63-75f1-48f3-ae0c-9035825423dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f349172c-d581-4082-a45f-f826fdf2b905	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	05/18/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eebf67fe-e705-4868-9930-3c0ff245aa43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	05/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
041d8aa2-51b1-469d-bdbc-748cea79458f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
83a5c122-3249-42b0-b3db-050ca070f016	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d39b3572-36bb-49db-ba59-f87467be1471	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
932e7fc6-847d-4134-a3f0-1358b7066a8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	05/18/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e5f0ddb8-8af8-4b21-9eb6-ac5739def04b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1fb8d2da-2304-46e8-9ecf-1ba5c39348ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
faa87d1a-a65e-4d0f-a451-830d7d40520c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	05/18/2023		Super bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bbb2bcfb-fd6e-414b-9ba0-ecd42e5b95d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c34b2a5-a885-444d-839f-ae1758b23cbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a02b53db-d6ca-4376-bbb6-4be34b182629	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	05/18/2023		Muy good el bano
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec9b529d-6beb-4d28-a95c-615d6b8aacd7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb2d179b-8fd8-4078-9db5-5763fa307593	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1637f25a-85e6-43b3-b9ce-357ff5183afe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	05/18/2023		Super todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b49e8fe4-6332-4b34-a749-ba935d4fb84c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/18/2023		Olor bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30cefbf-c1ec-4fc1-9361-22fa60d8b758	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca52a5c9-b32e-442b-8936-07945552f9dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9df58722-5aae-4df3-91d6-1fcd2fc0aa02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
264a7d69-b655-45e2-a5d1-7aa6d0716ec4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	05/18/2023		Todo recojido
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8179a4cb-1988-4477-a3b9-1aecaac34857	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	05/18/2023		Limpio todo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cb00c618-6dee-4c25-bad9-a9cc985758a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1c9ea67a-e709-4e73-86f0-b938188ea300	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
44c5228e-0ccf-4968-9970-81e24895086e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4d0a06e4-f53a-4762-9998-3793ec66017e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	05/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38c24e3c-a597-4bdb-a8c9-ee7807d60d9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
258cba1f-19fc-407c-8678-f190a740ad61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
859b13e6-2f35-4632-b1ae-59e5f5a4710b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
299fd87f-ef61-4d0a-83a7-fbf62e8c61cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
671cdbc0-5fbc-41c1-a538-3efbe031c252	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb6753ba-7760-4acb-a4ee-453d4242f0c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fc141af3-9061-4385-9b35-67a92b456923	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a7575ef-2ace-4151-b178-4e5b06fba81f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1808ebf1-07fd-4589-bd4d-d9b34125bbdd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6286be29-db39-4dd0-9ac3-6d42fb8948f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
8f4f1615-1ff2-4f4c-828c-fd7964dd9ab6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f0a9b4e-edcc-4c94-94c1-1347d44b0b12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1db473d1-939e-488b-8a18-9f73e940fa69	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
36d5d8f4-7269-467a-9043-d944a6074b71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91f29943-3998-45dc-a564-42bf190bb5d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a54a5e10-545c-48b1-b5ee-8bf79f3aa91d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7c64584e-4fb1-4540-aded-20ef8ddcff40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	05/18/2023		Horrible
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cf20c07-b998-4af9-8f08-a92ca7d67fbf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:17:00	TRUE	FALSE			en-gb	10:17:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
db613301-a298-496b-a7b8-5c866c268653	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:18:00	TRUE	FALSE		en-gb	10:18:00	05/18/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
															Yes												
ebd4d0d0-ae83-4617-862b-c327539687ca	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:27:00	TRUE	FALSE		en-gb	10:27:00	05/18/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
			Yes																								
6c3605e1-17c8-4b71-b5e6-b88c4ce3a8b0	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:29:00	TRUE	FALSE		en-gb	10:29:00	05/18/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
			Yes																								
32a1180c-6fb5-4f2c-8016-36899e53d250	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:34:00	TRUE	FALSE		en-gb	10:34:00	05/18/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
			Yes																								
8fefe4b7-8d08-49f8-ba65-2e96ee408a52	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:40:00	TRUE	FALSE		en-gb	10:40:00	05/18/2023															
		How would you rate this restroom today?																									
		Average	Good												Poor												
			Yes																								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f307fa54-7c8c-431b-81e9-2aec369a493c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
30b4ae27-bf71-4b5c-a380-01e811d29c33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a86799bd-a4e9-4346-9328-4f5328de7038	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
94809180-b932-4b55-a7f8-5256cd4cc50e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8a93d2d8-631e-4ecc-9cb5-ada2043822f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8b690aa6-74bd-4f7f-8c60-2d4c64795f00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2dde0b6a-514c-400c-a799-4c7a8cb168e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68e5d365-d0a0-4690-bfae-b4c2422f0bae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c6cd28d3-dee0-4dcb-bdbd-b393df538f0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76de2959-06cf-43b6-9741-958aa0be8750	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/18/2023		Todo limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b74c25c6-1e14-4fd0-9bea-6df0f7055709	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aeb70c23-07f4-4ed6-b91a-51d900e9e2f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
43e49c3e-926d-4bdb-8ac3-be286b5c8b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c0fbacc9-a764-4f4c-a6ac-f90aca8603cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6f35d977-0bb1-4bbc-be33-bbb89f546a78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8a2aa69d-6c71-4156-acf7-2692b22325f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
88ef8bcf-c844-4a5e-9e4c-e2a3afd03924	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c5c65430-28fb-4412-af15-8515b53c4ae4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
47334faa-ef20-40a0-acb9-f029b864a00c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9139a1fa-04d0-497a-ba13-257515720f28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6424d9a2-156e-4635-8d0b-f0cc5293ef8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a62f7fec-2511-4e68-82aa-afe2a112a78d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1a981d9-6ad7-4fb1-92e4-fda5bf990ce9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3786e6e-b6d8-4afd-b85e-c15d3f588620	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3ccc6408-8e6c-45de-afdb-1014a3f74da0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7ca95e70-af87-401d-9007-9efa99726b88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53d87102-89a8-4824-8d99-a67e14365ae2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
14093281-e86a-4b01-82d5-204b566b561d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
11a5c89e-a56b-4d42-af47-83af2640c159	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54e773fc-e9c9-4b0f-a2ff-875b8199b8ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ce27cb16-83f5-4f45-a51d-41bff2e9bdca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c541e29-c899-4f3e-8cd3-eb8fd4dc2a96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9eb2b858-c53b-4f66-9f21-4e33fd20cf95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3cb1239-84cb-40ef-8a14-ee62f50668b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76605658-5fd6-4c20-8c59-cb65cfa22390	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/18/2023		Stinks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
36dae9d8-e608-4511-847c-5273c2925242	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
97f7fc63-56d1-44df-85ed-895de486f40b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c1876ee5-23ea-4e36-8116-33f00408cfa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f3dc2c6f-426d-41dc-87d7-43fd877a6151	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8f78c87-4116-4936-a93a-45a14f491ac5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb5ac65b-9e61-46ad-916a-7d3ec87ca9c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1c678a02-ff9c-455d-851c-e9ea70c6bc1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
64d990ee-2f69-408c-ae6f-ed80f59735ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cce3cb03-a2f0-497a-9947-bd3998277f80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a1484ef5-1a67-48d3-b5cb-1eff78730366	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ac40db1-9be9-4c2e-9169-98503b401084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c841d84-aa11-40dd-bd1c-13065146c47e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
04152d81-95cb-48fd-88d8-02b9f038cacd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
80a7db44-c72b-4d9a-ac18-e17d2567bfd5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5438dbc6-b66d-4e42-a857-68157a702945	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a8b9239-a36b-4578-bca8-2e255e4c3549	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70263ffa-e1c2-45c4-99fe-0d8e2885398a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
37e99620-49b6-4e98-a461-f963d8ef0df0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ff5d428e-dd22-4b2d-8afb-2623f9ebf941	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/18/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e5fa168-0e1e-4a43-a8c6-5fd85b2d2ffd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	05/18/2023		Super el bano
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1529bc88-400e-41d5-b394-f8378d974ee0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	05/18/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
67ae30f2-4764-44b5-a2da-b1e6c290ba50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e47e6e18-a33b-42cb-a23c-12946418363e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a9427bdb-7930-4064-9558-d0e1d8ce3f36	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
440557e9-b370-4718-b7a0-003679735a20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76ab85b3-c098-40ac-b449-a34a6c71c85a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
154f2b9c-2569-4805-9b9f-bd5ba9626c5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3ba5aee-2102-4a4e-9c2d-092dc2d2e27b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2e92cc06-d598-45c3-992b-7e2f4f7222b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b885ff5-df39-4fc0-be44-e3516126f07f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3b570019-73ba-4ec5-90ad-7e809282655c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
184f87a4-d6ce-4c08-9aed-948ecc012811	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
584aa60d-1c8b-4fa1-9cfc-ccac58fda581	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1956b124-7ed4-4aa0-bf14-75c7ecd01a5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7af35cc9-9528-40c8-9a7d-6dceff5fc531	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
554ebf41-f783-4f92-8f6d-ea96f1340f6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ec2eeffe-c06c-49b3-9a8c-bdc4ce2becf7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
972f5add-ca46-40be-bc2e-f5d0b096fbc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e2d474e-bbcd-4c9c-b5e6-623f55a6686e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f24d5686-b82d-4726-ac01-be3043dd1447	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
371f71ae-aab7-4a38-b01d-e80df84e4bef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	05/18/2023		Good condition this r r
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81ecf3c1-d03f-48bb-af6e-01213f4ca048	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	05/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8857c426-7460-4e6a-b19a-bd380f7ca181	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a9782e55-b062-4960-8121-a117eb7998af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc375b99-a375-412a-9c9f-8af207b1c6a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
359dd46a-6574-43ef-99ad-787d3df202c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes		Yes				Yes	Yes	Yes					
d9da50ab-27ac-4832-9a09-5443de96f19a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2f753893-1dce-40fe-8fe9-9af1d0d5c987	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95ad1d08-e326-46f6-8d77-b1db665fbdee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1b26c078-8166-4861-8955-bd49c0df4ffa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c45ab71-48ed-4349-97ce-1bc2f2e333c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
224059fb-60eb-4798-897a-99823c81b959	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70a7f662-49f3-4571-8f7a-f5fa33fa95ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b6350e74-4d1b-4fd0-ad13-353155bf643a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce60b013-1647-4b6e-b52c-0fed4e0cf802	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
079d9935-5072-42a6-bf48-ab38a1a17ad1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8576388c-0f10-4e13-b6d4-849d6737012c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4c9b219-51c3-40a7-bef3-ec125d400476	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8eaa1338-c3e4-4ba9-8a73-248be607b66f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
806b32cc-20d2-4d14-9190-85348dd70409	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/18/2023		Great	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c79101df-5aea-4ced-86de-b00c993b4342	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92ee101b-4135-462c-9a0e-a3d713b0c134	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	05/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
21226bac-b949-4615-a259-b173417a0caa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dca8ceb4-05b7-4e47-8c53-b8e37c8eb5b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cae58947-6235-475d-9e16-10a2ed1c14d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8860699f-fbec-458f-9805-dc57aec0131f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c57e3a5-829b-4f5a-aeed-7e2170b2dd1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75035b02-1144-4c69-9184-892ccca2e9c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07ecff0d-e345-417b-948b-66832e78850e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
187628f7-6d95-4292-86d3-ee492b691f52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f2ef2cc5-e348-4cf9-893b-c94be294f2b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b260a79-0650-4053-8dc1-bd1a33855aa2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75ea97f3-0edf-4483-8e13-265d375dcef2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e63399f-8ca6-40ef-8dd3-901340cd9cbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
261fdf97-9453-4dab-812e-8c2e83b35b51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7851ddfc-84aa-4762-8eb0-c81a7579dbf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c641dd03-26c1-46ea-9e6c-d23bd1d7e835	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	05/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a9ad1d76-db20-4141-acb5-5327cf2359f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fbf3e453-e849-4773-9772-a14c1eebd2e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
abd6705d-da25-4f7f-bbed-88f38c06bad9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41563c76-41d6-49f7-b8cf-211a2d4b8270	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e260b945-b4f3-4b62-8ca2-8bee6bb3f113	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bbcfa9b-d2ef-4a26-9769-186dee1169ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a7a2c95-ce0c-489a-b7e3-27a8b801b0e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a476169b-2b45-4dad-940c-2346d3bde7e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
46ad1720-7f62-40d4-99dd-97c0a86bfd82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
374701d6-dc52-47ca-8f97-370f1731a251	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f975f9af-0993-4a5b-8beb-41c24867a087	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	05/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
64ee2c51-16fb-41a0-af1b-98ecda8149d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
02e3d9d8-9cb4-487f-bd67-945980d31b45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:17:00	TRUE	FALSE			en-gb	22:17:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
005792d6-1f98-41ab-a579-b9ca331c35a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:36:00	TRUE	FALSE			en-gb	22:36:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
38efc94c-c8d1-454d-942d-4079a4a40904	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	05/18/2023		Brasil	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e625e862-158b-4e9b-a94f-f2a38de98886	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/18/2023 23:56:00	TRUE	FALSE			en-gb	23:56:00	05/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d2edb19c-8679-4f97-9d3b-bc8e1a6daacf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 03:39:00	TRUE	FALSE			en-gb	03:39:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfd59b26-0d13-4266-ab67-cccc9b3cce33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:16:00	TRUE	FALSE			en-gb	04:16:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0bf7094f-4827-4323-befc-8c7bb10f1363	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:22:00	TRUE	FALSE			en-gb	04:22:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9c0256f9-2083-496b-9bbb-d9397ff254cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:24:00	TRUE	FALSE			en-gb	04:24:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8fc2ab6e-9cb6-44de-8a10-a415706f993c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:34:00	TRUE	FALSE			en-gb	04:34:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4c452cc8-ea9a-4699-8d77-ed3790beb6b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f8f824eb-75c8-49a3-9a10-bc4ca50291d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 04:58:00	TRUE	FALSE			en-gb	04:58:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17a1f77b-d0f1-4eef-8b77-57b893d613bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 05:06:00	TRUE	FALSE			en-gb	05:06:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bbe812dc-7c52-4a43-86a6-4a4fe7163ecd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
274e89b5-e9f7-4322-9028-1666415a44f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 05:56:00	TRUE	FALSE			en-gb	05:56:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c023c7d-4464-42a1-b62b-6a6ee7431b90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	05/19/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f5531820-679c-4f91-a03b-7408fd5b68f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:10:00	TRUE	FALSE			en-gb	06:10:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6be33d21-219c-4b2c-8f17-9567c21fd1a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:16:00	TRUE	FALSE			en-gb	06:16:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4eb5633d-aba8-43bd-84e1-ca723daf3fe7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	05/19/2023		Muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
441f0367-18e5-42b7-a2f4-fba5ad44649d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
354a3b79-1453-4b86-b3ea-e5d662866f74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes						
1d11987a-d032-4276-b548-5921f9089510	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6d7eca39-3ba5-4105-8e5a-d4f6433237ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a591dd7a-62e9-44cd-8f51-0fde7de4f645	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:18:00	TRUE	FALSE			en-gb	07:18:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
412c39c1-4d0f-4fa2-86d1-755eee52ced9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ff6e8dd6-24ec-48d2-8731-0d4d7c813bac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/19/2023		Super limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
01541486-c75a-4ded-9524-4a955a177209	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
667f61a3-e0cb-4c67-af9d-f237b62b244c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
206c4b90-1aeb-4b3d-95ff-16694bb043eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3423f11b-a05a-4b79-b0b6-af456fc0dcb0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	05/19/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5e1326d8-fcaa-476e-babd-772528f68606	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6278b754-82ae-4801-bb33-de21e5e5dd4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef2adb14-a273-4e74-a856-d5604063c3a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
771b9697-dc98-4b55-a6a5-a10c34f10b1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a8999a28-2490-42a8-b574-3227544c196d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	05/19/2023		Stink	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3b47707a-3378-472a-9f16-5e85b4cb4f45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	05/19/2023		Excelent	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e3065172-845a-4286-a670-1ced2053ec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7e4ca117-7b88-470f-88f2-2ab3cd5b8b80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
201a7fbc-7499-4c87-87af-e6989ee825c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44128d84-ddbf-427f-bac9-d7788cf0fad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9a339d08-ffa-4469-8aef-af024bbfe76d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b792499c-b0ea-4acb-8574-52787bda3ca9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
741302b0-bd6d-40d5-aa7b-db0dc66d261f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ba8087cf-f886-4194-8ab5-70dea74faaf7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
31234d4a-0936-48c7-881b-687ba970c064	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	05/19/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b442dabd-0993-455a-bea7-3223116a4a50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae0329d5-dc33-49e8-863b-518ba865eeb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ebdec011-7e43-4ed7-b443-a192351df5a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
343b9a21-9a84-47e5-9d40-0c45042480db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d314f63a-9247-47bb-89c2-fa12a9491f12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
12b14664-5324-4513-9b31-a02fe8d461c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a98f64ef-8cb7-4cf2-aa79-ac06c9bdf29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
56091e91-9282-4e35-b6ea-eb3304a27476	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1dbd0889-1d74-4016-981e-024b12a4e7ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d795046-9eee-4ba3-b7fb-68f5dc9f3585	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b5e7797-9cbc-4622-b106-4de8e927ab2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bc4c33ce-e54a-4c5d-9aab-4ba5541dd1dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cd121d05-b226-418d-bfcc-622ad40b6675	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dfe48e8a-fb76-4a39-ab90-443a8ca153de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e52df2b-24f6-4b4e-9d49-0da342b7e56f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b849cb86-b0c8-4fe4-8e55-154e2e6cf01d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f593c1d2-9578-46dc-983f-0654cec4f171	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9218a51c-2b95-495b-8f08-1d7ec47c4297	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
553a35c9-3626-41a0-b1c7-3935a18fe467	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b98ccf7a-5492-4b04-a44d-1b5aaac03edc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5101f19f-6d05-4ee8-aa80-0616dc0cecb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0d12b22-03ca-42b7-b6fb-bdb3f38ebb46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17af5078-d9ea-434b-b4ee-1e5763d3f2e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2949e129-0564-4749-92cd-b07c236104c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eb9f2f4e-8ecd-4254-aa67-d35470a07180	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32861e91-4d71-4347-91bf-921b45f52769	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc5a2cbe-4dc5-4202-b038-890fa0f2629	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1e323253-2f5e-45cf-acd2-c6e55329ced4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d69849c-4406-4d4e-a287-85fff9c9ff5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d580026-68c3-4dd9-8d19-ccf4f9ca80b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f67c130b-6289-431f-bc40-a5c0e4484421	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
90eefbb1-9f31-4ac8-9b9a-91c690a49f8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76b193f6-e765-49f2-88cb-31a7c5b9093f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	05/19/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ae249a8-22b8-43fa-9b26-249ebf406780	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes	Yes						
7300f7c2-a8d0-45e5-a2c5-b85af2f71d82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cc88b8cd-4d38-4086-bba9-42be25b244cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8b8c36ee-83aa-4511-9d10-39c0964b467a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes								Yes					
c1bdb396-ca8e-44b6-b83b-dfa0d1c3ce38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7885619-6980-493f-9f35-cc2a07cc199c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
132a8406-99b2-4235-a5b9-03e6a8eb733a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6244f4ca-106e-44a7-af5a-2a401bf5f0c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
821c8312-89e1-446e-ad8f-be29989e7cc0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1af1cd2f-8861-44ed-b1da-593ba5f11276	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d417effa-90c3-4ea0-9c95-963b5779216b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a1cc419f-e6bb-40f4-822d-566f3a92036b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eb12bcc0-5928-47a2-9e3f-fb0945913822	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/19/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
271bfe6a-ca7b-40c3-861f-86a6a482da96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be41b736-72fd-4087-acb8-3e35ed88f478	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11e2e4ca-7a54-477c-90f0-95025bb5a35f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Ofac6472-c2c4-4555-8e9b-19282ac13919	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5aa96e25-f250-4135-ba9f-9071ced54ab9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/19/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5aa96e25-f250-4135-ba9f-9071ced54ab9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
f5691c68-4797-4c8e-9b94-021ed3c5d8d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	05/19/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
8d7607a5-8a11-4e87-912d-1af0b366fd0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e95b5768-1e8c-4239-8e4b-c19f1aeb8cd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d850028c-06b7-4242-98ec-7cadfbd14720	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
426108ee-4020-42dd-bfc6-1724da343dd4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/19/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
250985e8-885c-4d59-b43b-0de04691c184	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
49e9bc38-7d8e-42da-9a4d-8b0d96195bb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
33254594-a72f-4642-80ab-dba1ec847b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
93224224-1471-4d4c-8f2e-0d7ada0c9840	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	05/19/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f069ba58-7a08-475a-9f38-bc3ae0870216	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a4825cb2-ca8e-456e-8a1a-bce87d518899	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:12:00	TRUE	FALSE			en-gb	12:12:00	05/19/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
ae2a6018-2a0b-4b0e-bbf2-1e999aa5812f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
03c72e94-6e96-4fbc-a482-de7f37f12f4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/19/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af1315c8-d1fe-4565-9c49-0e80dd5b78cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0072d12a-83e1-469f-b563-c58d267f4c10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7eee5535-de66-4b85-b6fe-b61e3078e944	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82bcce41-8c13-461c-8890-e04a4452bec3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
398435e4-435b-4b51-aa82-aa660a900f81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e71147fb-8ed4-4d0a-b038-bf0588f64227	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d6ea182d-2ad3-4a75-8e9f-38a35b5d9e62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
badd87ff-7676-414b-b61a-0aacd87d0fc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25af4abf-1199-4359-96dc-3bb6db50760b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3e2e497-7414-4a63-baa4-93743d8c14e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
854c222e-944c-44d5-9595-a6fc61859680	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae8be0cd-ac2a-435d-9f05-e058eea6898c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bb81b987-d85d-4089-b627-e3272f3ed37e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b4867d62-5124-4631-98e9-c91310a7aed1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e599dbb5-f62d-4f3d-89aa-843e01074037	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b376c703-76f9-444d-a614-f3924c683239	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78a5ccd8-33f4-46a2-a2f6-38df9782d54f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:29:00	TRUE	FALSE			en-gb	13:29:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8bb846bd-6b36-4604-95b6-e9d9eb223c25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ce5af8cd-5926-4edb-945a-de512a3a72ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
265d371d-78ab-4ba8-9b13-9ae9a267d70d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b441cfd3-9775-4d0f-8cc8-e6a20d53f2a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
83c219d2-cf96-4432-b99f-ff5cdc9c66f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:39:00	TRUE	FALSE			en-gb	13:39:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da29b2ba-cd2a-44ca-a9ac-9a8ca8f2447d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0e843920-9665-44a8-befa-a073902a68db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f8286295-14fb-4c8d-be78-d3a7d2669c5c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
abe92f4d-45d3-4617-9aa9-c397ca07624c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/19/2023		And smell	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
dd603aa9-7e5c-4ac3-a717-eb25d0c3c2ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e15b1b5d-0ebe-4deb-a82f-13e6daf930f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d874f9d6-2631-4224-b9d0-41dacf1662ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	05/19/2023		Muy super bueno	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
4c9195b7-c1a1-419d-919b-1dc0c22190e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
b7dfacbd-1127-4670-8a92-18020eb28e4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
1421b9ec-b6a1-4738-9378-b0a1170afea9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
9f10adf8-f56b-4b30-8aa2-ba276c535c54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c01cfe8d-057c-41ff-97c6-d46f4b489eca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
fdcbd4b7-fffc-4f82-9ebe-1f325d775034	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fcdcb4b7-fffc-4f82-9ebe-1f325d775034	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
ce799755-741e-4ef9-92dc-4e549903dc5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
def481d8-8d7f-4005-8521-0370ec64906f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb823736-ec56-4475-b7ea-37c54ddf7e32	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d0bd5cf-3c70-416c-8229-ad7337bf94cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aa6b57e3-8bf2-4401-93fd-920ce80ed388	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f3443a1f-7722-40b0-b6db-903a720ba748	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bbe64818-a3c9-449a-9482-fa601892edcf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
49c7debc-de1c-46c3-8985-035c80de95bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d40b745b-032b-4667-b993-91de6ba8ee4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3549ecf-656c-418c-9bbe-4a0a4a5935f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
943f87bc-38fa-42b4-abd2-75efee074a53	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
94227dcd-8d9a-4dc4-9efc-f9247a802503	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5da92456-07a3-474e-bab7-3929e9c855a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07a40422-cec6-4fc5-ac5e-7c62158259ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0837e645-5ec9-425e-90b5-caee7d5b5ad2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0dfb1c0a-41c8-4216-bd2a-0484d8493f9d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	05/19/2023		Yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
36ba8d0c-e98c-4ba5-b6ec-bceabacc34f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	05/19/2023		yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2e00c08c-142c-4d01-80bb-fb8cfc2755e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/19/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb4f7509-d835-4874-a033-5c8c8d000f28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/19/2023		Yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc79041e-cbdb-47dd-88a6-b849382d85ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 19:56:00	TRUE	FALSE			en-gb	19:56:00	05/19/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ff23f47d-64b8-424d-b833-d29d552c38df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bd4fb10-26ef-4b32-ab64-5e93da4e533c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	05/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0fa98709-681e-4632-bc61-1b4bd7d96c79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/19/2023		No soap	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2779374a-fa4e-444b-8238-0cc824dcffe0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6aa57b6b-6878-4d5e-b5fe-dcf73ce6a667	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/19/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	05/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
98e97279-ade9-4ffa-aede-26611efdbf4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 04:02:00	TRUE	FALSE			en-gb	04:02:00	05/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
228483de-346d-44b4-af1e-5ffc0668cab3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 04:08:00	TRUE	FALSE			en-gb	04:08:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81ebad3b-6130-4377-9720-2eff81192a0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5273fa5b-d3ca-411d-93e5-d5e711f378a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes							
b5a702f9-3e6b-4d47-87ee-e78241439e27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
67595c62-219e-4b76-8789-6f965073d6a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
602ae92d-3051-4384-a2d2-6037512795a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c510112a-573d-44df-b6c0-7a9bc2fce495	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c7d85d61-cc70-4baa-95d3-bacdb14f9bae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc201f90-1c17-45b9-9d33-e5576493cc73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae326de2-bd80-4a51-a431-e870fe1f444f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
84092f22-6079-4953-9c6f-af2bb453f2a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
84092f22-6079-4953-9c6f-af2bb453f2a1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
357ce37f-8e1a-4f75-8a43-71cae02f93bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8e9d15ca-9067-4d82-bc56-4bf482dc77dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0d277cef-d71e-40cd-a151-f404082bc68c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c341d3f1-31bd-4f6b-9a66-ba46efbc13e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a3ee21e-ec35-48d4-9655-e7e235b0b938	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cbf6b781-7c75-482e-9c4c-e8b562f32ef4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fe5de3a2-728f-464d-944d-d1d0111ed7f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d091eacd-84d8-4b23-a8b8-5b38c4481fd7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fad4d471-ae7c-4ab2-bc6b-11024afe89d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	05/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e89dff4-6f72-4480-8dcf-78d1e7da0ab2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	05/20/2023		Excelen clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
63d8c11d-c157-4cf2-abdf-71e2d11fdeb9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	05/20/2023		Sucio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1e80b87d-f594-48b4-a5d3-4d78eda1576f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
66f1d1e9-af68-45a2-adb5-1532aaedc1b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
089eb163-6ab9-4831-81de-b4dae5041830	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/20/2023		All,good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
11d88dc5-31ac-450c-9ca0-de4e954db83d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6f1f9eab-beac-4c1b-9a72-6d1601ca4fd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8579ee27-cc30-4629-a297-7e5415065eee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c4c3314d-5fe4-4ae1-b0cb-b95eb416d248	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc8ef629-4658-4a33-a68b-a0253024dfaf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c1157d4b-04df-40ff-bc48-e5e22297e7c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07f101f3-a782-40ec-af0a-c0fa9400db35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
71ce2b70-c000-4eb8-8540-80272dccaec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	05/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
41802f43-2580-4b2b-a7e1-dff02fa3dc31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e5c95d8d-c5f7-4498-a8fc-398da7039544	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 19:24:00	TRUE	FALSE			en-gb	19:24:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c508d6e-1ee1-42c0-98d6-f1c47c40f155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a953daf-bb04-4ca5-bd17-63c6347f9273	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8de90010-7cf8-409d-85e5-b870d8d52e81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30d4428e-beee-42e5-b661-1104efd8000d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	05/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
0716aed2-6945-48e0-96e5-726374c17c82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/20/2023 23:48:00	TRUE	FALSE			en-gb	23:48:00	05/20/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
6dc11390-388d-4647-8b3a-fe80fd82ab10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 00:12:00	TRUE	FALSE			en-gb	00:12:00	05/21/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
1d861baa-ad2a-4bf7-b859-9b512b2a8a22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 02:02:00	TRUE	FALSE			en-gb	02:02:00	05/21/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
855b1728-2c33-4c8f-8cb2-8b987e5e80e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 02:52:00	TRUE	FALSE			en-gb	02:52:00	05/21/2023		No														
														How would you rate this restroom today?														
														<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes																											
b84bf4d3-3af3-4669-a28e-0a0fc0aadb44	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 03:17:00	TRUE	FALSE			en-gb	03:17:00	05/21/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
6c1e1b6e-1de9-4698-8003-fc977283350e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 04:25:00	TRUE	FALSE			en-gb	04:25:00	05/21/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6c1e1b6e-1de9-4698-8003-fc977283350e		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cef35e9e-84b7-41b2-95ce-915a7e691058	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 04:50:00	TRUE	FALSE			en-gb	04:50:00	05/21/2023		It's clean and smell good
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
48bd5aea-0d4e-416b-8f50-bad7f92f64b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 05:31:00	TRUE	FALSE			en-gb	05:31:00	05/21/2023		No
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
78525696-1aed-46f1-87df-30fcd5063229	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
a2dd7266-03cf-4d14-b3b8-14bc01036475	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
355e2faf-1ade-4dbb-852d-9d2b47a3a97d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e43d4415-1e31-4238-af21-f09dadcb5c90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	05/21/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c35de1a5-7015-481d-af01-ebf123659aef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	05/21/2023		Asqueroso	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f8a10d7b-2425-4f50-81cc-9355dc4c65e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5010deaa-84b4-4059-8daf-b5402ce3594a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
3f089c6e-54e8-42f2-af3f-cec05e4002d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4b0aa11b-f7ba-4b71-b6a5-dce05b0e3b6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
374ae84f-9c77-4fa1-947e-d7cf4f762558	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	05/21/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												
c0178e16-d016-4d58-a879-f11f37278cac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8914c6ef-a8eb-402b-9610-78bdce5dd302	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bc6d73ec-b52d-4048-921a-aa7788c05f6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2f0257aa-12e1-43c3-821a-c96e1263d8bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:01:00	TRUE	FALSE			en-gb	12:01:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eb96198e-12cf-42ae-8e33-54f42e5a7ed3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	05/21/2023		More ventalation
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40e2be73-a597-49f2-ae59-bd0a0dd1c297	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65690b8c-f121-49dc-beec-555adf3ebcf6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
716b293f-1b0d-40c4-a55e-d6044090f873	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	05/21/2023		Muy sucio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
cecb93da-0276-42bd-a094-bd058b632f3a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1b1bb137-4a8d-40c2-9d0e-7b45bbd5c622	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f7474107-c726-4264-8565-7f97f6b0038a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
544392d2-f35d-47fb-b112-090ea41cb9e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
915d1646-2e48-4ebc-a081-649fde707ce8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ff9004a0-75bb-497e-be46-e0f23d76c14f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	05/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff9004a0-75bb-497e-be46-e0f23d76c14f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
de815748-700d-4fa2-8407-1bae75bbe536	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a47bdda-88e3-47d9-88e5-52105ecb0a0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
244c1706-ff5c-4772-93df-5e92785f977b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e77f770d-e543-406f-914b-0be186ab1146	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ec707168-a300-46f7-8373-c93b27fd95d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
02dba735-4c9d-438a-899a-7b66b4e1158b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
39b97d43-e5c4-4c7e-90c2-b17dacce4b95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
d5b5f9cf-6436-419f-ba07-927af7f6343c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	05/21/2023		Stink	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
540cd166-fbdd-42ce-bcdf-dc72d5134614	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3fc3b6c-9123-40c2-8137-15aa62e8f0fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4add895-dfc3-495f-b786-3fc1a1d1c797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a72ff6b-b25d-44f8-a0df-9a9e8cd188bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d80e68ec-4015-4ac5-8ac5-c21ef614faef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7278983-0387-449f-8300-fa120eb63111	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
94eb997d-c11f-4c86-ac09-a174511ab65b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c922daf-6d5d-48cd-b708-11e88fd60a56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b2068b3-871c-4c5d-93ec-ee567a857084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96e06d05-7047-4d2d-ada5-ca5e528d575b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	05/21/2023		It was very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
820256d3-4263-4095-9d6e-bd8847843dc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 21:24:00	TRUE	FALSE			en-gb	21:24:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9ee296e9-5aa9-4b51-a155-cdfffa08002a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	05/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ce35506-27f7-4371-bbb1-da8507735883	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8c2824a9-8b72-48ca-b668-9ba13bd55c9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/21/2023 23:08:00	TRUE	FALSE			en-gb	23:08:00	05/21/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1c544490-e9f8-415d-ba2d-6a2e8ed610a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 01:18:00	TRUE	FALSE			en-gb	01:18:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bef13090-c83c-4ff2-a3e2-5c8e81983a9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 04:56:00	TRUE	FALSE			en-gb	04:56:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c529e3eb-e089-432a-8790-59ec88288da9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
179ff816-a9f3-42c6-b145-d3217f173c9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	05/22/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44513590-f3b4-4d7d-93d1-e351a865ac6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e32f5de7-75ed-4322-8a51-1ef248b2042c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cba6d971-0c20-4d42-b55b-08066b8ce23d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3bcff07-f465-4466-be5d-97791d58fea6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd8cd2ba-57c4-4fd3-913f-3664d3e0ca2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76844432-0777-4a2d-b353-fcd8bf4ddce7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8f1f2b80-1078-4c7d-9797-14787254af36	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bf29c464-55e1-4aac-9185-c46877fce6d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ed8fbc2-2e65-423d-a66e-684ca4f22d43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	05/22/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6f73cdf-aaa3-4960-b9b2-ed858bb84404	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d0bb094-08d9-4058-aa60-75febad44d7e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b581a979-e711-4768-baed-205d87b1dacd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/22/2023		Good job, congratulations
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
691c86b8-5663-4d29-ac52-5bc467075b68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
8ab81aac-9fbd-42b2-9f3a-1cdb03208f10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
6b606dca-d090-4150-9d29-7a8ad6b77247	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
28547c2f-41a7-4d1e-9fad-77dbe48631ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
78f8d948-320e-46ea-9da1-026bd7f5d223	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/22/2023		God	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
493ba44f-b1fe-47da-a441-a66604e86166	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c8415739-48e5-43a5-a81e-98d9d79ea115	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
7ac034a8-4343-4295-9468-62acf187caed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4806b3b9-6559-46c0-bd11-2cc169910b9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cca8e6de-29f0-4cfb-ae0b-b81a9c967617	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
58a4507b-79c1-4fb5-8643-b74d3ef71717	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2ca1461-cee6-4a37-bac9-2ea8f1a43ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	05/22/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
21e09c41-b953-4651-a490-4d9d7471e921	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fe834087-0db6-4d08-b925-381c8c0589b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
555296a8-1bac-453f-b23b-fc654d8c6422	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7bd30620-b2df-4554-a07f-ac7ce2f387fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6ee02cb7-a224-496b-bba7-e48891a54de2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 18:17:00	TRUE	FALSE			en-gb	18:17:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
776a78e5-d251-492f-9aeb-85a5aa4d681e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91f7abc0-7477-4018-8549-32e4c18c97cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54b9f872-4ac5-435a-b954-f82a9505675a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1459ed1c-873e-4e4c-a214-98493fe7d8e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	05/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1459ed1c-873e-4e4c-a214-98493fe7d8e4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes								Yes			
544b745c-409e-4ff7-b813-5b049d062cf8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d4ea9ef0-8645-4771-9860-5abda02d8fa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	05/22/2023		Guy working cleaned good.						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
4d79c7ae-f243-4e99-bf03-5c1d9b51f830	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
a0a3f5ed-16ac-48f2-98bd-2f3e732c1f41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
3ffdd30d-0f0d-491a-8454-72fdbfb043b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/22/2023 22:43:00	TRUE	FALSE			en-gb	22:43:00	05/22/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c52850b2-5739-4073-9ccc-e95eb55deace	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	05/23/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
686aa40d-1955-4884-b7eb-21adc5263dc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 00:32:00	TRUE	FALSE			en-gb	00:32:00	05/23/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50d0342c-288c-45b9-9b6b-7e7305003f66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 02:49:00	TRUE	FALSE			en-gb	02:49:00	05/23/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d3ee05b-13cc-4c20-9a88-6eaa366d656	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 03:20:00	TRUE	FALSE			en-gb	03:20:00	05/23/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cce882f9-68bc-4fed-ac99-ea08b4f90e17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 04:52:00	TRUE	FALSE			en-gb	04:52:00	05/23/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
96f20a2e-98b9-4603-84a7-9ff3a15eb1fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 05:25:00	TRUE	FALSE			en-gb	05:25:00	05/23/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
95776ae0-5812-43d2-b79a-6108d4ef2e22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51640b99-d871-4177-b3fa-2cbe2c5248be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	05/23/2023		Muy clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee6e89c8-49d7-450a-995a-6418e1cefb42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5ef8df04-2b58-458b-949f-a3f130eb7ef8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3aff1b5f-bc3b-4bfb-ac4e-8a1ccb7ecb47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	05/23/2023		Dey clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62e0dbcb-b396-4a78-8f17-39c96607dd43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2b472a4c-6018-4036-97cd-4181f672a084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f87a8902-ceca-4cea-8676-d13e1e1a036d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
817fb9ed-3b0d-40f9-9fd6-74fd75de556e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3cc4cce8-bb15-4f7c-9c25-1561aa5d670c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d0f6be54-ded8-4949-a9b2-5236b47074f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c633b3e1-5064-4673-bb2a-3cd0e6d12cbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aece2add-6bb4-4c6f-a8c2-8fa38f2e2e0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	05/23/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
abdfc91-d6de-4285-ab22-f784b5ae31bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bae636bd-fd33-4e17-8abe-af55f2a4bf48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da6306ad-c357-4dd5-a2bf-a46ad010437c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9c9dd427-7d69-49d8-9206-d7129f2f9d6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ae99a05f-91e8-4a3a-8155-e92fb467be6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	05/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dcab3356-e4c1-48c1-9761-29f2a3035097	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6053cd0c-9625-4cf1-beee-ec661aba5ca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	05/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
607ea08c-add1-4c65-8b01-3ef47e20025d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cc7bc819-6c27-4578-b06f-73906521b892	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cc7bc819-6c27-4578-b06f-73906521b892	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
a8d1bf6a-8c01-41b0-827d-cf562f642abc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 15:24:00	TRUE	FALSE			en-gb	15:24:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4dd73447-0219-4a7d-879c-c48187ce46dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
21cd2f44-1ba6-41ed-b26b-11a54e00203c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c17751e0-f7ea-468a-bed5-b6ba5f0a99af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
93751e22-b63e-4b18-8319-be741c349774	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7fefe167-5973-424d-97b3-8b3ad171c53c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a462acba-e008-4cca-a88c-94bd1b566a74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
452b1e37-7ae6-4402-bb45-f097ea7811e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
642b02c0-1949-4df9-bb79-6956ddaa8bd4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c682d3f3-a5d7-42e9-9026-5cb7b24ff02f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 18:28:00	TRUE	FALSE			en-gb	18:28:00	05/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0565c0ee-aac2-479d-9ec0-12e1e8a5c19f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2314a5ed-ac8c-4bf5-bf23-08e07b5e3601	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55965782-d15c-4eb3-9fb1-0f67bd6b85ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ecb33c36-7a7d-4555-be9c-3211ccc3b738	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2706fa95-f251-4c21-91a0-cf9506bf3d40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4bee973-a709-4fd0-bed7-60a5d253618d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	05/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a4bee973-a709-4fd0-bed7-60a5d253618d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes							
6b3ad696-3e23-4f4d-b8d5-0cc8097a78c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	05/23/2023		Good						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
739f2056-c91f-4be9-95ef-890f80aec5e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/23/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
														Yes				Yes		
60d57595-bba9-4dee-a228-6b39db746ddd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/23/2023 23:38:00	TRUE	FALSE			en-gb	23:38:00	05/23/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
9f6f8000-3c1c-4357-a199-e9388f00a888	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 04:33:00	TRUE	FALSE			en-gb	04:33:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cb593f9f-2585-4c75-8f61-e42e2c801a09	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd4107f-1ffa-4339-af3e-ce7714bb5fdc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 05:49:00	TRUE	FALSE			en-gb	05:49:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4d97120-3ba7-4563-8745-5d69f3f940c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4615851b-4502-4086-8e35-56b2e3a0f200	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 06:19:00	TRUE	FALSE			en-gb	06:19:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
48cba56d-5b33-4179-ae0-a7a34b876345	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40a17daa-cc47-4fbd-b312-12f2bec8ffae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ee0b94c6-693b-4270-aedb-2b69c9a83da1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
9533152a-2037-4961-84f2-48b7e499caf6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7706acf0-1d95-4d9d-bddc-51ef5550eb5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
69993d26-f092-4eed-921c-6949d87dbe27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c07f8a27-7560-42e7-a061-7a82910ce7b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	05/24/2023		Test
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
98608b07-9db4-4a2f-8735-1659ff88abc8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9fe86c8a-b4ec-415d-be62-c55fd420bd8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
edb25b70-66ae-41ce-b7aa-bce47013b2c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3156980b-a96f-4313-8e65-97fe25678859	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
adc7c07e-47cd-4d10-b904-fd124f66c744	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd06630a-5c7f-4836-bc41-e69a174b5deb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	05/24/2023		It cool
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8c6e58f0-c4c1-4e4d-8463-a74cf294f13a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be3ba5df-d10a-44ac-9955-22046a33936d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f23a90d2-9731-4aac-9568-96f3d60b090b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
61ccdf8f-2a94-4cb9-be26-a66a8d1a89c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
712482d1-bb62-499a-baa7-d7c71197a85d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51b42ff9-94e9-4c73-a8a9-1ad578a61f37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c5cd9f61-e077-4a6e-81d3-dca470e09bfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d52eeff-08fb-4e5a-a70a-9686397fabfe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
89c9e145-2d70-4f89-be61-8d4459129272	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	05/24/2023		Hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
dc11f2eb-bb1c-4865-a4f5-666e6f05f52d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c314c365-2273-4cd3-8487-f0ee04fe2332	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c314c365-2273-4cd3-8487-f0ee04fe2332	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes			
1920cd5c-a1d8-4b5e-a14b-8a6ecc7d8b1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
fcf1e692-b746-494b-bf20-989edbad0547	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
3fc5cd98-335a-4c56-851a-1d21b1397a43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
f6a9aa6a-6dfa-4d5e-99a6-78b0267b2541	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
97d5b37c-cf7f-4ed6-aa7a-9d40f8cdf956	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	05/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b1a720a-188c-40b4-9943-ebecf5bf9304	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bf2eedfd-96b9-434f-9166-e2a9f887fbe2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e8a43ff7-cc51-4c6a-8bde-3654cb5304ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
6bc37f7f-669a-426f-84ed-ea9e6b1c60a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5dcbe5ec-411d-4c84-8306-1815660c10aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2dedf633-bcef-47f2-a372-c7b4df83af79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53fd9c84-69f5-4e63-9514-91ad759dffda	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a10a90e8-b768-4b25-8a57-7f8c5d5a006f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9b4d0892-1c38-4822-a5b7-4b1f7f358a30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3fc420e2-877a-466a-beaa-4a90daa7852a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e172f3e-7be0-452a-9425-49ec1fc828a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/24/2023		Not AC
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e172f3e-7be0-452a-9425-49ec1fc828a6	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
f45f60dd-192c-4828-8045-293606253d1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
429d4ca2-7555-48e4-ba05-5c4790eee806	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d96d9589-b021-44f4-9580-53a36212054d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
029136e3-f973-4816-b609-738b1030e865	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b7b61d5d-700c-43b6-befe-10ef57664f73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7b61d5d-700c-43b6-befe-10ef57664f73	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
f95ea8c4-932a-4352-a87c-0c9d5a960d7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	05/24/2023		Hb	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
0903988b-5a25-4a53-ba6c-17293fdf95b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a9571ee2-1b7a-4561-b6e4-38cdc1319ac8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a6444cb5-1b68-4365-978d-0cd99c7b380d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a0e2372c-d597-41ff-87fb-7703a6068f11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d4689205-6e29-4aef-a107-16b3dff7a7d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/24/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
83354220-a267-4e29-a99b-bbd158cf46e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d17b215-a4d9-45da-92d5-44edf9732114	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
10e6c1fa-185d-421c-89e6-b183010e2c05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d412beb-769a-4e55-9a0e-3b7691bb23c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	05/24/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5fd4735b-d23f-4090-9371-77605a30f1c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
61e390e8-277c-4f8b-ab49-a1117c6aeb19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6ec3781a-f1a0-4a45-9e23-95f9a56bbe18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9ca5ddd-70cc-4fb0-9104-452c173417cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1406a209-f51c-4470-adf4-f9c2a10174f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e94d635-511a-44f0-b557-a7364cfa2d62	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4ec8124-c302-4e26-b802-5cb862f164e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
519e60dc-f80c-4f20-a56a-ba341026eae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
901acb0f-5e16-493e-98c2-65718f652e79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
741a17ae-4e75-4cb9-9aa0-48cb9c606d97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e5dbecd6-8d56-4384-a531-bbc9c96ee74a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4096061b-6d20-4c3b-9747-2739404e3f7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ee0e865c-b54f-4694-8070-0d00dfb7debb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
75031ed6-4305-4870-85f9-1119ab5dfb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a3d10484-7d81-4ac5-8e68-cc900c538583	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	05/24/2023		Excelente, todo muy limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
134c666b-02f9-43bb-bec1-cb9d502e2793	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	05/24/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
abaf2320-59cf-4dda-9dd6-6fc5bff39884	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
065b59c3-32a1-4242-b6cd-96a810c8a3cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4aa79284-49ee-4d09-9bc8-ea94c0c80ea8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5af79337-c9c3-49d8-b097-eac8ace2841b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b60a7385-7aca-4824-a900-3e1b6447de14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:56:00	TRUE	FALSE			en-gb	15:56:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9dd3db7a-2ce9-435b-af6f-fa807144951b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
35eced8a-2646-4600-aa35-d673447bc0c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d7c99222-4eee-4f39-b185-b8420b6799cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:15:00	TRUE	FALSE			en-gb	16:15:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da1c5eb6-637f-4bcc-a7d7-0ac266b270b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da95f827-9ba4-4164-be16-9e664035782a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0998fff8-5a35-4517-88a2-fb6d0daf2b24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b119135e-90fe-40b6-b6fd-cf380ba61940	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d634820e-c9c7-417e-b775-a4342af08408	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eae789f4-5189-4a83-b989-6da5beadea81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4e82e950-efd8-4aef-9114-29b2675abca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:01:00	TRUE	FALSE			en-gb	17:01:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1ed2ca28-92a2-4759-9022-37dfe0ac37eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82e23c8f-ad6d-4d44-90bc-ecfc0030eab8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
82e23c8f-ad6d-4d44-90bc-ecfc0030eab8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
9efcd99c-4749-49e7-bbd8-f6f128096d9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6a154608-27bc-480c-8a8d-0fcf62d6bcab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77de72f8-9fc2-45cd-9a85-8980382eaa6e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
c23d7b30-06a3-4615-94a7-d8ce6bad8e18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
facceb1e-1f3e-4d83-b554-3059fa652243	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c3ae973b-6e2d-44d2-ad19-2b13b15c0075	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4435898c-a382-46f4-a5bb-b83a1047cf21	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
94a5ebd4-ea9f-4605-a37c-fcb9e3fff00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a199a057-c020-4f75-a53e-9e55bd34489b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
88c1f796-fad7-4d57-afe1-31195ba1a9e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
b0bb301a-25bd-460e-9a57-cb3cc2ca12a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
738e0bde-b934-4d97-93aa-2ab276646440	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes							
97e95e61-dd51-497f-8a6c-45460177bbd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
f9b4313e-1496-436b-a5db-c2d2f517554d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	05/24/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
fdfdbac5-1086-4072-8ce2-5cbd6886435a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	05/24/2023		Dirty diaper on counter														
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
05aad90d-9772-4a87-8af2-6950067d2222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:36:00	TRUE	FALSE			en-gb	18:36:00	05/24/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
d6476689-568e-41f9-b429-aab5152f2c2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	05/24/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b85180e9-84f1-42e4-846d-e4c4bb0b4c5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c630c4e5-d0d9-4251-b1a2-0b0fb052cd22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f58ab8ec-6508-4a2b-8789-ca9dbd0f9a8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88931b16-76ba-471c-ba49-9195fae57709	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dae2b34d-db1c-460f-a2fe-5b9ed9373aa7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
4db8fc84-198c-4729-965b-e4476f41fab6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
680e8533-a842-4e2e-ba6f-5338b313b7c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	05/24/2023		Beautiful restroom
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c20daa5d-6e33-4870-8806-c424b50b67b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	05/24/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5149f64a-a33d-4d3a-a635-06db2ba20d8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c65463ad-aa48-4d56-add0-44f6a6e90742	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ff183614-ed0d-4809-999a-2ab6c83c6e5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22884ace-f8b2-48ce-98e4-a01fbcea8d0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
357be701-d48d-48c0-b631-ee316827380e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
07fe391e-c27f-478d-be85-96713aa32648	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	05/24/2023		No
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
a68e9aca-bda6-42b3-8dd1-d30b3e4798bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
dc5f1cfb-b2e8-42ec-b5bf-16b4e87e7b48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc5f1cfb-b2e8-42ec-b5bf-16b4e87e7b48	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
							Yes							
5292b57e-f802-42d2-81b5-59935b4b14a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d93d4308-5f5b-479f-8d4c-e0a58ef85451	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
8733cfaf-00de-4fba-9ea3-9c3595d62142	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2010dabb-c1a3-438b-bcb7-e79e16ec9561	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e918a87b-22e2-43b9-a549-cf8cfde9715f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e918a87b-22e2-43b9-a549-cf8cfde9715f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
00273879-c1f5-47ac-90a6-f18b309d1dd3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a06e42b2-3a76-46c3-adc1-5aaa31bd2917	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
77faf0af-bb20-42ae-aa34-f06d69f5a9b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
b9b209a7-4b4a-4979-820e-aa95d1a3f685	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b9b209a7-4b4a-4979-820e-aa95d1a3f685	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
635493d0-e2a2-4328-abf6-74f9d54948da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	05/24/2023		Clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9139e81e-8beb-49b5-b4f9-5890b4100b3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc519cdb-2fc5-4646-a6a5-ea3c9ace330c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9a6faa28-e962-4bec-8291-e5dfe4f13491	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
92d51b81-b41e-416e-aa90-cceed0f0086f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
817a3183-5589-4cd4-8321-9e98a9e09016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c6f61c09-e024-4f07-9bf6-0604889eb068	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
869f0122-f1cf-4079-83a2-f5df32b27b88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
79153aa8-0222-40da-8fa9-92d6e3f805bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c8506200-007d-4687-a59c-2e6235b4e764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f8369a21-f824-4bd2-8116-64ff6250156e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	05/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9fdf016-cbe9-41c9-a574-08d8e4b8d796	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39876729-2968-4e0e-abec-7bbe0088f45a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
106835d4-1651-48fb-8ae3-e4bda77b4c52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7249b10-ae49-4954-8e7d-17da4d22ad4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc0d3ec8-7d8a-4ab5-b88e-7f5fa0004046	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/24/2023		Mjgh
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1bfc0c32-6799-4ef1-bd09-a51313c9a0a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6755e62b-f675-4ef6-ac00-669a42c3fb16	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:03:00	TRUE	FALSE			en-gb	21:03:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1d281904-6512-4df5-9006-4b901367534a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1066a9b8-7604-4763-b271-c564395f3301	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e0b9bacd-3dc1-4e77-abf9-5758ea9f5da1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0b9bacd-3dc1-4e77-abf9-5758ea9f5da1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
648ad32b-735f-4545-b05d-57cb01b58354	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26556c15-819d-4556-8f03-5b059441c570	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
34b845cd-684b-4da2-b65a-a0ea7961cd1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
35435b63-23fe-481f-a3b2-06a0812431a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
91276190-7b6b-4663-99c8-2d3f248f2326	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2a7f1b71-7de8-4a1c-ae34-b9355968dfe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	05/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4f892f9b-a3c6-4df1-a670-67952fbb7e30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
441fd014-c189-44b8-a205-e51610c7cf98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	05/24/2023		Ok everything	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
29032522-cd8d-49e0-b6bd-1dbeb9ee88ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3fb03f2a-b22e-47f6-9584-d1d61072882b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	05/24/2023		O	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes		Yes	Yes	Yes	Yes	Yes					
1c60e96b-e8e9-4362-adde-536aff7010a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a829c72c-d895-4069-acc9-b999111ae749	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0bb60328-ef90-404c-bf3a-64fbc9a85f03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
afe5873f-0dd6-4ff4-bd6a-b49a2772fc42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:25:00	TRUE	FALSE			en-gb	22:25:00	05/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
						Yes	Yes			Yes	Yes				



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
91d2df66-62bc-48f2-9cb1-c7b79231ee56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
626beb8b-7b45-45bc-b8f5-43ed73d9846f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d62e714-e932-44b3-b4de-05bbe91bf1e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b1ef3a9-6173-40d3-86ea-1f7b1f00bbc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:44:00	TRUE	FALSE			en-gb	22:44:00	05/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							
6adcf7ab-e53d-4692-98e4-ff944c9fc9db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:49:00	TRUE	FALSE			en-gb	22:49:00	05/24/2023		All clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
84f58b43-163f-4996-afac-090b3784ffce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:57:00	TRUE	FALSE			en-gb	22:57:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
a7a75c52-1203-497c-8975-2a62b299f995	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 22:58:00	TRUE	FALSE			en-gb	22:58:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
331abd28-392d-49ff-9ec4-4bb6b0e6ae41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:12:00	TRUE	FALSE			en-gb	23:12:00	05/24/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
301fde45-f2e4-4890-a945-14bd188c9430	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:24:00	TRUE	FALSE			en-gb	23:24:00	05/24/2023		Bathroom completely unattended...no one here to clean		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
301fde45-f2e4-4890-a945-14bd188c9430	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
f2a5e7a0-07cd-4319-b910-6b7fae467343	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:41:00	TRUE	FALSE			en-gb	23:41:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
01105f01-ec1c-412f-b549-5bb0f07b80c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/24/2023 23:50:00	TRUE	FALSE			en-gb	23:50:00	05/24/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes											
63b02a61-bc62-4f18-a980-79cd4897d44a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 01:36:00	TRUE	FALSE			en-gb	01:36:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
63b02a61-bc62-4f18-a980-79cd4897d44a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes						Yes					
f6720230-ae4e-43a3-ac9a-1532eb923b71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 01:55:00	TRUE	FALSE			en-gb	01:55:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
bf901135-21a5-491b-9e33-e9640b2d5762	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 02:38:00	TRUE	FALSE			en-gb	02:38:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
2ec6a5ca-c72d-4d4b-bb93-445862c7c099	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:18:00	TRUE	FALSE			en-gb	04:18:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
efac760c-1b67-4f43-87e7-75dba290e4f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:21:00	TRUE	FALSE			en-gb	04:21:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
3d095c1c-2f04-4dc6-9d36-d59dab8b4737	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:25:00	TRUE	FALSE			en-gb	04:25:00	05/25/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5223c77d-4e9e-4f55-8b5b-9aa6ccfd1c52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:42:00	TRUE	FALSE			en-gb	04:42:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1c76483b-473c-4a82-af19-580de972184a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 04:43:00	TRUE	FALSE			en-gb	04:43:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
977e6055-4a45-46ba-abb6-c8662862a87f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:09:00	TRUE	FALSE			en-gb	05:09:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
59be9ac0-923e-499f-90cc-2963374a0195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
294372d0-93e6-454c-82ec-4dec13bcb334	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:15:00	TRUE	FALSE			en-gb	05:15:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cac4acc1-d1b4-415e-94ad-d4d68a0a3cca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51eab57c-2ce2-4c11-9a99-fd13c4cac821	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82e8c05c-0217-43f9-82c7-c3423560cb44	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9073e711-07bc-46ef-a9a5-daec937dd190	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aefea173-855f-499b-ade2-27f58540de81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00059316-e076-42cf-9bdf-8e395c8ce6b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65555907-6f8d-4cda-b98a-de76859c2734	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	05/25/2023		Muy bien limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
74b1a23e-26fe-43d7-b015-3f259ae7c644	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
97b1a5e4-d2b8-4023-8cc0-29473920cb76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41304bda-4321-4289-a9c0-88c59626e58c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
425e6d10-eb6d-46c7-bebd-376e9f3b4202	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:47:00	TRUE	FALSE			en-gb	06:47:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e043cee5-f7b0-441d-bcf1-dcd4949fd921	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b39ebd0-0c92-47ad-bf5d-130d7e39478e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:55:00	TRUE	FALSE			en-gb	06:55:00	05/25/2023		Mucho bueno
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
31d4f347-2b7d-4811-a81d-057441121883	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85724d48-e9ae-483e-9d50-bfeb4dd30d24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2db4d29-a354-4a44-b342-5d73bf922ce3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a88cd70a-99c9-4c11-9540-cf3a3b2bdd2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	05/25/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
196db1f3-d385-4e9a-944d-7b3e672ba970	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4aad17a0-0af6-40d1-8580-c3fa13dad210	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:03:00	TRUE	FALSE			en-gb	07:03:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cbb6330f-96c2-406d-9bfa-6cbc5981400f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:05:00	TRUE	FALSE			en-gb	07:05:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dac5b2f0-aea7-4821-ac4c-ac4bb0140109	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3ffb579-bfae-4a89-a1a8-c3869b4a5ce7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:15:00	TRUE	FALSE			en-gb	07:15:00	05/25/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
12c03429-ef5f-4d52-999f-c7bd5c2040cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
44a6e273-71e9-4edb-9c0e-d9c7de537e55	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:34:00	TRUE	FALSE		en-gb	07:34:00	05/25/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
f480ce93-a30c-4a42-979f-ce2dac3918a8	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:42:00	TRUE	FALSE		en-gb	07:42:00	05/25/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
1bc77185-bbb3-4505-9d81-6cb2dfacceb9	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:50:00	TRUE	FALSE		en-gb	07:50:00	05/25/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
9118e7be-0570-4a7e-9e28-3779e5917cc0	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 07:53:00	TRUE	FALSE		en-gb	07:53:00	05/25/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
61ecfbcc-b21e-4832-97ce-5e14139564c9	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:01:00	TRUE	FALSE		en-gb	08:01:00	05/25/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
ea41107f-e0eb-495c-810c-2e981592dfaa	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:16:00	TRUE	FALSE		en-gb	08:16:00	05/25/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4bc219f2-af88-4e66-93b7-f54aeed885d4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cb1906d5-2959-4fd1-886e-0c26f500ed41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
319ec21a-4eae-4fca-a118-6a3ab9d304ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/25/2023		Es bueno muy limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54170223-0b04-4c5c-a4c1-0be0e17b475a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment										
bd341780-e76b-4bf0-8784-2d1982e4c0f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	05/25/2023		Por favor si no tienen en que gastar el dinero delen un bono ca 6 meses a estas empleadas que trabajan tanto porque estas tablet los muchachos las cojen para jugar y las rompen por favor asi se estimul										
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							
3799b197-309d-4b5e-8ca5-0d38c6644bc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	05/25/2023												
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							
1a5d25db-8990-4d23-852e-be1dc8f7b399	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/25/2023												
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							
95427d03-2828-4c35-8832-b7a8689c3a37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/25/2023												
														How would you rate this restroom today?										
														<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
229f9d29-2cf7-49af-9ae6-6817eecee4f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5594b072-157c-4698-80ad-5fecc7071935	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1e2ab6cf-d536-47f6-aab9-38cf2becc87a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0b31fc7-a0d3-479c-a545-89a49e65f897	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0556e3d-8aca-4665-922e-913ce1db4f8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b73e61a6-e083-4e3f-9948-97458644ae8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f0592b4d-138c-4876-a258-175b40dfe5a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
646ed157-ec13-468b-bf83-b9ca2ffccc89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4fb07d63-e0f0-4286-9577-b65a90df0e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0fd62053-147a-4b3e-87d1-511f3b3a8227	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c9d6c80-5a3e-4786-95be-338606e90b72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b7ed568-2fa0-4620-bc79-2dcc8638492d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
313c4f20-30f0-41a0-8b1c-d91ad02b1dc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2edcfd-8eca-4437-b223-76ab60ea5f3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2e76b37d-66ed-4b53-bcce-4e38794da689	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be89bf62-2fcf-4048-9d1a-1cba452ac9c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3fb3ee21-7574-4166-8679-b421beb4083c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8269c4e9-a597-4ac0-87a2-5206f85852d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	05/25/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8269c4e9-a597-4ac0-87a2-5206f85852d3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
c5611f05-9d92-4abd-8621-82c04cc71edd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51f2551e-24da-4a76-a5dc-068a74f63f89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										
52018221-f0f4-413d-8d4b-fd1c606714a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dfb0a601-1c9f-49a5-97e9-471017011541	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c7337c14-6775-4e27-8c34-1b3eaadb3b89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/25/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f6d6f620-37cf-4d97-8fb1-d62146888ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/25/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
5ad77b68-85db-4b76-8bb6-3806f23fed28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	05/25/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e8478769-5608-4b13-92a7-e3a5b2f53979	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	05/25/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0f842013-cba3-4abf-a339-d3168f43a02f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	05/25/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c90af3af-c36d-41b5-969e-dc942f747c36	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	05/25/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fe2aa723-825c-4f4c-9f4b-166c79f3066a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ed09551a-afd4-4c43-8086-11fe5b9206de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d29013dd-825f-41ca-ae63-6849e10df158	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca4a2291-00c0-47a9-8441-ce93c7c9b0c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8366744-bd2b-492d-bbfd-1f6d7bb62665	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	05/25/2023		Yes this bathroom needs disinfectant and fabulisa. It smelks terrible. The paper towels terrible. help the ladies thank you
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d8366744-bd2b-492d-bbfd-1f6d7bb62665	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
914c5f57-7e8c-4638-9f98-03c432be278c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fee5ae4f-ccec-4977-b254-e91d2596d271	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3505d22-4fd9-4f38-8804-15ba3dfb4a74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
edf0a253-465b-4fa2-a3d1-a36f67dd56b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef3c1e64-f16e-49b7-a09d-480c8a774e92	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
48ac9f52-ce41-4a13-a626-55480aad66b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
9ce561c1-7ec6-4d3a-b459-aaf03928e86e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b9f31158-1633-4c09-930a-ef6bf354c4bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes							Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5b2d8b3f-a6eb-4450-841a-f7cc52b298c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3683f08-168e-40ca-b95e-a582be5c247b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes				Yes	Yes					
a49addf7-5c2c-44ab-9eda-5b11bac70a04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
04fcde1f-de91-4fca-92f3-dd546af26a8c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1a2f4f0-d50e-4876-a8ce-b2fb4ff8b9e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cae49e21-aa18-42c1-a19b-1f9071c28cc5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49793f9e-856a-4326-aced-76d01dc42bd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f96e704-a366-45ec-85fd-1ac620084813	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
003fd85c-c7b6-49f9-b67f-80128f4591af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d416faca-230b-4c18-b5ba-5b3d517cc921	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9fc65da6-6b37-4607-9966-dfa5ad82b313	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ec7d994a-ec8e-47b1-b77a-3809c0ee123f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7b93644a-4b1a-4979-9d93-38ecdc9bf213	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
7ab89664-6e29-486d-ad9a-dfac99be772e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
38fd677c-85f6-4234-bd37-cbe389eeeb42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
577faae5-2738-464d-acd2-fddde537dd86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:01:00	TRUE	FALSE			en-gb	12:01:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
				Yes		Yes								Yes					
327a8e0e-9ccd-4c7d-a65d-3a698b5fac60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes												Yes				Yes	
bfac468b-e3a7-4fb4-b8a2-f05bccd32076	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
e4ce232e-9a74-4786-bcee-b8fd6b310673	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	05/25/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
db7c1989-3f12-4ba8-bac7-9a6b9720ac3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/25/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
6e981834-581e-4a31-bb88-a8b678351185	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	05/25/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																Yes												
cfe1a67e-0fb4-4829-8eca-9eabe0357945	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/25/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cfe1a67e-0fb4-4829-8eca-9eabe0357945	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes	Yes				
2414be88-3804-4594-8c5b-7fe07177b4ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ef95454a-a4ba-4e81-b193-aaf782ff21f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3216a16-4829-4373-92c7-1277393f0eb9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7181d650-24f1-49da-8ccc-9c33e50a17ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:30:00	TRUE	FALSE			en-gb	12:30:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1e86f899-c2b6-4ed3-aa29-7417f9217a0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f86d6baa-7658-4fa6-97c8-1c77cd7c105a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/25/2023		Good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cf54c4e0-59e5-415f-96b8-d61beb7d7fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3a059ff-ecef-46a5-a1b5-de2a15a96898	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
90814782-7b37-4a00-9274-db13a9862259	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c668b68-5515-4db3-95d3-c57db7999b0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50b9654e-3bd6-4edc-9f2a-2bc4d168293b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b81cf255-dd4a-4cf7-9ff0-5192201cdfcb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	05/25/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62c8f922-695d-465e-aa14-b6b831995cf3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1080b9ae-05d8-4a6a-8bca-dc4332b99ca7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	05/25/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
323add75-0a8d-4a5c-9f12-2f15c64a6e4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1628fd23-5c35-480c-bf11-fb0e7a229f2b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	05/25/2023		Small' busy restroom but well managed by employee
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eda3e4b7-2c1b-4732-a27f-1f505bb623cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3bd8d1cd-83da-4b5b-a1ad-82c5c5772c96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3591c0f8-738d-4bf7-97dc-b024a5478e64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89b12569-1577-4f2c-b060-deff93f88410	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ee0b2d7-e21c-4588-9afe-1f6c47245909	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
12f19c28-9661-4121-9da8-7cefb5920362	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
42d04d07-31e6-49b6-ae30-8d821d1553da	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f006ad5b-4604-4cc4-ac77-d666eba5f4d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	05/25/2023		Great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5e69de00-7086-442e-92b7-249bc4a7ba35	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28728b0b-9118-4ccd-8e8b-1299153bc738	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eb7ac40d-5e3f-4488-99f6-d73e4d7e22d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d2882e8-a190-490a-9044-9c2ac3fb09c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e4a901d4-5a6f-42ce-94d3-e2039dc2a2a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
23166ea0-2a64-4d8d-ae71-4a8ef9feeadf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
64c8209e-92ec-44ea-80c7-e0422e1b1250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/25/2023		Super especial
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d952d615-5d8b-40e4-bd55-fa59972840aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/25/2023		Limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7e85f31f-8a84-4422-9dd8-5e47923ddbcb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e3822a7c-3189-4a6c-aa06-e071eeb6b0cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
05008a9a-ea08-4924-8fbb-60bae3172770	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
181c884d-12af-4a02-980b-a7c341e058b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	05/25/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d5989fe2-9f15-419d-9482-853e2b6225f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b735b3e-2169-4eed-bad9-b5f1e33a18c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aa45b1cb-b41e-4e70-bfb5-30214b051ed2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	05/25/2023		Good survice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2aaffb3c-9070-471e-8f78-d87e76d9777b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
eaf479ae-e82e-4e8b-a33d-b254baf114ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
05ebed84-e7d8-4a55-9c9c-b2400ffe9a9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:20:00	TRUE	FALSE			en-gb	14:20:00	05/25/2023		Yes i think you should fix the lock in stall number 3.	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
daf0f083-f2ba-41a5-9d56-51aa5eb3b63e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	05/25/2023		Broken door locks	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
4dc19b36-d637-45ac-bd87-0506354896ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:36:00	TRUE	FALSE			en-gb	14:36:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
794454a8-c61d-43ba-a05b-a5e0aeba4949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	05/25/2023		Broken door lock		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
acc558d6-6d14-43e3-8f62-43d47c6815c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	05/25/2023		Clean		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
00307d63-1f39-4fa5-90ba-d44f6e2a0eaf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	05/25/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30ae1146-a2fc-40ba-ada8-8574d3dac2dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
59612134-eb72-40df-ab95-2056f67aae72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:57:00	TRUE	FALSE			en-gb	14:57:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e4ba5239-1688-40df-820e-bc0e079a467e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
75668a9a-060e-411d-8974-73fd0b1ad5be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
aae28551-f68b-405e-9969-0cb100a32a2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
				Yes										Yes		Yes		Yes	
afed0b82-5321-45f0-9835-e78eb4391e36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
18c79df9-47b7-4f20-9192-a5ff52f6fd96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
d4dd73de-2162-424e-9e2a-1102bc9fb338	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	05/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3c914645-020d-4c5f-b15f-6e2dad4a56e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	05/25/2023		It was great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1ed673ad-93ee-4679-8d1f-f48012f05378	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
048dd5cd-b444-40e6-9aeb-a75a099dfe51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b8673b7-5ac9-4169-9c1b-5e3347a4d545	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0949fb4-4f04-4434-927b-005c0e77c8ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6c496496-7d67-4166-8df8-85ce2d8b8bc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6c496496-7d67-4166-8df8-85ce2d8b8bc1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				
5e73068f-6bb1-4e77-9c38-3c6b062062b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 15:55:00	TRUE	FALSE			en-gb	15:55:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
273508cb-3e19-4470-97f2-fbe16ad512d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c95db959-fe8f-49ee-9ded-da8c38d882f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
de15e599-1cbb-4f23-a7bf-796c3a3d8328	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7b9b49a3-e64d-4e86-acac-046da2d5b08f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b4d3ae4-6725-45cc-8565-ed523f728b11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0c78c3e2-00fd-48e2-8de3-bd60e69b17c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5a318556-2255-4e76-ab39-d758df2c91d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6a9cf97f-9387-49e5-a7a9-0234f2eed373	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	05/25/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
68eff11b-9d08-47d5-96e6-121ec961509a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3fcab5cf-6b05-4ff3-b06c-4d6f7f94d514	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
930d53ad-f113-4ed4-b773-e84be366ab3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16210e2d-a078-4897-bbc5-8b510939014a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d32a121-3a9a-48ed-9d09-9b3d404d2dcf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
331cb9cf-265c-4d19-b1a8-c41a63ba1164	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	05/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2a722619-4775-4d6d-a3dc-b283cb043add	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	05/25/2023		Clean thank you	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8f266b8d-7b9e-4ddd-a304-ce7c956fc553	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes							
7b467e55-3971-4d59-8813-62cb0c937aa1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c1246f0-7cc2-4924-9180-8cd6d9de22f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9e069137-7ea4-455c-8ad3-9ab88a45745f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9e069137-7ea4-455c-8ad3-9ab88a45745f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
d00cb742-8f02-4dbc-be02-7eccbf7a4f48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c1729522-617e-4393-abdf-3037b1abc543	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9891cde0-d22f-479e-b78f-67eb0399fb6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0105663a-a6eb-439d-989d-c229de735758	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	05/25/2023		Good' excelent
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8122016a-3bdb-4152-a688-65bf96724b84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7cfbe5c-4903-44c3-a0fd-89a175c6d04d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/25/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72153a04-fb7e-4fef-a189-c9e533a99247	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e2d5de2-ea44-432b-9540-88b240a56798	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
4fbc614a-e778-4ab4-bdb2-bcf89a1e7aff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f1778899-825f-4fe9-aaae-baba1035052a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:49:00	TRUE	FALSE			en-gb	19:49:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4aef2da-05f4-4b7d-b5f4-72e393170da1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	05/25/2023		W BATHROOM
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
82c4265f-945f-4c76-aad5-64411e0c253e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b5181e4-1b5e-42bc-98a1-3cf8b7923f3a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50e344a8-acb1-4f6b-8d90-7c3b3f94fc10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	05/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c5307f7a-8984-491b-a03b-a8d618741a2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:10:00	TRUE	FALSE			en-gb	22:10:00	05/25/2023		No soap....
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c5307f7a-8984-491b-a03b-a8d618741a2a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
b12897e0-9ae8-4a15-af9d-08bec3001816	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes					Yes							
b7080333-dd33-471d-9736-f190228faeca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes							Yes						
7f8778e2-b64a-40cd-a2c2-cc640dce229b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	05/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
7f8778e2-b64a-40cd-a2c2-cc640dce229b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes										Yes		Yes	
e8d2c075-8e50-4676-974d-29ef69a6dcf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/25/2023 23:16:00	TRUE	FALSE			en-gb	23:16:00	05/25/2023		Dirty floor						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				
1f30f666-0d55-4e74-bafa-f9888b0b7580	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	05/26/2023		Why is always wet						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
605cc8f7-093e-44e3-9f87-0f78124a5f16	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 05:54:00	TRUE	FALSE			en-gb	05:54:00	05/26/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ed126170-52f5-4d68-923b-69f47847c12c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:06:00	TRUE	FALSE			en-gb	06:06:00	05/26/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
2686fafa-fef2-4013-bfab-3226a01f61d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	05/26/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
233ee0a0-d7c5-4f1a-9aaf-1b87f24e8896	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	05/26/2023		Mhhh
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
809465f1-1ee3-4882-acc8-fb0ef123869a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:19:00	TRUE	FALSE			en-gb	06:19:00	05/26/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
addb8ecd-f207-4af9-ab69-e924d3637593	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e63591a-09a5-4201-8e8d-f59f1eefe87d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6239acc1-4805-453e-9668-4735353bd220	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f45f7e34-b93e-4976-a8d3-418b39f3598e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c42b6c34-04cd-4f18-b1a3-a05ceaaeb835	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e6ff238-edc5-4e31-8bd2-7bb7e11cf686	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
29a10dcd-0602-48d8-a322-39abea966a47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9211c892-018c-4401-a8fc-23ad615ab5e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f445045-acdf-44df-be5a-6eda8d995102	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/26/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
728f0ad8-1fba-449a-92e4-bf15e2b3007b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d4cd2cfe-3850-4cd3-87cc-6071c744ace3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4feaca14-6865-48ab-9b69-b728029e57af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	05/26/2023		Thanks
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1ee66ac8-ea1b-49b0-95d8-b846e6179409	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/26/2023		Na
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
68593661-39f2-4a88-b585-c619987a1acd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/26/2023		Good job
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f9a2f96a-5c44-4dda-a4e3-5ac86be9e8cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0476eecb-5a0e-41a8-9502-48df4180b099	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	05/26/2023		Super todo
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2994d88c-38b4-4358-88e8-676647867d0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a6dbfcd-0519-4ff7-b979-9a6f43deaa67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da0915df-bff1-4afa-9466-351c49dec487	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2dc74917-904f-4dd1-8f9f-9ffa4320f666	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e8831490-7af2-40ea-8a13-34622dbfbd58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
126ff2a4-af0c-4f73-970f-3f1ba833419a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:05:00	TRUE	FALSE			en-gb	08:05:00	05/26/2023		Recuerden no gasten dinero en tab denle bono	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9278992f-97b2-4778-909c-e2e7ee56bfe1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:09:00	TRUE	FALSE			en-gb	08:09:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes			Yes												
d65bf34f-a115-45ac-bcf2-34d121440a07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a12012a5-8efe-49ee-8098-d52d77596c39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f2b8fed6-6f0f-4254-86b0-10e25dc37737	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	05/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e12369c-fe8b-4c54-8a1b-d0dceb85c61c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
328548a4-cd2d-4613-9e13-a782f60985ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	05/26/2023		None	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4e1f125b-a817-423b-965d-12ee648c180c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c017782a-3774-45d5-a8ee-72534325f102	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c28b0311-172e-45bd-a425-c30c63ac372f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b5d8d6fa-a315-4112-97ee-380d83dc4682	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a0705d3-19ff-4b2f-9eaa-53ada8628a0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ece84ab9-7b2c-4f90-b1fd-7c1a1a7d5256	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	05/26/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b37d0333-05bd-4c9e-bc2f-7121abd9a764	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
559a8757-3c97-4f09-9945-4987c97827ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
45147ea5-76c0-4fcd-865c-15eef08914bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4e91d45c-ceeb-4cd6-a8dc-f89895d9a889	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2d94b65-c966-46f2-950e-2d158fff4e58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c446ffb0-6c8c-48f0-97a8-5c393d6046c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2a02797-f167-4ec3-a8f4-cb3e9c533222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15b518e5-1089-4cc9-9824-1150dac47c7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d61a0a26-6a39-4290-964e-543b2dc15ba4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
28f3c440-633f-4c72-8218-5fe64d147987	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	05/26/2023		I dont know	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f5989821-1358-4055-9025-7b9051607031	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0914fbca-12ae-4f1f-8d67-de2ff44da12e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
af2ed3f2-522b-413e-8255-40ce46d9d4a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cd67328c-939c-453e-90c1-78862a55156e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
71a46b9a-835d-4daa-a753-a0be1eb73c4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
86a915bb-a5c9-461c-80dc-515b7dd6109c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
acf9418a-e029-4fa9-8c82-dfee2c3f71fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f666dc9b-e99e-464d-83e9-3df55414572d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d7e0996e-7d28-490d-9592-4785b80db589	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a8541abe-3b07-4eef-97f8-468c8748f5a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d656d22-d1e4-4bbe-a732-317bd92b274a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2276907a-d254-44bf-8c96-88db51c55be6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a17ecaf6-3eeb-44ca-b722-8020a453707e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/26/2023		clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f4c4c265-851f-49c9-9774-37663dac974e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	05/26/2023		Rude attendant
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b46201e-d9f0-4eb6-ac6f-a15a0964b340	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fc45dffe-06d3-4603-a741-54e01ff428a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f6970191-81f9-4c8d-a6fc-0bc50c738426	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
68748ce3-3ab1-4f33-b1fd-a3a9c60b887f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb208090-7a71-4c25-bf6b-99cc6b0a130d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfbbf693-0545-4e87-9515-7839f3bdbc7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
699e1f59-b9d2-407e-9a03-f291d66568a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb32747e-cd18-4999-9c22-b317b7c6fdfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/26/2023		Ok
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7bc3fac6-5e78-4b7a-ae2d-b17221ef13e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/26/2023		Bueno esto
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb86af3a-df3d-4a82-a7a1-42cc3cf3b33a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb7dda6d-018f-4b70-a296-46c8821672af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9e5d6444-368d-4c71-80f1-2560506fb54a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f86eb955-f6f0-4a48-a4a3-7cdc4924be4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1639ec02-6c29-4fad-b58c-e3761625a2e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
46672a1a-8775-446a-b837-0bd2e0dc7a9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f1acfe9-cd75-4a6f-8ee4-89f02eee9699	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
46fc16fa-f24b-4f4e-9fc9-78781d207d1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8c03e601-1ad6-4804-8b20-d37bed87e670	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f7f15c98-1d75-4a47-9aac-3e273ed66e47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f479b283-7af4-496f-a545-3e72e1518724	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
364bcfb3-f3d4-4efa-81a7-432fe5c99f1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 11:59:00	TRUE	FALSE			en-gb	11:59:00	05/26/2023		It didnt have any soap on some sinks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f32f66f8-444b-4a5d-9172-f40d8c4a6d25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
389e7105-bc47-4b33-ae28-9ec43d396119	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
efa20b96-1044-4175-bb43-c49270e85ee4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f5e0fc5-79bd-438a-bf1f-615bbababc76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0247c917-04bf-445c-9351-f4ea8fcedbbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a777b56-1609-4be1-8803-c0cbe4fa01a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bfebe00-c5dd-40dd-8268-30ecfcf49240	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f954bf4-a0a6-4f76-a8f9-a2c4a0302268	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7b1fe322-27af-4817-8608-1a9a5b0739a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a9f5226-f084-4a65-89e0-3dae6402f3b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c477ae87-9442-44a9-ad12-811ea95676e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4f820abd-5d9b-497b-9f2b-cf7070f4ad9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1b85a765-5237-46a6-9b5f-a56e4ad2772a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c53b326d-fa00-4c34-b8d1-90267a9bf18b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2a6ac758-4e43-4726-9bcf-a11893911c9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78f8b266-9070-4444-9896-1652a5b32f3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 12:58:00	TRUE	FALSE			en-gb	12:58:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
68da79c8-bafb-4df0-ae9b-431e9bad2f45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76c5e0bc-fb52-4973-948b-fd50500fd3c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
b4f93557-f256-4274-831b-645cf4c4db47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/26/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c00c0770-8c02-457f-b861-41129d7e7d12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2e32a32-718c-4f93-9312-8865c690d50b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	05/26/2023		Ecelente todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6a21190-1511-499c-a1b0-15c826f69755	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
79e67446-65c7-4a3e-a176-44044c96e486	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	05/26/2023		Muy bien esto
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75890ea9-efcb-4775-bec0-bad84696c19c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e37449a0-2f8f-4bb0-8a61-701d7ee9b844	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
51b923c5-1d1b-44b2-b5fb-6f00b0318619	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b945558-9c66-477f-b505-795425efd8c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/26/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7326a5fd-c33e-4223-9ac1-5426c25110af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
866a382c-d621-4728-bd5e-af8dd278fc7c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03f83aab-407b-4921-bd6e-47fec0f08223	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0abdba8e-88c7-4430-9942-46fc1e569514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0abdba8e-88c7-4430-9942-46fc1e569514	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes		Yes						Yes					
9aa996ae-56fa-4d53-8953-aeb4182c310d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
99cd5bc3-eb7c-4639-80b4-c782cbf83147	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
2f82ccc4-d341-4873-aed3-7508050db35f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
a0a14162-20ee-421d-9be7-13fe168c55fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
988fa201-24d7-4f2e-9b1e-b0047d69a625	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e56cd8fa-8b36-4d23-b1c0-09129da4babb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0de99bc3-a888-4ad3-af16-bde0db2a11b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fde16d0a-e3ef-4ade-b6cc-74b0ae3bc602	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:46:00	TRUE	FALSE			en-gb	14:46:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5574e791-598a-471b-a865-ddfac5c0ac60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d6d35e32-9613-4b9f-b48b-ba7dc5d4c008	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d264c78-d3d4-4e8e-bc45-a878c7e8f912	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3b9c8730-8174-4575-9d94-760a2ce8d674	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bf9209e7-1654-45a4-970d-11aac5f54045	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ecaff6da-0323-4017-b29e-13689a856b04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
427b696b-e207-4906-896c-92a58343155d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d53d6972-fbd3-4a64-ac1f-0e782d618a76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd02b6b8-7743-40ec-a49e-e5e10b51fe6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
761095d7-15aa-4ff6-a5f8-24dcab55e93f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6700907c-8829-4480-a866-eaf56ff51082	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f41a4faa-8b61-40cd-b9b7-850a800872c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0a86151-cdc1-431b-8d09-c26f663d7b0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c3fddb4-f3c1-4ae8-b960-8c619a1970ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1ff28dc3-9037-4074-822b-bcc90ea4c53a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
23632877-5675-4f53-988a-924e51c67ce6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	05/26/2023		All good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6739cb47-4bf5-4a15-a164-071f7e387491	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a6530f28-f572-48a3-b277-5894eff93c66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bbbce28e-6f96-411b-9cab-77d8a46cc492	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
47676907-154d-443d-9b07-d2b2bb2c66bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca3fef5c-8b78-4d08-bf62-6e389b7ac05c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff438c1e-bb9f-4f07-b00d-911c86176b4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2899b2f8-2af0-4f50-a3ec-93be2f41dccc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41d92dcf-fc3c-48f5-b39e-2b5f599de949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:00:00	TRUE	FALSE			en-gb	18:00:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
6e1df814-8018-462f-8daf-84280b12cb0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3c977d1-fe20-4841-ae46-7ba7dfe39762	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
edaad221-9927-4313-9888-55419b9bcec1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
177dcec2-19a7-4260-865e-1b96d228182b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
85a990db-9dd0-4a25-acdd-e4d901fe4dc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfc82119-9195-4a95-b950-4da802e8a179	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d8fdaada-252b-46b4-b224-fe0c1896e69b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
af74cd56-5a5d-43a2-b42c-8a6321cc344f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a181c00e-0efd-4f2a-91b2-502d47513013	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1a82ebd-5f10-4a83-a9de-23e54033d68a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4da88260-7f77-49f4-8477-ed4dfb683f08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
649c62a0-27db-4c40-adac-aae2614475d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
567c46f7-df4e-4eb1-bc32-50bed4b6dd1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3ac124c-68b0-4ea4-965b-5691795b4b99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	05/26/2023		Disgusting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes		Yes		Yes	Yes	Yes					
19912ab7-f042-4be5-a1d4-dfb9d247f310	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	05/26/2023		Fuch u	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
a6f7dd1d-ada6-4767-9c5f-f94b5ddb7936	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:14:00	TRUE	FALSE			en-gb	20:14:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
09c5bbba-1706-44ac-9b5f-28f6bab4ef1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
ef451e64-074e-45b0-b8b8-2b128e488a57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
7d9061f9-6f2e-4776-88a5-258bd2b4a550	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									
4225305c-db3a-48b5-bfc5-bf5ff95ae378	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	05/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4225305c-db3a-48b5-bfc5-bf5ff95ae378	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes					Yes					
17f99f76-edfa-4c98-8f94-45b668783c13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f4e3ce4-6497-4490-87ea-4ebc83cde8c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4183767b-6ca2-4e70-890f-7a755b78995c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8db9427-f004-4bc6-b28e-54ac58258d38	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/26/2023		Smells bad
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c5d8dfc-2335-4e56-9cc5-a4343afa53ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0cf4a8ef-7b7b-4b1e-8463-ef3e2c52ed9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:32:00	TRUE	FALSE			en-gb	21:32:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9812855a-dd52-4ad3-9eb1-486df370b329	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
109dd20c-0e9c-46a5-a64a-b72d60f394d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f3f6d3d-ed76-410c-850d-8fc2b9dfac9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
21a4fe59-2f60-4b3e-878f-306f7d82e9ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ddcc554-665a-47e1-9f01-3dd3dc6877ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e138d825-c2f2-42c0-b923-1d514c3cfd50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
05db27b2-e7e0-43ea-8a42-a1e06c629779	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
60c047a0-1c38-462f-ab1a-67f0d9b02195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8e87f078-a0d8-4443-87f0-fcaa19f85bd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
bb18de89-907d-4a60-8671-e975325a6415	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:50:00	TRUE	FALSE			en-gb	21:50:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f54ce0bf-bbbe-4a26-9826-9530bd9bd53e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	05/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f8ecf1c9-ba77-4a78-8922-18d5f8fe24d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/26/2023 23:18:00	TRUE	FALSE			en-gb	23:18:00	05/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d670f917-38ba-426a-801b-e772ba27f678	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:03:00	TRUE	FALSE			en-gb	00:03:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6205b197-e124-40e7-ab9f-a0ec2300cc0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:21:00	TRUE	FALSE			en-gb	00:21:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
53d076c6-3758-4db4-b45e-0ac30162d5a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:22:00	TRUE	FALSE			en-gb	00:22:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
325f0872-d075-4668-99b1-075d50851295	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:23:00	TRUE	FALSE			en-gb	00:23:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7dbd4b6a-94b3-4898-95e1-8b7ab6fb634d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f92266cb-7677-4d6d-8d21-1d7dc146fc62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 04:35:00	TRUE	FALSE			en-gb	04:35:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5694f787-615f-4a01-b788-9ddc1f8b4da9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 04:41:00	TRUE	FALSE			en-gb	04:41:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f65a308b-3a14-47f5-ab9b-382bcbae6fa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 04:47:00	TRUE	FALSE			en-gb	04:47:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
00ac99fb-f20a-4db2-b730-a93b50111e1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba6a0873-23b7-44d7-a6b8-cd527d983b94	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34099ad5-743a-40b3-931c-bc76c2c8b47d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
df09095c-ad7a-48c1-b5d3-f6e51a021e4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b5f374d0-c078-49c4-96ff-06c916aed4a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00f42513-8142-4564-b80c-251ae1850887	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6021c277-5ab2-4de1-8c81-51d5c13238c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3c3a72d1-561a-4be5-8aa8-0d22c6c75b97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2893abb-8a35-478a-9a04-5267fc5f8494	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
928d287b-67bb-4378-90f2-d082a84212f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c67c959b-c2f1-4877-88e4-5937cb87b93e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	05/27/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd556c09-ca4e-468b-a103-d1069a8951c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:04:00	TRUE	FALSE			en-gb	08:04:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4dadafe5-5d52-46c6-be38-10fa56c8d4a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
146467ff-607f-40ba-b44f-7762a1f9941a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1e64e613-6384-4263-a93c-64a5fa22100d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
664e306d-aa6c-4901-b0ac-03594327915e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c681f439-c9e8-4304-b1ff-4f167de9a08b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes	Yes						
a94c2440-e6fb-4e1b-95ba-26e7609bf0a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
192c3139-b0fb-4a93-a65b-4698cb7a6f36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76f0e3c5-e904-4451-8b45-04a66844e4c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f0457d4-f311-418f-9160-fa4fcc717dde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8237a7f5-808c-413d-bb98-ee8bf3d9be7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1d878443-9f61-4882-ba89-5c56bb634b30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
80bf833d-5702-4f6f-999a-97f54b68ac6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0eb3381e-fdc7-48be-bd22-8324a07d33b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dd583ebc-ecef-4172-818b-bde6b1e367bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
f256b0e4-6685-4135-bd44-e644298fd9f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1db4d752-3e0c-4566-b14e-4b57a39f8e25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	05/27/2023		Air freshner	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1db4d752-3e0c-4566-b14e-4b57a39f8e25	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes						
b72f5253-4c41-431c-9a60-a7e8b3fcaec3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
5ba97bc3-588c-4ee2-9ddf-eb690271ed6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ea1d0256-2800-4cdc-a596-b6a67360faa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
086751e8-a6b2-4319-9403-b6751c87d298	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
086751e8-a6b2-4319-9403-b6751c87d298	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
36236418-fcb8-47c6-b75b-0e6ef887e015	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/27/2023		Na	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e33a533e-ce69-408e-81fa-266a95694bc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	05/27/2023		Wel o t h e r t a hhhhhsb ns a nnnnnn	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes		Yes								
f725df31-a0ff-423f-8ff0-4e7710d06dac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d00183c-8e91-4fae-b812-758e60357c61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dfc06de0-44eb-4f20-97ea-9d7d88466c43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7fc66da0-a1f8-4a89-a878-37c7e32d8033	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a5310a1d-b2d8-44b2-8a7e-f005265cf51f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7115d924-09e7-450e-8d52-cb977671003d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7115d924-09e7-450e-8d52-cb977671003d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes					
74be4b62-b85f-4d55-bcd8-b0d7d0af9674	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66a446c0-ea42-4312-9296-40c641797e54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c72fb14b-83fe-4c1b-b705-77fc73444e1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes			Yes										
4eea5e8e-da05-42c7-98a5-7f40cc470b98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38e6266b-2d6f-4ace-b30e-11ef6748a044	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:04:00	TRUE	FALSE			en-gb	12:04:00	05/27/2023		Sucioooo
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7cefb36a-ffa2-4451-8145-0024a3826879	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
68fdab9d-d30f-485a-9c41-3a844a2434e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a526d24e-3a00-4a49-b0ac-624390b51caa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5489f311-4d8b-4af8-a4d9-2573c79a3b19	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
811bfd20-aea3-447b-8afd-5a88370b337a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c22b6c54-f2f7-4038-8b9a-e61b01e9bb18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	05/27/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f1a72fb9-9829-436a-8fb5-ad9d59263b0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
39b90d6d-5662-47be-ae4d-129df3757b5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6a251fe7-bad1-4728-ba8d-8fa4a08e7a4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
39ebc7f7-b182-4c08-9593-32c38004504a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	05/27/2023		I am so happy to go to jordan and see my cosins and i am i little sad my dad is not coming
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
b1142421-9f03-408b-811f-4b84968c0f33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
816a60f8-594a-4d69-8164-ac7ce1527aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
4f1ac541-f72f-4e98-8585-76424a42b773	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	05/27/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
099d541a-5801-4103-a3d1-da3f0fab4961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0839f28d-fa68-4872-8b5b-edb662f3c4cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f564c113-5924-476a-85b6-389acf86ab04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
1e0bf92d-bb94-4b5e-8a87-f95f97ed8c48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	05/27/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aa346324-0893-48d9-ae93-15750cb85abc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ae52ad4a-dfd7-4900-a7a0-6c61dc2fa944	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c3dd080b-0878-4ca6-821f-d11a4e9fb16a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
0a6ca51c-0bac-4657-b024-eced1c7a191b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
4ec22d0d-c628-4d0b-96d9-e55b27128bac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	05/27/2023		Rsc
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
0e96ae59-8f85-4f5c-b9ae-4dc23ad7a553	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
73b6c0a2-1c74-4edf-8779-8906d37266cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	05/27/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
0c7482b8-be82-4665-a349-ef38e445a32a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	05/27/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
b3471f5c-bda0-4264-9552-ec076efcc61a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/27/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
5134b297-2753-4ac0-b469-3947dbb194fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/27/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
b464976c-eebb-4a00-b6c2-53f73cb4bed6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/27/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7cfddf08-b9e8-4acd-b9cf-79d312f18f40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a7a1981b-515f-467e-89a9-0a6d0e13ec75	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
31b70556-213b-4a6f-af92-1bbe45f777e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ba148f75-cb8c-4a6c-bad2-7dca302d3a6d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
64dc252d-c87f-4f75-82b7-2760b86cedb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0b359ef6-71ad-4224-8f13-edacd18e9e92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
662555aa-425d-4439-90b8-ff6c2c915a46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 15:55:00	TRUE	FALSE			en-gb	15:55:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
85a62bee-f832-4094-b008-cf093b2bb9d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
01415a8b-1337-4a01-8d71-5e591ea93f88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c4de4075-d1c9-4bd9-985d-3cb78f413ae8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	05/27/2023		Love	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
043eeb52-a332-4013-aa20-abdcabe992f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02937e21-8c0e-441a-8e46-7b436f76842f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55f18a0b-0b33-4a9f-b859-49bf9feafeb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96b63485-a251-4ea2-99ba-2b93774fb3ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	05/27/2023		Cleaner
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44adce91-e1b8-4b38-93e1-6151be4dc05a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	05/27/2023		Thanks!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0a33a2b-6859-43eb-84f9-79e3f36dc536	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
28a629bc-2f2f-43dc-8140-526207fa7ce8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a618016-71ad-41c2-9ab2-acbcfb6b02ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
5f31d899-3159-40cf-a2a5-71c1feb63a22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b6e01055-4b4f-4e8e-9b0f-96328a8460e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7214c439-016b-4ce4-a611-9b22a79cac9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 17:59:00	TRUE	FALSE			en-gb	17:59:00	05/27/2023		Love	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5ebfcd3d-4712-4c2f-8d17-799858443b5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bf95235e-1251-4a85-b861-c9953afcbd20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1195a795-748b-42e1-835e-2785cf0d0c45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4e2509b5-b60f-450a-9d53-e31faa466cfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4e2509b5-b60f-450a-9d53-e31faa466cfd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
9b6cd013-7d3c-4777-a69b-ba3975febd0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dcf9ed4c-a823-4930-aa4e-40ff00a097b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b1f9c479-fb1b-4cbe-a57b-5ca3a2a69cf8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	05/27/2023		This is a gross bathroom	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes			Yes		Yes							
a21b12d8-edd5-4cfb-85cc-7ea310d4dd4d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6e8d474f-0ce3-4554-87b1-d1a8752abcc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3418f6c-b7e0-4782-8731-3c3f1f552dbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a6345123-03bd-4e9c-a276-20c8ed4c60f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f889bae-2925-4786-914a-f4803be0c523	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8ad02120-f5f1-4842-8041-c51a10f28cfc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/27/2023		Very good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2942d706-760a-4a77-b215-9476edf1bbe5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2023d060-d7e5-4ef9-b6b7-308148578dd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6864266b-6d06-439a-ad1e-de1d779bc75d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1c46670e-a316-4df2-bd46-9647e731e2e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	05/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ed82dfc2-6b42-46f3-ab42-09b67415d5fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									
bca6d6ab-f36f-43fb-b132-830b0b3c1556	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									
171901d9-a07b-4596-a463-6dceda9b8cb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
65fafe4a-6093-4101-a816-b4085200fceb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
65f4e4a-6093-4101-a816-b4085200fceb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes	Yes				
9b19b347-5108-420c-beb6-7c8cf5d45f83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	05/27/2023		Shes great
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9b75337f-4888-490e-b844-644b74614383	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fcf7ac78-cfd6-4553-a34a-30fc7d14d5d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
366037c7-dd66-4818-b17e-d90c9aba3fa2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f0a51b7-6b1e-402b-b2e8-767cfeef149d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	05/27/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
600a2378-0b1c-4b1a-8f5e-b4f435e8a34b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a27f4696-eaca-4907-b9f9-603a8440d6ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:11:00	TRUE	FALSE			en-gb	22:11:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c03eca9d-2c42-4443-9a71-669e03c2b78b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:26:00	TRUE	FALSE			en-gb	22:26:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
0478a8d8-b535-42aa-b5bf-c342f8e1564f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14417942-1cf9-4887-a78e-acdab0d2d021	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	05/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
14417942-1cf9-4887-a78e-acdab0d2d021	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes				Yes						
19f97fd0-d93a-44ef-a758-52e62a861d1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 22:52:00	TRUE	FALSE			en-gb	22:52:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
cb13b29e-3136-4740-a068-be48443eb082	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/27/2023 23:18:00	TRUE	FALSE			en-gb	23:18:00	05/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
b792f94f-f614-447a-ac24-e5fbf3a9243e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 04:49:00	TRUE	FALSE			en-gb	04:49:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
77eb3df0-a08e-46be-b27a-ae4e961e4027	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 04:50:00	TRUE	FALSE			en-gb	04:50:00	05/28/2023		Very good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
680626fb-5897-4c62-ae71-6b7a9564744e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
455e18f3-74ac-4feb-889d-f5e09e2f9a90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29c95a5a-7d13-441d-8108-ed64a4c872e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f020c378-b67d-4d38-b227-09f4392a331a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34721cdf-f853-4df7-ab88-74f6e7acb63f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1772a212-36c9-4e8c-b060-ff03f1665065	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	05/28/2023		Bad
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1772a212-36c9-4e8c-b060-ff03f1665065	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
dc03ff4b-01ba-4d81-922a-b60660f9b16e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes											
65bfdd2f-9a01-4830-a734-61ecb687111a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					
2cd20740-a43e-4349-b665-69459d8a4155	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	05/28/2023		Tganjs
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2cd20740-a43e-4349-b665-69459d8a4155	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e19cafa1-3550-47c2-8619-5410e33c3d02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/28/2023		Ew	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes		Yes					
7350e86e-5cbd-4ca9-8320-c2961df474fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
f0866e36-9b68-4269-989b-378ac1baab68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
7537cecc-6a10-48cf-9566-a8179e211664	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	05/28/2023		Very bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7537cecc-6a10-48cf-9566-a8179e211664		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes			
30c6a0b3-ef0c-44ec-b3a5-7680824832d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 09:32:00	TRUE	FALSE				en-gb	09:32:00	05/28/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7049f84b-eaaf-485d-9912-d7ea35849087	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:09:00	TRUE	FALSE				en-gb	10:09:00	05/28/2023	Very bad smell
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes			Yes	Yes	Yes				
3319ccdb-d256-44e2-898f-48ce2e60224f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:11:00	TRUE	FALSE				en-gb	10:11:00	05/28/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
1feea5a5-c793-4459-bcda-116ef3e48974	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:12:00	TRUE	FALSE				en-gb	10:12:00	05/28/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1feea5a5-c793-4459-bcda-116ef3e48974	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes		Yes										Yes					
99745773-f9bd-4e1e-b148-303638f33893	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/28/2023		Muy suvio						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
5838b881-fb97-4080-9c2e-dc9d99ecb478	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
631f4c37-540f-4547-b9ab-181a7f82ab94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ee3cc78c-2e7f-4248-a349-74f6ff85a961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ecf1923a-a92a-4d75-90b2-08c6cfefd584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	05/28/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a73ca112-1f69-47cb-b8c5-178129fad8ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/28/2023		Good	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4314cafd-190d-49ac-af49-e5f61318820e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4af8cc19-54c9-4693-bc32-52e5b7e4d384	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes	Yes								
8cb6b504-f36a-4c9d-a0ea-4884bbbabd6e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes				Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
90536079-34dd-4a09-84ac-a7727c4480f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
15b599ac-ed7e-47c9-a63d-b6df45b26a23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4cb11841-f92a-40ff-8fa6-87425533ead5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
55885f1a-6ecf-4b89-b8e4-5eb08f80ad1e	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:57:00	TRUE	FALSE		en-gb	11:57:00	05/28/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
															Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																
		Yes	Yes		Yes																						
c257f399-c82f-429a-972d-da7b96ce7ada	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 11:58:00	TRUE	FALSE		en-gb	11:58:00	05/28/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								
0c0ea8cd-eebe-438c-b029-d35587e1fa38	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:10:00	TRUE	FALSE		en-gb	12:10:00	05/28/2023		Disgusting													
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
															Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																
				Yes	Yes				Yes		Yes																
01c567e1-fac7-406f-a87f-5edc34cd321d	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:11:00	TRUE	FALSE		en-gb	12:11:00	05/28/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
															Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
01c567e1-fac7-406f-a87f-5edc34cd321d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
6f52245d-ba64-4826-8eb2-5bd9881fb750	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b8fe0f6-78ba-4d45-aa1d-729377a3a8d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c972be7b-0074-4763-bafa-8d0ef6663c32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aac4204f-dff8-469f-af3e-fb1bb03286e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd67e914-481c-4e91-a173-af5ad9880dc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
065e44b3-da90-40d0-b7e7-507afd882479	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	05/28/2023		Puerquisimo
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87ee3b00-dacd-4432-8dba-ca21ab163dd6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a34e77b-fba3-4396-a001-3497a098361a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3acb4724-e776-4675-a837-d006bb955f11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	05/28/2023		Right
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5f1221de-71da-478c-be7a-980a24fc6015	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1599902b-3846-4f93-9e76-cf29d1d2e6c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:37:00	TRUE	FALSE			en-gb	13:37:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
43e63cda-5afc-4131-b8e4-b9a2bfbd88f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd424ec7-efab-44ee-8c78-2463abe640c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2611e8a2-c307-4c1f-893b-4a39876548ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9525ef9-2540-4a65-9fed-9ad6ffe14912	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	05/28/2023		All is unacceptable
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes	Yes			Yes		Yes					
d058db49-8279-4f7f-bda7-5f68dc934e86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:36:00	TRUE	FALSE			en-gb	14:36:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
047c93b5-b076-4af6-bc0e-683aa518da53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
63252001-042a-4d60-a7df-ea836ee45778	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 14:57:00	TRUE	FALSE			en-gb	14:57:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85cbc734-5919-4f99-8b71-588d26f9eee4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30fab814-1d8c-4019-87cd-817843d70f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52909617-5f60-4cc4-a4b6-690c3fb5bb5a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c827042-6917-43d8-88ff-b7ccf773a8ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
af090895-f9dd-4300-ad70-4aa20c45a225	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
356355d7-b6d2-4dd1-a4ab-9ae1de86d4c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb0fa930-4f19-4805-8ab5-8ccf6b46795d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
79e054f3-71ca-421d-914e-3c15cfa91b54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7a72aa92-5019-492e-9982-42e53cc8b9ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b528b27b-235a-47e9-a2de-89a4932b16fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	05/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7bbc7375-cd9e-4642-912f-6be02be073bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fa7d3151-93f2-4a8b-9989-0d0914562691	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d4ef9c1-3d2e-4f6b-8adc-0385dfa06484	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cbfe0ca8-5abb-416e-8ab5-dd49db5ce2fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e18fb8a6-6a6b-4b56-8c12-fde62e0916f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3cc7ac5c-56e9-47e3-8a14-deccc5e5ecfa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72e7f3d9-1649-4f38-bf38-e763cc7438c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb7991b5-43f7-4ff7-b7ac-36c5000baa4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
07d2ef81-d249-4dcb-bd65-02676afad137	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
6530a518-63ae-4e28-b512-027e46f55cd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ba9ce68-4aed-4246-b7e6-ff0964819d01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
36266eaa-0e61-4223-aceb-ab34ff16a490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0b80bf3e-0134-4dfe-8cef-139cb8cd8a6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
6bda62df-cb3b-4180-b7f2-763e2a99345f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
a22ea779-483e-4076-b42d-edd280a0cde0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	05/28/2023		j	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fa1239a8-642e-48fa-9da8-0fdcc19caae2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b26ee7cf-ff70-4784-95a2-3d3fc403c374	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
62436def-597f-4e14-8b6a-269b49996554	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4fc43bb9-848f-4800-bf76-8690059758a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
54095ce1-a42a-4119-85db-fe94465e4b2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bb255f99-a9e1-444d-abf2-a4fbc97bb4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6e23d6c8-a275-4391-a00d-c4d9b220b268	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes					Yes	Yes				
e19af826-de23-4cde-8e52-3c4942590eec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	05/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
685f68fa-bff2-4ac4-bc16-662cb6cbeb4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													
948aff14-b87b-4a1f-9ee5-abf3b285b33e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
ca68e7c6-cce7-4f3c-a796-fd01de936aee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
2df20c59-3747-48cf-bb7f-cae151570b58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	05/28/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
920fe36d-180f-4ef7-8a8e-3e06bfa349c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
231f24f7-6f8c-4462-827d-bea4c5e06c66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
daaedcc9-2b6d-4899-aea3-a4e0d7b74de7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							
4472567c-4c20-4bb8-b8bd-d781ac4af1a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a5c9ea56-dc29-4863-9cf2-69c46f235cf1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6db4255-06f0-453e-8076-8f0ddb58a391	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7ab0a0c-f099-4606-b95e-c0d0dda060b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1aba9371-2b53-47f2-ac87-384ed9295977	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6f426330-20b5-4ecc-a3c0-004ced9f3f98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2eee1453-022e-44f1-93e2-d139c928723e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:14:00	TRUE	FALSE			en-gb	20:14:00	05/28/2023		clean better	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6f54c378-f663-4793-873c-cac17388e6b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7a24bb38-02ef-47b0-a5f7-26eaf993745d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e7ea959b-d6d6-4fda-872f-a011e6760685	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e7ea959b-d6d6-4fda-872f-a011e6760685	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
95a6cbc7-0cbb-4642-88af-46d98eb9afb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ed9b3d5-e744-4c29-8e61-e29cd431fa16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	05/28/2023		It would be better if it had good smell
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
959518a2-f971-4c72-90a8-1f3a167683ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	05/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e9fef383-b63a-4c74-9aac-1065bcc29af7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9966f0ca-df5c-428b-858b-ef36b012d640	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1005b725-5c60-4507-a3b0-e7e22f71b2eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d74632fc-446a-418d-8cbf-85c3bfbfd6794	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	05/28/2023		Bad odor	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9da02eea-c37d-4832-bfe0-c6a7f5937875	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72aebd17-e2d5-476f-9cd6-26f6308c4f7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 23:05:00	TRUE	FALSE			en-gb	23:05:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
2a501931-2945-4054-8a61-e2102b509cdc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/28/2023 23:07:00	TRUE	FALSE			en-gb	23:07:00	05/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes		Yes					
88691a0a-41a4-40ce-aa31-287fb2409a85	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 00:20:00	TRUE	FALSE			en-gb	00:20:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2eb92909-9c22-4ace-bf87-563d53a9b762	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 00:52:00	TRUE	FALSE			en-gb	00:52:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6d3949f1-6e88-4996-b9da-e5831f70e8ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 01:59:00	TRUE	FALSE			en-gb	01:59:00	05/29/2023		It is find
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca7851ef-273f-4b83-83f0-1d6f4551e546	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 04:48:00	TRUE	FALSE			en-gb	04:48:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e70fa8c5-668f-4cf3-9908-b653e5b468b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 04:52:00	TRUE	FALSE			en-gb	04:52:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a90ed4d3-7975-475d-8525-f4dfea1dbe24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 04:59:00	TRUE	FALSE			en-gb	04:59:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f5a8897-dc89-445a-a489-98e68d9601dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4a86fec2-4b6e-4089-9aef-941b51788f83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
09020569-36dd-4020-91d0-da024b857fe6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:01:00	TRUE	FALSE			en-gb	06:01:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f3e8c768-8624-489f-a1a0-146a528ce77c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
501bbfc0-a756-4284-9c02-7255c744c17d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bfc95d2e-5b7c-4ac6-947f-6275a8e1fb72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	05/29/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
60491467-de4c-4ef0-8a17-52d7d1dada8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
78779482-ba74-4396-baba-04be796b2afb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a7cec49b-0a78-4bda-ba5c-15bccd42ee31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	05/29/2023		Limpo e perfumado.....not a dez !!!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
20bd678f-5243-4420-bfc7-d45f3f254de6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
837a5037-cb56-4993-a3fd-ef3d949f67ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes								
c616ce2a-7d06-47ef-88ba-d9137be1e256	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b873b3ba-8275-4995-98b0-47c6dfe0398f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ba6af28-e7c0-423f-8f9d-30a2b85e562f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
83de6d86-cda2-46b4-82b1-716bd92a967e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/29/2023		Thank you
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69004b8e-f8dc-4df9-a227-2f7346aa4f3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1408bc4c-1591-4537-a1c8-39ac51074fea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39b95cea-d058-4159-943d-6c7608e34acd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:17:00	TRUE	FALSE			en-gb	08:17:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39b95cea-d058-4159-943d-6c7608e34acd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
a69156df-5b0f-4091-a161-32d554fd26ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
4ca149b9-f2f0-4efb-a7ec-7842643d3dde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
d4c741b9-0e30-4a7d-aacf-89c8b8166795	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
9508f7f3-088c-437b-83da-d888a2eb2f4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
d37af0e3-f94d-4e80-8e20-8b1d1e28cd3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	05/29/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
4f2674b0-f7d8-459f-bd18-a7e9978514fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	05/29/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
48639970-8590-40e9-a6d7-2ff743e816f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	05/29/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
220eb57b-46f6-4f65-932e-1286ce831b1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/29/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
																		Yes	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a40264a6-8123-442f-a9e6-f2cdb696a913	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
99c1a4a5-26bf-4505-b2eb-b7e04b84130e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7d4a7dff-1838-4255-97ea-074aaab40528	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ab3d8fea-de5e-44d8-84cc-60f2e8e0b5a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4fe70a27-39eb-4d9e-a3a4-b04771e35bc0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a8e4ae1f-a91f-4049-be46-8903199ef418	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	05/29/2023		Fix toilets
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a8e4ae1f-a91f-4049-be46-8903199ef418	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
7393292f-c138-4eb1-b4b7-fe44540a3e24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
965d5aed-dfb6-4341-b3ea-78626758593f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
c47b1c10-b71d-44cb-9a4c-76d9d16d37c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
e7d6f098-2ccf-4b18-b1ce-eed3caa6dfae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
99fcff12-bcf5-4765-b578-5db1093d6d4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	05/29/2023		It was neat.						
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7c9e6e49-e0b9-4f90-8e5b-f120ae870d4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c07bf96c-8bb8-43b1-9b4e-24598e2472ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1fd6ca72-6099-45f6-86f4-bcaa9fb6328f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e973a745-b1e1-4bf0-b11c-4d739167b530	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
898b5134-2637-4141-a181-df5cc449befe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7ee860d1-a535-4929-9243-66b942394a9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7462222f-a918-4bb5-b8c1-f0b302361520	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2f9d78a6-db1a-4c83-b91d-675d91ee5d8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8ae67109-5632-44f4-806b-d75f54d35e07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	05/29/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8acc4b76-8d54-4c9f-ad2f-f0bfbea63f37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
26192328-0074-4e9d-87e1-213b422e1ba1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6f37d543-6176-44bc-b4a5-c5529362932e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/29/2023		Do better	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
084a9a1b-27d4-4893-9d4d-8d4a1ac53b2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5cfe5f9e-cb32-4eca-a12a-f7d309ecfe39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
011ca1bc-a436-4c9e-9b22-08951fa155d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
011ca1bc-a436-4c9e-9b22-08951fa155d2	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes							Yes		Yes			
6d374946-d965-4e59-8d55-9d77d84d7086	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
6d374946-d965-4e59-8d55-9d77d84d7086	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes					Yes	Yes						
ae2bf35c-8649-4c0c-af2d-e77bcc4066ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
ae2bf35c-8649-4c0c-af2d-e77bcc4066ce	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												
9365407c-c147-43c5-bb88-6a2ee5e8b54b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	05/29/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
9365407c-c147-43c5-bb88-6a2ee5e8b54b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes		Yes				Yes		Yes			
7373f16b-7073-4879-9c0e-d634bc1102d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	05/29/2023		Smells terrible						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
4644b78a-5537-4f68-b0cc-2cea0f016c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
e4b445e5-e80e-4e17-87a1-258ed6eed2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
1ccbad7a-0c1d-4a79-8cd4-1807426c5cd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/29/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
52d1ea30-b8cb-4710-9c21-97f162235227	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c5d528af-0617-4563-aa67-4bdb0dff928f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2246e7f-7b2d-4b84-a20d-113117ca3f0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3957f4b5-dfc3-4077-9b3f-9c316c1d54e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2e069726-b8ca-49c6-bd25-7734c236aca6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76401625-a62a-450d-bde0-42cd647feba4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
76401625-a62a-450d-bde0-42cd647feba4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes					Yes						
717246d1-282b-477a-829d-2448f46ce998	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d1c7fd08-238b-4830-b01b-d8653a2f9d49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc55d2c9-e408-423d-a405-a8a52faaaa12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
8aa93e0e-a217-4793-af67-b8e8c34dee72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
4fdec7f9-1549-46dd-9e1e-ad9236fa01d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
f3ea4b94-8d13-416f-852a-43b050e81890	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
4217e1f8-3b87-460e-98ef-75ad52d9a3a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	05/29/2023		The best		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
39520270-da6f-4e14-9d53-19e465981e23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes															
daa27d08-e098-4b8f-950b-a8258e9f60b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	05/29/2023		Smelt nice		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c55acdb-2b16-46d0-9e52-85c3eafda1fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1fc35981-9d42-4009-a94b-89c7cb46e693	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
33f3838b-7140-4ad2-a83f-3ffd74e3fca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
49965a9c-befd-4e05-9302-8e3536511509	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/29/2023		This bathroom needs a upgrade or clean	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a2a4d395-3afb-46ea-a75a-b57645fc0bf4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/29/2023		Clean it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
aa8db29e-2bc5-48a6-95f7-ee176d221808	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
4b880ae9-8067-4848-a99e-02c0cbea05d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0688bcc7-147b-45cb-87ca-dc8c21cd40cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
68e35615-d15c-4eaf-b9c9-a8c7215a5114	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e9266e9f-9666-4936-95d5-fb37e8a7ccaf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f6857040-d73e-405f-8c42-9a993851fea0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9dcfddc1-f095-46ad-b070-880059c460e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bff951d3-3594-4fed-b3e7-e2f7951466ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
32890924-0e6a-42a0-9554-2513fb024d9a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	05/29/2023		Good job	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b76eeef9-825b-42e4-a368-f5cbe19c39d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6d0b93ef-4f2c-4e19-b6f5-a679b1f5fa8a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:00:00	TRUE	FALSE			en-gb	17:00:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
016c5451-8e32-44bb-a443-ceef93f5ea42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
01668fd0-dc16-456a-a2aa-c0da8940c51e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
61d10c84-c8cb-4d5d-af05-e39224ec42c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77278090-ade0-4213-863d-46c16ce6d68e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
4039572a-7a4b-4cde-8be0-d3f2feda09da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes			Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
63541775-6345-4f0d-9ace-4026bcfa97f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/29/2023		Bad
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e0e7221c-a1ad-45af-9fc1-9e51c1a6cb25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e6d5b518-ccd7-4eac-acd1-18a09d140a63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
23c2760d-33f7-4cc5-ac49-b798d3d8098f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f6cbb684-aac1-46f6-9514-65cf914b4f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
760a0f8e-42c0-4243-b2a5-391adf1c124e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
20061fbc-2930-4112-9255-4892259f20bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:02:00	TRUE	FALSE			en-gb	18:02:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
f711e735-f559-41bf-a771-ca00f74330b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
53b2ffd7-48a6-4119-9705-ee8b93a07431	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:14:00	TRUE	FALSE			en-gb	18:14:00	05/29/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
afc308d6-4e49-48a2-af1d-249d9a5c8d6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	05/29/2023		Stalls need service
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81c82144-0d01-43ee-85c9-a9b92eba516f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
9e772608-69af-47df-8b31-f8809fdd235d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:17:00	TRUE	FALSE			en-gb	18:17:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc099ffe-5b55-4746-9c12-de157ba0469e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1dd9e8b-50d9-4803-976c-8cfcd966af65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1bfc4679-ad12-405b-a48a-5efdbe3aeb53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07482ab2-6255-4132-8bfc-92f4e3282bd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
276b71ab-97f8-43f4-a205-d82715610abf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e08cd7e6-ba8f-4990-a59f-6519e2e02b98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae643db6-a5cc-46f3-a8ec-e09bbf8c232c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
84fc8b28-6a5e-468f-a937-c32969efcf27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	05/29/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
1e6f97d6-7859-4913-8e35-6fba07063eef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	05/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
b9194959-88a3-4627-9ff8-299902f30e3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
42fcb87a-35db-42e4-81d7-d956b964a472	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	05/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
98bbbeb5-ff07-423e-b85d-95c8dfbb08f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	05/29/2023		Nasty														
														How would you rate this restroom today?														
														<b>Average</b>	<b>Good</b>	<b>Poor</b>												
																Yes												
														Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes																				
60adb616-ed04-489a-8574-f4615f76bfd4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	05/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
46726825-cb2f-46d8-9113-da55740212b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
27c60516-7753-4306-a760-71af44d3e343	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	05/29/2023		Smell like marihuana	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
fdc1beae-66c6-4f08-bdc2-63938749e035	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
96b6466f-b644-43b7-bf75-6d4a03bc9c4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a60474d-5687-4404-9a0c-84d7c190e2aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	05/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
70ceaf38-7ad1-4519-880b-19fb94986c86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e69d17e8-b3b0-4a44-906f-7a4824d441f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d8f4d60-bf2d-4962-b63c-289fba9d4cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
51fa5a85-ea35-426a-8727-dda4f7d91b41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8dfdf9f1-205f-468d-b0c6-3a93ff91aa02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7f97c3f2-e333-43dd-9576-4c03dfc6be33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 20:57:00	TRUE	FALSE			en-gb	20:57:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0f6e712f-c3b4-4298-8d45-47a332dc8a00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	05/29/2023		Smels urine
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
f18ab090-d6fc-42af-b4a9-237c3feea41c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
66b64505-85b4-462f-895a-20c15f1cff69	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	05/29/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
02950f0e-150b-4b2c-a576-5670b04db69f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	05/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
02950f0e-150b-4b2c-a576-5670b04db69f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
7acedda5-1d67-4270-a3b6-b18302fa900e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14682e9a-7ac8-4f1f-8584-28ac8d4e48dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 22:33:00	TRUE	FALSE			en-gb	22:33:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
12d46d03-d3a0-4c2a-8266-8baf5c272825	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 23:42:00	TRUE	FALSE			en-gb	23:42:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
faaff2a1-f456-42a2-9f09-ce975d558fb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 23:47:00	TRUE	FALSE			en-gb	23:47:00	05/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
faaff2a1-f456-42a2-9f09-ce975d558fb4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes					Yes	Yes	Yes			
08e7f683-7b21-4211-9be0-9d910ea04483	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/29/2023 23:59:00	TRUE	FALSE			en-gb	23:59:00	05/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2c25a6c0-9f5f-48b8-9f19-57f553875ce7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 00:55:00	TRUE	FALSE			en-gb	00:55:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7d1d96b-0bf2-4737-aa1d-8ef6700409e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 01:39:00	TRUE	FALSE			en-gb	01:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0dc3ea09-fa03-4809-9abb-2633fc9c7e68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 04:03:00	TRUE	FALSE			en-gb	04:03:00	05/30/2023		Limpio
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dc6627dc-4a3f-47ab-b7f0-c7f6e0d8cc0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 04:35:00	TRUE	FALSE			en-gb	04:35:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc6627dc-4a3f-47ab-b7f0-c7f6e0d8cc0c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cc98278c-f2b7-4744-9e0d-00a83c5b13ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9cb4ab4b-71dc-4ce9-b2f0-247e1efe6c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:36:00	TRUE	FALSE			en-gb	05:36:00	05/30/2023		Thx
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a399a87d-052f-4fe6-a7e2-e9ce30b9cf65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:43:00	TRUE	FALSE			en-gb	05:43:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4408bba-2b3c-4c46-9990-4be6e2337d94	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 05:53:00	TRUE	FALSE			en-gb	05:53:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07c31b13-216b-4a49-9e6b-a6a7fb1c6af1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:10:00	TRUE	FALSE			en-gb	06:10:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ab4aa921-5b3c-4a60-b9d4-f9345c9afa74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:27:00	TRUE	FALSE			en-gb	06:27:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3163ffa5-c46a-43be-9309-4c24cf8742dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	05/30/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c092a06-ea7e-45d5-89f0-bf088bd6277d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dfc35c6d-c3e0-4113-af98-9efb31f390d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d14d69cf-6072-44f6-9ccf-1b4d9c498276	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d8c6192f-0573-4909-a7fb-3a80283bb892	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9cfc9343-dd93-44f3-b321-4c9e9caab7c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd368772-cd5a-4964-8e60-e990ff2e1900	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	05/30/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d8ce1a0a-84b8-4371-be5d-8fbfdc765279	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d4124159-834c-486e-b0df-996c4a2e345d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7c4a946-bda7-4e3a-86c2-fe675b8595e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d4eba6f-ae4b-4e3f-8347-eb9ce7a2f0f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cb484d73-53d8-43c5-b274-5d3c38da56bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
45491f8f-c6d6-4eee-b860-75c0983f2e68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
678ac430-6f74-417c-812c-bb59679ee64f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3abb00fc-7938-487c-8a44-807d749d60ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:17:00	TRUE	FALSE			en-gb	08:17:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
91931cf3-e943-4b23-9c28-219ff051e597	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	05/30/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fbaa6498-b5fc-4d52-89e1-69432169025a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	05/30/2023		Hiooooo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes													
0391187d-34f0-4cc3-8442-df2302f303ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	05/30/2023		Hhsbfgggndnfbf bddd ssssbfnfgfg fgfff f ffg f fhfh gghgh t ht ffmtmtmyyyhhh,h hh?hhjh??h? hj,hju,uiiuuiyig ?? jghhghggmgggm g?hgm?ggg? g,hhh,yyy,yyy,uuu uuuuuulgghhhm hhnnhhnggghhh h ggg ggg ggg g	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
86ba862b-7ead-455d-bcc1-237c3d4164e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
80a43435-19f4-4539-984d-86f51cf4c362	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2588f2f-b214-4db9-bddd-31ac717dc660	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f80c07b-e857-4176-9611-59bf4f466b5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7e87c43-6283-4f14-b74f-059a93be8340	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17282fe8-0764-4a98-bbbf-3b21d7201c08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0778eba0-7917-48fb-a9d4-9387f1f2f1e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a43d36a7-8fdb-4322-bcc6-38d193fd09f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0590953b-7a37-480f-a005-1501fc1b29e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6826e88-f455-404c-aeb5-5242c8f4ea63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cb11af85-bc5c-4051-ad15-541714f0603c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a506f9a7-e133-4e9e-9835-d9ca399ed197	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
975979fd-83b6-4add-9d62-3d55811bf07f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bda8db97-8ae8-4053-9c2e-a4726905d90c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
3a642150-d289-4c45-aeac-e727e4c3c15a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5314e4bc-dda5-4b51-b8f8-1f68581a343d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
748f7193-49d4-4e32-a2ac-ecee18a70f80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
748f7193-49d4-4e32-a2ac-ecee18a70f80		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
3fed9633-df59-465d-b3f7-c3e15069948c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
a3f69b33-9e45-4772-8c6d-d6cde4ab603a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
5792312b-5e0d-4f5b-b50a-b557d83d3e65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
4e0a3b1f-5a2d-4a05-bf11-ad1f12019d24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	05/30/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4e0a3b1f-5a2d-4a05-bf11-ad1f12019d24	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
9668423f-923d-4c0e-a5c6-e728f6ce5584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	05/30/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e88e5d3c-27b8-46c5-bd78-b797b52eff53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes						Yes					
2eb563e4-8399-41bc-9c26-4e41a0f56ab5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e3eaf19c-e1a8-4485-b351-e3f12dac198a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5534ed37-ad6f-41fa-8b47-5c60aa8a7377	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
9473d3ac-770a-4cbf-8077-da6c8392c3cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
7c6f9def-a5c6-4f44-994a-d24f16d6a0fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
9605c7f8-355e-4e0e-bd2e-618cbd694025	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5589bb34-0ec3-4a5c-979e-b756e65473f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9224e3ff-c533-4087-a039-a4506d49e4fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fab24ff0-41f4-494b-8215-a61b93cde5d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a6745afa-85eb-4b9c-b06e-b339e8ca5491	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
143c70bb-dc59-4f4d-aa35-af8649c402aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d9c3c5a-feb3-43f9-ab5a-125c68eea2bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b974adba-2bd7-4e1d-a7da-974cf0639df0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1246fd71-9c87-4919-9505-cf5f0fdd4b0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b1b7c7e4-5545-4ddf-a1c0-15e6cdefa27a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a6edc22-01de-4cbc-8746-216af296dd27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b125e5e2-b0d2-4660-b0b1-1d94286d69cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	05/30/2023		Clean it please	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9fb2e80e-34ab-46b6-ba7a-c13f460308bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
20ef672a-7fe2-44c9-9c65-129fcd739b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b3c7a361-634b-4b96-9532-11c1a6087bb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/30/2023		Ugly *** bathroom	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b3c7a361-634b-4b96-9532-11c1a6087bb4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes						Yes						
67e189f8-e2e1-4156-8193-5890e2eedaba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	05/30/2023		Good job	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
a070227b-8b77-4d42-aa3e-3b055a15eb97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes		Yes										
7e26e691-b855-4ff5-ad45-9de21761bcc8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
608c4a1a-3b4c-4b2e-89e3-3eeb90eb8804	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2ce45b4-3534-4ff6-87e1-835e7aeb3e04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4ca2cb7-fd98-4f28-9949-d32f6d7ff37b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
7772d72e-2b42-4ec4-8155-c45d9ce6d370	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
06057976-04a9-4561-84cf-d46c09652908	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b72117d4-a122-4bec-a732-a11a9031af51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
31ae50cf-bfa3-46e3-ae91-2150291440c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes					
a95e23bf-5bdb-4fa6-b495-d4f65b2308db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
740c9f35-6944-4aee-a975-f54ceb348c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
40f0182a-418f-4536-a4bd-35e6ef0e2514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
40f0182a-418f-4536-a4bd-35e6ef0e2514	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
a2ad84fb-39ba-4948-834b-49b56dbec2d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
4967a779-4973-4496-b3d2-773b52fa9ef2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4ca8232-606a-4c1b-82e0-9e79b397a390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e7e1156f-c987-401a-b820-01d42028f3ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
eeaea811-30b4-457c-b500-81c5eb14020c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
84f8f809-a965-4bb4-8c17-fdde00ddac55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
9affceba-f843-4ca4-9ef2-1bf4185939b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
387d44a7-94db-4a68-b671-dff4f637f0e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
8bf18b75-dec7-4f02-b159-9983950f6139	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
a4c0f56e-e60f-46cd-b9b8-a47907f999ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	05/30/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a4c0f56e-e60f-46cd-b9b8-a47907f999ea	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes										Yes		Yes					
97182a52-ed91-4a85-b50d-d6b58838df9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	05/30/2023		Good						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
360d12d6-47e3-48e1-9599-cdc8eda6556e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	05/30/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
efba337a-878f-41a3-9d52-bf2e730eda6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	05/30/2023		Very clean. thank you						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
75467d2b-63f2-47bb-936e-bbd3ac696a58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/30/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
518eae96-ff64-4f99-9717-eb1ae176d055	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	05/30/2023		Good						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1a9bd25b-efbf-47b3-af95-3cd16fc0347f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ef9d5736-0e85-4687-be9e-80bcb2a9f514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	05/30/2023		Good	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1bb62d03-24f9-4b08-8472-0f31aa954434	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4dcccfaa-25d4-4268-9845-1a086ba0e8c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
612caf29-6272-42d8-bdf2-342e6be9a6e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:31:00	TRUE	FALSE			en-gb	17:31:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
612caf29-6272-42d8-bdf2-342e6be9a6e9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes					Yes	Yes	Yes			
600adbf2-780e-4e85-86d4-307df7f4dd80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
64c69cf0-c6ea-4928-9f7a-ad2a8df59951	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0aadba63-9cb8-437c-b6b5-b44ea9438cbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
0aadba63-9cb8-437c-b6b5-b44ea9438cbb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes	Yes					Yes		Yes			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
43de0fe6-5ac1-4874-825d-67315fdc7332	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
970fbc86-6557-4fba-9d6e-e924a96a1825	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ce305d01-11a4-400c-a4f8-e330b486bcd3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:07:00	TRUE	FALSE			en-gb	18:07:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
31023f25-54ef-49d7-9123-2ab1242f627a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e751a5ea-96fd-4a16-bcb8-c6b0a48af7ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25302978-970f-4751-a5f5-5029e2900b5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:17:00	TRUE	FALSE			en-gb	18:17:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
53528708-01cb-4c1a-9792-ed18a8da7c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32c886c2-3554-49e4-8cbb-5bffbdd6187b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	05/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2e6a70af-051e-4150-a354-5e68e9a28c0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
								Yes	Yes						
ef6c7a9b-d8b4-431e-916f-268df4979e94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:30:00	TRUE	FALSE			en-gb	18:30:00	05/30/2023		Bug	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes	Yes	Yes							
aca2718b-8865-4e0d-8289-f75c5666eef7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:31:00	TRUE	FALSE			en-gb	18:31:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes					Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3ecd5ff-3277-4e0c-833b-14e5098f7c81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
586739bd-b060-4048-b215-757ad4bb8001	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
badb9d92-7a9b-42ee-8a7c-0982dfffbd64	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3de9e5a5-b39a-4cf5-af0e-00c165a1c59f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78875e4b-9804-4f3c-bc3a-104bd581d3a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4ef0ed4f-30f7-43a4-87f3-6e430de95f21	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:43:00	TRUE	FALSE		en-gb	19:43:00	05/30/2023		Gurk yo booty stamnk	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes			Yes	Yes	Yes					
6b7bf4d8-da31-459c-84e4-ed7a3bebbe2a	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:43:00	TRUE	FALSE		en-gb	19:43:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d43aaacd-e9da-47d0-9495-943235b05aaa	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:46:00	TRUE	FALSE		en-gb	19:46:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c2d163a0-25cd-43d2-881f-828035a9f5bd	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 19:58:00	TRUE	FALSE		en-gb	19:58:00	05/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c2d163a0-25cd-43d2-881f-828035a9f5bd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
									Yes		Yes				
431eda7e-a3b7-4a21-a672-2a71a96a1ca4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:11:00	TRUE	FALSE			en-gb	20:11:00	05/30/2023			
	How would you rate this restroom today?														
ce86f6f7-197c-4f78-9ea5-2418c759235f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	05/30/2023			
	How would you rate this restroom today?														
9998086c-e605-42a3-b2f8-eee9357d0bb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	05/30/2023		Bug	
	How would you rate this restroom today?														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
9998086c-e605-42a3-b2f8-eee9357d0bb1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes		Yes		Yes			
8130019d-0265-46b6-ba10-20ae84aa17e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	05/30/2023		Roaches, broken locks, no purse hook.						
	How would you rate this restroom today?																			
	Average		Good		Poor															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
												Yes								
a8d31255-eabf-4d51-91b7-318820a28458	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	05/30/2023		Smell bad						
	How would you rate this restroom today?																			
	Average		Good		Poor															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
a7996763-1253-44cc-8cc9-c462d4f88541	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	05/30/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
		Yes		Yes										Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3876883f-11d4-423f-a2d7-c2d6c0dedc67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad84a6bb-b9b1-4ff1-8441-e9686c861053	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
47d0f006-3153-4a68-9703-8f5a5a506f08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0ed32240-a7ef-40d8-ad87-f106532a0991	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ccb53d82-24e6-4a25-a4af-08990ef6246f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	05/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
065055cc-8d2d-4cf5-9cb8-947422d8a69a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2bd8c44e-e426-4b13-a587-1de5b332a966	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 22:04:00	TRUE	FALSE			en-gb	22:04:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7cf098f9-02a2-420d-ab52-a80a3601522f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:21:00	TRUE	FALSE			en-gb	23:21:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes	Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72cf93e1-e0be-4e67-ab5c-9d5b8cf0d7b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:27:00	TRUE	FALSE			en-gb	23:27:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
54f4be15-dca4-4d1f-bf89-9561925666a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:34:00	TRUE	FALSE			en-gb	23:34:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
d57827ef-414e-4a8a-8f20-0407ee40e772	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:44:00	TRUE	FALSE			en-gb	23:44:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4a3bae69-ee58-4278-ac42-2fe9ce4849d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/30/2023 23:54:00	TRUE	FALSE			en-gb	23:54:00	05/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4a3bae69-ee58-4278-ac42-2fe9ce4849d3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes	Yes	Yes			
ba31433b-9537-475a-8782-3062dc4199f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:03:00	TRUE	FALSE			en-gb	00:03:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
86717465-ecfb-4307-b7c7-a4b342555b59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:11:00	TRUE	FALSE			en-gb	00:11:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
04b864c1-48a9-4e4a-aeb6-cae15995933a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:15:00	TRUE	FALSE			en-gb	00:15:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0c509f8c-b9e6-4d09-a862-ee9c0a126544	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 00:43:00	TRUE	FALSE			en-gb	00:43:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
0c509f8c-b9e6-4d09-a862-ee9c0a126544	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
52575ec2-1645-4e2b-8c0a-a32450a76898	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:09:00	TRUE	FALSE			en-gb	01:09:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
48c68902-8c9f-4a2f-a295-10ba21290a53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:10:00	TRUE	FALSE			en-gb	01:10:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
c0578d1d-f509-4673-8d19-90a7da118bc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:19:00	TRUE	FALSE			en-gb	01:19:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c0578d1d-f509-4673-8d19-90a7da118bc0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes		Yes		Yes		Yes				
4d253408-5076-403d-b530-3cb806e4f422	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:32:00	TRUE	FALSE			en-gb	01:32:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
feb3d1c6-5267-4be8-82c0-95c8ef565e23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:34:00	TRUE	FALSE			en-gb	01:34:00	05/31/2023		Do better	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes			Yes				Yes							
660cf3d0-e985-4cdd-8315-d09107711c39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 01:36:00	TRUE	FALSE			en-gb	01:36:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
660cf3d0-e985-4cdd-8315-d09107711c39	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes				Yes		Yes		Yes				Yes		Yes		Yes			
66001ba4-ebfb-4402-bb46-e9aa7b9fac95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f450da43-30f2-4ae4-ba99-0b13a83911e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
a40adf37-2977-4b45-974a-70be4d90ec75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
12f22068-0602-44f8-8fc6-5e338b280b33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
d515b5e8-8675-49f4-9a98-aa3415b0f376	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3adc4fcc-77c4-43b2-a9a5-bf66d2799e0e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
90e86f57-c6b3-4d22-a26b-34907c6f4dbb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5eb47f4f-17ae-4208-9c6d-d31e7714fe81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b0e14847-d889-48fd-ae41-e586e1c4b9bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	05/31/2023		Good ****
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd080b0a-4452-4aa6-944f-22f01babfe5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d92b25b-9f07-406d-8775-5df680a97313	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c5a55b94-7c96-4447-b6a6-3c9f71146d84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5b2d5640-d64f-4643-b914-bbcf1c64a7e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5397c43f-86a6-4f87-b8e3-0add14ce30f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3aec4868-4424-48ab-81e3-0dcbc59d0453	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	05/31/2023		Good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cf600d52-8b5b-44d9-92dd-8eead130f055	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f5fdbb56-592a-45fc-8a10-2877694424af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
87abcdfd-9181-4439-875a-423920874c58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													
ab6fdce2-b130-4351-a99b-bf53be021006	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
53bbc391-07d2-42bb-82b7-8d89820f9d1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
db17b355-e798-4d92-9997-0f71f804a40e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8af50a1-c4a9-4fc4-a99f-80bfefc00e37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d45434b7-58de-4c23-bdb8-6cbaab9ba16b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:20:00	TRUE	FALSE			en-gb	08:20:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
1de6f2e3-fe87-4de5-9a53-2c36e74b4599	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
041dee67-4b36-4e20-aa3a-81e9b6327ba2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	05/31/2023		Good cleaning	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5943d8b1-d463-4fca-83e5-09fb2f8df972	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
93f0b6da-cb51-4b26-afaf-fb3a2b280922	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc9643ab-bd2c-4f5d-8834-d4e561ded1bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
7820429f-36e3-4d7c-b78a-8a8acde1aafb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
64d4bb66-cbb0-4cb2-9123-8a2cd3b15430	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1e074f50-5c76-47b8-8644-93fd970036cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c7ba85c9-77b2-4a2e-9c20-b3aea99c12a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
35b897b4-847f-4396-8ec8-b5f0ad076603	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7f44e61d-76f0-4058-95b5-1f5f91a91c46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d258ba5a-a88f-4343-8383-53c415569e13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0a7ad2fc-ff2a-4d0a-8c0b-adce83bf271	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a4b868f-9048-44a5-a6b1-e16a0c2e9db1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d7f685c-57ec-47f7-a042-1624db92a50a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
19b67263-0d13-4013-a576-4badc16cc3c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dff9587-dbea-4dc0-98a1-517255c3ad84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d608af07-4ef2-4fea-be66-350c3187b0fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a793a7f-4b63-4136-ad56-3083c2169f3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a5df2028-10f2-45af-946e-270b2ced2684	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes	Yes			Yes	Yes	Yes					
eefc8f62-86ce-4cdc-9a53-1c0a6a4a7d13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4f975958-69c3-418d-ab9b-4b4bb1cdc807	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e975c9b-9f4b-4c76-80b9-d23bab0b8bc7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
6726edf9-2611-44b6-b2da-8ff748e8d693	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8499adec-1b0c-414e-acd0-57a2cb9d8ae8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
705e676f-7302-4cbd-b4f1-e642a15de5a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9fcec8f9-a32c-4134-9b59-52d9dfe370c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4bcae84c-d0ec-4816-b1cf-e8033efbd979	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a666e79-53c9-4a95-83ec-d4f0eed92a08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	05/31/2023		Hhbgh
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes	Yes	Yes					Yes				
596b8868-2133-40cd-8c70-41727dbe7143	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	05/31/2023		One of the sinks do not stop gushing water
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c91f1144-d103-4e0c-91ad-9c527453c525	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
197499b4-756a-442f-a810-54ebfe5b6ccc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3a002be5-d041-4751-a673-b4fd846fbf6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be6601c3-a042-4c75-b19c-541ba284db54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8d1ca099-ca03-41eb-abe5-bb9f4d3011e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edff64ed-6de6-4a38-807f-a2ef3f88845c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a626492d-aae9-499e-93aa-4c556badcee2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
83d9dd88-be17-4464-b24d-afae81b66e9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6fcdfac2-36d2-4be8-af19-2fc2baec2c41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9951db61-8ac0-4cfb-a4ed-e8b004f6cbd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										
								Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
de205e59-a2c0-4120-870d-c066b8640b28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d53e3cd4-7814-49c5-b699-e2630e52b40f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6916de92-ee26-41e8-b9bb-3d3d6b9a3e37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee1717ca-30e5-40d5-8da1-3721952a49fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd84181-0835-424c-893b-df8350658f95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a5b078bb-e176-4493-a38a-439b77ee8e0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e520a173-1b15-4f78-a20b-a4a94f67e893	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
498f9d1e-0636-49c7-ade2-7ad1aba13dfe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1a41159f-0085-4b90-8637-fdd9dd669cfc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4c43ecb4-d3bb-40e7-9179-7a0bffee5094	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						
c25baa20-88e1-4ada-b4f9-1fea668f6aea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c25baa20-88e1-4ada-b4f9-1fea668f6aea	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
																	Yes			
8466a329-2039-49ae-bb29-3e2513aa0ce2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
51b472d9-ec1b-4e67-80b3-55a41d112412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
e5a53e07-524b-4b01-925c-c4457d2827c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	05/31/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
															Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e581206d-e195-4915-80fd-36ee46d6b096	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
93300a32-f6de-48da-b1e2-27dcbffe548e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10e88e75-96c6-497d-bd7e-269be4db4d3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
987ed373-d20d-44de-b321-61abe65e9238	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2efc45b-47bd-490f-af74-ed1d7896bf5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
15c0e21c-f174-412d-b65a-d0e22858573e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	05/31/2023		.	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
92509622-bcfc-4de3-ae7c-68b35dbf0dd0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
751faf66-3ef2-4e86-bf7e-40278c555d23	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	05/31/2023		Restroom in good conditions	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
969376e0-3605-4a44-9f1f-31669acfaa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9628d65b-cb6a-42f6-a17a-af4a9b3d75ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6b5745bc-35d1-47a5-8212-2ac3731ef770	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
33e35a86-6337-449b-a3db-f9fca32100a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
753c9167-84f1-4604-9e38-a160766d49a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c682759-36a2-456a-a43c-900f5c68f452	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce14bea6-31b6-4452-9247-d462e1ccab2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:20:00	TRUE	FALSE			en-gb	16:20:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
77617abf-5a84-4ace-b6b0-2c002e6e0949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	05/31/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fc3cfe4a-7496-4604-9177-d6fc850065a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	05/31/2023		Hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c78f2fa6-c09f-41ca-ae89-dad48527d487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6bc53f57-d6d3-44d9-88e1-fddaf3e54bb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d1618f33-16da-4a3a-9f18-0e8351c339b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
907ec053-d439-4eb5-ad06-2e64f0b7861d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e76874af-def6-4548-a496-932b838b9592	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes		Yes					
1c3a127d-12d6-46e2-93c2-75bd75dc9980	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1c3a127d-12d6-46e2-93c2-75bd75dc9980	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
						Yes									
ee12b319-c16c-4b0a-9d82-5278ccb2ab2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	05/31/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a6b97e8-1a59-48ac-b915-81fc2df25462	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41ae3c77-0ec2-4915-bd95-12b6891dfc7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4632766d-bc0b-436c-99be-0e7e2cf4d3f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a93afa14-05cd-428d-b036-b4ba4ef83813	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
38281816-63c8-463e-95b6-e344bd3aef7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
33123a63-626e-4f1e-9242-421c353fee0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
27cd4f77-71e1-4a27-8b35-4f3c97f4994a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	05/31/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
49a82249-f605-4f3c-8a8f-b4c0e64d6397	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd5893de-df87-461f-b37c-e89ad645a498	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1847d41c-ee02-4e21-9c7e-f685881383fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00558aec-ece5-436f-9337-22ede42f843e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
658a52eb-a2d4-445f-89bb-0ed7be4616b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c38f50f9-0e95-4a5d-883d-628a4f0c33a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	05/31/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c38f50f9-0e95-4a5d-883d-628a4f0c33a2	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes		Yes				
82c983ee-b770-434f-8df9-78f207c7d37a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a2d6240-4c12-4256-9979-0a97adb23713	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
3d486d78-1156-430c-8bca-b9de8c7db61e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a75f8b0e-8079-45b7-8910-264cff475e6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ee02f59f-4b2e-4f35-8709-9ecf5ec99d11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d2487b77-50c2-4e1d-bbaf-23fbf8fe6ec8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
085ac075-fe61-4da2-83e2-5c313c0f448c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes	Yes						
38328027-8dd0-4ea9-9682-5f5a798d2158	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38328027-8dd0-4ea9-9682-5f5a798d2158	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes						Yes				
40dc2bad-eb1d-4243-82e6-e6ef92c069fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
8b3fbe9f-dbe2-4f21-a045-62237dd3ea5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								
c4c1e595-dabb-412f-bc5f-d85dc8d9ec4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7b396c44-1840-4a97-9ca6-f6e9a6c04326	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
272b92e6-fe4a-4661-8623-5186f0b3a62c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d1c74120-d1ca-4f5b-9c0b-ee77ae13a5b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
0eca4db3-64fa-4d35-916c-c0ebc526646c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
165f4862-b6f0-4e6b-881c-ceb8c6fc8d2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
96c0ae41-069f-46e3-829b-74db7386d10f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:15:00	TRUE	FALSE			en-gb	21:15:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea76b00b-437c-4caa-b926-56cb0eb46724	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0063c0c2-6b9d-4530-8baa-1797f6b051db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	05/31/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8c7ecbe1-bd97-4672-9668-4ebc9f115474	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	05/31/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1887e6c8-ce32-49f2-98dc-9e5086583ee8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c57d078-452c-4bfb-825f-6a4ee1d074a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
942a7bfd-7695-41a1-8bde-146bf1225329	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 21:50:00	TRUE	FALSE			en-gb	21:50:00	05/31/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c5d1cd48-7b18-44ff-b3b2-720ce4709590	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 22:02:00	TRUE	FALSE			en-gb	22:02:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes									
a83546d6-9547-429c-98d8-2de6e2f6bdc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 22:17:00	TRUE	FALSE			en-gb	22:17:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6ae3a2d9-9e5a-44b7-9d7c-a76756b831dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	05/31/2023 23:43:00	TRUE	FALSE			en-gb	23:43:00	05/31/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d6510df-8648-4236-ab3f-25f528d7b89a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 00:16:00	TRUE	FALSE			en-gb	00:16:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9bdb8cac-4ff7-4af8-a542-b5585f48de4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 00:17:00	TRUE	FALSE			en-gb	00:17:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a816ba6-b4b7-468f-b81d-9400a1255c45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 00:31:00	TRUE	FALSE			en-gb	00:31:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f0b05b7-a187-423c-9464-c63a594bce05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 03:52:00	TRUE	FALSE			en-gb	03:52:00	06/01/2023		Keep the bathroom clead
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
25fd4f44-cedf-43ef-9708-bc99861af848	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:04:00	TRUE	FALSE			en-gb	04:04:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
6835711c-8f1f-431e-8560-b47316cbf72a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:15:00	TRUE	FALSE			en-gb	04:15:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
0c137d31-dcfe-4ac2-ba9a-cb2d4f67a403	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:22:00	TRUE	FALSE			en-gb	04:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
b3141e66-e9cc-465c-9028-ae9fb9eecf1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:48:00	TRUE	FALSE			en-gb	04:48:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
322b6e13-d5ef-4800-b7d5-8d2ea6dbdf5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5f2e8e74-2943-467c-9b37-44ad5e19ce7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
43daa35b-6d22-4407-9e2e-721194ca95e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 05:43:00	TRUE	FALSE			en-gb	05:43:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0f7d643f-58d5-489c-bfd6-34cee93fe138	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f7adc070-4abb-4439-a4f0-6130b221474c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d119eeef-1774-457c-ba70-41a18c820cc3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c1403dfe-9efb-46ad-8939-a6a68da2e72d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 06:41:00	TRUE	FALSE			en-gb	06:41:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
109f3a30-b3e0-4a64-810c-477506741181	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fee24ca0-3eb6-46f1-ae14-2a1f278cf078	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14ce400f-6c9c-469d-bced-205259275d45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
252cc91d-7bd5-41b8-906e-b87279dc77fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes					Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8dc96cec-a26f-4f62-af3e-9bbb8340506c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
08b68034-ecf5-40dc-8282-3b0885b003ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
71b663f7-4590-49e8-829c-eba5491f76b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0661cf05-a6a9-4014-88e2-cc62acf57763	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d14b5647-92a2-4c89-bea4-6d36ee5925f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1591df13-0f58-4a21-9ef6-d9e3937af401	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
04203e60-1514-4e43-888a-cb64571f06f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/01/2023		Mai	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a2af7f3-b678-47b8-91d8-741ae8d18c05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/01/2023		Super	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ad6bb425-f6f9-4fb0-aefe-b09f3c785edf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes	Yes	Yes					
7feb6408-e271-4818-b4ac-25ae5633524d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
25cb80e6-19a4-4ca4-99cf-44e9e5cf204c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
df1f3867-387e-4ed3-83ba-604323a8322f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6b85cf6e-e9a9-408c-a4a5-9ad5a1717851	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87e191e4-e9c3-40d3-a94a-1c89e34c6fd5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7b74f510-8ac1-4547-8193-2690fdec6e5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ec61129f-6e2c-4323-851b-ae0874167200	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6a42940b-6ffc-475d-9657-588c7d395b33	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b27953b4-9b9b-49b6-93ee-c711af256f8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes		Yes		Yes		Yes	Yes	Yes						
f12d4f5d-ac29-4f74-9941-e6813f390166	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f13d029-6cf6-4379-b1fd-d3467e017753	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55a7ece4-f91e-4bc4-8182-3f8c9b9ad29f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
407c3771-e7e0-4e7e-b007-67f1c54a7731	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2d1d692-df84-4609-91f4-a1b612edd8e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6aaa91bf-b1da-4f49-ba3f-0ff7848af429	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e44735c-c5d3-4cb7-b014-b242721bea35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b1af683-a53e-4be1-a5c1-c434807ec8b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/01/2023		Could be cleaner
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30bf1810-98cd-4245-afe5-1b3f54d1c0db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99a8852c-2ea0-4f92-b478-54d044da24a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
50d99fbf-beef-4dbe-b247-cbdcd3e77057	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						
409da39a-15c4-494c-998e-e2c2dd5286ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0f78551f-9530-4de9-b1c7-580a017cd044	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
Of78551f-9530-4de9-b1c7-580a017cd044	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes						
efb0095d-a7e4-42ac-95d7-c22257359ac4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e08c9155-e98e-4f27-8b0c-78849ecc4c36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
01dba875-0f3c-428c-838b-8bcf00aa1a45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a57dc0d1-3a67-444a-8fef-47c1c91ab403	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ccb9994-1b07-4e91-bd68-9c26fe823f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2ccb9994-1b07-4e91-bd68-9c26fe823f3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				
333bc37b-fd07-4fe7-8da1-6fe8580fc490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
f1fd59ea-c8ee-411c-9c3c-e1968a620b7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
80ecb5ed-0418-44e1-b9e9-8025e0df6bad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
0d1eb45e-0532-4076-a81d-4d8a79357526	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
63391830-41ba-4941-a05d-997090520738	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0033474-a15e-417e-811b-6c291f2095b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cfb831e9-7af9-40e5-badf-05e10fb97041	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
14480be2-face-4e7f-8990-f463eac6e27b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2b25d15-50bf-4b59-a778-f0862c0e643f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec9764b9-a778-4034-8be7-2a69e7b8679c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c1a1213d-2c7a-4bc5-9c3c-19ef9917fa7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7920e1d-2f37-4db2-94b0-b37c7117b3cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d993aa75-bc5a-4f08-8c26-c6c179f0bc54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
632cdbad-9f27-4102-8b62-d557510abb70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:11:00	TRUE	FALSE			en-gb	13:11:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a852f2f-e10a-47d2-8389-77f07aedd5fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0cc6f957-a6c2-4f46-9d93-41d71ede2972	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18b2323a-2211-43dc-8e5d-765925628eed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/01/2023		Q buen servicio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
650c7cb2-549e-4bbc-97e0-0aa60f2c0e57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/01/2023		Esta muy limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03529bb5-c5c4-48e6-a1a9-d5d0bb26c44e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c23fd0d7-029e-4778-b1f5-9f21d3480d6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2423741-a700-408d-abbd-1665188ae4e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/01/2023		Limpio todo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d079c06-115e-4191-b3ff-1e16d863ba3c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	06/01/2023		Todo muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
86723902-f10e-4e35-8445-93aa5a751d84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ecf41818-9991-48a6-9a31-763c62dd702e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7112a925-1585-4ebb-9862-dd8c98d2e500	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
885bb18e-f068-4e92-b87f-5eec184c5301	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
553d64e5-fbc9-44a3-a6fa-a379b879d6c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1b6c0b8-4169-4c24-8239-a9d365327993	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce2ffb5a-6980-494e-97df-711130f32fc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d96c85e6-747b-4ee4-a8d5-6c21f659bbb9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cdfda8d5-b2c7-4dfc-af2a-a698af644c5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b9b9d08-279b-4b12-9139-fbb76c68d9c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a44f3a69-b8bb-4117-bf01-99f36052609a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
49a6f152-1ab7-4d01-a156-f9554f4c7fcb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1424042e-670d-4712-b524-0eb9103d2cb0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
a16bba72-b4e5-4b8b-99cc-8c70818794ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
deeb12fd-ff3a-44e6-8180-a86b530c25a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20de7572-4df3-447f-9c92-536b5686ab1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5009c129-9895-4360-9e98-174ac0adfd47	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/01/2023		Excelente
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
803f3b95-0f88-4ee0-94c2-054c377024ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 15:57:00	TRUE	FALSE			en-gb	15:57:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a661160-b190-4f01-9e24-36dc11aa0409	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/01/2023		Very well
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28723d51-ea88-4436-b6f3-c37b5b1bb6ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:15:00	TRUE	FALSE			en-gb	16:15:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes	Yes					
34ae74c7-62fd-47e0-bc25-d5380dca8be9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
178911f3-4c9b-4d53-b446-bb787ae50655	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51589b38-c633-483f-9b99-5817a9eb45f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5a3b381e-139a-4e2e-b38e-796376ed3999	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/01/2023		Pee	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ca71ceb-f551-4a0d-84b9-b97a647b5bf0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
43382cf4-aff1-4f33-99c3-23dba7b1b7e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	06/01/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
585f9292-2702-4c3f-bbce-4e8581340141	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cc6f5f7b-e43b-4742-aa8b-1cd4ba75e33f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
11b0ac9a-6905-4f6c-acf3-dfcc6070628f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
675e5ba7-b72a-436b-bff4-81c795283fc4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9dc671ae-6f58-41f9-978c-ed2323e27f60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/01/2023		Super	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ead06c4c-1feb-43d2-94ce-332c63e981b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9a8ccba1-9007-4879-9c72-d974d6ab24bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2a66292d-e61b-4561-892c-5cde0d241d1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8c80aa91-fb2b-48e7-a09a-fb2b667a8448	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d24e814c-e509-4ea4-a611-bb3241b6c77c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:46:00	TRUE	FALSE			en-gb	17:46:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
200fb892-04bd-4682-b0c1-6e65dfb37e2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
167e283c-270c-4f6d-8307-64a9655ae62f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e75007ec-a6e7-4651-9abc-2dee8e62e7d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e75007ec-a6e7-4651-9abc-2dee8e62e7d8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7b488adc-83a2-4014-964a-6ae0f5edeb67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ad31468a-7511-4c44-a225-aa6669fe9127	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9475e41c-70bb-479b-a840-ef1328505835	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
178e1885-38dc-4607-a20d-a92c1705c3a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cf7b79e9-f89e-4902-9081-32cf694dc6ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6fd6badf-21bb-4da3-b744-1e3deadfc515	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes		Yes					
068e2a9e-2920-4e5d-b81f-4f03d7ec2a65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					
86a76698-1575-454d-9dda-24797336b45e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
da4e3729-30f4-4744-89ba-a8b6b88f5bf3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/01/2023		Very good experience	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
215b70cb-d731-4bf8-9a94-9da8a2496345	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					
08f33081-3a65-41a7-aff-ec4c0d4076e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
414fb1e5-1781-4980-9abf-3ca1854e155f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/01/2023		lets go nuggets	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cf3b6e68-4ed8-4d6f-b1ce-2ada5677d058	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cfbcac40-619a-49ab-8294-6867f9aa6bc7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8e29f7ab-9235-4363-bc52-1d23a6047866	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
dc52c0b2-68a8-4333-9d78-193dbe314c36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/01/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
												Yes			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8d68b153-6600-4d4b-9a40-ac6f94ce8805	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
303ea57d-3ec2-4f6e-9b72-9537b29716f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
67562484-f4cb-4f55-bdcd-661b44cf4047	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
01ce7dee-a5c3-4efd-a85b-8dfa34f0a70	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes							
23d23625-2f05-4c0a-a9f7-978f999dc213	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
23d23625-2f05-4c0a-a9f7-978f999dc213	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
21a7d0a0-2c5d-492e-b8ea-d67e974da346	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aba2f5c8-618f-43ff-a7e5-1f42459914f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51508e8a-94a1-4c06-8bf9-12269dc1fb8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:11:00	TRUE	FALSE			en-gb	21:11:00	06/01/2023		Asco	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes		Yes					
944018aa-c1db-4c43-8032-fba6ce9ebcea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2a1e1b1-e1da-4244-8f39-4699a9b1d9b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a436755a-66d7-47b8-8575-377fa8ab58b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29fbaa38-f129-4969-8ed7-d2cc0a38d2a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	06/01/2023		Goo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22952f6a-ebe0-4976-83ef-93be61926b3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:24:00	TRUE	FALSE			en-gb	21:24:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d3781dd-cd88-4c5e-8f43-7ec35bbebe00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b23f6d1d-e562-4dcf-80b6-faac604449b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9b5f713a-8228-4dd0-8021-4296a3901290	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a368f3cf-868d-4d46-bfaf-9a697851af77	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8fd70606-cfaf-4881-951f-f5a1b9580410	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
699d4917-0fc3-4348-b791-3e9d792ba95a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 21:58:00	TRUE	FALSE			en-gb	21:58:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes			Yes				Yes	Yes	Yes					
ab1a116e-254c-422f-8c1d-220a12c1d9f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8ec2932b-24ca-4281-9773-aa55cfe2fa2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2f17134-4c4b-44dc-af80-0a009a12e020	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
872924f4-f5bf-4c31-8837-bc37f6ebe53c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 23:20:00	TRUE	FALSE			en-gb	23:20:00	06/01/2023		JI
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc85238f-9d04-41f8-a71d-976f230b4eaa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/01/2023 23:25:00	TRUE	FALSE			en-gb	23:25:00	06/01/2023		Excelent
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
084115b6-586b-4322-9c2d-2560029c80a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 00:01:00	TRUE	FALSE			en-gb	00:01:00	06/02/2023		There needs to be a box for sanitary napkins in the stall!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes					Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9bac1f36-4dae-4b96-b2f5-d8aa00ea626d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 00:11:00	TRUE	FALSE			en-gb	00:11:00	06/02/2023		Bueno	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92541602-1d3c-4279-ad54-0734dcb2cbcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 01:10:00	TRUE	FALSE			en-gb	01:10:00	06/02/2023		Smells bad but i kobr tge	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1148b854-24cc-4ff1-a8e8-d0dcadda72b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/02/2023		It smekks	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
9df91975-4ab9-4a1e-a891-0e2c390a82d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 01:56:00	TRUE	FALSE			en-gb	01:56:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ce6198d4-3528-4388-94a0-bad453ab31bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 03:59:00	TRUE	FALSE			en-gb	03:59:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4955919b-88cf-49ca-87ea-146d0714769d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 05:20:00	TRUE	FALSE			en-gb	05:20:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9f080896-1063-4521-b6a9-6062547e58ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3f90bd3f-9119-49e6-bd6e-b13a46bf686b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7f56b1e8-c232-42d5-a871-fb6e078081dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ad318a3-8331-48b2-b496-27d93d3d48fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
56aaf172-767d-443f-8a0d-f08401d5d292	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:16:00	TRUE	FALSE			en-gb	06:16:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
aed6e105-c2ff-4f8c-bf6c-5f7240c37b47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	06/02/2023		Super todo muy bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98953c4d-6e9e-4023-8209-24fd353d97e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1b0c5863-d171-4375-b084-da01fe61001e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:02:00	TRUE	FALSE			en-gb	07:02:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b435d32e-57ef-42a9-85d4-a9f7c2b33c4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4756908b-d776-4ddf-bd05-9a9b81321a2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/02/2023		Bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f160a81-91ac-4893-aec5-88ea014a7482	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fd111c8e-f007-441c-b0eb-6ea4b7b0a87d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20f7fc1-a7c3-44a4-8713-dccf0b18ae21	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cfbe0b2e-9864-4879-911c-5d359ee5a5f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1946a26c-a6d7-40ef-b2d2-dfe2515bc7ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
136118a1-7faf-4150-afe0-2e7c881079bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4ac9b63c-3ff8-4e0c-a571-555fc2cb1f87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d0b3d1a4-bf49-47e3-9af6-bdae8ac2b989	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
30a5b9f4-888e-4d9b-b390-b0a8bdd40cc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
39a67ddc-587f-4f0b-871f-5d7802dcd18b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes	Yes							
5871ccf2-11bd-4005-81b9-50e76d3ebbb29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/02/2023		Muy limpio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d97feef2-c0c4-497d-b03a-6457be2b9fc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
429a8839-a952-459e-8625-19e5538e0539	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b26c3793-1176-482a-a6ae-b26f420cd443	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
597a6838-da21-4857-b6b0-81c967bdac15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3731a7a2-c199-47d0-ac10-0f6bcd2f8ce7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ba4cdd5-6a16-475f-abab-cf1cd2f1aa0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae402098-64e1-4d8f-a76e-91759be6a4d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/02/2023		Riquete bien
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dee5bd72-d319-48ec-82c8-c25aed5f42d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9de9a5c2-c997-457c-b9fb-9811155d4615	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8b0439ec-69de-466b-a1fa-adfe34fb248d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd6829c6-e87b-4fc1-a6e9-c8853e0cc81c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
172dd8c9-2523-4ef8-8b40-7ab87d784223	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
897903d6-1c1d-4140-b6ed-177ca4d4ab1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
dbfa43f0-c3cb-496a-860a-662dd2f50cd3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
23e420c2-c2e6-48b4-9cff-d72d3276cfb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
6831b44c-3a9c-4cc0-aafa-670f5ab44772	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
a2814fd3-6f7d-462c-9ebe-61d43bfce9b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
							Yes																					
37528d40-098b-475e-994e-27d0179bd361	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
951bc4d9-4639-4390-99e2-ac8f027865c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28a6bc19-c3a0-44cf-ab47-6e2e37935d03	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dbda39a8-6408-46ff-9702-cbc3285ff9c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
75fd893d-8cfa-4eb0-a01b-d212559e42f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
92b8e909-c2c7-4571-bf0e-26c302135205	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
6b0667c4-9687-4472-8d7e-4ed745b3b1cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6b0667c4-9687-4472-8d7e-4ed745b3b1cc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes	Yes					Yes	Yes	Yes			
b3e60904-6e90-46b0-8f21-0ea0f463d175	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/02/2023		No attendant
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
18aec471-df5e-4483-854f-66124f30ec8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7ed0900c-1d6d-4fc6-bf28-cac08d3776c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53e66f55-8a29-4497-8281-edbc8affeed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:40:00	TRUE	FALSE			en-gb	09:40:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6da28e92-2bed-490b-8629-2a29006139ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b6b20013-7ecd-4c19-931a-e1a7bbd4fe4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
03637efd-2bd1-4388-8614-f1caafe66013	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/02/2023		Bjen
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aa19265c-a8b5-4b24-bf1b-a4a95840dbae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5270259c-f635-4f80-a461-7874600b49c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
03273b09-b3b0-44f3-b06b-55781b6abb0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5463c124-fcbd-4d11-a849-3515d3836fed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:21:00	TRUE	FALSE			en-gb	10:21:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
04cb1883-4ae8-4b92-b832-358665ed4ce5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6b5ff3c-ec26-4d1e-b4eb-2e7cff4f52a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d4515a14-a70e-4ffd-ade1-bb33a80232a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cffaf645-c8ca-4b88-bb4a-52aac0e7aba1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e34287f6-351b-4ffb-ad50-db29a7ba866a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
26b72419-c53a-4150-bf08-139a992fe239	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
641a18b4-5fef-4759-8cde-0301fe935ec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dcbc5088-50a8-46a4-856c-69691d5de439	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
63fb7fa1-84e8-4350-a7c8-ef74128bf89d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f441bfb-9177-40ff-a455-5099b44298d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76de63ef-5049-430a-ba9e-c6e315323598	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
76de63ef-5049-430a-ba9e-c6e315323598	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
d820c8e0-a01f-4b71-9bb6-8ed9f8dfc1ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c49b7ea5-b2f7-493e-ad81-9ae0c130eff1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:04:00	TRUE	FALSE			en-gb	12:04:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ebc09c76-7e7f-4d15-94ce-b56034a3db57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
b534edfd-2176-432b-8927-124d01c6d84f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b534edfd-2176-432b-8927-124d01c6d84f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes				Yes	Yes	Yes	Yes	Yes	Yes				
afc88368-42bc-4315-85d4-4d348fad2b77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
675ad54e-84de-4662-972f-47183d0b0db2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9377a08f-24e2-443c-983b-02fe6faa1e5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes			Yes	Yes							
a89e4164-1366-42a7-b36d-b43f26a7c296	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1db5dddf-8634-40f9-a67b-c64daa1f56e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19b3ee48-49b2-4a74-a9d0-6d37fbb84335	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fe135e06-2392-4a6e-b199-8f70a19d04e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:30:00	TRUE	FALSE			en-gb	12:30:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da5a3c6e-86e0-421d-9254-3fce15d18b86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
10ed062f-b11e-46fa-b2fb-456a4ede46ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00a4ccc9-04af-441e-ba88-0d8435b3366c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f4210f83-48bc-4424-8b8b-928aa2875d72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9879f4f-246f-4e2b-928b-af1e07a3de5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cadde74e-e85b-4d43-868e-a01bafabfd65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	06/02/2023		Thank yyou	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab7c8f1f-a53c-4bb7-aa61-3e7482468f98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32358336-510d-40e2-a4f1-96fddb52a4d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
51ed1b6f-8c4e-4db9-b300-14f083a7915a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15349913-66bd-446f-bb8d-c8618a8a5e46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc6c54c5-b125-4fd2-9df7-07b3d7fd73f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0bc9810-6e7f-4fe7-974e-8a291055e81c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0583b83e-81f5-4c89-b731-909afb96ad33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d2258e4a-f2fd-464c-af36-ddb98da009cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb9fdbb6-f607-4e21-a09a-e0573c1c9213	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
12e30fa2-c24e-4a15-b07e-f906efae589c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f0d3b3b-9b00-49d4-a34d-7e4f6de8ed2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab9be58e-62c7-49f8-b31b-c3e5e8a0c9bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b911b5a-fe6a-4933-a32c-0c6c0013f690	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2fb420e0-3cf0-4f0b-8599-68717b0524ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4ed92e11-8804-468b-9d2e-ee2ce2f13215	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3b401472-3198-4177-81e0-893982724a16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
478c41d6-9e55-41fb-b7d4-63d01bf8b9be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	06/02/2023		Stupid	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
478c41d6-9e55-41fb-b7d4-63d01bf8b9be	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
da8e42c1-9717-4e80-b490-aa6e6f9052c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c713195-c8c3-4971-9dcb-51867eeeb9c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f0cf701a-1939-4fa8-a59a-37d046d8bb3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e5e32d92-be9b-4f96-81ef-56007fb84395	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/02/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
cac0c011-6f7b-418b-93b7-77a406d87299	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
8af2ef40-3c1e-4b17-8534-d6f49d54ec94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
fba1ee0c-dee2-42d1-ba37-d991d634b268	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
98e5df67-61f9-4101-82e1-38c6b157ccce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/02/2023		Excelente														
														How would you rate this restroom today?														
														<b>Average</b>	<b>Good</b>	<b>Poor</b>												
														Yes														
7606b971-2398-4fa0-8d25-b66001a46a35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	06/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f0ec6df9-94fb-4ffb-a015-8262234ed0de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:20:00	TRUE	FALSE			en-gb	16:20:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2c8bc076-f470-404f-9ca4-3cb54a3e5501	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
963ae383-579d-44f7-bddf-7e2fe370db68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1560b08e-de74-4b9d-bc70-cf8062bb20ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
57db1249-f07f-4ac6-a17c-a4f02012e887	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
f4d56070-a344-4374-8b54-2bb2fa5a4c12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes						Yes									
5eaceb77-839a-499e-8362-d7b27e442453	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
44626def-7247-48a0-b15a-233f378aa1c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
								Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0470d298-6bcf-40df-87db-f2f5bda27412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
581cc534-f164-47e7-ae2b-69144af4dbeb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec17838d-4909-42ae-9506-0f253487bdac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:04:00	TRUE	FALSE			en-gb	17:04:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91871b51-8f94-47e0-a0e2-4cf803328c68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:06:00	TRUE	FALSE			en-gb	17:06:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a86ecfb-7ba8-444f-9485-caab05341098	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1fe34de5-ad11-4c71-bb5b-ca4a678e1ab4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff4d8f12-7d65-436a-8d81-4c8fe7fe9291	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
709e50a0-2fb7-4801-9073-6223a51c733c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/02/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
05715aa8-917b-434f-a25d-e02c5d0a6200	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53878b5a-3626-4377-ae30-5f9c20b6a6e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a0a38f80-fbeb-47c9-a6cf-11e3872767ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
537d99b5-3adf-42e9-8c8d-906f061a92a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd978b50-a544-4bee-9cf4-8d90746a1a91	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95d439e6-7a90-4e59-b709-c7a6e4bcd646	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:03:00	TRUE	FALSE			en-gb	18:03:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7d39d3f9-3e19-40a4-93cf-0d216c6cf393	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c55d8003-66aa-4e79-a76d-72ba3da5c44e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15eec924-d397-40e1-abe1-fec5556de222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
15eec924-d397-40e1-abe1-fec5556de222	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes	Yes					
8fdf7905-6aac-4b13-b996-1c48fa5b2775	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3b6f3a1d-ccb9-4b3a-a1c7-a4b7b33fd66e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/02/2023		Paper all over the floor	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
363dc4b8-ca93-4a7d-aab6-abe07b034dcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
596b0735-31d9-47cd-b32e-cdb47d7d2ac5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0fe0c53b-b7c6-4b9d-9e47-62f567e68da3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7af4968b-7a67-4e05-a543-0739d7f03558	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b06da723-ec29-40cb-80bb-01928daa91b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8fb2f421-efa9-4fd4-81cc-3664f811bd27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
515199cb-4bf5-4b1d-8798-50b548f948fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70c52b28-f68f-4865-8a5f-dba5b129bb8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
70c52b28-f68f-4865-8a5f-dba5b129bb8f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes							
987e8020-5acc-4897-8948-c95de7200eac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/02/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
e2071f37-ce04-4def-bced-29abe181bcd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/02/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
3fb2e7c9-f977-491f-88bc-28cf0e05e568	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/02/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f899b728-0e7f-433d-bc84-5987c7778f48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/02/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e1667371-7a78-4902-8e5a-b249311554b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/02/2023		Please put a garbage in the stalls	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
f82061b3-6284-48e0-881d-36c186784253	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
25ebaf09-5a77-45c3-9269-1cc598265678	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
95c81bbc-9c48-4b70-bd3c-f4bb75073021	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
a4ccfc55-9448-4c72-a219-839b71a05dac	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:46:00	TRUE	FALSE		en-gb	19:46:00	06/02/2023														
		How would you rate this restroom today?																								
		Average	Good												Poor											
															Yes											
32f19b42-2c66-4602-94ac-bb6a4b26c2f2	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:53:00	TRUE	FALSE		en-gb	19:53:00	06/02/2023														
		How would you rate this restroom today?																								
		Average	Good												Poor											
															Yes											
bc4ffc46-dcc8-4db6-937f-8aab4a303dfe	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 19:54:00	TRUE	FALSE		en-gb	19:54:00	06/02/2023														
		How would you rate this restroom today?																								
		Average	Good												Poor											
															Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																								
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters															
			Yes						Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4680f958-a563-4337-b86c-14313359f419	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
dc316bea-5097-48eb-88b8-ffd6d6d250b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:07:00	TRUE	FALSE			en-gb	20:07:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes			Yes		Yes							
d30201cc-48c0-4c52-bd01-a90861d120a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
29186bd4-445a-442e-a701-00e4993493d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6e063dc8-e259-488c-9afb-b30353fe35b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1f3fd46f-ebbb-464e-b05e-0a8789bea70b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
658071ab-9197-434f-9099-5ba34e9743fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/02/2023		Ho	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d38261c7-b084-4c2d-9a5a-98fd9d261655	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e98b47e-8fe2-4f8a-a11f-f40d62653a20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/02/2023		Nasty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6e98b47e-8fe2-4f8a-a11f-f40d62653a20	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes				Yes				Yes					
997f78a2-3373-4bce-87a4-7a0be8e8cc0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/02/2023		It was mid couldnt **** in here tho						
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				
9b1a5c8d-abe1-4a3c-8dce-61cbccfe29a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/02/2023		No						
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				
4ff56fc0-6ad4-4037-b596-a5e01fb86fc6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	06/02/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
e58eb706-6a5c-48fb-9939-c975a8bec210	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
ca6fc6cf-da11-4e1f-8fcd-7c5bf91739ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
380cd457-1d53-4b6a-a779-758a31497b2e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
51492f89-a43a-4989-a343-3437d86c6bd8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	06/02/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes		Yes	Yes	Yes		Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dd2fe86d-a8b0-402d-8fc0-94079c45047f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
aaba120b-04c0-4f9b-bfc4-f1d655fa8163	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f9eb18db-8970-4f8b-ad5d-3b8e5ddb284e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/02/2023 23:29:00	TRUE	FALSE			en-gb	23:29:00	06/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9529970b-1c09-4761-82a7-2d4d07a719c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 00:00:00	TRUE	FALSE			en-gb	00:00:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes						Yes					
72b60011-95b5-4b46-a098-c8bdb1843676	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 00:53:00	TRUE	FALSE			en-gb	00:53:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72b60011-95b5-4b46-a098-c8bdb1843676	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes			Yes							
86e8baa0-1ac4-4ef5-b71b-24f64f46602a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 01:46:00	TRUE	FALSE			en-gb	01:46:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6d60f7ef-7e9b-4994-9d5b-0ec91ab48e23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 02:22:00	TRUE	FALSE			en-gb	02:22:00	06/03/2023		Door locks broken, hangers for bags missing	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes								
49842df6-f47b-4af5-ab35-8eb6f51ca0ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 03:30:00	TRUE	FALSE			en-gb	03:30:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2b57edd7-f5a7-4491-8388-c2fbe8d3b0d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 03:45:00	TRUE	FALSE			en-gb	03:45:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
67a0c0f3-8907-4351-87a5-0a2ad3ced410	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 03:59:00	TRUE	FALSE			en-gb	03:59:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4c4f8201-d24d-44df-ac81-f3d9a87ced71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:09:00	TRUE	FALSE			en-gb	04:09:00	06/03/2023		Good service	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f45517e3-54b0-428b-b421-9d9d5f1c9d7d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:21:00	TRUE	FALSE			en-gb	04:21:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b8d62861-4c85-4c81-acda-447644be183a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:23:00	TRUE	FALSE			en-gb	04:23:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes	Yes							
3bbab1ce-c289-4779-a098-b58d0e878cf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:44:00	TRUE	FALSE			en-gb	04:44:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
5e850c62-31cd-4293-b875-0afca596129e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 04:55:00	TRUE	FALSE			en-gb	04:55:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
0b09c4bc-af3d-4fbe-82c5-1e24c0e711e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:10:00	TRUE	FALSE			en-gb	05:10:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
53811312-3127-43a6-9e66-186acdd13f15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:18:00	TRUE	FALSE			en-gb	05:18:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
86361ce8-8bdd-4cbd-884b-ba61706f05e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
4c83a2de-1269-4815-928c-7653e8ccb0e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	06/03/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3f15539f-ed1e-49ac-94a3-628088da19db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:43:00	TRUE	FALSE			en-gb	05:43:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b36ad51-2b81-4cb8-908b-72219f1b2406	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da428b9a-41a8-4471-9a6d-0cbf4e930b6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06a5cde7-e270-4414-b0a5-7da7538c9358	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86b9ee5c-ba0f-4711-8580-1db08bcc3405	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fde438a3-bf1f-42cc-b454-dd99a6bf12c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4fa0ce3d-6bab-42d8-b900-18a8d165e807	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	06/03/2023		**** smell	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2b0b98c4-139c-49bd-8759-2429af4b7d02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:13:00	TRUE	FALSE			en-gb	07:13:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
76167a42-9085-4d64-9059-a56b17c7c429	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f2b70f2a-b2f2-41fc-a3ef-0d096c6cff4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
136a099c-5003-47b7-ab03-7a6e7e01d7f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d04663b2-1ef4-4e4f-a07f-0d63db63c9b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4b4c0de9-4fac-4ab0-8100-7a7d4b99a604	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e83cf06-077d-4b70-af72-1b64564094b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f81e4284-de6e-4dbb-8abe-d691e40c418d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d6a5386-5500-4671-838f-82efa8731965	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3ef202e6-6b9c-4db3-bbc3-d6e556529dba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
2233748f-3407-4d12-99bc-0eb083530afb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:05:00	TRUE	FALSE			en-gb	08:05:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
ad566dcf-50b8-48d3-ad38-1ed96e695854	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:05:00	TRUE	FALSE			en-gb	08:05:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
03c6677c-f29d-4278-9a5e-37cbe78acdc8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
212ea93d-57d9-4572-ac8e-2c6afd1ae6e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
212ea93d-57d9-4572-ac8e-2c6afd1ae6e1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes	Yes	Yes			
50711f83-6132-4559-8ec8-69da8802a2fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a003f9a6-f199-4f09-960a-b0ddf527329c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4ca1eb8e-77a2-4b7c-9ace-5103e053155b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:25:00	TRUE	FALSE			en-gb	08:25:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
76c83c27-62d5-4d85-ac9f-dc52f5ff2471	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
298a2cea-06b8-4ce7-813c-06a3e11a0930	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6973238-595f-4b5e-a601-3991f215114a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b72e60f2-c40a-49b5-99dd-68307ec7ed78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e1dd92ac-bd13-4639-a573-79b060fb485a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8c9350a-69e4-48bb-95e3-46e163d66379	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/03/2023		Hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
a61e797f-b7bf-44fb-8fdf-f67426965859	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
262536b1-6686-4cdb-9363-0fb54e77b134	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10c334ce-c93a-4884-abe2-029eba2ab774	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9fe38e96-c63c-467f-8741-8751ceb75a02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f955da85-02f2-4cc9-beee-96fef982bd2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0bd9116b-52a5-417a-986d-647f01c43985	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
193ec128-0a42-432c-95f5-813c64b45fa0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9f052686-de30-424a-a302-4d7bd8d3efc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7f53fece-d72d-40d5-9673-a7ea2fccd60a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
433e284a-0154-4e67-af54-e0305648db2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f655d9d9-e369-4d52-a7a2-059bab91c944	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
199931f1-e49f-4e81-84c3-aa72c04ea487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
39619e81-d044-4d60-8ed8-fc6bff99a967	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	06/03/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39619e81-d044-4d60-8ed8-fc6bff99a967	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
85108ff2-a245-4361-a4d3-db72e673e5b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/03/2023		Sucuo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7e15ea02-f4c0-46d9-ba31-ab6bdbde4662	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/03/2023		Gross	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes			Yes							
3be4f20e-0b05-4f85-81b6-17c0a40fa2f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3a0067ef-413f-4bdd-a97b-9661edb0d9ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
58900496-2887-47e6-8776-686f6d69d0f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/03/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
b6b4611d-f50f-42d8-8feb-c1eff6047d3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
479b5f82-ba39-489f-b442-6677095126ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a925be2b-0bce-481e-8d71-811af4a6dc5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7f5c856e-0816-4602-aefc-9813deb4b9d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cb49ecf0-cd8d-4a83-81d6-4ac33d3978d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fbd93d6b-9d01-4ee1-842d-6897c2c770c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a6c9d3ab-531e-474c-8f6d-4e74d8baa727	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
676fb301-52f8-4e2a-b75e-362112fa8004	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8b6f3c0a-2e48-430e-b357-c2e8bfc78a2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2f0e6aa1-e859-4597-b668-2664affd33e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
afdb34d2-85c9-4a14-8075-ad5a061bc54a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f907b058-3148-4447-9c36-81bfeae785cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
200722f6-3aee-45a1-a4f5-9d3209888454	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ec6152d6-11d9-4033-9e5a-5705195f1705	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99e3475c-d91d-46e2-81d7-a59ec4a0a000	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d2c36116-b235-4743-9ffb-f547e8b5d95c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
de1b0d04-f22b-492f-a367-920089f49282	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5e017e1f-f905-4e63-a92e-6415894acd20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/03/2023		Nice and clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c60a3127-efc2-42b2-9136-957f2f13061d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/03/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5a162369-3b14-4a7f-ac9b-6f201575a8b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes		Yes					
cd25c5da-75cf-4860-95a0-9d2d8ce94b28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9ef6edb-774f-4ef0-bbef-c03fad75ca9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:17:00	TRUE	FALSE			en-gb	12:17:00	06/03/2023		Muy sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f2478e7c-3588-41ee-9d40-2a7cb57cbfb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	06/03/2023		Should be a clean example of who we are bad expression	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2478e7c-3588-41ee-9d40-2a7cb57cbfb1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes			Yes			Yes					
5a5fa993-a654-43e7-81ef-1118d46ba794	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
31b3907a-d4e4-4c3f-9687-e4abd92eaf51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
00c3d050-ae71-45be-af30-5796b83c53cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6cf8d8b5-f971-425f-8438-116dd6cb89e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2f30dbc-1501-4067-a483-7c9698bbd892	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a383c38-e78c-4041-a766-c6a8db098711	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5ca2aeaf-fabd-4194-82cd-926685078a9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
703f7955-84cf-4a54-be38-e0b3073d46a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae29350f-ba56-4841-bee2-63d161e5e582	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
33a4b809-5cea-4fa9-ade6-e8fc3350820a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8e81d4bc-137f-4351-b06e-a27de584a73c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb804493-03ac-435e-90d0-32eaea60664d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4787b4a0-bc66-453c-befe-7322cfe28ae6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b983881b-57cf-40a0-96ff-28d6bc0ef60c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
49bec92a-ddd9-4f33-b9a1-19e829c88644	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae29d4ea-8646-449b-ac26-3de395947bc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba9372f3-57b0-4568-86b0-e8c54e9be802	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
853c9539-42e0-4f90-9c36-603a67f96ac6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d55fa641-16bb-4b07-afe9-ee624015dfae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f3197d46-42ad-47c7-870d-c90f1d938d13	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
263e8638-7e85-4cbe-b069-cf0471706eff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b44b70fc-c9df-403c-ad93-84c9fbfd9319	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0f8a3144-60bf-4ee3-b13b-c3c4d3cb0189	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d07d1d-f826-4caa-ba76-408bf84bbcb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
595f5013-aeaf-406b-a209-9cd3166112ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b9832e8-3876-40a8-84e4-106831071797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:28:00	TRUE	FALSE			en-gb	13:28:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81ea26ad-0a13-47f3-ace4-1025e34ffeb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
881786a7-5456-4997-aac7-34db49fd25f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/03/2023		Xzabbvbbvvgb bbb'hhhhhhvfgvv vvvv'hhhhddddd dbkkkkkkkkknjjjj jjjjkkkkkkkrkc. V
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4de2b75-b0ef-40ee-9d59-294d5737f19e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:04:00	TRUE	FALSE			en-gb	14:04:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25bb0600-4154-4337-b036-e370cd033cc0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26619bb5-575f-4163-abe8-130092ec4dbf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/03/2023		Happy
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1cb5261a-6084-4b49-bf44-f99add28a3fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1cb5261a-6084-4b49-bf44-f99add28a3fb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
5fdb469-7ef9-4a5d-a82d-568f506f8e08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
97dab606-fb73-4b7f-bc19-2c069d354fec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bc2384e7-3b0a-4050-9683-2f775cfcbea7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
f1e3be9e-5401-4fc4-8c87-13487604a370	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f1e3be9e-5401-4fc4-8c87-13487604a370	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
077430e7-6e47-4d64-b1b1-d3d659da137a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
32ae4a80-5039-4aef-ae4f-244faaa2d0a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
3639c5af-377e-47a9-9825-5a229d7a13fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 14:46:00	TRUE	FALSE			en-gb	14:46:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
51e58914-6e4e-45f1-b8cb-4dff8a8c292c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
51e58914-6e4e-45f1-b8cb-4dff8a8c292c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											
0aaf9aaa-d9ec-40a2-8467-2edda41614ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
70bc351a-81a5-4bf8-91d0-d3bdfade47d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
efd59a40-deed-4596-a532-776ab2ad9eb6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b3cb91f7-adf4-416b-b18f-fc682af1ef92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7a1bc8f7-cab3-4ee8-b4f2-1fbd5a5b69f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e7d02e35-9e29-44fd-85b4-5b6b6b6931e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3369b4e4-61e3-408b-abf3-38d8b19c6874	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
454ac1c8-47fe-4019-bd5a-9e00f596cccd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/03/2023		****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
72151088-c349-4fc0-b670-55a7a0b2978c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
72151088-c349-4fc0-b670-55a7a0b2978c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes								Yes			
06b9339a-47ba-481d-a63a-76702cfcfa32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
122d0ba5-4c48-47ed-b5ea-a563033af00f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/03/2023		Todo limpio gracias
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1857a60b-3816-4418-8e00-90b99f1478ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74e9d91d-c5d6-4102-8d94-0ba5dad4504	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d21c89fc-d5a3-45ec-869f-71c1aa0ed50b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/03/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
44afa9b3-cb8e-40e9-8b15-cfddfa8c706c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ef125002-f42d-4935-861c-fbfc63987a9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d05f631-b5f5-495a-92fc-6ddd95a81d67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6fa9004f-2d5e-49a6-bf95-1ce2188ec20e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
17eb85ae-f3a3-4a33-8b5e-a9f98b2c40fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:24:00	TRUE	FALSE			en-gb	17:24:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f74de0ae-baa5-404c-bc28-0d92561ede3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
183da570-0807-412e-883a-60d7404fc30a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b4b833f2-6bde-4651-9a7a-6b6c9644f79e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:34:00	TRUE	FALSE			en-gb	17:34:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6f3c8a35-d49d-45ad-938e-a95c1314f76d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:42:00	TRUE	FALSE			en-gb	17:42:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
384fd5b0-ec78-4d00-b5e8-ac4b711489b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/03/2023		No					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes		Yes		Yes		Yes						Yes					
7d386f76-82c8-4ae9-a57d-f860d1c2f93a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/03/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes		Yes		Yes		Yes								Yes		Yes			
9b35f0da-ba9c-4238-ae5f-58612f73db57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/03/2023		No					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes												Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
07c9c252-9f0d-46f0-bd67-3291d5401283	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
65190e55-0563-4e0f-8278-fc75da7e5349	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8aaac5ec-88af-4db2-9e4c-61e3ca71b9f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
					Yes			Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fad612d6-570c-4f09-89f8-d02cc81ae0c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e330b1ed-3473-4e92-a121-bc6620682697	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
590749e9-4a75-48e4-a75b-8ad23db10934	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
0b91ad93-edfe-4bb0-803b-0972bf0818b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
de54137b-f8b7-4dcf-bde7-a62ba1258486	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/03/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c7baa012-4216-4848-8495-51afbcb06914	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/03/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
72506c50-127f-436b-bdd9-6f47e9e6419e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/03/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
482b412f-7992-4582-b1de-e3cc5d56f7da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/03/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
d3005a5e-8adf-45ce-9e53-1660277d8de7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/03/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
4fd51d2-4421-491b-8ebc-9fa26db796ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/03/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e21e6a46-f83c-471d-8bf4-84d9b2ca1837	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f917fe3-4ee8-4c95-ae4e-5518d659be8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
f24ae39d-dc76-44e2-b1c7-e1ca7d0a0e79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e8a68179-cfbc-4465-8a25-fe92690fd27c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/03/2023		It looks very poorly maintained and the smell is very strong	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes	Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dad28fc-c394-4dbb-a78d-40db69bbee9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
452dbf59-6849-4651-84d6-0918d4af58d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:04:00	TRUE	FALSE			en-gb	20:04:00	06/03/2023		No soap	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
3028db14-a5c3-429e-add3-5af697231764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
ad70b0fb-def5-435a-9717-a662298b03c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
06405789-4895-41f5-b931-5e236c0d626d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:24:00	TRUE	FALSE			en-gb	20:24:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3e0d1032-6aca-412a-a542-cef7f5822097	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0640bbb-bc5c-4d59-871e-1335e9f32b0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:29:00	TRUE	FALSE			en-gb	21:29:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd69bc0d-a7c1-4974-92ee-32b4cb54f10c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50ee0a50-f103-447a-be57-a0c713dd1c72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5b1a0709-a36f-4ded-acad-56458a6d4053	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	06/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dbf9cc3b-f05c-4474-b361-34cb541ae05b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c210db9e-437d-489d-af88-c6bd38e879a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:57:00	TRUE	FALSE			en-gb	21:57:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
017ee91d-04be-483d-a981-85a1eb4e3d36	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 21:58:00	TRUE	FALSE			en-gb	21:58:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
49c559be-8660-497d-bc0f-4d23f22fc023	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:07:00	TRUE	FALSE			en-gb	22:07:00	06/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cfb28af2-ac6a-4b55-af11-aca305b55a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3b55a805-abcc-4488-9073-74491645d322	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:17:00	TRUE	FALSE			en-gb	22:17:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes				Yes	Yes	Yes				
7f78c9de-1e89-4f86-ab75-eadaeb791faf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes			Yes				Yes						
9c9ce679-918d-4adc-b149-df58ff7afc8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:23:00	TRUE	FALSE			en-gb	22:23:00	06/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6297eac7-f3a0-4e78-b185-c97136a1ce0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:26:00	TRUE	FALSE			en-gb	22:26:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes								
6fe9a4dd-a53b-4875-bbd0-f356e24e0f4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:40:00	TRUE	FALSE			en-gb	22:40:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes			Yes				Yes	Yes							
6a5d56b6-82e3-4612-9274-b55c9cd87455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
65444b44-b43c-46e4-9d06-1734e6c8beba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
b6812b08-eb35-4111-b2f4-31dc1d43e3e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:48:00	TRUE	FALSE			en-gb	22:48:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
a072820e-be27-44b5-b93d-b0ab169e90a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:52:00	TRUE	FALSE			en-gb	22:52:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
b4fcad2e-60ee-44fd-9fd2-13d4fb91e51b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:53:00	TRUE	FALSE			en-gb	22:53:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
3668e079-df87-4442-9448-70224b6d0256	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 22:59:00	TRUE	FALSE			en-gb	22:59:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
98d0417e-6acb-4216-bf45-7a2f64b2231b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 23:03:00	TRUE	FALSE			en-gb	23:03:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
d3cd21c5-c652-4302-b6af-b4c39fc20eba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 23:28:00	TRUE	FALSE			en-gb	23:28:00	06/03/2023		Excellent														
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
7f763259-311f-42e0-9520-753d6e9633f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/03/2023 23:31:00	TRUE	FALSE			en-gb	23:31:00	06/03/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
f32fc82d-b286-43bd-aa9f-42c0b553b335	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 00:05:00	TRUE	FALSE			en-gb	00:05:00	06/04/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
1f671866-f66a-4c00-a8d7-36b3e586ed58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 00:33:00	TRUE	FALSE			en-gb	00:33:00	06/04/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1f671866-f66a-4c00-a8d7-36b3e586ed58	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
															Yes					
6476ca1c-bf6f-4c59-81ca-6def11df69c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 03:08:00	TRUE	FALSE			en-gb	03:08:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f4e97eeb-9707-4689-814f-dc5086278883	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 04:47:00	TRUE	FALSE			en-gb	04:47:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f549d627-77dd-4932-8e0c-981dbecf38ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 05:15:00	TRUE	FALSE			en-gb	05:15:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed9d9931-31fb-43ba-baf6-3d2e4baaecf4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 05:36:00	TRUE	FALSE			en-gb	05:36:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
44cbec5d-d169-49b9-bdb9-e2dfc189df53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
626681f7-ffd1-4ecb-a338-b6f2ae21b97f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
58879af8-1e36-4d45-93b7-33daad156fc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4145d1eb-60c6-4725-81c2-f676ea22ac5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
590970c0-93de-4b18-8478-a9833eb315	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
72d5a4b8-7124-4893-b9c4-b5546755d581	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	06/04/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
effade18-663f-40c0-aea7-8faffdc7e31b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8bce5386-97c1-436c-86d3-710fa551f3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b08b604e-3d86-4f37-b5ae-4e8e5de4272c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
384f6d42-529e-48ed-be71-d74305eedae9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b967b7e7-e67f-41cc-8ca5-0fa2cb39fdf7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7e4708b-1734-4c1f-8b2b-8145c4f29145	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
48148c98-140c-42d1-9fa1-fc0a49f257bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0066f70-f984-43bf-86c1-b64147f2219a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6ee12d8c-38df-496b-bd25-cdfd2bf878f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5be30c7d-a706-4f6e-a983-582db738a54a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cd99ff00-538d-4cfd-aaff-9e2cbc82114e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6f7477e3-4c00-4f0b-b9cf-54a756a76082	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:17:00	TRUE	FALSE			en-gb	08:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes	Yes	Yes					
788fa968-0da3-46ac-8681-edb9b3bc4c33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	06/04/2023		Sucio y prstoso	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d2cdae52-feb8-4fdc-acad-3ae678423271	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d39c0ad-ec22-47a2-b181-777d248ed740	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea6a9338-0cc0-4f31-aa4a-53199971cf87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
13343c89-d3cf-4b41-9a4d-01391f6119ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b0c4fd7a-20ac-4642-89c1-7e8c2315ba6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
743d1fee-f7c2-4951-8525-4e00cccaa1f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
16791b35-5c5c-4631-a450-f79a0a4d0f22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0bf24ba-47af-4ee5-833a-6de930a86354	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f8b581fc-6af1-4e44-9f15-87faf7eccf1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2f89bc61-7e0e-4a79-b47c-55c88a0c273c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4aa66cac-1eeb-4414-92e6-9df8b46d19b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b9eaf455-58fb-42df-ad3e-8e47faf6799a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1e3e3344-d493-4ea6-8766-21110af858aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
913d79e6-a23f-4762-9a34-f01392cb7f27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0427a4b9-4570-46e2-8b90-8083c1805944	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7df01ce6-6f25-41ba-b683-be0b526eacdb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0a75a0f9-aa38-4cbc-aafe-b0a9f251a5b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b3c27427-614a-4d1b-aba1-a8cf4f8dd89e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
046d8381-48d4-4674-9d07-081dfa901b2e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9014b703-27f7-4465-b786-ee3a8ecfceb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9da30e2e-f5d3-4ab1-9e2a-89f9e7c1b0b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d7c043e-1a60-4238-b0f3-20e6488b5797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e8be859d-76e2-47e1-8214-188ae6077b84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e27cf62-e72f-466a-882f-163033d116b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dca15930-57c4-480b-9746-3cec02e490c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
06261679-ae3a-40f8-b734-d4ded3b72da5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9137415c-f1ab-426a-b40f-39488c6b2f25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fc141c3e-2840-4f8f-b76d-85988f66b5d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
ca1c48ce-4277-4e7e-aae9-aa331ae578fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	06/04/2023		Puerco														
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										
528be483-b54f-4be8-844b-6898dada46a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
78011e74-f243-4eff-b945-11b85f7325b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
823ca315-0112-4d50-93ac-1a84d8ad4689	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
															Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
	Yes						Yes																					
4e74a85a-1528-4e8b-bac4-1733b51d2882	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/04/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes																										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4e74a85a-1528-4e8b-bac4-1733b51d2882	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes						
db8204c3-c844-4b8a-9a57-26a40bf65ce4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
03355717-70f5-452d-84de-fea4e2030762	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
cadec6ca-01cf-42a6-a5e0-3497742d8f46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3b396023-8ba7-45c8-823e-116ade878e1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3b396023-8ba7-45c8-823e-116ade878e1e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes													
46c86d24-2c0a-49cd-afa3-1ab6ab074afc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
77c35e05-6727-4bf0-a802-f27e9e7de741	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1844bd25-bd52-49de-9697-769e545c9158	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
95bc082d-d16c-4af3-ba27-3052363e25cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
124c06dd-a04f-4cf8-a7d8-dfa170f47a93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a425ad7-4028-4ca9-8a9f-eb276d8e472a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
e3c723c9-5d88-4e61-bbf3-f443b3e220ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
5bdb13f8-ca37-4e09-b8d4-968615b27011	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	06/04/2023		Uhuuuu
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5bdb13f8-ca37-4e09-b8d4-968615b27011	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes	Yes		Yes	Yes	Yes	Yes			
49335c2c-0964-4f75-a147-296f1e6ac4da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/04/2023		Dated
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
62932986-db2e-4a8f-8604-fa66fc628826	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cafb2f19-aea5-41a4-9449-ef76772ef82e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
521c470e-f9bd-4d59-bea1-7da0d81aae98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f91dca55-c80f-4db6-9d33-bbe632a144f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
30074872-ef67-4ba6-8de7-ecb921755c11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ff1315c-0177-4d3a-9210-df6b559227c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3a65c464-c423-4549-8741-5e1ca94d5278	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes		Yes					
cc38c210-72a6-4410-ac35-de78be3b77d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cc38c210-72a6-4410-ac35-de78be3b77d4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				
1032efd7-bba5-49ae-80cb-64236c17fe6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/04/2023		Bnhhhh	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b944d93-24c3-4410-91ad-c5e88cb91324	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6a905aba-fa0b-421a-8e77-badc13927c55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/04/2023		Got yhw p	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc6f6242-657c-4b4b-b12f-d1486926a1ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:17:00	TRUE	FALSE			en-gb	12:17:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
245121c3-e085-41ba-9ffe-3fc2cb77bdba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc6c1d57-9a22-4e19-af5d-ce3b5bfbaed6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c2aad285-fe9b-4570-9f5b-728c8c627b95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f5fec93-916e-4e9f-a9dd-9bd6b8bc9c63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
4f5fec93-916e-4e9f-a9dd-9bd6b8bc9c63	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes												Yes					
42416d66-c969-40bb-8862-f1bc3e425802	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
738b924e-6c1e-4496-b91f-249d83699465	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
25ed8f4a-5bbf-4e67-8c5f-885050dbc46b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
5e258313-fc9f-4948-a17f-b2a7fadfa7f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
3638377f-a3de-46ec-823b-1d49df340633	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1da5b2c9-ca4b-41a6-88d1-b702dc9052b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1c7491db-a030-4ef6-849a-30ba9a348a1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8183b5d6-7d27-4fde-9e58-16d776d23bcc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2d7ed8ce-0d96-4acf-9569-784a135ddccd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7fce5bf8-585e-48b5-b7af-68012084b543	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
335a6199-2b6a-4552-8e4b-0b09d4a93037	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/04/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
78ed22c0-11b1-406d-821b-91bbb71b4cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:29:00	TRUE	FALSE			en-gb	13:29:00	06/04/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
21c9818f-b3ad-4ea1-b0e8-a08f810f5604	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/04/2023		Smell so bad		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
						Yes										
9aba1857-5324-4a74-a445-06e5a629e996	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	06/04/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
106965b8-f3cb-4da5-94f9-f263c6c816f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
68636ef5-46ac-49f4-80d1-4e6620027c0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
0f950f5e-2467-4305-afd2-0ff6b8298f3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes		Yes	Yes		Yes	Yes					
3f31c27d-64d8-4bb2-a3b4-5f9fc457eb98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3f31c27d-64d8-4bb2-a3b4-5f9fc457eb98	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes					
d121faf7-d0e8-48fa-9540-7d62e782d4b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/04/2023		Sucio todo
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes						
910ce198-34bf-4713-8c97-f859ed64cc3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:05:00	TRUE	FALSE			en-gb	14:05:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes	Yes						
c6c841a5-b2d9-449b-88b8-67c04b9e7c39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c6c841a5-b2d9-449b-88b8-67c04b9e7c39	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
50a6e17c-fc7a-4587-83be-b23915c9d0c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
49c43b44-49ff-44ed-9cf8-adedc4c0f283c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9a0bd211-0bf9-4300-8aa7-f311cad718f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/04/2023		lck
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9a0bd211-0bf9-4300-8aa7-f311cad718f7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes							Yes	Yes	Yes				
316eb9df-85e5-4422-8e88-bef627e83de6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1bc335b8-65dc-42fb-a3c3-e95518f79793	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes	Yes				Yes	Yes	Yes					
c0298783-b0bf-40bc-a67c-a2423b3820ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:46:00	TRUE	FALSE			en-gb	14:46:00	06/04/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cdb6a7b-d200-43a2-8b86-5de2f231acd3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0903403c-48e4-4aee-8f27-97a55cd273cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b47f890-493d-4ca5-bb52-724651d6f4e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
de6bd58b-eb21-45fc-83be-4dfd7ed99cb5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes					Yes								
30e3dc21-a6cf-427f-876d-0a126316f438	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5a08c0f1-6ab2-4a22-9df1-b2dbb441df37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22b2da86-0692-4961-9220-5edecb5e1190	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ffe0acad-cfbd-4f3c-857f-309dec629b0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01b13565-b11c-40c0-95e1-2a10d298e270	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/04/2023		Muy limpio el bano
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9d343c1-6758-46e6-a5b8-c5477cc5dc08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9946ca91-6612-4eeb-b272-e3dbd22f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9946ca91-6612-4eeb-b272-e3dbdde22f3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes	Yes					
141822bd-3d71-4ebf-bb4c-0287e9b22789	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
d0081cf3-0ad0-4580-9ae3-f2376f774d14	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
d2a8f47f-704e-4cd6-87ec-3b117d9ff455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
190600a2-3680-431e-b0ce-7f183a128f08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/04/2023		Stinky	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5be4833a-f602-44a0-aff9-9fab61a737c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e0f6d16c-f124-480f-938c-bb1a4e949ec2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
11413670-cb61-4ee3-a782-131362c2d292	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a313eb0d-a808-4bd1-9925-1c4eac204d97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0ac1f76f-8b18-49ac-83cc-6342eefeca46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6a95cce3-bb63-4916-8ea5-7be3b4ef8b5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5091e72d-f634-42f9-8d04-4d8aa8425749	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3decb292-d7fe-4c81-94cc-707f81664c0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8415fcff-7dce-4008-93e8-5035129f74af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:07:00	TRUE	FALSE			en-gb	17:07:00	06/04/2023		Dirty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0d91b915-8cc2-43d0-ace7-e63fb4c26d88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
caafd456-54c4-41b3-b5de-52a7e84d71bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:20:00	TRUE	FALSE			en-gb	17:20:00	06/04/2023		Gross	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes	Yes						
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
18258b2d-ed4b-4471-8f74-05beec784b50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
dbd48066-fb10-4c49-b41e-be0aa46c2e65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
19376ada-dd1f-46c9-b380-42fb0eacd289	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/04/2023		Fantastic	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
661c8f73-018e-4b7f-b123-586a14179633	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
661c8f73-018e-4b7f-b123-586a14179633	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e7e8fb87-e069-47fa-ac56-2c6eced8ff8a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8b258a1-f2ac-4a76-a9a6-adeeabf7d2a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ae37ff0-c258-4605-a414-239263381323	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
83466dd3-3c12-4892-9d24-e135d7cd72fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
75996349-11a8-4efb-9bb2-809d63fd840d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b00fc9d-879f-47ff-ac80-0a3e5cd5abb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
c99cb21a-81e5-4651-afaa-a64e6deeb4ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
531d49bc-9a63-4a1d-8a86-cfda2faa74f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7365fcee-1ae4-4322-a016-421151f4b7fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7365fcee-1ae4-4322-a016-421151f4b7fe	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes	Yes				
68e2386e-76ea-4196-986b-682dc033ee72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b85115d9-8ca2-4aa6-9fae-9bd1dd330b18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
97223673-dffb-4dfa-b5bd-cfc9ce3047b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a90d482e-b30a-4c5d-8aea-f174b0741d55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d51a2578-96a2-47fc-a1e0-312e07d1087d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	06/04/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5f0ffc96-1fc6-4457-a7ce-06699eff5b0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/04/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f0c81855-fd38-4de9-96c8-6bdfa5c6f9ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
adf20440-49e1-4ac8-9c04-b727ecefba02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:38:00	TRUE	FALSE			en-gb	19:38:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2427315b-885b-4d54-9701-17a517143712	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f560577-9a4b-4d04-a5ef-2e187e9d460f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
63029ec2-8ea7-4b36-905a-ee4c442db007	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:49:00	TRUE	FALSE			en-gb	19:49:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
da316b2f-689b-4435-813e-70f36e89192d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	06/04/2023		,jhggnj	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e844c954-d079-43c3-a3f8-26d32e03548e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2d155158-1252-44ee-9228-8e65257c589d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2617c672-2224-4ac3-9c3a-b4da1cf1fcb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes	Yes	Yes					
c45abc4e-49fc-4792-83bb-5ba7f5394b27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c45abc4e-49fc-4792-83bb-5ba7f5394b27	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes														Yes		Yes	
9ff61ce7-4b22-4197-b719-3a4187d638b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/04/2023		This bathroom stinks really bad						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes				Yes								Yes		Yes		Yes		
8d9bfb79-d150-4bb7-9b8a-3d8f3d14fcdb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes																		
e45e64b9-ecdd-485c-a8e4-42adfc45b30f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes																		
15f577d6-0b6d-4099-bafc-bb2040a2ba31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/04/2023		Ok						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f42aed3d-756b-45c8-adc5-4b76ebdb8fa4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 20:56:00	TRUE	FALSE			en-gb	20:56:00	06/04/2023		Horrible	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c5776873-b1e6-4163-a167-a33a8fa7fc51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:14:00	TRUE	FALSE			en-gb	21:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
2f066bf5-4e24-4d25-84c3-10f50d004fbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a778cc84-354f-4ad9-a973-277ec568056e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e6b59ba2-3504-4301-8e45-9aad8c562d39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e4022401-d409-4844-8092-dbabaafcd438	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e8c26626-49f3-46ad-ad10-33b2b300e2aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Of1968ad-6a98-4da9-94c6-4b34793d6fb6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes					Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2335e7ef-2833-45da-bfb1-e74a3358aa78	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ee92a85-7e4a-412d-b9e8-64af86aeaa92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cebe891-dcc6-4f53-9266-8c6feb2011a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
09e86aa9-1488-4804-8faf-07d9877c83d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
782e451e-87f9-42d8-81df-f79c5fa1a4e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:57:00	TRUE	FALSE			en-gb	21:57:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ab49a85-cafb-4d5f-bb1e-a032c6044ef4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:58:00	TRUE	FALSE			en-gb	21:58:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
04b6e50a-6309-42b2-bc6c-04e8ee53e9c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
af9bcf51-1eae-43fe-98bc-43ef1ed56349	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e7df6993-aad5-4618-b985-bc08e89161df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
3ce6ab41-8bd6-4140-8a17-cf7f8330c6ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	06/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b623a23e-f847-404e-a0fc-c890d0e49696	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:08:00	TRUE	FALSE			en-gb	22:08:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9ca11c79-9240-4702-bb1b-64449d854c65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
233ae0fe-d60e-4a15-b28c-615a99e76988	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e71da7ee-722f-4be1-b816-5e5d88d5cf4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:24:00	TRUE	FALSE			en-gb	22:24:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
24840675-0c3d-4537-a408-75aba4610a79	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:32:00	TRUE	FALSE			en-gb	22:32:00	06/04/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
24840675-0c3d-4537-a408-75aba4610a79	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
e444e95b-d303-4edb-b57f-4165db071c8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 22:59:00	TRUE	FALSE			en-gb	22:59:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes		Yes					
0d97dccc-e933-4b40-88c7-8a503f1766a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 23:22:00	TRUE	FALSE			en-gb	23:22:00	06/04/2023		Bueno	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
fbcca1d0-ba30-4240-9690-3bbfd6b6b5f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/04/2023 23:35:00	TRUE	FALSE			en-gb	23:35:00	06/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
2f7936af-747e-4c98-9545-585e8b68aff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 00:27:00	TRUE	FALSE			en-gb	00:27:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc0cef64-00c7-49cd-b673-c97666feed94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 01:09:00	TRUE	FALSE			en-gb	01:09:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bd3cb9d-3711-4321-a938-11a838b5317e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:03:00	TRUE	FALSE			en-gb	02:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
294057d1-b0e1-4558-94cb-b2c87799099c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:11:00	TRUE	FALSE			en-gb	02:11:00	06/05/2023		Very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6c8edd2a-1050-4974-ab47-2281d743d42d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:12:00	TRUE	FALSE			en-gb	02:12:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
19ee92a2-f6a2-43ee-aa5b-a06bdd3ca892	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 02:18:00	TRUE	FALSE			en-gb	02:18:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be468fa9-7f53-4204-a0ae-f8bc7fc7c00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
be468fa9-7f53-4204-a0ae-f8bc7fc7c00	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
											Yes									
19071ad7-b0b8-4584-918b-09755f9e89ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:33:00	TRUE	FALSE			en-gb	05:33:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
48450c4f-ce13-4e89-86ae-1c71f34d011e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:34:00	TRUE	FALSE			en-gb	05:34:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d01a64cb-ba2b-4a99-b5a3-059370d50030	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:34:00	TRUE	FALSE			en-gb	05:34:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
438f473e-626b-4375-89e1-fa51aaa57c3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 05:41:00	TRUE	FALSE			en-gb	05:41:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
236829a9-3b2c-4b71-bd19-eae68be81575	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:01:00	TRUE	FALSE			en-gb	06:01:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ef5b705-9f3b-439e-9743-717f0b128540	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cddbdc49-c972-4cf4-ae5a-ee5e1aa49149	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/05/2023		:)
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ac486296-3acd-401f-9c81-0568e10e6b84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:20:00	TRUE	FALSE			en-gb	06:20:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7f23740-1e99-4f1c-91c8-b1a660b83aa6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:28:00	TRUE	FALSE			en-gb	06:28:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4d9bca8f-21e3-47b0-9418-72d5694a4fea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	06/05/2023		It was soo good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0f354925-747f-4d9f-9510-2745a8ce4870	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/05/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ca28f622-25c1-4c17-97f2-b6dd1462ba44	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
840f309c-5faf-4ef1-ac04-38c5c69044fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
64a87ec4-f685-465f-a01e-143fe0f9edea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db79fada-4b27-40d6-8c66-1deaa44b4aa9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6ad26428-d6d1-4932-a21e-188e0863ec60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
183b66bd-1e67-4509-b5af-31f311a22de7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
183b66bd-1e67-4509-b5af-31f311a22de7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
717124c0-f4c5-4d5a-8f92-6a1c0724bd85	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a2952900-52d9-4013-b2b6-edf35d373752	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
43bca287-4ef1-4e09-b0cb-2577da1e4782	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8f84b02e-2666-4d7c-931f-0ad45b32e5ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
96613d46-cd5e-406f-b352-69a86be46a01	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1c61aae-2e0d-47ca-9d3b-8fd2c699608b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e97610b7-3a8a-4edf-b4e0-3b5a39e99dc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea94a2ad-6ad9-4213-9c42-fcec60615621	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3b3db931-61d3-4700-a790-c16602f3d0b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c58a3f6a-f3de-4fca-bb6c-ed8fb15a7b89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/05/2023		Clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6c410dbe-d601-47b8-8aca-a9d74e37cf46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
885f1003-111d-470b-a694-b12cd1bae222	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0a521180-f40a-4d39-9b7d-caa8e8946b5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/05/2023		Sucio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
8fe8f058-bddc-4316-9e01-6d8e2bf0dbc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
033a0139-1465-4d0b-af58-8437a857863a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b1fb7b4-8c02-49f3-a86f-716c02ef40bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1bffbec0-4c21-4026-933f-d5e3f2041c3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/05/2023		Clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9625897a-39d2-4d72-9c12-4a9dc1d391a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f18e1ec4-cce5-471f-b365-3c095f44ba6c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f9397ae4-2c33-4aab-abef-eec8d98fcbbf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e1105f8-42ce-48aa-96af-040b422618dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:20:00	TRUE	FALSE			en-gb	08:20:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3bd45eee-e945-4284-8f31-e4e5c44564c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c1dfa33-6987-4869-a25b-0bdf6359fb07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c030fe2-8127-4a68-93d0-c203dd62ade8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes			Yes		Yes		Yes					
7bf2d19f-ab80-4a03-883e-ee293fb29791	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d378bdac-abc9-4dc9-adca-d6b7a1b72e51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be92c385-1267-4b82-bbac-308341656acf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1cacfd6f-2ef7-448b-9b69-26804503aabe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
67942b30-ba34-4e27-949b-dcd43f43febe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e90b642a-c7a8-4da4-8052-2e5234225933	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9311aaf4-88c5-411f-b347-846ffbcf5502	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c918876f-b242-421c-af29-7bbaea4d6032	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c918876f-b242-421c-af29-7bbaea4d6032	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes				Yes		Yes				
5412cb06-3892-49ff-bf57-d83584f1eec7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
300fe02d-9890-49dc-bc26-a5d145f8dd95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2cd31d6e-e54c-42ac-91a7-6d43ee48c44a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/05/2023		"	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes	Yes										
b84e78c3-ff8e-41ac-90db-40ca516df3b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b84e78c3-ff8e-41ac-90db-40ca516df3b3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes					Yes		Yes			
68391390-4e1d-43a0-b389-017bbe214388	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6307790a-733b-4353-8e65-eb46b8c88546	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
91fdb98d-ab73-4977-a1ba-8a710798a101	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
767d44ec-3eb5-4f68-8c64-59b69d5ba0ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5309cb86-c402-493c-b4b3-d9f279f2f4d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
037e6617-e5dd-4f36-b08a-0fff6942e959	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f23c5d65-faf6-4ffe-bb46-59e9208e8c60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9bcded65-efb2-4426-9da9-ca510ca9179a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a95f0d75-52f8-4393-94be-af18c4b6c23e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2edc3e5b-04b5-448a-a68e-5779e713481f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
185eced6-ff47-4dd9-a9d5-9f73429cf866	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													





### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4b27c42c-76cb-4104-9536-5b680fa4bf6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
513d0faf-591f-4ffd-95c3-1d36a45f3a9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28c6d240-7cf7-44b2-bf07-29656744da83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44b36605-c214-4918-bac0-a671559d6eef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5b6447bd-4589-4e3a-9e82-f2c32a865c41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3cdfc989-6166-4ea7-83de-087e1c56b10a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f08bb365-0dc6-438b-be45-81a8e5d1b194	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40aceb40-9552-4a53-b47e-492e1caed358	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c1b4fc1d-e171-4639-9802-4bd6bbe4cc11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	06/05/2023		Disgusting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							
2222385-afeb-4bb9-a361-57218f883439	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3d92122b-fdf8-4082-aa3e-1e9b89a97ff7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
49e08f36-4007-498c-a10c-1e92c5fdb96d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:31:00	TRUE	FALSE			en-gb	13:31:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
6d82bf66-8b59-45cb-8148-3e0c8a82abee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
e542a4ba-f71d-42d5-80ef-a54a72ae4688	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
								Yes						Yes					
8092ae68-2704-4cd7-819b-ae81e360678b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
								Yes						Yes		Yes			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bedf2b74-0953-410c-ba48-931b5142418d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81d69716-f133-4af1-98de-16e48ae0dee5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c07003cf-8744-483c-baf2-3c68bc008d23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:03:00	TRUE	FALSE			en-gb	15:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1408385-f952-43f5-84a8-378f5d9061ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
634538e4-2b8d-4a29-92f2-aa67ba37393f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a64d410-15c4-4cff-8d80-8cbbd95aa269	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8a7849ab-f49d-4533-a544-c0f82e02eb7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8ea3cfa6-2d46-4a56-8da9-2727b630d0e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
51ab99fa-b49f-4f73-9434-54b5a175238c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/05/2023		Muy limpio gracias	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
21e1d317-ddd5-44bf-8ea8-05c07a240d5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b89a71c-8ba1-4313-9081-9247e4f6cd97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
81dcadb3-c69b-4c2b-ae78-28451fb51cf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
72b1a84d-cbd4-4c85-8c7c-aec485d6d20c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
4ceb83eb-cc04-4307-8821-67cf3c4b91dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes					
5d9c6d3b-d62b-4ed7-aa7a-a69bbc74981a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/05/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e040a4a3-ad8e-4a3e-9045-90e0ecad8583	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7f7d6da9-65b4-44f5-9294-4cbde4e92a95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ec645c80-de94-4dba-9484-08f3290b030d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f9859a7-f74b-4168-8390-ae26a621c437	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1f60bc8b-46e3-40ac-8bb7-789d66633e6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b70311fd-a337-4a13-8caf-cf3cbdf11f78	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
40d213ce-f1ca-4f05-949f-e8d20dfb448d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6cd110b4-8fb1-43ba-adbe-694470d7ab30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
16ec66b1-f7e9-43cb-a362-fa991f31d496	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/05/2023		Redo it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
16ec66b1-f7e9-43cb-a362-fa991f31d496	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
					Yes															
98e95551-e3d0-4f0a-92f1-33d0dc7916dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
98e95551-e3d0-4f0a-92f1-33d0dc7916dc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
d290b42a-c8ec-4bd4-a6c5-66cdc9dd8909	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
d290b42a-c8ec-4bd4-a6c5-66cdc9dd8909	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
			Yes												Yes					
2c837df6-7d3f-4795-ac35-4286c9daba94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
2c837df6-7d3f-4795-ac35-4286c9daba94	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
					Yes		Yes						Yes		Yes		Yes			
d34d84cf-07ed-4437-beff-050c77749396	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				
699d1dfa-fb53-482b-ba16-4719a4aea5a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
9de65f07-7631-4022-86ba-9d739fc81450	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
244cfcba-5478-406d-ae7d-068c5abb78e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 17:24:00	TRUE	FALSE			en-gb	17:24:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1fd39fb7-862b-4262-930b-93242d2309e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	06/05/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
36ee56d2-c660-48bc-ac64-3c6a89ee8683	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
			Yes	Yes					Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
984cf917-3c1e-46c3-8564-f89b92c85aa9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/05/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
532e06fe-b476-40c3-88d4-70b7505cf46a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0473811-2ca7-4806-a685-bc19f0d1173d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	06/05/2023		L	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes						
456214b8-05d9-45d0-bfa1-739a3d42f150	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/05/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes	Yes				Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
d7ffd0af-5b1c-4375-8817-6c20cb4aed57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/05/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes	Yes	Yes				Yes	Yes	Yes							
b6b28f57-d9ad-4bde-ba27-fd2f5c53fada	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	06/05/2023		Nope		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
	Yes															
fdb09372-93dd-4f49-a64c-a5b9054929ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/05/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
			Yes				Yes		Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7c8124f6-4a68-46b9-a4eb-38b7aa0e9442	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c20f0de1-8945-4e5a-96a4-79c728d0ff3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
de72dd01-e424-449f-9beb-cde8821e1ff9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/05/2023		Good cleaning is good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd87380d-e8e5-461f-b122-e15cecc36ec6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
66c98eb2-4adf-4d0c-bdfe-db0fe094d86d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ebd89eea-01ce-42ee-b78b-b68f9830b043	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ebd89eea-01ce-42ee-b78b-b68f9830b043	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
befc6607-3e7e-4ba5-acd5-ef07cf64fdc2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
47367ad3-cbec-466e-b442-aa8c1cc12707	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes						
3ee7149e-2325-4675-9899-9dfd94766c5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3ee7149e-2325-4675-9899-9dfd94766c5b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
2e72ed82-f97b-434f-8c65-1edf9b56d5a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
dff3e26d-bc19-4d95-8f89-6e5f06cfb8e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ed09c83-830a-4247-8248-5007c3c9c96c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a277add4-2f0d-4159-83c9-5ca22de42e8b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/05/2023		No huele bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e89bcd38-df30-40cc-b098-6f77b43a3df2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9987e6f0-4d72-4c00-99db-8c8cbc2fb97e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
baeec266-38ca-4cf1-9205-ffd8d04594c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/05/2023		Hi	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3e594dac-6984-464a-a91f-6277534eef51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/05/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3e594dac-6984-464a-a91f-6277534eef51	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
34d98aff-2779-4a1b-adf2-796caa0b2630	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0538b7cc-f70d-419c-a139-c4a30d5ca98c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ed12125-ac1f-46b9-a20a-e2c222df51aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
37268503-fdec-4687-b5c2-cfaf930fd26b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
63a7521f-8c77-4b5b-9834-ace88e1290ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af8df832-6b8d-41cc-86c9-421f152dced4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:25:00	TRUE	FALSE			en-gb	20:25:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6bc3f839-a2bc-4ec9-a6e1-0b2854277192	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6bc3f839-a2bc-4ec9-a6e1-0b2854277192	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes								Yes		Yes		Yes	
0601e67f-97d0-4429-b84b-90b1554e5745	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
2b3c4434-214e-4bf0-9496-dd611f12d2fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
3fadeb0d-2e79-44bb-b106-8d6e05001fa0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/05/2023		It was nice and clean						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
e3a6ed47-c8c1-4dc0-a5db-9f2f3a0e0e17	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/05/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4eb734d1-75ec-454f-ab4c-0d762542be50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6200edbb-384d-43d3-9e8f-b900874ea447	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e700e002-e207-4a46-aa36-3c8478372a9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ec9241a-d5bb-4f69-bd0a-7dda4c6c0405	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:21:00	TRUE	FALSE			en-gb	21:21:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ae82a54-9944-4460-bdc8-165409d62886	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25f9c0e9-15a5-40f7-8339-d9f7aa451979	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	06/05/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
25f9c0e9-15a5-40f7-8339-d9f7aa451979	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
82037ddc-d58e-4077-acac-d81ae4725059	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
346e0c39-0f82-42e8-abbb-c1545e9232af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/05/2023		I hate it	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
ef0c72e9-2242-4ab4-bc29-83be1d57d468	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/05/2023		This airport sucks. 2,5 hrs immigration for us citizens???????	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
ef0c72e9-2242-4ab4-bc29-83be1d57d468	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes		Yes		Yes						Yes							
c0ee1b1c-874e-4e30-8a15-26f41fce6d5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 22:19:00	TRUE	FALSE			en-gb	22:19:00	06/05/2023		Very clean						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
0b1c8a3a-0735-4ab0-9d49-c89b513f593f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 22:50:00	TRUE	FALSE			en-gb	22:50:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
88a885c2-55c9-463b-89af-2e87a54e358a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 23:38:00	TRUE	FALSE			en-gb	23:38:00	06/05/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
88a885c2-55c9-463b-89af-2e87a54e358a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes				Yes						Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
3b60e94f-cf80-42f4-81fd-b19da11b77e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/05/2023 23:44:00	TRUE	FALSE			en-gb	23:44:00	06/05/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
88b49bab-2885-4294-bcf9-5ed5f7d2d76e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 00:35:00	TRUE	FALSE			en-gb	00:35:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
efd08f8c-aa3d-4f84-822c-c625ed8379b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 00:43:00	TRUE	FALSE			en-gb	00:43:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
9b353bc0-5cf6-44de-95c4-4fb94d7eaf7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 01:04:00	TRUE	FALSE			en-gb	01:04:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
50c5a3f2-95c0-41cf-9a05-390944167e3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 03:39:00	TRUE	FALSE			en-gb	03:39:00	06/06/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
50c5a3f2-95c0-41cf-9a05-390944167e3c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
4b123e0d-9fa0-4002-90ae-ca5d6f2cc2ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 03:42:00	TRUE	FALSE			en-gb	03:42:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6a566573-971c-4382-9f6c-74c2e121f510	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 04:02:00	TRUE	FALSE			en-gb	04:02:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9daf6c78-0994-4198-935e-4611d026d928	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:05:00	TRUE	FALSE			en-gb	05:05:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2cfd52b8-3c47-4468-bc2b-06ad44829a4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
56ccdeaa-bb0b-415d-a4cf-ca7b22d66ad1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fd14e754-bfd9-4337-b650-fbc7fe9cbb22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:21:00	TRUE	FALSE			en-gb	05:21:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
51f472fb-0cd1-401a-83f0-42009e8b91d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:22:00	TRUE	FALSE			en-gb	05:22:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0a6cb8f2-788a-4c59-8b0a-f80f73369610	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 05:52:00	TRUE	FALSE			en-gb	05:52:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
19b86273-b94e-44e5-90c3-b940ab0cdd7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aac18fd2-263d-4fbf-a472-abf83aac3fe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	06/06/2023		Very rude cleaning lady
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a1159568-c93c-47e3-94c5-84c1bae8e8c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
10a620aa-32e6-4720-8cd3-313da948f679	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
93a9afa5-e850-4d25-b336-867606976a28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
24e2c77f-a43a-4508-a4f5-746e2cdcc410	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0b6c9b81-b2f5-4c6d-b4cc-46591898586b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:03:00	TRUE	FALSE			en-gb	07:03:00	06/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
edd1f826-2db7-44ec-89aa-065dcea6935d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6190f14a-1612-437e-8bf9-b64d4f0de633	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2612326d-6fca-4907-87b1-3e332d66d86c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9361274e-7713-4df0-927b-d1abb80d6e3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
72796c61-5653-4f18-bfcc-96e743b15ce9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0ec13c98-d5d9-496c-a980-7fbfb2bfdc46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d44eae5a-282e-4c06-b5b6-6995c9741554	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
39be3453-3f1f-4712-b3ce-edaf4fd8e323	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:04:00	TRUE	FALSE			en-gb	08:04:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e3f17d7a-9ba7-455f-86a8-cb9f8fff05b8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2af89568-a282-49ad-937e-d2dc5c81cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f66678e5-4b66-4d52-8705-6d8df2a1fbb5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea5eaecb-62b5-4303-bc10-596b2dd3ba31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
680df655-bd94-475f-9110-d9ca9485e5c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b4bf102e-4c5e-47f9-b324-153901feec1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
99f274d0-3d7f-4233-a6fd-d812ad37d473	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8641be26-02e2-49e7-a410-b5bdb630a39a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b7bc2bf-1aef-449f-a82b-a38bb6c20d45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:10:00	TRUE	FALSE			en-gb	09:10:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
adb05852-d4c1-4dcd-a601-d3fa33014fff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
009b2796-9641-4ae6-a787-816a9ffbcd54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
33ec86c7-4125-4904-91bf-b04b3d7dc72d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
59ccfaf8-eb84-400e-9f95-f37345e0ada3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
64a7e4d4-5258-48c0-a81a-6c7e7fa692bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1b3a2960-b9eb-4dcd-ac8c-fa8eb723e311	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	06/06/2023		Todo bien gracias	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fe7125ff-93a1-4b2b-9333-e105750ceb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	06/06/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
62736bfb-90af-4827-b330-830efc902c31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c016bd4-ba7d-4180-8faf-8797fdc28400	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6358daab-c5cf-4a51-8704-ee4490dfe5db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ee651841-66b8-4465-b69a-b13867925513	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a912312-eee1-492f-a826-9b5846369fbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
caf5b804-1ba9-4a62-b50d-6ca60ab3aca2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/06/2023		Broken	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1ab3db80-4dba-4258-94b0-a22e41e300e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4b4ae05-f445-44c5-a402-eadf19598ba4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c588bf17-a9a7-464f-8022-0682e7a7c5d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ab7458b9-cc71-4e01-a3a2-bb4e0cb46016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
055b5cd0-f799-41ab-83cf-def234905191	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
365063a3-fdd9-4c8d-987d-c402a58d8714	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5523ae6f-5011-4ac3-afb8-2fcc2b01b302	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2fad3a1-e688-41f0-af5d-e76420bdc5a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/06/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b158864a-2f9f-4516-bf3a-761b9d1a50c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
339bfa31-fa6f-4c26-9bc8-037ca93fdf1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d66ef438-09cf-4e61-b013-772437d17191	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ce2685fd-c248-4b7b-a44b-9420fb82f463	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3c56242f-349b-4d0c-97b0-1f776621907c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f60c56e2-1420-42c0-8b3c-34d326f6de01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a42a9f9-aa5e-46cf-b6d4-ea5eb0d45532	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d90e620e-3971-46f3-8316-79970a75b303	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
44bc0133-613c-46ba-9f3b-b13380ebee6c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ac199994-7e13-42fb-8250-1e891e4f0876	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cd82b60d-8bc3-47e5-9854-cf629fd4bb48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db60eea1-4969-4978-b6bd-5272c77382ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a187ff8-2d16-4b3f-a935-3404ad2a4128	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9265f0b3-7fcf-4d43-8abf-1a87cf9a4511	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b59b04b3-d846-47c7-912b-b376c32e4224	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7d588e6c-4bce-46c7-8dec-bbe918a18af6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eabb864e-412c-43af-bec6-10b11e3b34dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b1464dcb-28ff-447b-9043-dea96223028b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a7acd86-9349-4519-8d41-17f6cefd218f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/06/2023		Outdated and raggedy	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
684681cc-8d3f-4970-86e2-b48c0de6b6cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
55fd3ed6-9e03-48de-b2ac-5b881c4ef1a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7158f9aa-ac31-4110-a7a7-98f9dbb80e27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e4ad1c4a-4b49-48f6-816a-15fd029949e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
54daddf8-b5f8-436e-98b1-bb529cd77e8c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
08109e86-6b55-43eb-9404-ab16fa36495c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1d9f88ce-3991-4e5c-a5c1-3426e218812a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d10d3de0-f2e0-48ed-bc7b-a1bcc3d96284	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d7a1189-8fe7-427c-adc7-087223b178f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4a531d9e-9b41-47d1-befe-00b17ef1631e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
80d23647-6ebe-46c5-9319-e653dc3b8474	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
9ce70e85-85a2-43f3-aabc-7800a0b474e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	06/06/2023		It was good		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
d126daa9-5746-4057-a608-63e349f2b3c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes							
1a14f0cb-c77e-4934-9196-79988b602a1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
0f02c433-9e51-4058-b575-b6f8453da1da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
						Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
946fab0-6660-4ee6-889b-6411ffd09913	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/06/2023		Good		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
aa64facf-6f34-4d24-af89-56f4e0bb44cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
7ba9c8de-f3fb-443e-811b-0e59a94d377b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
ecd4b967-1bb0-43a5-881b-79579716ad57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
bc283ce5-249b-408b-a3f4-558aae6dbe58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	06/06/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bc283ce5-249b-408b-a3f4-558aae6dbe58	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
				Yes			Yes							
c63c310b-7d9f-4618-a496-c491c2d487aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/06/2023		Stinks!!!!
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
095cee81-d7c5-4322-96a1-08a670b2e0b6	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
095cee81-d7c5-4322-96a1-08a670b2e0b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6626a98e-7d5b-49f4-abc1-8ba2a634b979	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
6626a98e-7d5b-49f4-abc1-8ba2a634b979	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6626a98e-7d5b-49f4-abc1-8ba2a634b979	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes							
324b97df-98c8-4796-983d-596f20eb04f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	06/06/2023		No						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
0286822a-c435-429d-86d2-bc5113c19e54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/06/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
2f1a893e-8ef1-4f9f-97b4-2ad499cdc77e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:10:00	TRUE	FALSE			en-gb	17:10:00	06/06/2023		It was very clean						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
c8059012-1f9b-47d2-b0c7-bee3c8a8b23d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/06/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment											
3f852e23-209f-4ef8-92ed-b5db42a3d928	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:18:00	TRUE	FALSE			en-gb	17:18:00	06/06/2023		No											
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
37313076-0cb6-472c-8757-28786ffae358	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/06/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
567a12d9-a642-4cd9-b9be-4640af798dd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	06/06/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
4e22ab30-cc0a-406d-bace-e501209155f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/06/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										
5b118daa-116d-4a66-8285-40eaf94d8bce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/06/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
															Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
254148b9-723c-4bcd-ace6-f5193cd675ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a653878-c748-4df4-b913-48446a98e25e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f6a448bf-136e-4252-a47a-7f9250994b0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3c36e78-a4a8-4b26-8d3d-a743ea2ff166	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5676af7a-5723-418d-9800-bd1118333a46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1983744b-46d7-4bca-a55e-db381650902a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:44:00	TRUE	FALSE			en-gb	19:44:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c0b273ce-6f09-4ab8-8316-3e79af1dc269	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/06/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6018d547-dd4b-4967-9ae0-853cc18ed746	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	06/06/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes						
d0fae78f-67f2-427e-be2a-f7ca167394c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	06/06/2023		Please i cant breath it stinks so bad in here.
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes						
5b5bb968-40df-4636-bd65-fb0abba9b965	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	06/06/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
763eedc6-5815-43f8-be0e-6275106c6cb0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
e4c5590c-e966-4762-a4dc-72f77dcf9c6d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
bfde0aa3-72df-4b0f-b86b-4f012e02ca9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
492264e4-5d5f-4e42-98df-ffc7fb210be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:38:00	TRUE	FALSE			en-gb	20:38:00	06/06/2023		Good														
														How would you rate this restroom today?														
														<b>Average</b>	<b>Good</b>	<b>Poor</b>												
														Yes														
a5dda7d1-ca0c-4c5f-8106-498ba0812309	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/06/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a5dda7d1-ca0c-4c5f-8106-498ba0812309	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
90a42d26-3ec2-4e0a-8940-aa0a176aa8be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
														Yes						
f23ac9f1-b2b7-4a80-b789-4db23003097e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/06/2023		It stink						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
														Yes						
879e4a7c-d827-4209-ab9a-cccdef21c865	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/06/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
879e4a7c-d827-4209-ab9a-cccdef21c865	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
d2c1b252-90cd-4ee0-ac30-3c92b3e6fcbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
52bee864-42f1-4fa2-817f-4708be61b9b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c3ca02bc-0934-4077-ba9c-bc09e3d23fed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:14:00	TRUE	FALSE			en-gb	21:14:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
dd85a485-39c7-44de-88ab-d24b99ab381b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f77f4d1b-25ba-4400-87fa-047518444611	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f77f4d1b-25ba-4400-87fa-047518444611	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
411def09-3491-4923-856f-3d5b6fc9757	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
21e376c8-fbbf-47ae-801b-c7fa009abe4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:41:00	TRUE	FALSE			en-gb	21:41:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
25e0113f-067c-462f-8dba-79dca83536f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:44:00	TRUE	FALSE			en-gb	21:44:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
26cbf5bd-d6ad-4f5f-b198-cda975e7352d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b09812c5-f072-4b54-8709-b6b15b1a665b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
217468a0-5360-4277-9793-da20938ac902	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
6f34ac2e-1200-4998-a33a-51dabbd0459a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:06:00	TRUE	FALSE			en-gb	22:06:00	06/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
03d9d778-26bf-47c9-b9a7-9401329aee11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:12:00	TRUE	FALSE			en-gb	22:12:00	06/06/2023		Muito sujo e sem sabonete
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
03d9d778-26bf-47c9-b9a7-9401329aee11	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes						Yes				
ce83a771-9c5c-4832-b4e6-2b2f6bf84c5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3dc9943a-435d-4974-910a-d9530abb5a5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
2d9d3e67-f859-4cde-825c-0b84f6f57786	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:27:00	TRUE	FALSE			en-gb	22:27:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2e2de67-940c-42fa-8b71-eb3fd04f19a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
f4578abb-8f6d-48a6-aad9-4512bf4cb5c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:32:00	TRUE	FALSE			en-gb	22:32:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
27eb5c8b-f05d-4aa9-9f4c-eee57ae48ba0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 22:49:00	TRUE	FALSE			en-gb	22:49:00	06/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
ee9f64b4-e867-4d09-8aa3-d1769b8c35f7	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/06/2023 23:56:00	TRUE	FALSE		en-gb	23:56:00	06/06/2023															
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>												<b>Poor</b>												
			Yes																								
06652ed6-4f08-4bcc-b3d1-f28f7dca712	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	06/07/2023														
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>													<b>Poor</b>											
			Yes																								
fcd5a53f-709c-4899-86d3-17bdb5e028b0	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	06/07/2023														
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>													<b>Poor</b>											
			Yes																								
cc9c5343-fb70-431a-9a2c-8c44f144235b	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/07/2023														
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>													<b>Poor</b>											
			Yes																								
1869c008-64dd-4475-8b0c-12b363287730	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 06:34:00	TRUE	FALSE			en-gb	06:34:00	06/07/2023														
		How would you rate this restroom today?																									
		<b>Average</b>	<b>Good</b>													<b>Poor</b>											
			Yes																								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7b4e5def-7c6c-4739-9299-e470b73beb66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:00:00	TRUE	FALSE			en-gb	07:00:00	06/07/2023		Esta muy ordenado y amable la atencion	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e49ce7e2-8850-40fc-8574-70476a64657d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:02:00	TRUE	FALSE			en-gb	07:02:00	06/07/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c4542a05-9bab-4529-a1c2-82c4132381d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:13:00	TRUE	FALSE			en-gb	07:13:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
330d132a-1232-49dc-9611-2ad91571f217	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ceafbc-4a4c-4159-875a-b9dee4a1e3e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ba246a1c-ac07-4444-ab42-2bd89312bb83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/07/2023		No everything is goog	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ce7319a-265f-4398-a996-a33948539f0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes		Yes										
cc812217-1634-4e6d-8008-752b51723204	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f7cf3121-d270-4af6-afa0-ec7055e4cc3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/07/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1bfa9458-6b66-41cf-bcec-69641b1f93c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/07/2023		Dirty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1bfa9458-6b66-41cf-bcec-69641b1f93c8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes										
f7403725-ef1a-464f-b0d0-6536f7d253a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/07/2023		Pee all over and dirty
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
eeba9378-4cf6-420e-8363-ee17f9eadcfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
06eea39f-79c7-4c76-bb0b-780680e2e037	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							
efaf294c-a234-4ad2-ac01-13038719d1bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e757ea82-bee6-4e5d-8295-bfba9d7e40dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
316f69f0-5796-4379-8729-bd35ce011dc7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7047e3a6-67ac-41f1-a5e7-92edb4fcc285	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes	Yes				Yes								
578078c4-6d58-4b85-bb62-f06f8ee65eee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
345552c8-978d-4ae8-bb7d-2e1a27fd287e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
19f24c45-5d5b-4eba-8cd4-b1314610efcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7de57143-6c40-4386-888b-594db4c01af3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	06/07/2023		/	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
eb3c3eab-3bab-443c-aaf4-08d119d0041a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5d27dcf1-ca9c-4ae1-807d-f8e6af6816ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d8b89ee1-0f41-4fe2-b5f2-5fded1e9a078	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99766e1c-aa99-4328-90a8-e179cc1d875e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40419fc5-ed40-49bb-94cd-9c37f129ba65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1678209f-ce16-4734-b20c-5dbc8ea53fbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
9648109e-d2f5-4ce7-9cae-dec459362745	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
941784bd-dfa9-48de-b362-9b220f3a6e8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/07/2023		Clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78da4d72-d50b-44cf-81c8-1303764d240f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/07/2023		Clean sinks
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4a8604e-614c-41cf-9cbb-36623132092e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
89004ffd-de63-49cf-9b96-c01f253572ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
73ec3f27-5099-4999-a34e-a5bf5d094252	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5e302b07-14c7-43e5-9eb8-3fb863ed1fec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
efb167d3-8d59-4d98-9370-61178d44be46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fc78cfe2-7765-40bf-b0e2-3537250b2181	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ce63ff93-1b6e-44ae-8b8f-5a1a5598480d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2795556e-c651-4607-89c1-fc0d0597e5e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
180edaf0-fa6c-41c9-8c67-504ef7b1a867	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c89ba49-d2fa-4ae5-b712-9486ce1a488b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/07/2023		Clean and nice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5cf54ba2-4e23-4cb2-80aa-c67cfbe04bbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0e46946a-1ab6-420b-840e-cc54e281b136	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a92e933b-9c2a-4c3d-84c7-808be25d8f31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:18:00	TRUE	FALSE			en-gb	11:18:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3c55cbe-8157-49a3-8d30-1c351e1f3c82	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f9e0b11-ede9-4887-9894-93ee3c859590	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	06/07/2023		Great job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bec17b0-8955-4710-9c77-ff68b8de391d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
09f9b9d3-8544-4090-8b29-39224b3908a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
86cfdb7c-6bfa-48dc-a559-d6e91c436d4e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
280a85d3-9174-4cc9-b5d6-d48fbeb7abda	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d261c142-ff45-41b0-acbe-4ee0e1c50445	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8952c1cb-ec01-4baf-9000-a9f6906b0f57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0cd72a08-e5d0-45e8-97ed-1e41d6b43aa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/07/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0b4b68e0-789b-4163-bb6b-2c5bd4aad2cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f4030081-4a2f-4226-9252-4745ed211e34	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fc550d90-7774-4ca4-8a83-3c938581b27f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4c687db1-6639-46c0-8cd7-f6716524430d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6a853c5c-5ca5-422d-9c63-983e6e82d737	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0d952bab-0c74-4978-aedc-595565a088ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
111518f4-c7dd-402d-b8c9-85e02b0b26d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9a9158e9-11b1-4153-8cab-b0cb98a000c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ec29e0e-7a0a-4855-8580-faf9a8bec6db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4f161d9-d198-44ab-b043-4abdf9503da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c7725ca-8877-4ac4-9b36-2fa53bc069f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c0aaa62f-a5dd-4dc1-91cf-ecf0a88776aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:16:00	TRUE	FALSE			en-gb	12:16:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cbe5ec93-38e3-4bca-bdff-82ec16f39c21	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5bc4058a-29bd-4331-8a14-ec12cf73de9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f47bac88-99c0-4c27-ae87-f306f6d0a141	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7f6a44d9-27cf-4a5e-aae3-9d6b22f41340	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0ba8697a-0f25-4da6-8bde-a05cf7aab5fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d887ae-5444-4683-a239-65a983353769	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad32d9d4-2ae5-47f1-91a1-eacc5907174f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6ee4dafd-9d77-4841-ac76-d37bc856d242	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
076689a0-120b-4f26-a712-cb65de25dd0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d8ffb1-1162-4f0c-a83c-9919805ff8bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6a58591f-63ce-4552-a6e1-90676239f558	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4345841d-ff1a-4534-837d-2aa2ab51373c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
574a6b70-e607-4acf-9eff-63a16dbe860c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2f2a22a1-575b-4d6b-b8a3-fa241eab9c94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:45:00	TRUE	FALSE			en-gb	14:45:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4816ae05-9f04-4406-9684-f890dcd0dc72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7c888915-f08e-46c1-8177-5044b069d394	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3feed544-907a-4ac3-9d70-1c5b617f27e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/07/2023		N	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ba141522-be4e-41e3-97a0-3309dce027bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5d4801f1-aa5b-4180-8002-0465e8300c0c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b67c8d61-9253-46b4-829f-9762783a375f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:28:00	TRUE	FALSE			en-gb	15:28:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4d94b370-323b-4fd7-a160-7e645ab88031	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/07/2023		Very dirty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
e08353cd-fae8-4712-bfea-8df297cfdbfe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
57362c3a-85e0-429b-832a-3b7ad07c24a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:41:00	TRUE	FALSE			en-gb	15:41:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
71ecf69c-4cd2-4333-9d13-b8a6b196dd61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
14fe5641-c280-4377-8db5-73c482328c03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
1d9d39c8-6326-4a36-885e-f5ff60c9fbee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
dbbb0736-ad48-49f0-8f68-e05b40cba63b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
720d73ba-5b5b-4097-b6a2-b6ef0e9632ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/07/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
934079fc-44c7-426e-af99-31dc760080ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40f0b1b4-cb2b-4970-8d7c-57e96c371d9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:40:00	TRUE	FALSE			en-gb	16:40:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4940963e-c21f-4ea0-ac69-c64130e35985	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
0b520f56-047d-41c0-b4bf-86da1b860ff1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9cbd78e8-7f09-4698-846b-92984f33dff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e3d3659e-a6d7-461b-9596-16e44f734123	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a7d09c0a-c332-43aa-95ea-8c40168af0bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bf5c638e-94b9-458c-bf8b-b83bc5e7f6cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b84dbd84-d600-4ecc-9e08-c964ce34aa4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:25:00	TRUE	FALSE			en-gb	17:25:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
53b9c63a-cb27-456c-b2dc-90e2e257c25c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
24fb922a-8add-416e-b2b8-17f9ea98ecd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
984c6167-53f7-4aec-a6c4-ea7e0d53fd57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0b373b33-a6be-42cf-9b3f-d15aceae168d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7a15f6ff-a00a-4dce-a59b-d67f3ba15759	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/07/2023		Awesome service they evem helped me wipe	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b42c4bd6-e180-425f-9602-140eddad45f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:31:00	TRUE	FALSE			en-gb	17:31:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9fe21983-3cb8-4721-bac5-9713aa5bdc64	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					
de1ee499-8923-4cac-b623-03469840f25c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
e803a626-02ab-48e3-add2-c8fec62f439b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
7f048325-13bd-4734-b530-6f897519b3db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1c47bac8-6dde-4c28-aa43-da898890a5a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/07/2023		Wemdys	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b9594f6f-4bea-4d3c-beba-e6a44e19ec52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						
22700b61-38c8-4560-8ede-f959ec5e3a8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5241674e-9292-48ea-9d2d-143573d8c418	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/07/2023		Miami heattttttt	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a93a3587-b354-4e46-b556-9b6c85fd1502	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
46fed5c6-aaa4-4931-9357-76c512e8aea3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																		
			Yes						Yes																				
244abf18-f681-46d2-b5e1-7e5d0c2121ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																		
									Yes																				
aabdfa0e-32a8-4897-a97d-fd5d5a5ace52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																		
									Yes																				
1a33ed01-78e4-484e-a4ce-342877166b9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																		
									Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e0f868e-b09a-4c56-a958-d03ce5db40eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66bb1491-6c67-4a1d-8910-e2ed171f2570	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0374e6f0-fdc6-4f1e-a04c-d597375f7fcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9aa6ba1f-e844-4951-94ce-1770d7f3b1a9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
9aa6ba1f-e844-4951-94ce-1770d7f3b1a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
df4b059f-b2f7-48aa-9f86-bcd80d902ce4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9f8beb64-ebf8-491d-87d5-9deda72b3899	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/07/2023		Bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7d8a7a33-1369-49fc-911b-8f85f7cbf552	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
8b0e2e89-2abb-4180-b469-9fee429f976b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/07/2023		Muy buena atencion	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f0e2e697-12f1-4245-9ce7-6653e2dd4491	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
02dc3aee-3a8d-49b6-aae0-6e525effb49b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
936788c4-9a3a-42a1-af57-67e9a7c6673e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b5bb3eb-b264-4f89-9307-9701a4583680	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes								Yes	Yes					
b76c991e-d5bc-416a-9330-3947255ea781	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
459418f7-dec0-43e9-a5be-38fad66765b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
633cde84-e840-4487-9c90-b26841fa11d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
633cde84-e840-4487-9c90-b26841fa11d0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes	Yes				
d1e97ed8-df96-4345-884f-aa8312c2d22a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9701e1cd-5e7c-4bee-a3b8-5ba93d28c93f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/07/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a62f70b-aea4-42d6-addc-dc957ce82c19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
f7836e91-68f7-4934-a14f-f1900d289d20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f7836e91-68f7-4934-a14f-f1900d289d20	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes			Yes							
9f2496ac-5e21-4f05-b2eb-a2a6359164f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0df60b98-02d5-4f8f-9169-1265bfa1cd28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
779683f7-9979-48f7-b319-e507ac160897	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes							Yes						
939feec9-bcca-4b4c-aadc-7c008cc3b8f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
939feec9-bcca-4b4c-aadc-7c008cc3b8f9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes			
85f20161-de8d-471b-afce-479529c9ab48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
43733cc9-fbaa-40f5-9997-4d9e71959278	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
691bff63-8984-4122-84a6-6ac388dd36d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
56e832ac-290a-4fe1-90a7-ca49b573c5bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
dcb81ac2-5291-45fd-9cb2-f5705103405e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/07/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/07/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dcb81ac2-5291-45fd-9cb2-f5705103405e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes					Yes						
ff12c238-6631-4b79-bf33-9010d918ffd6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes	Yes	Yes					
8610ebd0-15a4-4a6d-ab6f-b4bc2d563f4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 00:34:00	TRUE	FALSE			en-gb	00:34:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes	Yes	Yes					
dc4f4a86-25a9-444a-ba8e-7fe7bc3dcf31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 00:41:00	TRUE	FALSE			en-gb	00:41:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes	Yes	Yes					
2c05c232-df7f-4bdf-9cca-001e66f4c721	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 03:00:00	TRUE	FALSE			en-gb	03:00:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4dc64c74-4eac-422e-b1bb-2dc35f9b07ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 05:08:00	TRUE	FALSE			en-gb	05:08:00	06/08/2023		Keep up the excellent work
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7ef7b0a5-4088-46b8-ab34-43f245c08180	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 05:14:00	TRUE	FALSE			en-gb	05:14:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dcef6ab8-f53f-4bdd-a90d-093b8c6498af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6889acd4-38e1-4d16-9f48-3d270aca0bb0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d31a9c55-5bc4-47aa-a52d-ad651aa8120e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b0c3f94-6874-4079-9a17-541e10059fe0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
709db156-14b1-4148-92a9-cce108a0cc12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:30:00	TRUE	FALSE			en-gb	06:30:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95b9c3bc-31ed-4e17-b5e2-323ecc9e5eb7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
661224dd-a95b-497c-9c54-eddf152e72d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b853293-ed1f-4383-8636-0a6c94d23f68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 06:54:00	TRUE	FALSE			en-gb	06:54:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bf8290eb-8d53-492b-bd15-09d7040812bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d1559deb-13aa-4943-9b1d-cb89907da942	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1ad2bfb-be50-41cc-8a09-b9408bd304f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
927b112a-c85c-4db0-9968-75d0eeec2df7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/08/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6e73fc7d-1a6b-44b6-b1da-f405b865a639	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c67539e-881a-4fc1-a424-1a3b05e08fb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7c28b5ee-4615-4af5-b4a9-834e6951a64b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/08/2023		Na	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3cc0c3c7-a904-408c-888e-c0b7cd7e4b72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/08/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8ce09b6c-a3df-4349-baa7-2de4a25cea0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
88d4738c-1cb7-46fb-99c5-03a9fce2f790	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f6878ee5-6cda-4e3f-9dc5-36e6aee66f8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	06/08/2023		*****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
890b40a5-ec6f-42e3-9a93-0d59cf66e342	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	06/08/2023		Esta limpio es mejor les den bonos a lo que limpian bien para estimularlos	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea667ef8-cfb0-46d1-84eb-c8276edd53ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes								Yes							
3f192e15-1655-4f1a-9862-3fe368acee96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e6def92e-304e-4c71-9597-7cf7fc1aa714	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/08/2023		The door open both ways	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
98046a66-9aec-43d4-8db6-8ac42b63f7f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5eb3e4e8-7841-4419-83bf-ac5a92e8ae59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c08874ef-92cd-41e2-8e89-c8eeddae4ffd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2dac0aeb-d29b-4b77-b51f-cdc74c4b181f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a795588e-5d10-46ec-a93b-f50efb69b134	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d616e98-2ab2-4337-8497-37e1f0636754	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	06/08/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4af40bbb-3947-4c23-a432-810d928e75db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/08/2023		Cgood
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c43c2254-6858-4bac-9232-712f94ef270a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a96a229e-4889-42d6-9eb5-0c458eaa860a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
14086021-6335-456b-83f4-3dcb38ac82c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15dc9b02-9749-45ee-ac09-d367f7591eb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/08/2023		Super bien
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2c7df231-77e8-47cf-9d5a-452fa948affe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e7a04d8-c624-4065-85eb-ca2058ad07fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4eac6f6-c19f-4b4c-97c0-8bcf64a63df7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9a46837e-0d9e-4027-b4cf-839bd8d8108f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38706996-c6b7-446b-96e4-f04172542561	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5ac42bf-bfc3-4aea-842f-e5839445e041	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
545dc6c1-2671-4a47-ae8b-cbd24d5a45d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bf004116-f6e2-41c5-a9ba-c3be6728b7e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89f562bb-aa84-41e2-8922-eb024238e9bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1dd9714b-54a4-48a3-8d6d-df5ddd1a6d49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6bd73b0-43cb-49ba-b3fb-22f36929989a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes	Yes				Yes						
e5aa3287-4f64-41b9-b46d-cb9064c5e440	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
e5aa3287-4f64-41b9-b46d-cb9064c5e440	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
															Yes					
d9687efa-1ec1-48f3-97d1-b20a8e225927	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/08/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
e8d2986b-813d-43c1-bd24-9595db46657a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/08/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
c5532b57-4d53-4bad-8190-3099eee835f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/08/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
3670c219-8951-4343-b27e-9a0831a80ff2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/08/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
88130c8a-7fc9-4fd6-a571-3749dd069a96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82932f0f-376c-4a15-839f-235e0f6aa470	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e0ae7ee5-219f-4d69-a46e-03a80e92bfab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 09:57:00	TRUE	FALSE			en-gb	09:57:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
ebe32dc9-5ecf-474f-ae4b-2cbbd0675889	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
553187bd-a5f0-4af6-9c2c-b2d8b829a76b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ddc56df-9912-4b5c-875c-a8b07e6e8c51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	06/08/2023		Hhm	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes		Yes					
5b51bfa4-da15-485a-b491-ef88813aefb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b06da947-3de2-4241-9eaa-08210aacf8bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/08/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef9a61ce-3f3b-4712-b275-1154f6f42839	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0f62ba8-427a-44b7-bde4-4c7e7170df40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:21:00	TRUE	FALSE			en-gb	10:21:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b31ccff-0eba-42dc-aaa0-3fe7d552f764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e876fdc1-7735-4107-b682-0ee1786372b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed9aff54-481c-421c-afed-aefbf0f11960	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f7678b2c-d7bb-45d5-ad2d-2cc6ef0550d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/08/2023		So sad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
db4aa09b-6a0e-412c-916b-a0d3285f6aac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
828a8997-2b45-4191-9424-e8e77dba383a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a33a27c3-bfce-499b-8e73-f3b24169091c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2356f72a-9ad9-4eef-ae5f-7d0fb6cbc6ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c04ff0a8-cb1c-4077-b67b-8e2992f30286	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
251f932c-d0b7-451f-acc6-ada082c13f18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2235e557-3deb-473d-9f78-fd6a1033e9aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25ce3f61-5295-421c-88ae-c3e0775c954c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b837a3f8-75eb-41cc-b910-6348ad18b499	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2a026c88-74e3-4563-9764-fb0495afa77f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
391c059d-14fd-426b-919c-3d8fad50e376	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ac71fd9f-fc52-4afb-90b7-571c68b4ccf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
32df9823-7960-40c8-952f-74a590a5c75b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b86336a2-5d9a-439a-9970-cf06153e1c04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef945a15-fcb1-4223-a220-dfc471268c18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ea6e55ad-303d-4a71-8d20-e3bfe3c3b103	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b62f7e8f-85aa-46d8-8a96-327bb9d22b5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes												
7bbfb2c2-7a08-4dbb-8066-1478fbeba7a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bb0294a5-6ef6-4df2-83ac-763070152205	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
729ca2ce-c71d-4693-b0fb-76732c61bf19	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
89f69ea3-aa3a-4825-97cf-b0379cefa970	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3490d573-d6b1-4d41-ba82-b4a7e48aa71f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7b35eeb-3be3-4578-8494-a6a7f077bf48	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81d473e1-e544-4aa3-bd10-99de72c054f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
22016ed4-e75d-463d-8d10-cce1cf25be66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
22016ed4-e75d-463d-8d10-cce1cf25be66	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes			Yes	Yes	Yes						
05da456e-f31b-4933-ab2e-8f111f87d4a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
99905fc1-5140-45ec-84f4-0ad7d082afd8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
65258b99-01f9-47ad-b9e7-4aa60a965c16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
133e22ca-970c-4aeb-9c96-eb10d8c80805	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
252b1168-1203-47db-8dc8-a0ffd4a2334a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
cca6556a-169c-4e86-925a-a0e4982a9bca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:39:00	TRUE	FALSE			en-gb	13:39:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
e47f6145-f22e-4e32-bfc6-1b41b8f7bec6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:41:00	TRUE	FALSE			en-gb	13:41:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
18c792f1-60d1-4e6c-8737-411a2aa6453c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	06/08/2023		Super limpio este lugar
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
9acd4852-746b-419a-894b-efb41e0323aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6356b1a9-f127-4c47-a9da-20a381e482ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7c8383fa-dcf2-4aed-8cf5-bf38df55565f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:28:00	TRUE	FALSE			en-gb	14:28:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ca3bf52-e8a3-44dc-861f-84d5343feb8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8bdd8fc9-97b0-447f-8633-4959001fac7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6aea7ed5-ccdc-4374-b410-699970fe5b29	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c8eda0dc-38d2-4f23-b875-d0439860f332	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c25723e5-8c39-4cfb-b769-e3eaf4bf5b2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a800559b-7efa-40c5-b3cc-d1c55cf24028	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
da07812e-78e1-4a91-833a-b18ab342b4ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
702a18a1-1fb6-4b09-ab83-4330d63fe525	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
62e2e574-a62f-4c29-8fe4-afcadf07e133	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
02345b6d-0451-4c2e-914c-bdf5ba662ad9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c2044048-a015-4510-b7d4-bfdc6a41eda6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4d565622-bbfa-4ef1-bf1a-2cebe7429adb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4d565622-bbfa-4ef1-bf1a-2cebe7429adb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cb754c86-703e-4409-963a-6b951e4e29a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5045ad5f-6264-4417-81fe-cc0ed117e95e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
60480a9c-03c7-41f5-8098-79171d700af4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c483702-ce43-423d-b1a9-c3602a79f4ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
961ce1ee-0a25-4125-aa4f-5c2ca95c5996	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
061d7756-7792-4336-9d48-b0508c305293	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
71719510-b55c-435f-8649-c72b8524afca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a04e695-c483-4855-a956-66598621be12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4156fee3-4cf8-4637-b1c6-48b8120114d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c8c9ef3-c284-462e-b575-b38fd6534dbc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bc65e22f-6bc6-43c8-a119-3082535502ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d8522af-23b1-43ba-af26-b1e623291743	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b213087-d0a8-4a03-806d-5f0832c5a8e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					
c393d1a9-a8a1-435e-9210-5691ec396232	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:02:00	TRUE	FALSE			en-gb	18:02:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes							
830a7106-a71f-460b-bbf7-8ff366579f44	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
d60b1be4-12d2-4515-972f-30e8db47a674	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
ea035965-dc1e-460d-b2cc-a4a0e7b00ea5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
459b1243-9468-457b-ab9f-9455c9826412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
222f674d-73d9-4c53-993c-9b4001df7b56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
349f5eb6-c82b-469b-8ebf-26427a74e9fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/08/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
349f5eb6-c82b-469b-8ebf-26427a74e9fe	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
6b3b378c-673f-460a-b262-886bfe0ddece	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e416e339-0068-4d48-9bcd-366a010818f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
039002c6-51a4-4bdd-b1e0-39162761568b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d79df06c-4c6d-4abb-919f-f1a78be0f61b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0b591b85-1b02-47c0-8746-bec6a9425bd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72ef71ed-1e2f-4b61-b8c3-1d530af2191b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes				Yes		Yes							
7c94b19c-e797-4b78-beca-592d479430c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/08/2023		Gracias	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ae6f0fd6-ac67-4bbd-a852-d240c1392e0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c6b0dc6-7784-4b1c-b749-e9ab9c9bd25b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2da9e869-d6d0-4994-955f-84a626a2719f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c300e162-0dde-465c-9f1e-21aab05ec90d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
be20e166-a7ec-427e-a4e1-a7d30cc145f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/08/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be20e166-a7ec-427e-a4e1-a7d30cc145f9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
fbc6dd3-6833-4655-b272-d1882589d908	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
09dfd057-b7d7-4a8b-8be8-36ea9f872cf0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b566a626-07f2-4f42-8f3b-3910ce9487f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
16d05409-0dd9-4216-a2d2-a2077a22b5ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
84e367d0-ffa7-40e2-8812-a1dac101ceb1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/08/2023		Awful
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
84e367d0-ffa7-40e2-8812-a1dac101ceb1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes				Yes	Yes		Yes	Yes				
e9a0de3f-e71f-4286-a8c0-b095b4f867fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a3884bd-5297-46b8-a3da-533ddc753954	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
0e160739-40a8-4d7d-b171-8896734437c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
59ef1e68-b667-494d-b827-0d99333874da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/08/2023		Angel					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
8d6e4f8d-803f-43c7-b52b-a25d4f05ad4b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/08/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>
								Yes						Yes					
2d38861e-e0fc-4f66-a608-b53d9fd873bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	06/08/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes												Yes					
0b5dcacf-88b7-4f53-982c-1c5ec216a559	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/08/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
				Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0b5dcacf-88b7-4f53-982c-1c5ec216a559	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes					Yes		Yes		Yes				
a37e4f2a-21c4-4fd6-8a3c-9cf5f36eba7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/08/2023		The bathroom is discusting can be beter
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes		Yes	Yes	Yes	Yes	Yes	Yes					
15e8da05-c5be-4efa-bbbf-1b0a2c5e410a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
aa77cdb4-a228-4f22-9033-9956c1f75d91	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
31465b35-8414-481f-a3fc-2f02721a1c8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
31465b35-8414-481f-a3fc-2f02721a1c8b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes		Yes				
c5217ed5-d00c-445f-a75a-7246b9dbe7c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:07:00	TRUE	FALSE			en-gb	22:07:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
646b6f3d-6589-4fdb-b9ab-c3d878707833	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes		Yes					
de64dd82-53d4-4679-b7ca-f98ca1d660e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:20:00	TRUE	FALSE			en-gb	22:20:00	06/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
de64dd82-53d4-4679-b7ca-f98ca1d660e9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes									
f6eb8016-80bf-4658-ab2e-afa970880861	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
34e5920f-10da-4eed-a3a4-c486026a0da0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:27:00	TRUE	FALSE			en-gb	22:27:00	06/08/2023		Poor
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
a9a8e7e0-59f5-4534-af32-7818fd43555d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/08/2023 22:33:00	TRUE	FALSE			en-gb	22:33:00	06/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a9a8e7e0-59f5-4534-af32-7818fd43555d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
6b3cbc81-8777-4c87-95fc-142e36cffc63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e3687b5b-cc43-4cce-b100-78047b885e39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/09/2023		E
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
efd5ca8e-f691-48ca-bf50-135ed209e021	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:32:00	TRUE	FALSE			en-gb	00:32:00	06/09/2023		Smell :(
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
0fd8104d-0ca8-4f6f-abe7-7d0e0eb848c3	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 00:41:00	TRUE	FALSE		en-gb	00:41:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
ae32a24f-a0f2-41a4-842d-5a6f8af30077	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:01:00	TRUE	FALSE		en-gb	01:01:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
45e54b74-ba9f-41e1-99cb-0fc89c653137	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:06:00	TRUE	FALSE		en-gb	01:06:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
bccdb0c0-2b18-41d6-ad8d-6cf0ed8ad5b4	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:46:00	TRUE	FALSE		en-gb	01:46:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
d99915d9-20d9-4e37-b609-d5095c682d4d	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 01:48:00	TRUE	FALSE		en-gb	01:48:00	06/09/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eae417b7-f487-4ba0-8feb-f02bd9ca1aaa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 02:18:00	TRUE	FALSE			en-gb	02:18:00	06/09/2023		Nnnnnnnnj	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
788e9947-4786-4590-8f74-ba6b2f8cc4d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 02:43:00	TRUE	FALSE			en-gb	02:43:00	06/09/2023		P	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd50e2e0-ac7f-4a08-b30c-d2ddc7af1709	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 03:42:00	TRUE	FALSE			en-gb	03:42:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
494f7d63-2b60-4945-b18d-ccbe2f330956	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 04:33:00	TRUE	FALSE			en-gb	04:33:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0a894ee8-2651-4b5c-8188-343b771d7f4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
285a6dfa-2163-40dc-aa2c-16b4749f3b2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:09:00	TRUE	FALSE			en-gb	06:09:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
206698db-43cc-44b6-b377-689cde43d1e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0252c0d-6cf9-44d0-a323-8e6086c37739	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2d68074-d7f5-4e93-91e2-d4f89825ae7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:19:00	TRUE	FALSE			en-gb	06:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88ff8845-f419-4c98-a5e5-6eb7a8370413	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85dc480e-7bee-4ecf-8062-adba65c057fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cb8d744a-20ed-406c-b742-475b9aa3ae3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
568a3159-1c9c-4bce-aceb-db7afd4ca00c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:44:00	TRUE	FALSE			en-gb	06:44:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0dd89a35-e3bd-4849-86b6-73d8d43bbe9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4dbace13-1d69-4faa-81be-d0a90522db45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:05:00	TRUE	FALSE			en-gb	07:05:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db2df8b7-2108-4a42-8ae9-f5ec0caf904b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba91b99f-e527-4247-9926-90ccb9703b4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c1361234-de47-4554-bab7-ca4041c13b39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
75abe700-cb52-4135-b9c7-8029d7a66c64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fd24c4c9-3758-4907-9b9a-a2181373bfe5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3b4b9ff-637b-4f32-9717-c83ae2c5b94c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
16d066d0-f9e7-47bd-a42b-639f75b75621	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fe4693c4-f977-4d0e-9305-5bfae48efa05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9a912fcc-a83c-44d5-a3e9-24760bcf44b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb707ade-8b48-4c6b-a71f-bb35ee431048	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70b128cc-a0a3-4990-8729-c34271b89999	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
551ab6d7-bcc2-4cfb-9cbb-76b5d968f237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
264164f1-59c9-4986-8b1e-f5f01ef53fba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
264164f1-59c9-4986-8b1e-f5f01ef53fba	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes		Yes			
75b964dd-c34a-44fa-9995-866da31978e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38a70e03-04bf-4157-833f-012db2ce995b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e41825d-09b1-4563-bd40-7182815d6176	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e91890db-6a9b-43f4-bcf1-91bf333bfc1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
584525ef-f962-4629-9767-2ad69194ce60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a4a6a29f-f5b6-4cbf-927f-fb73b4066d63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6ae425b-fe29-4135-899e-cfa277d45ea9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
64bbde84-7d3f-4a09-aa67-6b874026f4a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
839639b9-f643-48a0-8a49-0a0eb588b40f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c082bfef-2069-471f-8c70-2c5019a84ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7f914a3a-9b02-4bf6-82b0-cce877bcfc88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9d7311b7-843d-4613-8bc9-6020aa6941f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
99b5476f-61e5-484a-bddd-499e3995c5f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50e3c421-20d2-472a-9271-b8546cf3efe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
67a977cb-a8d4-4c6a-bfd2-8cfa9821d01c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85fc4bcd-3e7c-48d5-8394-b11b84efc293	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
678f4a92-7f69-4e0a-9e2e-53322e5f2d54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
678f4a92-7f69-4e0a-9e2e-53322e5f2d54	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes		Yes		Yes							
16dcbfdf-d4b6-4c80-8bad-1fb2f2bea6396	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/09/2023		Nice						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
c9973fe7-15f4-4676-87e5-9b7796b46b94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
4f47dedc-48c9-4d85-8cda-76c134d5aa62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
4a3f038c-b3bb-4377-acdc-04a20642297d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
863cf17a-1f8c-4416-9432-218f7f411b7c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c35f6b8-0ec4-40fb-bd68-5996b57c785f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1f8ef7c5-bf9a-46cc-9ed0-dbd9d34a9fd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b2ccf62b-a65a-47f7-8ad5-c2744aaec37f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f42c2300-685d-41fa-8183-7319df9305af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0cc11e74-a3a7-46d6-8f13-284cc9091692	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes					Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
88171d08-8dcc-44e9-9b6f-de881e968b60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:04:00	TRUE	FALSE			en-gb	10:04:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6010b9f2-b376-4538-a125-31ba6bdeda2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1e6a216d-86d9-41e1-b79f-58eb3071bf97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:21:00	TRUE	FALSE			en-gb	10:21:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3a511134-fb2b-4e35-a516-a0877a07345a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/09/2023		Mop with clean sanitized water, change it out before finishing whole bathroom	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3a511134-fb2b-4e35-a516-a0877a07345a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
c182ff68-b008-4bef-a851-e5680415a51f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
83be7fae-38dc-420a-af19-1333b6b0fcf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fe4cb564-752e-460a-b5d4-32e000d2a4e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	06/09/2023		Horrible	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes	Yes					
3194a7aa-a478-4d87-8ad2-70e8e18c61c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/09/2023		Vvvvfhhhhcggg ggvvvvvfaaacsss sse	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
3194a7aa-a478-4d87-8ad2-70e8e18c61c1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes				Yes		Yes		Yes			
f9bd9186-43ad-41ad-b69e-65292529d45e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/09/2023		Stupid bathroom						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
d973f119-5536-4139-a04c-aa1d622ba52d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ae3a8149-136c-4141-b07b-154335c3b244	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
b0101c0d-13f2-4dbd-a627-6e9df1ff3862	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	06/09/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bffa8f8d-9910-476e-892c-92b881200155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46bed297-30de-4f9c-8a53-8728f3a035ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed77f369-7f60-4655-9336-8fad1459d6c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6dbad864-ab51-4e32-bced-c53221054022	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/09/2023		P	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
63822a7a-ba6b-4b03-ac59-ecc5202acf3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/09/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
63822a7a-ba6b-4b03-ac59-ecc5202acf3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
126fd4fc-3fd8-440a-b31f-3614368c1dbb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
26c909b7-b5b4-44f2-83d8-9840b562781b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes	Yes	Yes					
be1786ca-a127-4f32-9d16-1686ee138ce2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54be4b5b-9089-46f3-ab1d-6f6a615f56a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3b0a7510-f91a-4331-8842-841d37175c41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
79fcf570-dcfa-4084-9256-c71733e1a051	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f888620e-b2ca-48a8-b0eb-f2cd6d5c4f34	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9cd5326-6cd5-4da7-be39-87dc3004c028	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/09/2023		Friendly staff
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5115c63c-54e1-48ea-b39f-e62ef25a1fe1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f4768ebd-e9e2-4f4f-8071-4d7415dfef97	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2abbabb5-8fdf-4235-8461-8e180807486c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81df2e56-890e-4642-a503-e6f3e602ab93	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/09/2023		Todo limpio bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
181e03ac-6599-453d-974b-b8d3aac6677f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
815d4624-eea5-466c-b0be-053011daf231	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2ef8638e-e76e-4d80-8496-75deee4f6019	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
825f86b7-39cb-4def-aef0-ce18cbe1af11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes							
eb65de87-edbf-4ca5-be8d-a3edec2c9e12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
509e2834-8a6a-4219-8436-268215001032	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8003eb94-faeb-4b12-a188-b3751a8cb2bf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ab8faea8-b15b-4f63-a5ac-e27fd8862a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
33b6c4ba-2301-4fb8-8d93-cad06ceedcf3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:28:00	TRUE	FALSE			en-gb	13:28:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
af16ed93-6f1f-42de-8e55-bf4474c6a304	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b1995a86-575e-4fb3-acd3-f9a6d6f28db5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c7c5b27f-ea9b-4f1e-9520-0ab91bed5284	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6f7ae18-9764-417e-8121-1e47b16e473e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98cf75b3-7281-48ca-bbb2-9fa8b5365efb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6048e928-6be1-42b2-a7e6-ba38971ea0c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
be9955a5-f8b0-44f7-9ff9-9b582a464e51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes				Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fcd585c4-31e3-4f59-ba0d-79a620c6d5db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
028c2297-1f56-44e3-93d4-0c188af479d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
96a2e7d7-fdbd-4ede-b983-3573cbffa0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:05:00	TRUE	FALSE			en-gb	14:05:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
01aa4338-0507-492a-b279-35ba500538a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
27719ef3-ee5b-456e-8f94-9996cb98e723	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7121f677-d25d-468f-ac70-799344ff612b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8e488308-04da-4d31-b12f-6a6bb4d8db87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11429aba-cf8d-4369-bfba-6be6c34c4693	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8019c8ee-4bc1-4190-baba-12b30a5f22f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b781fa4e-414b-40b5-a2da-3cf4ff7874db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:36:00	TRUE	FALSE			en-gb	14:36:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
88f1c881-b15b-4af9-8556-80e436b6a2e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d6461607-1f50-4ea4-9ca6-9964a0491b48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
741c6ec8-13a3-4eaf-b80c-ca6fa8ae7755	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
abc6f763-3682-460f-9712-7ca5efa95789	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:52:00	TRUE	FALSE			en-gb	14:52:00	06/09/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
0e6a82b7-62c6-4329-af2c-30ef8ce4a984	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
411e2c52-fbcd-4052-97c4-e351774f6ba4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 14:54:00	TRUE	FALSE			en-gb	14:54:00	06/09/2023		The soap dispenser broke.	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bbdfdd35-c31b-4904-9a70-b5a526adc53f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5813e744-29c2-4841-a11e-5583417a2253	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
53bbc8a2-ba66-4be0-890d-4afc46dc2e81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
79a0ba56-48fb-4bd2-b0f1-d8b3418b44db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a7c946d-e7de-421a-b4eb-fac220ddb30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5d598a3-f287-48e6-8dbc-f09fecc899e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
96c0ff29-3b14-47cc-a494-8a79d4448663	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c819f429-880d-4053-b8b6-f98b68189afa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c39a4baa-895a-4348-a3ea-e32f22fd3377	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d137027f-993d-4171-9c45-f4fcad29edd2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
136564ae-d868-46b8-a42d-77ddd8564aa1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2981e78b-bf64-4836-b2b6-e5db6ef781e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b3331026-2289-4054-8508-ec9817d641a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f93858d1-27d9-4a91-87ca-927bbc0baabe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/09/2023		Thanks
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bb877a4-4c4b-4ec4-b000-6274b466c456	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:55:00	TRUE	FALSE			en-gb	15:55:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e6da446f-6159-47b6-8da5-49dd913d0df1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6d0eb3c8-3f24-447d-9d8e-086dc4338b7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
31147f86-76e7-4d08-8d01-712617c60157	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:10:00	TRUE	FALSE			en-gb	16:10:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
91a88334-4742-489c-9638-43fe5825383b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:15:00	TRUE	FALSE			en-gb	16:15:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
62cc2516-d4f3-477e-aae9-685acbdfdc11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f5038ae6-eb2e-4104-b74e-e4c7c4de2efd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ae264de-512a-4add-a94d-29e59c59abc2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/09/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ad65164b-9643-4f56-ac88-b167c89dff11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/09/2023		****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes														
a407894c-f79e-4d91-a29c-aaf2eeb3f1e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/09/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
112409f5-aa6c-4d83-97ac-084ea1d6719d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0867296d-9862-4e9c-867a-bbfa69becb3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c9c5e8c-65dc-47ff-9bf2-05b5c59991a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5f126d1d-2a74-42a9-8b01-f96129346610	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9a41a4a0-ca79-4b1f-abf8-553a76276417	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/09/2023		***
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
0bb6c6b5-c380-4f70-983b-e5aabda30d55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
17505a54-1196-4032-a359-a6ecb6d767f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ad24e840-e582-460b-ba19-0e56d35c27a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:25:00	TRUE	FALSE			en-gb	17:25:00	06/09/2023		Nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d2e2a066-1caa-47bc-b104-ca83a3449263	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/09/2023		N/a
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b8a1d7d0-4514-46b4-8525-9de067b9860a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:40:00	TRUE	FALSE			en-gb	17:40:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
711abb9a-1180-4164-9b05-c854a9c078e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d384926c-949b-4a2d-ac12-282f362c1a5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
328df791-6ba3-4b5e-b41e-079439b7a425	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b4322c7e-7429-4621-8dd2-d7a078b30704	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77e7bdc3-e5bf-4a84-9aa0-47acc9dce54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
27503b7e-696f-4c73-b6dc-0f02be54bb8b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aa797c6b-08ed-42a2-8d23-784b27f4679f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
030f1bb7-5592-42b5-b9b6-0b8efcbdfadf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/09/2023		Bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f387b6fc-5416-4e9b-95ba-8c3ed5d8dd24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6556a123-2e95-41b5-88f9-214314bfa691	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9ebc57d6-65e8-401d-9a21-ef595570baaa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	06/09/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ebc57d6-65e8-401d-9a21-ef595570baaa	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
587151fe-181d-4256-9af4-ddacf223869e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1551b835-7a45-46d6-9e0d-72adb0fb6a0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:36:00	TRUE	FALSE			en-gb	18:36:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes							
39ea52b3-f66b-4569-89cc-a2d93cc77f55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d8a8cee-c69e-406c-9c2a-4c509f4df3bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:53:00	TRUE	FALSE			en-gb	18:53:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38f415a9-0106-4825-be50-20106e836b10	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81f48e2b-5494-44fa-814b-087cee4fe0d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
84166c60-03e4-4b44-888c-922e321692d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e3205f75-01f5-4d0f-861e-c51a291fbbb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c5feb50-d9f7-4880-88e1-c8c9e8cac5ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d68f39bf-bd07-4c9b-86cf-e9325a903752	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d68f39bf-bd07-4c9b-86cf-e9325a903752		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes						Yes					
f7021a4f-bcc7-4f0d-a651-2a4f0ad9f5e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:20:00	TRUE	FALSE			en-gb	19:20:00	06/09/2023		So clean
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
c647888e-a1d3-40db-bdcc-8b383cd33b24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/09/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
11eabd6e-8e6c-43ea-94ae-f4b56c06cde5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/09/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7207b0cb-7204-4ff1-9a7d-18474ecb2d01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/09/2023		Super
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
de44f190-4c1b-4882-9634-7f542362c155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/09/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dbcfce1b-5ed6-490b-8f4e-a71beac7a83f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3a29d601-d0c2-428b-b9f6-844e43794115	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e867932-6070-45f9-9ba9-26cf16c5e7b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	06/09/2023		Missing toilet paper.
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2e2a9165-0042-4e0f-b7d9-45abbc9aed79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20fc368e-2074-4ad4-b30f-9558d349c1c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b0772dad-caf6-4779-83df-1ff7340315ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/09/2023		10/10
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
214082bd-1268-4eba-8200-a2f29d0289de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
53370458-f1b6-4c57-8fc1-1facb71e8ead	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c818642c-13e4-43a1-ae74-edc3bb6d4ab6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2269683-1537-45ee-a024-33c47b6625c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:05:00	TRUE	FALSE			en-gb	21:05:00	06/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
33150b74-c4a2-441f-bd84-aa9c09fe8e3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9324d9c0-5f8b-4c9a-a4ba-4a078310b219	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/09/2023		Super	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4d04402e-7667-44be-84a2-92969190ae52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab9564a7-e486-404a-9933-d712a1c6055f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d4d5eed-0a2e-4a71-a293-a524ce7e119b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/09/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b0236669-9244-4f61-890f-6d892cb72ee4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 22:44:00	TRUE	FALSE			en-gb	22:44:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2c84cfca-e7ee-4e68-927f-42a2ee2984f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/09/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/09/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9b22fc7c-32ab-4e72-9870-d353019006b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 00:57:00	TRUE	FALSE			en-gb	00:57:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fec9e1e4-5396-4e79-bbbf-1d9519a6dec2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 01:49:00	TRUE	FALSE			en-gb	01:49:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cf5e25e8-96a3-46a1-ab33-d2ee69a97342	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 04:26:00	TRUE	FALSE			en-gb	04:26:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
aef66d85-cf7a-4994-b483-dcf9168a1b86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 05:25:00	TRUE	FALSE			en-gb	05:25:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1ff34da1-222c-4bca-bfee-666d86a73424	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes						
f304eed6-3639-446b-8e61-1f4e3612651a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	06/10/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes			Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4c394e4c-465a-449c-9fd0-4af261b7f11a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:00:00	TRUE	FALSE			en-gb	06:00:00	06/10/2023		An airdryer for hands
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
0c87e7a0-79b9-4899-acef-f4857a6ebc9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
236b4ccd-cc12-46b5-a64f-b095925f8390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
24f267eb-feac-4fc5-9e53-71a4a0575516	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:22:00	TRUE	FALSE			en-gb	06:22:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9dcd5373-71c6-4588-a674-566321940119	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c3385d7-a07c-4370-8559-f2300d037a59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
70019394-03c3-41ae-a9c5-83a84aa28d43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b27f1d6a-739a-4b68-b9cb-b63fc443633f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a81ec92-a778-45f4-93b8-e5617b11f34d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:40:00	TRUE	FALSE			en-gb	06:40:00	06/10/2023		Jaylanie
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e4b85cf7-1fcb-4db9-960f-fc5ad497b70c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
46e070f2-8086-4feb-ba89-bfba323da67e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8cbdd028-eb1c-4fce-9de9-d661cc9e29c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3076392f-397a-490d-a953-5aac3f4854f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b378f841-ee26-4c8e-a4ee-31ff92cd66bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c525a6e2-19aa-49fe-85fe-c66ac112e75d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a0ae14a6-b64d-4097-8479-0809479344e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
21168948-7740-420d-8287-72995ddaefb3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8110a02c-69fe-466a-9dac-67d2f6f2c8eb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e8078953-a5cf-4cc6-941e-0bc3b8d245b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7544c916-47b3-4ea4-a6ef-f792a376a1bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a6b7fff8-acb3-4b45-a098-2bf608f5a0bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
23c347a4-bc5e-4914-a64f-055392989aca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9dab87f5-f26e-496f-9ea4-f8274799a868	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c08476be-299a-438b-8d43-32ea2026dd9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5ee8df6b-3ebc-48f0-983c-556e999064c8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4f349636-85e6-4bde-91fe-aa075e32957f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	06/10/2023		I dont really like it
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f349636-85e6-4bde-91fe-aa075e32957f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes													
a1af49ab-6a7b-4639-a7e4-83eb789ce430	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ae34e21e-a95b-41dd-bcd4-887d8145501c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00a0a6f6-c3ca-4501-bdc2-2ea2bc4fc1b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4b225090-e83a-408e-955b-ab3cff55b157	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
280c16cc-38ca-4e89-a73d-b9312746c716	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:25:00	TRUE	FALSE			en-gb	08:25:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c21753bc-3981-418b-aadc-57fa76e390c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a5d10aaf-a508-4185-b841-9ee590c34dce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e8a4db8d-fa8e-4a22-b619-d889bb69a697	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
60929be9-373b-4952-832f-86f1770b27aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34c614c8-7fcc-4345-a204-39bc7a170ffb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1773c198-d04a-4bf9-9a2f-d390f506beef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54cea9ae-34b1-4b0f-863b-669330f05761	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
35f9590b-c37a-4111-95c0-f716e63c9d01	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e11ffa37-f7ca-4cb0-9a36-b7b91eb7e7a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2475262-4d21-4cc3-aa56-80fdca11bbee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b4e3e86-7e20-4a52-a3ec-35d0bb98c6ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
933d3f42-e204-4d55-b605-2e72de86f85d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e97f8074-c608-469c-9428-5858a561bd4e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bf458a7-50f4-4f73-92f5-0e284e3c0ebd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b8b9801d-a472-496c-917c-a6ffe7f0c87c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28bf9f97-e34b-4e42-a007-8e1b334f8be2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3bf2b40d-93cc-44ff-87b8-429773450477	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6b173f4-057d-419f-9ef9-faa37a1fa3f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fc24e953-6c18-4fb6-b40e-70062a022453	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0e75167f-8d21-4be4-bca5-3ebc3221f4cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3822bf1-7c44-4662-8ed3-3158ebbb79e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0750c1a5-2b65-43a2-bf26-804d46b2cbba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
751ffdc-314a-45c1-a0c6-fb3859f53f73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b12b5478-3ac5-4dda-8744-699468b9ad05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b12b5478-3ac5-4dda-8744-699468b9ad05	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes			Yes	Yes		Yes					
71b62e12-eea4-4572-8131-822fe48ec827	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
54635ec7-4cf2-489e-93bc-2f8fb107c6a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/10/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
34e23a6c-32ca-4f1e-91ee-396d6be7531a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
23232bb4-c52c-4a4c-a8cd-a3a34e4d845e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5196a9c5-8589-4d2c-b95e-70b22a3dd02f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cc113130-7650-4386-b17b-002c58631ebf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ab0da407-cbb9-4e4b-8afc-455ff7a52264	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d938d93f-14c5-463c-bd39-0028d78d5b63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a50fcbb-d70d-4569-babc-835aac55041f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56fafa6a-e3b9-491f-b74f-1465f4a39efa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
56fafa6a-e3b9-491f-b74f-1465f4a39efa	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes		Yes					
c9e7b3d0-7b6b-4340-85f6-50c118fa3838	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
d39ce738-b160-4217-9faa-adea9bf66666	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				
1d3e2836-ce6a-46da-82c9-86999a82c245	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
1d3e2836-ce6a-46da-82c9-86999a82c245	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes													
cfad9ba5-72c6-4498-bec0-35f686551b39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
d82a6b51-5d6b-4e34-8ae6-479aa71d63c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
27a097e9-e6c1-44ab-bab9-c9db06d07af5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
f75b422a-5be8-41a8-af65-6a833ffde882	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
930bdd75-2e8c-45e6-af14-c0e76494929d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/10/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
797ccab3-8c1c-45f3-b15f-1ad40ed4db9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/10/2023		**** on wa						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
ae357730-7528-4cd1-946d-c08d1f1c6033	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
4115420f-2b43-431b-96ff-63deb6649f27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
b5167623-8aea-4079-8124-fb10e7a36514	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes												Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
83bdf9ad-71f0-43a0-b8cb-54d6e9ad72c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a6b1574-6bc7-445f-b6b5-61294762d137	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/10/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
167cf70a-dfcb-489b-98c1-853865371415	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:16:00	TRUE	FALSE			en-gb	11:16:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7fcdcc0a-e73d-4c66-8c09-e46e6cd7d263	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/10/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b0afd93d-9625-4c1e-a58a-b3750703eb76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ec6dc61a-fd60-4d9c-8712-53e173371c6a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
abf3ab7d-1c5f-48b4-bb44-54a021ebb573	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
bfbb0074-631f-45f2-9694-e75f51f99112	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/10/2023		A man jerkinb off and ***** on the wall
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
00a7330e-4ec9-4c60-ab73-ce8a786a7207	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/10/2023		Stinky
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
2ffc5ab-f2cc-400b-83bb-dffc5d7350ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/10/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6d69ed34-c0b2-4c76-8352-a216ddcda784	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34c1826e-9665-4a7f-84bc-9fc7008e251d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d73efa94-87cc-4cf2-bd93-ccf518b2a721	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9aef663f-35b3-4a08-95fe-383a62ea8ffb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/10/2023		Clean
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78a042a8-8155-427b-b0f8-753187689d18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87d3a4d2-12c5-49fa-8552-933dd72847ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
95fcb3a7-4e91-4669-8088-fbd70ed11492	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34ea3ceb-6958-40c0-afb6-1a58de452bdf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e246923b-706e-4254-8bc4-22b3f39b2b9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
73254e92-cb74-42a2-9905-0f79a909060d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ef1ae234-2c86-400b-82dd-14e8e2d92bba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d5271b48-902e-4e69-bec8-df8135e1866b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	06/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0ed62507-532c-4a39-942d-b311cca24457	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0127ff41-af97-4a46-b2ed-7bbdc264a69e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
05f66b98-2674-4f53-bcd9-d46e5c505743	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:46:00	TRUE	FALSE			en-gb	13:46:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c7e45f4f-57c0-4e6f-ad48-ffc9be4c00f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/10/2023		Thank u
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b5c03be9-1fde-40f4-82a7-a7ccf7dc1ad4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7bd2a1a3-b4dc-4641-97cd-b7ee95755b28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/10/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
7bd2a1a3-b4dc-4641-97cd-b7ee95755b28	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
b0581253-373e-409c-b361-d67ad62235a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/10/2023		Potato						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
d9b7a7a3-ac6a-494a-9eb1-ea94f02e4c9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
04fe2be9-7382-4f03-b5d7-3eb21567d0fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
971f4f14-2d04-419b-9aeb-aa2ef6692467	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/10/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
														Yes						

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e55b5e3f-9bdb-47c6-955a-051b4024a453	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
dfcb8643-dcce-44fb-a0a0-1266e0ae1948	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bc2ac12b-dd86-4f91-af48-d3ea1293cf6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5133920e-cf4d-4868-9107-2c616838856e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0e985395-ce77-4e89-8d53-d627210c4746	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c7d97e01-5f3d-40e6-83ec-9354265a8bab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0132895e-beaf-47dc-8c39-4608eae64188	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:24:00	TRUE	FALSE			en-gb	15:24:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
77ff428c-8607-4901-acfe-7ef881c42016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7dd21270-f1d9-4adb-855e-8ed3cf544d39	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:33:00	TRUE	FALSE			en-gb	15:33:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes						Yes							



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
974d29e4-408b-44b9-95ad-72419e389ff9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bff139ac-f1f6-46a2-81ee-13562292b4ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 15:57:00	TRUE	FALSE			en-gb	15:57:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
034a33fd-c9b3-491d-88d9-2cf275dce027	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes					Yes					
d447da19-f6b4-460e-8212-946e8be66fab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c5642cd-c65e-4a5d-a4a6-2ecd5c1ae1cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e211dc34-0178-48a2-94e1-c86bb151921c	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 16:40:00	TRUE	FALSE		en-gb	16:40:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7c22f193-a05b-4272-b3bb-d256350cdd9f	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:06:00	TRUE	FALSE		en-gb	17:06:00	06/10/2023		?	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
aa346119-52c0-4516-9d96-9a2fa632492b	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:10:00	TRUE	FALSE		en-gb	17:10:00	06/10/2023		Smell ****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes	Yes	Yes				Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
98ae4c6b-4233-412b-b263-506e6139a1a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
87dca238-0ed2-4bf3-b8f7-280dd077702a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes	Yes	Yes					
3baf44ce-348a-4361-a183-b3568677381a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bf941818-b1fc-4e1f-b909-f2b7cb7f89c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/10/2023		J	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
507f2112-9ed3-4006-9250-5e1a5cab0239	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18c8f465-16eb-4794-a78e-0473268f8c1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/10/2023		Ew
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
1082c6cb-713b-48d8-9a36-868285aa147a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
45f16696-5697-4049-9581-2c764a07d869	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
aace68d5-20c8-4bd7-ab23-9b5d416b5091	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
099ea314-bd97-4df1-a8c3-92587ba050ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ba87ff10-6866-47a9-b2a6-6debc2edd525	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
882adce5-7f19-4006-a2fe-2cea3895484f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eadbc1db-3e75-44ab-83e9-0991a8a4c4d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
36cdc53d-7544-467d-b97e-cfe8f8ff7325	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56f5dd45-44fb-49f7-a49b-c790972ba897	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c8b42e0d-240b-41bf-a120-71e903ae6a73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:23:00	TRUE	FALSE			en-gb	19:23:00	06/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
48e54240-5adf-4ddf-8dc3-dbb2a4c0fab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fc160280-985b-4b12-a67b-bc88b1596817	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d0505470-ca62-40e1-81db-c66761556cb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
753cd927-a0b8-44bd-af08-6e4dd416aea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fbb70c85-250a-47b7-9a77-66ce393c5898	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:14:00	TRUE	FALSE			en-gb	20:14:00	06/10/2023		Good job	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
095b86b0-f0d1-4d50-8e4b-801686f8cd6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:17:00	TRUE	FALSE			en-gb	20:17:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2a230a1c-91f6-4180-8f47-77c092281158	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9def31ef-7bb0-4f39-970b-9d2a19b0df49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/10/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0af40a16-6293-4260-ae22-37d8ab221195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9f973d11-10fa-4d1d-816f-99fa14d486c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e990a0b7-eb13-40a9-b7f8-2df7329f68f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
36c874e7-7780-4cd5-9761-e49ac8af4a81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c41f049c-3a38-47ce-af77-2b29856ea0ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
87afb74a-658b-450a-a0d0-515856c842fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
87afb74a-658b-450a-a0d0-515856c842fe	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
ddefadf6-9af2-4e99-a8e5-b9c953a1d233	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
05707bf-8279-4f0c-ac22-6270e76ed9c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes		Yes								
4664e03d-7bbd-4caa-afc0-9d7cdb30e1af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/10/2023 22:05:00	TRUE	FALSE			en-gb	22:05:00	06/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cd50cb89-2bc5-4526-a22c-dfbd04a97f37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:02:00	TRUE	FALSE			en-gb	00:02:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e472036b-728b-4277-b9df-b1963cde3e93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:15:00	TRUE	FALSE			en-gb	00:15:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bc7b4d62-ac62-45c9-9cd1-a28f105224ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:27:00	TRUE	FALSE			en-gb	00:27:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3ee86c4a-f8cd-4e53-a55a-6e7221bba5a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 00:32:00	TRUE	FALSE			en-gb	00:32:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
722a1b1a-5359-4833-a61b-aae6937a9d7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 02:32:00	TRUE	FALSE			en-gb	02:32:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ad89a968-a1a2-4a60-ae37-82c5e53d8777	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 02:34:00	TRUE	FALSE			en-gb	02:34:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ad89a968-a1a2-4a60-ae37-82c5e53d8777	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
4d31f9be-995b-457a-b4f9-7725890452e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 04:47:00	TRUE	FALSE			en-gb	04:47:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
4d31f9be-995b-457a-b4f9-7725890452e8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes					Yes						
0b77b366-4150-4b63-8f13-c0d9f42ec40d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
0b77b366-4150-4b63-8f13-c0d9f42ec40d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes									
528320fd-164f-42fc-af6f-fe3c839fbf2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
edb4ad22-2f58-4fb4-933c-97effc6a2309	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 05:50:00	TRUE	FALSE			en-gb	05:50:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eba38d66-e442-404e-b443-7fcd813213ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:04:00	TRUE	FALSE			en-gb	06:04:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fcdd38f1-eea0-4edc-8ab2-d62d989b70f2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes		Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c34f4893-db9c-4336-85e4-2865db32e44e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:20:00	TRUE	FALSE			en-gb	06:20:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a3834b2c-36eb-4e6f-86ff-12b7a2cf1395	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
58b5f4af-96b3-44a2-9119-5c0c9c90449a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d350ab4c-49a0-4f4b-ba18-3cc43f8d35a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f829449c-8f17-4994-8abc-a189361205ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d7f95e11-3423-4dc6-a094-8515172ade7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5860296a-1db7-4b87-beda-5b16aba1585e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:50:00	TRUE	FALSE			en-gb	06:50:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b9c3808-b77c-4c32-ae4-8a7059b5a644	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
55f54c44-f0f9-4643-9b78-a5cac7e3a5c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a69dafef-75e1-4517-abf7-e838a12bd56c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72b6446f-4861-44ad-991d-a32bfd063d71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c99e9602-b443-431d-a013-73711045edb2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f36e4bec-aa6d-45cc-a67c-dfa4013d984a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88533938-cc85-4780-8da0-893b965a2c2b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65860b50-1121-474b-a9da-4420a5da6736	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8678014a-101c-4f3d-a890-413b0fd9c9b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cbc655aa-3e67-4014-a5b9-5d7118bd8f70	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f88ef87-bfd3-472a-b232-894c39d1aff7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e14ec6c2-bf4c-4734-a661-b1c7b8b42192	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6dbe1841-9d69-4006-9289-9c243fe977db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f869216a-2953-44e4-87d2-fe6ed8388cc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f5a43445-aae4-4ee8-8a73-23c9ecff6552	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5d0aed53-6e04-4e19-9c08-9f6602aeb3a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5261e668-6cfd-408c-a9bf-47850ab4d660	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bdf86701-ff95-48a3-a52d-2fd72cf393df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72d3dde8-d373-4d70-9b4f-1602bbd85f1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c4752391-156b-4ee9-80c9-8323e4539209	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b76e1e52-62ba-473c-a628-004ccd8f0333	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a15df1fd-0209-4b13-bfda-0e6d5bed75a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d424ef5-626d-4474-ba07-f656a317df64	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
14eefb42-ec7a-4d73-a7f5-81b8d35e7a51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
03159841-2df9-4431-a324-a9bc6d70d2ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2142778a-9fd9-405a-94b2-3cd266b4aff8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:35:00	TRUE	FALSE			en-gb	08:35:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c0dd9a43-c516-475a-acfe-a294f680c24e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1554c49f-99a6-48c3-8277-0f82225a7647	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d2802d1-3fff-4747-a065-290167bb6a94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
f37d3e92-c96c-4ebc-abb3-fbd2208abd56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
19b4fd99-ffa0-4d90-b9fd-e52ec69b35b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
1c74c8c3-ae53-4003-8711-09b83caefe04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
e708cb75-8fa4-466e-81ce-473697cb046c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:32:00	TRUE	FALSE			en-gb	09:32:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1923927b-a2f7-42e5-a858-4d9dd53f539b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7b234639-f39f-4079-85d0-ca2f0d70a366	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d7532332-14a2-484e-9878-c35e2a69c51a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7821181-f5f9-4cc3-9382-e800436830d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9754bb9-21d1-497c-af1a-604946b0cd60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
289e31f5-08cb-4d83-a716-4d7f20485e46	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
18ec2f5b-5a1a-4023-bc63-a56542483101	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
068164c5-9396-4d45-97e7-f31580d2a3de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
a1c36136-3d0e-4594-a2f0-52f62b756195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes		Yes			
eb46c44d-e5f9-4042-a07e-01c2486a9778	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eb46c44d-e5f9-4042-a07e-01c2486a9778	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
06277600-20aa-4ac6-922e-f3c39cc637df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37ff4416-fbe9-4b25-8b0c-d56096254751	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:19:00	TRUE	FALSE			en-gb	10:19:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes	Yes						
9d75ec74-82bd-4ee3-9b7a-6c09d870c4dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/11/2023		Hott	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cbb1cd6e-8f02-4365-a0bd-6908677260c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:25:00	TRUE	FALSE			en-gb	10:25:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d1777d62-14a0-452f-8b7a-7f6dd5156e87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:27:00	TRUE	FALSE			en-gb	10:27:00	06/11/2023		Sucio	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b3ec7014-b224-43dc-b23a-492671b6fed9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes					Yes					
					Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b708e70a-b370-4186-a137-da0142f23fae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
358dc14e-3dbd-4ade-b4ed-9dfd4304251c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:32:00	TRUE	FALSE			en-gb	10:32:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c7970551-e617-49e2-91e9-db28e3aeb879	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0ae6510f-1446-4651-99cd-820e606e332f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
46f63fd0-0b08-4489-9c27-b63b3236484d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
76eedf53-5357-4e8d-b113-352d00ccbdbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:41:00	TRUE	FALSE			en-gb	10:41:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a49e17ec-b57d-48c7-8661-396eb2cb6780	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c8bbb415-91ec-45bb-aabe-77b90685fdbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b148186f-ff13-4c04-a6c9-1dea0374ceca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cf3a7a2a-b116-42a4-a958-ac66e3b94abb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/11/2023		"
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6a7ed52a-527e-4578-bdbf-b222ac089bf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
356c4971-cd6e-4659-8dc6-86e6e3246a84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c6f81518-b998-4216-8174-3158c69438da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a420276-0dc0-4289-a015-0b3860d3aedb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/11/2023		Georgina was exelent,,,restroom so clean.thanks to her .thanks georgina for been so good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
623e0662-45d1-4fef-8542-1af4bf9df767	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/11/2023		You dont have to tuch the toilt
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
302de6a7-8aed-430e-b369-32d2c7b7be87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
22a298f1-927e-4033-9e83-7e6b9c28cfd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d3d5c99a-78c5-4e3e-a133-ad80ed4b9074	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9834bb7c-57bf-4e4d-bdb6-2e100ef5b67e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9834bb7c-57bf-4e4d-bdb6-2e100ef5b67e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
b71115bd-36b2-4d73-bbd7-ada19cee6b08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:17:00	TRUE	FALSE			en-gb	12:17:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a6682b1-6464-4928-a4c9-674d1d229634	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes		Yes							
209ec196-2d88-4c05-aa95-3d27039d145f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:30:00	TRUE	FALSE			en-gb	12:30:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a91fe0b4-d30b-42ee-8a4d-4ac239efc55f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6ad41e2f-a1a8-46ad-aafc-09719ff175d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f603d6ee-2894-4b82-bef0-9fe64e333668	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7c0ba232-cade-4bc0-80d5-b5c469b7cfa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3e8feb78-34a6-4b48-803f-2271974502a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/11/2023		Hard working employee.
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2b252b82-2621-4979-9765-2c7398181017	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d04e1b2-f24c-4de9-92f2-bf703adf9687	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cf80a3cb-a821-4acd-bf77-376f781feb9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
06739040-eb7d-4c61-a4f7-e434372c0698	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d8b3a861-08d9-4223-a738-b3c172ea7870	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2f0098f8-c013-44a0-b4b0-f630693a2141	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2f0098f8-c013-44a0-b4b0-f630693a2141	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
f2793392-62d5-43e6-ad41-9f67a1d0bb3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9c66ef54-6531-4664-951d-f1245d7c1d8f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d0361ef1-551b-47c7-9221-ab99c308e56d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74ec6db4-b148-4449-a117-662c5a75a23b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/11/2023		L
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c7fcaac-58d6-4ffb-a08d-ae8b8efc9be0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	06/11/2023		**** you
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5c7fcaac-58d6-4ffb-a08d-ae8b8efc9be0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes				
68259338-b366-4593-a40d-afbf3a2689f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/11/2023		****
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
025ca0a1-74da-45db-876a-371c68187dea	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
025ca0a1-74da-45db-876a-371c68187dea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
372fe44d-423e-482d-9755-ea4feace368a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
95ac27e5-d5de-41ee-9812-ee479a8671cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
94b929bb-51b2-4c9b-8248-5afda6bb6f09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes		Yes						
4671b988-d167-47ff-92a8-c4f0527c45d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:56:00	TRUE	FALSE			en-gb	15:56:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e87b4347-8005-4df9-968d-d9c196348fd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
172fcb81-7276-4ee5-af9d-f0454e31fa87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1be4acfe-46d2-4bdb-95b8-19166d377ed3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:01:00	TRUE	FALSE			en-gb	16:01:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cb1d8475-ee60-4ce2-a3bd-4e9450b3ab31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/11/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes	Yes	Yes						
757dbae5-bd5c-4792-832a-a0493f46e241	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b11b3f87-9bfd-4151-89b3-c2fe5492c092	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
166384bd-7c9d-44ab-a708-b726a30a0b1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
23df0e97-59f9-4910-96d7-63571b82e764	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
e3eac49c-9bb7-4b8a-8693-eb2c394c7c30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
7392270f-92eb-4f0e-b9b4-cb1d0981ea81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
9650019a-7148-4fe7-8ae7-28502e44fc71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	06/11/2023		E
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
12b4da8a-b07d-4c61-b698-1dd7c294a58b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/11/2023		No
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
12b4da8a-b07d-4c61-b698-1dd7c294a58b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes						
cb5006c6-610b-40ae-abbb-61a23c64bcc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
47f00971-3cc3-4848-8200-2bf0a0bf3433	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8007a9e8-6f56-4322-a28d-aa57b185b4c1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/11/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes			Yes	Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
4f9c7c33-7e2c-4183-960e-c32b79aee02a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
27fcc438-1d52-4d3e-85d4-0668fee92961	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/11/2023		Clean up		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
3c8fdda7-7759-4b73-87da-0b4b7088c992	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
1d3f9295-37e1-43be-9532-9ef8df11f4c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8301b88b-1535-4e48-a2fd-374a63bb1af0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:51:00	TRUE	FALSE			en-gb	18:51:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1336f87e-62db-4fc7-a904-9f19cb5a21e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												
4e40a31f-bb07-409a-b5d6-a197f8dba67a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
af35ffc7-f295-4b3b-a5cf-37ed6e7c6455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/11/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes					Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54fa1e6c-5143-4624-b66b-3f190b983a20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
a2872cc9-c676-4402-8665-848cbc17fff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
4772d8ee-9401-4880-808a-58ad82e23c08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
06616a59-095f-4c66-9b7f-0fd9a89fff7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/11/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
fc0518d8-1e16-46c6-a52e-3a29fb34c115	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
abc23f64-4613-4b3a-9a43-94f53fbcafef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
fb374123-19c1-4b69-86ed-ba7ee5a2f566	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/11/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes	Yes				Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cc1b247d-4514-4ccf-bc36-990c13e5138a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5d4ec764-6c28-4d90-a4d8-8cbdf6305785	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												
ac1dc87a-42a6-475f-a1b6-5d0d2a82deb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes	Yes	Yes				
86c1f095-1e0a-4c86-b7d7-9b0008405f40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
9d45b2bf-ea2c-4759-9e42-807b57666cf8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
cc5fb91c-73a8-4ecb-bef6-c797419ea88b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes						Yes						Yes					
c316d19e-db37-4da0-a1ba-753375a0b0d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
45290438-c6aa-490e-95b3-bed96c2eb4b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/11/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes		Yes			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a4d1be11-259d-4022-ab0e-98a446f3db3c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9957fd2d-8733-4155-89d0-7116aa916752	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d26ab7aa-c868-4988-bf68-264bfe87f73c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	06/11/2023		Hot	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2bcd3122-dca1-476b-aece-35b11d7afb3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2bcd3122-dca1-476b-aece-35b11d7afb3a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
3a75b797-964a-4a73-b896-7c8e0a8cfe05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	06/11/2023		Really nasty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
bdce547a-a3c8-43dd-9faf-16d7b8885161	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:04:00	TRUE	FALSE			en-gb	22:04:00	06/11/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes					Yes	Yes					
050f6d82-0e08-4743-9df1-ffa4fe6db4e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	06/11/2023		Gross	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
050f6d82-0e08-4743-9df1-fffa4fe6db4e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes					
ff780245-6dfd-4350-814f-6d7eb60b0c49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7c4d5509-f88a-4a03-9828-26505606a282	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:22:00	TRUE	FALSE			en-gb	22:22:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b4aa1f0-1c05-4791-a4e3-75e3d5b53b0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:33:00	TRUE	FALSE			en-gb	22:33:00	06/11/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30916513-be64-4c9b-b7f6-16aa31126e22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes							Yes	Yes						
7397cf38-f3f6-46bd-b4c3-c525b23492e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:39:00	TRUE	FALSE			en-gb	22:39:00	06/11/2023		P	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes		Yes						
7e581a93-be67-4e7d-8cfb-0372b2c6d630	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/11/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7e22e0d6-b3a3-4334-8c3d-2afe0397ae5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 23:04:00	TRUE	FALSE			en-gb	23:04:00	06/11/2023		Dfr
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9ba8f24-c20d-464d-b200-dccedafbba89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/11/2023 23:50:00	TRUE	FALSE			en-gb	23:50:00	06/11/2023		Very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
68d2e339-e6ee-4b3e-bfc5-e945ae3e2f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 00:55:00	TRUE	FALSE			en-gb	00:55:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b03ab3a-d5fc-4932-8b46-01fee3bb8214	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 01:21:00	TRUE	FALSE			en-gb	01:21:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3e8a6fb6-5def-4c13-b981-86e8782fcc25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 03:17:00	TRUE	FALSE			en-gb	03:17:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a88b7fe8-5a47-4279-aa38-12541b8838d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 05:34:00	TRUE	FALSE			en-gb	05:34:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a88b7fe8-5a47-4279-aa38-12541b8838d9		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes						Yes					
a69a3b93-9d9e-4743-b260-04b9e4fd67e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
efe9dea1-38e4-4f57-987f-bc24d362b971	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
e13aebc3-824f-4fb0-9738-3cb6c79e5584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:15:00	TRUE	FALSE			en-gb	06:15:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
2cfe910c-9614-41e0-a78d-0c6ea7c176b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
5bbcedda-ba16-4ecc-8fd9-718cd1cad420	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/12/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
85c68f98-652b-4ab0-a70e-b71a4c74cbfd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd12dd5f-021a-47d4-8c45-2802458deffa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:44:00	TRUE	FALSE			en-gb	06:44:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a782116d-fdd2-4f40-a621-1f5108baae0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
20032978-d75f-4c0d-88dd-cc538529be52	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ed480a15-391f-4e2b-86d0-d7488c3acdf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:50:00	TRUE	FALSE			en-gb	06:50:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
da83b6c3-c86b-4e49-8202-a255949d5412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
e0cda24d-e225-4405-833f-32e850425ab9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
781db705-f274-47e0-96d5-df9e57094e93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ca55ee9c-ef9d-45e0-a7ac-9e30bca851f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:02:00	TRUE	FALSE			en-gb	07:02:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ecb9e20d-fd0d-47e2-985e-0d30c451d6b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
be25f956-e965-4bc6-b932-402458fb9db6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:15:00	TRUE	FALSE			en-gb	07:15:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01ac85c4-8ec7-470c-9ce9-337a3ee04b9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1f57bc8-4724-4574-a502-2c20c0fc0359	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
193ff26a-3d2e-49e3-be14-e4439397d677	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
adbfb11-5a25-4dba-b9df-b9885683a282	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d330bd6-f9e7-4ab1-afef-c531cd97d483	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/12/2023		Like clean bathrooms. Thank you
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
127df3c7-6739-4569-a2d4-5c178aaade7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:42:00	TRUE	FALSE			en-gb	07:42:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
153d9f6e-1943-4e72-b2c7-0ef6583e5a7b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
5c03771c-b865-41e4-8073-00238424a372	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												
b514655f-3c36-4a99-9e20-8810ba4cc92f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0a46a657-5ae1-4cb8-961c-a151331a011f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:53:00	TRUE	FALSE			en-gb	07:53:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28f8364a-04c9-4f83-ac41-633d77eadf68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:58:00	TRUE	FALSE			en-gb	07:58:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a06b5192-9aae-4145-b328-a7025e966b0f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8ac3f991-f274-4fc6-86ab-4afe29d5b431	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d3698594-ae36-422e-88ce-a8708d59126e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6ffe0434-b623-4ed5-9753-ffe77119193c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
213904d8-4ffb-4924-8bce-7d56c2d6faf9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
42928b5a-2fe5-49b6-86c9-cfe404b7a94a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/12/2023		It was hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4c2e8621-c99e-4d28-8b0f-779973994c2f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
27955576-57c4-4dd6-8d9b-2446fc73c203	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9c86c5c8-d644-42d5-93c0-01b4f226e1ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
83cc21d6-e395-40e4-9804-b5e80a30cdd0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea84ec57-d911-4246-b0f6-6d5f1fd16106	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0f0c14a7-da51-4ff2-b05a-66d853e707b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae8a3921-2a69-40fc-982f-cfe9db106a27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0ae7b830-ec16-4d60-a934-73f8dbe6d601	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2975e29d-e2dd-447c-b3fe-36a79c503451	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
80925aae-6bea-4c40-9275-7d8a29bf4e1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
29abb923-5bc3-4d7a-ae1b-8dc61e781fc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4524cfd-74e9-4117-a7e0-2a05747f457a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e443f4d1-1678-4770-8b29-3b72a6c3a556	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3d0242a-f3f6-41ac-b646-9920bce92330	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ef024f14-e497-413d-9af0-b04c8af5a23c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef024f14-e497-413d-9af0-b04c8af5a23c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
4d834889-ffbe-4c35-b37a-e3e7ca712c8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dae05513-977f-4145-844b-5cb233eeb3fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c4200e8b-83cf-4ef0-880c-405cb9fd728e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/12/2023		It was hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
0816d5bc-4274-45be-b66c-221a03bfd64d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
41ed61ae-d0e2-4883-a5aa-8aa982657b2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3afdd49f-b26c-4cfe-bb78-2e36eb6ba4d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14287268-54b4-4849-b556-70945e5f39aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3e06c8c8-32eb-4a46-9c45-e606378f29b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fb2a338b-4bb6-418d-8a62-b61832d9d80f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:32:00	TRUE	FALSE			en-gb	10:32:00	06/12/2023		Terrible conditions, hot as balls.	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb2a338b-4bb6-418d-8a62-b61832d9d80f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
						Yes			Yes	Yes				
d1c6e158-e934-4123-9de7-10262ef3e36d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
677981d0-524d-4d9e-abc1-4dc60633af1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
66928f3a-f616-4547-9d84-065d5d274390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a78d2ecd-b983-4b0a-872a-27dce39b4ede	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
44c604f1-5e3e-47b7-a02e-65f19623ec13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
497ea655-86f3-46b0-92f5-0febb5d80fc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a0fa7721-a9bc-401c-8087-40e0524d07e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3e7e6c5a-6636-4ee8-98d8-a670f7484390	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
95a31a6d-6898-46c3-bc32-2565ecd0ee0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
3949b1e8-c3c5-4f3a-bf93-99e2e8644efd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
80db8d9c-e663-4dfc-9ba5-5b434b8aa7c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
d6b134c8-225a-4556-b325-a8c2c5c0e146	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/12/2023		Nk garbage in mf		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
61a08e63-beb7-4aff-8a7f-ea99c37f7dcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
04a82d10-8a25-4e08-9898-f51718edba60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
ed4825ce-6e36-40e4-9225-c1e0557445c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
0760f355-e67c-44e2-bed3-67ef6305c0d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/12/2023		Good job															
														How would you rate this restroom today?															
														Average	Good	Poor													
															Yes														
001b443f-1f23-4b40-bcf4-bef70cce2507	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/12/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3a934e55-3b50-4479-b989-25b1d562633f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
60aa678c-185f-444d-9238-8aba0f7d157a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
703c0dc3-bbc3-43c7-ad6b-3ac6963541e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Gate D10 WRR	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
02bf14ff-6fac-4d4d-9990-eded2d1f3745	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
649bf18c-ca14-4558-aa48-f7f44dca6653	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes														
52223ccc-1504-4320-924d-5d9b3fed8f7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e167bb80-99d4-4b43-b731-3f56a21ef63d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f4a7989e-b442-420e-aaf4-1a8a72e2808b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
f2d6eeeb-de37-45a8-b11e-9cd5e8397bcd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	06/12/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																	Yes											
6cdc9553-bf53-4173-8591-2a2a451b0840	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/12/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
1a657bab-a429-4f0a-adf1-1e31a91ec631	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/12/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
36b000f4-df66-439e-a241-91b4d6efddc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/12/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
9bbb80ba-9929-4d24-8d14-b63d128cef16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 12:58:00	TRUE	FALSE			en-gb	12:58:00	06/12/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9bbb80ba-9929-4d24-8d14-b63d128cef16	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
a1cba269-61a6-40df-855b-2c71f12531a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d90b9096-f63e-4bf9-850a-b839ab9a1c06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d22dec83-109d-409b-af46-72a860d7e1d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9adb2376-8c36-4f8d-a429-d04eb16698fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
32fffc41-f563-4c58-bc08-dab9be36860c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e6ce1368-46de-49c3-a15c-75e0d9278ae0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5a21eb78-5ffa-4927-b58c-70aec5a5893	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d2436e58-11bb-45fc-8c71-5945601d227b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
880dde1-87de-44ad-936a-ab383c08ff91	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b4496cb-fa9b-4652-891d-20d9eb36a8cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d561c6b8-6d93-45a5-8195-2b818814cbbd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
44855e7d-6974-40eb-a732-248155577e2b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a8513a56-151e-4b7e-b17b-b50c198dac49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c9fb77a5-9deb-4f7c-8b90-930195236511	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b811fecc-aa36-453e-b2e5-d64b884a0097	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 14:55:00	TRUE	FALSE			en-gb	14:55:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
56a48983-e1ca-45cf-ac17-2c7e6d5dec9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:05:00	TRUE	FALSE			en-gb	15:05:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c5f663f5-9ca9-47f0-bb59-7777c623b3fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46f05838-beb8-472b-b80d-816ba7b1e433	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
095364bd-37cf-4674-836d-ab9ec8d7e8de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
c2f3ceee-5d0b-4326-9bb5-087899895465	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	06/12/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c2f3ceee-5d0b-4326-9bb5-087899895465	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
													Yes							
bb025aac-e382-4db0-bbef-59f76c6c6e1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/12/2023		no						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
65b885ea-c869-432d-91c1-9a5d4a6a4492	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/12/2023		It stinks						
	How would you rate this restroom today?																			
	Average		Good		Poor															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
												Yes								
741f655b-e5ab-421d-8e62-f33e73629f24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/12/2023		Stinks						
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
														Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
99fcb74a-f151-4966-a2b5-4e1c3634e2cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 15:45:00	TRUE	FALSE			en-gb	15:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
805ca9b0-4717-4f13-a531-5526ad62afe2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2bb6a88e-bff4-47b9-80ed-4d67f0112657	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
90315563-16fd-4785-a3ff-4b0367158ccc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
889a5653-436d-401d-b571-93654fd63937	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:23:00	TRUE	FALSE			en-gb	16:23:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
729e19c2-1d02-40b4-89a0-eb05de1d3ca8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4006eb68-62e4-400f-970d-3bc80c71614f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fdd2e335-c164-4e4d-93bb-f720b4534d90	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes			Yes	Yes	Yes	Yes				
							Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d7cbd478-56f9-41dd-aec0-0159650b0a41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3ed4457f-3677-426f-8336-b84685e267dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
09e69043-eb80-4a7d-8293-02d50ff63533	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
033eefc8-bb0e-4d5a-9f64-127b325feff9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b88efe24-c73e-4439-a1f6-0601ea3d9bfa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
128fa270-a16b-4084-bdb0-2b3142d0653a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d738c038-c264-4201-ac92-bc0d63f61a7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
636a6cb7-7658-4b61-97ed-bfb8b4ed41ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
73b9f1a1-b3fc-46e5-98fd-b09e49684ad6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/12/2023		Very clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
16e21ef5-bd47-40c6-b8d1-6580e3c184df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	06/12/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5899d3a2-1f48-4936-9712-29d63ea525e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a0771883-7995-4823-a598-93f4e14b5789	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
61a2c815-0f7f-453d-8cd3-1506cf805cde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9ae0db4c-9872-43a6-a8de-e10a250b3a15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/12/2023		Ac and air quality	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ae0db4c-9872-43a6-a8de-e10a250b3a15	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
478e9425-962e-4ad6-ade5-4412fc6e09c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 17:59:00	TRUE	FALSE			en-gb	17:59:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
16059592-d757-48ae-80b3-f70c2de7ee37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:09:00	TRUE	FALSE			en-gb	18:09:00	06/12/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
60f9a326-053f-4317-b17a-c99bd5f59529	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
a5d4185f-ca68-4791-9a8e-1adb842e7a4d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
8de0ccc7-025c-43cc-a5bd-ad0eb795038b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes		Yes	Yes				Yes	Yes	Yes							
bc5ed00a-7309-43e7-945a-ea8eadd66ba8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/12/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
Yes	Yes	Yes	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d4de4e9b-b8bc-4183-b7d0-3c0b53bc84a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes			Yes		Yes					
9eb95bd4-7df5-40b1-a3e4-f0b2b13151b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/12/2023		no mm	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
76f32c93-cd15-4585-b64b-15a94fea293d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5c7157a1-d613-4678-b2c2-e08b96fa721b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b8124b4f-2117-4450-ba22-e6b3a8750af7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
cd8cfeb7-5ffa-42ff-946a-ae033ffc1204	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
400af746-2e4f-46c9-b903-82fda8aa19aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8a502e8d-b91d-4474-ab5b-a087d0051d0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d2e8f159-a482-4d4f-a383-6b79e3328853	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
77990780-4eb8-49dd-aa51-2f39acfd856a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b7281ef1-28ec-4a67-83ac-8deae34329f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7281ef1-28ec-4a67-83ac-8deae34329f7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
e4bf24b9-e5c6-45db-9d5d-d84e0c5fa4bc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
73f354fd-ef45-4cb0-82af-ae5567121db8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes							
bee6233b-d6df-4e3a-8a6d-a8e02f7dfb41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9d8e246-481d-4b40-b267-8f63a9c2884d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a9d8e246-481d-4b40-b267-8f63a9c2884d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
c97d3856-d15d-4ea3-8ebd-10216c1cf1e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c2307729-303d-4694-a92e-066835e1e0e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
4782cedd-949e-48c3-95a9-8cf8d00a0a7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f46c660c-356e-4dfc-b1f3-5b2dd9d879cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:34:00	TRUE	FALSE			en-gb	20:34:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
bb2efc40-b59e-47fe-bcb8-aa12a3f79780	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
512dc1c0-fa08-48f3-9ec4-0f3d5ce15d89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
250b7a57-6662-45da-9e6f-ba90b9286297	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0b5bc291-7e45-49b9-b6eb-c58c1f7b6849	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/12/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6a84c7bc-c4e8-489c-9b6e-3d31c66a3cba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
023f5b6d-de50-406d-b510-09136fa78c4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
54246e21-df04-479a-bab1-271db1a47579	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:07:00	TRUE	FALSE			en-gb	21:07:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
293b419d-3384-4f86-bebd-cd00733c9c08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
4de63c2d-82c9-4ae2-938f-86bdbe4f8c6f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:24:00	TRUE	FALSE			en-gb	21:24:00	06/12/2023		Mfggnfhgg	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5f4aee8c-8588-45a4-ac6e-25484a135839	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f35d32c-67d0-4282-a26a-cd76cacbf04f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7a573ef8-5744-4082-ba18-75379f0fa5b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
93cbb3cc-7f05-4e3c-af76-10ceada75e13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:07:00	TRUE	FALSE			en-gb	22:07:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1e263787-59cb-4864-94f7-25a343991197	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:10:00	TRUE	FALSE			en-gb	22:10:00	06/12/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
024a4993-c9ff-489c-9f2e-2bd74d9265db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/12/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e673666e-c330-4849-b809-d83fe359423b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fd95e393-703a-4ed9-8ace-b6368ef75f32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 22:35:00	TRUE	FALSE			en-gb	22:35:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
bf2a2751-e312-4012-b85a-a132f7c66506	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/12/2023		Dirty toilets!!!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0d7ba21a-89e7-40b1-85f2-2b77c9f489a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/12/2023 23:02:00	TRUE	FALSE			en-gb	23:02:00	06/12/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
03fe88df-ed17-49c8-aa51-8c22c913b901	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 00:24:00	TRUE	FALSE			en-gb	00:24:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
34181f85-a648-4925-95f0-646b9efc6b9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3e90bb2c-3324-4c21-9d2a-6688c5182a99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 01:22:00	TRUE	FALSE			en-gb	01:22:00	06/13/2023		Lack of counter space inside stall (for wallet or hats)	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eafb1d62-55eb-45b6-af1f-683ed63e0baf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 03:44:00	TRUE	FALSE			en-gb	03:44:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a51200f-21ec-43fb-ac0e-48e54abbe755	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:34:00	TRUE	FALSE			en-gb	04:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b5de2b16-e38a-48a4-a3ef-feaa351d2af4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:34:00	TRUE	FALSE			en-gb	04:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
228268c4-b3d2-4f52-ae17-1912b8f4450c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:35:00	TRUE	FALSE			en-gb	04:35:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
74260fc6-78e0-439e-af2d-b344ba90b036	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 04:59:00	TRUE	FALSE			en-gb	04:59:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9097c511-a4e5-4e32-8e69-23b73d4fcbfc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:02:00	TRUE	FALSE			en-gb	05:02:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3df2e593-1c60-4b67-b0e8-8d197da13e64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:08:00	TRUE	FALSE			en-gb	05:08:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
b3baa27d-4002-45ea-b15f-f87da72dffbc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:16:00	TRUE	FALSE			en-gb	05:16:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
50d67892-9686-44cb-9fe8-d45b60503a1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	06/13/2023		Dirty	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
00639387-903c-42db-bd88-6fc96872037f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:02:00	TRUE	FALSE			en-gb	06:02:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00639387-903c-42db-bd88-6fc96872037f		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
								Yes			Yes			
c239ba84-09e0-4d8c-8664-9d08c4363850	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:07:00	TRUE	FALSE				en-gb	06:07:00	06/13/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
0b863da0-dd10-4680-b2c7-b3737360f75d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:38:00	TRUE	FALSE				en-gb	06:38:00	06/13/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
c5b8531e-0e0a-4f6d-9d43-2ad74c2a1f9c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:42:00	TRUE	FALSE				en-gb	06:42:00	06/13/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
1d12dd67-f6d7-444e-a6a3-da162781cb31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:46:00	TRUE	FALSE				en-gb	06:46:00	06/13/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
93cb2c89-084f-4178-b67e-abddc1597dce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:46:00	TRUE	FALSE				en-gb	06:46:00	06/13/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f6422fba-251f-4fe6-85ff-9b20a58674b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
173ce8b3-1fa1-47fe-9baf-0685ca88ae5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dfbf1ecc-6be6-4854-a70a-a3d6cae5a897	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
83ed098e-f24e-4164-9b94-186608a44f80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e37eb589-b5b1-4528-aa1d-98736b579c0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
444f2b4e-1c8f-4778-847d-c6b500e5e091	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a83bf03e-2103-4db2-8777-a83c0102bac0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b305c07-10c5-4e5c-ae7e-4bb8c45c39cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0a606674-94ce-41ca-b29b-7bbf77486594	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b70c7e1-95e1-4d32-ae60-f848e9d50778	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
751309b5-c8ac-4dc6-b30c-cb2278a2fc9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes	Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1debdab1-3c84-4a01-8539-747afc9c4cc8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
654da83a-72f0-4881-9814-29b3b5079bb1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/13/2023		Naw
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7b41456-7aac-4d2a-9f24-2c7d651c771e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes		Yes							
fe533dfd-eca8-40b1-a6c4-55d27547b903	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/13/2023		Hot
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
31d16641-7a34-4ba1-a6bd-1a8c4927d2ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
83d1a093-0c64-4210-9d94-760b0148b322	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e15da35d-c3c1-44d4-aab4-00e23e599f42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
863023a5-09b2-415f-927d-c8d90303798d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aa1ad653-d11e-4c41-8704-d0a1de2462e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:43:00	TRUE	FALSE			en-gb	08:43:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8363eacc-1fd3-4f65-9bce-a6846c2171c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e5a6e056-aaea-4671-b909-4bb613994495	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ca8b14f-8fff-4df5-847c-1ac293c370b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f19bcdad-8bbd-4c7b-8f31-52be5f5fc218	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
483924dd-f0c0-4a68-82ab-6ce27538da83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 08:56:00	TRUE	FALSE			en-gb	08:56:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
22a4699e-ad90-42b7-8c8f-16b71fcb4a0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a5f6cf59-42e8-47f0-8eab-cb56bab77cca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06b677cc-386f-4ef0-81bd-55b117aa6cfa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
028e312a-e74c-4d32-b00e-fd6126e8ce14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29970a35-47b8-46cc-9728-4bb8a71fcab2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7aa4bf2a-894e-466e-a6da-f08146f94cd2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9047d17-a87e-4c5c-9b13-58210ead7705	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
e760f0fa-7c63-4c64-bf56-d336ca37daf1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
ca5ad1ba-c9da-4a62-b34c-9caa6556d303	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
												Yes							
7eec66a4-e8ac-4c21-9197-bda40629d4c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	06/13/2023		Long line					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
										Yes		Yes		Yes					
e4880fe0-c864-4a31-a3e4-9ff55c9f6a56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e4880fe0-c864-4a31-a3e4-9ff55c9f6a56	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
ecc66451-ce24-4a18-80f4-2f470bacbe95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f77b9d0-fba9-4b1f-b3b8-e71febba44c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dfdd71c1-4ff3-4205-a794-eb17f121c201	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
a981e9df-9b05-447d-b330-8120f4abba72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ee5c1197-3fd2-4715-9223-6863e636d75b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1e0636a4-16ec-404a-8da2-7a29c17d793f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6628a198-4570-4311-9510-6f1a2a08cdfb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:58:00	TRUE	FALSE			en-gb	09:58:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5b4ef037-fd49-4ee7-8534-594e329130d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes					Yes							
d8393813-51ff-48c0-b12d-f7831845e5ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/13/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
17eedca-d9bf-4b5a-832f-c0fe32366277	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:05:00	TRUE	FALSE			en-gb	10:05:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
2b2015c4-eb2a-470a-8eec-71efa9a451fd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/13/2023		Good						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
316705ef-2029-468e-94a2-e8628f561a93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:23:00	TRUE	FALSE			en-gb	10:23:00	06/13/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
d83dd628-d05f-4ed5-b227-e72fd5a8def4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/13/2023		Dirty!						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bc8a7d83-59a7-4cf6-989f-7d6ce0384d11	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f040b40a-d5ff-48f2-a5bf-7523e2ab62f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0d6ad93b-92a1-47ef-9a90-d3294a317329	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
276029c6-85d7-4952-8fcf-e194ce72f98a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c7106e3-fe8e-45ca-8bad-dd86486f662b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
23956c7d-d3a2-4319-bdb9-1b798e0c359b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4378f5ad-b1fa-4c98-8f7b-ef527e5437a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a93c12f2-c05c-4e54-8b6f-fa7fb20345ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes	Yes					Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
039c7cbb-75fb-4d4b-9e16-d22670c8e536	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d7436335-58c6-4c3d-af3b-4b2ccdd4bddc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
19b8caa8-fc4e-48f8-b0d7-aa172a122d15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a7c2bd71-bb58-4fb3-9294-6b069a74b2e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
5ed81215-6a62-4700-8bd9-9855d357ebeb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/13/2023		P	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment			
5ed81215-6a62-4700-8bd9-9855d357ebeb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>
															Yes		
b049d257-7b9d-41dd-b3e1-951dbe4ac03f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/13/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
f0268693-54b1-4044-b223-2ed79203c0cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/13/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
		Yes															
34090bbb-eff7-411d-b2e1-aefde4191f72	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/13/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
					Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>	
														Yes			
00293d19-6d71-4569-abb4-a9c93b0acb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/13/2023					
	How would you rate this restroom today?																
	<b>Average</b>		<b>Good</b>		<b>Poor</b>												
				Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
00293d19-6d71-4569-abb4-a9c93b0acb4c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes						
c6c68212-c2a9-4b14-aaf7-e0e6c3dd0d94	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9b12a9b2-01d6-44d1-adf5-4b4217c12ac9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
c9f0dffe-e7d5-4266-aaa3-f9cdef01ce05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bedba94f-891a-4d21-a8da-a981e88b1f8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 12:44:00	TRUE	FALSE			en-gb	12:44:00	06/13/2023		Muy limpio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1e8c43fa-b29c-4101-94fb-e0d3b37b22b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/13/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69e42f13-740f-4b5b-b4e6-ebbcac6e11cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d09e0d9c-3c65-48e5-9aae-d99accfe484b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6739c1e5-a5b4-43e6-b4cf-a7b814008889	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db51af8c-fa69-4b1b-b16a-f0ffd111ea6d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3cc81762-bf4c-4ad1-a7ff-b9c4680179af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:45:00	TRUE	FALSE			en-gb	13:45:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
3e01bfa7-bebc-479c-9ecd-e9b9d8c8f584	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
92119bd7-6a43-49d2-88da-d86843cd7738	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
efafe19e-f3bc-4c56-9c31-56d2507aa078	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
8c56e86c-613a-488c-95fd-5c27e9e5ddb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:04:00	TRUE	FALSE			en-gb	14:04:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
33d0dba3-2dfe-4245-a02e-f74a479fc318	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	06/13/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
33d0dba3-2dfe-4245-a02e-f74a479fc318	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
8d76468a-d7c2-48e9-b1ac-eb4623e8156d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
65a75a49-b89a-4160-983e-f268b4e5b164	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b699dec-f49f-40b0-971a-f1fa2f916881	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55b2d326-965b-4e20-9186-69deb35f40eb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ca7b7023-c113-40af-ac5f-97c17209bdde	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1cbd307-5277-4ed9-9aa5-2b4186e82894	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9df08863-ed36-4a87-ba10-8597fad5b1d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
6703321e-c533-49e9-a7c2-ec378a17bc3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
7c58774a-26eb-4613-941a-ad76e028f524	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:45:00	TRUE	FALSE			en-gb	14:45:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes												Yes					
5ad31c3b-921e-46eb-917c-15f4f34e71a0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/13/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes		Yes			
13a3398d-3419-47ea-bf7e-d53c882a48c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/13/2023		Super clean					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bb4d374c-3fea-4f98-a69b-1b6d2a70ffcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b9e07b6e-41c4-4d88-b1f0-9b4c4ea4a6b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b2a64d69-ef72-46d8-87c9-6b233238016b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92ee2d0f-2e08-413f-a134-ed097ea53a76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
41613341-a815-4cb3-a900-17bc1ea43c0d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
59d331b1-48f2-4614-ba6b-8413ebd86a0a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f4f3e509-2664-42cd-a4d4-571952b44f3e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34273888-ea11-4bd1-8bd8-dc711a8389a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b52b156-1b49-401d-943e-2e141f170b0a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b789c4aa-96c8-41d6-ac48-67e085729b22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d1052873-50ab-49ec-8668-604a1b1234ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d1052873-50ab-49ec-8668-604a1b1234ce	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
59dc77f3-05b3-4f0b-bd40-4baeedde46ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
625d34e1-0137-4da8-a3ba-90e711122e15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
618aa053-46b1-48c7-9e43-c3b8ebd9f23e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
0e8c9710-aa5e-46f9-aac1-86c20c7e4650	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d53164b5-f8c6-4d04-974f-ae30b7612b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f97b01fd-fa8f-4a1f-99be-0c457cac1743	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
1aa26224-9918-46fb-baad-71283834e930	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76ee4a32-ac1c-45e1-824c-351b32faa58e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1acee37f-f6bb-415d-87e6-4d2d18ce45d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1acee37f-f6bb-415d-87e6-4d2d18ce45d0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
bc9ec08d-5ee4-453a-b558-8653684e7d89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:38:00	TRUE	FALSE			en-gb	17:38:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
cb14ab29-be31-4fa9-a59f-be568d0958c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c6a2ef48-656b-4da8-ab26-a2a41f58fc17	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b24ce356-42bd-455b-89bd-c5c40e117260	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/13/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6cfc4c53-bef5-41fc-ad15-d02d246d630f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
56f41fd4-06d9-4a61-8514-9b8f117a8449	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
27eb5982-c58a-4cd4-9011-9298a0ccd716	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
671b8880-dafe-496c-9d77-5f7b1d07a2b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
708887d5-0585-483d-b9ad-37e2ae587fa1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dcb08305-cd2a-4e13-a5b5-52bdb3c3d87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:01:00	TRUE	FALSE			en-gb	19:01:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
640f5398-e766-4fa1-bac7-0630707e05d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8950ad53-0ae1-4592-b7ea-461e034b36b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e2e73d4f-46b2-44e8-a2ae-9d177a0a982a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
384e06ab-8df1-4e9a-aff2-6fbaec2ebcbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/13/2023		Clean thisplace,	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
51ed9ef5-a764-4abf-a956-6fa4d8e0da65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6f20aac1-3677-4105-8331-80d521682adc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
07919649-981e-410a-8c45-633755b9071f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
422cc430-033a-4490-ae1c-a1592b9323e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
953457dd-cf1e-4bdc-9d39-8c8f13dd5faa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
806df061-d46e-498d-855e-5a0bbe4d88b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/13/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes		Yes				Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3a4c3811-4b2a-43ff-9ab1-7abc4b249b91	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f66b2fa4-d28a-49ad-9f25-62f54165f7d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0ce36dbf-5fe0-4855-a8a1-877bf2291bee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f37cd227-c65d-4a1b-91ac-f54da36cf35c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/13/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f37cd227-c65d-4a1b-91ac-f54da36cf35c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes				Yes	Yes	Yes				
1ee91a0c-ff8d-4303-9283-783ac4f26027	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes				Yes							
40235b91-39f8-4f69-a01d-e08d5e97c606	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:11:00	TRUE	FALSE			en-gb	20:11:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes						
e9d8e2fe-7f2a-4e78-983f-ebee3b490020	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
39e6ce3c-70e1-4447-b19b-ea7fddfa4237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3e8993e8-4752-4b07-aa45-d665c1b32def	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4332421a-9495-4e15-aefe-b1a475aec070	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/13/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d09804a-837a-437c-8773-6febccc40143	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/13/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ec2f54ec-4a09-4f63-b8ed-60824c19128c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4689cebf-51d2-49cb-a4b4-44b40d888120	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
655a2452-6008-4dde-a538-11b75793484f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e957cda-b462-492a-adc9-9ea04d73b9fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2d78203-f112-407d-aa86-4ff4efb0684a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fc422a44-6726-4cb1-82ca-1d980a4f906c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:23:00	TRUE	FALSE			en-gb	21:23:00	06/13/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fc422a44-6726-4cb1-82ca-1d980a4f906c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
6a638dc8-c705-426e-a62a-4e496654e487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0413a0c5-7f1e-45b4-b848-db48c88417c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4884ce57-49f3-4063-bc94-d6e0e78c79b9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 21:36:00	TRUE	FALSE			en-gb	21:36:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							
b857125d-7488-4be1-97e6-9e12389c3966	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/13/2023 22:00:00	TRUE	FALSE			en-gb	22:00:00	06/13/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b857125d-7488-4be1-97e6-9e12389c3966	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes					Yes				
3013ec4d-7e77-4e31-8fb8-12bf221a88a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 00:40:00	TRUE	FALSE			en-gb	00:40:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4d1f211a-442b-47d7-a518-9b4b94d8a949	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 00:41:00	TRUE	FALSE			en-gb	00:41:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a48d436-34af-4ff3-9835-dd536834285d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 02:40:00	TRUE	FALSE			en-gb	02:40:00	06/14/2023		Gg
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc7b0fed-e977-4c2e-b670-e08e08862ebc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
10b9b71f-86d1-46ea-a704-3d5a5c244250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 05:24:00	TRUE	FALSE			en-gb	05:24:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f018ca44-a800-491d-9db3-cff291cdb814	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 05:32:00	TRUE	FALSE			en-gb	05:32:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
07e2fe27-bce2-41a3-8354-0889590ec5e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a7a9abd4-784b-43ed-a3d1-0aaa18877bcb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ba2f05e6-7eb1-4940-9f6e-b461ac224815	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0763aeba-beb2-4de0-bc56-7ac49d308292	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
de9d2dfa-05b4-4eb2-9b00-9fcf3f435322	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2fae4fa3-18c4-43b7-ab33-6012f17d29e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0118a072-8b90-46c2-b76f-cf8b62fb3c48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c48dfe7-153d-4ca2-803f-38d86643a4ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9bd7a501-7142-4ade-9b64-c047912b1cec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1803148-f948-48dc-95c6-401a972237d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
127d21d8-f203-4929-adf9-3f7b5f3d9ecc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c048bc9b-a8ff-4555-9991-15852cbddcf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	06/14/2023		Hi
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2bfe4854-9c76-4bc9-a87e-5ddac7502cdb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f5f4fa1f-fd04-4544-8fba-a38258ea3fea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	06/14/2023		Quiten este sistema y den bonos
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0127ee84-a3f3-4e1d-9725-a5ad61bded0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e94d670e-03f1-4601-9ec3-6d0a7c599e1b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
93da5ca3-21ec-4a23-97ad-1ce3eb871b98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b1a4ee8a-f689-4582-9aa3-a528377e4b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
171513c6-f2b8-44af-ad1c-c8ef9b57be0a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c9995351-9398-4ed2-b821-cd25cfada259	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50e018b6-4705-4b80-9876-43d84f9f56ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9bcc8928-5d16-4ea8-a5e3-33b0f4d59f49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8eac5067-9209-4fd4-90f8-971c1beb8271	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
65464711-e040-435a-b95f-98d1d9d365d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:16:00	TRUE	FALSE			en-gb	08:16:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c3a03c4c-f474-48a2-8b06-a3c972da32ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes							Yes							
fb3d213b-83bb-489d-bff2-ad222568c60b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2cf102a3-e46b-45c7-9627-dbb016a5adc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
59ecae6f-708e-4b0f-89a4-bd2fa7684b23	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes		Yes					Yes	Yes					
9d105157-55dd-4590-a99d-a5bef1a22043	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/14/2023		These restrooms are in dire need of an upgrade	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes							Yes	Yes					
ca5b9055-9321-481e-8db1-5231b7a19f6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ca5b9055-9321-481e-8db1-5231b7a19f6b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes	Yes						Yes				
48a81db6-ad86-4989-a201-8ddc3570b5c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b95f619a-435f-412f-bb83-9c0824052aa8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ba06b9b-d9cb-4d6c-8554-2f8e0254e5a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
727db233-8a09-4f7a-967a-f08b9b8385ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:40:00	TRUE	FALSE			en-gb	09:40:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7911b7fb-682e-4bd9-88b9-553a4b5d25bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
834966ad-3d65-416c-9814-07f8117d97fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7e64e312-f506-4f36-8fa6-70eaaf60225d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
6bd9d978-d681-4567-adc7-2a3872108bbf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
846b6318-0ab2-40d1-8cc8-20b30be33da1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/14/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
066a6b4e-a722-4a3d-95bf-625c28dfa493	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
595c69c6-c502-4f02-af34-e73532923825	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/14/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
5cc59df7-610d-4c6e-a6a1-f6fb46a2bc4d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:32:00	TRUE	FALSE			en-gb	10:32:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
49bc7d24-b96a-4b74-a472-862228164c47	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e306bccf-b07d-4820-9c99-f92e2445ac9a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:40:00	TRUE	FALSE			en-gb	10:40:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e306bccf-b07d-4820-9c99-f92e2445ac9a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes					Yes	Yes						
dad6bb2b-85e8-4588-9859-b3b22ecbe3f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a3d801f9-8cc9-4540-99e1-9dd65dd3753d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a58293ce-a84d-4163-ac49-11a50f394d54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cdcd4890-3f33-4be4-8bc5-c687e5e286f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5055cce9-5dac-4077-b44a-e244a4c804fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
8a997063-2cd4-40d3-ae92-db7e2b74f829	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
8b726a36-84a7-4aa9-8c9b-3027973f942f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
24f7065e-2786-45be-98c3-3da5dddb7808	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/14/2023		Okk		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
c227cb30-df03-4c75-b321-3e4293005585	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
ca5a078d-f03c-4c52-8794-7b6583baa437	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/14/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
494fd080-77c6-4219-bc28-7697d7a8d83d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
796ccea0-690c-410a-ada3-6c17130e5cfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a3407d3a-86a7-4dcb-947a-890a294a1a80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3d63dfc6-ba4e-424b-8ef6-806c80479281	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9792c88-0f50-4a6c-9c67-b1acb1c8c2a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
891b820c-fb80-4c6b-be4d-1364da9a15c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ffb939cc-58c8-4d27-b2f8-efc512af2014	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/14/2023		Well done job
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0fe2a453-27c9-4da1-8017-e20493b65fe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f68958ad-a59a-47da-b077-fd9021534fe0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
bf1a61af-c7f5-4d3a-93db-e1ed7d48d103	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
c33b2ad8-a239-4775-bd02-b72db35f35ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 11:57:00	TRUE	FALSE			en-gb	11:57:00	06/14/2023		Bueno
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d47d8917-f295-4c14-b56e-0f89f99a428a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:08:00	TRUE	FALSE			en-gb	12:08:00	06/14/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
d47d8917-f295-4c14-b56e-0f89f99a428a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
					Yes						Yes				Yes		Yes			
5f13b7dc-ad87-4bae-b696-592975bce7a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
						Yes								Yes		Yes				
2a0d20f2-7588-4c4d-b387-7c5febacefebe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
						Yes								Yes		Yes				
2dd2099e-f7f8-4a0a-a275-76d0b5d2a46a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
						Yes								Yes		Yes				
67a8109b-02b1-48c0-babb-81c762238ed8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
						Yes								Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
90d11d20-f9c5-4798-a3c4-2b7bfb7e9fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
86cdfb16-21cc-4b7f-98b2-11e5efbf01f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0bba206b-7730-45b7-978b-43bf6ffa7fcc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25273a25-6702-47f7-8fc9-83ebdda1476e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/14/2023		Very nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0ca092f8-fd6c-492c-b4df-16159be95a32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
42acf30b-285c-4571-9a3c-aaaf5c35fb8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b054675f-c5b9-42a8-a821-f53e8167533d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c3387b00-d532-4a75-873d-00ef81c9078f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2cea799-33e8-4f4f-9854-5366db4fb946	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c5884969-c972-4857-bf7c-c36fad4e048c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24013df6-05c7-4922-b4c2-dddb3419e7ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c2363ac9-e2a5-40e9-b6f7-e29548cd7d08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0a5c8671-34f9-4007-bdab-79c76129b66d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2204a76a-63d6-4584-b862-95ad4f2a253d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1df0fc41-c8d5-44bd-b558-fc0f40b6b1ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
49e7e951-d7b2-42b3-9c37-1cb10f28f2c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7859b9ee-9868-41ca-b3e1-03be1e124ed5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/14/2023		I love pooping	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a0a32f6b-5b64-45c6-9c6a-f0abb9d54d40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9d5b8207-216c-4a9b-a3f4-59abba0d8078	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c13b7896-9d83-4e93-ae79-79bfbcb52196a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes							
30863edd-2ed2-40d6-8496-d0e726da12c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
30863edd-2ed2-40d6-8496-d0e726da12c9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																Yes	
68468a54-2c74-4e3b-90e2-f7b90b89b879	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
64098916-e59c-4b03-8c9d-dd578449f2e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
b982ba37-6f2b-4ba3-81ba-c7fb9e42d7ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/14/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9d68fec5-d19d-4542-9013-3d519fbc1cb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1094ca85-0404-4d24-8bed-360b8e8db061	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	06/14/2023		Hi	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
40b8297c-dfc6-4052-a894-142cd3ac22b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/14/2023		Hi r	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
28ff72a4-278c-4df2-8914-47cde428a3b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
82d663d7-6f36-4cd9-a534-7caed3d16fc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2c7b02d-ad18-4856-9d37-b8f833b8efad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e13d191-ce53-4447-8493-cb612661447a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30069feb-511d-4b9b-aba7-a2ef331abb1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
886a4d0c-79fc-44dc-adeb-8641c2fab56a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40f9dee7-2018-4dec-915f-52d400aa9755	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b926513e-8d3f-48f4-a689-ebca2e5e85e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment													
449f5d5b-872a-451b-8216-f0717d5e1441	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	06/14/2023		nothingbto say just clean and make smell go away													
														How would you rate this restroom today?													
														Average	Good	Poor											
																Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
			Yes		Yes			Yes	Yes																		
97c5e490-b637-466d-8e98-f65f5954ed2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	06/14/2023		Please do better at your cleaning job													
														How would you rate this restroom today?													
														Average	Good	Poor											
																Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
			Yes		Yes		Yes	Yes	Yes		Yes																
5eece83f-1a1f-4f58-92fe-6b1ec302feb4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/14/2023															
														How would you rate this restroom today?													
														Average	Good	Poor											
																Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																											
		Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																
		Yes	Yes	Yes	Yes				Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f3d1e9af-47ea-4b8a-8553-c040e4bacd55	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
415961cd-83e5-45a3-8f48-bbd48583eafc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85edf7ee-44bd-4282-b3a4-3425142a4a5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes						
6c07c8de-1f5f-4855-ada8-31f01290b32e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
564c4054-0fe7-4448-9f51-b5ae73f58fb3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:26:00	TRUE	FALSE			en-gb	17:26:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d7856fab-7a7b-4bed-9460-914c6c7a7ae5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:28:00	TRUE	FALSE			en-gb	17:28:00	06/14/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76a1fa6e-9e62-4129-beab-2969cf52f281	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e62879c9-ca95-45b9-a9cd-1a9bd5398b9c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ddddec4b-a30e-4130-9633-12fdf76b9606	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
52400589-29e0-4e85-bf4f-e8c0389179ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
52d14231-aef4-4d37-ba30-e846a9e3f3bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9d893a41-4312-4204-8ddf-d5d5a329270b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3b2e7385-152e-4459-8238-aa3d941ed906	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9c230a02-d70d-46a4-b53c-34038c9045d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9c230a02-d70d-46a4-b53c-34038c9045d5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes							Yes	Yes			
21978772-9f21-4e65-a25b-39edc9cb4d26	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7840c013-67b7-46c7-bb77-3d1179fe4cc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0bc11463-32fb-4928-a6ae-b945216150ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c4a8b92-c0e4-40d5-8586-5f9a7ee74910	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24f502eb-12c5-469f-a3a1-09017341b160	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
2fbe695d-c670-4b0d-a337-96cf37048f02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	06/14/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
60bc4fd2-6fad-42e2-aa91-99aeda0e4fa7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	06/14/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes								Yes					
91a136af-e4b6-4949-94eb-7ae73525a01b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:26:00	TRUE	FALSE			en-gb	19:26:00	06/14/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d9a2d7f-7c12-40b2-8f04-af858d846f7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
67572691-9b71-4749-bfec-6c02cd6f61c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
331c2a02-6668-4379-81b3-890aa3270aff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes	Yes					
4a236ac0-7546-4cd8-b39b-4afa9cf52ad8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
287a90e7-3f8c-4d77-8f34-ecf7fa9ba21e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/14/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
	Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																			
									Yes																				
2b141fbd-f0d7-4172-8790-446cb1a0ff86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:42:00	TRUE	FALSE			en-gb	19:42:00	06/14/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
	Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																			
								Yes																					
f651314f-fcd9-43bc-a732-efeb63dffca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	06/14/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																													
	Dirty Mirrors	Dirty Stalls or Urinals	Dirty Walls	Litter on the floor	No Paper Towels	No Supplies e.g. Soaps/Paper	Other	Smell	Wet Floor	Wet/Dirty Counters																			
				Yes				Yes																					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e01a30bc-ca86-4605-8c9d-dd67077eef09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:46:00	TRUE	FALSE			en-gb	19:46:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7c7ce5f4-801b-4364-84fb-ac22298812da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
45139ff3-b2c4-45ff-bc0a-537116b9ebb1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 19:56:00	TRUE	FALSE			en-gb	19:56:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8cc93a67-e1b8-491e-b4ab-92c4eb13d37a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
df27ebb0-0f56-4182-8bb6-22e755e64d6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/14/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e4f6f515-84ee-40f1-90b3-c52fe890ed2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fb0a38c8-4c4e-474f-8a95-cf18537541c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														
01fe957a-85db-4530-9881-bef3709ce572	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b1deee2-0a2a-4502-8bd3-68a2cef451f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					
5d8e9c33-9471-4d11-a6c9-1ea623ac4bfc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5d8e9c33-9471-4d11-a6c9-1ea623ac4bfc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes		Yes			
a08e559c-3d5a-44b6-8476-c5d3f289891e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e87b5535-edaa-4696-ba04-4ae14b336395	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:23:00	TRUE	FALSE			en-gb	20:23:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cb47b0a5-3be2-4762-9327-6845bfb2af6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
48761e7f-3509-41bc-a92d-a392e57bdbf7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f99f4f0a-5ec3-450d-a0fb-377d4c47fd7b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/14/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
96323364-14f3-4311-bb4f-f11e185aef7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d8ab574-733b-4751-8029-aa685339b9ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
1d6ffc18-bf92-420c-9569-251072ec8f48	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:49:00	TRUE	FALSE			en-gb	20:49:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1f79d019-e8f6-4686-a960-9a0db13782f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5e60ef0a-ba42-4a07-bf43-e0ec333a71ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1601a26e-89d0-49cf-b4d7-6323a273e968	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b22b46f2-87b5-4931-ae48-7e156a3f4bad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4992c4c4-2e8e-4b3e-874b-25bb9f561b59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
7d020559-1aff-4f1c-a4df-2c78a9e0feb9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6988be7c-ed41-4562-8448-74a540c6b91b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	06/14/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
19af0248-12b8-4eaa-aea2-8b221d924cb9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ec2b5db-a023-4ea9-ab7b-f357b924e64e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
66fcd894-69d8-41c0-bcde-edd8062a0bf4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2fb587a0-c5a4-4246-8d5c-7a74584ff576	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/14/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/14/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a421ac96-eb56-4c14-9bcf-ff068243cea6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 00:29:00	TRUE	FALSE			en-gb	00:29:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
91d58210-ad22-431d-8f8a-f9b8343d7184	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 01:55:00	TRUE	FALSE			en-gb	01:55:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
77454bbb-ebf9-47d2-a4a0-43e47be690be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 02:43:00	TRUE	FALSE			en-gb	02:43:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
18ebe53c-7663-4fbe-a3b8-233d56d5d47e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 02:54:00	TRUE	FALSE			en-gb	02:54:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea50af98-7b14-4be6-bb76-7c95497d84b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 04:31:00	TRUE	FALSE			en-gb	04:31:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9dcdeb49-82e2-4650-8d25-0f8f3e9401f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes			Yes					
964609f6-a9c2-458a-b47e-12221b706564	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 05:19:00	TRUE	FALSE			en-gb	05:19:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4756ed87-e726-4145-bebf-dc97b573aabb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 05:41:00	TRUE	FALSE			en-gb	05:41:00	06/15/2023		All wonderfull,	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2fab5716-3e70-41f9-a932-4e96ee3f167a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:11:00	TRUE	FALSE			en-gb	06:11:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37a77af3-b584-4371-9284-af4cacac46df	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0f681352-250f-487a-a7e9-85619fa05d6f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b8bf881b-e690-422b-b003-5c197013a470	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:43:00	TRUE	FALSE			en-gb	06:43:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b117080f-ad3b-473d-a141-2cddce51fc2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:49:00	TRUE	FALSE			en-gb	06:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
814c3e63-5c6e-4b3f-8222-65f24050c06f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d4513698-cc1e-4246-98da-b5e8c38d8d9f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:55:00	TRUE	FALSE			en-gb	06:55:00	06/15/2023		Necesita un extractor
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
6e26aab3-e164-49ad-b9e9-230b4bddf6a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/15/2023		:)
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9de63138-4217-4585-8b2d-e80e96045174	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d6f759e-f806-4547-9b77-bf0de8d41181	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c3bc402-b8e9-4a3e-9f03-a148ad8f0a98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e724705a-5ae8-4df0-8fc5-bbce281ae44c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
44537c61-3e75-4616-9bf5-aff009c5945e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f6a4e977-0121-4daf-b9f4-dbc53bb12a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/15/2023		It was awesome!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d640b590-e82e-4ec2-82d0-0ca81e9eb14e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e1b92e39-d9fc-483d-9745-cd6d3e6c241c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30a6b725-b2c5-466a-b296-1a80f8473de8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:30:00	TRUE	FALSE			en-gb	07:30:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a407386-d55a-4bb5-8322-dc149baddead	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0d5504ef-b5ad-4479-b098-f516efc0e7f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3a3a2128-925b-479b-b239-6f6c0050c880	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2cea8021-eb62-4103-960e-22761e503d7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d9a144e9-f3f5-4314-b962-f840cc75af26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
db68521c-6310-4b68-ba1a-1d3a3f9e33e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
074867ab-3907-4091-85e8-b8783f2177e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	06/15/2023		Nnnn	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
696d4918-5303-453e-9e31-23b92357dbb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4fbdbb71-a7c5-4763-b730-6d079b763360	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6441832c-54e8-4c9d-a2fb-b6eddb62f909	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd8326e-1d63-438f-a49e-73a2779ab019	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5eb1d69a-32f2-4c64-813a-d7b0906a4b47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3292e280-3617-46b2-a4fb-b5dc1416997a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ae3710ae-0d7a-4a4c-ae71-a698e2139eff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/15/2023		Your mo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b6fbed61-bd6b-4c13-b753-48955f0c30b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4d7e0bf6-451a-4dfa-ae9-013ddbc94fc4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
97464f7a-ef07-406a-a451-4e90c6d5161f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/15/2023		no	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
45212703-af4a-4b47-afbd-007580f37991	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
45212703-af4a-4b47-afbd-007580f37991	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes			Yes					Yes						
b0fd35d1-da4e-4573-bacf-393827aa7ba9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						
750e9381-d878-429b-b564-c191632e11a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						
b70489f8-9e4b-46a7-9edd-1cd2cc902d1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						
94c2a9bf-c4a0-42e4-bd2c-5f622ba5b274	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3e0c26f5-84ee-4cd4-bb07-5078c9f9145d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aeb9c38c-59e8-4478-ba4b-9eb505783328	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
89d37cbb-aac7-4aaf-916d-c8fa467d8006	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/15/2023		Good service
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9c11ff5a-6749-4628-80a2-70c24d1a21ab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/15/2023		Friendly staff
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9309b91-7de8-45b0-949d-ac86f4b664fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
acf3fd69-4951-469b-96fb-04d15c1618b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	06/15/2023		Good job
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1da5d00b-95a5-4f9a-a051-92b0f8009e6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
adb4d2e7-7721-4d40-868b-faa9eb0eda83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
642e447e-1722-462e-9a6e-b63104f96935	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:41:00	TRUE	FALSE			en-gb	09:41:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0cd4b88e-e85c-4e34-bc7a-d9ed0b08b497	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d85aaa0f-5912-4521-b60e-b787a5c40db6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f12c6a10-d98e-46fd-b00e-39ffd5c61321	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f4089d9-d47b-46ca-a8a6-012f6446eb28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/15/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
42141bee-f267-4f88-b797-b336bca0c57b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f5eb07fc-6eed-41db-aa68-e7292ed22259	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02d0f74a-140d-4e98-b713-ec0eac401523	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:09:00	TRUE	FALSE			en-gb	10:09:00	06/15/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9905a39c-f319-46bf-a09e-decdd99f0479	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4d27db4b-2495-4a30-9a38-0a84255d0822	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5fba0fb-1b3f-443a-85d3-54d80759a015	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:33:00	TRUE	FALSE			en-gb	10:33:00	06/15/2023		finish	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
d94b7b82-0b0a-4f88-a5db-294c0e54649c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a25c9608-75ad-4ec9-b1f4-56b910786521	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:46:00	TRUE	FALSE			en-gb	10:46:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
064fbc32-8444-4f16-8f95-60107961b574	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9da6ddc2-8297-46a5-8c27-53bf5cd9c5a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:49:00	TRUE	FALSE			en-gb	10:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
deddbdd6-b8d6-4c8b-8ba5-2071dbbceafe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82662bce-2c82-433f-bd39-a41188a51d62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a587876-d66c-41b0-af15-171d099c15b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b1cd9aa-de14-44b0-af68-7d822ebc275c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a2d0e497-d7e9-46a9-9697-76131fa62686	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:02:00	TRUE	FALSE			en-gb	11:02:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bb2e32bc-f5fe-4a5e-b853-ebb4f8f33483	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d966974-8ad4-42f9-9a16-a76a2b653fee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/15/2023		P	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4570bc22-f3b5-45d1-bb03-828044386ae6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46e34792-2ffe-418f-af71-856bd9165250	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:10:00	TRUE	FALSE			en-gb	11:10:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb7df57f-a8d9-42c4-8eef-83ee73aad9cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30104d10-1c2b-460b-b937-b5212084f315	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e16e93f1-0546-467b-a4c1-001e20cea106	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:30:00	TRUE	FALSE			en-gb	11:30:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
16f524d7-6244-4bdc-8e40-a3039a3a9e75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
45261708-8823-4953-9f27-95e9cce3b13c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ebc3fab-a218-4e4a-9f1b-73bdde7654f9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4ab660e7-f573-436c-9f63-58be334ababe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/15/2023		No she is really clear
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f98d2d0a-286d-442b-bfdd-20ac70150219	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/15/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5a098003-d552-495e-af3d-f5f3a29b6b00	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/15/2023		Great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fe437623-d22c-4b4d-a793-4a553123bda1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/15/2023		Skylar
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d2f2efb0-9203-4447-aa40-68ec66bf65de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6f43d6d2-b01c-439e-8e2e-47ae15c33442	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0b61485b-64b3-4b9a-8799-d2df83f76606	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
7dd3fff8-e485-4480-8c71-1482f3c4c811	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
82a45b27-b77d-414a-b8b3-e8f31206c718	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
4f24c7fa-6465-440c-a3bd-8c25ad966e20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/15/2023		love it
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
e39b2ded-1351-4491-8ec9-d5321d882619	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/15/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6d2e966-bbd1-4ffe-b915-66b592081e43	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af1a0945-ed24-4c75-9ee9-4a4126a68f6e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/15/2023		Smelly :(	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
745506be-968c-4355-b11a-a033f59aead2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7481c9ec-0475-47f2-8bd4-90dfe113e1a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76745c87-715e-4197-9881-9e4efb9f081d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7af84ab-e749-44c7-9d04-d987efa3c516	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8ec67876-7ba9-4a6d-a5d2-5210058a2263	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed6e8f7f-4442-49b2-8f52-cb9078f76dcd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/15/2023		Hhhhhddhhhvjjjiv	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
daf06f0f-b9b1-4a19-aaf7-e0865625b5a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
856625e7-3878-4f60-b7af-5f52054de626	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/15/2023		Bien	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9c65b074-7a8d-461a-9bd2-d239e647363d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a166b27c-396a-4902-9362-9a2d88b417cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
029648f1-2e4b-4866-b5b3-c05e4d864341	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
23493561-b155-4c55-aea9-4245c401ac0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8602bd27-634f-48c9-b315-243b8d678c78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
933bcd44-78ac-43de-b13f-647e3b223ccc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a768f188-5d54-48c9-afb2-fbda980eca71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
214de869-7997-48ce-af49-68d5979f88fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/15/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
66455150-c44a-4542-b7b0-866597727e56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6cdf93bf-07ef-4b6e-a950-41743e8af5d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
505b7ffd-d4b3-4448-a4d9-7c2379f01c20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fbd8f9e8-bfe7-42a7-98e8-8ce39c28aacb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
611529d7-b853-46eb-a87d-bd499e1d9e4c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
45d255d9-abbc-46fd-983b-1228c8eba0bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c70ea77-999f-41ff-a0e1-8963c7c7f22f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5935fedb-3c9c-4d55-a4a8-69f89ac18aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:57:00	TRUE	FALSE			en-gb	13:57:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
aee71f14-354d-4c39-99c8-2d5421d576fe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/15/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes				Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e42e75d2-3511-45a3-b3a1-0a73ad4f28f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3d232973-225a-4fd3-a697-50c07d183055	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:08:00	TRUE	FALSE			en-gb	14:08:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0ac34b24-7e70-46f5-a91b-65031a50ecec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
c131c3fc-9a32-4a69-8bb5-8565b9a180b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes				Yes						
71254296-677b-405d-9622-1f325f828e41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
71254296-677b-405d-9622-1f325f828e41	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
5a893f95-1ccf-4751-bc61-d06069c562ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
58c2f087-0838-48c2-aa17-0848b9cd992e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c125cab9-3103-4a1c-b88d-84bc169aaf7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8e73a84-17b3-4f60-b61f-f2fb4dd5cb9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
33fee787-d326-423c-8278-05d090baea81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:45:00	TRUE	FALSE			en-gb	14:45:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ff937d3b-fd64-42e4-8b2c-ab737f592a88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6b46b1a8-6ea9-401a-acbe-1a18104ae6b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0c2d0cd8-59cb-4999-b7aa-0da61e86a2ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	06/15/2023		Happy	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4cb77c0b-73a9-4c95-b345-4c024b0ae7b2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
26431e3e-91e2-4c6c-85c7-69eb651246cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
26431e3e-91e2-4c6c-85c7-69eb651246cd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
73c9f0ec-132b-499e-9232-fadf25b6c801	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b29cf3b0-92f6-4707-8af1-232175048c45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38ea0407-94cf-4762-87db-485d6dca7bac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d68d1b28-aff9-4da1-82e2-05a585f018ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
e4446cf5-c867-4f28-b153-a864322f55f7	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:28:00	TRUE	FALSE		en-gb	16:28:00	06/15/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
b0384ed3-621d-4d32-98db-4397ec409334	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:31:00	TRUE	FALSE		en-gb	16:31:00	06/15/2023		No												
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
aaec49bb-afc5-4d5c-8886-ad437538a093	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:33:00	TRUE	FALSE		en-gb	16:33:00	06/15/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
ae4b0bd4-3b16-4c5b-b12a-983072380006	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:35:00	TRUE	FALSE		en-gb	16:35:00	06/15/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							
a442c894-d092-474c-b598-12a668f346db	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:42:00	TRUE	FALSE		en-gb	16:42:00	06/15/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
			Yes																							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d12148df-1f67-48ab-a279-e0f89eeeb8ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cf1580a1-3bd0-4c31-9d73-2677b4e7c9be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e2ca6c8e-bf04-4dba-a7a9-e4351893f2e4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									
18eafc29-aff0-4485-b100-c60584b97af3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:23:00	TRUE	FALSE			en-gb	17:23:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0f2444f0-b10c-467b-9755-b7cb01775a07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
595a214b-af56-47f2-a273-6f601d396bea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cb8b4555-5ab3-485f-9e96-5a11ac635d9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/15/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
28f5f5c4-4753-46b2-9d4d-d3ab29f725fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4ca129c5-d51a-4f4b-9321-93899c52d8e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
96e66597-2e6e-4208-a0bc-8c1e42fa5556	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
adace830-e886-47ee-9c20-1d9987ea25c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7e26cab0-fac7-456b-a316-4e105ae0450b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
c3fdaaaf-f111-4205-a9f1-5674472e65d2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:06:00	TRUE	FALSE			en-gb	18:06:00	06/15/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1fef5ca-6103-427c-994b-4b7dea3fc1ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:10:00	TRUE	FALSE			en-gb	18:10:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
27a15c50-f5a5-4a15-b44e-cbd5a6378a38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:11:00	TRUE	FALSE			en-gb	18:11:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes									
fab6a27-a628-4bd7-aba9-bfb624cd7851	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:12:00	TRUE	FALSE			en-gb	18:12:00	06/15/2023		Gross
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes				Yes		Yes				
9b48ba78-835e-4dca-9137-57825ef811f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9b48ba78-835e-4dca-9137-57825ef811f4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes		Yes		Yes		Yes	Yes					
8a85fb86-6c84-4625-85c3-7d14b2fc6c13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db6afee1-72d0-47a6-96a0-87eb8ca1ffa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:27:00	TRUE	FALSE			en-gb	18:27:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
b3baf87e-3b43-4134-a3fe-0a8d79db1a1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
51cfafe6-e3c2-4b49-89b9-7c0f5d31ca2f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6005525c-0897-4a18-9b5d-179b555742f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:35:00	TRUE	FALSE			en-gb	18:35:00	06/15/2023		Nice batgrii? pp	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e6749618-5a56-4f2b-aa31-d2ecf9aad2a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:41:00	TRUE	FALSE			en-gb	18:41:00	06/15/2023		Appreciate a bano	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
498e8344-e525-49b8-8248-67b71001f7e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
498e8344-e525-49b8-8248-67b71001f7e0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
03dbd79f-9a1e-4367-822f-71a5213c2f03	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
04401afb-5d6d-4268-96f4-190e5e0e4a6d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
069e1636-4d00-4f8a-8f79-1ce1f636a5af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a33b174f-1f89-4454-ba89-1eb3831f5bf1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
656e8e86-176d-4e60-bc39-ec9425a9f247	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f095d760-2999-4000-9cbd-b467d810aadf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/15/2023		Its very nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cee1d218-d5ca-48fd-b338-aa695d23c603	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
26973e62-9254-46c0-b991-f16bcc6e78fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1ff33a3-b0ad-47c8-b135-c75bc71a8269	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f1716dd2-3ef3-4879-841a-2112e34abe5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/15/2023		No ac
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f1716dd2-3ef3-4879-841a-2112e34abe5d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes					Yes	Yes	Yes					
f4fd0dc5-b550-4ccb-bb06-e3d713 added8e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes									
1e7fe1dd-2c06-4a68-a516-c6a85d25b75e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
dce7dcab-547b-45a7-8d3a-04be9d2d6e15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/15/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1a93bc4a-a227-4b49-8da6-340adf25ab63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9d0ff657-ec1a-489e-a848-977775d81aff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/15/2023		No soap	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fb4b3df-3498-417d-a89b-73c8304bfa76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f1d32e8d-ba4d-4322-9cd2-d6d8091e18ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:24:00	TRUE	FALSE			en-gb	20:24:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
e03de3d9-0099-4055-9916-8ed8a0ccd1cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:25:00	TRUE	FALSE			en-gb	20:25:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
e03de3d9-0099-4055-9916-8ed8a0ccd1cc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes		Yes											
fd184116-8f7d-474d-bf74-c3e28766c826	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/15/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
89ff6400-dcf6-4d4a-816f-fe564ec537ad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/15/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
Yes																				
00f3c1eb-8006-479f-8af8-d07a85377045	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	06/15/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00f3c1eb-8006-479f-8af8-d07a85377045	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes	Yes							Yes					
1f39d91d-f7b0-4f8f-aa27-d5ace0b0681d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6149596d-1f7b-4a34-8a53-94cf6f2020e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53a70e8d-42fa-4c4c-afda-e5cb1a6f25b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7c948337-4112-45e9-a1cf-3b632c7f4160	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	06/15/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a83296c-9ef5-40e8-8614-31975f807c3b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:46:00	TRUE	FALSE			en-gb	20:46:00	06/15/2023		Nice and clean
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
35dd4451-6c48-4b19-90a5-804ee423ef07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 20:57:00	TRUE	FALSE			en-gb	20:57:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fcaf0907-6dda-452a-92a8-d40626be9128	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes									
2fbd52ea-7a9a-4cac-8984-32325b44ade8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
69429ffa-b013-49f1-848b-e5f3cc3d7516	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 21:54:00	TRUE	FALSE			en-gb	21:54:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
f2585948-ece6-40b5-9372-20a7479555f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:00:00	TRUE	FALSE			en-gb	22:00:00	06/15/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2585948-ece6-40b5-9372-20a7479555f0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes					Yes							
7ed7246f-f724-40ab-ae39-c3352ba1c3f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd992598-ec80-4dd8-93d7-9c25670dd89a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:39:00	TRUE	FALSE			en-gb	22:39:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
19357a97-1436-438a-a531-4a526115996b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 22:51:00	TRUE	FALSE			en-gb	22:51:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3be36111-4b8c-4250-82cb-2ddb9ecbec81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 23:18:00	TRUE	FALSE			en-gb	23:18:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes							Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0421ba9c-c2a1-45ac-b6fe-321b0c1a5df9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 23:36:00	TRUE	FALSE			en-gb	23:36:00	06/15/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
b5b71435-730c-4ea0-a459-37dc976bad66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/15/2023 23:45:00	TRUE	FALSE			en-gb	23:45:00	06/15/2023		Trash	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6b70dc78-fa3b-41b9-99cc-8257bc1ff4d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 00:03:00	TRUE	FALSE			en-gb	00:03:00	06/16/2023		Yuck	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
		Yes		Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e2531759-d448-4250-b168-f8b8033cf463	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 00:54:00	TRUE	FALSE			en-gb	00:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
76d33e1c-7259-497e-851b-4d84e7629194	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 02:13:00	TRUE	FALSE			en-gb	02:13:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e08cb44b-f4b9-4c45-8353-9d619637b795	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 02:23:00	TRUE	FALSE			en-gb	02:23:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c729235-d45b-4128-a1bf-af2700efac26	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 03:32:00	TRUE	FALSE			en-gb	03:32:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5d4bd806-ae16-440a-a6af-8fde2f2e0086	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 03:56:00	TRUE	FALSE			en-gb	03:56:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5ef2a309-2aa3-43f0-8838-69801e867aa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
be27f2ed-577a-409a-91ae-300337a7da23	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:00:00	TRUE	FALSE			en-gb	04:00:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2808a3f6-d5a8-4c19-9e4e-4c1a25bd881e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:11:00	TRUE	FALSE			en-gb	04:11:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3fbec991-0fdc-41a4-956b-ca284f6f4b41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:17:00	TRUE	FALSE			en-gb	04:17:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c8735c0c-5238-4909-9af2-7e215c1d0d1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 04:24:00	TRUE	FALSE			en-gb	04:24:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d053ff39-2bdd-4c69-989f-d409e0a85652	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 05:49:00	TRUE	FALSE			en-gb	05:49:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e92c59b4-f669-4c91-b89f-f3f0a3fb1106	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
506b69be-53ef-48df-82dd-5a1a92836416	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
41d9a56a-c2b7-4f78-a6b4-228d9110c542	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:42:00	TRUE	FALSE			en-gb	06:42:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5dfa817e-acd2-4463-a669-9ad0fd1473d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
30e3a7f7-9157-4864-95b7-6f46c53f4acc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eee6170e-bb01-4db6-919e-bc8b6829275f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
438ff9c7-60eb-4df2-a89c-a527bf8200b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ed8292ff-a2d7-430d-9c26-2f85a2e8886c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:22:00	TRUE	FALSE			en-gb	07:22:00	06/16/2023		2171
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1e2408cf-e03a-4320-b07d-2bd783dc879b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
784697e6-1d74-4bc0-bf47-64bfb0db5498	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d27203b-ac6d-4e69-b14f-98115b08734c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:28:00	TRUE	FALSE			en-gb	07:28:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25b0d6cf-d590-4f51-8185-1bdd361a6e63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ff32ac83-2895-43e0-b5e7-1e3a3d1e0b4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f97fea52-8bae-49a6-85e5-5be1b191ba9c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 07:57:00	TRUE	FALSE			en-gb	07:57:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d1cbb55f-d61d-4610-b3ce-dd5173a619ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8501be78-d504-4918-9052-edef0a453fe1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11434ec1-c4a0-477d-bf1d-f6fdb082f9e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
56a4faaf-eb03-4d56-994b-3059d3846820	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:25:00	TRUE	FALSE			en-gb	08:25:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
307b1186-a812-4ff1-a74d-7969373ed760	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:29:00	TRUE	FALSE			en-gb	08:29:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e217b410-f0b2-401c-9ee9-999619bc6605	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:34:00	TRUE	FALSE			en-gb	08:34:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c580a8c-474a-4b89-80bb-5b138f45f59d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bf6b7090-556c-4501-b2a8-27e1d30e4cea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
81fa2f2f-b121-4791-a248-bdc4f303f0ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b4618d2e-0b3f-4caf-b28a-dfe295d60847	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
036e0f59-1947-4fd6-bb7d-07796d08c911	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
228a1074-ba70-43c2-a047-b9d081e93c8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d8821736-102f-4e3e-b3ed-543107a87f26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40c0c2c6-b007-4ccf-8138-94058d6f2b16	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49c0712c-229a-430d-a290-2c0e7c36250d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8110144c-7e38-4387-a92d-890917700766	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f017c23b-ac83-46c1-a414-f6999c30786f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:07:00	TRUE	FALSE			en-gb	09:07:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24ac694a-8c49-4a6c-bd59-7e9cb95dd61f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7ce6015e-0119-4939-9b2f-1f63b08bdbbd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
793e2609-9e43-46ea-b5ae-29e793ae9157	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8cfec095-d920-4d40-9407-2ba6a79d1310	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2067b483-7f7d-44a5-a6a4-53a63a567b5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
decc63c5-5830-4699-81bf-a9c0085a780a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0df57e10-5c12-4b71-9a9d-f9bf088560d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
80b0680b-3e1f-4394-aeb4-f81b74dfb869	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:40:00	TRUE	FALSE			en-gb	09:40:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
da450d38-847a-4f89-b0ab-061bbcfe198d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38d4aa81-dcde-41fe-b8f1-6b59cb3691b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
48cc94c3-2ce8-4ef5-affc-4fd0973a8540	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aaf145be-0868-42e1-9063-2bf2e0397b0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9f8da58-4dfb-436a-a6c0-0df6d3e840d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cfe2b4f7-6f2e-42cd-8c32-da567141f954	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
33d98b19-6db7-4228-8ac1-cd5692618d56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
979ce079-2701-4ddf-9b8f-635b79b3a0c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d80c8634-22b6-4294-9d68-b42adadae863	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
e2383f35-d049-4ef6-8718-b501bf33cab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5c0dd423-34ab-4e91-a778-646ca30980bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:17:00	TRUE	FALSE			en-gb	10:17:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d3aa396c-0e78-4742-8e88-b363feb2ef92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ab4dd315-95fc-4873-ae3a-b45190ab298a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes		Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
39c8dbdd-a6f1-4b51-a2f2-4246f25b17cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8652ac17-fadd-40ad-b46b-7ac5337347ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eea939ce-b79f-4cc7-a2df-c151eb1e9485	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/16/2023		Mejor le dan bonos
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6e9c057e-29ce-4723-ae70-52feed4825db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f9b2c8a7-98e7-4487-9441-78e590a3fa16	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22d41656-c819-4028-b962-1cf790e6a97d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
06683d1b-3ec6-4ee8-af21-c2e68a7af18a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/16/2023		Nice lady
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b94c299-a7a8-4b36-8680-76f99245115b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2783416-18f4-445c-8f99-262a799815a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a051caa-0f54-4ccf-95d4-a174fce17887	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01120c71-96a9-4dd2-820b-4f71c46082e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
efbb87a0-6238-48dc-ae94-1cbbd7a12d76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2009baaf-4d41-488c-a46b-018af3494228	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e0947503-34e5-47cf-8c18-07fa2d0a6e76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:03:00	TRUE	FALSE			en-gb	12:03:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes	Yes	Yes	Yes		Yes	Yes	Yes					
df8dbbf7-f5da-4ae1-8941-f8c28611806b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
56aa8299-b972-4616-a6b7-33278f822a15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:11:00	TRUE	FALSE			en-gb	12:11:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e4195538-5f16-4cd0-9052-5e154077c705	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:11:00	TRUE	FALSE			en-gb	12:11:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
401320da-ffec-4ab3-914f-4c4571cc9796	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bd26fbc9-ab4a-4ef6-ada2-858c71fd13a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8007af12-2e0e-4dba-83c1-49f479df1857	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3317c9a8-4141-411b-949b-184d2097848b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a04a3daa-2ed2-4d41-95f7-46a601348a46	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
786b2709-90cd-4f07-870d-85d70cccec5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:33:00	TRUE	FALSE			en-gb	12:33:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8ba4d2e-31c2-4357-b080-f696a8e688fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
13f259c7-2c77-42bb-a9d7-05b4aac10f4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0200b63c-a363-43c6-a395-37cd62b9b7b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b8bcd23-d5be-430d-9c24-465d1ac0f0f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
36a06086-0241-4656-8184-1f3485cb7aef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6791d142-bb23-4abb-9a3e-a210bd9b2faa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes	Yes								
7948b790-4b9c-40eb-999d-649af350958a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:54:00	TRUE	FALSE			en-gb	12:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
70859568-22fd-4d14-8498-248c7a77c942	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bd21f390-63d0-44be-ab09-6296053e2312	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 12:57:00	TRUE	FALSE			en-gb	12:57:00	06/16/2023		Great assistance!	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2d213e47-2d40-425f-9d27-ba326ecae0df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/16/2023		Very clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a9e3298-bc91-4d41-9bfd-7b7bf677aa7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
77a26185-0f37-4682-a7f3-a518e3d37c1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aa01e9d6-734c-40d5-a543-8a515afc4fa9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
00eb1c1a-df38-4dfa-bd1c-c08dd19b0707	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cdcb146-2475-4ed9-9350-ae2442819c9a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3a107d50-b4c2-41f3-a14c-7d01a8b9e016	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8405187e-e182-4d7e-b92c-816c94313bce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:16:00	TRUE	FALSE			en-gb	13:16:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f914da9e-8e72-4d59-a7ad-d3c498c9d13f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
64cb2e17-bf68-4010-b830-8db6e715ac40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:20:00	TRUE	FALSE			en-gb	13:20:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
185835e2-9c01-429d-8caf-512d2861668b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4a7d2779-3da6-4dc5-9253-7719b94a7edf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:22:00	TRUE	FALSE			en-gb	13:22:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dbf1b5f0-8d76-46bf-8269-af20d24e279b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ce32d4a-cb97-46a9-aba8-7064d3df2654	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
259710f9-9233-4b47-a374-4645d61bdda7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/16/2023		Gaps in doorwtf	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
f0d857e4-3cc3-4685-a8d4-88dbebadf9d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/16/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d7ae5992-2f82-4676-a3c5-0b28cedf9f90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8eb2e46a-11f9-4935-be6c-30f5422d73e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
805bba3c-9748-4b26-8117-55637edefad5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fc8b2224-4132-423d-8581-36dcae7025b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:02:00	TRUE	FALSE			en-gb	14:02:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a2d65e61-57c1-4185-9b15-d16315c83a56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
						Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c7553b18-1853-4df6-b6a2-6dc10fcd1554	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
22aeb041-703d-4636-a9e2-abdf15403024	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/16/2023		Caca	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1645d352-75ce-456a-8f9a-2daddb6ee7a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6837f1cd-f9df-47b8-b582-e7387efe2b71	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/16/2023		Fix the bathroo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
6837f1cd-f9df-47b8-b582-e7387efe2b71	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes		Yes						Yes					
3e0792f4-6569-4ce4-825d-1e511d0ba7ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/16/2023		Fix the bathroom!::						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
cd64ac49-78e3-403d-a5e9-0f0f4f7128c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
946f568a-88a6-480d-9123-a0d9bf518f5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:35:00	TRUE	FALSE			en-gb	14:35:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
0da3c98e-e556-478d-a246-870ecf1f9c88	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/16/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b73e490-f526-433f-8db5-301173176da7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2e1e0a17-57ca-49a4-9388-a99976eb7470	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:57:00	TRUE	FALSE			en-gb	14:57:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
84385fc6-458c-442a-b627-e2bbf95668c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6295096c-5dbe-47f0-8453-38c711070eb17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/16/2023		Urine mostly	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ce4dcf18-7b07-4f4e-a30d-1003c0909072	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a9f45584-5e34-44dc-b799-461bb1703f80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
288d4ddf-5b98-4fdb-9c18-06dce47ecb5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c33e6862-ee48-49de-b1ec-19e2c2890067	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
57eefc4a-7475-4638-8650-dfb5088bdf5e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:56:00	TRUE	FALSE			en-gb	15:56:00	06/16/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5f07c7f8-793e-4b11-b83f-cef72d0db5da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0d9b6d95-feb1-4b0b-8ebd-175cbc99362e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:11:00	TRUE	FALSE			en-gb	16:11:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
fa875364-d332-4cd5-af44-2deccb0337f1	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:21:00	TRUE	FALSE			en-gb	16:21:00	06/16/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes						Yes								
f00e47ca-642c-44fe-992b-1f6c894f9c61	Gate D10 WRR	Gate D10 Women's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/16/2023			
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes							Yes							
f2f4b437-b610-4c8b-bfb1-a3a92e0a7c8a	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/16/2023		I love nuts' i didnt see any naked men	
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes	Yes			Yes	Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
08afc6f8-5df9-4062-aac8-7846a186c246	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
29ecde04-1c5e-4c4f-a55a-f772fa17e750	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:47:00	TRUE	FALSE			en-gb	16:47:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d5e05230-2c9c-4d52-b57f-0849ccdd06d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f370ae04-a40b-4e30-8853-f91087e56450	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
042037fb-e4c0-420b-b786-bc0cf1f496cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c81f6211-4b3a-4e53-82d5-c900feacc17e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/16/2023		Yuck
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c81f6211-4b3a-4e53-82d5-c900feacc17e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
1c0aea90-bfac-4456-9cc3-a4ccad8985dd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:16:00	TRUE	FALSE			en-gb	17:16:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ec98863-45ad-4336-88e5-8efd363ac906	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9af6500c-627f-471d-b358-06fe038f9d49	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d245456-598f-4acb-ab21-97edc9820e0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
548ad305-60de-419b-b5a4-c216bf47fcc9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/16/2023		Ran down
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
548ad305-60de-419b-b5a4-c216bf47fcc9	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
c6d9e503-942a-4f42-92f3-a5fc536a7e50	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	06/16/2023		Hgj	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6e5460c2-2645-46eb-90e7-227dc90d2693	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f67a036f-1989-4ff0-a875-1f7d2c1473c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d00fd8c2-fcb2-4c0a-8372-6b1ad3a703df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
11c6eb21-c095-4b50-bced-4a63e84911f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2de4f2aa-537b-4875-85f6-cf812dabbfe6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:08:00	TRUE	FALSE			en-gb	18:08:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
426283d4-049a-4c6c-8235-3adecd7851c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b19ebacc-2d01-4570-abfa-112309e52188	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
14d90869-3e67-4952-938d-f0a6b789aeee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
14d90869-3e67-4952-938d-f0a6b789aeee	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
				Yes				Yes						
0363f20e-9a9f-4ac2-aa39-43f9719e3151	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/16/2023		Good
	How would you rate this restroom today?													
bed0f349-1cc1-4aa2-8f3b-36f8634ec553	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/16/2023		
	How would you rate this restroom today?													
75038ed0-e739-4c1c-8fc6-e07a1a89dfec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	06/16/2023		
	How would you rate this restroom today?													
45cde2ca-790c-4053-bc1a-a9e1c70a9089	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/16/2023		Not
	How would you rate this restroom today?													
bb0ebf6a-fc93-424e-8c7a-67067134656c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/16/2023		Hot, doors don't work
	How would you rate this restroom today?													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
bb0ebf6a-fc93-424e-8c7a-67067134656c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
											Yes		Yes							
0a276e04-8d19-4cad-8325-293d53f7847e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:24:00	TRUE	FALSE			en-gb	19:24:00	06/16/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
04c0a3ed-2761-4ae7-abd9-aa6d507cec0e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:25:00	TRUE	FALSE			en-gb	19:25:00	06/16/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
f8f15a86-d1f1-493a-a04c-58e6086b7b8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/16/2023		Good						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
a32de37c-146a-4221-8efa-d4652553a988	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/16/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
8743b5d4-104d-4787-a713-72b48ebde7e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/16/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>										Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8743b5d4-104d-4787-a713-72b48ebde7e6	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
2de575bf-9c80-4391-832c-3b819a66fbd4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8f2289b2-b520-407a-bd47-b51dd6d4e63b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bb1afe73-c1be-4c0d-8bb5-eb79897ae4e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca9819ca-93e3-4827-89cf-e23509134a93	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/16/2023		Clean more
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3e3273c-8046-45d3-a3d7-e1e90e7ced6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:13:00	TRUE	FALSE			en-gb	20:13:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
10769f67-945b-4dfe-92ae-77fb827f3ea6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
94ea97da-9444-4098-bd8a-815bcf580478	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b70ef368-1495-4293-a5d1-54f606e863ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
894a4f82-d7f3-4163-8d62-27c1160997b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/16/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
894a4f82-d7f3-4163-8d62-27c1160997b3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
88389f85-b02f-4e1b-8b54-c5ffe102ad5b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9976f3fb-7e10-451b-a0d4-74b73efa9e9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:13:00	TRUE	FALSE			en-gb	21:13:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b8ef08b4-2c45-4e31-a238-6275f65921c6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:15:00	TRUE	FALSE			en-gb	21:15:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6c898d79-f29a-4e79-83bf-f741a987708b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:17:00	TRUE	FALSE			en-gb	21:17:00	06/16/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9063ae48-2f21-4220-9887-0a9942b0eec5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/16/2023		Amazing
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9063ae48-2f21-4220-9887-0a9942b0eec5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
fb65ba8c-c5bf-4e12-8a71-76e4b9116842	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
fb65ba8c-c5bf-4e12-8a71-76e4b9116842	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
8ccd274c-3ed7-49f0-a117-9d183b722676	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49c4efa9-fd96-4a49-bcfd-29e7fdb7c2c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/16/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
49c4efa9-fd96-4a49-bcfd-29e7fdb7c2c0	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a17be264-7cec-436a-bf0b-040980b82e1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/16/2023		P	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes	Yes	Yes						
47080e52-4e23-4cbd-b244-a36430d43e7b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 22:41:00	TRUE	FALSE			en-gb	22:41:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
b5be2d87-dd26-4c3b-9adc-70f0b25cc8f6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 22:46:00	TRUE	FALSE			en-gb	22:46:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
6cb9935a-2c56-4043-98e2-b6f89705efcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/16/2023 23:33:00	TRUE	FALSE			en-gb	23:33:00	06/16/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6cb9935a-2c56-4043-98e2-b6f89705efcf	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
9aa215e6-796a-4b85-9c24-545fc2b0a50f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 00:12:00	TRUE	FALSE			en-gb	00:12:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a4b60c8a-bef2-435c-9f15-aa0f287d49db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 00:13:00	TRUE	FALSE			en-gb	00:13:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8117e09-a229-47d4-aa38-6d5a6d2c1045	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 02:02:00	TRUE	FALSE			en-gb	02:02:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
51cbf3e2-12d9-4282-be95-b458569bacac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 03:52:00	TRUE	FALSE			en-gb	03:52:00	06/17/2023		;)
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3ace4877-325d-4d1a-9330-ed24288515f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 04:04:00	TRUE	FALSE			en-gb	04:04:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4a504942-afae-4931-a0a3-774529b5e747	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
116c174f-1ee0-4fa8-9541-ed551f7f5106	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 05:40:00	TRUE	FALSE			en-gb	05:40:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
defeb090-7a11-4ab9-8fa9-385c95b88942	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 05:48:00	TRUE	FALSE			en-gb	05:48:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d2937e20-7636-48ff-9a17-d253ba486e4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ab0adea4-02ca-44bd-b9d6-1202b6bf4c8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:32:00	TRUE	FALSE			en-gb	06:32:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0e9016d9-3a28-49fd-93bb-d3000babeaea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:48:00	TRUE	FALSE			en-gb	06:48:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9263b7bf-79b4-4eaa-b9a6-d420f2653515	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:52:00	TRUE	FALSE			en-gb	06:52:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6cc0ac94-29bc-4be5-b748-3cb066bbfc0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:56:00	TRUE	FALSE			en-gb	06:56:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f7abe372-e5a4-4dcf-b1ee-37d2680182de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:57:00	TRUE	FALSE			en-gb	06:57:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
131bfed7-7cb6-4278-914f-d8de25e35083	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c684e002-1480-4554-8caa-794a4b57d679	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5ec65d46-ee69-4d16-a877-505de2fd6356	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:06:00	TRUE	FALSE			en-gb	07:06:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ea281ce0-b544-4eaf-9b64-8cca30c4f056	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:15:00	TRUE	FALSE			en-gb	07:15:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9089f1c5-4f6d-4183-bb94-b3e98683f023	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:18:00	TRUE	FALSE			en-gb	07:18:00	06/17/2023		Excellent
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bcc50dc-7c6f-4e54-8fc2-6c0ac7193eaf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8ed183e-c917-45c1-9480-2f0ed643b89a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a7373106-8e04-4f37-9d28-fec18b27a8fc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f686d5ea-301e-48dc-ace0-144190dfae5a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5adbc303-b978-46e2-aaa4-e924657eb590	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e14394c4-db11-4f5c-ac41-9e463c73faf4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/17/2023		Very clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1e71b66-c41d-48c2-b003-751fa9669f9d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
28732e3a-59fc-417b-8aca-2a6e4ae6b7a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:03:00	TRUE	FALSE			en-gb	08:03:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
370c1cc8-e54b-41bb-8b38-5c5dbb600c99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c983eec-191a-44d7-bd01-3d23daf60a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:15:00	TRUE	FALSE			en-gb	08:15:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed2bb737-f0c6-4d72-af53-feb9e99ff8c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:18:00	TRUE	FALSE			en-gb	08:18:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37848a07-92cc-412f-9dd8-b3dc38cbf0b0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
46035f56-2d59-4c87-b668-8462ce004724	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
ac64f93a-d52c-4dff-a50d-9b6c3471e2b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b27d67b9-334d-492b-b844-cca31a7643d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:52:00	TRUE	FALSE			en-gb	08:52:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
cf7d6520-07b9-4223-9f46-d60bdc20f5ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
5362d4b6-ef9d-4ef3-9998-999ac092e7c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
aa645480-63ee-493b-ba32-5d22f3b7786a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6021e00a-32c1-49c6-80cf-b5ce7e697853	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8900ac6d-acea-4a24-b9df-03228c2b4f99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4d8f4cfb-bc8a-46d0-ae2b-50a62b336315	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
761bf3b-873c-4ebd-93eb-e407ee7d2ce8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
28b26e93-3564-4abb-b9b6-194d0fa6f062	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/17/2023		Need air freshner!!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2e111fce-4e4e-4190-8498-2ccc78ee03e0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1a7d7faf-bdde-42f5-b320-50d6c3f619d3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd2af91b-2710-4a79-a92f-1c461232fe2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
682cdca2-985d-4ac9-ade9-4ca0490f1110	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
522b0248-96f5-45a2-95d7-c1f61f0aaaa0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:43:00	TRUE	FALSE			en-gb	09:43:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
76652034-f3fa-4457-99b6-7581f6989265	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
09ce0885-e73c-4533-941c-ddead8dcfb89	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:46:00	TRUE	FALSE			en-gb	09:46:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
cb7f5d78-d85b-4a4a-929d-3a6f3e092eaf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0d079da5-df35-4e3d-b005-05c1e319d1ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4787fcb4-d673-4596-b6f0-6b69ccb2ef07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
532065d1-c3fd-465e-aaba-8959d7fa06dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
58d4ae62-44f1-40c2-abc0-6d0fb76189e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	06/17/2023		Cleaning should be done more often
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes			Yes		Yes						
52a9b6a0-bfbb-45f7-bf7c-3b91d08aab95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes	Yes					Yes					
679f0e18-08ab-455d-a5c4-dca3dd280621	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/17/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
679f0e18-08ab-455d-a5c4-dca3dd280621	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes	Yes									
6ca79573-6662-4325-a251-524a7922c15b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
54ae6ee2-fdd3-44db-bb49-9d1e75ae5c2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9bd4a381-52e8-4ca5-9a1a-f4c6f4bdbe2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d67fdf7c-3a4c-4d2f-995d-9a8f812a2c7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
67f51b3b-f111-4f2c-b75c-04bece56da25	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
05d57f81-1bf9-41be-9585-d07c4f06fb24	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
84ad0659-694f-4417-a394-f0cfd2094a8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
af5dbff7-bd71-44c0-90a3-0ceb02b1eaa5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:07:00	TRUE	FALSE			en-gb	11:07:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7b262655-9c89-45de-b230-c62ae03a6423	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
913660f3-4f90-4144-b17a-955893ffe22a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a4caciaa4-d7a4-467a-989e-0a92ca4c4d73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:31:00	TRUE	FALSE			en-gb	11:31:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
feabe875-3587-447b-98f3-7e22498f7349	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
67aadd7b-fded-4d06-b3c8-fe24c15e5a38	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes					Yes	Yes							
d52db78b-b263-452d-9dc2-d6d130b2959d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d52db78b-b263-452d-9dc2-d6d130b2959d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes	Yes								
965d1195-5d38-4efb-aafa-96520123ef07	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
028235a6-9c11-4c02-b725-fd8f63c06108	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
500a0e8b-a030-46bb-a0c9-defdd29f961b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ca77d080-6a61-4589-b7b3-52ad0a24d0a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1a883c40-da5c-4d9d-bde7-f1801f0de9b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
47b04755-e467-4450-9c9c-248cae032114	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d654573f-fb59-4baa-90b9-c637daf56211	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
a1571ca4-6814-437a-9ae0-40e6603c37ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
d058fd78-4d94-4b3d-b0cf-2e4f01b9b91f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
8e1f2a4d-af00-462b-96ac-716415671c18	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:20:00	TRUE	FALSE			en-gb	12:20:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
a0b962fb-4daf-4fcc-8506-0a39c6b82e1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/17/2023		Sucio
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
38355e5c-9000-4477-a783-eb09ca342751	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b274968b-c701-40fb-9adc-793c2dbd6e47	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2868bcf-9390-4779-9c44-c7f7a93e6222	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ff88c5e-c309-495e-b563-0edc32a0bfcd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
498668c6-aca2-43f9-9b32-a4f61dda0890	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88cbc687-f6f1-4ba9-8cca-7851ead8c8c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
88cbc687-f6f1-4ba9-8cca-7851ead8c8c3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes				Yes		Yes				
90815988-9cf7-4d52-b5ca-d3b0abce933e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/17/2023		Ee
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
90815988-9cf7-4d52-b5ca-d3b0abce933e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
35b39272-f335-4110-827b-002552b2a28f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/17/2023		Ee?
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
35b39272-f335-4110-827b-002552b2a28f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes	Yes	Yes				
1b04ecc1-80d0-4c15-b3af-484f7001ee9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
e3e3c683-c297-4d42-83f9-3e3e0890cc05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
9ab59740-ff3e-486a-83f8-9ba4043fb9ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	06/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
8347a2f6-ac9d-415a-b25d-b8c00aca8c0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
6b0367b5-38bc-4e94-bb77-802706bae145	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
d561dd41-9371-44b8-8f79-8bd0cd482961	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:11:00	TRUE	FALSE			en-gb	13:11:00	06/17/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f851b56c-9e33-400a-a7a3-a0cc4246bed0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d2e5161-91ed-456f-b155-a65e6bada196	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
26d3523d-9fd7-4422-bd68-f7ae6bd4b412	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
41dee8c2-e480-43a4-91c0-c6a8d723f10a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
172db318-5ffd-4553-b121-4a06ed2f7b40	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:14:00	TRUE	FALSE			en-gb	14:14:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
172db318-5ffd-4553-b121-4a06ed2f7b40	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes						
07c32805-eefd-4399-b9d5-2eb82d56eb41	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d96346f1-0974-40f1-ba9e-5c7f46266084	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:15:00	TRUE	FALSE			en-gb	14:15:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
0b432192-1144-4704-ae5e-de01e2d2a993	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4231302e-dd5c-4ae3-80b3-78ff26353491	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4231302e-dd5c-4ae3-80b3-78ff26353491	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
f4cf1213-bc87-4318-9604-0a708ccc064f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:20:00	TRUE	FALSE			en-gb	14:20:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
374d8aa1-e96d-4b8e-bba2-793c620be2c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes								Yes					
8ea9b318-30bf-47b8-84d1-3cf306219ade	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:33:00	TRUE	FALSE			en-gb	14:33:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
8ea9b318-30bf-47b8-84d1-3cf306219ade	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes		Yes								Yes		Yes	
f9944a24-b560-460f-bb75-28f1ab017671	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
c5ade74b-5fdc-48a1-af53-7abfa785b85d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
cc39922f-691a-4785-b51a-3040c21e76f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/17/2023		Smelly. Pee yew						
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
														Yes						
59560b28-dfe1-46c9-a0c5-e43cbbe80acd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
59560b28-dfe1-46c9-a0c5-e43cbb80acd	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes								Yes					
ab640f8a-fa66-4352-9828-f84e44d7c9a5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
6448114f-cb0c-474b-bb56-c4f899f36182	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
b3b97a4f-fab9-44bc-b08e-0e79e3c6657d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
25285a27-8a2d-4f2f-9ea1-b72c7f606b30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
55cce35-a71b-4e1d-900f-b9ed613e1070	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes			Yes	Yes						
be8627d9-c835-433f-a5d9-a666afdbd1aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c59c550a-ba76-4d00-914c-ef498af5d2f4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
218b58da-17d5-4521-95cf-4fba40996590	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9458942-ed57-4251-b8c8-426386ac63dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f666a30e-c95b-4538-8fab-75861e2f8608	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5f0cc821-0d73-4a8f-90c9-fe47795b8c5d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/17/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
867c1974-4626-4844-be6b-7bc68bc8edd9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes		Yes		Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
99a940d8-146a-416b-8aff-780d88d71bbe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
e8b138cc-df0e-4327-8445-e5b928b7aa30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes		Yes		Yes	
1d2bc416-ad49-4ebe-bb72-31c13e9dda66	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes		Yes			
c9d66edc-90d2-4a0a-9828-7b1653715325	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e698c40e-4915-4827-a325-59bd7ed9a110	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:50:00	TRUE	FALSE			en-gb	15:50:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
57602b58-7039-43ee-9a57-947ae1954a41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 15:57:00	TRUE	FALSE			en-gb	15:57:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8e2d749d-b471-49b9-bc35-259277d4b490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:02:00	TRUE	FALSE			en-gb	16:02:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
20a74933-2766-400f-b8df-0335d29ff241	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:04:00	TRUE	FALSE			en-gb	16:04:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes					Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d39d5799-bf8b-4c0e-841a-d6e911978065	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:04:00	TRUE	FALSE			en-gb	16:04:00	06/17/2023		No room	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes							Yes						
eae116e7-7c35-4f51-88a7-8b3e7ddf52a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes	Yes	Yes						
4a780371-d07c-46c6-aaab-be3d1038694d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:06:00	TRUE	FALSE			en-gb	16:06:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
970a6eab-e77d-40c6-ab31-200e4d2ac334	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
84d7826a-63f4-46b8-bc01-4621c249f578	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/17/2023		Hiii	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
884915c1-ef96-4398-91de-faa72044cc5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/17/2023		I WILL never come here agin	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f9a6f20a-0772-411f-b291-9f00e57746f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
34435899-8888-4f8e-bec9-7868ff07b2a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:20:00	TRUE	FALSE			en-gb	16:20:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1112cb5-25de-414d-8849-7ec747eb1936	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:29:00	TRUE	FALSE			en-gb	16:29:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes				Yes	Yes						
1c130c57-f4ac-479d-be2f-f42367f0291e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7f596be0-6426-456f-8294-ff734c4e0d33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2f2f41f4-7af6-430e-992f-1de21d3a8026	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ec7a993d-c295-49ff-a04b-c30fce38b062	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:46:00	TRUE	FALSE			en-gb	16:46:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8ac45b5a-478c-48fa-94c7-aaba9a0c53cd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:49:00	TRUE	FALSE			en-gb	16:49:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes	Yes						
ef66ea83-ce02-423f-b088-b0eae98d5da3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:50:00	TRUE	FALSE			en-gb	16:50:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef66ea83-ce02-423f-b088-b0eae98d5da3	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes						Yes					
45aaa8cf-63ab-4d57-82a6-08e66fddd921	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ebd68fe1-e7d2-48dc-8f50-f2c90431c3e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes	Yes					
cd183242-53d2-4fcf-a747-09164a18e6b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
46f7e8a1-ec1d-4ef5-b4c9-6f258450f686	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
46f7e8a1-ec1d-4ef5-b4c9-6f258450f686	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes					Yes						
d88625f4-fbbd-43d8-af99-f966427cdee8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
4997eb40-3252-4536-adcd-6d0f7672d285	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
72bc8c1f-df45-47e2-9391-4a5c70e63104	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:18:00	TRUE	FALSE			en-gb	17:18:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
981b1e04-4908-4a8d-a3ee-5c1cda1014ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment											
7dc72c61-f14b-425b-bf9e-e3746aa8573f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/17/2023		Flawless experience. Great job guys.											
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
4ce6f70f-2b82-41e8-a42f-6e7ccf68fed3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/17/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
b71ac8fe-a762-4f25-80d8-74838ad849d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/17/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
																	Yes								
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																									
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																
	Yes	Yes	Yes				Yes																		
d9879914-f14d-4e28-9f81-c3b1f19d3f99	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/17/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								
d747ecdd-4589-45cb-abe7-92ac86f4ecd1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/17/2023													
															How would you rate this restroom today?										
															<b>Average</b>	<b>Good</b>	<b>Poor</b>								
	Yes																								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
72ec48f3-32c8-42ac-ac90-389872c2f6c5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ee98a381-7777-4ea2-afea-e0e415fad195	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:00:00	TRUE	FALSE			en-gb	18:00:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ad81e477-cefb-423b-a187-69c145ea4e9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:03:00	TRUE	FALSE			en-gb	18:03:00	06/17/2023		Nah	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3046aba8-4b63-4de4-82c1-1f7e737a52e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1dbdcea0-85c1-4aba-a26a-1c2271aee6ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
dff87ad3-5be7-4daf-83e4-6f9185ce10a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
09f85cad-b07a-4ccc-95c3-513774d27781	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	06/17/2023		Facundo ochoa honor	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes										
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d34e674d-564a-4ed4-9237-6bbc464c07e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	06/17/2023		One bathroom locked	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
3c879ec9-9521-47f6-b146-2aa97efe180b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:33:00	TRUE	FALSE			en-gb	18:33:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
5fef1a89-eacc-4656-99a1-66876a540246	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b3f80f20-7e62-4453-a0ba-3ee9e22b3903	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
dfa00375-bf41-4e69-a3d7-b93fd7cf2e62	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bc35b678-78cf-4863-b064-405b6cbd3088	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
211eef2f-0fca-44d2-af19-6e98623cb5d8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eda46297-c6cb-4dba-8c11-2b8470af860f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
b10510f1-e3f9-4b0f-8510-4b64e5813bee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bbb1994e-a3cb-4b34-94a5-b2b047feb673	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d19e1b9-3f6f-4b83-862c-85fe46a435dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:08:00	TRUE	FALSE			en-gb	19:08:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8d19e1b9-3f6f-4b83-862c-85fe46a435dc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
031dab4b-19a0-409c-a4ef-f1c6fb2e723c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f8890fd9-21da-4f10-9716-bc39989275c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
4c44d872-2c24-46bb-afde-d5df019cebb0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:17:00	TRUE	FALSE			en-gb	19:17:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a409f0a6-4ede-4074-9ec6-f0c24b047975	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:29:00	TRUE	FALSE			en-gb	19:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a409f0a6-4ede-4074-9ec6-f0c24b047975	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes						Yes	Yes				
fcb5032a-3bb6-4c1f-85a5-3aac8b19354b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d8434d3a-497b-44ff-b2f8-36fcad9f9ecc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:32:00	TRUE	FALSE			en-gb	19:32:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0357d9cf-1586-45a6-bcb6-637b17f4d14d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6980da34-e429-4b81-ac0f-62486771d108	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
76edf237-b555-4ec6-b4cb-301007be9a42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
769fb849-ca63-4a1b-adb9-9eed6d36fc8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
fef05561-041d-42f7-98be-6b26ee4fe23e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:56:00	TRUE	FALSE			en-gb	19:56:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e84914c4-44c3-44e2-98ee-6b02304b50b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:57:00	TRUE	FALSE			en-gb	19:57:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
5eb67615-19ba-45cf-aa03-c21493bab108	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	06/17/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
5eb67615-19ba-45cf-aa03-c21493bab108	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes											
e53dcceb-5741-4e93-9851-162a0572a870	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
fa059993-7208-403c-b127-393041f9de04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
d30f5c3d-dfb7-40fb-8ec4-9adab629bc8a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
54d80281-733b-4b0f-afcf-b79c33546673	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:11:00	TRUE	FALSE			en-gb	20:11:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
140b700a-af2d-4d73-9c66-b53db6d7dd59	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/17/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
92056699-21a5-4305-9b52-062a4fe3066d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
531a638e-bb6d-4686-897b-2317a6598411	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bf48f67d-10a4-411e-8f4c-0c3244971dc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a13f38ba-60bd-47e3-8242-400be80e95fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5111950f-ad00-4465-a105-7d6e719ddd83	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7c14a10b-4273-484e-8527-c82a8d6d594e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ec4708fe-7498-4d54-aca8-8a1f59462a06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/17/2023		REEEEKS of urine	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
c26caf57-9445-4388-8b08-a18ae65f3da6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d909b071-f0c3-4497-9b5c-a5c084762d87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d909b071-f0c3-4497-9b5c-a5c084762d87		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes						Yes					
04b2cf9e-58db-4022-a1b8-e86c82bacf87	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/17/2023		Kojkkm
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
42173f84-b93b-4773-a0ee-8732d8a2ca09	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
d8b2101f-d671-49fa-9d9a-cae5f6fa83bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 20:59:00	TRUE	FALSE			en-gb	20:59:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
cdb2b41e-5fb0-4190-9591-83fca0b450cd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:06:00	TRUE	FALSE			en-gb	21:06:00	06/17/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5e4347ad-2ad9-496a-8787-bbfb3d4eb7b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
78cc03b6-b132-4c3f-ab5c-433aecbc41f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f730187b-01a0-41b6-9f24-80e4c446bff4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2495e9f9-4d3e-4f95-a713-1b6bce2ac958	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:33:00	TRUE	FALSE			en-gb	21:33:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6b35bfc6-6edb-4713-9c94-b2db4c5632e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:34:00	TRUE	FALSE			en-gb	21:34:00	06/17/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
75c50eb5-719f-4fcf-8c5e-cddcfcdc2022	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
c0b78a99-0268-4546-8e3e-efdc51827d7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:42:00	TRUE	FALSE			en-gb	21:42:00	06/17/2023		Smells like pee					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes					
b0d9d5c9-96e3-4d33-9be7-a0af5a4e6e58	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	06/17/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
d2c456f9-d458-4345-936e-801a8aa7e10a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/17/2023		Filth					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ae4d3cc-c56b-4895-8656-d321e5ffe02f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:50:00	TRUE	FALSE			en-gb	21:50:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
48f447b4-dc92-4be5-ac53-a9e0a7f13304	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/17/2023		Good time
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
43310727-ba29-4155-8c38-dd2ffbc11785	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
07712f4d-ccfc-4fa1-863b-b80e44d38e29	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:12:00	TRUE	FALSE			en-gb	22:12:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
694734e7-214d-45b4-94a7-91a34f352c23	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/17/2023		No **** on the gound!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
684e763d-e599-44ef-ab42-56ed9ec9b2a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:28:00	TRUE	FALSE			en-gb	22:28:00	06/17/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bebcf8ff-868d-4f60-a8a8-7e5c6c6cd1c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:29:00	TRUE	FALSE			en-gb	22:29:00	06/17/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
d2277183-03f9-4500-98ac-2d8e3ad03ee6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:30:00	TRUE	FALSE			en-gb	22:30:00	06/17/2023		****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0e7a8eff-2c2d-48c5-863f-daec1df9cef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:40:00	TRUE	FALSE			en-gb	22:40:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b3ab0065-7355-47d5-9f90-24400ef76def	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:42:00	TRUE	FALSE			en-gb	22:42:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
b3ab0065-7355-47d5-9f90-24400ef76def	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
									Yes											
14ecb4e3-2018-45f3-968c-44d77a583e04	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 22:45:00	TRUE	FALSE			en-gb	22:45:00	06/17/2023		****						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
82a25814-dcd6-4736-b107-1afa3c67238f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
3590517d-8a06-4bab-8ce5-097edf880b42	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:13:00	TRUE	FALSE			en-gb	23:13:00	06/17/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30b2ff46-1d68-4465-900b-0b48e2438e10	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:17:00	TRUE	FALSE			en-gb	23:17:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
801779a6-7068-4fc5-abbc-21c65f7ec9aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/17/2023 23:40:00	TRUE	FALSE			en-gb	23:40:00	06/17/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
98989573-6561-47bf-9600-cb5fccc917e3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 00:38:00	TRUE	FALSE			en-gb	00:38:00	06/18/2023		Smells like sh	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3e627225-5b9c-440d-bb78-4a80cd4bca07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 00:39:00	TRUE	FALSE			en-gb	00:39:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dfce7f34-8d06-433d-8978-6d02d6865f27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 01:17:00	TRUE	FALSE			en-gb	01:17:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d0d0670b-e332-4174-875e-21466eada4f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 02:01:00	TRUE	FALSE			en-gb	02:01:00	06/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
574932b7-c747-43ca-9066-d004609d759a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 02:48:00	TRUE	FALSE			en-gb	02:48:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
e34138ba-0aaa-4e50-9674-1b0c25774ab3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 02:48:00	TRUE	FALSE			en-gb	02:48:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2b322ec4-fa6c-4bd2-b5ad-58588f44e349	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:01:00	TRUE	FALSE			en-gb	03:01:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a640b75b-c157-46f5-b0e3-07cdb74c2859	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:02:00	TRUE	FALSE			en-gb	03:02:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes				Yes								
2f0eae7-7fdb-4db6-a976-cea5eff85cff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:29:00	TRUE	FALSE			en-gb	03:29:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
b0a35a35-f544-4f56-99f8-6a920e209d98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 03:48:00	TRUE	FALSE			en-gb	03:48:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
246a0bd3-0394-4c88-8d53-dd64375dfa1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:12:00	TRUE	FALSE			en-gb	04:12:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
454f358d-08d5-43e1-87ba-b35f9223bceb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:18:00	TRUE	FALSE			en-gb	04:18:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a30df957-1be9-499f-b5be-de21c8acc968	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:37:00	TRUE	FALSE			en-gb	04:37:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
71bc72c3-061c-4735-a1d7-3822c3b03958	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:43:00	TRUE	FALSE			en-gb	04:43:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ec620cbf-b138-4470-baf3-ad2d1413afc3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 04:49:00	TRUE	FALSE			en-gb	04:49:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a05bfa54-084a-4d3e-870d-2a09bbb51b4a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
a05bfa54-084a-4d3e-870d-2a09bbb51b4a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
8cd39922-4bc3-470b-8e8a-fc7699bdef04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:00:00	TRUE	FALSE			en-gb	06:00:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
7f058b3f-3e0e-4c0b-a959-cff82dcb16a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:01:00	TRUE	FALSE			en-gb	06:01:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
1d2fce94-e6de-41e9-89a0-71dacbed9669	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:02:00	TRUE	FALSE			en-gb	06:02:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
Yes				Yes		Yes		Yes				Yes								
f6293474-7c73-41ee-87ba-cb541ea94cb6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/18/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb58f940-70ee-412a-b102-9bd36f7e2073	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ffcbe8a7-36ce-47ef-be4a-55a9cc1e8f4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 06:59:00	TRUE	FALSE			en-gb	06:59:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
900c4706-fead-4173-bf26-0dde15189929	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:04:00	TRUE	FALSE			en-gb	07:04:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b40e0e8e-68e0-4bac-9706-17f9fa6c0f9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c4282a9-f3d1-4400-8f69-d02245b6edf2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8fb5f4af-6fd7-4c64-9b6a-9a60a3c095cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:19:00	TRUE	FALSE			en-gb	07:19:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f6471766-48a2-4928-a3ea-ca309fc5ca73	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
aba37fc9-7c4a-45ec-a6ca-689687a52425	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b2e286d2-dc31-44f5-a241-94e03bac057d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3d5e0659-56d4-488a-9cad-01b2a444ba80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8aed7206-c3be-41ea-b000-2699b55b8b68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
570d93c8-6ff9-4c0f-b3df-259ff499e5a2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40fd394f-01de-4545-8d90-877d8aa79f05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1dfdd556-5439-4574-880b-273a66622185	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b2fdd64b-3847-4a12-afbc-ecdfe1e4a8a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f881f421-b30c-4b66-84e6-8ce0e2135a2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15b97159-8e20-47dc-8b68-094eada7f1db	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
159c19dc-6444-43ec-b109-459060fd6506	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
7693cfdb-a758-439d-b176-1ee325685703	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:51:00	TRUE	FALSE			en-gb	07:51:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
1454a5bd-9a85-4dcd-9f51-a6f28a7a9daa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:52:00	TRUE	FALSE			en-gb	07:52:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
871716bd-530c-49e1-9366-2bb83dba9751	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
30686eb5-4cd7-4fb4-9202-b304c235d346	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	06/18/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f8a6db4b-def0-42cd-a6f9-33c9827d00b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
75f4efb3-1c77-4686-8d78-e107ca1a3c74	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
d74808ab-c08a-49ca-8488-fc8f3ede2a76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:13:00	TRUE	FALSE			en-gb	08:13:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
9c8b17c9-a358-4f77-a0c1-f6bb18071a80	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:22:00	TRUE	FALSE			en-gb	08:22:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
5c8a30e0-6702-455e-854a-fc09468568aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/18/2023		Smell bad
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0e31ab1e-0a0d-4404-9161-d0cb182004b5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
212ae4bc-dcf8-49e3-b38b-bdf05f5d12d4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/18/2023		Ri	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
796bc706-86c7-477e-8b43-aa7c5c95555d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fb4cd10a-db97-4f71-900c-9656bdce473d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4962e8d1-4b3d-4e38-85bd-b12f5d56e72b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
de3490a2-c487-4a55-8797-62c0a89c7756	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:28:00	TRUE	FALSE			en-gb	08:28:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
751ee6a2-466c-4c8e-bf57-edf643dd32d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	06/18/2023		Its a little dirty
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
372928f3-be37-47f5-97b1-6d3ac39aba54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7bc4db28-c345-4539-b3a8-888491935080	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:32:00	TRUE	FALSE			en-gb	08:32:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
9c3c452f-265c-4452-8ac3-6c0c4badacec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:33:00	TRUE	FALSE			en-gb	08:33:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
455cad2c-cc3b-448c-8fb1-6db0c7657015	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:38:00	TRUE	FALSE			en-gb	08:38:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
50e1210a-ab8a-4f15-8c67-e4a979ce95fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dff7b5cf-aaec-4acf-8c92-126453257cc6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4fb2cd0-6e89-41b3-95ed-46832373ee52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2f74008f-1dc9-4e2e-90da-385ddf1ce059	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
81ed9beb-a74f-4fae-b55b-5bfb816805ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
28357233-e72b-45b3-8273-1425b99ea8c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ca3099d3-2266-48d6-97ec-7b0d48925e62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
9cb71a39-c7b2-49c9-b176-85025770e15d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1a5bc7d3-0b91-4f3c-8331-6e93d261ba28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
a8beaea4-d201-4526-b082-7c920cb7fa12	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
010f211c-eb21-41ac-b04f-0ef6dd446560	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:00:00	TRUE	FALSE			en-gb	09:00:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes							Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
36d07eed-e416-4687-a1d4-6c54c6503d37	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
159f87a4-ba43-4b87-9560-ea8917d07f6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b367e181-ee5c-4a68-988b-8531ec97fb99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
11dcc03c-7d0e-45e2-a55a-ce9e8fe985a8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3210aa67-737e-40fc-92e8-3c15e8f66c98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
32cae31d-c7ee-4755-bb14-dab801889f3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
22615fc3-fbc2-4996-99c8-46280790552f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dea6dd76-2e4b-4aca-b5bb-a9e58c455b31	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
0a315455-c083-4f9d-9656-a0e6593a7173	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:27:00	TRUE	FALSE			en-gb	09:27:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
01fb65b7-5288-4134-86c8-bd2d40acfa5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0bcea0a5-1a29-48b9-b36e-178cd00e228c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:29:00	TRUE	FALSE			en-gb	09:29:00	06/18/2023		Very clen	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4b9eb90e-cb0c-4b29-b3eb-0a6542cc7c76	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1741a6c8-3446-4360-9bff-731e42a3ae63	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8fdb3e2b-dcc9-4dd9-876a-217706fe6aa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
93f3054b-0867-45f1-b3d9-9e9fc6960d7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bdceeff6-e2f4-4c9a-906e-6eed0029771f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes	Yes				Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b5a59298-bc6e-4b49-b3f9-4f66ff662e8e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3629cd67-5a0c-4850-b227-036318451c15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
d533fc1f-5653-4898-afac-6850d748603c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4da12574-ba68-48a2-a23a-53a19e32acfb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
30405773-daf2-46c5-8c4b-825bd7eb40fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/18/2023		Todo asqueroso	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
30405773-daf2-46c5-8c4b-825bd7eb40fa	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes													
9a75e524-38e7-4b22-8323-532a8a9d2192	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/18/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
45776f0d-3c13-49c0-98f6-dfca476d9c39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/18/2023		Asqueroso directo? a ota hola va						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
6e9e4b9d-8863-431c-aa84-93e8c0aaa292	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:20:00	TRUE	FALSE			en-gb	10:20:00	06/18/2023		Parece no trabsha nadue asco da						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
7cda4152-eb72-44c4-bd83-5f402b9ecde0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	06/18/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
1ceaf9f0-c4a5-4647-97da-565a5ee53298	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	06/18/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1ceaf9f0-c4a5-4647-97da-565a5ee53298	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes						Yes				
e5e2e718-b4ea-485f-bd78-040cd3bf9d10	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3db58d8b-27af-426d-abc9-4e0bb70e6e29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
48bb69b8-fd99-4781-8f6f-0607b07a11e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ce3ba4ae-1084-4b1e-830f-f367b70ef947	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2a7ef3fe-77fa-41f7-b787-1b8e55c70ef7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
deffb8ca-29e4-4f31-ae9-6b48d5e7e32d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
450cd2ea-b84b-43f3-bdc0-60cc5a532395	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
47a71d79-c528-45c2-8a72-cd11fb524583	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8c09083b-fd29-49cc-84cd-16418245ae9a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
59da4192-0d93-4690-a67d-07719e7ce93c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
59da4192-0d93-4690-a67d-07719e7ce93c		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes											
b1429fc9-d9a7-4b49-a40a-8c9da7119374	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:21:00	TRUE	FALSE			en-gb	11:21:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
8918b5d4-7be2-482f-aad5-e461c43e30f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/18/2023		Smells
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9a349ace-973e-4837-86ba-bb395e7b60e2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
d8d16d1d-a71f-4a70-9f2c-a46e92951f7c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
7578af8a-d51a-4fa0-be0f-352b4295e43e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d52cc1d8-4f19-4b89-af1a-a8efb7106045	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dcd845a6-b950-4706-b145-88beb5d7ef0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:32:00	TRUE	FALSE			en-gb	11:32:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8e73a6cf-d9cb-4d19-9d3f-890605dd6ab0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
db19ffe0-d84a-4c25-aa95-ed5f8dc33f2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e4445b72-12f1-4ff4-b568-f3b77a5b3a95	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
78571ada-b58b-43fd-b71e-1968dd7d137e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1815dc89-58d3-4c2d-920b-4d00505741bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
57233159-361d-4829-b54a-da9adc959fad	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
82277a0a-1146-4fa4-af7e-ce4ebeb8eb9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
69b7b594-be79-4270-af82-f9a624381576	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
bc27672f-843d-4637-9bf3-e3c0921d7200	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cee1786a-2d41-4a0b-9a87-b7d2474b2785	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
0dff1356-bd3d-44e3-a59f-41f114fb05c3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
84e5e064-689a-4837-816d-47d102d76351	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/18/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
86059b93-56b8-4747-9a8a-559d74fdc875	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:09:00	TRUE	FALSE			en-gb	12:09:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8d2ffd1d-b271-4934-a060-59a619dacf2e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ecd3517d-f435-4a1c-a455-03a1b9db9304	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fabd04cc-7e62-44e8-b49e-20adf66e21cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:21:00	TRUE	FALSE			en-gb	12:21:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ccdf78e5-f6f2-47e0-94c8-7f6e53d98ab1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
edd8ef55-057e-420d-b871-c19c15e74b75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
097ae4d5-17ef-46a1-bc74-589bab94b341	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
097ae4d5-17ef-46a1-bc74-589bab94b341	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
					Yes				Yes						
bb629a17-fda2-4b82-978b-1b8b2418f00b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
97017885-256f-4619-9be6-f26030bfa578	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b16876cf-0d27-481a-9c7e-b2171b45fc9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f2302101-72d0-4944-a457-211b313278d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:43:00	TRUE	FALSE			en-gb	12:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3445478d-1038-43d7-967f-a18ee1485a81	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cf2a042b-9e36-4b45-9b94-4e16201091ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4c21e26d-1330-44f4-a792-4d3d3aa6d18c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1011c06-6acb-4362-a303-c8222432b1dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
760bd19b-1af0-48a2-936f-d616f08c9ede	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:12:00	TRUE	FALSE			en-gb	13:12:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f71fdd91-87ec-49fd-b12d-681ba9361fcf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:27:00	TRUE	FALSE			en-gb	13:27:00	06/18/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d870c9d0-0b62-4d66-8e99-bf30a3eb1b2d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
edd7858f-36b1-4e42-a624-fa6d8368d1c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
44767f2f-45bb-46d2-a48b-ff15d2719eed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8563c85b-6876-48d6-8767-f447355017e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/18/2023		Smells like urine	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
69882503-b6f1-42da-85b9-b60e6a707af0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:06:00	TRUE	FALSE			en-gb	14:06:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2f3b83b1-6ee7-44e1-b98c-5491b24f8e5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	06/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c23c1167-c8b8-4cd1-bf30-11cb7f984882	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
895d9ef9-27d1-4ae0-a309-6775e5ee62ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
895d9ef9-27d1-4ae0-a309-6775e5ee62ca	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes													
097b0eb7-a648-4a3c-a9ba-f560f90bb0b7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
1a2e54da-da23-48cf-b970-f508eadf8fec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	06/18/2023		Great	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
31cd198f-c796-4114-b69a-2187bdb69c28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
53f2393e-ca9e-4665-a324-63a18a4377e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 14:59:00	TRUE	FALSE			en-gb	14:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e7463bf-2004-4a0c-b726-6ad8f0b2320e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:06:00	TRUE	FALSE			en-gb	15:06:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb94c7ab-c8d6-4df9-906b-c81104efd15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
60f3ae2e-2437-4adc-9ccf-4ff3c8da5f2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
37d7a6ba-0804-47ee-b5f0-01bde2feb8a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6fd04ab0-a862-4a1d-99f1-34467e7b13ae	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0f9dc816-4f64-4057-a28b-0ff82fadd9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1fc489e0-4e01-4fcc-8f69-d4de94e71b51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c90f1fd7-7cfc-4a8f-b07a-6bd9a4a69f47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9cc49247-a08a-4447-af40-ef01fac5b187	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8522582d-6c52-4f86-91f4-951fd24fe8b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:30:00	TRUE	FALSE			en-gb	15:30:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e1bb140-51ac-48b9-8d1a-2f20827d4406	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ad7ba096-2acc-4c93-b12e-d58f24ed7425	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
1dd0a2dc-7218-46b6-a61b-8113c6083f3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:39:00	TRUE	FALSE			en-gb	15:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
63d26b56-c5f0-41fc-a091-e9a26fc9248c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
fdf9ca7-0750-4e48-97b3-12ab3552e1ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:44:00	TRUE	FALSE			en-gb	15:44:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fdf9fca7-0750-4e48-97b3-12ab3552e1ee	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
272249ae-5b97-4494-91cc-6ffab7658e58	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:46:00	TRUE	FALSE			en-gb	15:46:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6fc9d0f4-b8dd-4058-b8a0-8d0cad1be689	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
50fb2e03-2527-48c9-bdbf-2de3e86b2e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5c8a820b-dcfa-45cb-9c3c-c98e3651f967	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
677ab5ce-9016-4e8d-8a46-1190e53a0a9f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c5d33da1-6b7c-4f17-b362-394730ce1708	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 15:59:00	TRUE	FALSE			en-gb	15:59:00	06/18/2023		no	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f670ce58-1274-41ec-984b-83af489c9e54	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
a36681b4-d9f3-4e1b-a201-d652c88492cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:03:00	TRUE	FALSE			en-gb	16:03:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bb8eaaab-d4ae-4199-8047-d2f9134435f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4024013b-3324-4fd7-a8e4-1a5d765b6bb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30a7975b-3477-411d-ab78-195659f5e232	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
34e641e7-3e90-42dc-9b24-16eba9e48f14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:29:00	TRUE	FALSE			en-gb	16:29:00	06/18/2023		De santis fix your airports before you fix books	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
145456dd-f3dc-4fed-8352-d97572ce8317	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c3a6671a-5dac-44ce-b870-2b357a96c82b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0777b828-4fef-402a-b5ea-3f334aceac65	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ce603416-e73e-488d-851a-151fc427f7e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/18/2023		Pp	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8b1c0f99-33c8-4260-80f0-18591b21566b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:43:00	TRUE	FALSE			en-gb	16:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bac1814c-608d-467a-bf7f-042ada11fee4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:45:00	TRUE	FALSE			en-gb	16:45:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cb90f7a2-023c-49c8-bf40-dc8376220360	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:46:00	TRUE	FALSE			en-gb	16:46:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d0a21d03-3626-4abe-ba9d-41975759feb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1560467-ff06-4502-a31f-6d36dadcf3c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
901ea072-dfff-48a6-99be-0e66dee01d01	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:01:00	TRUE	FALSE			en-gb	17:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
df2e3a66-5b7a-4926-be1a-7d6b9d99e4d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:03:00	TRUE	FALSE			en-gb	17:03:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fe2280fe-576d-411a-842f-06c5d0c3b5fd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:07:00	TRUE	FALSE			en-gb	17:07:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8f4770ec-c550-405c-9f28-da3ccb3c4dcc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
95a0c182-1f61-4108-bd88-117151b979ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
97d57e1b-2269-413e-91cd-062b7214b4c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c054386a-adb6-436c-832a-b071bf801da8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:37:00	TRUE	FALSE			en-gb	17:37:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ef5c9cce-5725-4094-9abc-632ec9089be0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:44:00	TRUE	FALSE			en-gb	17:44:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
41b56309-c4ca-4351-b54d-a7f6f44f53e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9c505de9-1f41-4b80-a7b4-206f793b54c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
71f1f698-823b-48fd-b0c5-3fe5b02dcaae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ff89015d-7103-4f86-a34f-12aba3ab78dc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
091699bf-1808-4040-9202-39d91686e911	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes					Yes						
7bf74ab5-0cee-4890-bdb4-9a94ae56b52d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e1158c1c-76b0-4969-8088-2cb935647486	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:55:00	TRUE	FALSE			en-gb	17:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
10027178-097c-4bf4-a487-a9a4830fa6b6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
01c52085-cf00-4e73-8b59-4052f0af1a99	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 17:59:00	TRUE	FALSE			en-gb	17:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ccd61dac-0794-484a-88ce-887c894c5e61	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
00656eac-b799-4eab-9198-e072d9a70d39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/18/2023		Steamy ****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
00656eac-b799-4eab-9198-e072d9a70d39	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
2112d311-1047-4a8d-aa70-32165b2a0aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
22e70402-ac78-4b51-84a4-5286182a8f65	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
e11bf37d-6119-45da-a273-bdd2463eeb37	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
88bd4290-9ff1-4ad5-9244-29bcaa199ab3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:26:00	TRUE	FALSE			en-gb	18:26:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
221b7727-67ff-4dbe-801f-a0f95cc5ce84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:37:00	TRUE	FALSE			en-gb	18:37:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
2bc66fda-31d8-4bac-bcd4-1196d410cc6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3a6bcf85-4fed-4a70-a7b1-8d2ad9ed9321	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f6637dae-09a1-4d4b-8aac-0288634fd049	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:50:00	TRUE	FALSE			en-gb	18:50:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c175cf85-e2d7-4334-b8c4-7291e5b811f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:56:00	TRUE	FALSE			en-gb	18:56:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ffda51a-7b2b-4790-955a-ef49a9f4d820	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/18/2023		Dope
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b604233-af07-4b9c-8477-61742ac302cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/18/2023		Super dope
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6bb8df2b-f8d4-46b6-b2b5-be716f535b27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
843ebc53-6b3e-4550-befb-063bab1a511c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/18/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72a143c7-b54f-4d80-8aa8-95f91d0cc2e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea9501d3-1064-41fc-94ac-1d20b785fb28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/18/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ebde231-baee-4f4d-be5d-d9d29f7f0cf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3d77afb-f112-4b8b-8e62-bae4168390da	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
957129eb-58cc-4dea-9de7-ec72c1ef409c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes	Yes					Yes	Yes					
1bf8d1b3-389c-4cde-b12a-082648f71b68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ad8c9343-345d-4181-83ac-aa74e20da898	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:28:00	TRUE	FALSE			en-gb	19:28:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9b3b9c0d-195b-409a-9d2f-58f0062a9e6b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
259b7877-d53f-4147-83fc-dced605f199b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/18/2023		'y"u"n'e'e'd"''''''''n' e'e'd' h"''''n' 'the' 's"a"s'	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
45afe203-b75e-4cad-8ce3-41b02d23ed11	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
16db5239-a06a-4d3c-a889-6d59fc62f32	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
de7af2bc-6df2-4a06-8817-f01ab27c8698	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/18/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
376f0bf3-539a-4e97-b419-e415464afed2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:43:00	TRUE	FALSE			en-gb	19:43:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a10fb823-f2d6-47c3-82ca-34631432fa06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ebfedd7e-dfcd-4f09-8920-c834e127af04	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:53:00	TRUE	FALSE			en-gb	19:53:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fc06add3-b038-43e9-bb79-b576f8c47ba7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a7b88528-5422-4750-a6bf-90bbc048bcdf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ecae5f47-7dd3-4c5f-a34c-968ede1e0766	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:09:00	TRUE	FALSE			en-gb	20:09:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5cc72c85-ba86-4a1f-81d1-ceb03093459b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:10:00	TRUE	FALSE			en-gb	20:10:00	06/18/2023		I	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes				Yes	Yes					
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4f6ccf75-4069-4e54-9394-0ba11f363dfd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
456a6d13-9095-479f-8921-ebcf6e10a17e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4bb8d3a2-a6b8-42e3-ac6c-c45e022044f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:22:00	TRUE	FALSE			en-gb	20:22:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes	Yes					Yes	Yes						
6d3355ce-2f1f-4459-8cb3-621a988c1b67	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b6523e4f-133b-4b20-9d4f-17dd1d64b623	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dffaaec6-83a5-4eca-8564-831de75f46c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6caaab56-3162-42ba-a5c5-328edad26a2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/18/2023		Cp	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9fc085fe-362d-4d1a-b529-24e2fa1f0460	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
9fc085fe-362d-4d1a-b529-24e2fa1f0460	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0237fada-6449-4bcc-994e-b3d2b29a4ee9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/18/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cef3b76-e636-43df-b409-83b0811a114e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f8abc0db-0482-4e66-a6a0-5ea3b4b35802	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:19:00	TRUE	FALSE			en-gb	21:19:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d7704b6-faea-47a2-ac39-1a5bd050c198	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c3a1016d-e219-41dd-895d-250c29a55021	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24b8d75a-1f32-4221-9a77-6a081057c7c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c2cafade-b5ab-4596-924d-a498e6b536c7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bc45f297-0865-4ddc-9587-3a1d670b4d45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:37:00	TRUE	FALSE			en-gb	21:37:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cd4dbaa6-8273-48cc-aaf5-140b703935d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:37:00	TRUE	FALSE			en-gb	21:37:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f77b350c-6091-4c4a-ae31-4282b9ce30a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:41:00	TRUE	FALSE			en-gb	21:41:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0a6634f6-7224-4d9f-859a-f328543cc474	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:43:00	TRUE	FALSE			en-gb	21:43:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1b663c27-ac08-4054-a970-0fa4bb6cce28	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:47:00	TRUE	FALSE			en-gb	21:47:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1e1b2fe1-6b7c-4945-8016-0ab0c467e9ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7d9f3e9c-7b26-4532-891b-6bdfa566ac5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
82b29e2b-5520-4f0d-afba-954ece4c6441	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:01:00	TRUE	FALSE			en-gb	22:01:00	06/18/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
e7c8c33a-9100-4e00-ac3c-23ddc3f55ab0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:02:00	TRUE	FALSE			en-gb	22:02:00	06/18/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
f33cfb4a-1a07-4092-96fb-14af1cefabc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	06/18/2023		gross and unkept, not a good reflection of usa					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes		Yes		Yes								Yes		Yes		Yes	
f4dded2c-66bc-47a8-8462-0ca9059178fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:14:00	TRUE	FALSE			en-gb	22:14:00	06/18/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes														Yes			
066f4128-6deb-497b-9e52-316dc19b0ff4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/18/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
066f4128-6deb-497b-9e52-316dc19b0ff4	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
			Yes		Yes				Yes		Yes			
3ce0f732-fec0-4d6f-8d19-7a67bb0586cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 22:55:00	TRUE	FALSE			en-gb	22:55:00	06/18/2023		Smells
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
00033f9e-399e-4970-9269-3a47ffafc927	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:19:00	TRUE	FALSE			en-gb	23:19:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9ef5746a-50e4-4cbb-aaaf-6bd15eaabcc1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:26:00	TRUE	FALSE			en-gb	23:26:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ef5746a-50e4-4cbb-aaaf-6bd15eaabcc1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes										
4ba9955b-7a7b-409c-9b0e-eece105b4e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:43:00	TRUE	FALSE			en-gb	23:43:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74497afc-57fc-4a30-8222-538d08498647	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/18/2023 23:44:00	TRUE	FALSE			en-gb	23:44:00	06/18/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
25be55de-3af2-4701-a0ea-3ce2521e7db3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 00:30:00	TRUE	FALSE			en-gb	00:30:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b24e9d07-dd4c-4496-83c5-62e2eb445f3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 00:52:00	TRUE	FALSE			en-gb	00:52:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78c8bc84-72c8-4cfc-9fb8-6f0c991cadbb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 01:07:00	TRUE	FALSE			en-gb	01:07:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7f88b6c1-b300-466d-a6ad-5b6552dd17e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 03:49:00	TRUE	FALSE			en-gb	03:49:00	06/19/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95579f8b-72d5-49bd-932d-11d0f3cfc0fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 04:54:00	TRUE	FALSE			en-gb	04:54:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes				Yes	Yes	Yes					
7c3c1437-6ea2-4649-a81d-efee77a62a07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2d463604-16c1-4521-a49a-4ca5b55c0a1f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes				Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
48d474b5-bb9f-43ab-b8bc-02716c917797	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:48:00	TRUE	FALSE			en-gb	05:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
daa81d3d-bdc2-4589-9ddc-eb03db0bb2e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a857806-60ca-4132-bda5-913274f5ded5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:00:00	TRUE	FALSE			en-gb	06:00:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										
ba16c4b5-dcb5-471c-b8cc-6c7c2d04ff68	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:07:00	TRUE	FALSE			en-gb	06:07:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f6eb6829-53f7-4d61-80f2-e16c192c641d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:15:00	TRUE	FALSE			en-gb	06:15:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
07913d4f-533d-4fd9-b4d4-74e5f1b94922	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:20:00	TRUE	FALSE			en-gb	06:20:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
82bdeea0-48fa-4846-8295-b3d6390edfee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e482ec81-2785-4fca-9aba-d9e3627f3d03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c78bcf6-1c20-4fe3-9f27-058a2c00329c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b4ef37df-f9df-42ec-ae87-c93044cd1725	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 06:51:00	TRUE	FALSE			en-gb	06:51:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
008229f5-7288-4af3-9b2d-ad763be21ed0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
02c06a64-48b5-445f-a3f7-34e63460a784	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
192a238c-90d4-4ff9-b119-e8c6c87d844e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:05:00	TRUE	FALSE			en-gb	07:05:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
958d1034-7413-481b-8204-0d33e77bcf57	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b252cd02-3123-4c44-8782-8e415e0d2f4d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/19/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							
c383cf47-73de-4050-bbe3-c66b5b2695ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
9a4c6cc3-2361-4919-990b-300cd62003ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/19/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
0ad76e22-230e-4c23-9cf3-1b071252954e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:24:00	TRUE	FALSE			en-gb	07:24:00	06/19/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes													
e33c5219-9453-4d93-b974-4ad2738ea3e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/19/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
								Yes						Yes					
11562e14-38f1-4292-bf25-b9593dca0806	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	06/19/2023		L					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
Yes																			

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
bca0e2b2-e6ab-4d8a-adc9-daaa985bedc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:27:00	TRUE	FALSE			en-gb	07:27:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
52634b5e-a518-43c8-9265-7a3f572769a6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c5280416-5861-4d31-b159-baa290afe046	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:36:00	TRUE	FALSE			en-gb	07:36:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
d9adee1d-8c69-4964-bab0-b3f4b280782f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:38:00	TRUE	FALSE			en-gb	07:38:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
273ddd9-8f28-4c2a-b1af-de6dcb53c3e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
2dfd281-cbab-4e15-84ee-128ee92183ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
416ad273-3a5a-4aa4-9984-834a437854d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:12:00	TRUE	FALSE			en-gb	08:12:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b93da836-90e1-4a60-b274-6171929ea364	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:14:00	TRUE	FALSE			en-gb	08:14:00	06/19/2023		Too hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
43fb679-08be-4950-8940-619170f33996	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
23f274fb-9d28-426d-b0c0-8ef0f2b48d99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:20:00	TRUE	FALSE			en-gb	08:20:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
418551f5-2645-4a78-b83f-3f4414ac590e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17169c6e-3657-40d0-93d4-4e5e34085287	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dea89e5e-259a-452e-b8d3-eebb1e15a5ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:27:00	TRUE	FALSE			en-gb	08:27:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9d80699-564b-4f54-8978-b1c2f0e716ac	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2842f900-014c-47b1-959c-d9bbe565d400	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:41:00	TRUE	FALSE			en-gb	08:41:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
244d7acf-c267-4992-ad93-26a683db8dee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:42:00	TRUE	FALSE			en-gb	08:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7652de1e-b2e6-4a72-b6c7-0561fcd533f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9e32038-31dc-4386-8ce2-14c5b9171741	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	06/19/2023		Na	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ff572b2-b740-4018-a3e7-5894abd72e3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0acef391-7d84-4738-9fc7-5b883b0037be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
15566e32-40c7-4f46-b9f5-977f450541ca	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
668abdc0-0795-458c-bffd-42ee08c517f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 08:59:00	TRUE	FALSE			en-gb	08:59:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
78144c5e-588f-406e-9352-45a08c511490	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
58f6f6dd-06b3-41e7-bbb6-934edf6454c0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:03:00	TRUE	FALSE			en-gb	09:03:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3e360424-320c-4415-9d07-4e540bfb74f0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
736ea615-9b92-4c7f-90b4-fa98e5e237a1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/19/2023		Very clean and well supplied even with so many ladies coming in, thank you!
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
237b4b37-156c-4a7d-9741-eed2687a8724	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a8672b69-c33c-4382-85fd-6ccc42f4a2ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:12:00	TRUE	FALSE			en-gb	09:12:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
226380b2-04bc-42b0-bebe-d2240f252231	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:13:00	TRUE	FALSE			en-gb	09:13:00	06/19/2023		G
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
65d77d54-552a-41f0-a016-1c20f39eab5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2601a25b-a23d-432e-9963-9d68649abe77	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ecb7b800-ba3c-4809-90cb-23a5634cf8e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:17:00	TRUE	FALSE			en-gb	09:17:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
42d05de8-fb76-4965-a1d1-cd440362581d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
683efb2f-6878-4ece-b674-4aa00436c161	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:20:00	TRUE	FALSE			en-gb	09:20:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4f789c1-2974-468b-9f70-d5b62b0dd2f5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4af5c2e1-10d3-4568-86ac-7094e4ae3c56	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:23:00	TRUE	FALSE			en-gb	09:23:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1d32bcca-d5c8-4128-b318-9ffb02687bc5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b32180e8-292c-4d36-97ff-fd21601e4669	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2ce7c78-07b6-4ae9-8347-f1d77c537240	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:31:00	TRUE	FALSE			en-gb	09:31:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d118eebd-7c2d-4b10-b336-8f2ad5033e90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:33:00	TRUE	FALSE			en-gb	09:33:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22835407-fcc2-4187-8798-9d0bf5e9f487	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:34:00	TRUE	FALSE			en-gb	09:34:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3004f752-c801-43a3-a1d5-2e2aaf8a73bb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:35:00	TRUE	FALSE			en-gb	09:35:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8646befe-a107-4a2d-ac90-1d78b15b268f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:38:00	TRUE	FALSE			en-gb	09:38:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eb92e220-50c1-4ee9-bcf0-086fd309d7f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1f7d4b62-2960-4263-afa2-4977b1cc6455	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
63423a6f-8202-40cc-b0ab-80e6fe4d53ff	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
90ea1902-c33c-47e1-b39e-2a5fa080d078	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca5fe2d6-6c77-4d67-ac5f-fdc738015eb7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:57:00	TRUE	FALSE			en-gb	09:57:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ef2d6ddb-8e59-4fd5-a394-acaa148a44c9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
82ef2d6b-1c42-40fb-9b7f-cd9fb32eaa02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d7afcaa-06b1-40ba-82e5-b013a1f1b541	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4594691a-d6d1-4bbb-a06d-20fb0f5e4c1c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:08:00	TRUE	FALSE			en-gb	10:08:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4a56625a-5961-4833-b802-9a18c03dbffe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
ee3514f8-d596-4c8c-807a-8955f60d7566	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9ae312c1-f38c-4f00-9469-262e59d2039c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c4dc2db4-53b2-441c-9966-865d3eccf23b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b28b56e6-d1cf-4e15-9197-eb0987f39bc3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc1be7f2-8cb9-4f82-aa07-8bac78572cb2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4266103-07d3-44ff-b9d4-98c290d8a400	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:01:00	TRUE	FALSE			en-gb	11:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
34acad5a-4657-4680-ad2a-2049ed908c7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5020a3fb-a760-4714-8264-9261a2e8a652	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
33ae4a58-0e76-458f-88f3-117028ca0e12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0dfc460d-6960-45d4-b67b-f07d2922d91f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5a8ac3c9-0a56-4e52-82ec-4982ff10b248	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:14:00	TRUE	FALSE			en-gb	11:14:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86b7508e-c219-486a-af55-1245e0fdb287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6cacede5-d917-4151-93a0-677c6bd3fe06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d7b3c8a1-b26d-4d45-9acb-5a1d349da123	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
63108160-4031-49c7-8585-cc384e840279	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
fe8e688d-a233-4c1b-bb83-2b52a36184f7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b8b95c26-6bc9-4651-b1e3-03c1c9a7e536	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f448f660-80e5-4445-bf94-e319d1449cf5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bc42e5d2-4535-4847-9518-b1d0b35c890e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:29:00	TRUE	FALSE			en-gb	11:29:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e77d69bb-5c66-4966-8fea-4f264e609b5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:34:00	TRUE	FALSE			en-gb	11:34:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
695f62e0-7e8b-43f1-8352-52b3dd49e4f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:42:00	TRUE	FALSE			en-gb	11:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
96e799b5-a640-49f5-a8f3-8f7c32c23ef0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:49:00	TRUE	FALSE			en-gb	11:49:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b95ba7ab-bb99-4972-acd2-0d01f2513dd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	06/19/2023		Yes
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bfdea0a8-6e21-4116-b626-4934615ee5ee	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 11:56:00	TRUE	FALSE			en-gb	11:56:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
bfdea0a8-6e21-4116-b626-4934615ee5ee	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
							Yes													
e1119d8e-8e2f-4817-92dd-a9976f9e5641	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:01:00	TRUE	FALSE			en-gb	12:01:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
						Yes														
8953596c-6006-4ffb-9821-cce1c8c02dd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters		
						Yes								Yes				Yes		
199be5f7-efd6-4af6-aed2-427ff94229cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:19:00	TRUE	FALSE			en-gb	12:19:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
89f0ee6c-d6aa-4710-811e-e3a7f16c0748	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
4ef1f625-e817-443a-9742-dd5b05350172	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
732965a9-deba-44c5-b473-f4bc70e7d3bd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
424f29f1-1b94-4483-9262-c32139b52266	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/19/2023		**** rockin	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
d552e002-ff43-4ed2-b864-5d039ae3a16b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a140f60a-fe86-479b-a71e-ec45d067abce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:45:00	TRUE	FALSE			en-gb	12:45:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
053c14c7-70b2-4975-90c1-25a15eb2c952	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:47:00	TRUE	FALSE			en-gb	12:47:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd226d18-cf07-4744-807c-d8d249480cd5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6a9acc0b-bc3c-43fa-82da-fde7907fcb02	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b565886-7022-4e11-9c58-82b245652519	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8aa583ea-bb87-471f-9902-1d7383984084	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:00:00	TRUE	FALSE			en-gb	13:00:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8aa583ea-bb87-471f-9902-1d7383984084	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7816f483-fe85-410f-ac11-a84c02cae939	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d3a91ed-bfc6-4a6d-9b40-2c58755916aa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:01:00	TRUE	FALSE			en-gb	13:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
04d95846-9783-4106-9547-0035a07148cf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
adfd9052-d830-4cd7-8abb-ed0f3e8ae432	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d7111e8-983e-41e2-8ae0-4cf2c0e4ce20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
1dc6ad08-95ed-4746-a356-7d6f96caaa12	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
75f34b93-0ec2-4d22-969b-8dac16c38568	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
	Yes															
5a7b673d-e4c1-4249-ae0-e87149814300	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
							Yes									
79a0cd02-9487-406b-a20c-fbe6424cf5d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:43:00	TRUE	FALSE			en-gb	13:43:00	06/19/2023		Se		
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>							
									Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
951f3ead-d30b-4593-a4d5-77b5653dba8d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
031f9175-07d6-446c-8bea-044b143b1e45	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:49:00	TRUE	FALSE			en-gb	13:49:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
303044de-c10c-4f8b-98e2-de26b7360104	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5ef60e8d-dc83-49cb-a302-457adc2ae24e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:53:00	TRUE	FALSE			en-gb	13:53:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes		Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
84bd2367-91be-4ca3-8918-58f2006a49e1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes								
e4cc111b-738a-4605-8913-748292803ac5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
		Yes						Yes	Yes							
ca8e6aac-28f1-491b-8971-2c9edfde5eba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/19/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
				Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes				Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d47ca057-3ac5-4ee2-aa98-6df2474daf14	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes						Yes						
2ded3eb1-1d69-4063-990f-78448b1a70c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a81df281-72eb-4fb9-9da6-f5a5c7953767	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:10:00	TRUE	FALSE			en-gb	14:10:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
a4d77b22-7401-48a7-b31b-38bb5594d574	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:11:00	TRUE	FALSE			en-gb	14:11:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a4d77b22-7401-48a7-b31b-38bb5594d574	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											
378b829f-c775-4406-bacd-45d461b3c565	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:16:00	TRUE	FALSE			en-gb	14:16:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b20a413f-5e41-4611-b3f3-89860cc0bceb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:17:00	TRUE	FALSE			en-gb	14:17:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
f5ca6c2e-06dc-4f55-9006-b90e391d3ad5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3f5812a3-89fb-43ce-b240-4bba28a41f17	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:26:00	TRUE	FALSE			en-gb	14:26:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3f5812a3-89fb-43ce-b240-4bba28a41f17	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
8f60019a-034f-416b-80ff-73df977e06b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes											
f5cebe24-2e22-4477-a096-edcbf11b2923	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:28:00	TRUE	FALSE			en-gb	14:28:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes				Yes		Yes					
04147f68-e731-46bc-9b6c-e9cfbc227861	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:29:00	TRUE	FALSE			en-gb	14:29:00	06/19/2023		Smelly
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
04147f68-e731-46bc-9b6c-e9cfbc227861	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
78117f57-3609-416a-8f8e-9cab593d06f8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
452ae7a1-09bd-4dc6-bed8-21b6160159fb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:34:00	TRUE	FALSE			en-gb	14:34:00	06/19/2023		Smell like **** **						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
22acf679-7f02-4137-a6e7-676f175f04ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
9ac945a6-3191-4462-a2b1-700fc91726cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
9b32d84a-c960-4fcf-9008-7965c420991b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:08:00	TRUE	FALSE			en-gb	15:08:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
dad049ba-6d3a-46e1-9b7f-68fb62c28f5f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
c6107f9e-9f52-4d8f-b9de-dc8a1dd9c58f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
b0b059cb-2dcf-4ca8-b483-acb4c3a88f05	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/19/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
b0b059cb-2dcf-4ca8-b483-acb4c3a88f05	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
1f9607b3-be75-410f-923e-7db923a0ddb8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:34:00	TRUE	FALSE			en-gb	15:34:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
93f29ead-2d55-43fd-9d62-53a9c5015662	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
6f3fe45a-9b96-48fc-afa3-35bc0479e18d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
bb7473bf-facb-4980-a7ef-a47d1fc516a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:52:00	TRUE	FALSE			en-gb	15:52:00	06/19/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0ffa43ee-6e77-4227-8eb4-5fb569725f67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
49f2dd60-6a48-439b-97da-e48162b5b19d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
794e98cb-6b14-4859-8563-46691d5355aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:08:00	TRUE	FALSE			en-gb	16:08:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
92cec3c4-5ed7-41af-8496-2ad6e88471ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:12:00	TRUE	FALSE			en-gb	16:12:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
25f6e027-a6eb-43be-8bae-d62c4277373b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:19:00	TRUE	FALSE			en-gb	16:19:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
95554ced-18cd-4058-9a9d-34f816e0e237	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:26:00	TRUE	FALSE			en-gb	16:26:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2c053f4e-389e-4fd3-9200-7efe791876a7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:27:00	TRUE	FALSE			en-gb	16:27:00	06/19/2023		Disgusting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes											
bd0b2ff9-cb9b-44cd-b52c-2f0c9613bd2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
91f3681c-462a-47e8-b98c-55927df4c0cb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:30:00	TRUE	FALSE			en-gb	16:30:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a94fc301-da8a-43eb-a0af-59ed759b7bcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a94fc301-da8a-43eb-a0af-59ed759b7bcf	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											
b4fcb2d-70b9-491e-a006-9cc47c23edd9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:33:00	TRUE	FALSE			en-gb	16:33:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
5afba9a0-25bc-4d75-b506-73824fb5bc9b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
14e8e7a6-3757-4693-8d8d-ad221aa0a564	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:48:00	TRUE	FALSE			en-gb	16:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c58c8cff-d4eb-44aa-badf-b1a9ec63ac25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:55:00	TRUE	FALSE			en-gb	16:55:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b088b4c7-fee9-422a-af6a-31bc807a9db7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes						
1ecff14b-a821-4ea7-90ce-32c6300703ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 16:59:00	TRUE	FALSE			en-gb	16:59:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0d9be832-a462-4ab0-9ea3-b3b5cf8eb740	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fac31521-8d45-494a-9e86-0100a35b5756	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
ff25c6f8-4dc4-47d2-a8ff-8ad76690686e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes				Yes		Yes								
8f589cd8-007e-419f-a541-df1d89999990	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
17326e40-0ca3-41a4-b293-f33c44791bb8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
69918516-7649-4407-8e66-6df22824753c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:42:00	TRUE	FALSE			en-gb	17:42:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ef851672-b3cf-4e8d-9b0f-0c7ff7c5e935	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:42:00	TRUE	FALSE			en-gb	17:42:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6c387cb-dfd5-4ee3-a9ed-fec5fed477a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:50:00	TRUE	FALSE			en-gb	17:50:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0cc81728-4364-45de-a0f9-c293e5126b90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4d4abc2f-5aef-4bdb-88f9-935261afec20	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea809838-4d1c-4af0-8b04-538a6e218aa9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9ee9ef2f-42b7-4550-9865-9c2141579877	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:04:00	TRUE	FALSE			en-gb	18:04:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9ee9ef2f-42b7-4550-9865-9c2141579877	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
0753d6c9-1653-4ba4-8f30-4b813e08efc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/19/2023		Stinky	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
bc75c2ba-1a34-480a-89e8-178e9e5c4803	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:13:00	TRUE	FALSE			en-gb	18:13:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
69f07cd1-b46e-44a9-999e-4c1e6db15bdc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:15:00	TRUE	FALSE			en-gb	18:15:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4b495d6f-4fad-4524-8780-529c2a385405	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/19/2023		Bad condition	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4b495d6f-4fad-4524-8780-529c2a385405	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes					Yes	Yes				
f9bb46a8-082e-431b-be00-6d13a668808b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b1a20b07-20e4-4fcd-985f-1a828f23e9b1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
b1a20b07-20e4-4fcd-985f-1a828f23e9b1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b469cd26-744b-4c56-a65b-1262491c8aac	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
b2bb21b7-8eae-42cb-95dd-8ce819d814d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:45:00	TRUE	FALSE			en-gb	18:45:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7cbbb17a-8f56-4ddc-8ef3-6bf74f4e967e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7d9c84c0-d78a-4e0c-aa22-0bc0ca4d4b53	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c29ab08e-2ebd-46ac-850f-598b5a7bbfd4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
32f51b59-a426-45b2-a0c3-bf3aad8c8cfd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:49:00	TRUE	FALSE			en-gb	18:49:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
79ed7de6-0192-4a48-bc65-81ee0590fa3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/19/2023		Ctdddsvbm,.kmdd wshjuft	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
91494b15-15ed-421e-8194-f74b318713bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:57:00	TRUE	FALSE			en-gb	18:57:00	06/19/2023		GfddssXcv mx	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
750a96fc-7158-4866-89f3-2f13ef1be0e6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8d38166d-4314-466a-933c-17e8c1d9c27c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:58:00	TRUE	FALSE			en-gb	18:58:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes									Yes					
73053658-44e3-4ac2-ab34-c8238d7237e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
23e8f75f-d5c3-458f-9485-12a686baf010	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/19/2023		Bvggggfggcfvcbvxd	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
749b0acb-d2be-4e80-b5e5-a51367333efc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
1b7fa5da-afac-42dd-8d98-417e1b0687ed	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:31:00	TRUE	FALSE			en-gb	19:31:00	06/19/2023		Ryker	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												



### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
54e8c064-f7db-4121-8ea8-36f39c2f5976	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes					Yes	Yes				
f2870029-f1a6-4a2c-8a47-013f7e09b5d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1145041f-cc7f-4d7e-9bcd-8c12389eb23c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
ef72d7d6-457b-4d30-bbe4-d341f94a830b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:47:00	TRUE	FALSE			en-gb	19:47:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
440deb55-14bc-40fb-a413-8171de1386bd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f2317a81-145d-4be6-953e-3456ce344eaf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5fa137fd-935b-4dc2-9d0f-20dc3c425d4f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
53416b35-0e4b-412a-bae3-2c9770e9c8b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:04:00	TRUE	FALSE			en-gb	20:04:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
598515a6-5e4a-4d5e-b731-57790704068d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:15:00	TRUE	FALSE			en-gb	20:15:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
368dae58-20c9-4393-b5cf-9bedf101cfe3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:26:00	TRUE	FALSE			en-gb	20:26:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ae427aba-d3ce-49b0-84b0-58ce8cddec98	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:30:00	TRUE	FALSE			en-gb	20:30:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
303122f1-c73f-4add-b13d-c2d80c6bbccd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
298f1cc1-8b65-452f-8ea1-b8c379aecdc5c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
bea65d92-0057-4d00-85fa-9400003d374c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	06/19/2023		Good clean	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f0c06fbc-f413-4d7d-b4ba-27f8157ce77c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:51:00	TRUE	FALSE			en-gb	20:51:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes		Yes					
b4b305ee-e2d3-4ff8-9449-b74c75b1cec4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0e55eb1e-dc7c-4d1c-8427-0ef56f971cb0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
124c2bab-9822-40de-b3a3-a7d949068f2e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f7528754-81da-42ea-8bfb-62c13953b550	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:57:00	TRUE	FALSE			en-gb	20:57:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
334e2a6e-ed1a-4174-8009-9e7d749a2c0b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
bfcfb513-5992-43c5-91ed-2bfa9ede5f50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
be16beb0-7df0-4c41-822e-c8e26c46df4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:04:00	TRUE	FALSE			en-gb	21:04:00	06/19/2023		Nice
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
838533dd-3197-45c2-8e40-5e3992eb5b05	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:10:00	TRUE	FALSE			en-gb	21:10:00	06/19/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5f9d0ce3-9547-439b-8c62-3fcea5a8f7ba	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:13:00	TRUE	FALSE			en-gb	21:13:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c0e4553-740b-4079-8260-f2a284674f9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
511f1b07-86ab-42ca-a2df-a0323068cf1d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes		Yes					
357faf8-5c32-4a04-92c5-7c77239bd025	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/19/2023		I was happy to be here
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3aa05b12-643c-4109-9eaa-3e2ec3757b06	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:26:00	TRUE	FALSE			en-gb	21:26:00	06/19/2023		It smells
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3aa05b12-643c-4109-9eaa-3e2ec3757b06	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes						
37110e45-94e9-4b5b-80cc-0f12dd66cd22	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:35:00	TRUE	FALSE			en-gb	21:35:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dc378c9c-fe6f-4ca2-bb10-89d748e26452	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:52:00	TRUE	FALSE			en-gb	21:52:00	06/19/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1404401a-8785-4ae1-b4e3-f89722906217	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	06/19/2023		Ab
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4ed9fe88-4585-410a-938c-bc83c216918b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:00:00	TRUE	FALSE			en-gb	22:00:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ea457ef9-7174-44e8-86d1-fb5fb9e8f0ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:13:00	TRUE	FALSE			en-gb	22:13:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9865dcad-efd9-4b48-a049-ecb4d9a535d6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:16:00	TRUE	FALSE			en-gb	22:16:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ab857166-a1a1-47aa-b224-48a0de0e257b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:23:00	TRUE	FALSE			en-gb	22:23:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4d0c525c-a33f-4c15-82eb-b7be970958b4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:27:00	TRUE	FALSE			en-gb	22:27:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
300a9638-9f3d-4bb2-94d2-7d3b654835cb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
16472204-c3c0-49e9-bf46-755976f45532	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:35:00	TRUE	FALSE			en-gb	22:35:00	06/19/2023		I hate american airlines	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6fb38e66-bb31-4f01-a3c7-14dad632558d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
95f73711-d139-4ca3-9ea8-de7aa7e2afe5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:45:00	TRUE	FALSE			en-gb	22:45:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes	Yes					
4279040e-73e2-4731-a2e7-3043d6e7ab85	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:47:00	TRUE	FALSE			en-gb	22:47:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes					Yes	Yes					
1f94431a-31c2-4023-b993-0ec8e2474a6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 22:53:00	TRUE	FALSE			en-gb	22:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c2a3496f-047d-432e-8bb8-6f129e36ede9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:00:00	TRUE	FALSE			en-gb	23:00:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
188f880d-42d1-4fab-990b-72e09714cf29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:07:00	TRUE	FALSE			en-gb	23:07:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c2a23274-8f00-475a-a41e-adfeadafe3fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:14:00	TRUE	FALSE			en-gb	23:14:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ffc172aa-f2a6-47d7-86e6-9be4d8949274	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:14:00	TRUE	FALSE			en-gb	23:14:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
4d99336c-54a3-4a16-8531-74273c966253	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:53:00	TRUE	FALSE			en-gb	23:53:00	06/19/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9e4e9c88-96c2-4d34-a08d-2c44497a7531	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/19/2023 23:53:00	TRUE	FALSE			en-gb	23:53:00	06/19/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6ac54f34-ed19-4ca1-961c-d024dbf36a51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:01:00	TRUE	FALSE			en-gb	00:01:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes					Yes	Yes						
c801c303-4ad7-471a-a35d-85e5d6760602	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:19:00	TRUE	FALSE			en-gb	00:19:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes		Yes						
e58c2465-18f6-48c5-8ddc-d5231e412ec1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:22:00	TRUE	FALSE			en-gb	00:22:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e58c2465-18f6-48c5-8ddc-d5231e412ec1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
8b43b3f8-6edb-4185-b873-cd31fac240c2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:25:00	TRUE	FALSE			en-gb	00:25:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dac87c9a-dc17-48a2-a080-22f60a4ca04f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:28:00	TRUE	FALSE			en-gb	00:28:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes						Yes							
cb648fbf-b159-4c7d-963f-7e1f0cbf0b7f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:47:00	TRUE	FALSE			en-gb	00:47:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc2c3ff5-f001-49dd-a3a3-44d5086f5fb8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 00:54:00	TRUE	FALSE			en-gb	00:54:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dc2c3ff5-f001-49dd-a3a3-44d5086f5fb8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes			Yes	Yes	Yes	Yes				
0ad13ef3-ebbe-405d-8584-0594db93a39d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 01:02:00	TRUE	FALSE			en-gb	01:02:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d852ce69-e929-43b7-8f8f-86ceb9c0ff27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 01:17:00	TRUE	FALSE			en-gb	01:17:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes	Yes	Yes					
f166ed60-9d5d-4fa4-9c48-00e3fbd4b957	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 02:19:00	TRUE	FALSE			en-gb	02:19:00	06/20/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29a9a30e-e9da-47bc-a273-a8ccaffbd308	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 03:38:00	TRUE	FALSE			en-gb	03:38:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b8dae8f-7d1f-468e-9dc1-96a48a44b1ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 03:49:00	TRUE	FALSE			en-gb	03:49:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
cc0fc9d-d573-4f68-be44-0fad25aaafb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 04:33:00	TRUE	FALSE			en-gb	04:33:00	06/20/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
99b82349-1285-4289-b358-5ce6c4cc1e86	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:04:00	TRUE	FALSE			en-gb	05:04:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
c0b2a998-2ea9-4e2b-a3aa-37b796ac2a8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:23:00	TRUE	FALSE			en-gb	05:23:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
92ff2066-0325-4057-be8f-05d7f1e194ff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:28:00	TRUE	FALSE			en-gb	05:28:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2500f3ef-58b0-4673-9ff0-81ed29c55198	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:32:00	TRUE	FALSE			en-gb	05:32:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d6067adc-f72b-45e2-8607-0385dda0e62e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:40:00	TRUE	FALSE			en-gb	05:40:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5044b780-f842-45f8-a4ec-6c9382381f74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 05:51:00	TRUE	FALSE			en-gb	05:51:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5e740169-0d2f-4cd7-9825-6f06ebf82009	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:03:00	TRUE	FALSE			en-gb	06:03:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes		Yes	Yes	Yes		Yes	Yes	Yes				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f179641f-5992-4089-8b88-0ff044263216	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:08:00	TRUE	FALSE			en-gb	06:08:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c42376b-674a-42ea-8300-47c831341a09	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:12:00	TRUE	FALSE			en-gb	06:12:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
0fc8420c-a10a-462f-8cc5-871893e20fd6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:17:00	TRUE	FALSE			en-gb	06:17:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e83e1c2f-d85d-4dd5-afa1-f17be59c2d60	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:25:00	TRUE	FALSE			en-gb	06:25:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
73065625-8c39-40d7-8637-57f2b2123152	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d736ee63-ab82-4c36-af5c-471ebf93793f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 06:45:00	TRUE	FALSE			en-gb	06:45:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6beb71a-7f14-4c67-94a5-f277e3a5dcab	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:00:00	TRUE	FALSE			en-gb	07:00:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b41c0d4-a2d5-417a-aeec-5b9fa1a5ab08	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:03:00	TRUE	FALSE			en-gb	07:03:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5cac0ef4-96cb-47dd-9a31-90cc67dfcd5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
15fd871e-12dc-4c5b-9e21-9497268367cc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 07:18:00	TRUE	FALSE			en-gb	07:18:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
793183bb-bb7d-4146-a0bc-b2fef235a655	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 08:07:00	TRUE	FALSE			en-gb	08:07:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
89a7d761-3ed4-46d4-bb1f-e734a7f0754e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
258f77cf-d485-4bfc-bf29-e5d5d5b9237e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 08:49:00	TRUE	FALSE			en-gb	08:49:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3b804a7f-b871-4780-9dc8-1a882241ac69	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
975a1c14-f6b9-4103-83a4-1b40a88aae2a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:06:00	TRUE	FALSE			en-gb	09:06:00	06/20/2023		Mnhuik
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2a211ea1-702c-415e-9b2b-6365fe90e4ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76ee098f-54cd-4073-ac2c-0b187097f173	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
e2d0df6e-6ae2-42bb-b629-26569389b5f9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
010573c1-cda2-4e0e-bc0a-0692ac7a1b55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 10:47:00	TRUE	FALSE			en-gb	10:47:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af63a596-df58-40f3-9691-22c45e2d99d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes				Yes	Yes		Yes							
fa89a681-1e96-4405-ac9f-4d4fe218ba6c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
71fab164-e222-41bc-b77f-19b42140a35b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/20/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
71fab164-e222-41bc-b77f-19b42140a35b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes		Yes					Yes	Yes	Yes				
1e71ae36-c72a-498a-9a78-9ec7f65eac86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes	Yes					
7225e134-1a79-40d0-910b-0a76d98acc4a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
10013462-87dc-4104-a886-9fc3c61ef704	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
e315d6fb-75b5-40d7-9ce2-ee453ced8f19	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:18:00	TRUE	FALSE			en-gb	12:18:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
11defeb2-c31e-4544-bf59-5b0771059dde	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:28:00	TRUE	FALSE			en-gb	12:28:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f9dfc60d-4a19-42df-acbd-3e096c61130f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d1a1592d-f459-4b82-a9fb-f5f1c364a4e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 12:59:00	TRUE	FALSE			en-gb	12:59:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
093ca251-849f-47a6-9d2f-66f29a86ab92	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
89169360-28d3-46ab-abf7-37db5adccc7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b6fc956b-f4cc-4bfb-82dc-238997db095e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
b6285ecc-a72a-4d30-8216-b897744cc91e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/20/2023		Finish												
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
645f9f5d-9291-491e-85cb-2bc5fbc6b7ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	06/20/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
af923116-3093-4c77-af92-93a601622bc6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:12:00	TRUE	FALSE			en-gb	15:12:00	06/20/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
51a398e9-df65-436f-aef2-c30805e869d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:20:00	TRUE	FALSE			en-gb	15:20:00	06/20/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										
924ada29-030b-4947-9a9b-4b2f8f9943f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	06/20/2023														
															How would you rate this restroom today?											
															Average	Good	Poor									
																Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cadc2c7f-846e-49e1-b96e-96734aad06a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 15:53:00	TRUE	FALSE			en-gb	15:53:00	06/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
63cc43b6-5962-436a-bf88-6f8000e10522	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4a160d5e-306e-4bc4-9caa-f6f35b0b3d71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	06/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f689605b-c8b6-4aa6-8dbc-96db4a1aafd5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
343c81b2-0df2-4aa1-b640-5c7cc824da35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	06/20/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c685c271-b04a-4583-a1b1-cd6475decacb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:07:00	TRUE	FALSE			en-gb	17:07:00	06/20/2023		****
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
336bc4c1-acdc-4daf-9d0b-dcd31a150828	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
455c3f65-73ad-4e3c-b04e-669a2b39d5cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
35be5ba4-a91f-4dc3-a7aa-c5c08ac5020d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 17:54:00	TRUE	FALSE			en-gb	17:54:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes		Yes						
9c7440c6-63ac-4025-9438-c26a0f6e8506	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:05:00	TRUE	FALSE			en-gb	18:05:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
df053044-bacf-4924-91c2-ccc81cd65b94	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:22:00	TRUE	FALSE			en-gb	18:22:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b91b78d7-a092-47fa-8158-8db28b82fc2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8b9efa1b-ebf6-4d3b-9f75-d174e1cd473d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:43:00	TRUE	FALSE			en-gb	18:43:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ee4efa8-bf6a-4ae7-a866-514fcaa8e1c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 18:54:00	TRUE	FALSE			en-gb	18:54:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e0f1897b-058e-44b2-afa3-9b85c38cfcfb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:00:00	TRUE	FALSE			en-gb	19:00:00	06/20/2023		Keep up the good job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
590731cf-1c6e-443c-9d78-c8c08f7ffdee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:07:00	TRUE	FALSE			en-gb	19:07:00	06/20/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b451ab5-e31a-438c-aa50-55a9e0a9641e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	06/20/2023		Make equipment newer
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fbeca1fa-4894-47d3-af7b-318a8be03e86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d4b615c1-f0e8-43c2-b6ad-30b6b2317b49	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9e166d26-0df9-4d3e-b945-6b0535e96ae8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e9703351-d607-4a43-87fe-74ce58cb41f4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c89cb05c-19d8-47c5-9d43-08683546d64b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 20:52:00	TRUE	FALSE			en-gb	20:52:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b1f27e2f-fceb-437f-9747-2017d04324fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/20/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cfe307bb-a16d-44b9-aeb8-d3bb2ab858c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:16:00	TRUE	FALSE			en-gb	21:16:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55a07ebb-fa3c-49ec-b9d2-6e2d4bc2a35b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:18:00	TRUE	FALSE			en-gb	21:18:00	06/20/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fe3e021c-8d9f-447a-9666-69af7c77bf22	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:30:00	TRUE	FALSE			en-gb	21:30:00	06/20/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes		Yes	Yes			Yes	Yes						
4c2f2b0f-8922-4e39-a7f0-e5630be32563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/20/2023		It was very clean and good to use	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a3241c46-faad-4b73-bf15-be0cb9458a26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 21:40:00	TRUE	FALSE			en-gb	21:40:00	06/20/2023		The toilet was clean	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment												
0e1883f7-a3dc-4ec7-860d-5454d50f49de	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 22:42:00	TRUE	FALSE		en-gb	22:42:00	06/20/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
ff674276-6b6a-4f0e-b039-00ee6bda9795	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 23:13:00	TRUE	FALSE		en-gb	23:13:00	06/20/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
															Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																	
	Yes	Yes	Yes				Yes																			
e670cb44-fe5a-47f9-9857-51758783d16b	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 23:22:00	TRUE	FALSE		en-gb	23:22:00	06/20/2023														
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>												<b>Poor</b>											
	Yes																									
614386b6-90e8-4d60-a45c-9191924c31d8	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/20/2023 23:26:00	TRUE	FALSE		en-gb	23:26:00	06/20/2023		***** streaks												
		How would you rate this restroom today?																								
		<b>Average</b>	<b>Good</b>											<b>Poor</b>												
														Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																										
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																	
						Yes																				

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5e774616-3251-4dfc-bbf9-47721b79c556	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 00:04:00	TRUE	FALSE			en-gb	00:04:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
5c294e18-c23d-4f4a-baa1-174dda37dca0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 00:58:00	TRUE	FALSE			en-gb	00:58:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
1003d98c-0646-4355-8237-3bc41ca34827	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 01:14:00	TRUE	FALSE			en-gb	01:14:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
29833d73-47a7-43db-bf42-90098b49a237	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 02:42:00	TRUE	FALSE			en-gb	02:42:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3f56f452-84b1-45a9-b165-3bddd88bf41	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1ccd5444-8fd0-46db-b44e-15287438047c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes		Yes			Yes	Yes					
31013a6d-5363-4704-be24-cbdbbacfc624	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6c094b04-d2f3-4853-a51b-2bfd1c43b66d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98986f69-2188-4dc6-a129-b807402972e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	06/21/2023		Excelente	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
92b33312-f2c8-4d50-b4e4-3c0d5dd3c549	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1446fa6f-116f-4217-8c9d-8cea77092c42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 07:56:00	TRUE	FALSE			en-gb	07:56:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
efa936b4-3876-4d2c-b2f1-4251460f9a02	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 08:45:00	TRUE	FALSE			en-gb	08:45:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
31a066e3-d992-43f4-a131-20e41db9153b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b906f86-74a9-4cb8-8a3d-c139bcf559d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 08:53:00	TRUE	FALSE			en-gb	08:53:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a95562c5-d4b2-4eb3-9a15-6c51e9168abd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 09:15:00	TRUE	FALSE			en-gb	09:15:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c5477d31-60a9-4cb7-8b57-9fe8a4d6e9bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dbf12942-03d0-498d-94ab-18a3a9ecebf7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3271268f-225d-4a50-a167-d63b03af4b1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:03:00	TRUE	FALSE			en-gb	10:03:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
263854f1-fd22-4768-a078-67f566aa9502	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:10:00	TRUE	FALSE			en-gb	10:10:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2ae2069e-4400-4d55-b7ad-3d4dc457cafc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/21/2023		Its amazingly not good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes							

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
555794c2-17ee-45f3-b836-25ca04cf9832	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 10:45:00	TRUE	FALSE			en-gb	10:45:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
eac28dc7-22cc-4eb8-a8cf-90fcc7d4294f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3031321f-2c1f-4234-b886-8bc23771d598	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7f7b9d0e-89bb-4285-9b68-90414fe4a917	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
57310b30-12f3-4bee-9289-2bafa84161d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a42bce47-98f1-4c41-81ee-9b281baa07ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
47d14bc5-0961-4bde-9465-31107aed388c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d8a663b4-e32a-459f-a412-e10832306e3c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:42:00	TRUE	FALSE			en-gb	12:42:00	06/21/2023		ldk what tht smell is..	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes	Yes							
45de3a2a-1e65-4c01-a22a-d9988341bde0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2bf424a3-8fd8-4af9-80f8-9fbe8e7910a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/21/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
d30d85ff-b136-4f7d-8cf7-df96ffe7206f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/21/2023		H	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d30d85ff-b136-4f7d-8cf7-df96ffe7206f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes	Yes		Yes						
ee8cee89-d26a-44a4-ad00-2383534cabe8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
98eede09-059e-4968-ae45-a09b9bf0adf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/21/2023		I liked it today more than i did yesterday when i got stuck in the toilet
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f8bbb065-c90c-4d40-bf9a-9dfa143e83c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f220ff1-8876-416b-bf98-1f80f675a730	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
861418cc-a529-4653-9f3a-5b265f762f4b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:27:00	TRUE	FALSE			en-gb	14:27:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3462b4fa-9031-46c9-a835-3de5527f2c81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:31:00	TRUE	FALSE			en-gb	14:31:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e20b6cd0-3003-46ae-a22e-fe1e3ec32899	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
061b6b8b-a57f-4f05-a7da-6ea5600026ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:51:00	TRUE	FALSE			en-gb	14:51:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes						Yes	Yes	Yes					
41fa6971-4f8e-4343-b7a1-39f7a3faede1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 14:53:00	TRUE	FALSE			en-gb	14:53:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4f5d9bad-f19d-44b9-9ba5-f955313d9a78	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4ad1add4-9eab-4575-aba6-7930230c10ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
84433ac6-fca4-4984-bd0a-19f6bb7a20c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:19:00	TRUE	FALSE			en-gb	15:19:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40b571a7-020f-4fbb-82e4-bd62f66f78e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d780ab1b-6fb8-4771-99d1-8afd175c2cb1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/21/2023		The bathroom was so clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
50bd9893-6f82-44cf-9178-e2bae0e76058	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
46d44fc4-14d0-4ac1-b517-fa3bfe93a70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fa3f6b8a-4ff5-4199-a0c1-027383e1a968	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
06669546-6b7f-4863-a442-630a6300f8f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
65d12a9d-7ff9-4f0b-845c-10056ce10566	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 17:08:00	TRUE	FALSE			en-gb	17:08:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
80e780f5-b5ae-4002-ba6d-3789960af410	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 17:32:00	TRUE	FALSE			en-gb	17:32:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
133e4271-ece7-4022-b04f-8d634eb6aedb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	06/21/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
11c6821a-20cb-4cfe-b105-bc5cfabe297e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b947562f-2aaa-4d40-9aab-30a7adb9e5f3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
881fd5eb-1d08-4e1e-87a6-e62bb68723fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 20:08:00	TRUE	FALSE			en-gb	20:08:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0c3961fb-3166-4173-9399-2d73847d8ae7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ef0084ee-779f-4050-b330-038b9bade3ad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
81136899-c250-485d-8ec4-f37f25f45985	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 21:20:00	TRUE	FALSE			en-gb	21:20:00	06/21/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
81136899-c250-485d-8ec4-f37f25f45985	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
										Yes					
799b122e-af61-4b68-a75a-2c0072a103b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32142ae9-ec6c-4115-9c97-9cb78d34d8ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/21/2023 23:19:00	TRUE	FALSE			en-gb	23:19:00	06/21/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
8dd95b69-0378-4a1a-8725-5db7d3353c07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 00:05:00	TRUE	FALSE			en-gb	00:05:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4b415cd4-e52b-4e2e-8dcd-1c49cefc78d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 03:38:00	TRUE	FALSE			en-gb	03:38:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02b01e71-a427-4b42-aeb6-f250951b2bfa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 04:57:00	TRUE	FALSE			en-gb	04:57:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9418577-24bb-4210-bb37-f5ca8a891927	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b148522-54e3-427a-8847-77b66835c2e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 06:18:00	TRUE	FALSE			en-gb	06:18:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1c1e4d8-353b-41b0-a991-0224054a50db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1b0dc11-a93a-4ba6-aa2f-857384df8175	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f27b030b-8585-416e-9763-a2be7f8171ef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 07:49:00	TRUE	FALSE			en-gb	07:49:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b3b7ba54-4114-4641-b7b4-5a80ac9f3436	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes					
35ab5c5c-1d46-4233-a083-b3ec995244c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:23:00	TRUE	FALSE			en-gb	08:23:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9320d3bc-5ca2-4c15-a9d9-fbbf6f6d824c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ee05abb4-fd95-4662-bced-100db59a4c5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
0b5cf416-55ad-4e33-96e3-4706b3ecf976	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
54a578c3-0a00-4a7b-aa8f-e0453f159372	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
877aa2de-3ad0-4e04-ae20-cef6e5cc0b1f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:14:00	TRUE	FALSE			en-gb	09:14:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
a0313eec-3c10-4d27-a643-42292f695a3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:49:00	TRUE	FALSE			en-gb	09:49:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
384c9b59-f0e8-442b-8aa0-9b810a4244ea	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:50:00	TRUE	FALSE			en-gb	09:50:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
cd96b821-ed6-41c3-882d-8919da5df49f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:54:00	TRUE	FALSE			en-gb	09:54:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
23395d5f-55b6-42c7-bd18-0f93341ec2c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 09:57:00	TRUE	FALSE			en-gb	09:57:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c97b340e-fe93-460c-8ca6-5f5919515b2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
68a34283-f225-4400-97b2-2afc7f5f54cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes		Yes					
fed2402e-1cd3-4c13-9065-729c89079e77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:07:00	TRUE	FALSE			en-gb	10:07:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6d55dc09-6644-434f-836d-57db780df119	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:12:00	TRUE	FALSE		en-gb	10:12:00	06/22/2023		FffydtezeaEe stgbbuccwzwtv bhnnninnj,oko,ll.l.p	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
85a5782f-386d-4c1f-b387-d8aa38f1f5b7	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:19:00	TRUE	FALSE		en-gb	10:19:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8636397b-e206-4a3b-a19c-409d01be7512	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:42:00	TRUE	FALSE		en-gb	10:42:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
daca5a8d-6e9a-45aa-89ba-b7be0c2d2c84	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:45:00	TRUE	FALSE		en-gb	10:45:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
be3f51c9-edbd-46aa-b24a-f0ea07d16128	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:50:00	TRUE	FALSE		en-gb	10:50:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
94c90c3b-c3f0-4659-b7d6-b2a0ca75ad5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
d23fe557-8cba-48f5-a50a-bfd1b0555824	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 10:54:00	TRUE	FALSE			en-gb	10:54:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
ea4be07e-cd8c-4881-b482-9cb2568d95a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
f0bf8001-24d1-461b-97e2-974f4cb6cc88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:08:00	TRUE	FALSE			en-gb	11:08:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
d1d32b5c-921b-4711-a7bd-55c5153a71dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	06/22/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
710e529b-97e6-4501-af19-c7c4bcc02b1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c5820c2-9843-4f79-8623-20d47bc09797	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
39c0a33e-0c9a-4017-8dbb-6df9680befe8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 11:54:00	TRUE	FALSE			en-gb	11:54:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1a6a4e3f-7339-4905-a8b0-96d534cfb9d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:05:00	TRUE	FALSE			en-gb	12:05:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2d489e8-2b6f-4a23-af75-fa63093a8d28	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:24:00	TRUE	FALSE			en-gb	12:24:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d993c15e-cac2-484c-a2e4-7181735ec145	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:25:00	TRUE	FALSE			en-gb	12:25:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
578a0027-0c04-46ee-822a-7e4c2a2cbfa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:31:00	TRUE	FALSE			en-gb	12:31:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2e8009f6-26bb-454e-ba2b-2c82a713ceba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 12:36:00	TRUE	FALSE			en-gb	12:36:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ded7629c-2ca2-490d-afc0-341a35bcbd73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/22/2023		Super
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ff795b66-62e0-4bec-a947-aebd5b7072a0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:06:00	TRUE	FALSE			en-gb	13:06:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
367efc0d-c66a-4a26-a3fc-0bc0a736633a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/22/2023		Limpio
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
541aafac-0dfc-4e7b-b22d-8cf3fb7dbec7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b7c6052b-4501-48e6-9be8-a7e1e6e9a874	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:29:00	TRUE	FALSE			en-gb	13:29:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
3c2a2115-c29e-4c52-9756-be5fb8c2c236	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/22/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f52cf988-06dc-4547-89b4-3c855c76a658	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
196cfd48-c1b4-4cf0-8336-c937377d8a87	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
a80d7776-3f45-41d8-887a-d10db76471fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:51:00	TRUE	FALSE			en-gb	13:51:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
212040ff-d78c-464f-8843-284e1f915556	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
72a58aca-b900-41dd-a89c-195b71de796a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6191c8eb-78a3-49e7-82fc-ad95acf68715	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:12:00	TRUE	FALSE			en-gb	14:12:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b09c3469-7e60-40b7-91bb-d38b3efebae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a35e4b81-1f20-4580-9c3f-f40c56766d64	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
78fb8b64-cf22-49c9-a213-8ce460e60756	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:41:00	TRUE	FALSE			en-gb	14:41:00	06/22/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
dfb1c076-58fc-4afe-86da-1c63f807be13	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	06/22/2023		****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f3595a95-d655-49b6-baa4-6fa7a876a8ea	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes						Yes								
2140f5a0-5e4b-49cb-a2bd-4f06cc40c86b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:31:00	TRUE	FALSE			en-gb	15:31:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
af5b205d-18cd-4e83-b8cb-d60fdde59424	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:37:00	TRUE	FALSE			en-gb	15:37:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eeded6e8-ee7f-4ab2-9a46-3eae0f544642	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
296a0058-01e7-4ff7-8bd2-b5c6efbca15e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/22/2023		Clean bathroom	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e71e249d-ade1-4947-966e-7312e85aa5ca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
ccef1621-37da-4364-bd64-4a00d8ec3df3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32c2dba6-e6cf-42a3-a8c8-219a100df443	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	06/22/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d7ed7ae0-fc66-4977-9a2e-7e55bf94681a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:57:00	TRUE	FALSE			en-gb	16:57:00	06/22/2023		R	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d7ed7ae0-fc66-4977-9a2e-7e55bf94681a	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
	Yes													
e6cc1e5c-f1d9-4190-aa84-580a62ad3da2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
e541c4cc-daf3-42c2-9033-f67a08dc7a30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1e0b70f4-b524-432f-81fd-1abbcc5de68e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
546af792-0410-40d1-b607-1039bc8bc8eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
420b01f4-0e58-4e23-93f5-f8a512fcfb08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 17:35:00	TRUE	FALSE			en-gb	17:35:00	06/22/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
420b01f4-0e58-4e23-93f5-f8a512cfb08	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
										Yes					
4e366ac5-551c-4e52-8e22-d18be54144a9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 18:44:00	TRUE	FALSE			en-gb	18:44:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6336e50b-b711-4115-a956-7253697f5e03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes											
59a702e3-a977-41e0-a9f9-995c1eb21a0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 21:25:00	TRUE	FALSE			en-gb	21:25:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4ef54b71-b987-411e-b503-8e94c6581bfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/22/2023 21:38:00	TRUE	FALSE			en-gb	21:38:00	06/22/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
70fb0960-1df9-4cdf-8977-2c337fa3bf2d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 03:51:00	TRUE	FALSE			en-gb	03:51:00	06/23/2023		Goob job
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0b170b88-b38f-4b98-b374-25d91e985e84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 05:41:00	TRUE	FALSE			en-gb	05:41:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
63bfba8c-ce4f-4172-924c-27332a3a6b3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:21:00	TRUE	FALSE			en-gb	06:21:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
69df4dca-eddf-471a-9013-396c5b9e3efd	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:31:00	TRUE	FALSE			en-gb	06:31:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6e64cf9a-83fa-47f5-85c9-4748b020d52e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:33:00	TRUE	FALSE			en-gb	06:33:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc3f8c04-b36d-4156-9e31-9c6113340667	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:38:00	TRUE	FALSE			en-gb	06:38:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
eabc95f0-dd67-4aad-a52d-97a367f4b217	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 06:46:00	TRUE	FALSE			en-gb	06:46:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55122b45-0592-4038-b29c-fe6c42db6c5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes				Yes								
2403f1b4-d8f2-418a-8e55-cabdd6c8a9cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:33:00	TRUE	FALSE			en-gb	07:33:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2e7783cc-9662-4177-bd05-61eb8a462701	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:39:00	TRUE	FALSE			en-gb	07:39:00	06/23/2023		Ecelente todo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
21c19367-8f9c-4869-823d-9b6acc57faa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 07:41:00	TRUE	FALSE			en-gb	07:41:00	06/23/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ef52b354-d265-4122-8dcf-5e566a95c0c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
470142bc-53cc-4b0c-a9ac-fcb3824bab2c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:36:00	TRUE	FALSE			en-gb	08:36:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5ed99417-132c-4a08-9666-de5924b159a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
fb9d6bcb-b5d6-4d9e-98a3-698cfe78677	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:46:00	TRUE	FALSE			en-gb	08:46:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
f7849d8a-ac0d-4db9-8cde-bb0513752af0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 08:47:00	TRUE	FALSE			en-gb	08:47:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4d8643d1-ddcb-4cde-b40c-d9b9692647e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca50d368-3f83-45b5-b855-68a8d781c5e7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes											
9f3d4ed7-e43a-4740-b08a-92e3dbb8f889	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
809b0d31-c8cd-40f5-84ec-3684c66bb703	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:44:00	TRUE	FALSE			en-gb	09:44:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
22d9db25-da89-4aea-bbe8-8cc339286c98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
ed54b76e-530d-4364-8c12-5c74f49dc422	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/23/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
0c3b8179-8771-450a-ab7c-33b3e4623f8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:06:00	TRUE	FALSE			en-gb	10:06:00	06/23/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes					
2c3712b7-b2c5-437a-9812-060e8f8a227d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:18:00	TRUE	FALSE			en-gb	10:18:00	06/23/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
														Yes		Yes		Yes	
7d8c84bf-fc15-4ec0-bce5-8becccd13746	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/23/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3cf54e09-55e7-4702-8ac0-68c1fff97cca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:37:00	TRUE	FALSE			en-gb	10:37:00	06/23/2023		Tood
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a27b5fc3-1d93-4cd3-83af-5ef963f16b86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:52:00	TRUE	FALSE			en-gb	10:52:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d30adcf4-dcf4-438d-9f04-513bce30f3fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7b4f6963-df3e-4e2a-9c32-af67132f51e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd02e704-fdd7-4910-aa31-91ee205471a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b72c5cc5-6c65-4bac-b948-b21ee4c8723c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:41:00	TRUE	FALSE			en-gb	11:41:00	06/23/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
80f41e3c-e964-4a91-a139-f3230e1c826e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f2c0537c-d9e1-45aa-ba5a-d2bd9a6a64d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:35:00	TRUE	FALSE			en-gb	12:35:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7eec3b33-fb23-43b1-b016-5d3db5943837	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:39:00	TRUE	FALSE			en-gb	12:39:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ed3b7d19-26f1-482f-bf70-1b51334c5054	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:51:00	TRUE	FALSE			en-gb	12:51:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						
812cd458-9910-4353-bd23-c96cbc38f787	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b71e988a-0784-4e8a-9ccd-5ecd1dda0836	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4281f4a3-e4ac-4c73-b69a-601656e47ddc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	06/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
20c9f425-66db-43ab-bb59-233dddab6c66	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:17:00	TRUE	FALSE			en-gb	13:17:00	06/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6a2f5fe0-398e-414a-ad13-6701080c6985	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/23/2023		Its alright
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
55f82fee-1cc8-4b7e-b6bc-de4ef71248f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
356b728f-af7e-49be-bb70-6027345ce3d0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/23/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
63631ef4-f035-4d5a-837b-5c65349ca053	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b4d31063-3a4f-4091-bf5d-47a597747579	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
13306158-df11-4fc4-a7cb-d04ad9b9d683	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes							
0412813a-815e-47d6-8ffb-861a77ac55ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:32:00	TRUE	FALSE			en-gb	15:32:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
3a77dab2-ea3b-4fbd-8308-f6b7ce9783c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/23/2023		1	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
3a77dab2-ea3b-4fbd-8308-f6b7ce9783c8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes											
e1c690c8-0bd8-4220-9f02-b4e29316cecd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/23/2023		???						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
05e52d97-2415-45bd-8625-9ea3110bbbd7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
09bbe6e6-7514-4336-82e4-3638ac90a452	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
ee8d3aa9-64c7-482f-b8f2-18d8094c5d43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 16:53:00	TRUE	FALSE			en-gb	16:53:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		
1782b72e-a982-44e6-adfe-d3226d4dabf6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 17:05:00	TRUE	FALSE			en-gb	17:05:00	06/23/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
56361e58-da21-4991-814c-c0f182acbb29	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c1162408-9a0c-4d5f-a145-ae66754fc1d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 20:03:00	TRUE	FALSE			en-gb	20:03:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aade9e55-164b-480f-9895-3415603e8f1b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes				Yes	Yes						
ced356fa-1d5e-432e-8752-f63494ee052d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
eab71bd6-0da1-45ca-ad9a-bb555c708e3d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	06/23/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023      **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
eab71bd6-0da1-45ca-ad9a-bb555c708e3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
							Yes								Yes					
6b1c6dc3-287b-4612-a6bb-4ea42af0b6a9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/23/2023 23:11:00	TRUE	FALSE			en-gb	23:11:00	06/23/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
f5f02590-1b55-44ff-ab38-cc1fc0adf2de	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 02:14:00	TRUE	FALSE			en-gb	02:14:00	06/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
a1836172-407e-4144-8a95-f65ef02d9156	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 02:36:00	TRUE	FALSE			en-gb	02:36:00	06/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
71dc92f6-95c5-4b12-8c12-3f7903913aa1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 04:21:00	TRUE	FALSE			en-gb	04:21:00	06/24/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
					Yes															
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
		Yes												Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
255bc594-8358-498b-85dc-e1e1a02076d7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 05:50:00	TRUE	FALSE			en-gb	05:50:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
74504ccf-9453-4e2e-b05f-db946ac1b87a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
752802d1-c36c-4d69-b4a7-cf163f9e8324	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ba4eaf7f-a07a-41af-a44d-60446d3cca3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
94fb75bd-67ea-465f-98b1-bdc76722eed1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
571b06d2-4bbb-41f3-8601-5ae152db94e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/24/2023		Sucioooo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
126df87e-b94c-499a-ad95-734d8c8637a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:30:00	TRUE	FALSE			en-gb	10:30:00	06/24/2023		Parece hace un mes no se limpia aqui	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a06d7712-2ee5-4d41-87c3-3e95219ca10e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 10:34:00	TRUE	FALSE			en-gb	10:34:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes		Yes												
2ab3bcfa-42c1-4f1b-b81d-f9b5920dd9a7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:11:00	TRUE	FALSE			en-gb	11:11:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7838b9e9-1406-4118-b5ed-935174538563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/24/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7838b9e9-1406-4118-b5ed-935174538563	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
d9564c7f-32a1-4750-856d-dacdce4a4c08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:17:00	TRUE	FALSE			en-gb	11:17:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6db1cd91-cc57-4232-84af-6108e9cb317e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd5faa01-2206-4e26-afbb-d4c32330d5f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b69f74ab-4fe3-40cf-94f0-d9092acedee5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9e19d2fd-46f7-42f4-9899-b4aa68500763	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:02:00	TRUE	FALSE			en-gb	12:02:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dd05bd3d-8784-45fb-850c-998556797f5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:10:00	TRUE	FALSE			en-gb	12:10:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0ee5aaca-dcb2-456e-98bc-69b699fb4eef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
25473d52-d6b6-44d0-9242-540aae7b21fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
0bb9281f-116c-446a-a33e-504c5af6486b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	06/24/2023		Funky joe is cool	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8f355dde-2b56-4511-9a31-0f396dff46b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
583685c4-17c2-41a5-b725-e167c0d39b6a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
582e38ab-02b6-4805-8823-ed5c4e39861f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
f1116084-b97f-439f-98d4-f9dccb3a3955	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cdb62f88-a799-4c4f-a198-b71f58b9685f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0b625636-9610-4054-840f-46b783c70914	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:48:00	TRUE	FALSE			en-gb	14:48:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
09cc8882-4d11-4f19-8a19-cc86c098b358	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 14:58:00	TRUE	FALSE			en-gb	14:58:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
218bc727-acdf-4ce6-a9c2-1ed1dd55181f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 15:10:00	TRUE	FALSE			en-gb	15:10:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
15c3c46e-cb49-427d-a3ba-3c8165d36ea8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 15:11:00	TRUE	FALSE			en-gb	15:11:00	06/24/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
15c3c46e-cb49-427d-a3ba-3c8165d36ea8	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
9d3d0dc6-58e6-4d24-82e5-5311a4a52aa0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 15:54:00	TRUE	FALSE			en-gb	15:54:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
83ecf1dd-a2c7-425e-8226-99bbc99b9bbd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c93a1401-576a-4cd6-952e-4e02daed264b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 17:11:00	TRUE	FALSE			en-gb	17:11:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
8461e2ce-c0b9-483d-9c52-d4a7c8b78e97	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3bedd3cf-87f6-4fd9-a4c4-c5f865a704dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:00:00	TRUE	FALSE			en-gb	18:00:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
ff999e42-0766-41bc-8826-7695c034e0d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
38013116-847a-4352-9149-f223dbd3674e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:23:00	TRUE	FALSE			en-gb	18:23:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
cae68719-14f7-4c8c-909a-f57ba3ff2eef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:28:00	TRUE	FALSE			en-gb	18:28:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes		Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5bcf711f-87d6-4d87-a0f5-5d280a9691c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:36:00	TRUE	FALSE			en-gb	18:36:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
cdfcc3b-e1cc-47c0-bbd9-02e6f8c5ac24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0757f162-c362-4a16-a391-81a9965c8a57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:02:00	TRUE	FALSE			en-gb	19:02:00	06/24/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8fd7428b-5e04-4ecc-9113-290217fa83a4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:04:00	TRUE	FALSE			en-gb	19:04:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5e28c81f-6746-4f50-a1e8-d1b909bc797f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c8923ca1-69c4-4338-8fb8-d9ae3a4b30a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:16:00	TRUE	FALSE			en-gb	19:16:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
2321e52f-8743-4234-8c4a-3114b944c795	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
d1a2e29b-1750-4167-a029-2a5b3f53bd67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/24/2023		Needbmore stalls	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
cdddeb0b-22cc-40c8-80fc-7aa9bf9dc571	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:36:00	TRUE	FALSE			en-gb	19:36:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8aa52968-f2b1-4270-bba5-d1f99ff1b146	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/24/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
8aa52968-f2b1-4270-bba5-d1f99ff1b146	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
0789cb63-b04c-4957-9597-c573b8f517c4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
53e9e051-4a91-498a-bab4-1b951f71929c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8709f758-531f-4abb-8719-328a00b17987	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:06:00	TRUE	FALSE			en-gb	20:06:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
944db65b-d7de-4a65-91ad-cb576ad9bb8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:21:00	TRUE	FALSE			en-gb	20:21:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
22d93f92-b624-4873-b5f6-45064c69ad56	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/24/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1f8beea2-db4d-4c1d-baf0-b86bf8bbaaac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:40:00	TRUE	FALSE			en-gb	20:40:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0adf5dbc-7e3a-4fb3-8c2d-91112721b0d4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:47:00	TRUE	FALSE			en-gb	20:47:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d60fb363-e544-4265-9bb4-93a96f7d430e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
48d3bd37-978f-456c-9a25-17e81140d502	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a3104acd-a137-46e5-b44f-4e5fcd8e2081	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 21:02:00	TRUE	FALSE			en-gb	21:02:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
06f1f92b-aa45-4106-806b-6200aebf1bb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 22:12:00	TRUE	FALSE			en-gb	22:12:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
4feb8131-2c78-47bc-a760-37d6d61fee9e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 22:15:00	TRUE	FALSE			en-gb	22:15:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
8c80bcd1-876d-498f-95a3-f92da614806a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/24/2023 23:12:00	TRUE	FALSE			en-gb	23:12:00	06/24/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
8b201051-282d-439c-9f3b-71183e4315bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 00:04:00	TRUE	FALSE			en-gb	00:04:00	06/25/2023		Smell terrible	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8b201051-282d-439c-9f3b-71183e4315bf	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
									Yes						
23729759-be1d-4741-b582-c7210528b613	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d2b0bef0-87b9-4c6b-ac2b-7812cde67ac7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 01:28:00	TRUE	FALSE			en-gb	01:28:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
							Yes								
768274ed-6308-43fb-8272-267dd5d4256a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 02:54:00	TRUE	FALSE			en-gb	02:54:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fbca4f62-2bc8-4798-bcba-5ce99bbca325	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 02:58:00	TRUE	FALSE			en-gb	02:58:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
fbca4f62-2bc8-4798-bcba-5ce99bbca325	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes		Yes										
d5250e2e-be31-43ad-8d82-0a1c259c7ba4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 04:22:00	TRUE	FALSE			en-gb	04:22:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66b3b79c-50cb-463a-9e89-a99d403b8f99	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:14:00	TRUE	FALSE			en-gb	05:14:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ee395174-c622-4bc2-98b7-a19eabf514de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:17:00	TRUE	FALSE			en-gb	05:17:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes			Yes			Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f9758669-f302-4b71-bc80-ac34002dac3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:51:00	TRUE	FALSE			en-gb	05:51:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9230348b-f377-4caa-a705-fab1fb680f5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 05:55:00	TRUE	FALSE			en-gb	05:55:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5046019e-7c3c-4361-8398-fb3ebc27ca52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 06:58:00	TRUE	FALSE			en-gb	06:58:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
62c93cdc-d2a2-4983-b8e5-19d85c0b7d9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c1fe5f80-bd27-49fd-8f6f-2daf9106c641	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
475c5ee1-1e4e-4779-8b25-53cd91de1997	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 08:19:00	TRUE	FALSE			en-gb	08:19:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
54840011-94a8-431c-8e7f-15f45b9780b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85211060-e60d-4199-9c86-7e94db593ba9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b18514b0-035b-4743-bcb4-a325c12297bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3936fe75-acf6-4df2-9e6b-07a8736156c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:28:00	TRUE	FALSE			en-gb	09:28:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0f374f34-0f49-448e-9553-f491aed533a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
706de0d1-5051-4356-8c2e-5f20df8a42b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4bd52eb3-3d75-4abd-b5ee-490963375d95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:15:00	TRUE	FALSE			en-gb	10:15:00	06/25/2023		Tom
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c216d856-56f2-43f7-ba06-fbe2162d1b39	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:31:00	TRUE	FALSE			en-gb	10:31:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dd07e376-0951-4802-8081-5addc22055a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	06/25/2023		No trajan aquinsuciooo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
4bdb2a6e-0731-4137-b437-8c6f53b71a79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:57:00	TRUE	FALSE			en-gb	10:57:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
093e9c66-c270-473a-8455-844fec3d9883	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0739c1eb-ce27-4c62-ac8f-e52ac682cae3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0cb7bb5-c605-4370-8a2c-c8fe86e5e119	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:00:00	TRUE	FALSE			en-gb	11:00:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
485a09f8-559e-4806-83a3-16c732e8ef08	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bd08ec22-c022-408f-82ec-2d8e7fe1dcd6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:38:00	TRUE	FALSE			en-gb	11:38:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d33e499-7bd1-40ca-ae0d-1e468d51a503	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 11:48:00	TRUE	FALSE			en-gb	11:48:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
1e366212-7115-4aed-9e1d-a2c1073eef4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/25/2023		Dirty	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes					Yes		Yes					
908d577d-e108-46ac-b52f-6dd47e144e98	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
28575a21-dc26-47cd-a17f-70d25b0ba823	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes				Yes							
df6d258f-e40d-45e3-988a-3373759a6467	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
df6d258f-e40d-45e3-988a-3373759a6467	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes							Yes					
cd0879bb-114c-4091-9064-4d37b6a49f7a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:40:00	TRUE	FALSE			en-gb	12:40:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2ca786cc-9eb1-469d-94d3-a9fdb13cac8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:53:00	TRUE	FALSE			en-gb	12:53:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74d432b9-a14f-4b0f-9473-f9100846df43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 12:55:00	TRUE	FALSE			en-gb	12:55:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
38173d5f-6c95-4bf6-81b1-eba3b5fdd255	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5bc5b9d4-ee32-49f3-85ba-4c0080a34467	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:02:00	TRUE	FALSE			en-gb	13:02:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
30fd1760-bf4e-43d4-af3a-10fc498db05e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:07:00	TRUE	FALSE			en-gb	13:07:00	06/25/2023		G
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
575ed528-7a95-4611-82e5-11a70a947a17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:15:00	TRUE	FALSE			en-gb	13:15:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes												
ac234436-aa89-4a98-9ef9-ea11ef32b092	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:34:00	TRUE	FALSE			en-gb	13:34:00	06/25/2023		Dfghjk, b cv bvawrtg??m v,,,lmmmmmlhhc ssss md cn xxxrggggddddd dcccccc dddvcbrt tttv fnff nnddcff xvmmmmmmm mmmmjnnnnnn nnnnnnnnh hhhh hhhhhhhh,,,,,
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
b195daa7-be62-4399-8b0e-8eebd6aa31f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:35:00	TRUE	FALSE			en-gb	13:35:00	06/25/2023		Jj xshhjdcmddddd dd,ddddnhhhb ccccc kkk,nnnhjjjjigaas					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes													
cd5c9012-7ede-49c8-9d91-a6cff9d878fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:36:00	TRUE	FALSE			en-gb	13:36:00	06/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
Yes														Yes					
ce308943-b97c-4f64-ac57-a51797af18d1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	06/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
cadabb23-24ff-4015-bd76-b75dd71f6a68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:03:00	TRUE	FALSE			en-gb	14:03:00	06/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
cadabb23-24ff-4015-bd76-b75dd71f6a68	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
															Yes					
56709a02-0796-49e9-87ca-3c8373a086c5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:05:00	TRUE	FALSE			en-gb	14:05:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
672d3cad-6553-43ee-aedf-8183781aa4b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:25:00	TRUE	FALSE			en-gb	14:25:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
			Yes																	
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
			Yes																	
0171128d-011f-4b46-87e9-cb293fd8c1ec	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
1e926b34-339c-4965-bb84-4082179d7f9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:01:00	TRUE	FALSE			en-gb	15:01:00	06/25/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0fa9b0bb-74c8-4eb8-8e89-99d43e6b6518	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
556bf66f-caea-4871-bf47-c682095a0fa8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
566b9ff3-6292-40f7-bc01-27f565c42303	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:43:00	TRUE	FALSE			en-gb	15:43:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
167411fd-e575-44ac-bfa2-36aed6b5f465	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 15:58:00	TRUE	FALSE			en-gb	15:58:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad01398f-ed22-457f-bf6b-d01db213141c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes								Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
74926bb9-a096-4766-b696-9b2546e9adbf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
62e5bc96-b885-41e8-8e68-d8b82b6aef6b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:39:00	TRUE	FALSE			en-gb	16:39:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ac9f2625-8f14-4db8-9dc2-3b4a552a2114	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:41:00	TRUE	FALSE			en-gb	16:41:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c364a7b9-ebbb-4c99-9387-8849ef4d5e68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 16:58:00	TRUE	FALSE			en-gb	16:58:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
30152984-f187-456d-818e-3527a57e28c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 17:41:00	TRUE	FALSE			en-gb	17:41:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
4411bb68-f963-4325-b951-3fbd634bf6a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	06/25/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
97af9359-3f24-4ba9-a4f7-da7f6f3e5965	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c7a37750-cebf-44a2-a17f-aef143d9a106	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
76f8fc03-affd-4240-96ef-feb2b778210c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:05:00	TRUE	FALSE			en-gb	19:05:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2c1ca7ad-c231-4068-8285-4c4fe99940b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:18:00	TRUE	FALSE			en-gb	19:18:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
35f9b662-9abd-43bd-8610-c953fe46514e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:19:00	TRUE	FALSE			en-gb	19:19:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f8fcc6a4-3723-4052-9fcb-906c5c9aca52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
e1cca707-9831-40b9-a4e4-d7bfb0250478	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
		Yes				Yes								Yes					
09145a50-349d-4aed-97b0-07c4417b85ee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
b6b3c521-d698-4769-a9ad-99fc42fa9c8c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	06/25/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
196e7bf9-f683-4202-a11b-2e6a4acf28e1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	06/25/2023		No condoms					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
												Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f4f4923a-d361-42f6-b1bc-8def21196b1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:52:00	TRUE	FALSE			en-gb	19:52:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
084b6b61-c198-490d-9ebe-c52999419043	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 19:54:00	TRUE	FALSE			en-gb	19:54:00	06/25/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes											
a6f13f82-4897-4c9f-a7e0-5c86d40f2d76	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes	Yes						
11b91b9f-9782-4bd3-b39b-a7eedc12a06c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a0e4d8a0-ffb0-4cdb-b58b-b19df3f243d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:48:00	TRUE	FALSE			en-gb	20:48:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fbbd14a3-1161-43c9-8e5a-7c713db5152a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
537882a7-8cce-43cd-a2ac-56a6420a45d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:55:00	TRUE	FALSE			en-gb	20:55:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2d38efd6-2d54-4531-8b5e-c183a4a44f00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ded5daf9-2a5e-43a5-92ba-45acf855ee15	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 21:31:00	TRUE	FALSE			en-gb	21:31:00	06/25/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c831ea3-c379-450f-aab7-efe662d73c5b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 21:53:00	TRUE	FALSE			en-gb	21:53:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8324174-7984-4340-9334-cffa3adcea84	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:06:00	TRUE	FALSE			en-gb	23:06:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
66dd1982-335b-404f-9c28-f56c6d2eee30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:33:00	TRUE	FALSE			en-gb	23:33:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
729b8837-7cc6-41ca-8ae3-5f11581e9166	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:47:00	TRUE	FALSE			en-gb	23:47:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
105438ed-2dfe-440f-8083-ee7089568301	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/25/2023 23:57:00	TRUE	FALSE			en-gb	23:57:00	06/25/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
105438ed-2dfe-440f-8083-ee7089568301	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
555f4561-a2e4-418d-a7fe-69e497803b3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:02:00	TRUE	FALSE			en-gb	00:02:00	06/26/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
555f4561-a2e4-418d-a7fe-69e497803b3b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
b7164684-3ab1-4404-b5cc-36f192532eb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:14:00	TRUE	FALSE			en-gb	00:14:00	06/26/2023		Bad smell
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
b7164684-3ab1-4404-b5cc-36f192532eb5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
c69e8113-91c8-4d55-b438-3a10e958f9de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:44:00	TRUE	FALSE			en-gb	00:44:00	06/26/2023		Zzzffgdddddy
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
531a2eab-95c1-4618-a949-ff6593725916	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 00:52:00	TRUE	FALSE			en-gb	00:52:00	06/26/2023		Ewww stinky	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
8d4cf25b-c1c5-4bf3-a25d-91ae49c84e52	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 01:03:00	TRUE	FALSE			en-gb	01:03:00	06/26/2023		To hot	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
2ed4b2ac-ccfe-4b98-a2c6-cc6b9bac4f4f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
d4d67e12-656e-4309-9a1a-29d97a59c94d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 01:59:00	TRUE	FALSE			en-gb	01:59:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6452617b-9624-40ac-95cc-d4cd65830e0e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 02:25:00	TRUE	FALSE			en-gb	02:25:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6882f94e-6eff-41f9-8e46-8c36d668529f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 02:31:00	TRUE	FALSE			en-gb	02:31:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f6b45179-8e62-46bd-9151-63c149bff7bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 03:03:00	TRUE	FALSE			en-gb	03:03:00	06/26/2023		Smells bad	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
89322c16-cc45-4040-abdb-f45956897256	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 03:04:00	TRUE	FALSE			en-gb	03:04:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1b588a18-5da2-44cf-bcd5-b508c047e18d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 03:26:00	TRUE	FALSE			en-gb	03:26:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
ffbda842-c895-47fb-a307-e0ccf6fe7b01	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 04:11:00	TRUE	FALSE			en-gb	04:11:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d9acca3d-446f-482f-84f1-5385a3855083	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 04:36:00	TRUE	FALSE			en-gb	04:36:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c8bff6cd-f09a-4870-8381-85fd2d642026	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 04:53:00	TRUE	FALSE			en-gb	04:53:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b9bc81cf-f34c-4948-80a3-41bdaf2117fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:15:00	TRUE	FALSE			en-gb	05:15:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
eedb8f4-b415-42c3-8f15-7c0c39c0c5e5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:30:00	TRUE	FALSE			en-gb	05:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9dbf4777-4615-4145-aa42-0ba55bc491f0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:39:00	TRUE	FALSE			en-gb	05:39:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5dbcc9ea-8777-4559-a275-616788a680de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 05:45:00	TRUE	FALSE			en-gb	05:45:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10d82e92-933f-4cab-957c-4a8b7efec5ef	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 06:30:00	TRUE	FALSE			en-gb	06:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ad7b95da-dea0-4554-acf8-54e1d2db519e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 06:30:00	TRUE	FALSE			en-gb	06:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6b599326-bb2d-46f6-a7e1-3aaf9fa5e6c4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dbb92a3d-fc6e-4ce9-810a-4c0902d47e75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 08:24:00	TRUE	FALSE			en-gb	08:24:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fa1922f1-8724-48b9-9efc-60c5dd45edae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1a098948-9fc1-405f-b39d-209d31554964	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8a0e5bd7-6403-4462-9745-17a6497a19aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e0190dae-ff45-434b-8951-210c791dea6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2aa3316a-5727-494a-b1f7-b3d975bf3081	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:39:00	TRUE	FALSE			en-gb	09:39:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
78f0989a-009f-4a36-9825-893a2c1dd959	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6fd8ec1-e8dc-4d21-8088-f5b29afff885	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0291c8bc-41de-4342-98fc-58ac8c2ced2f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9184598d-ff28-41d1-9b24-07e86f219249	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
9a940c38-89ca-4bfd-a27b-cbbcc0eef040	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:35:00	TRUE	FALSE			en-gb	11:35:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
56c9cb40-7b7e-4d1d-8d83-5dbfb57dc5d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:36:00	TRUE	FALSE			en-gb	11:36:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6adf1ca9-9388-4b98-b97f-faff1baf105f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	06/26/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a6d94842-b886-48d9-9e17-eb11c0b27182	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3c70449d-6920-4626-ad9d-50257522fe35	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 12:14:00	TRUE	FALSE			en-gb	12:14:00	06/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
75aea0d4-e95c-4535-b5be-cf3acfa0b3fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c97c14e4-af39-4444-9805-bb869fcb6781	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 12:37:00	TRUE	FALSE			en-gb	12:37:00	06/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d82303a6-f880-40ba-a868-2f87a8b6914e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:08:00	TRUE	FALSE			en-gb	13:08:00	06/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
877ce1bf-71e5-4d7d-9426-5b0327cafd2a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:13:00	TRUE	FALSE			en-gb	13:13:00	06/26/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
42d36c7f-4a54-45fc-b895-16b873d6f8db	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
17d824a2-19ca-425f-bcd4-3ba09e516888	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:55:00	TRUE	FALSE			en-gb	13:55:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
20fede87-2d33-41dc-a0de-3a58d0ef47df	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f4d98452-c903-4b89-a27b-5d9886640052	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:56:00	TRUE	FALSE			en-gb	13:56:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bb8783c7-794f-400e-9260-fa429d6bce5d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c29d708-f60a-4cf7-a120-45ee7cc3cfd0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	06/26/2023		Right
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7026ac1b-0d03-4319-9965-620a31d167e2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 14:54:00	TRUE	FALSE			en-gb	14:54:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f2378868-623d-4a5b-8881-65ea4abfe1bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	06/26/2023		Add a smeller so it can smell good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6b1e6e1-1f09-47cc-853e-327e8424bf86	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 15:15:00	TRUE	FALSE			en-gb	15:15:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f1e9a902-18b9-4717-a595-59267ee4ca73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 15:18:00	TRUE	FALSE			en-gb	15:18:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
787ce17b-3cd2-4af9-8a73-704181b12e33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 15:50:00	TRUE	FALSE			en-gb	15:50:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2950a263-f661-4b9d-a16e-5d6f578b6de6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 16:17:00	TRUE	FALSE			en-gb	16:17:00	06/26/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
60a83bec-dab1-4843-b63c-fdb2ff744d8c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b7d0ca5a-91d4-46af-b969-68b4513a7751	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 17:14:00	TRUE	FALSE			en-gb	17:14:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bf757ab1-3df2-4b54-b480-972eed880f0f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 17:17:00	TRUE	FALSE			en-gb	17:17:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2875c5ec-b22b-4602-ab1f-0db9b123bd38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/26/2023		Rigth
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b1d92ee2-fdea-4dfe-8a0b-8528bf834eb7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 19:09:00	TRUE	FALSE			en-gb	19:09:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d51f56ad-08dd-4b9d-8a5e-614f401c7542	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 20:38:00	TRUE	FALSE			en-gb	20:38:00	06/26/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
30e367e9-a55e-4704-8922-18b862d3a3f1	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
25472375-7260-4dd0-a86a-6682ca06e8ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	06/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
48f1bf0f-545e-4e42-a381-ce931676a659	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/26/2023 22:03:00	TRUE	FALSE			en-gb	22:03:00	06/26/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
73ebde0c-8941-4239-a8cf-4ed93affc5fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 02:00:00	TRUE	FALSE			en-gb	02:00:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
023b010c-0b6f-4794-a4ac-66b4a3f91251	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 04:14:00	TRUE	FALSE			en-gb	04:14:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ce7898fa-8264-4eb3-8506-0187c5f73521	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 05:27:00	TRUE	FALSE			en-gb	05:27:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
										Yes					
ce512221-7218-4701-8caf-68810f17dbf9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ebd96c61-4142-4d4c-9cb1-dfecb356ec43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 06:35:00	TRUE	FALSE			en-gb	06:35:00	06/27/2023		Great cleaning	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
6418cf85-bb14-40c3-a0bc-6cf6036c8528	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
17684b15-6903-4351-b342-9a2fef6596c1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:07:00	TRUE	FALSE			en-gb	07:07:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9f721e84-1cef-4898-904c-c9ddd6501403	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
69aa9754-cb51-4f37-b2e2-97496989efa1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:14:00	TRUE	FALSE			en-gb	07:14:00	06/27/2023		Your bathrom is ****	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
69aa9754-cb51-4f37-b2e2-97496989efa1	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												
26b83ca7-18bf-441c-8520-1ca6c3928408	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:16:00	TRUE	FALSE			en-gb	07:16:00	06/27/2023		Joosh	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7c90140f-1df0-4d22-b8f2-187d25267657	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:20:00	TRUE	FALSE			en-gb	07:20:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes	Yes				Yes						
eeaa71b6-ea9e-41b7-a63b-4c946dd3749a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
31f27bc7-8244-4461-9307-a00f49b37e81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:47:00	TRUE	FALSE			en-gb	07:47:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
59aa4758-63ba-47af-a2b9-757a429590c9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
90a68b47-c6be-4d80-9c6d-5c86b024128a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 08:10:00	TRUE	FALSE			en-gb	08:10:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0da6ceff-0069-4e06-a3fa-257196c43845	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 08:21:00	TRUE	FALSE			en-gb	08:21:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5bf30134-2304-4b54-859a-42a89e1d84d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
201a0ce4-5685-43e1-8dfe-f6735f325a6a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4de86eb3-2dbf-419f-84fe-5991fb64f91c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
876879cd-69fa-4a46-9786-0578bb31d252	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
08acfb94-aebc-4676-9c0a-aeaff56ce00a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5be1a029-a237-4ec8-b2f3-82250172b9de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 10:56:00	TRUE	FALSE			en-gb	10:56:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1cd270fd-4207-43d7-bf18-203fe6943477	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 10:59:00	TRUE	FALSE			en-gb	10:59:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d6260027-167a-497a-8906-c7c9d03b56f1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:03:00	TRUE	FALSE			en-gb	11:03:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d6260027-167a-497a-8906-c7c9d03b56f1		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
							Yes							
c57a7e79-81bd-411a-85f6-d171949d0878	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:05:00	TRUE	FALSE			en-gb	11:05:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ebd4ecfd-c467-41c1-b40a-673c094b2497	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:26:00	TRUE	FALSE			en-gb	11:26:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
860cc21b-080b-4eda-b92f-43a753a31563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
e84024f8-2fe6-4339-b182-b543a2a65fce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
b43ef8ad-4232-45e1-89c2-019385689c89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	06/27/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3d182add-1ff0-4e86-b5ab-4023d75cf14c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ebfe5eb8-0218-4908-9f60-39aaaed455a3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 12:06:00	TRUE	FALSE			en-gb	12:06:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0db1fc07-b602-46c0-97c5-c8b2053ae955	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 12:07:00	TRUE	FALSE			en-gb	12:07:00	06/27/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9e70513-6c5b-4dec-b7a9-053ba8d7ef59	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c019f48c-3f70-4a0a-a8e3-797508e0f8fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 13:44:00	TRUE	FALSE			en-gb	13:44:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
					Yes										

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
4997c7e9-6f70-4881-9b78-f91a57b7c056	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 13:52:00	TRUE	FALSE			en-gb	13:52:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9d4861b4-9105-4acb-a5f0-1b711dd2792c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 14:19:00	TRUE	FALSE			en-gb	14:19:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
760b8aba-b9f4-4723-a291-b803b950d58b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a0c18e34-fabb-468b-811a-c4e1966d7c1c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9e0b107d-5c29-4c41-9e95-8eda8f41e0e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4b08ee15-5b5e-40cc-a8c9-c570287d1adb	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:21:00	TRUE	FALSE			en-gb	15:21:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4b08ee15-5b5e-40cc-a8c9-c570287d1adb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
8be180f0-065c-4a59-b3cd-1f9a34ad6392	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 15:29:00	TRUE	FALSE			en-gb	15:29:00	06/27/2023		Good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
e38de5f6-c349-44c6-a3b1-276ad6fcd9b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 16:09:00	TRUE	FALSE			en-gb	16:09:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d3f797af-4ed8-4ac1-b946-7158ff00a355	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea267d97-f706-470e-bb1a-f1663f9fb509	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 16:26:00	TRUE	FALSE			en-gb	16:26:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18c04493-cf37-4b21-9736-5a87d97a8964	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:25:00	TRUE	FALSE			en-gb	17:25:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e7330eee-1b19-4490-b7b6-e18dbc93ce87	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:33:00	TRUE	FALSE			en-gb	17:33:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c62be447-2d3e-49af-a901-88a2b481b16f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
409e9da9-a8e2-4c5c-8887-868c8c994179	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 17:53:00	TRUE	FALSE			en-gb	17:53:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4630c39f-42ec-4b3f-bde3-b20013ce2a61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
896c8542-8a4d-4505-ab9c-86f28ba68769	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:19:00	TRUE	FALSE			en-gb	18:19:00	06/27/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
8be9a107-c946-4773-8e74-2e39e2980c1c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
90bef88e-d10e-40df-b3ca-5a2600788f91	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:34:00	TRUE	FALSE			en-gb	18:34:00	06/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
c69eb743-fb36-4706-adb4-91e3ed89e90c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	06/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
f7739688-fe14-4372-bdcd-a32164bf50a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:48:00	TRUE	FALSE			en-gb	18:48:00	06/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													
20f3cf51-2fea-43bf-ad4b-d9a83d87a9d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 18:55:00	TRUE	FALSE			en-gb	18:55:00	06/27/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
			Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c083cf2a-3b6a-47ec-9694-4912b86a3779	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
01ac544c-a506-49c1-8630-210781392e77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:40:00	TRUE	FALSE			en-gb	19:40:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4061e994-9048-451e-8c01-af97705fe99d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:41:00	TRUE	FALSE			en-gb	19:41:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8496cc3c-91c5-4d2c-8559-973ba47ee847	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	06/27/2023		Very good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
490d6a32-fd1d-4767-9aff-38749abb3529	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/27/2023		c	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes			Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
49bec07e-2497-4bd0-924c-63e57dc21155	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:18:00	TRUE	FALSE			en-gb	20:18:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
0346251b-5949-446d-bba7-7ccc023eb4e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:28:00	TRUE	FALSE			en-gb	20:28:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ec5e64e4-e03b-460f-a50a-7a75deb68e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
dc81ac01-8fd0-4c0b-9ef2-f48c5d9f7db6	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:41:00	TRUE	FALSE			en-gb	20:41:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
	Yes	Yes					Yes								
65c930f4-c11c-4a32-8060-9fb730a67dec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:42:00	TRUE	FALSE			en-gb	20:42:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
45e65193-e652-45d4-98e6-15b288b3e400	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:43:00	TRUE	FALSE			en-gb	20:43:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a9452cf4-cc12-452a-829a-e928f0360ea3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	06/27/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
86a95a3e-5e56-4367-88c5-a85f2a4d28be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 20:54:00	TRUE	FALSE			en-gb	20:54:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
54d2b50a-d95c-4c70-8657-36c9d8c3850c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
8a55dbee-3cb0-4cfc-b4dd-1305edd67120	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:48:00	TRUE	FALSE			en-gb	21:48:00	06/27/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f0ad5f6f-b042-42ce-a711-1788159ae72a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:49:00	TRUE	FALSE			en-gb	21:49:00	06/27/2023		Dfffffffffffffggggxxgmkcdd	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
17cba600-e88d-44be-835b-70055252c62f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 21:55:00	TRUE	FALSE			en-gb	21:55:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes				Yes							
ef01a571-dda8-43fb-b838-e0fcd84fddad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 22:06:00	TRUE	FALSE			en-gb	22:06:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2e3de1c8-f8b5-41f9-880e-2cd3aaed0885	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 22:11:00	TRUE	FALSE			en-gb	22:11:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4f5412fa-f474-453b-91a6-c65f4a47a73c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 22:21:00	TRUE	FALSE			en-gb	22:21:00	06/27/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
0c2b798c-88fd-4e02-8b6a-735563ae48e8	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/27/2023 23:32:00	TRUE	FALSE			en-gb	23:32:00	06/27/2023		Saw a bug,	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2c8483dd-7e69-4189-9ede-d568c6c39d7a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:17:00	TRUE	FALSE			en-gb	00:17:00	06/28/2023		Fix some of the door of the bathroom doors!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
0d14ac56-ddba-4bc4-9f9a-df77577101e9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:20:00	TRUE	FALSE			en-gb	00:20:00	06/28/2023		Fix the doors	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b344eae8-88e3-4c65-88b3-400f2b709433	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:22:00	TRUE	FALSE			en-gb	00:22:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
09d6ec2c-c792-45fc-a763-064f53348fb4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 00:24:00	TRUE	FALSE			en-gb	00:24:00	06/28/2023		Clean yo bathroom please bc it smells badddd!!!!!!	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
Yes									Yes						
b6d43c54-46e9-4269-9d4b-990c13e6084e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 05:35:00	TRUE	FALSE			en-gb	05:35:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
ab48bed6-d31d-4ad7-bb85-810ac493549a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:10:00	TRUE	FALSE			en-gb	07:10:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
381cfb5c-54eb-4552-817c-18c5bf47d6d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
b92d1f9c-37c3-4898-b905-edc5602c0c60	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	06/28/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e804859d-4037-4956-a887-fcbce8fbfbfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:12:00	TRUE	FALSE			en-gb	07:12:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
740fe70f-8ed2-4172-b884-ce2c773d4f96	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
077aebf2-578e-446e-b766-fd86e59db728	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:43:00	TRUE	FALSE			en-gb	07:43:00	06/28/2023		Nooooooooo
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8dfbb413-cefa-4d6c-aba2-d0914d7b82d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/28/2023		Make it beterc
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes		Yes	Yes			Yes	Yes							
0aa1c9fc-3d4a-49e1-8e92-40ba4316a05c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/28/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
0aa1c9fc-3d4a-49e1-8e92-40ba4316a05c	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
53c24bdb-b714-4516-a613-43e928015ce1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/28/2023		Uuuuuuu,
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes		Yes	Yes		Yes						
b6ad0c7f-be3f-4045-8957-d027a02b6623	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/28/2023		??????
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
e78b804e-e03f-40ea-81c1-8184ae13e437	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:54:00	TRUE	FALSE			en-gb	07:54:00	06/28/2023		Noice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
5bf5223a-f6bf-42c0-87e1-96f3f45d96b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 07:55:00	TRUE	FALSE			en-gb	07:55:00	06/28/2023		Noice
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
527b7b4b-fee3-42e2-a122-34efd971aa92	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f862e66-fa00-4704-aa2d-a9e58d654548	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:16:00	TRUE	FALSE			en-gb	10:16:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cb229029-413a-4209-90a6-c3d85aef2bf0	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:24:00	TRUE	FALSE			en-gb	10:24:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
8687c8a9-9fc0-4e07-b61a-410172b0cadc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:26:00	TRUE	FALSE			en-gb	10:26:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
cf906e0f-67d9-41d8-b4aa-529e73cff3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	06/28/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
838a97df-2a9a-40be-8871-1ec269ca35b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:38:00	TRUE	FALSE			en-gb	10:38:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
36b75b1f-ceb1-469b-b56c-94c2261c4c8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2f6b6484-789a-4970-ab4b-a359e1e259f2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 11:12:00	TRUE	FALSE			en-gb	11:12:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6812c7d6-530c-431d-ae6e-32d580b64110	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes						Yes					
108eb072-0c91-4ea1-a16f-46ecdcc9aede	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 12:23:00	TRUE	FALSE			en-gb	12:23:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment		
1b86c092-7d8a-4d5e-91aa-5811c8204979	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
6d19cd3a-b8ad-49e1-9569-24d953cf31be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 13:19:00	TRUE	FALSE			en-gb	13:19:00	06/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
cad76381-a766-4f9c-8c2c-d39eb3e9c1f3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 13:47:00	TRUE	FALSE			en-gb	13:47:00	06/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
3d8dabcb-0ae6-4263-9555-b9e2fb5e76d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														
7f60f619-8a19-41fa-85f6-eb802a846c55	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:07:00	TRUE	FALSE			en-gb	15:07:00	06/28/2023				
		How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>												
		Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
4c697a91-2d92-4ee7-aec8-13bce07aa467	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:13:00	TRUE	FALSE			en-gb	15:13:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32f74859-b0ea-4caf-8c5d-e3d77a768de4	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:16:00	TRUE	FALSE			en-gb	15:16:00	06/28/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes	Yes	Yes			Yes	Yes							
b1bfa3c-4569-4fbb-9c08-91d37231b592	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:36:00	TRUE	FALSE			en-gb	15:36:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
da364df9-8240-42e1-b65a-bbec1ea8a6d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 15:38:00	TRUE	FALSE			en-gb	15:38:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6ff15319-a24c-4403-9e3a-0d5ff3e77377	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 17:12:00	TRUE	FALSE			en-gb	17:12:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment					
b1910e2c-6583-4cf7-a37a-1afb23ddfb4e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 17:24:00	TRUE	FALSE			en-gb	17:24:00	06/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
			Yes																
d33f5c70-1bf7-49a1-bccd-627e6961dbb2	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 18:20:00	TRUE	FALSE			en-gb	18:20:00	06/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
					Yes														
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes								Yes					
f80d2e3e-9de5-4c2c-b016-7f39dbd11d31	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 18:24:00	TRUE	FALSE			en-gb	18:24:00	06/28/2023							
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
	Yes																		
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																		
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
						Yes													
e64ae82f-8f87-4121-81e0-951a86c3c0f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	06/28/2023		Happy					
	How would you rate this restroom today?																		
	<b>Average</b>		<b>Good</b>		<b>Poor</b>														
		Yes																	

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8c2f4573-b125-4fd3-af59-51c1014ec8bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:12:00	TRUE	FALSE			en-gb	19:12:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d21706b0-8768-4a29-b1d5-d4d1772ce494	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b7a5eb58-c426-41c9-9e08-9eefd41a6d95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:21:00	TRUE	FALSE			en-gb	19:21:00	06/28/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes		Yes					Yes		Yes					
adfb78b-d4f1-4f9a-8c4b-a6f0354a6b2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:22:00	TRUE	FALSE			en-gb	19:22:00	06/28/2023		Floor was mad wet ngl gang	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
967d9387-2592-4bd7-942d-9a331baf054e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	06/28/2023		No	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
967d9387-2592-4bd7-942d-9a331baf054e	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes					
1be34f12-0453-4c61-97f4-0b8c4c0760dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 19:39:00	TRUE	FALSE			en-gb	19:39:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d35ddc38-6ca5-4c04-a646-4a5a8aafbef2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
80274978-d033-45f8-b345-4dd91b1cae7e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
6553a10c-9154-43f8-b713-ea79c4839b70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/28/2023 21:00:00	TRUE	FALSE			en-gb	21:00:00	06/28/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1b3fcf87-dde0-4676-ab85-4c0d0133f287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 00:37:00	TRUE	FALSE			en-gb	00:37:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5b01e650-b02b-4b70-9259-62c300aeadc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 00:45:00	TRUE	FALSE			en-gb	00:45:00	06/29/2023		Great
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f523ca13-c48d-482d-8cf0-7edf382842d7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 02:39:00	TRUE	FALSE			en-gb	02:39:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7f83c77-0427-498b-ba2f-7bdf18cddf89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 02:51:00	TRUE	FALSE			en-gb	02:51:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
24cf0a39-80c6-479e-a60c-b2a3a4deb56d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 06:14:00	TRUE	FALSE			en-gb	06:14:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
749a8b65-1389-4f11-bc0e-c4b7fbd637be	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 06:39:00	TRUE	FALSE			en-gb	06:39:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a8090ec1-bb95-4c6c-a46f-ccfb81e32bce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 07:09:00	TRUE	FALSE			en-gb	07:09:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
cce3b48e-b5da-48c6-b942-09c61429748a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 07:23:00	TRUE	FALSE			en-gb	07:23:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9c145231-d616-4602-a4fb-3d2c99bf00da	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:01:00	TRUE	FALSE			en-gb	09:01:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d3ea59bb-8abd-412e-831c-78fda16f831d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:36:00	TRUE	FALSE			en-gb	09:36:00	06/29/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fa624fe9-2916-4ff5-8d9a-ffb03706c993	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
24b45558-adb3-45eb-b8e4-7fe2cef47907	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 09:52:00	TRUE	FALSE			en-gb	09:52:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
13e40779-bd4e-442c-ab20-c50f0b074316	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 10:35:00	TRUE	FALSE			en-gb	10:35:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
3ee083b6-ae47-4209-8c38-ae7e8c24403b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	06/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
24daa651-c082-44d7-a080-f254a183f604	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:13:00	TRUE	FALSE			en-gb	11:13:00	06/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
8b001d7e-710b-46a3-bc42-7a5ce6b711f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:22:00	TRUE	FALSE			en-gb	11:22:00	06/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
																	Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																												
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>																			
							Yes																					
7a1e640d-b88d-4edf-ae1d-8b2ceda5e0ab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
bb7a7f18-68fe-42ab-9ac2-6a0caa10a790	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	06/29/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
af71ea25-b227-4b86-906a-2b6ba52adb84	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:53:00	TRUE	FALSE			en-gb	11:53:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
693b7efb-c493-4091-be70-1c5d4ee64c5e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 11:58:00	TRUE	FALSE			en-gb	11:58:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes	Yes	Yes							Yes						
a583f2d1-919d-45b3-b2e1-52bc628a5022	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:15:00	TRUE	FALSE			en-gb	12:15:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
86366ed4-be27-49a9-a2f2-ef34b01e9f73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:34:00	TRUE	FALSE			en-gb	12:34:00	06/29/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
19ceb96-d3f0-4183-aef6-53c647ce2fa1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:41:00	TRUE	FALSE			en-gb	12:41:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
00e83b2a-fae7-4abe-839b-dd63a99d3592	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:48:00	TRUE	FALSE			en-gb	12:48:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
fce61bf7-9e41-4c11-ae8d-e1a683a789b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:49:00	TRUE	FALSE			en-gb	12:49:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f0b183a4-b0a0-4d67-b47b-f3ac5bb8cf50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 12:52:00	TRUE	FALSE			en-gb	12:52:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ad002b32-510c-4b8e-b2ed-29ba18ed09bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:10:00	TRUE	FALSE			en-gb	13:10:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e3b3282f-4977-405c-896f-41e99e79e8b0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
eb5f4e64-fbda-437e-9582-6fa4ca510e75	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
efdbb80b-914a-49fa-94a1-ae770da2f753	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f85ed86a-6704-43a4-a478-9be8351ad36e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:23:00	TRUE	FALSE			en-gb	13:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9834248e-adbd-47f2-bcf6-274798adea27	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:24:00	TRUE	FALSE			en-gb	13:24:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7ab53fac-fcce-47d6-9c53-8198a0fc82a2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:25:00	TRUE	FALSE			en-gb	13:25:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ee4d7456-b0b1-4bb9-bb01-db602c5d4c50	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3b0edc15-22f2-4f04-a671-849c50081268	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 13:50:00	TRUE	FALSE			en-gb	13:50:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e1879c07-ed57-4b63-90a8-49a93a8ec9fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:00:00	TRUE	FALSE			en-gb	14:00:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ca6bf63e-afc7-44dc-970f-76c82fdda429	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:23:00	TRUE	FALSE			en-gb	14:23:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
59ffd323-c7ec-4cec-a8e3-9ca900fc0a9c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:30:00	TRUE	FALSE			en-gb	14:30:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d34c87a2-8670-4f53-8fa7-69219048025e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:42:00	TRUE	FALSE			en-gb	14:42:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
01059f1e-9f6e-4664-8f69-861e56efb4eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 14:44:00	TRUE	FALSE			en-gb	14:44:00	06/29/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
01059f1e-9f6e-4664-8f69-861e56efb4eb	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
24fb494e-2512-444c-bb78-6f0a9dcf4eaa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 15:00:00	TRUE	FALSE			en-gb	15:00:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3989e00b-5c65-4b47-8adc-732ae65a8e09	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
93c3dba7-5677-417b-be3e-d82a78767b07	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 15:50:00	TRUE	FALSE			en-gb	15:50:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1417764c-b5ac-43d4-bdc9-251731dd7d79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 16:22:00	TRUE	FALSE			en-gb	16:22:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e1a2f207-8d13-4fed-9c14-b0c9b413453f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 16:38:00	TRUE	FALSE			en-gb	16:38:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
365190b6-68f8-4030-a67d-f5644b49dd83	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
c9cf0822-da6f-40e8-b2e0-ae0ce411e9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:19:00	TRUE	FALSE			en-gb	17:19:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
70a6be71-d673-4f39-a1f3-edb2b0e2a19b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5a588b3e-b514-43dd-a951-f962715c042c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:43:00	TRUE	FALSE			en-gb	17:43:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d266afbc-ed49-484a-b3c6-abc74861f273	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	06/29/2023		Need more toilets	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
fec92a87-f726-4d63-8e5d-8e15facdc78b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 17:51:00	TRUE	FALSE			en-gb	17:51:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
a143ea4a-75ba-4593-93ba-7f97c71e5253	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
3edf4133-ad09-439f-82d3-b5a21580ec80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9e951ba2-e924-4e5b-b456-6ee4a918011b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 20:44:00	TRUE	FALSE			en-gb	20:44:00	06/29/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9e951ba2-e924-4e5b-b456-6ee4a918011b	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes		Yes					Yes					
b2336d66-fac4-4fbb-b40a-88d868dfd048	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/29/2023 20:53:00	TRUE	FALSE			en-gb	20:53:00	06/29/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a152491b-c00e-4560-b5b6-1b959071e1a3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 00:19:00	TRUE	FALSE			en-gb	00:19:00	06/30/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e6515fa5-e406-4b70-b401-dec6dd32e8a4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 01:13:00	TRUE	FALSE			en-gb	01:13:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd942cf9-a97b-469b-a90f-fd10e448bfc4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 06:37:00	TRUE	FALSE			en-gb	06:37:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d9cf547-f189-4b78-b8f1-f715ddff9bfe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 06:53:00	TRUE	FALSE			en-gb	06:53:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
606cb1de-87af-417e-a616-13a507d1c65a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:21:00	TRUE	FALSE			en-gb	07:21:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
14db2b2f-58ad-4f80-901e-9958f9ce6ffc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
97fa6f3e-4f5b-4af7-96c8-a4302b26dc49	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:32:00	TRUE	FALSE			en-gb	07:32:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
867f5a9b-b865-4472-a0b1-308ceca64978	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:44:00	TRUE	FALSE			en-gb	07:44:00	06/30/2023		Not enough stalls	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
						Yes									
e76da3d1-49e7-4dc3-a239-409dbc03662e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:45:00	TRUE	FALSE			en-gb	07:45:00	06/30/2023		Super todo	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a6aed582-e7dd-4947-a0b4-5829cbbd384c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	06/30/2023		Limpio	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6bc6b2ea-1132-41c5-a5df-d10b547e9589	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fd049fed-69d4-4fdb-9ce2-f7da3c70710f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 08:48:00	TRUE	FALSE			en-gb	08:48:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
Yes															
11772f8a-c8fa-474c-a4ed-e8b6f6da21e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:16:00	TRUE	FALSE			en-gb	09:16:00	06/30/2023		Middle sink doesnt work, right sink doesnt drain	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
					Yes	Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
dfb07224-4f5c-436a-9a67-078cf7b3726d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:22:00	TRUE	FALSE			en-gb	09:22:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8c62a805-9039-47fc-aa99-6352625f3a71	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dda982f2-f519-41d5-a769-64b454813307	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 09:51:00	TRUE	FALSE			en-gb	09:51:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a28c08b2-cd98-4600-b627-92abb0bda12c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 10:11:00	TRUE	FALSE			en-gb	10:11:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1f8f67b2-4927-4597-8b9a-b71e7fe20ca3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
251dd269-334d-477d-bae4-65de4beabe7f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:33:00	TRUE	FALSE			en-gb	11:33:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
59e14cba-d80d-4754-814d-1d7d49016119	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:39:00	TRUE	FALSE			en-gb	11:39:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
515ce972-8bd7-47d0-ae75-c3f1db2fa4e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:45:00	TRUE	FALSE			en-gb	11:45:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
284150b3-45fa-4c03-ad29-e6a7608ff759	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 11:46:00	TRUE	FALSE			en-gb	11:46:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
fff5e550-5915-4f5d-a3ce-8ea6d1815fa9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:00:00	TRUE	FALSE			en-gb	12:00:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
afa17feb-06b2-45ff-9d7f-95cdb2b16652	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:13:00	TRUE	FALSE			en-gb	12:13:00	06/30/2023		Sucioooooompesimo	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bda36e7a-fd87-45de-baf0-167be484f50b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
74d2b745-64d8-4559-8112-d6df1bc022aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19bf4a78-d06f-4344-8a84-38d2f07f7493	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	06/30/2023		Luv
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0800b775-20ff-4746-bd01-a213f26f87f7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b78ed129-a422-4218-bb10-6accbef133e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:05:00	TRUE	FALSE			en-gb	13:05:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cb2dff68-e4ae-4ea4-a1ee-2df981328c8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
52c0aa53-f055-47d0-92ac-71695e4a03a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
2980dfef-8523-45be-9a91-bc4d2d236b79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ba43741d-2e6c-4c88-bd0d-135d0076f2d0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:32:00	TRUE	FALSE			en-gb	13:32:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
85d4d6d9-49f9-48da-8233-ef9e2687d505	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:33:00	TRUE	FALSE			en-gb	13:33:00	06/30/2023		.biem
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d05be8cc-a8d0-4871-9abb-102df6d7faac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:40:00	TRUE	FALSE			en-gb	13:40:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f380a8bf-25a1-4b66-a30e-6f3efdd38379	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:54:00	TRUE	FALSE			en-gb	13:54:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6d080ba0-15f2-4ab2-8aa7-e43bd0eaf465	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cb74ae85-1e7e-4857-b2f9-29d0c9964d30	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:01:00	TRUE	FALSE			en-gb	14:01:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c208ddfc-d427-48e2-a449-4ce8bd10a732	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:22:00	TRUE	FALSE			en-gb	14:22:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06f66cac-647a-4433-9d59-e761dc82857e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes				Yes	Yes	Yes					
b1e000e0-2d72-4650-9dd6-5dffec0ccb5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:39:00	TRUE	FALSE			en-gb	14:39:00	06/30/2023		Just do a little bit more cleaning
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b1e000e0-2d72-4650-9dd6-5dffec0ccb5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes				
501f21f5-c1e8-412e-91c5-789434e9e161	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 14:40:00	TRUE	FALSE			en-gb	14:40:00	06/30/2023		Clean it !!!!!!!
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					
5bae4a66-dc2d-4f17-9496-0244153e7b0b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 15:02:00	TRUE	FALSE			en-gb	15:02:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					
62c46cd3-5316-4343-bddf-cf4557e734f6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					
54150061-2d7a-4191-a9da-1fb4dd33d6a5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	06/30/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
54150061-2d7a-4191-a9da-1fb4dd33d6a5	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
											Yes			
651a2240-b883-4d81-9058-41d508271511	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
267615a2-d3bd-4318-8e9f-383bb89b103f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 16:44:00	TRUE	FALSE			en-gb	16:44:00	06/30/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ace9909d-bec6-41d7-ba67-cf301b6ff5bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:01:00	TRUE	FALSE			en-gb	17:01:00	06/30/2023		Nop
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
5d62b0e9-4410-420d-973c-bfab5a0461b2	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
											Yes			
5d62b0e9-4410-420d-973c-bfab5a0461b2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d4c08f33-826c-4473-b5fb-0d03dd5b42eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:29:00	TRUE	FALSE			en-gb	17:29:00	06/30/2023		Dood	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
42ababe4-fc59-4e4b-acc6-aae43274e150	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:39:00	TRUE	FALSE			en-gb	17:39:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a1b631f0-ec16-49ca-8f30-a7557d5827ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 17:58:00	TRUE	FALSE			en-gb	17:58:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
446ab724-8ed7-48ca-8c14-7fe52be1353b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 18:04:00	TRUE	FALSE			en-gb	18:04:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
24ae844e-a267-4350-8c06-0c6db5fa65b8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 18:40:00	TRUE	FALSE			en-gb	18:40:00	06/30/2023		This bath are discuting	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes						Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f0dd24c7-b7e7-4511-9faa-54ffa294e83a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ca7f1643-27d8-42eb-a1b5-482022170c5a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 19:59:00	TRUE	FALSE			en-gb	19:59:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
35421326-793e-4172-b421-5eab68fb31ed	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
005c6d3d-3581-469a-9516-2abad9b9fc30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
			Yes												
86c5091c-c317-49e1-8e78-69c2c3c7af13	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:29:00	TRUE	FALSE			en-gb	20:29:00	06/30/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
86c5091c-c317-49e1-8e78-69c2c3c7af13	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes		Yes					Yes	Yes					
a5002c5a-f78a-47e8-b492-2f04ac9d21d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	06/30/2023		Ffrf	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
9ba8d048-b99e-4307-bf7f-f203e38ac45c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 20:58:00	TRUE	FALSE			en-gb	20:58:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
97d8bd0e-2c2d-4dbe-a051-dd0c0c9eaccf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 21:01:00	TRUE	FALSE			en-gb	21:01:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					
9fd718f3-a6db-4cb7-9c92-fa9f83000983	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 21:27:00	TRUE	FALSE			en-gb	21:27:00	06/30/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9fd718f3-a6db-4cb7-9c92-fa9f83000983	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes												
28d7479c-05b2-4177-89ae-fafa682469e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	06/30/2023 22:40:00	TRUE	FALSE			en-gb	22:40:00	06/30/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ffdc0983-bc52-4f07-a50d-ba5fae3f9275	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 04:28:00	TRUE	FALSE			en-gb	04:28:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
19319cb9-ea88-42fe-8e42-19389e47b9b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 05:04:00	TRUE	FALSE			en-gb	05:04:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0f6d01df-44c3-4b28-b729-baca7fb3d267	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
9d6af817-e005-44fd-bb7c-ce11487fab7d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 06:26:00	TRUE	FALSE			en-gb	06:26:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f5723b91-5909-48e3-b11b-e43e8b523bf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:29:00	TRUE	FALSE			en-gb	07:29:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
23052e36-c5a2-492f-ad4c-4c37d9105ebc	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ccf4fdea-eb48-4188-acf2-fd98fcd19e1e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:31:00	TRUE	FALSE			en-gb	07:31:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfc75959-b5b1-4917-8b7a-373626a9a75d	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 07:37:00	TRUE	FALSE			en-gb	07:37:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d44af0ed-62d8-4c31-823c-e2e775da412e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 08:39:00	TRUE	FALSE			en-gb	08:39:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f12e4ef4-3063-4a42-b846-cfceb400ed79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 08:40:00	TRUE	FALSE			en-gb	08:40:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
57f51121-4b52-4403-a25c-5c1d527009a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b0183776-50dc-43ae-afb6-495445ab7758	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 09:05:00	TRUE	FALSE			en-gb	09:05:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b6ba9fbc-8d83-41ea-928a-993c07001255	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 09:19:00	TRUE	FALSE			en-gb	09:19:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
97c323c4-388d-473d-9982-d9339e82fa80	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:01:00	TRUE	FALSE			en-gb	10:01:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ba9100cd-97ac-4323-baf8-e6dec471fdcd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:08:00	TRUE	FALSE			en-gb	10:08:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0648dca8-5a05-46c8-afbb-c75cc3382813	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:12:00	TRUE	FALSE			en-gb	10:12:00	07/01/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f02e9091-b465-40d5-88c4-93b4145cae1a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:29:00	TRUE	FALSE			en-gb	10:29:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0cce6509-512f-4288-af29-80c49ac27cc2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:36:00	TRUE	FALSE			en-gb	10:36:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
9d1d5efb-202f-4b86-89d7-15e22fff912d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:39:00	TRUE	FALSE			en-gb	10:39:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
03187037-d9d9-4db7-88cc-19f511b1116f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 10:43:00	TRUE	FALSE			en-gb	10:43:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
073a4109-4797-41a2-b31d-0a6772c7a205	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 18:59:00	TRUE	FALSE			en-gb	18:59:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
321ebae2-2591-4f31-968b-fe71cc9f2e8b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:11:00	TRUE	FALSE			en-gb	19:11:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a2e1235f-1412-492d-8607-12b25c8a4dc6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	07/01/2023		Mui bon
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
6dad0458-bc55-44e2-bb09-d28e1cd64006	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:14:00	TRUE	FALSE			en-gb	19:14:00	07/01/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c9e56b80-a1fd-4e84-886c-1246d5f42f8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:27:00	TRUE	FALSE			en-gb	19:27:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f557b777-0685-4675-a7f2-0ef3599de3ce	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:37:00	TRUE	FALSE			en-gb	19:37:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
ff91983a-77f7-4b74-ad8c-271bd7560fb2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	07/01/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
a59c40c6-3c6b-4c74-9f35-95dcb6b29e5f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 19:58:00	TRUE	FALSE			en-gb	19:58:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
4677af4c-2542-4dd1-8cbf-a215f9c22c67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:16:00	TRUE	FALSE			en-gb	20:16:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
				Yes			Yes								
e8cb64cd-f65a-4805-8529-ab6746f39000	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:19:00	TRUE	FALSE			en-gb	20:19:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ec8cc408-85f8-4e21-8728-0047fb3cf356	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ba72299-0a4d-48fc-b53a-7a7a1a5a83bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 20:36:00	TRUE	FALSE			en-gb	20:36:00	07/01/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f398353a-9692-4486-8627-30a8c6ed9ac5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 21:28:00	TRUE	FALSE			en-gb	21:28:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
1c2aba90-b18c-4ac0-a539-37c579c9deff	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 21:56:00	TRUE	FALSE			en-gb	21:56:00	07/01/2023		Ggfff	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
2f118415-3383-4a64-b63a-b865965de20c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:09:00	TRUE	FALSE			en-gb	22:09:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes													
b83ec000-9d0f-4e7a-9564-816d6366be51	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:18:00	TRUE	FALSE			en-gb	22:18:00	07/01/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
f8ca5726-a0b7-41cd-ad2e-ca3447ff5d2b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:34:00	TRUE	FALSE			en-gb	22:34:00	07/01/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
9c4a756f-ce52-49be-bb9e-84f62f1b5b69	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 22:37:00	TRUE	FALSE			en-gb	22:37:00	07/01/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
75065b5a-5522-43d9-809a-d5bf122f1d3a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/01/2023 23:51:00	TRUE	FALSE			en-gb	23:51:00	07/01/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
e401cdb3-a919-4e72-a626-535167a26e03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 00:37:00	TRUE	FALSE			en-gb	00:37:00	07/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													
6e62f088-fc91-40de-b34e-d46233fc1b42	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 00:45:00	TRUE	FALSE			en-gb	00:45:00	07/02/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
															Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
18a57ac8-bba0-4e8c-98c5-a57701912d40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 00:46:00	TRUE	FALSE			en-gb	00:46:00	07/02/2023		Melvik  eerqaszxcvdergtgfff ffffff hsutsygs
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
7188404e-de05-46c0-85a6-967caf7d39ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 01:38:00	TRUE	FALSE			en-gb	01:38:00	07/02/2023		Mer
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
b9568e05-7b22-48a8-8116-99038f616af0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 02:27:00	TRUE	FALSE			en-gb	02:27:00	07/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
0e1c49fc-0f73-4cda-b135-25704ad5dc3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 04:15:00	TRUE	FALSE			en-gb	04:15:00	07/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
276bfc20-72fc-4b8a-ac1b-9ca4fd9546d3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 04:16:00	TRUE	FALSE			en-gb	04:16:00	07/02/2023		
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
937159c5-16b9-4de9-a969-49fd44d7a804	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 05:04:00	TRUE	FALSE			en-gb	05:04:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
aafc4480-af15-476b-a9d6-d031c68394ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	07/02/2023		No	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0042e74e-20da-40ed-9fe6-b0600b6d9852	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
74e6818e-0614-4a31-9003-80fcf0393e95	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 06:06:00	TRUE	FALSE			en-gb	06:06:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
74e6818e-0614-4a31-9003-80fcf0393e95		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)												
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes			
0aee1353-e652-4d0b-ad5a-f98a0392a6b3	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 06:08:00	TRUE	FALSE				en-gb	06:08:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
ed8be166-27f6-4049-8b76-489228e92e8e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:11:00	TRUE	FALSE				en-gb	07:11:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
9a1a9450-eb64-4d05-ae25-de4b4e7cef19	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:12:00	TRUE	FALSE				en-gb	07:12:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
cb1d523e-06f3-4fbc-af8c-4dcd656eb27	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:13:00	TRUE	FALSE				en-gb	07:13:00	07/02/2023	Estaba sucio
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
				Yes										
90402065-9445-4472-8527-f0ba21e651c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:27:00	TRUE	FALSE				en-gb	07:27:00	07/02/2023	
		How would you rate this restroom today?												
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
9455456d-baba-4915-96c1-e1e1d73e7f79	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e364a33a-e8ec-47d1-bc5c-c75f7b800f4c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a16d2694-aeb2-4a54-934d-dff046137160	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:06:00	TRUE	FALSE			en-gb	08:06:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1048a9b7-45c2-4c7a-8d13-74891edc561a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:08:00	TRUE	FALSE			en-gb	08:08:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c84dcfdb-0020-4e77-83cf-46a0e115d0b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
6da880bf-c31a-4016-9bec-9ee1b505b602	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 08:51:00	TRUE	FALSE			en-gb	08:51:00	07/02/2023		G
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
44054877-1bac-4ef8-b4b2-61d5e18e2003	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 09:08:00	TRUE	FALSE			en-gb	09:08:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
2ae074d8-15cc-4cda-9a5e-2c94f6cc3aef	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 09:56:00	TRUE	FALSE			en-gb	09:56:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes		Yes						
648512f5-d1b5-40c1-82c2-745e7835339e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 10:51:00	TRUE	FALSE			en-gb	10:51:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
55ce1aea-a329-4864-8ab6-9fb177562a0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:04:00	TRUE	FALSE			en-gb	11:04:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b0b2c0b0-a5f1-4b6c-a165-d02e9dee5d00	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:06:00	TRUE	FALSE			en-gb	11:06:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
a4609246-a7be-4e77-8b81-1d566176d32e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:09:00	TRUE	FALSE			en-gb	11:09:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
53946a57-17c7-4574-84d8-d828e1052198	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:19:00	TRUE	FALSE			en-gb	11:19:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7c012dc7-f5a5-415d-8099-3fcd45d3daf1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
29a50562-7602-42b1-80ac-07593ec595af	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 12:38:00	TRUE	FALSE			en-gb	12:38:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
df9e94cf-5ba1-4e2d-aead-e3c9beb04757	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 13:09:00	TRUE	FALSE			en-gb	13:09:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f175a5c9-4ea2-491a-93c3-5c4e1135103e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 13:26:00	TRUE	FALSE			en-gb	13:26:00	07/02/2023		Pestoso y sucio parece no?trabaja nadie aqui	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
34188baf-517d-483c-bf7c-87726c05fab4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 13:59:00	TRUE	FALSE			en-gb	13:59:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ffb1b550-096b-4801-80d9-72d792a67d1e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 14:18:00	TRUE	FALSE			en-gb	14:18:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
03670f7b-3668-4c7a-aaeb-9a067c1d67ce	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 14:32:00	TRUE	FALSE			en-gb	14:32:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes						Yes					
6d2c51fe-9765-46ef-9188-8c43b4d786c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 14:50:00	TRUE	FALSE			en-gb	14:50:00	07/02/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
3002a3b1-3837-417b-a7ff-3992f94a1930	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 15:14:00	TRUE	FALSE			en-gb	15:14:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfd3be28-6091-4d0f-9ea7-482403d87078	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:05:00	TRUE	FALSE			en-gb	16:05:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c1299ab8-53c7-4560-a57d-ce31b8015d72	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:10:00	TRUE	FALSE			en-gb	16:10:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
84c48785-2fa0-48ed-b761-adc066c92e54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:24:00	TRUE	FALSE			en-gb	16:24:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2d190571-17e3-4576-9cbd-871e6baabb17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:28:00	TRUE	FALSE			en-gb	16:28:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cc61dc4e-61d8-424c-9cf5-e4c70bc28bec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 16:54:00	TRUE	FALSE			en-gb	16:54:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f827493d-0ed6-4764-9e6d-af9df3147bba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:09:00	TRUE	FALSE			en-gb	17:09:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e6067fce-ecff-4791-8660-3eca08c7d93f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b9b8ebd3-e927-41ec-9c26-1b7239a25c7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:30:00	TRUE	FALSE			en-gb	17:30:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9684ca89-fb54-45f4-9e4a-7cbae249af18	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:31:00	TRUE	FALSE			en-gb	17:31:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
654677de-fda9-410c-b1ae-81d34b20e9e3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:47:00	TRUE	FALSE			en-gb	17:47:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9d065d6-8271-4bd1-9567-f4cda808cba5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b3ff9138-6c68-4392-969a-8c41fa194be3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 18:18:00	TRUE	FALSE			en-gb	18:18:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
01521881-44c6-4469-ac8c-25147d7eca90	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 18:42:00	TRUE	FALSE			en-gb	18:42:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
86456821-534f-4d26-af6f-c004416d41f7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 18:52:00	TRUE	FALSE			en-gb	18:52:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
6d4d170d-3edd-4cba-8402-27a1631bc996	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 19:06:00	TRUE	FALSE			en-gb	19:06:00	07/02/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fee46ba5-aa89-4329-855e-91079276e9fa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 19:34:00	TRUE	FALSE			en-gb	19:34:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b2f1ebd0-703a-4a6f-8777-442580bec4ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f013c15-927f-4c69-906e-5c8ffaecf63f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5bfd9c8b-ae72-4a51-bff0-e110ecef63d2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:35:00	TRUE	FALSE			en-gb	20:35:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
bfb8b436-2ef3-4d0f-ab4b-77803895eca1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:37:00	TRUE	FALSE			en-gb	20:37:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0001cf2b-94f1-4676-a5d0-5e11bd2bea17	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	07/02/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e1e8b9da-f3e4-4ab6-9c97-5feb47a67087	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86eeb9f9-c729-4fb5-9e60-d603a4583451	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:12:00	TRUE	FALSE			en-gb	21:12:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9b43036b-82f4-4920-b3f4-ccc73560fb03	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:39:00	TRUE	FALSE			en-gb	21:39:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
d0c3346d-f257-4ad8-b1ee-ad46d1d487af	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:41:00	TRUE	FALSE			en-gb	21:41:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
16d47939-7b0a-4f42-92e9-2ab6f8c0f2c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/02/2023 21:59:00	TRUE	FALSE			en-gb	21:59:00	07/02/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
004a654f-c828-4138-9e21-77f14d8535d1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 00:07:00	TRUE	FALSE			en-gb	00:07:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
7d43b7c1-d161-4303-9325-b972f2b5802a	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 00:09:00	TRUE	FALSE			en-gb	00:09:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
053229b5-859a-4a6f-970c-09e3f159a00b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 02:22:00	TRUE	FALSE			en-gb	02:22:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
2d9cdae0-08b3-4ea7-8ef0-3a06ebe18059	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 03:02:00	TRUE	FALSE			en-gb	03:02:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e19d84e3-532e-4f11-a26d-f0b926c1e7b3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 04:11:00	TRUE	FALSE			en-gb	04:11:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
e76f4071-019c-4b4b-bcd6-5ddf1bddf3e5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 05:14:00	TRUE	FALSE			en-gb	05:14:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4d0a932-8df8-403c-ab0a-6ab780eab1d5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 05:38:00	TRUE	FALSE			en-gb	05:38:00	07/03/2023		Muy limpios
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
be903b44-a121-4d8f-8cf8-bc4e0644e5bf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 06:36:00	TRUE	FALSE			en-gb	06:36:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0aadb81-829d-4a55-8e13-4cb85aa6a66e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:11:00	TRUE	FALSE			en-gb	07:11:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
530e8290-3a89-4b1a-a9fb-951764d6178b	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:17:00	TRUE	FALSE			en-gb	07:17:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e565456e-ae81-4d82-95c2-059c24a5e3f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:40:00	TRUE	FALSE			en-gb	07:40:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7e1747a0-d457-44ab-b573-88e565d54f8d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a615debf-68c0-402b-97e7-06b9ea945e30	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:00:00	TRUE	FALSE			en-gb	08:00:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
02fd7802-337c-44f3-9824-458d183fce51	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c16fd02-0f33-40a0-8d48-4ec132803e9e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:02:00	TRUE	FALSE			en-gb	08:02:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes	Yes										
5e281e50-e282-4b11-9045-f1157548d5bc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:31:00	TRUE	FALSE			en-gb	08:31:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5e281e50-e282-4b11-9045-f1157548d5bc	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
										Yes				
9a1dc357-73d0-411e-a59e-146476de0ff8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	07/03/2023		Clean it!!!!
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											
163a8669-1a6a-446f-a93d-b3654951cbbe	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:50:00	TRUE	FALSE			en-gb	08:50:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f3a41268-7aba-4af6-a61d-b5830c4f68b5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 08:58:00	TRUE	FALSE			en-gb	08:58:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
93c7137b-d367-4bc2-b45e-e48b5778a4fc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 09:09:00	TRUE	FALSE			en-gb	09:09:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
8b9144fc-8bc5-41b7-bd8d-1ac6c4ac8a7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
759ed550-d85a-4ea4-a30f-9f4b5d8564b1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
778e121a-1044-47be-bf4c-dfbfe36a4dd7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
646aff4e-22c0-4dc1-acea-3d9d559e8f0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:28:00	TRUE	FALSE			en-gb	10:28:00	07/03/2023		Sucio	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
7dfcdcd4-cb7e-41a6-a314-bf5d77a745	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes	Yes				Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f393c1f9-f3a4-46e8-8d4d-8646e3b0568b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 10:44:00	TRUE	FALSE			en-gb	10:44:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes		Yes				Yes							
6966def8-ab1d-42f6-8dc6-039f73b4b02e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:15:00	TRUE	FALSE			en-gb	11:15:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5c3a5111-2f46-4b40-9bd2-ff098c9d6c0d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:18:00	TRUE	FALSE			en-gb	11:18:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
19aecf8d-e15d-466e-baaa-334d9bb497b4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
d1811875-4b98-4c75-b7d2-1dd1d2edbe2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:37:00	TRUE	FALSE			en-gb	11:37:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d1811875-4b98-4c75-b7d2-1dd1d2edbe2f	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
					Yes				Yes					
e157411b-c120-41a3-8470-ffa81cf3391b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 11:43:00	TRUE	FALSE			en-gb	11:43:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
951e7993-7074-4fc7-ba6e-05e2d40fa10a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 12:22:00	TRUE	FALSE			en-gb	12:22:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
f677cae8-5050-4479-939a-87781a2a3f74	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 12:46:00	TRUE	FALSE			en-gb	12:46:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
2d4099c4-fa6b-4634-b571-f261423cff26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/03/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2d4099c4-fa6b-4634-b571-f261423cff26	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
								Yes							
75c95354-1d3d-47bc-896f-b2d4235ecc67	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 13:48:00	TRUE	FALSE			en-gb	13:48:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes						Yes							
aba9b72f-b3dc-4acd-b79d-6bcdca6b45cf	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 14:07:00	TRUE	FALSE			en-gb	14:07:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
a31a2f5d-136d-4896-9ae4-e13739885bad	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:26:00	TRUE	FALSE			en-gb	15:26:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
3dace061-609b-40d3-a887-d6a66adb8f3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:35:00	TRUE	FALSE			en-gb	15:35:00	07/03/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
192eb914-7b59-49eb-9ab1-1287c922ff3f	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:42:00	TRUE	FALSE			en-gb	15:42:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a87f5b61-c321-428b-b5fa-20d25a8fbbee	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	07/03/2023		Ngodvd2
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a4544496-bf57-42a4-909c-0d040e322d2c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:48:00	TRUE	FALSE			en-gb	15:48:00	07/03/2023		Good
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												
9c3d9ca0-5627-4a34-8244-4a0c4f7aee26	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 15:49:00	TRUE	FALSE			en-gb	15:49:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
09597cba-27cb-41ac-aad4-582f0dd295e4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dcd1b170-1b4b-48b6-a27a-325f9a8be93f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
bb0d520e-15e6-4f1a-9c7a-65e0cca1ab89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 16:42:00	TRUE	FALSE			en-gb	16:42:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
62145292-3610-4dfa-9c46-2033d3cf8d73	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
cb2b261d-fa21-4bd7-9640-c3f2af4b01bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
833d12fd-e130-4e0d-98cd-9db090fe98c2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	07/03/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
71af1ecf-c00e-4efd-b525-07bb4696c3eb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:35:00	TRUE	FALSE			en-gb	19:35:00	07/03/2023		Bgb
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
Yes	Yes						Yes	Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
78d2c040-f624-4be8-bf3e-30d02cb93ea5	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:50:00	TRUE	FALSE			en-gb	19:50:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6757d218-a204-417e-983b-89b15052db7e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:51:00	TRUE	FALSE			en-gb	19:51:00	07/03/2023		Bad	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
e23d5fc7-0c21-4195-b91d-0d6e616ac6a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 19:55:00	TRUE	FALSE			en-gb	19:55:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
25e0871b-edef-4cad-b07c-c235a1ba76e7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 20:50:00	TRUE	FALSE			en-gb	20:50:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
2614b7f3-3f3a-4203-817c-527a2c849bcf	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 21:09:00	TRUE	FALSE			en-gb	21:09:00	07/03/2023		F	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
34c20817-0cc1-4d03-9355-061f43dc703e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 22:52:00	TRUE	FALSE			en-gb	22:52:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
b4391d24-8226-4270-8e24-3a3bedf51563	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/03/2023 23:22:00	TRUE	FALSE			en-gb	23:22:00	07/03/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
89a27e21-464f-4d3e-b1a7-730db14e70ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 01:06:00	TRUE	FALSE			en-gb	01:06:00	07/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
8cb71149-404a-489c-a345-077d8bc1c73a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 03:17:00	TRUE	FALSE			en-gb	03:17:00	07/04/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9fa141ab-b2e2-4838-bee6-de8b17aee89e	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 05:40:00	TRUE	FALSE			en-gb	05:40:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72a95f3c-800e-438f-b548-4f50d928e75c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 05:44:00	TRUE	FALSE			en-gb	05:44:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes				Yes			Yes		Yes					
e64849bd-8848-47c8-bf7c-509e9fc52864	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 07:08:00	TRUE	FALSE			en-gb	07:08:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
				Yes						Yes					
51b26f4e-624e-4c32-a312-9aa68aafbd3d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 07:25:00	TRUE	FALSE			en-gb	07:25:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
51b26f4e-624e-4c32-a312-9aa68aafbd3d	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
													Yes		Yes					
ced9754f-54e6-4763-92b5-aeb7715d02bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
fac4a715-2c12-4a87-b89d-024078d88808	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 10:42:00	TRUE	FALSE			en-gb	10:42:00	07/04/2023		No						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
761db4d0-b639-4bc5-a372-4e29e49cff68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 10:50:00	TRUE	FALSE			en-gb	10:50:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
	Yes																			
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>		
								Yes												
4adaefe0-c4ca-4128-b814-6d34357ceeca	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 11:28:00	TRUE	FALSE			en-gb	11:28:00	07/04/2023		Love						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
173b3004-0c74-463d-980b-4e7c041c015f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 11:51:00	TRUE	FALSE			en-gb	11:51:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a8699d0-f11e-4c68-99d3-0fd3ffb169c6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 11:52:00	TRUE	FALSE			en-gb	11:52:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
08549766-d660-4946-9aec-495b3cbe5282	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 13:58:00	TRUE	FALSE			en-gb	13:58:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
79f20e7d-1b4c-46a4-bdc6-843cb5187c15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 15:27:00	TRUE	FALSE			en-gb	15:27:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86ae924b-7887-483d-b2bd-5ae67aeae456	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:07:00	TRUE	FALSE			en-gb	16:07:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c4e471cf-6d1d-42f2-8c84-297e571c6d74	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	07/04/2023		Mj
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
c4e471cf-6d1d-42f2-8c84-297e571c6d74	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	<b>Dirty Mirrors</b>		<b>Dirty Stalls or Urinals</b>		<b>Dirty Walls</b>		<b>Litter on the floor</b>		<b>No Paper Towels</b>		<b>No Supplies e.g. Soaps/Paper</b>		<b>Other</b>		<b>Smell</b>		<b>Wet Floor</b>		<b>Wet/Dirty Counters</b>	
	Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes		Yes			
5ad266c4-b85c-43c0-8143-f8f4ab42d4f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:18:00	TRUE	FALSE			en-gb	16:18:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
ae5a0dec-5131-4f83-a84c-48abe489d7a8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:25:00	TRUE	FALSE			en-gb	16:25:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
b94387a8-86a6-4278-a146-a936958100dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:32:00	TRUE	FALSE			en-gb	16:32:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
23e146c7-6b69-44dd-a9c8-f85caf22defc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:34:00	TRUE	FALSE			en-gb	16:34:00	07/04/2023		More stalls						
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		
fcf185de-f277-4aa9-b61f-f87594b8527e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:35:00	TRUE	FALSE			en-gb	16:35:00	07/04/2023								
	How would you rate this restroom today?																			
	<b>Average</b>		<b>Good</b>		<b>Poor</b>															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
f7e283c4-5cc5-462d-853e-ca5b7c9b4042	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													
fda81cad-cec4-45c9-9ef9-374a50831067	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 16:36:00	TRUE	FALSE			en-gb	16:36:00	07/04/2023		Very nice he helped me
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
					Yes									
f936e60e-085b-4336-bf75-ab911ed89798	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 17:36:00	TRUE	FALSE			en-gb	17:36:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
			Yes											
c9a71e78-039d-4b5e-8fb3-c45179038169	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 17:48:00	TRUE	FALSE			en-gb	17:48:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>		<b>Good</b>		<b>Poor</b>									
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
c9a71e78-039d-4b5e-8fb3-c45179038169	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes							Yes					
ef812058-2cc3-4ccb-a302-4bf7f322a3dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 18:16:00	TRUE	FALSE			en-gb	18:16:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c623a310-209c-49aa-a95e-710d660ea2d9	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 18:38:00	TRUE	FALSE			en-gb	18:38:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9f98efe-35ad-4e92-9958-535d8c0b9ff7	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 19:45:00	TRUE	FALSE			en-gb	19:45:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
			Yes												
858608d2-384c-410d-aa29-9cdc846796dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	07/04/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA

**Buildings:** All

**Zones:** All

**Locations:** All

**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2e4de218-f2af-48d9-b15b-f52ad0834336	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 20:27:00	TRUE	FALSE			en-gb	20:27:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0677e277-51ad-4ee1-af63-bdbe85c23df9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/04/2023 23:26:00	TRUE	FALSE			en-gb	23:26:00	07/04/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
40227254-8233-4518-9b3e-5ec3fc8db122	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 03:44:00	TRUE	FALSE			en-gb	03:44:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
58a85934-682f-478d-95f7-213561384faa	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 04:29:00	TRUE	FALSE			en-gb	04:29:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
359b72ba-c867-44d7-9e4b-10b4dfc6121c	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:00:00	TRUE	FALSE			en-gb	05:00:00	07/05/2023		Clean
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea7fbcce-0f30-459b-b77c-6eb70f92be77	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:09:00	TRUE	FALSE			en-gb	05:09:00	07/05/2023		Ok
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
d57a1604-6bb6-424a-a396-d8470352cd61	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:20:00	TRUE	FALSE			en-gb	05:20:00	07/05/2023		100
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e9088294-e878-49e8-81b7-332bea847013	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 05:58:00	TRUE	FALSE			en-gb	05:58:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3c6fbfc9-2f72-488b-b8fd-4a7d6e84a3f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 06:41:00	TRUE	FALSE			en-gb	06:41:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c3b41e7e-4b4e-4066-a3fd-7c2e01da9d40	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3f4da96a-d8cb-4e7f-be72-5f5792e984c3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 07:46:00	TRUE	FALSE			en-gb	07:46:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
5c753249-81ec-4b01-b140-a7ed7974d83c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 07:59:00	TRUE	FALSE			en-gb	07:59:00	07/05/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
1218cc42-2057-42d4-ade2-105dd2c79dfb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 08:11:00	TRUE	FALSE			en-gb	08:11:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
b94d3a15-27be-48a2-8454-cc5013079fa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
01c4742a-6843-43b0-9cf3-a1d516d8c444	Gate D10 WRR	Gate D10 Women's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 09:45:00	TRUE	FALSE			en-gb	09:45:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c55dce9-fca8-4b6a-baff-0ed91ed10242	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 09:48:00	TRUE	FALSE			en-gb	09:48:00	07/05/2023		Bhg h
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
d9efb382-0b88-468d-9099-e666dab640a1	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/05/2023		Suck my ****
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
dd022b9f-aa2f-43b9-b345-fcfd96c9263	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 10:22:00	TRUE	FALSE			en-gb	10:22:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7a0c86c2-ad79-4c22-9bf8-4b8290381cfc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 10:53:00	TRUE	FALSE			en-gb	10:53:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
cf84dfab-4193-42d0-a279-971c3328dc88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 11:44:00	TRUE	FALSE			en-gb	11:44:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
345a2682-2fd8-4640-8d6e-f52a32f1e0ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 16:51:00	TRUE	FALSE			en-gb	16:51:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
354d18bc-916c-4467-af43-c7cc1eba2fbd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 16:52:00	TRUE	FALSE			en-gb	16:52:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5250c1f2-8587-493f-9048-26dd25d0d5d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 17:21:00	TRUE	FALSE			en-gb	17:21:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5fa66b7-82cb-4800-aaa3-569f5855c7b7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
			Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
5fa666b7-82cb-4800-aaa3-569f5855c7b7	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
7bfc4b9b-0082-424d-969b-b6693fb5aa47	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 18:29:00	TRUE	FALSE			en-gb	18:29:00	07/05/2023		Update
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
af9c2483-ba3a-4e43-ae61-7c69bfc03b62	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 18:31:00	TRUE	FALSE			en-gb	18:31:00	07/05/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
1f31c1f4-46d4-4737-ad65-bbc83b2ed857	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 19:03:00	TRUE	FALSE			en-gb	19:03:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													
3162fbd0-b34f-4f13-8f73-adeb187df221	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	07/05/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
3e4f3346-720d-4d93-804f-68bdae5ee7d8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 20:00:00	TRUE	FALSE			en-gb	20:00:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
62baf6a-e8e4-40fc-a552-025b8121446f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 20:39:00	TRUE	FALSE			en-gb	20:39:00	07/05/2023		It is very good i approve	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
bfce586f-c2b9-485d-aac0-cedddd2c0d38	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
0b87ff02-3be1-412c-b629-03fa24077fa6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
039e62d0-6224-4fa8-a237-0982b688c744	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 21:22:00	TRUE	FALSE			en-gb	21:22:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
69a2a68d-9a2f-4e0d-9ff8-eb4323d81f33	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 23:13:00	TRUE	FALSE			en-gb	23:13:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6d13368c-638f-4243-b650-b716032ef41c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/05/2023 23:29:00	TRUE	FALSE			en-gb	23:29:00	07/05/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						
c829acfb-da16-40a3-a017-faf83635bab2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 01:09:00	TRUE	FALSE			en-gb	01:09:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb974955-3faf-413c-81df-cc8fdfaea5d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 01:23:00	TRUE	FALSE			en-gb	01:23:00	07/06/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f912de2a-2aaf-4f91-8cb9-8c3c2f4cf2d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:11:00	TRUE	FALSE			en-gb	05:11:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
aef91cae-c1e6-4d9c-b656-95045b285246	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:12:00	TRUE	FALSE			en-gb	05:12:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
2926fd38-8b10-452b-bf07-5858cee56276	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:46:00	TRUE	FALSE			en-gb	05:46:00	07/06/2023		Good love the vibe
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
a992ba66-41b6-4e75-bd9a-d7f4e2d59cc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 05:47:00	TRUE	FALSE			en-gb	05:47:00	07/06/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c0d75098-dc0c-47ee-bf1e-af068c0cf582	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
754d6221-c1ca-43b8-a3e3-1ae977996027	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 06:24:00	TRUE	FALSE			en-gb	06:24:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
72d4b22f-47ae-40c0-989e-8986f513f972	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 07:26:00	TRUE	FALSE			en-gb	07:26:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ade5a53b-baff-42c8-91cd-27c52301b335	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 07:34:00	TRUE	FALSE			en-gb	07:34:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
f9e7e597-5dff-4ae8-9a95-d7b0598a2957	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 08:01:00	TRUE	FALSE			en-gb	08:01:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
d9dfc0c7-3a81-4aec-8194-4f2a45103489	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 08:30:00	TRUE	FALSE			en-gb	08:30:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9615fa36-4cb6-4806-a986-7498aba47e6e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 08:44:00	TRUE	FALSE			en-gb	08:44:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
5c1e2092-a068-4ba3-a3e7-66297bc4a46c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:11:00	TRUE	FALSE			en-gb	09:11:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
7f0d4f99-c431-46c9-a4e3-78f06cd849a6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:18:00	TRUE	FALSE			en-gb	09:18:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6489c47f-e1ba-4061-818b-bf7ad0f3031b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:21:00	TRUE	FALSE			en-gb	09:21:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6ecde8d7-9965-4ad7-8325-6fd3ebce80d6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:25:00	TRUE	FALSE			en-gb	09:25:00	07/06/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
b2858db3-bf50-46ef-a0c8-500c83612bc8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 09:37:00	TRUE	FALSE			en-gb	09:37:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
9ef644b2-b34f-4b1a-9c41-90b423cf3e24	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:00:00	TRUE	FALSE			en-gb	10:00:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
c05f9711-09ad-4033-8313-07798fef3e3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:02:00	TRUE	FALSE			en-gb	10:02:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
ea1c289a-a360-4e7c-8bd7-797ac7785bf2	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
67395d97-ca85-41eb-8d69-13e6fd3b7f0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 10:55:00	TRUE	FALSE			en-gb	10:55:00	07/06/2023		Only two stalls and it smells	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes	Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
7ccdbfe7-776f-4a7f-b4cb-303bc8257257	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:26:00	TRUE	FALSE			en-gb	12:26:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
10b74bd9-71a0-416c-8dd1-e9b2e0b795b9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	07/06/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
caa90ab1-4baa-42be-b00c-bfcea47fc8159	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:29:00	TRUE	FALSE			en-gb	12:29:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3ac96d6c-6414-4e4d-849a-28a91867f26e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:50:00	TRUE	FALSE			en-gb	12:50:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4c8f384a-9a25-4189-a63b-2f622596c6f8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
06493f87-5d33-4d9f-ac37-e7667cacb1e8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/06/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fc0c1ed8-1894-4d11-acc1-20b7d218be43	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3d041dd4-1dec-4b3a-8a0e-d08f1ffd44dc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:30:00	TRUE	FALSE			en-gb	13:30:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
1f7ec5ac-93f2-41c5-b897-c387d1402d45	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 13:42:00	TRUE	FALSE			en-gb	13:42:00	07/06/2023		No
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3cfc3b39-1fd3-44c7-be9f-e66e90718b3b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 15:40:00	TRUE	FALSE			en-gb	15:40:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
7c79650b-962a-4623-a614-55b53290d003	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 16:37:00	TRUE	FALSE			en-gb	16:37:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3aeffa9d-896a-4ea7-a540-3409c5c65cde	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 17:02:00	TRUE	FALSE			en-gb	17:02:00	07/06/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
5735f9e9-7208-4f16-a876-9217ee2aeefd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 17:49:00	TRUE	FALSE			en-gb	17:49:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
6386cc81-c34e-4406-a54f-ed444cad9a81	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 17:52:00	TRUE	FALSE			en-gb	17:52:00	07/06/2023		Restrom good	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
126d2e74-3f1c-44b3-9a17-eb8c99fef5be	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 20:20:00	TRUE	FALSE			en-gb	20:20:00	07/06/2023		Keep up the good work	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
aeed84a8-7d13-44a0-8f3a-9a679c82bde9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/06/2023 20:32:00	TRUE	FALSE			en-gb	20:32:00	07/06/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
81537566-1886-4291-a123-cb60d69da811	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 06:13:00	TRUE	FALSE			en-gb	06:13:00	07/07/2023		***	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
									Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
64bb564b-f329-4cb7-8b5f-9f7ccb2e76b6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 06:23:00	TRUE	FALSE			en-gb	06:23:00	07/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
98d5dc8a-5207-4a1a-9546-fc090cead302	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 07:01:00	TRUE	FALSE			en-gb	07:01:00	07/07/2023		Gunner
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
fd6227b8-69d2-4a58-83e0-08d03b54121c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 07:35:00	TRUE	FALSE			en-gb	07:35:00	07/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
8aadb0d1-4fdf-4020-94c4-e318b3988425	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 08:55:00	TRUE	FALSE			en-gb	08:55:00	07/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
9f790ee6-489e-42f4-b02d-0de19a8a80ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 08:57:00	TRUE	FALSE			en-gb	08:57:00	07/07/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f9cca8ff-e3cd-47e0-9a4a-d9b0b59df637	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:04:00	TRUE	FALSE			en-gb	09:04:00	07/07/2023		No
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9cd563a6-9f52-46c0-8024-455b1deb559a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:30:00	TRUE	FALSE			en-gb	09:30:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
23d22d02-a63b-4174-974e-3a98625177e6	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:53:00	TRUE	FALSE			en-gb	09:53:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
413424a9-cf0d-461a-9ddc-e20b3297c991	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 09:59:00	TRUE	FALSE			en-gb	09:59:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
301eac60-0007-44f2-bafb-5ab9707fa966	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 10:17:00	TRUE	FALSE			en-gb	10:17:00	07/07/2023		*****	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>						
							Yes								
a2f2aab7-6bf0-46f2-97b1-dbb65f5f6985	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 11:27:00	TRUE	FALSE			en-gb	11:27:00	07/07/2023		Best	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
093226ab-596f-4086-9b43-fc8820c6b4e9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 11:50:00	TRUE	FALSE			en-gb	11:50:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
d8940f6d-1bcb-4ad8-a802-eee3f9fc0f3e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 12:27:00	TRUE	FALSE			en-gb	12:27:00	07/07/2023		Very clean :)	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
32a4b233-587a-4c42-99c8-9927340ea9cc	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 13:03:00	TRUE	FALSE			en-gb	13:03:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
58e4e888-2238-4401-8de9-a027553ac8de	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 13:04:00	TRUE	FALSE			en-gb	13:04:00	07/07/2023		Smelly eww	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
77ab3cc4-0036-456c-b6b4-15c88209646f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 13:38:00	TRUE	FALSE			en-gb	13:38:00	07/07/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
205c3e5c-33e3-4785-adf4-d985ab3f509c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 15:04:00	TRUE	FALSE			en-gb	15:04:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
4ac710d-e77a-459a-bc21-5d759d69aa89	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
b2c3a36e-460c-4e65-9034-5963787a0ecd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 15:51:00	TRUE	FALSE			en-gb	15:51:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
02279a47-33a1-4a46-bb7c-5dfe41c172ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 17:15:00	TRUE	FALSE			en-gb	17:15:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
dda90f52-084d-4ede-aea7-67cb12dd1e14	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 17:22:00	TRUE	FALSE			en-gb	17:22:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment						
dda90f52-084d-4ede-aea7-67cb12dd1e14	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
82f0b0e3-7844-4406-9eef-521721e0feba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	07/07/2023								
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
									Yes						Yes				Yes	
eb1c9227-b996-4e4b-b5f3-bdbb14caa3c8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 18:25:00	TRUE	FALSE			en-gb	18:25:00	07/07/2023		Puto						
	How would you rate this restroom today?																			
	Average		Good		Poor															
				Yes																
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)																			
	Dirty Mirrors		Dirty Stalls or Urinals		Dirty Walls		Litter on the floor		No Paper Towels		No Supplies e.g. Soaps/Paper		Other		Smell		Wet Floor		Wet/Dirty Counters	
															Yes					
c2e646ff-1f1c-4beb-8a75-9546e6fda993	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 18:47:00	TRUE	FALSE			en-gb	18:47:00	07/07/2023		Great job team						
	How would you rate this restroom today?																			
	Average		Good		Poor															
		Yes																		

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
98ca8d1b-6360-41a1-a685-675296784694	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:10:00	TRUE	FALSE			en-gb	19:10:00	07/07/2023		Bad work														
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
9e1006e9-a5c4-4068-925f-21ea6d29de20	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:13:00	TRUE	FALSE			en-gb	19:13:00	07/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
a9ec5886-052c-4824-b394-bff612964259	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:15:00	TRUE	FALSE			en-gb	19:15:00	07/07/2023		No														
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
76bf794d-c052-460d-b5e3-f0330b4f2191	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:38:00	TRUE	FALSE			en-gb	19:38:00	07/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												
9e039979-f810-4c1a-8d1d-8a7bebcc8b9b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:48:00	TRUE	FALSE			en-gb	19:48:00	07/07/2023																
															How would you rate this restroom today?													
															Average	Good	Poor											
																Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
f269b03c-f696-4d8f-9777-fa9e21385ad7	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 19:58:00	TRUE	FALSE		en-gb	19:58:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
a6587478-b5f9-49ff-82d8-13aef282741e	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 20:25:00	TRUE	FALSE		en-gb	20:25:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
89e48f1a-e047-4589-9bc4-0bf37274dcaa	Gate D10 MRR	Gate D10 Men's		3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 20:52:00	TRUE	FALSE		en-gb	20:52:00	07/07/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
		Yes	Yes	Yes	Yes	Yes			Yes		Yes				
					Yes	Yes			Yes						

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment															
e02def45-bec1-4eb7-b5ce-5ca27a70b37c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 21:08:00	TRUE	FALSE			en-gb	21:08:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																	Yes												
a16c88af-5c3e-4803-903d-189537428fa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 21:45:00	TRUE	FALSE			en-gb	21:45:00	07/07/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
07413e50-942b-4888-b7e9-0ac600efe33e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/07/2023 22:19:00	TRUE	FALSE			en-gb	22:19:00	07/07/2023		Hi															
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
b4f51c62-ce99-49cc-a2ff-1138819dbb93	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 01:14:00	TRUE	FALSE			en-gb	01:14:00	07/08/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													
d668c7e4-3b24-4a49-aded-eba3e4a837ec	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 06:29:00	TRUE	FALSE			en-gb	06:29:00	07/08/2023																	
															How would you rate this restroom today?														
															Average	Good	Poor												
																Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
d847b730-65ea-4a9a-8043-6f2f462c7198	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 08:54:00	TRUE	FALSE			en-gb	08:54:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
6348cbc8-50a0-47fb-bffc-ec984c731ac4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 09:02:00	TRUE	FALSE			en-gb	09:02:00	07/08/2023		h	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
b6219299-d112-4cc4-8835-dfcbb2a4af1a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 09:24:00	TRUE	FALSE			en-gb	09:24:00	07/08/2023		Not enough stalls	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
							Yes								
b24116b4-93e1-425f-a47b-a0fe614966ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 10:13:00	TRUE	FALSE			en-gb	10:13:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
b24116b4-93e1-425f-a47b-a0fe614966ba	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
									Yes					
267a5487-131a-49b3-a510-c6356e7684ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 10:14:00	TRUE	FALSE			en-gb	10:14:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
87d76d12-c792-462c-b4eb-7570f39d8438	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 11:20:00	TRUE	FALSE			en-gb	11:20:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
f20b45dc-ee2a-4012-adb7-c1dc0c4f14e0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 11:25:00	TRUE	FALSE			en-gb	11:25:00	07/08/2023		It was great
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e4a823c9-e97d-45a3-aaaa-2b9f19451c88	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 12:32:00	TRUE	FALSE			en-gb	12:32:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
182e76cf-355e-4479-bf35-21a26048d087	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 13:14:00	TRUE	FALSE			en-gb	13:14:00	07/08/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
9251a0b1-b84f-4f93-8809-a35d7b649da4	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 13:28:00	TRUE	FALSE			en-gb	13:28:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
7dad7f6b-89b1-4414-9cf9-3cc1f27ee755	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 14:21:00	TRUE	FALSE			en-gb	14:21:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
744bd5bd-e962-4780-a6d2-d504206e56fa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 14:37:00	TRUE	FALSE			en-gb	14:37:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
98d9c37c-0e84-4503-bf77-92d6981af971	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 14:47:00	TRUE	FALSE			en-gb	14:47:00	07/08/2023		Smell	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment														
6abab454-9e82-4480-ad39-5fd072d026dd	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:09:00	TRUE	FALSE			en-gb	15:09:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
c34c171d-709a-4409-bc7b-4520f4daef63	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:22:00	TRUE	FALSE			en-gb	15:22:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
e27eb9e9-94de-471e-a25e-91fe89fa43ac	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:23:00	TRUE	FALSE			en-gb	15:23:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
8f7d4c92-521c-42e6-8968-4af29427fcd9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:25:00	TRUE	FALSE			en-gb	15:25:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
49a87ca5-c4f6-481f-9588-e5143eae2485	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 15:47:00	TRUE	FALSE			en-gb	15:47:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											
07348a1b-7ea0-486b-ad35-4d97d45ce9c0	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:00:00	TRUE	FALSE			en-gb	16:00:00	07/08/2023																
															How would you rate this restroom today?													
															<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes																											

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
2b50fca8-4ea5-4406-b529-8e79a46269aa	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:16:00	TRUE	FALSE			en-gb	16:16:00	07/08/2023		E
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4f60a3d1-292d-41ef-bb6b-ec17178e466a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:31:00	TRUE	FALSE			en-gb	16:31:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
86612a15-4ad1-4d94-84b1-5f8562efd374	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:46:00	TRUE	FALSE			en-gb	16:46:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
dce0372c-0cc9-48ab-a93f-fec11993409f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 16:56:00	TRUE	FALSE			en-gb	16:56:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
929591a1-db6d-4cb7-a23d-dfe52809f002	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 17:45:00	TRUE	FALSE			en-gb	17:45:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7dd88cb5-2d13-4967-bf12-ba83a6e1284b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 18:01:00	TRUE	FALSE			en-gb	18:01:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
de2fac12-7e07-4db9-9549-caed1acb7a8f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:01:00	TRUE	FALSE			en-gb	20:01:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
b9349c40-41f5-4018-b59d-148c4fb3e15f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:12:00	TRUE	FALSE			en-gb	20:12:00	07/08/2023		People bottom was leaking	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
								Yes							
ad376f75-2cd1-46fa-90c0-ae563133f00a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:31:00	TRUE	FALSE			en-gb	20:31:00	07/08/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
5c010383-f0ab-4b9e-9a9d-d551dab8d8fe	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 20:33:00	TRUE	FALSE			en-gb	20:33:00	07/08/2023		*** on floor	
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
				Yes											
Why was the restroom experience poor today? (Please select all that apply, then press next to continue)															
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes					

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
fb4361cc-c1f3-4fa6-9f32-e0561d1e3e7b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/08/2023 21:46:00	TRUE	FALSE			en-gb	21:46:00	07/08/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
a7506915-071a-4307-a9e9-149444d0879c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 06:50:00	TRUE	FALSE			en-gb	06:50:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
af8ac89b-5859-4bfd-9946-9a23009f3bc9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 07:13:00	TRUE	FALSE			en-gb	07:13:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e2059d37-71ae-4e31-8912-55c2db4eae5a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 07:50:00	TRUE	FALSE			en-gb	07:50:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f12d8718-1f1d-4993-87df-6bfa1829b884	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 08:26:00	TRUE	FALSE			en-gb	08:26:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
		Yes					Yes							

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6a520838-0174-44fb-b0d0-61f47611790b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 10:08:00	TRUE	FALSE			en-gb	10:08:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3fd2a7a-a498-48b3-8efe-ebb7042d1559	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 12:47:00	TRUE	FALSE			en-gb	12:47:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
b8ca5933-2658-4e2a-9c66-858b235d86ae	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 12:56:00	TRUE	FALSE			en-gb	12:56:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bc927849-89b2-41cf-9f42-9a925aa1472b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 13:21:00	TRUE	FALSE			en-gb	13:21:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
21faf8a0-7872-45e4-a75e-bff5ef55debb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 14:43:00	TRUE	FALSE			en-gb	14:43:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
faea3479-1a9c-46f3-a326-716a2de26c03	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 14:49:00	TRUE	FALSE			en-gb	14:49:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
faea3479-1a9c-46f3-a326-716a2de26c03	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>			
						Yes								
95bc4b8f-c3ab-497f-8e0a-fa4b8bc55d15	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 15:17:00	TRUE	FALSE			en-gb	15:17:00	07/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
3f43b365-fbc3-4c03-af44-973faf7d8b68	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 16:13:00	TRUE	FALSE			en-gb	16:13:00	07/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
957d196a-53e5-4839-8a0e-452706c324f5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 16:14:00	TRUE	FALSE			en-gb	16:14:00	07/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
e596170e-6bb9-4f36-9f70-6b95d3ed8aa3	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:13:00	TRUE	FALSE			en-gb	17:13:00	07/09/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0f913608-ecb0-45af-a7e7-7b5b01505f9d	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:27:00	TRUE	FALSE			en-gb	17:27:00	07/09/2023		Good
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
c2e18e49-11b2-4f70-bbdf-bd235d6cdcab	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:56:00	TRUE	FALSE			en-gb	17:56:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e9d858a-9efd-4b35-b452-72d1a9b8d92f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 17:57:00	TRUE	FALSE			en-gb	17:57:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
3bf64f31-7eeb-4b28-a01d-45d26cf9e765	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:21:00	TRUE	FALSE			en-gb	18:21:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bb9927c0-1bd8-414f-b8bc-2b390ca9f671	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:32:00	TRUE	FALSE			en-gb	18:32:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
bd2bba2d-f8ea-4d49-a402-6d1545335f0c	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:39:00	TRUE	FALSE			en-gb	18:39:00	07/09/2023		No coments
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4526573d-8539-4246-8b13-2d8a8a152e70	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 18:46:00	TRUE	FALSE			en-gb	18:46:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
78a5ec6a-dff5-49d6-925c-8d0755da31d5	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 19:30:00	TRUE	FALSE			en-gb	19:30:00	07/09/2023		Very Clean. Thank you.
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
e200450f-deea-4fad-8f29-21872be3b737	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 19:33:00	TRUE	FALSE			en-gb	19:33:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
21598744-c781-4fd9-8596-ed51644e23d9	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 20:02:00	TRUE	FALSE			en-gb	20:02:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
30f8f48d-bbf5-4d13-803b-adac0d752e2f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 20:05:00	TRUE	FALSE			en-gb	20:05:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
ea17e8a1-5eb9-4b8e-80b1-0858cbda3215	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 20:45:00	TRUE	FALSE			en-gb	20:45:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7743b0dc-0007-4244-a049-43898eee43fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 23:41:00	TRUE	FALSE			en-gb	23:41:00	07/09/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
6912b11a-d25e-4c2d-8c38-a6d822548958	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/09/2023 23:42:00	TRUE	FALSE			en-gb	23:42:00	07/09/2023		Israel
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f703fda2-81ca-4397-9bd3-638b61fa1398	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 00:16:00	TRUE	FALSE			en-gb	00:16:00	07/10/2023		Cleaned
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
1c45e678-0d06-428d-9fdd-40afb2a8b6f7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 00:23:00	TRUE	FALSE			en-gb	00:23:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c9fd98f3-2779-426b-8043-42972654951b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 01:37:00	TRUE	FALSE			en-gb	01:37:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
4a2bc442-8783-4e1d-9292-bdf88ea5b19b	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 04:12:00	TRUE	FALSE			en-gb	04:12:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c53a9cd2-2c81-4df2-9bb4-a654cc965747	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 05:03:00	TRUE	FALSE			en-gb	05:03:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
8c467247-f5a6-4188-85c7-1a608704a521	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 05:20:00	TRUE	FALSE			en-gb	05:20:00	07/10/2023		Fernando	
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes														
3404abec-a603-4e06-a8df-0809e536b584	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 05:50:00	TRUE	FALSE			en-gb	05:50:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
Yes															
21f565d3-305f-4626-8171-8c04a52a2731	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 06:05:00	TRUE	FALSE			en-gb	06:05:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
						Yes			Yes						
6b0da0ef-47d1-4942-90bd-7d84de4f6b25	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 06:55:00	TRUE	FALSE			en-gb	06:55:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes			Yes									

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
460f1784-e477-497c-9e84-3ef5e0710945	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 07:48:00	TRUE	FALSE			en-gb	07:48:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
455b284d-6528-40c5-8e6b-eed23fef878a	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 08:37:00	TRUE	FALSE			en-gb	08:37:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
7e7c2aae-2417-4daf-b063-8875b7f9c287	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:26:00	TRUE	FALSE			en-gb	09:26:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
c2e88071-d12b-4505-b55a-536261ba6407	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:42:00	TRUE	FALSE			en-gb	09:42:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
f87552a8-ab0e-4cd6-85e3-81bc5e238bb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:47:00	TRUE	FALSE			en-gb	09:47:00	07/10/2023		Ni
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													
0249bee0-8f34-484b-9fd3-52efbb6359fb	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 09:55:00	TRUE	FALSE			en-gb	09:55:00	07/10/2023		
	How would you rate this restroom today?													
	<b>Average</b>	<b>Good</b>	<b>Poor</b>											
	Yes													

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023 **To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
ed31751a-babd-441e-b57c-d6939e7783c7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 10:48:00	TRUE	FALSE			en-gb	10:48:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
994716dd-7e92-45f8-9834-1c27dac6d464	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 10:58:00	TRUE	FALSE			en-gb	10:58:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
5f6d60c9-8e0c-4608-a17b-f4866ea88dc7	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:23:00	TRUE	FALSE			en-gb	11:23:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
			Yes												
7f070058-d329-43fa-9551-61d1a11f633e	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:24:00	TRUE	FALSE			en-gb	11:24:00	07/10/2023			
		How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
		Why was the restroom experience poor today? (Please select all that apply, then press next to continue)													
		<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>				
			Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment
770fa12e-15dc-4361-be08-e5ad47e10d54	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:40:00	TRUE	FALSE			en-gb	11:40:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
c120a0e2-7b7a-41f9-bcf8-e2a520a0325f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:47:00	TRUE	FALSE			en-gb	11:47:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0a83e2ac-69de-412a-af0f-1bc99ee61950	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 11:55:00	TRUE	FALSE			en-gb	11:55:00	07/10/2023		
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
5a1f037a-6c62-4318-a389-35a26d00235f	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 13:18:00	TRUE	FALSE			en-gb	13:18:00	07/10/2023		We want a bouncy house in this john
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												
0c04aa2c-5d34-4bd3-b431-47cc1c21a4ba	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:09:00	TRUE	FALSE			en-gb	14:09:00	07/10/2023		The water was anice tempreture and the pee felt great
	How would you rate this restroom today?													
		<b>Average</b>	<b>Good</b>	<b>Poor</b>										
		Yes												

### Avius Feedback Report

**Venue:** MIA  
**Buildings:** All  
**Zones:** All  
**Locations:** All  
**From Date:** 05/08/2023

**To Date:** 07/10/2023

Result ID	Location	Survey Device	Survey ID	Survey Name	Time Started	Completed	Hidden	Contains Profanity	Completion Time In Seconds	Language Name	Time	Date	Smart Code	Comment	
662ef13a-778a-4579-87da-4050bdaea800	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:24:00	TRUE	FALSE			en-gb	14:24:00	07/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
08461b8f-2fb1-40cb-9ee4-b3c57d6a6ac8	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:38:00	TRUE	FALSE			en-gb	14:38:00	07/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													
	Why was the restroom experience poor today? (Please select all that apply, then press next to continue)														
	<b>Dirty Mirrors</b>	<b>Dirty Stalls or Urinals</b>	<b>Dirty Walls</b>	<b>Litter on the floor</b>	<b>No Paper Towels</b>	<b>No Supplies e.g. Soaps/Paper</b>	<b>Other</b>	<b>Smell</b>	<b>Wet Floor</b>	<b>Wet/Dirty Counters</b>					
	Yes	Yes	Yes	Yes	Yes	Yes		Yes	Yes	Yes					
18a64483-8494-4a68-9c1a-a42aa7498f57	Gate D10 MRR	Gate D10 Men's	3278fa3e-85d3-4dea-9d63-c97d39326c22	Miami Restroom Survey	07/10/2023 14:56:00	TRUE	FALSE			en-gb	14:56:00	07/10/2023			
	How would you rate this restroom today?														
		<b>Average</b>	<b>Good</b>	<b>Poor</b>											
		Yes													